



**DETAILS**



<b>UNIT</b>	<b>2185</b>
<b>YEAR</b>	<b>2024</b>
<b>MAKE</b>	<b>Chevrolet</b>
<b>MODEL</b>	<b>Silverado 3500</b>
<b>SERIAL</b>	<b>1GC3YTEY4RF325542</b>
<b>ENGINE SER.</b>	<b>-</b>

---

**REGULAR MAINTENANCE**

**\* NO LARGE REPAIRS FROM 2023 TO CURRENT \***



**KEN SARGENT**  
GMC BUICK

12308 100 Street, Grande Prairie, AB T8V 4H7

Phone: (780) 532-8865 | Fax: (780) 539-7510 | Toll Free: (888) 532-8865

Parts Direct Line: (780) 539-3745 | Parts Fax: (780) 830-4220

Service Direct Line: (780) 830-4200

**SO # S109050**

Status  
Printed 12/16/2025 3:57:09 PM

**SERVICE ORDER  
CUSTOMER COPY**



User KendraH Page 1

<b>Customer No</b> 27958	<b>Advisor</b> Kendra Hare	<b>Promised</b> 11/27/2025 5:00 PM	<b>Tag#</b> 7248
Mur-Cal Services Ltd Box 1308 Grande Prairie, AB T8V 4Z1	<b>Shop</b> S1	<b>Opened</b> 11/18/2025 3:22 PM	<b>Location</b>
<b>Home</b> (780) 539-0928	<b>Bus</b> (780) 539-0928	<b>Cashed</b>	<b>PO #</b>
<b>Cell</b> Today			
<b>Email</b> ap@mur-cal.ca			
<b>Type</b> Cash			
<b>Term</b>			

  

<b>License</b>	<b>Odom In</b> 44071	<b>Odom Out</b> 44073	<b>In Service Date</b> 02/29/2024	<b>Stock No</b> MC2185
<b>Year</b> 2024	<b>Make</b> CHEVROLET	<b>Model</b> SILVERADO 3500 HD LT	<b>Model Number</b>	<b>Colour</b> WHITE
<b>Vehicle ID No</b> 1GC3YTEY4RF325542	<b>Selling Dealer</b>	<b>Extended Warranty</b>	<b>Delivery Date</b>	
<b>Engine</b> 6.6L V8 F OHV 32V	<b>Fleet #</b> MC2185			

Request	Description	Job	CSR	Severity	Status				
DIAG	Customer concerned the check engine light is on, please advise	1	0442	Low	Original				
<b>Labour</b>	<b>Description</b>				<b>Amount</b>				
DIAG	Customer concerned the check engine light is on, please advise								
<b>Part</b>	<b>Description</b>	<b>Shp</b>	<b>OH</b>	<b>AOH</b>	<b>SL</b>	<b>Bin</b>	<b>Retail</b>	<b>Price</b>	<b>Amount</b>
87858138	FILTER	1	0	0		SP8			
USA									
CORE CHARGE	CORE CHARGE 87858138	1	0	0					
C-87858138	CORE RETURN	-1	1	1					
15709703	NUT-MUFFL	4	221	209		052K03			
37183442	SEAL	1	5	5		WALL			
86517347	PIPE	1	0	0		SP7			
Cause	Scanned for codes, P2002. Put white cloth over tailpipe. Accelerated to WOT 3 times. Found excessive black smoke from tailpipe due to DPF failures.					Est Parts			0.00
						Est Labour			0.00
Correction	Parts ordered USA> Removed and replaced particulate filter. Re-assembled with new gasket and fasteners. Could not remove pressure sensor pipes without destroying them so installed new pipes. Cleared codes and completed resets. All ok.								

Request	Description	Job	CSR	Severity	Status				
DIAG	Customer concerned the service emissions system message is on, please advise	2	0442	Low	Original				
<b>Labour</b>	<b>Description</b>				<b>Amount</b>				
4122160	High Pressure Diesel Fuel Injection Rail Replacement - Bank 2								
<b>Part</b>	<b>Description</b>	<b>Shp</b>	<b>OH</b>	<b>AOH</b>	<b>SL</b>	<b>Bin</b>	<b>Retail</b>	<b>Price</b>	<b>Amount</b>
12731370	RAIL	1	2	2		002TOP			
12685923	PIPE	2	24	20		004F02			
12685924	PIPE	2	23	19		004D01			
12662184	GASKET	2	14	12		035C07			
Cause	Scanned for codes, P2293. Commanded FRP with regulator 2 and does not follow command. Varies as much as 29MPA. Requires replacement of bank 2 fuel rail.					Est Parts			0.00
						Est Labour			0.00
Correction	Parts ordered from Edmonton. Removed and replaced bank 2 fuel rail. Re-assembled with new high pressure pipes and pressure relief pipe seals. Cleared codes and tested. All ok.								

Request	Description	Job	CSR	Severity	Status
DIAG	Customer concerned the wipers will just stop working, freeze in the middle of the	3	0442	Low	Original

I hereby authorize the repair work herein set forth to be done along with the necessary material and agree that to the extent permitted by law, you are not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets highways or elsewhere for the purpose of testing and/or inspection. Until payment in full of the within account. I hereby acknowledge the existence of a repair lien in favor of the within dealer on the vehicle described herein in respect of the material supplied and services rendered under this work order for the full amount charged therefor I further acknowledge that the said lien shall continue in force at all times, whether the vehicle is in my possession or possession of the dealer, until the within account is paid in full. While the vehicle is in my possession it shas at all times be subject to repossession on demand by the dealer until the within account is paid in full

Date: \_\_\_\_\_

Signature: \_\_\_\_\_



**KEN SARGENT**  
GMC BUICK

12308 100 Street, Grande Prairie, AB T8V 4H7

Phone: (780) 532-8865 | Fax: (780) 539-7510 | Toll Free: (888) 532-8865

Parts Direct Line: (780) 539-3745 | Parts Fax: (780) 830-4220

Service Direct Line: (780) 830-4200

**SO # S109050**

Status  
Printed 12/16/2025 3:57:10 PM

**SERVICE ORDER  
CUSTOMER COPY**



User KendraH Page 2

**Customer No** 27958  
Mur-Cal Services Ltd  
Box 1308  
Grande Prairie, AB T8V 4Z1

**Home** (780) 539-0928 **Bus** (780) 539-0928  
**Cell** Today  
**Email** ap@mur-cal.ca

**Type**  
**Term** Cash

**Advisor** Kendra Hare **Promised** 11/27/2025 5:00 PM **Tag#** 7248  
**Shop** S1 **Opened** 11/18/2025 3:22 PM **Location**  
**Cashiered** **PO #**

<b>License</b>	<b>Odom In</b>	<b>Odom Out</b>	<b>In Service Date</b>	<b>Stock No</b>
	44071	44073	02/29/2024	MC2185
<b>Year</b>	<b>Make</b>	<b>Model</b>	<b>Model Number</b>	<b>Colour</b>
2024	CHEVROLET	SILVERADO 3500 HD LT		WHITE
<b>Vehicle ID No</b>	<b>Selling Dealer</b>	<b>Extended Warranty</b>	<b>Delivery Date</b>	
1GC3YTEY4RF325542				
<b>Engine</b>	6.6L V8	F OHV 32V	<b>Fleet #</b>	MC2185

wjndshield, please advise

Labour	Description	Amount
DIAG	Customer concerned the wipers will just stop working, freeze in the middle of the windshield, please advise	0.00
Rate	210.00	Est Parts 0.00
Cause	This fault is related to bulletin on case 4.	Est Labour 0.00
Correction	Repaired on case 4.	

Request	Description	Job	CSR	Severity	Status
DIAG	Customer concerned the headlights will randomly flash while driving, please advise	4	0442	Low	Original
Labour	Description	Amount			
2811105	Lighting Control Module Reprogramming with SPS	0.00			
Cause	Verified concern. P0606 set in lighting control module. Requires module reprogram as per bulletin #24-NA-005	Est Parts	0.00		
Correction	Reprogrammed lighting control module, claim code 41YZ304628981	Est Labour	0.00		

Request	Description	Job	CSR	Severity	Status
DIAG	Customer concenred the signals will start flashing fast, please advise	5	0442	Low	Original
Labour	Description	Amount			
DIAG	Customer concenred the signals will start flashing fast, please advise	0.00			
Rate	210.00	Est Parts	0.00		
Cause	Tested and signal lights are working properly at this time.	Est Labour	0.00		
Correction	Possibly related to bulletin for lighting control module reprogram.				

Request	Description	Job	CSR	Severity	Status
Z7911	2 Way Warranty Shuttle	6	0442	Low	Original
Labour	Description	Amount			
Z7911	2 Way Warranty Shuttle	0.00			
		Est Parts	0.00		
		Est Labour	0.00		

I hereby authorize the repair work herein set forth to be done along with the necessary material and agree that to the extent permitted by law, you are not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets highways or elsewhere for the purpose of testing and/or inspection. Until payment in full of the within account. I hereby acknowledge the existence of a repair lien in favor of the within dealer on the vehicle described herein in respect of the material supplied and services rendered under this work order for the full amount charged therefor I further acknowledge that the said lien shall continue in force at all times, whether the vehicle is in my possession or possession of the dealer, until the within account is paid in full. While the vehicle is in my possession it shas at all times be subject to repossession on demand by the dealer until the within account is paid in full

Date: \_\_\_\_\_

Signature: \_\_\_\_\_



**KEN SARGENT**  
GMC BUICK

12308 100 Street, Grande Prairie, AB T8V 4H7  
Phone: (780) 532-8865 | Fax: (780) 539-7510 | Toll Free: (888) 532-8865  
Parts Direct Line: (780) 539-3745 | Parts Fax: (780) 830-4220  
Service Direct Line: (780) 830-4200

**SO # S109050**

Status  
Printed 12/16/2025 3:57:10 PM

**SERVICE ORDER  
CUSTOMER COPY**



User KendraH Page 3

<b>Customer No</b> 27958	<b>Advisor</b> Kendra Hare	<b>Promised</b> 11/27/2025 5:00 PM	<b>Tag#</b> 7248
Mur-Cal Services Ltd Box 1308 Grande Prairie, AB T8V 4Z1	<b>Shop</b> S1	<b>Opened</b> 11/18/2025 3:22 PM	<b>Location</b>
<b>Home</b> (780) 539-0928 <b>Bus</b> (780) 539-0928	<b>License</b>	<b>Odom In</b> 44071	<b>Odom Out</b> 44073
<b>Cell</b> Today	<b>Year</b> 2024	<b>Make</b> CHEVROLET	<b>Model</b> SILVERADO 3500 HD LT
<b>Email</b> ap@mur-cal.ca	<b>Vehicle ID No</b> 1GC3YTEY4RF325542	<b>Selling Dealer</b>	<b>Extended Warranty</b>
<b>Type</b> Cash	<b>Engine</b> 6.6L V8 F OHV 32V	<b>Fleet #</b> MC2185	<b>Stock No</b> MC2185
			<b>Colour</b> WHITE
			<b>Delivery Date</b>
			<b>PO #</b>

Jason dropped off, no appointment have put in for the 27th

Labour	0.00
Parts	0.00
Fees	0.00
Supplies	0.00
<b>Sub-Total</b>	<b>0.00</b>
GST	0.00
<b>Total Invoice</b>	<b>0.00</b>

I hereby authorize the repair work herein set forth to be done along with the necessary material and agree that to the extent permitted by law, you are not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets highways or elsewhere for the purpose of testing and/or inspection. Until payment in full of the within account. I hereby acknowledge the existence of a repair lien in favor of the within dealer on the vehicle described herein in respect of the material supplied and services rendered under this work order for the full amount charged therefor I further acknowledge that the said lien shall continue in force at all times, whether the vehicle is in my possession or possession of the dealer, until the within account is paid in full. While the vehicle is in my possession it shas at all times be subject to repossession on demand by the dealer until the within account is paid in full

Date: \_\_\_\_\_

Signature: \_\_\_\_\_



12308 100 Street  
Grande Prairie, AB  
T8V 4H7

Phone: (780) 532-8865  
Administrative Fax: (780) 539-7510  
Toll Free: (888) 532-8865  
Parts Direct Line: (780) 539-3745  
Parts Fax: (780) 830-4220  
Service Direct Line: (780) 830-4200

INVOICE ORIGINAL  
Work Order  
#422654  
Mur-Cal Services Ltd.  
March 14, 2025  
Svc. Adv Sonnenberg, Brenda  
Cust. Ph. (780) 539-0928  
Tag# 4196

Page 1 of 3  
03/25/2025 09:48:43

<b>To: Mur-Cal Services Ltd.</b>  <b>Box 1308</b>  <b>Grande Prairie AB</b> <b>T8V 4Z1</b>	Year: 2024 Veh Id: 108686 Unit #: MC2185 Make: Chevrolet License #: Model: Silverado 3500 Hd LT Odo. In: 34,785 Colour: White Odo. Out: V.I.N.#: 1GC3YTEY4RF325542 <b>Next Service:</b> Date In: 03/14/2025 In Service Date: 02/29/2024 Out: Cases: 7 Ext. War - - ( mo/ ) - D: \$0.00 R/Lab. Rate 210.00 Promised Time: 03/28/2025 05:00:00 PM Call When Ready:
---	--

Case: 1 Customer concerned the service engine light is on please advise

Quantity	Description/Correction	Retail	Price	Total
1.00	12685923 - Pipe - Warranty	\$62.10	\$0.00	\$0.00
8.00	12654651 - WASHER-CM/SHF CVR - Warranty	\$8.83	\$0.00	\$0.00
1.00	12731731 - INJECTOR ASM-HIGH PRESS DSL FUEL - Warranty	\$387.20	\$0.00	\$0.00
			\$0.00	\$0.00

• Tech Cause: P01D1 Cylinder 4 Fuel Injection Timing Retarded, P24B1 particulate matter sensor circuit high voltage, P2463 DPF soot accumulation. History DTCs set P059F active grille shutter performance, U2627 reductant control module lost communication with level sensor, U2628 reductant control module lost communication with quality sensor, U2630 reductant control module lost communication with tank temp sensor 2. P059F, U2627, U2628, U2630 are set in history and is operating as designed at this time.  
 • -P01D1 got fuel sample, fuel is clean and tests 36api. No aftermarket devices, fuel injector 4 has failed.  
 Requires fuel injector 4  
 • Tech Comments: Replaced Fuel Injector - Bank 2 Cylinder 4. Programmed flow rate. Recovered and recharged R134a A/C system. Road tested P24B1, P2463 remains set current will require further diagnosis.  
 - Warranty  
 • Completed by: Cote, Sheldon Tech  
 License #: (J-13-137725)

Misc	\$0.00	Labour	\$0.00	Parts	\$0.00	Prepaid Parts Amt:	\$0.00	Case Total:	\$0.00
------	--------	--------	--------	-------	--------	--------------------	--------	-------------	--------

Case: 2 Customer concerned the service emission message is on please advise

Quantity	Description/Correction	Retail	Price	Total
1.00	12713949 - SENSOR ASM-EXH PRTL - Warranty	\$230.93	\$0.00	\$0.00
			\$0.00	\$0.00

• Tech Cause: P24B1 particulate matter sensor circuit high voltage, P2463 DPF soot accumulation remains set current after repairs from case 1. P24B1 is current, circuits are good. Requires particulate matter sensor. DPF soot mass is at 255%, will require DPF service regen after repairs due to high soot mass.  
 • Tech Comments: Replaced Exhaust Particulate Matter Sensor. DPF soot mass is at 255%, will require add time to perform DPF service regen due to high soot mass. ST1: Performed DPF service regeneration soot mass now at 0%. Road tested no DTCs. Operating as designed. - Warranty



12308 100 Street  
Grande Prairie, AB  
T8V 4H7

**Phone:** (780) 532-8865  
**Administrative Fax:** (780) 539-7510  
**Toll Free:** (888) 532-8865  
**Parts Direct Line:** (780) 539-3745  
**Parts Fax:** (780) 830-4220  
**Service Direct Line:** (780) 830-4200

**INVOICE ORIGINAL**  
**Work Order**  
**#422654**  
**Mur-Cal Services Ltd.**  
**March 14, 2025**  
**Svc.Adv Sonnenberg, Brenda**  
**Cust.Ph. (780) 539-0928**  
**Tag# 4196**

Page 2 of 3  
03/25/2025 09:48:44

- Completed by: Cote, Sheldon Tech  
License #: (J-13-137725)

\$0.00 \$0.00

**Misc** \$0.00    **Labour** \$0.00    **Parts** \$0.00    **Prepaid Parts Amt:** \$0.00    **Case Total:** \$0.00

**Case: 4 # N242435631 Serial Data Gateway Module -**  
Serial Gateway Module Reprogramming with SPS 9107414 .4

**Quantity Description/Correction**

**Price**    **Total**  
\$0.00    \$0.00

- Tech Cause: # N242435631
- Tech Comments: Reprogrammed SDGM as per # N242435631. WCC: 0SYY268110771 - Warranty
- Completed by: Cote, Sheldon Tech  
License #: (J-13-137725)

\$0.00 \$0.00

**Misc** \$0.00    **Labour** \$0.00    **Parts** \$0.00    **Prepaid Parts Amt:** \$0.00    **Case Total:** \$0.00

**Case: 5 # N242469160 Tailgate May Open Unexpectedly -**  
Liftgate Exterior Release Switch Replacement 9107708

**Quantity Description/Correction**

**Retail**    **Price**    **Total**  
\$52.09    \$0.00    \$0.00  
\$0.00    \$0.00    \$0.00

1.00 85734717 - Switch - Warranty (FP)

- Tech Cause: # N242469160
- Tech Comments: Replaced tailgate switch as per # N242469160. Verified correct operation. - Warranty
- Completed by: Cote, Sheldon Tech  
License #: (J-13-137725)

\$0.00 \$0.00

**Misc** \$0.00    **Labour** \$0.00    **Parts** \$0.00    **Prepaid Parts Amt:** \$0.00    **Case Total:** \$0.00

**Case: 6 # N242478480 No Lock Remote Start - Expires with Base Warranty -**  
Engine and transmission Control Module Programming with SPS 9107512 .7

**Quantity Description/Correction**

**Price**    **Total**  
\$0.00    \$0.00

- Tech Cause: # N242478480
- Tech Comments: Reprogrammed ECM/TCM as per # N242478480. WCC: 0SYY268113300 - Warranty
- Completed by: Cote, Sheldon Tech  
License #: (J-13-137725)

\$0.00 \$0.00

**Misc** \$0.00    **Labour** \$0.00    **Parts** \$0.00    **Prepaid Parts Amt:** \$0.00    **Case Total:** \$0.00

**Case: 7 2 Way Warranty Shuttle**

**Quantity Description/Correction**

**Price**    **Total**

**Misc** \$0.00    **Labour** \$0.00    **Parts** \$0.00    **Prepaid Parts Amt:** \$0.00    **Case Total:** \$0.00



12308 100 Street  
Grande Prairie, AB  
T8V 4H7

**Phone:** (780) 532-8865  
**Administrative Fax:** (780) 539-7510  
**Toll Free:** (888) 532-8865  
**Parts Direct Line:** (780) 539-3745  
**Parts Fax:** (780) 830-4220  
**Service Direct Line:** (780) 830-4200

**INVOICE ORIGINAL**  
**Work Order**  
**#422654**  
**Mur-Cal Services Ltd.**  
**March 14, 2025**  
**Svc.Adv Sonnenberg, Brenda**  
**Cust.Ph. (780) 539-0928**  
**Tag# 4196**

Page 3 of 3  
03/25/2025 09:48:44

**Case: 8** Added Operation: New Body Diesel Fuel Filter Replacement \*filter life is at 0%. - Tech Cause: Maintenance -  
Tech Comments: Replaced fuel filter. Reset filter life.

Quantity	Description/Correction	Retail	Price	Total
1.00	13539108 - Filter kit, fuel	\$76.70	\$0.00	\$0.00
			\$119.05	\$119.05

- Tech Cause: Maintenance
- Tech Comments: Replaced fuel filter. Reset filter life.
- Completed by: Cote, Sheldon Tech  
License #: (J-13-137725)

<b>Misc</b> \$0.00	<b>Labour</b> \$61.79	<b>Parts</b> \$57.26	<b>Prepaid Parts Amt:</b> \$0.00	<b>Case Total:</b> \$119.05
				\$0.00

O U T	Indebtedness is hereby acknowledged for the "Total Charges" being all or the balance owing to repairs, parts & accessories described in this work order.		Currency:	<b>Labour:</b> \$61.79
				<b>Parts:</b> \$57.26
			<b>Payment Ref:</b>	<b>Misc:</b> \$0.00
			<b>Expiry Date:</b>	<b>Sub Total:</b> \$119.05
			<b>P/O#:</b> 2185	<b>G/HST:</b> \$5.95
			<b>G/HST Reg #</b> 105411359RT0001	<b>PST:</b> \$0.00
				<b>Tax Adjustment:</b> \$0.00
	03/25/2025			
Date	Signature	<b>Payment Type</b>	<b>Total:</b>	<b>\$125.00</b>



12308 100 Street  
Grande Prairie, AB  
T8V 4H7

**Phone:** (780) 532-8865  
**Administrative Fax:** (780) 539-7510  
**Toll Free:** (888) 532-8865  
**Parts Direct Line:** (780) 539-3745  
**Parts Fax:** (780) 830-4220  
**Service Direct Line:** (780) 830-4200

**INVOICE ORIGINAL**  
**Work Order**  
**#421697**  
**Mur-Cal Services Ltd.**  
**February 27, 2025**  
**Svc. Adv Vogelesang, Alex**  
**Cust. Ph. (780) 539-0928**  
**Tag# OIL10**

Page 1 of 2  
02/27/2025 09:35:51

<b>To: Mur-Cal Services Ltd.</b>  <b>Box 1308</b>  <b>Grande Prairie AB</b> <b>T8V 4Z1</b>	<b>Year:</b> 2024 <b>Veh Id:</b> 108686 <b>Unit #:</b> MC2185 <b>Make:</b> Chevrolet <b>License #:</b> <b>Model:</b> Silverado 3500 Hd LT <b>Odo. In:</b> 32,894 <b>Colour:</b> White <b>Odo. Out:</b> <b>V.I.N.#:</b> 1GC3YTEY4RF325542 <b>Next Service:</b> <b>Date In:</b> 02/27/2025 <b>In Service Date:</b> 02/29/2024 <b>Out:</b> 02/27/2025 <b>Cases:</b> 3 <b>Ext. War - - ( mo/ ) - D:</b> \$0.00 <b>R/Lab. Rate</b> 210.00 <b>Promised Time:</b> 00/00/0000 00:00:00 AM <b>Call When Ready:</b> No
---	--

**Case: 1 Winter Diesel Oil Change (Includes Lube, Oil & Filter, 12 Pt Inspection, Check levels top up fluid levels)**

Quantity	Description/Correction	Retail	Price	Total
1.00	12735811 - Filter	\$18.57	\$0.00	\$0.00
10.00	19420609 - ENG DELVAC 1 ESP CK4 DIESEL 5W40 MOBIL	\$12.25	\$0.00	\$0.00
			\$165.00	\$165.00

- Tech Cause: lof
- Tech Comments: lof

POSTED

**Misc** \$0.00    **Labour** \$46.60    **Parts** \$118.40    **Prepaid Parts Amt:** \$0.00    **Case Total:** \$165.00

**Case: 2 NEEDS AIR FILTER**

Quantity	Description/Correction	Retail	Price	Total
1.00	85614334 - ELEMENT-A/VCL	\$82.37	\$74.13	\$74.13
			\$0.00	\$0.00

- Tech Cause: dirty
- Tech Comments: replaced

**Misc** \$0.00    **Labour** \$0.00    **Parts** \$74.13    **Prepaid Parts Amt:** \$0.00    **Case Total:** \$74.13

**Case: 3 requested cabin air filter**

Quantity	Description/Correction	Retail	Price	Total
1.00	13508023 - Filter	\$48.66	\$43.80	\$43.80
			\$0.00	\$0.00

- Tech Cause: requested
- Tech Comments: supplied



12308 100 Street  
Grande Prairie, AB  
T8V 4H7

**Phone:** (780) 532-8865  
**Administrative Fax:** (780) 539-7510  
**Toll Free:** (888) 532-8865  
**Parts Direct Line:** (780) 539-3745  
**Parts Fax:** (780) 830-4220  
**Service Direct Line:** (780) 830-4200

**INVOICE ORIGINAL**  
**Work Order**  
**#421697**  
**Mur-Cal Services Ltd.**  
**February 27, 2025**  
**Svc.Adv Voogesang, Alex**  
**Cust.Ph. (780) 539-0928**  
**Tag# OIL10**

Page 2 of 2  
02/27/2025 09:35:51

<b>Misc</b> \$0.00	<b>Labour</b> \$0.00	<b>Parts</b> \$43.80	<b>Prepaid Parts Amt:</b> \$0.00	<b>Case Total:</b> \$43.80
				\$0.00

Indebtedness is hereby acknowledged for the "Total Charges" being all or the balance owing to repairs, parts & accessories described in this work order.

Currency:

**Labour:** \$46.60  
**Parts:** \$236.33  
**Misc:** \$0.00  
**Sub Total:** \$282.93  
**G/HST:** \$14.15  
**PST:** \$0.00  
**Tax Adjustment:** \$0.00

**Payment Ref:**  
**Expiry Date:**  
**P/O#:** UNIT - 2185  
**G/HST Reg #** 105411359RT0001

O  
U  
T

02/27/2025  
Date

Signature

**Payment Type Charge**

**Total: \$297.08**



12308 100 Street  
Grande Prairie, AB  
T8V 4H7

**Phone:** (780) 532-8865  
**Administrative Fax:** (780) 539-7510  
**Toll Free:** (888) 532-8865  
**Parts Direct Line:** (780) 539-3745  
**Parts Fax:** (780) 830-4220  
**Service Direct Line:** (780) 830-4200

INVOICE ORIGINAL

**Work Order**  
**#414986**  
**Mur-Cal Services Ltd.**  
**October 28, 2024**  
**Svc. Adv Voogesang, Alex**  
**Cust.Ph. (780) 539-0928**  
**Tag# OIL 10**

Page 1 of 2  
10/28/2024 09:49:31

<b>To: Mur-Cal Services Ltd.</b>  <b>Box 1308</b>  <b>Grande Prairie AB</b> <b>T8V 4Z1</b> <b>Bill-To: Mur-Cal Services Ltd.</b>	<b>Year:</b> 2024 <b>Veh Id: 108686</b> <b>Unit #: MC2185</b> <b>Make:</b> Chevrolet <b>License #:</b> <b>Model:</b> Silverado 3500 Hd LT <b>Odo. In:</b> 21,572 <b>Colour:</b> White <b>Odo. Out:</b> <b>V.I.N.#:</b> 1GC3YTEY4RF325542 <b>Next Service:</b> <b>Date In:</b> 10/28/2024 <b>In Service Date:</b> 02/29/2024 <b>Out:</b> 10/28/2024 <b>Cases:</b> 2 <b>Ext. War - - ( mo/ ) - D:</b> \$0.00 <b>R/Lab. Rate</b> 210.00 <b>Promised Time:</b> 00/00/0000 00:00:00 AM <b>Call When Ready:</b> No
--	--

**Case: 1** Free Diesel 2500/3500 Oil Change (Includes Lube, Oil & Filter, 12 Pt Inspection, Check levels top up fluid levels)

Quantity	Description/Correction	Retail	Price	Total
1.00	12735811 - Filter - Warranty	\$18.24	\$0.00	\$0.00
10.00	88865794 - CK4 DIESEL 15W40 ACDELCO - Warranty	\$5.80	\$0.00	\$0.00
			\$122.00	\$122.00

- Tech Cause: lof
- Tech Comments: lof

**Misc** \$0.00    **Labour** \$40.91    **Parts** \$0.00    **Prepaid Parts Amt:** \$0.00    **Case Total:** \$40.91

**Case: 2** air filter

Quantity	Description/Correction	Retail	Price	Total
1.00	85614334 - ELEMENT-A/CL	\$80.91	\$72.82	\$72.82
			\$0.00	\$0.00

- Tech Cause: dirty
- Tech Comments: replaced

**Misc** \$0.00    **Labour** \$0.00    **Parts** \$72.82    **Prepaid Parts Amt:** \$0.00    **Case Total:** \$72.82

\$0.00



12308 100 Street  
Grande Prairie, AB  
T8V 4H7

**Phone:** (780) 532-8865  
**Administrative Fax:** (780) 539-7510  
**Toll Free:** (888) 532-8865  
**Parts Direct Line:** (780) 539-3745  
**Parts Fax:** (780) 830-4220  
**Service Direct Line:** (780) 830-4200

**INVOICE ORIGINAL**  
**Work Order**  
**#414986**  
**Mur-Cal Services Ltd.**  
**October 28, 2024**  
**Svc.Adv Vogelesang, Alex**  
**Cust.Ph. (780) 539-0928**  
**Tag# OIL 10**

Page 2 of 2  
 10/28/2024 09:49:31

O U T	Indebtedness is hereby acknowledged for the "Total Charges" being all or the balance owing to repairs, parts & accessories described in this work order.		Currency:	<b>Labour:</b>	\$0.00
				<b>Parts:</b>	\$72.82
				<b>Misc:</b>	\$0.00
			<b>Payment Ref:</b>	<b>Sub Total:</b>	\$72.82
			<b>Expiry Date:</b>	<b>G/HST:</b>	\$3.64
			<b>P/O#:</b> 2185	<b>PST:</b>	\$0.00
			<b>G/HST Reg #</b> 105411359RT0001	<b>Tax Adjustment:</b>	\$0.00
10/28/2024			<b>Payment Type</b>	<b>Charge</b>	<b>Total:</b>
Date	Signature				\$76.46