



H.F. NODES CONSTRUCTION

JD46 – Deere 850K Dozer

6:40 AM 12/12/2014

HOURS

7:10 AM 03/06/2015

HOURS 815 NEXT SERVICE DUE AT 1065

SERVICE TECH RANDY

SERVICED THE ENGINE 15/40

REPLACED THE OIL AIR AND FUEL FILTERS

TOOK OIL SAMPLE OF THE ENGINE

8:50 AM 22/07/2015

HOURS 1160 NEXT SERVICE DUE AT 1410

SERVICE TECH CHRIS

SERVICED THE ENGINE 15/40

REPLACED THE OIL AIR AND FUEL FILTERS

11:25 AM 19/08/2015

HOURS

SERVICE TECH BRANDT TRACTOR

CHECKED OUT THE BROKEN CAB MOUNT

4:37 PM 27/07/2016

HOURS 1452 NEXT SERVICE DUE AT 1647

6:42 AM 24/09/2016



H.F. NODES CONSTRUCTION

HOURS 1665 NEXT SERVICE DUE AT 1915

SERVICE TECH SLADE

SERVICED THE ENGINE 10/30

REPLACED THE OIL AIR AND FUEL FILTERS

FIRE EXT APRIL 2016

6:39 AM 12/12/2016

HOURS 1920 NEXT SERVICE DUE AT 2175

SERVICE TECH GORDON

SERVICED THE ENGINE 10/30

REPLACED THE OIL AIR AND FUEL FILTERS

FIRE EXT APRIL 2016

4:26 PM 22/12/2016

HOURS 2210 NEXT SERVICE DUE AT 2460

SERVICE TECH NEIL;

SERVICE THE ENGINE 10/30

REPLACED THE OIL AIR AND FUEL FILTERS

8:45 AM 29/12/2016

HOURS 2215 NEXT SERVICE DUE AT 2460

SERVICE TECH GORDON

REPLACED THE RIPPER CYLINDER THAT THE ROD GOT BROKE

1:50 PM 24/01/2017

HOURS 2265 NEXT SERVICE DUE AT 2460

SERVICE TECH GORDON AND NEIL

CHECKED MACHINE OVER



H.F. NODES CONSTRUCTION

REPLACED THE REAR CAB MOUNTS

CHANGED CUTTING EDGES AND CORNER BITS

REPLACED THE ALT

CHECKED OUT THE HEATER

HEAT ONLY ONCE IN A WHILE

FIRE EXT SEPT 2016

7:57 AM 21/02/2017

HOURS 2312 NEXT SERVICE DUE AT 2460

SERVICE TECH COLE

CHECKED MACHINE OVER

FIRE EXT SEPT 2017

3:43 PM 05/06/2017

HOURS 2478 NEXT SERVICE DUE AT 2728

SERVICE TECH GORDON

SERVIED THE ENGINE 15/40

REPLACED THE OIL AIR AND FUEL FILTERS

3:47 PM 27/07/2017

HOURS 2760 NEXT SERVICE DUE AT 3010

SERVICE TECH NEIL;

SERVICED THE ENGINE 15/40

REPLACED THE OIL AIR AND FUEL FILTERS

9:23 AM 29/08/2017

HOURS 3030 NEXT SERVICE DUE AT 3280

SERVICE TECH NEIL



H.F. NODES CONSTRUCTION

SERVICED THE ENGINE 15/40

REPLACED THE OIL AIR AND FUEL FILTERS

FIRE EXT JULY 2017

10:20 AM 27/10/2017

HOURS 3436 NEXT SERVICE DUE AT 3686

SERVICE TECH NEIL

SERVICED THE ENGINE 10/30

REPLACED THE OIL AIR AND FUEL FILTERS

FIRE EXT JULY 2017

6:20 AM 12/04/2018

HOURS

SERVICE TECH RANDY

REMOVED THE FUSE FOR THE TOP-CON ON THE GROUND SIDE

6:20 AM 30/08/2018

HOURS 3809 NEXT SERVICE DUE AT 4059

SERVICE TECH RANDY

SERVICED THE ENGINE 15/40

REPLACED THE OIL AIR AND FUEL FILTERS

CHECKED THE MACHINE OVER REAL GOOD

10:43 AM 15/01/2019

HOURS 4060 NEXT SERVICE DUE AT 4310

SERVICE TECH DENNIS

SERVICED THE ENGINE 10/30

REPLACED THE OIL AIR AND FUEL FILTERS



H.F. NODES CONSTRUCTION

FIRE EXT MAY 2018

2:26 PM 24/04/2019

HOURS 4070 service due at 4320

SERVICE TECH NEIL AND COLE

INSTALLED THE TRACK TENSIONER UPDATE.

REMOVED THE ENGINE

REPLACED THE OIL PAN GASKET

REPLACED THE FRONT AND REAR SEALS

INSTALLED THE ENGINE

CHANGED FINAL DRIVE OILS, HYD, TRANS ALL FILTERS.

REPLACED THE DOGBONE LINK

REMOVED SHIMS FROM BALL STUD

REPLACED ALL THE RIPPER HOSES

REMOVED ENGINE OIL, COOLENT SAMPLE PORTS/LINES.

NEW CAT BATTERIES.

FIX STUMP PANS

WASHED

FIRE EXT MARCH/2019

2:45 PM 19/06/2019

HOURS 4417 NEXT SERVICE DUE AT 4320

SERVICE TECH AYDEN

CHECKED THE MACHINE OVER

FIRE EXT MAY 2020

4:36 PM 02/10/2019

HOURS 4429



H.F. NODES CONSTRUCTION

SERVICE TECH SLADE

CHECKED OUT THE ENGINE CODES

REPLACED THE PRESSURE REGULATOR ON THE FULE SYSTEM

REPLACED THE SCV AND THE PRESSURE SENDER

4:26 PM 18/12/2019

HOURS 4704 NEXT SERVICE DUE AT 4954

SERVICE TECH AYDEN

SERVICED THE ENGINE 10/30

REPLACED THE OIL AIR AND FUEL FILTERS

FIRE EXT MARCH 2019

7:25 AM 07/02/2020

HOURS 4802 SERVICE DUE AT 4954

SERVICE TECH AYDEN

ONE GLOWPLUG WASNT WORKING,REMOVED ALL 6

#1 GLOWPLUG BROKE OFF IN THE HEAD. COULDNT GET IT OUT.

REPLACED CYLINDER HEAD WITH EXCHANGE FROM BRANDT TRACTOR.

REPLACED ALL 6 GLOWPLUGS WITH NEW ONES.

NEW EXHAUST MANIFOLD STUDS/GASKETS,, TURBO BOLTS/GASKETS.

NEW INJECTOR FEED TUBES,ALL NEW TOP END GASKETS.

NEW HEAD BOLTS, ROCKER SHAFT BOLTS.

ALL NEW TOP END GASKETS/SEALS.

REPLACED THE REAR CAB MOUNTS.

CHANGED LEFT TRAVEL MOTOR SPEED SENSOR.

REPLACED ALL OF THE TOPCON BUSHINGS.

INSTALLED NEW RAILS WITH USED PADS

NEW SPROCKET SEGMENTS.



H.F. NODES CONSTRUCTION

3:12 PM 17/07/2020

HOURS 4997 NEXT SERVICE DUE AT 5247

SERVICE TECH MURRAY

SERVICED THE ENGINE 15/40

REPLACED THE OIL AIR AND FUEL FILTERS

FIRE EXT SEPT 2019

9:21 AM 23/01/2021

HOURS 5247 NEXT SERVICE DUE AT 5247

SERVICE TECH AYDEN

REPLACED THE PIN IN THE CAB MOUNT

2:54 PM 09/02/2021

HOURS 5445 NEXT SERVICE DUE AT 5745

SERVICE TECH AYDEN

SERVICED THE ENGINE 10/30

REPLACED THE OIL AIR AND FUEL FILTERS

FIRE EXT SEPT 2019

3:41 PM 23/02/2021

HOURS 5575 NEXT SERVICE DUE AT 5745

SERVICE TECH MURRAY

REPLACED THE CUTTING EDGES AND CORNER BITS

2:51 PM 24/03/2021

HOURS 5603 NEXT SERVICE DUE AT 5745

SERVICE TECH SLADE



H.F. NODES CONSTRUCTION

CHECKED THE CODES

FOUND THE BOOST SENSOR WAS NOT PLUGGED IN CORRECTLY

ORDERED A CLAMP FOR THE EXHAUST PIPE

REPLACED THE PLASTIC ON THE DOZER CONTROL HANDLE

REPLACED THE BROKEN EXHAUST CLAMP

11:04 AM 15/07/2021

HOURS 5617 NEXT SERVICE DUE AT 5745

SERVICE TECH AYDEN

REPLACED THE LEFT BLADE LIF HOSE UNDER THE CAB

NEEDS A WASH

7:41 AM 04/08/2021

HOURS 5733 NEXT SERVICE DUE AT 6033

SERVICE TECH COLE

SERVICED THE ENGINE 15/40

REPLACED THE OIL AIR AND FUEL FILTERS

REPLACED THE ALTERNATOR

REPAIRED THE GREASE LINES

REPAIRED THE HYD LEAK ON THE RIPPER

FIRE EXT JULY 2020

11:40 AM 22/11/2021

HOURS 5898

SERVICE TECH AYDEN

REPLACED THE BATTERY

2:26 PM 23/12/2021



H.F. NODES CONSTRUCTION

HOURS 6013 NEXT SERVICE DUE AT 6313

SERVICE TECH AYDEN

SERVICED THE ENGINE 10/30

RPLACED THE OIL AIR AND FUEL FILTERS

FIRE EXT AUG 2021

9:02 AM 10/03/2022

HOURS 6465 NEXT SERVICE DUE AT 6313

FLIPPED THE EDGES AND INSTALLED NEW CORNERS

9:49 AM 13/12/2022

HOURS 6606 NEXT SERVICE DUE AT 6906

SEVICE TECH ROB B.

SERVICED THE ENGINE 10/30

REPLACED THE OIL AIR AND FUEL FILTERS

CHANGED THE FINAL DRIVE OIL

9:52 AM 13/12/2022

HOURS 6804 NEXT SERVICE DUE AT 6906

SERVICE TECH SLADE

REMOVED THE TRACK GROUPS AND TRACK FRAMES

REMOVED THE BOTTOM ROLLERS

REMOVED THE HARD BAR AND SENT TO BEARING AND HYD TO GET THE END BEARING

BORES REPAIRED

REPLACED THE REAR CAB MOUNT ISOLATERS (HEAVY DUTY STYLE)

INSTALLED NEW CAT TRACK GROUPS

INSTALLED NEW CAT BOTTOM ROLLERS

INSTALLED OEM SEGMENTS



INSTALLED ITR FRONT IDLERS

REPLACED THE LEFT HAND BLADE ANGLE CYLINDER WITH A REBUILT ONE OUT OF STOCK

RESEALED BOTH RIPPER LIFT CYLINDERS

INSTALLED NEW BUSHINGS IN THE TILT CYLINDER

SENT THE HARD BAR TO BHS TO GET THE END BORES REDONE

INSTALLED ALL NEW PINS AND BUSHINGS IN THE HARD BAR

10:43 AM 24/04/2024

HOURS 8175 NEXT SERVICE DUE AT 8476

SERVICE TECH ROB

SERVICED THE ENGINE 15/40

REPLACED THE OIL AIR AND FUEL FILTERS

2:34 PM 05/07/2024

HOURS 8480 NEXT SERVICE DUE AT 8780

SERVICE TECH ROB

SERVICED THE ENGINE 15/40

REPLACED THE OIL AIR AND FUEL FILTERS

8:39 AM 22/06/2024

HOURS 8548 NEXT SERVICE DUE AT 8476

SERVICE TECH AYDEN

REPAIRED THE A/C

FOUND LOOSE HOSES AND ORINGS BLOWN OUT

REPLACED THE ORINGS AND RECHARGED THE SYSTEM