



H.F. NODES CONSTRUCTION

JD41 – Deere 850J Dozer

5:29 PM 6/28/2012

HOURS 1080

MACHINE HAS A WINCH ON IT

11:05 AM 20/03/2013

HOURS 460 NEXT SERVICE DUE AT 710

SERVICE TECH TRAVIS

SERVICED THE ENGINE 10/30

REPLACED THE OIL AIR AND FUEL FILTERS

1:47 PM 23/11/2016

HOURS

SERVICE TECH SLADE

CHECKED OUT THE CODES FOR TRAVEL SENSOR

REPAIRED A BAD WIRE

TEST RUN

REPLACED THE SENSOR ON THE LEFT SIDE

9:10 AM 02/05/2018

HOURS 5349 NEXT SERVICE DUE AT 5599

SERVICE TECH RANDY

SERVICED THE ENGINE 15/40

REPLACED THE OIL AIR AND FUEL FILTERS

THE WATER PUMP WAS LEAKING

RANDY SENT BRANDT TRACTOR FROM GP TO REPLACE THE



WATER PUMP

11:06 AM 31/05/2018

HOURS

SERVICE TECH RANDY

OPERATOR COMPLAINED THAT THE ENGINE JUST QUIT

CHECKED THE CODES AND FOUND THE POWER WIRE TO THE ECM HAD SHORTERD OUT AND BLEW THE FUSE

CODE 190.09

REPAIRED THE WIRE AND REPLACED THE FUSE

7:09 AM 22/08/2018

HOURS 5615 NEXT SERVICE DUE AT 5865

SERVICE TECH RANDY

SERVICED THE ENGINE 15/40

REPLACED THE OIL AIR AND FUEL FILTERS

4:48 PM 10/10/2018

HOURS 5737

SERVICE TECH RANDY

REPLACED THE FAN DRIVE MOTOR

11:21 AM 16/01/2020

HOURS 6357 NEXT SERVICE DUE AT 6607

SERVICE TECH COLE

SERVICED THE ENGINE 10/30

REPLACED THE OIL AIR AND FUEL FILTERS

REPLACED THE THERMASTATS, TOPPED UP THE COOLANT

FIRE EXT AUG 2019



H.F. NODES CONSTRUCTION

11:24 AM 23/04/2020

HOURS 6401 SERVICE DUE AT 6607

SERVICE TECH SLADE

REPLACED TRANSMISSION WIRING

REPLACED ALL THE CAB MOUNTS

RESEALED BOTH THE ANGLE CYLINDER

REPLACED THE END BEARINGS AND SEALS IN THE HARD BAR

BUILT NEW REMOTE GREASE LINES AND MOUNTS

REMOVED THE COOLING PACKAGE AND WASHED OUT

CHANGED OIL IN THE FINAL, HYD AND TRANSMISSION

REPLACED THE FILTERS

REPLACED THE POOR HYD AND TRANSMISSION HOSES

1:22 PM 27/05/2020

HOURS 6585 NEXT SERVICE DUE AT 66077

SERVICE TECH MURRAY

TURNED THE CUTTING EDGES AND REPLACED THE CORNER BITS

11:28 AM 09/07/2020

HOURS 6689

SERVICE TECH SLADE

REPLACED THE HYD CONTROL LEVER IT WAS BROKEN OFF

JASON WELDED THE CRACKS ON THE BACK OF THE DOZER

FIRE EXT AUG 2019

11:38 AM 11/07/2022



H.F. NODES CONSTRUCTION

HOURS 7154 NEXT SERVICE DUE AT 7227

OPERATOR MIKE BOWLES

DATED JULY 4

NO COMMENTS

11:39 AM 09/08/2022

HOURS 7154 NEXT SERVICE DUE AT 7227

OPERATOR MIKE

COMMENTS

RIGHT HAND ANGLE CLYINDER IS LEAKING

DATED JULT 11 22

11:41 AM 18/10/2022

HOURS 7188 NEXT SERVICE DUE AT 7388

SERVICE TECH SLADE

CHECKED OUT THE COOLANT IN THE OIL

REMOVED THE ENGINE

FOUND THE LINER SEALS HAD FAILED

REPLACED THE LINERS AND PISTONS WITH KITS

ASSEMBLED THE ENGINE

WASHED THE COOLING PACKAGE

INSTALLED THE ENGINE

REPLACED THE BELT IDLER PULLEYS

INSTALLED A NEW SEAL IN THE FRONT OF THE HYDROSTATIC PUMP

INSTALLED A NEW RIGHT HAND ANGLE CYLINDER

REPLACED THE SEGMENTS

2:26 PM 13/06/2023



H.F. NODES CONSTRUCTION

HOURS

SERVICE TECH MURRAY

CHECKED OUT THE RIGHT HAND DOOR WIPER

FOUND THE GROUND WIRE WAS BROKEN

RUN A JUMPER TO GET THE MACHINE GOING ON THE JOB SITE

5:43 PM 19/06/2023

HOURS 7293 NEXT SERVICE DUE AT 7388

SERVICE TECH WESTLY

REPAIRED THE ROAD RADIO

REPLACED THE FUEL TANK SENDER

10:37 AM 27/09/2023

HOURS 7314

SERVICE TECH SLADE

INSTALLED A NEW JD LINK COMPUTER

9:48 AM 11/12/2023

HOURS 7386 NEXT SERVICE DUE AT 7686

SERVICE TECH WESTLY

SERVICED THE ENGINE 10/30

REPLACED THE OIL AIR AND FUEL FILTERS

REPLACED THE BATTERY

REMOVED SOME SHIMS ON THE BLADE PIVOT

REPLACED THE ORINGS ON THE BLADE TILT CYLINDER FITTINGS

REPLACE A HOSE ON THE BLADE ANGLE CYLINDER

FIRE EXT JUNE 2024

U/C IS ABOUT 70% WORN



H.F. NODES CONSTRUCTION

7:37 AM 11/02/2024

HOURS 7714 NEXT SERVICE DUE AT 8014

SERVICE TECH SLADE

SERVICED THE ENGINE 10/30

REPLACED THE OIL AIR AND FUEL FILTERS

REPLACED THE POOR HOSES ON THE DOZER FOR THE ANGLE AND TILT CYLINDERS

REPLACED THE BLOCK HEATER WITH A TEMRO ONE

FIRE EXT JUNE 2023

9:27 AM 20/06/2024

HOURS 7731 NEXT SERVICE DUE AT 8014

SERVICE TECH AYDEN

REPLACED THE A/C CONDESSOR FAN ON THE RIGHT SIDE

8:07 AM 27/07/2024

HOURS 7749 NEXT SERVICE DUE AT 8014

SERVICE TECH MURRAY

CHECKED THE MACHINE OVER

FOUND THE AIR FILTER HOUSING TO BE MELTED

REPLACED THE ASSEMBLY WITH NEW ONE FROM BRANDT TRACTOR

2:08 PM 06/08/2024

HOURS 7749 NEXT SERVICE DUE AT 8014

SERVICE TECH AYDEN

REPLACED THE WINCH LINE

7:22 AM 27/12/2024



H.F. NODES CONSTRUCTION

HOURS 7409 NEXT SERVICE DUE AT 8014

SERVICE TECH AYDEN

REPLACED THE BATTERY

INSTALLED A NEW JD LINK ANTENNA

TOPPED UP THE HYD

FIRE EXT APRIL 2024