

Asset	Registration	Work	Work Order	Service	RM	Task	Employee	Product	W/H	Supplier
RPS21	719QWU	2812	07/04/2016 TRA			1 LABOUR	MECH	Labour		
RPS21	719QWU	2813	07/21/2016 TRA			1 LABOUR	MECH	Labour		
RPS21	719QWU	2814	08/15/2016 TRA			1 LABOUR	MECH	Labour		
RPS21	719QWU	2815	09/05/2016 TRA			1 LABOUR	MECH	Labour		
RPS21	719QWU	2815	09/05/2016 TRB			1 LABOUR	MECH	Labour		
RPS21	719QWU	2816	09/19/2016 TRA			1 LABOUR	MECH	Labour		
RPS21	719QWU	2817	09/30/2016 TRA			1 LABOUR	MECH	Labour		
RPS21	719QWU	2818	10/12/2016 TRA			1 LABOUR	MECH	Labour		
RPS21	719QWU	2819	11/18/2016 TRA			1 LABOUR	MECH	Labour		
RPS21	719QWU	2820	01/17/2017 TRA			1 LABOUR	MECH	Labour		
RPS21	719QWU	2820	01/17/2017 TRB			1 LABOUR	MECH	Labour		
RPS21	719QWU	3390	03/29/2017 TRA			0 LABOUR	MECH1	Labour - Internal		
RPS21	719QWU	3390	03/29/2017 TRA			0 LABOUR	MECH	Labour - Internal		
RPS21	719QWU	3390	03/29/2017 TRA			14	91700BL	YAT	Clearance Light, LED Amber, Narva	
RPS21	719QWU	3390	03/29/2017 TRA			16	CON	YAT	Consumables	
RPS21	719QWU	3390	03/29/2017 TRA			REPAIRED WIRING FOR LIGHTS IN TOP RHR CORNER. REPAIRED WIRING UNDERNEATH AT REAR OF TRAILER.				
RPS21	719QWU	4287	05/26/2017 GEN			15	33000084	BRIAUS01	EX00001661	FIT TBR TYRE,
RPS21	719QWU	4287	05/26/2017 GEN			15	33000241	BRIAUS01	EX00001661	SCRAP TYRES TBR,
RPS21	719QWU	4287	05/26/2017 GEN			15	33000361	BRIAUS01	EX00001661	NWR N CASE - IRREGULAR WEAR,
RPS21	719QWU	4287	05/26/2017 GEN			15	33000361	BRIAUS01	4.42E+09	NWR N CASE - IRREGULAR WEAR,
RPS21	719QWU	4287	05/26/2017 GEN			15	33000241	BRIAUS01	4.42E+09	SCRAP TYRES TBR,
RPS21	719QWU	4287	05/26/2017 GEN			15	33000084	BRIAUS01	4.42E+09	FIT TBR TYRE,
RPS21	719QWU	4339	06/01/2017 GEN			15	33000084	BRIAUS01	EX00001706	FIT TBR TYRE,NO CHARGE
RPS21	719QWU	4339	06/01/2017 GEN			15	77000180	BRIAUS01	EX00001706	CASE STOCK 11-22.5,
RPS21	719QWU	4339	06/01/2017 GEN			15	77000180	BRIAUS01	4.42E+09	CASE STOCK 11-22.5,
RPS21	719QWU	4339	06/01/2017 GEN			15	33000084	BRIAUS01	4.42E+09	FIT TBR TYRE,NO CHARGE
RPS21	719QWU	5008	06/20/2017 FRIVANA			1	LABOUR	Labour		0
RPS21	719QWU	5008	06/20/2017 FRIVANA			ZERO DOLLAR WORK ORDER CREATED TO BRING SERVICING INTO LINE WITH QTK RECORDS 12/07/2017				
RPS21	719QWU	5009	06/20/2017 FRIVCAL			1	LABOUR	Labour		0
RPS21	719QWU	5009	06/20/2017 FRIVCAL			ZERO DOLLAR WORK ORDER CREATED TO BRING SERVICING INTO LINE WITH QTK RECORDS 12/07/2017				
RPS21	719QWU	4713	06/23/2017 GEN			39	LABEXT	QTKGRO01	PERFORMED ANNUAL SERVICE ON UNIT, REPLACED OIL & FILTERS, CHECKED AND REPALCED ALL BELTS	

RPS21	719QWU	4713	06/23/2017 GEN	39 LABEXT	QTKGRO01	SI-100612	PERFORMED ANNUAL SERVICE ON UNIT, REPLACED OIL & FILTERS, CHECKED AN
RPS21	719QWU	5150	07/21/2017 TRA	1 LABOUR	Labour		0
RPS21	719QWU	5150	07/21/2017 TRA	0 LABOUR	MECH1	Labour - Internal	
RPS21	719QWU	5150	07/21/2017 TRA	16 CON		YAT Consumables	
				BEARING			
				LOOSE			
				6 X			
				SPRING			
				EYE			
				BUSHES			
				NEED			
				ATTENTIO			
				N			
				POGO			
				RAILS IN			
				FRONT OF			
				VAN ARE			
				SEVERLY			
				RUSTED			
				SIDE			
				DOOR			
				INTERNAL			
				FRAME			
				SPLIT			
				NEEDS			
				URGENT C			
				& D			
				SERVICE			
				CHECKED			
				WHEEL			
RPS21	719QWU	5150	07/21/2017 TRA	BEARINGS			

RPS21	719QWU	5270	07/27/2017 EXOINS	1 LABOUR	Labour			0
RPS21	719QWU	5270	07/27/2017 EXOINS	0 LABOUR	MECH1	Labour - Internal		
RPS21	719QWU	5270	07/27/2017 EXOINS	ANNUAL INSPECTION PASSED.				
RPS21	719QWU	5271	07/27/2017 TRA	1 LABOUR	Labour			0
RPS21	719QWU	5271	07/27/2017 TRB	1 LABOUR	Labour			0
RPS21	719QWU	5271	07/27/2017 TRC	1 LABOUR	Labour			0
RPS21	719QWU	5271	07/27/2017 TRC	0 LABOUR	MECH1	Labour - Internal		
RPS21	719QWU	5271	07/27/2017 TRC	0 LABOUR	TRADEA	Labour - Internal		
RPS21	719QWU	5271	07/27/2017 TRC	0 LABOUR	APPREN	Labour - Internal		
RPS21	719QWU	5271	07/27/2017 TRC	8 T04-4021	YAT	Hub Cap Oring Seal		
RPS21	719QWU	5271	07/27/2017 TRC	10 2.03E+08	YAT	SPRING EYE BUSH SRS AL2		
RPS21	719QWU	5271	07/27/2017 TRC	16 CON	YAT	25 15 375		
RPS21	719QWU	5271	07/27/2017 TRC	'C' SERVICE COMPLETED.				
RPS21	719QWU	5264	07/28/2017 TYRES	15 33000084	BRIAUS01	EX00002249	FIT TBR TYRE,RP21	
RPS21	719QWU	5264	07/28/2017 TYRES	15 77000180	BRIAUS01	EX00002249	CASE STOCK 11-22.5,RP21	
RPS21	719QWU	5264	07/28/2017 TYRES	15 11001464	YAT	TYRE 11R22.5 148/145L 16 BS R187		
RPS21	719QWU	5264	07/28/2017 TYRES	15 33000084	BRIAUS01	4.42E+09	FIT TBR TYRE,RP21	
RPS21	719QWU	5264	07/28/2017 TYRES	15 77000180	BRIAUS01	4.42E+09	CASE STOCK 11-22.5,RP21	
RPS21	719QWU	5430	08/08/2017 FRIVANSE	40 15W40	QTKGRO01	EX00002329	ENGINE OIL,RP21	
RPS21	719QWU	5430	08/08/2017 FRIVANSE	0 LABEXT	QTKGRO01	EX00002329	Labour External,RP21	
							Consumables	
RPS21	719QWU	5430	08/08/2017 FRIVANSE	16 CON	QTKGRO01	EX00002329	,RP21	
RPS21	719QWU	5430	08/08/2017 FRIVANSE	'A' SERVICE CARRIED OUT ON FRIDGE MOTOR				
RPS21	719QWU	5430	08/08/2017 FRIVANSE	40 15W40	QTKGRO01	SI-103557	ENGINE OIL,RP21	
RPS21	719QWU	5430	08/08/2017 FRIVANSE	0 LABEXT	QTKGRO01	SI-103557	Labour External,RP21	
							Consumables	
RPS21	719QWU	5430	08/08/2017 FRIVANSE	16 CON	QTKGRO01	SI-103557	,RP21	
RPS21	719QWU	5807	09/04/2017 TYRES	15 33000096	BRIAUS01	EX00002586	PUNCTURE REPAIR TBR,RP21	
RPS21	719QWU	5807	09/04/2017 TYRES	REPAIRED PUNCTURE.				
RPS21	719QWU	5807	09/04/2017 TYRES	15 33000096	BRIAUS01	4.81E+09	PUNCTURE REPAIR TBR,RP21	
RPS21	719QWU	5926	09/11/2017 TYRES	15 77000180	BRIAUS01	EX00002656	CASE STOCK 11-22.5,RP21	
RPS21	719QWU	5926	09/11/2017 TYRES	15 33000084	YAT	FIT TBR TYRE		
RPS21	719QWU	5926	09/11/2017 TYRES	15 33000085	YAT	ROTATE TBR TYRE		
RPS21	719QWU	5926	09/11/2017 TYRES	15 11001464	YAT	TYRE 11R22.5 148/145L 16 BS R187		
RPS21	719QWU	5926	09/11/2017 TYRES	FIT UP 2X R187 11R22.5				
RPS21	719QWU	5926	09/11/2017 TYRES	15 77000180	BRIAUS01	4.42E+09	CASE STOCK 11-22.5,RP21	
							Consumables	
RPS21	719QWU	6196	09/27/2017 FRIVANA	1 CON	QTKGRO01	EX00002834	,RP21	
RPS21	719QWU	6196	09/27/2017 FRIVANA	1 LABEXT	QTKGRO01	EX00002834	Labour External,RP21	
RPS21	719QWU	6196	09/27/2017 FRIVANA	SERVICE COMPLETED BY QTK				

RPS21	719QWU	6196	09/27/2017 FRIVANA	1 CON		QTKGRO01	SI-106629	Consumables,RP21
RPS21	719QWU	6196	09/27/2017 FRIVANA	1 LABEXT		QTKGRO01	SI-106629	Labour External,RP21
RPS21	719QWU	6382	10/10/2017 TRA	1 LABOUR	Labour			0
RPS21	719QWU	6382	10/10/2017 TRA	0 LABOUR	APPREN	Labour - Internal		
RPS21	719QWU	6382	10/10/2017 TRA	0 LABOUR	MECH	Labour - Internal		
RPS21	719QWU	6382	10/10/2017 TRA	16 CON		YAT Consumables		
				SERVICE COMPLETED. TENSIONED GUARD POLE REPLACED MAINTENANCE LABEL.				
RPS21	719QWU	6382	10/10/2017 TRA					
RPS21	719QWU	6721	10/30/2017 FRIVANSE	1	100417	QTKGRO01	EX00003142	Filter Service Kit, Fridge Motor, SLX-400,RP21
								Consumables,RP21
RPS21	719QWU	6721	10/30/2017 FRIVANSE	1 CON		QTKGRO01	EX00003142	
								CJ-4 15w/40,RP21
RPS21	719QWU	6721	10/30/2017 FRIVANSE	1 ENGOIL		QTKGRO01	EX00003142	
								Consumables,RP21
RPS21	719QWU	6721	10/30/2017 FRIVANSE	1 CON		QTKGRO01	EX00003142	
								Consumables,RP21
RPS21	719QWU	6721	10/30/2017 FRIVANSE	1 CON		QTKGRO01	EX00003142	
RPS21	719QWU	6721	10/30/2017 FRIVANSE	1 CC		QTKGRO01	EX00003142	CALIBRATION CETIFICATE,RP21
RPS21	719QWU	6721	10/30/2017 FRIVANSE	1 LABEXT		QTKGRO01	EX00003142	Labour External,RP21
RPS21	719QWU	6721	10/30/2017 FRIVANSE	SERVICE COMPLETED BY QTK.				
RPS21	719QWU	6721	10/30/2017 FRIVANSE	1 LABEXT		QTKGRO01	SI-108948	Labour External,RP21
RPS21	719QWU	6721	10/30/2017 FRIVANSE	1 CC		QTKGRO01	SI-108948	CALIBRATION CETIFICATE,RP21

RPS21	719QWU	6721	10/30/2017 FRIVANSE	1 CON	QTKGRO01	SI-108948	Consumables,RP21
RPS21	719QWU	6721	10/30/2017 FRIVANSE	1 CON	QTKGRO01	SI-108948	Consumables,RP21
RPS21	719QWU	6721	10/30/2017 FRIVANSE	1 ENGOIL	QTKGRO01	SI-108948	CJ-4 15w/40,RP21
RPS21	719QWU	6721	10/30/2017 FRIVANSE	1 CON	QTKGRO01	SI-108948	Consumables,RP21
RPS21	719QWU	6721	10/30/2017 FRIVANSE	1 100417	QTKGRO01	SI-108948	Filter Service Kit, Fridge Motor, SLX-400,RP21
RPS21	719QWU	6777	11/06/2017 TRA	1 LABOUR	Labour		0
RPS21	719QWU	6777	11/06/2017 TRA	0 LABOUR	APPREN	Labour - Internal	
RPS21	719QWU	6777	11/06/2017 TRA	0 LABOUR	MECH1	Labour - Internal	
RPS21	719QWU	6777	11/06/2017 TRA	16 CON	YAT	Consumables	
RPS21	719QWU	6777	11/06/2017 TRA	SERVICE COMPLETED.			
RPS21	719QWU	7474	12/19/2017 FRIVANA	1 CON	QTKGRO01	EX00003668	Consumables,RP21
RPS21	719QWU	7474	12/19/2017 FRIVANA	1 LABEXT	QTKGRO01	EX00003668	Labour External,RP21
RPS21	719QWU	7474	12/19/2017 FRIVANA	QTK CALLED TOO SITE, SERVICED FRIDGE UNIT. DOWNLOAD CONFIRMED CODE 112. FOUND CORODED TERMINAL. STRIPPED IT, CLEANED IT, AND SECURED IT.			
RPS21	719QWU	7474	12/19/2017 FRIVANA	1 CON	QTKGRO01	SI-112478	Consumables,RP21
RPS21	719QWU	7474	12/19/2017 FRIVANA	1 LABEXT	QTKGRO01	SI-112478	Labour External,RP21
RPS21	719QWU	7371	12/19/2017 TRA	1 LABOUR	Labour		0
RPS21	719QWU	7371	12/19/2017 TRA	0 LABOUR	MECH1	Labour - Internal	
RPS21	719QWU	7371	12/19/2017 TRA	16 CON	YAT	Consumables	
RPS21	719QWU	7371	12/19/2017 TRA	SERVICE COMPLETED.			
RPS21	719QWU	7812	01/16/2018 TYRES	15 77000180	BRIAUS01	EX00003854	CASE STOCK 11-22.5,RP21
RPS21	719QWU	7812	01/16/2018 TYRES	15 33000084	YAT	FIT TBR TYRE	
RPS21	719QWU	7812	01/16/2018 TYRES	15 11001464	YAT	TYRE 11R22.5 148/145L 16 BS R187	
RPS21	719QWU	7812	01/16/2018 TYRES	15 77000180	BRIAUS01	4.42E+09	CASE STOCK 11-22.5,RP21
RPS21	719QWU	8075	01/29/2018 GEN	39 15W40	JC&SL01	EX00004041	ENGINE OIL,RP21

RPS21	719QWU	8075	01/29/2018 GEN	39 COO	JC&SL01	EX00004041	Coolant Allcool K/worth ,RP21
RPS21	719QWU	8075	01/29/2018 GEN	39 CON	JC&SL01	EX00004041	Consumables ,RP21
RPS21	719QWU	8075	01/29/2018 GEN	39 LABEXT	JC&SL01	EX00004041	Labour External,RP21
				JC & SL REFRIGERATION COMPLETED SERVICE AND/OR REPAIRS. TOPPED UP ENGINE COOLANT AND OIL.			
RPS21	719QWU	8075	01/29/2018 GEN				
RPS21	719QWU	8075	01/29/2018 GEN	39 LABEXT	JC&SL01	8134	Labour External,RP21 Consumables ,RP21
RPS21	719QWU	8075	01/29/2018 GEN	39 CON	JC&SL01	8134	
RPS21	719QWU	8075	01/29/2018 GEN	39 COO	JC&SL01	8134	Coolant Allcool K/worth ,RP21
RPS21	719QWU	8075	01/29/2018 GEN	39 15W40	JC&SL01	8134	ENGINE OIL,RP21
RPS21	719QWU	8017	01/29/2018 TRA	1 LABOUR	Labour		0
RPS21	719QWU	8017	01/29/2018 TRA	0 LABOUR	MECH1	Labour - Internal	
RPS21	719QWU	8017	01/29/2018 TRA	16 CON	YAT	1	
RPS21	719QWU	8017	01/29/2018 TRA	SERVICE COMPLETED.			
RPS21	719QWU	8471	02/22/2018 TYRES	15 77000180	BRIAUS01	EX00004297	CASE STOCK 11-22.5,RP21
RPS21	719QWU	8471	02/22/2018 TYRES	15 33000084	YAT	FIT TBR TYRE	
RPS21	719QWU	8471	02/22/2018 TYRES	15 11001464	YAT	TYRE 11R22.5 148/145L 16 BS R187	
RPS21	719QWU	8471	02/22/2018 TYRES	15 77000180	BRIAUS01	4.42E+09	CASE STOCK 11-22.5,RP21
RPS21	719QWU	8771	03/15/2018 TRA	1 LABOUR	Labour		0
RPS21	719QWU	8771	03/15/2018 TRA	0 LABOUR	MECH1	Labour - Internal	
RPS21	719QWU	8771	03/15/2018 TRA	16 CON	YAT	Consumables	

				SERVICE COMPLET ED. RHF SHOCKY NEEDS A SLING.				
RPS21	719QWU	8771	03/15/2018 TRA					
RPS21	719QWU	9006	03/29/2018 GEN	39 LABOUR	Labour			0
RPS21	719QWU	9006	03/29/2018 GEN	0 LABOUR	APPREN	Labour - Internal		
RPS21	719QWU	9006	03/29/2018 GEN	0 LABOUR	MECH	Labour - Internal		
RPS21	719QWU	9006	03/29/2018 GEN	14 SS70ZZM		YAT Battery 12v		
RPS21	719QWU	9006	03/29/2018 GEN	16 CON		YAT Consumables		
				FRIDGE WOULD NOT START, BATTERY FLAT. S/F A NEW BATTERY.				
RPS21	719QWU	9006	03/29/2018 GEN					
RPS21	719QWU	9064	04/03/2018 FRIVANSE	1 15W40	JC&SL01	EX00004651	ENGINE OIL,RP21 Coolant Allcool K/worth	
RPS21	719QWU	9064	04/03/2018 FRIVANSE	1 COO	JC&SL01	EX00004651	,	
RPS21	719QWU	9064	04/03/2018 FRIVANSE	1 119300	JC&SL01	EX00004651	QTK Fridge A/Filter EMI 3000,	
RPS21	719QWU	9064	04/03/2018 FRIVANSE	1 Nov-82	JC&SL01	EX00004651	OIL FILTER, FRIDGE MOTOR,	
RPS21	719QWU	9064	04/03/2018 FRIVANSE	1 Nov-42	JC&SL01	EX00004651	FUEL FILTER, FRIDGE MOTOR,	
RPS21	719QWU	9064	04/03/2018 FRIVANSE	1 COIL	JC&SL01	EX00004651	COIL CLEAN, EVAPORATOR/CONDENSOR,	
RPS21	719QWU	9064	04/03/2018 FRIVANSE	1 SUND	JC&SL01	EX00004651	SUNDRIES,	
RPS21	719QWU	9064	04/03/2018 FRIVANSE	1 LABEXT	JC&SL01	EX00004651	Labour External,RP21	
RPS21	719QWU	9064	04/03/2018 FRIVANSE	1 CC	JC&SL01	EX00004651	CALIBRATION CETIFICATE,	
RPS21	719QWU	9064	04/03/2018 FRIVANSE	SERVICE COMPLETED BY JC & SL REFRIGERATION.				
RPS21	719QWU	9064	04/03/2018 FRIVANSE	1 CC	JC&SL01	8387	CALIBRATION CETIFICATE,	
RPS21	719QWU	9064	04/03/2018 FRIVANSE	1 LABEXT	JC&SL01	8387	Labour External,RP21	
RPS21	719QWU	9064	04/03/2018 FRIVANSE	1 SUND	JC&SL01	8387	SUNDRIES,	
RPS21	719QWU	9064	04/03/2018 FRIVANSE	1 COIL	JC&SL01	8387	COIL CLEAN, EVAPORATOR/CONDENSOR,	
RPS21	719QWU	9064	04/03/2018 FRIVANSE	1 Nov-42	JC&SL01	8387	FUEL FILTER, FRIDGE MOTOR,	
RPS21	719QWU	9064	04/03/2018 FRIVANSE	1 Nov-82	JC&SL01	8387	OIL FILTER, FRIDGE MOTOR,	
RPS21	719QWU	9064	04/03/2018 FRIVANSE	1 119300	JC&SL01	8387	QTK Fridge A/Filter EMI 3000,	

RPS21	719QWU	9064	04/03/2018 FRIVANSE	1 COO	JC&SL01	8387	Coolant Allcool K/worth ,
RPS21	719QWU	9064	04/03/2018 FRIVANSE	1 15W40	JC&SL01	8387	ENGINE OIL,RP21
RPS21	719QWU	9484	04/30/2018 GEN	39 LABOUR	Labour		0
RPS21	719QWU	9484	04/30/2018 GEN	0 LABOUR	MECH1	Labour - Internal	
RPS21	719QWU	9484	04/30/2018 GEN	6 53520	YAT	COOLANT PRO, RED H/DTY CONCENTRATE	
RPS21	719QWU	9484	04/30/2018 GEN	16 CON	YAT	Consumables	
RPS21	719QWU	9484	04/30/2018 GEN	TOPPED UP FRIDGE MOTOR COOLANT.			
RPS21	719QWU	9661	05/11/2018 TRA	1 LABOUR	Labour		0
RPS21	719QWU	9661	05/11/2018 TRB	1 LABOUR	Labour		0
RPS21	719QWU	9661	05/11/2018 TRB	0 LABOUR	MECH1	Labour - Internal	
RPS21	719QWU	9661	05/11/2018 TRB	0 LABOUR	TRADEA	Labour - Internal	
RPS21	719QWU	9661	05/11/2018 TRB	0 LABOUR	APPREN	Labour - Internal	
RPS21	719QWU	9661	05/11/2018 TRB	16 CON	YAT	Consumables	
RPS21	719QWU	9661	05/11/2018 TRB	SERVICE COMPLETED.			
RPS21	719QWU	9875	05/23/2018 TYRES	15 77000180	BRIAUS01	EX00005200	CASE STOCK 11-22.5,RP21
RPS21	719QWU	9875	05/23/2018 TYRES	15 33000084	YAT	FIT TBR TYRE	
RPS21	719QWU	9875	05/23/2018 TYRES	15 11001464	YAT	TYRE 11R22.5 148/145L 16 BS R187	
RPS21	719QWU	9875	05/23/2018 TYRES	15 33000085	YAT	ROTATE TBR TYRE	
RPS21	719QWU	9875	05/23/2018 TYRES	15 33000188	YAT	B FLEET PRESSURE CHECK	
RPS21	719QWU	9875	05/23/2018 TYRES	15 77000180	BRIAUS01	4.42E+09	CASE STOCK 11-22.5,RP21
RPS21	719QWU	10310	06/13/2018 TRA	1 LABOUR	Labour		0
RPS21	719QWU	10310	06/13/2018 TRA	0 LABOUR	MECH1	Labour - Internal	
RPS21	719QWU	10310	06/13/2018 TRA	0 LABOUR	MECH1	Labour - Internal	
RPS21	719QWU	10310	06/13/2018 TRA	13 CRAHAN	YAT	Crank Handle Landing Legs	
RPS21	719QWU	10310	06/13/2018 TRA	16 CON	YAT	Consumables	
RPS21	719QWU	10310	06/13/2018 TRA	SERVICE COMPLETED. S/F NEW CRANK HANDLE FOR LEGS.			
RPS21	719QWU	10621	06/25/2018 FRIVANA	1 15W40	JC&SL01	EX00005606	ENGINE OIL,RP21
RPS21	719QWU	10621	06/25/2018 FRIVANA	1 COO	JC&SL01	EX00005606	Coolant Allcool K/worth ,RP21
RPS21	719QWU	10621	06/25/2018 FRIVANA	1 SUND	JC&SL01	EX00005606	SUNDRIES,RP21
RPS21	719QWU	10621	06/25/2018 FRIVANA	1 LABEXT	JC&SL01	EX00005606	Labour External,RP21
RPS21	719QWU	10621	06/25/2018 FRIVANA	SERVICE COMPLETED BY JC & SL REFRIGERATION.			

RPS21	719QWU	10621	06/25/2018 FRIVANA	1 LABEXT	JC&SL01	8686	Labour External,RP21
RPS21	719QWU	10621	06/25/2018 FRIVANA	1 SUND	JC&SL01	8686	SUNDRIES,RP21
							Coolant
							Allcool
							K/worth
RPS21	719QWU	10621	06/25/2018 FRIVANA	1 COO	JC&SL01	8686	,RP21
RPS21	719QWU	10621	06/25/2018 FRIVANA	1 15W40	JC&SL01	8686	ENGINE OIL,RP21
RPS21	719QWU	10511	06/26/2018 GEN	39 LABOUR	Labour		0
RPS21	719QWU	10511	06/26/2018 GEN	0 LABOUR	MECH	Labour - Internal	
RPS21	719QWU	10511	06/26/2018 GEN	0 LABOUR	MECH1	Labour - Internal	
RPS21	719QWU	10511	06/26/2018 GEN	0 LABOUR	MECH1	Labour - Internal	
RPS21	719QWU	10511	06/26/2018 GEN	13 50339	YAT	Hinge, Trailer door (Maxicube)	
RPS21	719QWU	10511	06/26/2018 GEN	16 CON	YAT	Consumables	
RPS21	719QWU	10511	06/26/2018 GEN	REPLACED 3 HINGES.			
RPS21	719QWU	11134	07/30/2018 TRA	1 LABOUR	Labour		0
RPS21	719QWU	11134	07/30/2018 TRA	0 LABOUR	MECH1	Labour - Internal	
RPS21	719QWU	11134	07/30/2018 TRA	13 37FW1	YAT	HOOD HOOK LATCH, RUBBER,	
RPS21	719QWU	11134	07/30/2018 TRA	16 CON	YAT	Consumables	
				COMPLET			
				ED			
				FITTED			
				NEW			
				REGO			
				LABEL			
				WITH			
				HOLDER			
				REPAIRED			
				WORN			
				BRAKE			
				HOSE			
				RE POP			
				RIVETED			
				STEEL			
				COVERS			
				INSIDE			
				VAN			
				GUARDS			
				SLIGHTLY			
				BENT			
				NEEDS			
				SHOCKY			
				SLING			
				FRONT			
				RIGHT			
RPS21	719QWU	11134	07/30/2018 TRA	AXLE			

RPS21	719QWU	11395	08/09/2018 FRIVANSE	1 15W40	JC&SL01	EX00006104	ENGINE OIL,RP21
RPS21	719QWU	11395	08/09/2018 FRIVANSE	1 119300	JC&SL01	EX00006104	QTK Fridge A/Filter EMI 3000,RP21
RPS21	719QWU	11395	08/09/2018 FRIVANSE	1 Nov-82	JC&SL01	EX00006104	OIL FILTER, FRIDGE MOTOR,RP21
RPS21	719QWU	11395	08/09/2018 FRIVANSE	1 Nov-42	JC&SL01	EX00006104	FUEL FILTER, FRIDGE MOTOR,RP21
RPS21	719QWU	11395	08/09/2018 FRIVANSE	1 COIL	JC&SL01	EX00006104	COIL CLEAN, EVAPORATOR/CONDENSOR,RP21
RPS21	719QWU	11395	08/09/2018 FRIVANSE	1 SUND	JC&SL01	EX00006104	SUNDRIES,RP21
RPS21	719QWU	11395	08/09/2018 FRIVANSE	1 LABEXT	JC&SL01	EX00006104	Labour External,RP21
RPS21	719QWU	11395	08/09/2018 FRIVANSE	B SERVICE COMPLETED & CALIBRATION - JC & SL			
RPS21	719QWU	11395	08/09/2018 FRIVANSE	1 LABEXT	JC&SL01	8841	Labour External,RP21
RPS21	719QWU	11395	08/09/2018 FRIVANSE	1 SUND	JC&SL01	8841	SUNDRIES,RP21
RPS21	719QWU	11395	08/09/2018 FRIVANSE	1 COIL	JC&SL01	8841	COIL CLEAN, EVAPORATOR/CONDENSOR,RP21
RPS21	719QWU	11395	08/09/2018 FRIVANSE	1 Nov-42	JC&SL01	8841	FUEL FILTER, FRIDGE MOTOR,RP21
RPS21	719QWU	11395	08/09/2018 FRIVANSE	1 Nov-82	JC&SL01	8841	OIL FILTER, FRIDGE MOTOR,RP21
RPS21	719QWU	11395	08/09/2018 FRIVANSE	1 119300	JC&SL01	8841	QTK Fridge A/Filter EMI 3000,RP21
RPS21	719QWU	11395	08/09/2018 FRIVANSE	1 15W40	JC&SL01	8841	ENGINE OIL,RP21
RPS21	719QWU	11815	09/11/2018 GEN	39 LABOUR	Labour		0
RPS21	719QWU	11815	09/11/2018 GEN	0 LABOUR	TRADEA	Labour - Internal	
RPS21	719QWU	11815	09/11/2018 GEN	16 CON	YAT	Consumables	
RPS21	719QWU	11815	09/11/2018 GEN	RERIVETED 3 SECTIONS OF POGO RAIL			
RPS21	719QWU	11864	09/14/2018 TYRES	15 77000180	BRIAUS01	EX00006398	CASE STOCK 11-22.5,RP21
RPS21	719QWU	11864	09/14/2018 TYRES	15 11001464	YAT	TYRE 11R22.5 148/145L 16 BS R187	
RPS21	719QWU	11864	09/14/2018 TYRES	R&R TYRES			
RPS21	719QWU	11864	09/14/2018 TYRES	15 77000180	BRIAUS01	96100460	CASE STOCK 11-22.5,RP21
RPS21	719QWU	12051	09/28/2018 DEFECT	1 LABOUR	MECH	Labour	

				Defect :-
				Defect
				Code :
				00001564
				Defect
				Reference
				: 01653
				Date :
				26/07/20
				18
				Description
				n of
				Defect :
				FUSE OR
				CIRCUIT
				BREAKERS
				BLOWN
				FOR
				CLEARENC
				E LIGHTS
				ON
				TRAILER.
				ALL
				OTHER
				LIGHTS
				WORKING
RPS21	719QWU	12051	09/28/2018 DEFECT	THOUGH

				Reported
				Defect :-
				Defect
				Code :
				00001065
				Defect
				Reference
				: W/O
				8771
				Date :
				15/03/20
				18
				Description of
				Defect :
				RHF
				SHOCKY
				NEEDS A
RPS21	719QWU	12051	09/28/2018 DEFECT	SLING.

				Reported
				Defect :-
				Defect
				Code :
				00001572
				Defect
				Reference
				:
				W/O1113
				4
				Date :
				30/07/20
				18
				Description of
				Defect :
				NEEDS
				SHOCKY
				SLING
				FRONT
				RIGHT
RPS21	719QWU	12051	09/28/2018 DEFECT	AXLE

RPS21	719QWU	12051	09/28/2018 TRA	1 LABOUR	Labour		0
RPS21	719QWU	12051	09/28/2018 TRA	0 LABOUR	MECH1	Labour - Internal	
RPS21	719QWU	12051	09/28/2018 TRA	16 CON		YAT Consumables	

				SERVICE COMPLET ED TIGHTENE D REAR AIR TANK BOLTS			
RPS21	719QWU	12051	09/28/2018 TRA				
RPS21	719QWU	15139	10/04/2018 BEARPK	0 LABOUR	MECH	Labour - Internal	
RPS21	719QWU	12152	10/04/2018 EXOINS	1 LABOUR	Labour		0
RPS21	719QWU	12152	10/04/2018 EXOINS	0 LABOUR	MECH1	Labour - Internal	
RPS21	719QWU	12152	10/04/2018 EXOINS	PASSED 1ST INSPECTION			
RPS21	719QWU	12151	10/04/2018 TRA	1 LABOUR	Labour		0
RPS21	719QWU	12151	10/04/2018 TRB	1 LABOUR	Labour		0
RPS21	719QWU	12151	10/04/2018 TRC	1 LABOUR	Labour		0
RPS21	719QWU	12151	10/04/2018 TRC	0 LABOUR	MECH1	Labour - Internal	
RPS21	719QWU	12151	10/04/2018 TRC	0 LABOUR	APPREN	Labour - Internal	
RPS21	719QWU	12151	10/04/2018 TRC	16 CON		YAT Consumables	

				SERVICE COMPLET ED FITTED WEIGHT GAUGE REPAIRED 2X GUARD BRACKETS RHS REPLACED GREASE IN WHEEL BEARINGS REPLACED SLEVE BETWEEN OIL SLINGS IN HUBS REPALCED 3M OF 1/2 INCH BRAKE HOSE				
RPS21	719QWU	12151	10/04/2018 TRC					
RPS21	719QWU	12151	10/04/2018 TRC	13 B310-30KG-PP	YAT	WEIGH GAUGE,TRI AXLE,W/LGE AIR BAG. PUSH/PULL SWITCH		
RPS21	719QWU	12518	10/24/2018 FRIVANA	1 LABEXT	RIXREF01	EX00006820	Labour External,RP21	
RPS21	719QWU	12518	10/24/2018 FRIVANA	1 SUND	RIXREF01	EX00006820	SUNDRIES,RP21	
				SERVICE COMPLET ED R&R ENGINE MOUNTS R&R DSICHARG E CLAMP				
RPS21	719QWU	12518	10/24/2018 FRIVANA					

RPS21	719QWU	12518	10/24/2018 FRIVANA	1 SUND	RIXREF01	18334	SUNDRIES,RP21
RPS21	719QWU	12518	10/24/2018 FRIVANA	1 LABEXT	RIXREF01	18334	Labour External,RP21
RPS21	719QWU	12655	10/24/2018 GEN	39 LABOUR	Labour		0
RPS21	719QWU	12655	10/24/2018 GEN	3 914159	YAT	VIBRATION ENGINE MOUNT FRIDGE SB310	
RPS21	719QWU	12655	10/24/2018 GEN	3 914159	YAT	VIBRATION ENGINE MOUNT FRIDGE SB310	
RPS21	719QWU	12655	10/24/2018 GEN	3 91-0372	YAT	CLAMP TUBE, FRIDGE MOTOR	
RPS21	719QWU	12655	10/24/2018 GEN	PARTS SUPPLIED BY EXODAS FOR SERVICING BY RIXON			
RPS21	719QWU	12627	10/29/2018 FRIVANA	1 LABEXT	RIXREF01	EX00006866	Labour External,RP21
RPS21	719QWU	12627	10/29/2018 FRIVANA	1 SUND	RIXREF01	EX00006866	SUNDRIES,RP21
RPS21	719QWU	12627	10/29/2018 FRIVANA	SERVICE COMPLETED			
RPS21	719QWU	12627	10/29/2018 FRIVANA	1 SUND	RIXREF01	18392	SUNDRIES,RP21
RPS21	719QWU	12627	10/29/2018 FRIVANA	1 LABEXT	RIXREF01	18392	Labour External,RP21
RPS21	719QWU	12733	11/01/2018 FRIVANA	1 PART	RIXREF01	EX00006921	ALTERNATOR BELT,RP21
RPS21	719QWU	12733	11/01/2018 FRIVANA	1 PART	RIXREF01	EX00006921	FAN ELT,RP21
RPS21	719QWU	12733	11/01/2018 FRIVANA	1 PART	RIXREF01	EX00006921	ENGINE BELT,RP21
RPS21	719QWU	12733	11/01/2018 FRIVANA	1 PART	RIXREF01	EX00006921	ALTERNATOR,RP21
RPS21	719QWU	12733	11/01/2018 FRIVANA	1 LABEXT	RIXREF01	EX00006921	Labour External,RP21
RPS21	719QWU	12733	11/01/2018 FRIVANA	1 SUND	RIXREF01	EX00006921	SUNDRIES,RP21
RPS21	719QWU	12733	11/01/2018 FRIVANA	1 SUND	RIXREF01	18408	SUNDRIES,RP21
RPS21	719QWU	12733	11/01/2018 FRIVANA	1 LABEXT	RIXREF01	18408	Labour External,RP21
RPS21	719QWU	12733	11/01/2018 FRIVANA	1 PART	RIXREF01	18408	ALTERNATOR,RP21
RPS21	719QWU	12733	11/01/2018 FRIVANA	1 PART	RIXREF01	18408	ENGINE BELT,RP21
RPS21	719QWU	12733	11/01/2018 FRIVANA	1 PART	RIXREF01	18408	FAN ELT,RP21
RPS21	719QWU	12733	11/01/2018 FRIVANA	1 PART	RIXREF01	18408	ALTERNATOR BELT,RP21
RPS21	719QWU	12724	11/02/2018 FRIVANA	1 914159	RIXREF01	EX00006916	VIBRATION ENGINE MOUNT FRIDGE SB310,RP21
RPS21	719QWU	12724	11/02/2018 FRIVANA	1 914043	RIXREF01	EX00006916	SNUBBER ENGINE MOUNT FRIDGE SB310,RP21
RPS21	719QWU	12724	11/02/2018 FRIVANA	1 LABEXT	RIXREF01	EX00006916	Labour External,RP21
RPS21	719QWU	12724	11/02/2018 FRIVANA	1 SUND	RIXREF01	EX00006916	SUNDRIES,RP21
RPS21	719QWU	12724	11/02/2018 FRIVANA	SERVICE COMPLET ED R&R ENGINE MOUNTS			
RPS21	719QWU	12724	11/02/2018 FRIVANA	1 SUND	RIXREF01	18413	SUNDRIES,RP21
RPS21	719QWU	12724	11/02/2018 FRIVANA	1 914043	RIXREF01	18413	SNUBBER ENGINE MOUNT FRIDGE SB310,RP21
RPS21	719QWU	12724	11/02/2018 FRIVANA	1 LABEXT	RIXREF01	18413	Labour External,RP21
RPS21	719QWU	12724	11/02/2018 FRIVANA	1 914159	RIXREF01	18413	VIBRATION ENGINE MOUNT FRIDGE SB310,RP21
RPS21	719QWU	13102	11/20/2018 FRIVANA	1 R404A	RIXREF01	EX00007118	GAS R404A,RP21
RPS21	719QWU	13102	11/20/2018 FRIVANA	1 LABEXT	RIXREF01	EX00007118	Labour External,RP21
RPS21	719QWU	13102	11/20/2018 FRIVANA	1 SUND	RIXREF01	EX00007118	SUNDRIES,RP21

				SERVICE COMPLET ED NOT COOLING PROPERLY - DIAGNOS ED GAS LEAK IN EVAPORA TOR REPAIRED GAS LEAK AT DISTRIBUT OR TUBES (SOLDER) REGASED 11KGS			
RPS21	719QWU	13102	11/20/2018 FRIVANA	11KGS			
RPS21	719QWU	13102	11/20/2018 FRIVANA	1 SUND	RIXREF01	18563	SUNDRIES,RP21
RPS21	719QWU	13102	11/20/2018 FRIVANA	1 LABEXT	RIXREF01	18563	Labour External,RP21
RPS21	719QWU	13102	11/20/2018 FRIVANA	1 R404A	RIXREF01	18563	GAS R404A,RP21
RPS21	719QWU	13216	11/26/2018 FRIVANA	1 LABEXT	RIXREF01	EX00007183	Labour External,RP21
RPS21	719QWU	13216	11/26/2018 FRIVANA	1 SUND	RIXREF01	EX00007183	SUNDRIES,RP21
RPS21	719QWU	13216	11/26/2018 FRIVANA	SERVICE COMPLETED			
RPS21	719QWU	13216	11/26/2018 FRIVANA	1 SUND	RIXREF01	18621	SUNDRIES,RP21
RPS21	719QWU	13216	11/26/2018 FRIVANA	1 LABEXT	RIXREF01	18621	Labour External,RP21
RPS21	719QWU	13246	11/27/2018 FRIVANA	1 LABEXT	RIXREF01	EX00007194	Labour External,RP21
RPS21	719QWU	13246	11/27/2018 FRIVANA	1 SUND	RIXREF01	EX00007194	SUNDRIES,RP21
				SERVICE COMPLET ED R&R HEAD GASKET KIT			
RPS21	719QWU	13246	11/27/2018 FRIVANA	KIT			
RPS21	719QWU	13246	11/27/2018 FRIVANA	11 300339	YAT	KIT HEAD GASKET REV5 TK486	
RPS21	719QWU	13246	11/27/2018 FRIVANA	1 LABEXT	RIXREF01	18624	Labour External,RP21
RPS21	719QWU	13246	11/27/2018 FRIVANA	1 SUND	RIXREF01	18624	SUNDRIES,RP21
RPS21	719QWU	13330	11/28/2018 FRIVANA	1 LABEXT	RIXREF01	EX00007255	Labour External,RP21
RPS21	719QWU	13330	11/28/2018 FRIVANA	1 SUND	RIXREF01	EX00007255	SUNDRIES,RP21
RPS21	719QWU	13330	11/28/2018 FRIVANA	SERVICE COMPLETED			

RPS21	719QWU	13330	11/28/2018 FRIVANA	1 SUND		RIXREF01	18630	SUNDRIES,RP21
RPS21	719QWU	13330	11/28/2018 FRIVANA	1 LABEXT		RIXREF01	18630	Labour External,RP21
RPS21	719QWU	13351	12/11/2018 DEFECT	1 LABOUR	MECH	Labour		

Reported
Defect :-
Defect
Code :
00001573
Defect
Reference
: 9815
Date :
30/07/20
18
Descriptio
n of
Defect :
METAL
STRAP
ANGING
DOWN
INSIDE
VAN
CHECKED
BUT
COULDN'T
FAULT

RPS21	719QWU	13351	12/11/2018 DEFECT
-------	--------	-------	-------------------

RPS21	719QWU	13351	12/11/2018 TRA	1 LABOUR	Labour			0
RPS21	719QWU	13351	12/11/2018 TRA	0 LABOUR	MECH1	Labour - Internal		
RPS21	719QWU	13351	12/11/2018 TRA	0 LABOUR	APPREN	Labour - Internal		
RPS21	719QWU	13351	12/11/2018 TRA	16 CON	YAT	Consumables		

				SERVICE COMPLET ED FIBER GLASS ON REAR OF TRAILER HAS HOLES IN IT ADJUSTED WHEEL BEARINGS AS REQUIRED				
RPS21	719QWU	13351	12/11/2018 TRA					
							Consuma bles ,RP21	
RPS21	719QWU	13451	12/12/2018 FRIVANA	1 CON	BRIVAL01	EX00007322		
RPS21	719QWU	13451	12/12/2018 FRIVANA	1 LABEXT	BRIVAL01	EX00007322	Labour External,RP21	
				UNIT NOT REACHIIN G SET POINT DOWNLO ADED FAULT TRACED TO PILOT SOLENOID CIRCUIT REPAIRED RUB IN HARNESS LUBRICAT ED DEFROST DAMPER BUSHES PASSED RE TRIP				
RPS21	719QWU	13451	12/12/2018 FRIVANA					

							Consumables,RP21
RPS21	719QWU	13451	12/12/2018 FRIVANA	1 CON	BRIVAL01	16	
RPS21	719QWU	13451	12/12/2018 FRIVANA	1 LABEXT	BRIVAL01	16	Labour External,RP21
RPS21	719QWU	13932	12/21/2018 FRIVANA	1 LABEXT	RIXREF01	EX00007573	Labour External,RP21
RPS21	719QWU	13932	12/21/2018 FRIVANA	1 SUND	RIXREF01	EX00007573	SUNDRIES,RP21
RPS21	719QWU	13932	12/21/2018 FRIVANA	1 PART	RIXREF01	EX00007573	HOT GAS VALVE KIT,RP21
				SERVICE COMPLETED R&R U/S HOT GAS VALVE KIT			
RPS21	719QWU	13932	12/21/2018 FRIVANA				
RPS21	719QWU	13932	12/21/2018 FRIVANA	1 PART	RIXREF01	18804	HOT GAS VALVE KIT,RP21
RPS21	719QWU	13932	12/21/2018 FRIVANA	1 SUND	RIXREF01	18804	SUNDRIES,RP21
RPS21	719QWU	13932	12/21/2018 FRIVANA	1 LABEXT	RIXREF01	18804	Labour External,RP21
RPS21	719QWU	13983	12/31/2018 FRIVANA	1 LABEXT	RIXREF01	EX00007587	Labour External,RP21
RPS21	719QWU	13983	12/31/2018 FRIVANA	1 SUND	RIXREF01	EX00007587	SUNDRIES,RP21
RPS21	719QWU	13983	12/31/2018 FRIVANA	SERVICE COMPLETED			
RPS21	719QWU	13983	12/31/2018 FRIVANA	1 SUND	RIXREF01	18851	SUNDRIES,RP21
RPS21	719QWU	13983	12/31/2018 FRIVANA	1 LABEXT	RIXREF01	18851	Labour External,RP21
RPS21	719QWU	14100	01/06/2019 FRIVANA	1 LABEXT	BRIVAL01	EX00007647	Labour External,RP21
							Consumables,RP21
RPS21	719QWU	14100	01/06/2019 FRIVANA	1 CON	BRIVAL01	EX00007647	
RPS21	719QWU	14100	01/06/2019 FRIVANA	SERVICE COMPLETED			
							Consumables,RP21
RPS21	719QWU	14100	01/06/2019 FRIVANA	1 CON	BRIVAL01	43	
RPS21	719QWU	14100	01/06/2019 FRIVANA	1 LABEXT	BRIVAL01	43	Labour External,RP21
RPS21	719QWU	13748	01/07/2019 GEN	39 LABOUR	Labour		0
RPS21	719QWU	13748	01/07/2019 GEN	0 LABOUR	APPREN		
RPS21	719QWU	13748	01/07/2019 GEN	16 CON	YAT	Consumables	
RPS21	719QWU	13748	01/07/2019 GEN	REPLACED 1.5M OF POGO RAIL			
RPS21	719QWU	13992	01/11/2019 FRIVANA	1 LABCON	BRIVAL01	EX00009447	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	13992	01/11/2019 FRIVANA	1 LABCON	BRIVAL01	EX00009476	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	13992	01/11/2019 FRIVANA	1 LABCON	BRIVAL01	310	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	13992	01/11/2019 FRIVANA	1 LABCON	BRIVAL01	450	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	13992	01/11/2019 FRIVANA	1 LABCON	BRIVAL01	EX00009562	LABOUR & CONSUMABLES,RP21

RPS21	719QWU	13992	01/11/2019 FRIVANA	1 LABCON	BRIVAL01	403	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	13992	01/11/2019 FRIVANA	1 LABCON	BRIVAL01	EX00010050	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	13992	01/11/2019 FRIVANA	1 LABCON	BRIVAL01	616	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	13992	01/11/2019 FRIVANA	1 LABCON	BRIVAL01	EX00010209	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	13992	01/11/2019 FRIVANA	1 LABCON	BRIVAL01	654	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	13992	01/11/2019 FRIVANA	1 LABCON	BRIVAL01	EX00010376	LABOUR & CONSUMABLES,RP21,28319
RPS21	719QWU	13992	01/11/2019 FRIVANA	1 LABCON	BRIVAL01	EX00010472	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	13992	01/11/2019 FRIVANA	1 LABCON	BRIVAL01	708	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	13992	01/11/2019 FRIVANA	1 LABCON	BRIVAL01	EX00010594	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	13992	01/11/2019 FRIVANA	1 LABCON	BRIVAL01	766	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	13992	01/11/2019 FRIVANA	1 LABCON	BRIVAL01	690	LABOUR & CONSUMABLES,RP21,28319
RPS21	719QWU	13992	01/11/2019 TYRES	15 77000180	BRIAUS01	EX00007591	CASE STOCK 11-22.5,RP21
RPS21	719QWU	13993	01/11/2019 TYRES	15 77000180	BRIAUS01	EX00007592	CASE STOCK 11-22.5,RP21
RPS21	719QWU	13993	01/11/2019 TYRES	15 11002822	YAT	11R2.5 148L 16 BS R168	
RPS21	719QWU	13993	01/11/2019 TYRES	R&R TYRES			
RPS21	719QWU	13993	01/11/2019 TYRES	15 77000180	BRIAUS01	96479401	CASE STOCK 11-22.5,RP21
RPS21	719QWU	14371	01/23/2019 FRIVANA	1 LABEXT	BRIVAL01	EX00007803	Labour External,RP21
RPS21	719QWU	14371	01/23/2019 FRIVANA	40 3413005	YAT	OIL 15W-40, CK 4/E9	
RPS21	719QWU	14371	01/23/2019 FRIVANA	SERVICE COMPLETED			
RPS21	719QWU	14371	01/23/2019 FRIVANA	1 LABEXT	BRIVAL01	69	Labour External,RP21
RPS21	719QWU	14384	01/23/2019 FRIVANSE	1 Nov-80	BRIVAL01	EX00007807	HAND PRIMER,RP21
RPS21	719QWU	14384	01/23/2019 FRIVANSE	1 CON	BRIVAL01	EX00007807	Consumables,RP21
RPS21	719QWU	14384	01/23/2019 FRIVANSE	1 LABEXT	BRIVAL01	EX00007807	Labour External,RP21
RPS21	719QWU	14384	01/23/2019 FRIVANSE	40 3413005	YAT	OIL 15W-40, CK 4/E9	
RPS21	719QWU	14384	01/23/2019 FRIVANSE	SERVICE COMPLETED REPALCED U/S HAND PRIMER CALIBRATED UNIT			
RPS21	719QWU	14384	01/23/2019 FRIVANSE	1 LABEXT	BRIVAL01	71	Labour External,RP21
RPS21	719QWU	14384	01/23/2019 FRIVANSE	1 CON	BRIVAL01	71	Consumables,RP21
RPS21	719QWU	14384	01/23/2019 FRIVANSE	1 Nov-80	BRIVAL01	71	HAND PRIMER,RP21
RPS21	719QWU	14526	01/23/2019 GEN	39 61-3401	BRIVAL01	EX00007902	HOT GAS VALVE,RP21
RPS21	719QWU	14526	01/23/2019 GEN	39 PART	BRIVAL01	EX00007902	BLUE TIP SILVER SOLDER,RP21

RPS21	719QWU	14526	01/23/2019 GEN	39 R404A	BRIVAL01	EX00007902	GAS R404A,RP21
RPS21	719QWU	14526	01/23/2019 GEN	39 LABEXT	BRIVAL01	EX00007902	Labour External,RP21
				FOUND UNIT NOT COOLING IN ZONE 2 TRACED TO HOT GAS VALVE - REPLACED			
RPS21	719QWU	14526	01/23/2019 GEN				
RPS21	719QWU	14526	01/23/2019 GEN	39 LABEXT	BRIVAL01	60	Labour External,RP21
RPS21	719QWU	14526	01/23/2019 GEN	39 R404A	BRIVAL01	60	GAS R404A,RP21
RPS21	719QWU	14526	01/23/2019 GEN	39 PART	BRIVAL01	60	BLUE TIP SILVER SOLDER,RP21
RPS21	719QWU	14526	01/23/2019 GEN	39 61-3401	BRIVAL01	60	HOT GAS VALVE,RP21
RPS21	719QWU	14174	01/24/2019 TRA	1 LABOUR	Labour		0
RPS21	719QWU	14174	01/24/2019 TRA	0 LABOUR	MECH1	Labour - Internal	
RPS21	719QWU	14174	01/24/2019 TRA	0 LABOUR	APPREN	Labour - Internal	
RPS21	719QWU	14174	01/24/2019 TRA	16 CON	YAT	Consumables	
RPS21	719QWU	14174	01/24/2019 TRA	SERVICE COMPLETED			
RPS21	719QWU	14563	01/28/2019 GEN	39 FILKIT	BRIVAL01	EX00007909	FILTER KIT FRIDGE,RP21
RPS21	719QWU	14563	01/28/2019 GEN	PART NO INCLUDED ON INVOICE	071 23.01.19 B	SERVICE FILTER KIT NOT CHARGED	
RPS21	719QWU	14563	01/28/2019 GEN	39 FILKIT	BRIVAL01	80	FILTER KIT FRIDGE,RP21
RPS21	719QWU	14630	01/30/2019 FRIVANA	1 LABCON	BRIVAL01	EX00007925	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	14630	01/30/2019 FRIVANA	SERVICE COMPLETED			
RPS21	719QWU	14630	01/30/2019 FRIVANA	1 LABCON	BRIVAL01	96	LABOUR & CONSUMABLES,RP21
							Consumables
RPS21	719QWU	14629	01/30/2019 GEN	39 CON	BRIVAL01	EX00007924	,RP21
RPS21	719QWU	14629	01/30/2019 GEN	39 LABEXT	BRIVAL01	EX00007924	Labour External,RP21
RPS21	719QWU	14629	01/30/2019 GEN	3 91-0372	YAT	CLAMP TUBE, FRIDGE MOTOR	
RPS21	719QWU	14629	01/30/2019 GEN	UNIT FAILED PRE TRIP - TRACED FAULT TO FUSE BLOWING ON CONTROLLER EACH TIME DEFROST IS EXITED - FOUND RUBBER POWER TO DAMPER SOLENOID - R			
							Consumables
RPS21	719QWU	14629	01/30/2019 GEN	39 CON	BRIVAL01	95	,RP21
RPS21	719QWU	14629	01/30/2019 GEN	39 LABEXT	BRIVAL01	95	Labour External,RP21
RPS21	719QWU	14797	02/22/2019 TRA	1 LABOUR	Labour		0
RPS21	719QWU	14797	02/22/2019 TRA	0 LABOUR	MECH1	Labour - Internal	
RPS21	719QWU	14797	02/22/2019 TRA	0 LABOUR	APPREN	Labour - Internal	
RPS21	719QWU	14797	02/22/2019 TRA	16 CON	YAT	Consumables	

				SERVICE COMPLET ED RERIVITED 2 SECTIONS OF POGO RAIL DONE PRE TRIP ON FRIDGE CAME UP CODE 29 ISSUE RESOLVED BY BVR BACK RHS AXLE INNER TYRE BALD, HAVE NOTIFIED DAVE				
RPS21	719QWU	14797	02/22/2019 TRA					
RPS21	719QWU	15203	03/05/2019 TYRES	15 77000180	BRIAUS01	EX00008256	CASE STOCK 11-22.5,RP21	
RPS21	719QWU	15203	03/05/2019 TYRES	15 11001464	YAT	TYRE 11R22.5 148/145L 16 BS R187		
RPS21	719QWU	15203	03/05/2019 TYRES	R&R TYRES PLUS ROTATION				
RPS21	719QWU	15203	03/05/2019 TYRES	15 77000180	BRIAUS01	96646751	CASE STOCK 11-22.5,RP21	
RPS21	719QWU	16045	03/14/2019 FRIVANA	1 LABCON	BRIVAL01	EX00008692	LABOUR & CONSUMABLES,RP21	
RPS21	719QWU	16045	03/14/2019 FRIVANA	SERVICE COMPLETED - 27,823 HOURS				
RPS21	719QWU	16045	03/14/2019 FRIVANA	1 LABCON	BRIVAL01	251	LABOUR & CONSUMABLES,RP21	
RPS21	719QWU	15764	03/20/2019 FRIVANA	1 LABCON	BRIVAL01	EX00008578	LABOUR & CONSUMABLES,RP21	
RPS21	719QWU	15764	03/20/2019 FRIVANA	SERVICE COMPLETED				
RPS21	719QWU	15764	03/20/2019 FRIVANA	1 LABCON	BRIVAL01	218	LABOUR & CONSUMABLES,RP21	
RPS21	719QWU	17385	04/10/2019 FRIVANA	SERVICE COMPLETED				
RPS21	719QWU	17263	04/22/2019 GEN	39 44-9298	BRIVAL01	EX00009385	RPM SENSOR, FRIDGE MOTOR,RP21 Consuma bles ,RP21	
RPS21	719QWU	17263	04/22/2019 GEN	39 CON	BRIVAL01	EX00009385		
RPS21	719QWU	17263	04/22/2019 GEN	39 LABEXT	BRIVAL01	EX00009385	Labour External,RP21	

				BVR - FOUND UNIT WITH CODE 7 RPM TRACED TO RPM SENSOR, R&R SENSOR				
RPS21	719QWU	17263	04/22/2019 GEN					
RPS21	719QWU	17263	04/22/2019 GEN	39 LABEXT	BRIVAL01	304	Labour External,RP21 Consumables ,RP21	
RPS21	719QWU	17263	04/22/2019 GEN	39 CON	BRIVAL01	304		
RPS21	719QWU	17263	04/22/2019 GEN	39 44-9298	BRIVAL01	304	RPM SENSOR, FRIDGE MOTOR,RP21	
RPS21	719QWU	16843	05/20/2019 DEFECT	1 LABOUR	MECH Labour			

				Reported Defect :- Defect Code : 00002113 Defect Reference : WO13351 Date : 11/12/20 18 Description of Defect : FIBER GLASS ON REAR OF TRAILER HAS HOLES IN IT NOT WORRIED ABOUT IT				
RPS21	719QWU	16843	05/20/2019 DEFECT					

RPS21	719QWU	16843	05/20/2019	DEFECT	REPAIRED
-------	--------	-------	------------	--------	----------

				Reported Defect :- Defect Code : 00002521 Defect Reference : 11809 Date : 01/05/20 19 Description n of Defect : RHS BACK GUARD RHS INSIDE FRONT WALL LOAD LOCKING RIPPED OUT REPAIRED
RPS21	719QWU	16843	05/20/2019 DEFECT	

RPS21	719QWU	16843	05/20/2019 TRA	1 LABOUR	Labour		0
RPS21	719QWU	16843	05/20/2019 TRB	1 LABOUR	Labour		0
RPS21	719QWU	16843	05/20/2019 TRB	0 LABOUR	APPREN	Labour - Internal	
RPS21	719QWU	16843	05/20/2019 TRB	0 LABOUR	MECH1	Labour - Internal	
RPS21	719QWU	16843	05/20/2019 TRB	13 2689 001 061	YAT	TRACK-F SERIES PER 5.8 MTR	
RPS21	719QWU	16843	05/20/2019 TRB	16 CON	YAT	Consumables	

				SERVICE COMPLET ED REPAIRED HOLE IN FRONT OF TRAILER FITTED 2.1M OF FTRACK TO FRONT RIGHT REPLACED FRONT BOTTOM MARKER LIGHT REPLACED 6 BPW AIR BAGS REPLACED RIGHT REAR GUARD WITH 2ND HAND ONE				
RPS21	719QWU	16843	05/20/2019 TRB					
RPS21	719QWU	16843	05/20/2019 TRB	10 5.43E+08	YAT	Airbag Bellow (BPW)		
RPS21	719QWU	17697	05/21/2019 FRIVANA	SERVICE COMPLETED				
RPS21	719QWU	16918	05/21/2019 TYRES	15 77000180	BRIAUS01	EX00009164	CASE STOCK 11-22.5,RP21	
RPS21	719QWU	16918	05/21/2019 TYRES	15 11001464	YAT	TYRE 11R22.5 148/145L 16 BS R187		
RPS21	719QWU	16918	05/21/2019 TYRES	R&R TYRES POS 21,22				
RPS21	719QWU	16918	05/21/2019 TYRES	15 77000180	BRIAUS01	96884151	CASE STOCK 11-22.5,RP21	
RPS21	719QWU	17625	05/26/2019 GEN	39 78-603	BRIVAL01	EX00009558	SB Fridge Fan belt,RP21	
							Consuma	
							bles	
RPS21	719QWU	17625	05/26/2019 GEN	39 CON	BRIVAL01	EX00009558	,RP21	
RPS21	719QWU	17625	05/26/2019 GEN	39 LABEXT	BRIVAL01	EX00009558	Labour External,RP21	

				BVR - REPLACED U/S CONDENS ER BELT ACID CLEAN EVAP & COND COILS			
RPS21	719QWU	17625	05/26/2019 GEN				
RPS21	719QWU	17625	05/26/2019 GEN	39 LABEXT	BRIVAL01	399	Labour External,RP21 Consumables ,RP21
RPS21	719QWU	17625	05/26/2019 GEN	39 CON	BRIVAL01	399	
RPS21	719QWU	17625	05/26/2019 GEN	39 78-603	BRIVAL01	399	SB Fridge Fan belt,RP21
RPS21	719QWU	17483	06/03/2019 FRIVANA	SERVICE COMPLETED			
RPS21	719QWU	17290	06/06/2019 FRIVANSE	1 FILKIT	BRIVAL01	EX00009401	FILTER KIT FRIDGE,RP21
RPS21	719QWU	17290	06/06/2019 FRIVANSE	1 Nov-80	BRIVAL01	EX00009401	HAND PRIMER,RP21 Consumables ,RP21
RPS21	719QWU	17290	06/06/2019 FRIVANSE	1 CON	BRIVAL01	EX00009401	
RPS21	719QWU	17290	06/06/2019 FRIVANSE	1 LABEXT	BRIVAL01	EX00009401	Labour External,RP21
				SERVICE COMPLET ED REPLACED U/S HAND PRIMER, CALIBRAT ED UNIT			
RPS21	719QWU	17290	06/06/2019 FRIVANSE				
RPS21	719QWU	17290	06/06/2019 FRIVANSE	1 LABEXT	BRIVAL01	445	Labour External,RP21 Consumables ,RP21
RPS21	719QWU	17290	06/06/2019 FRIVANSE	1 CON	BRIVAL01	445	
RPS21	719QWU	17290	06/06/2019 FRIVANSE	1 Nov-80	BRIVAL01	445	HAND PRIMER,RP21
RPS21	719QWU	17290	06/06/2019 FRIVANSE	1 FILKIT	BRIVAL01	445	FILTER KIT FRIDGE,RP21
RPS21	719QWU	18580	07/23/2019 DEFECT	1 LABOUR MECH	Labour		

RPS21	719QWU	18580	07/23/2019 DEFECT	Reported Defect :- Defect Code : 00002573 Defect Reference : 06644 Date : 26/05/20 19 Descriptio n of Defect : VERY NOISY BRAKES ADJUSTED & COULDN'T FAULT
-------	--------	-------	-------------------	--

RPS21	719QWU	18580	07/23/2019 DEFECT	Reported Defect :- Defect Code : 00002572 Defect Reference : 06645 Date : 26/05/20 19 Descriptio n of Defect : FAULTY TEMP SENSOR NO CODE ACTIVE
-------	--------	-------	-------------------	--

RPS21	719QWU	18826	07/23/2019 FRIVANA	SERVICE COMPLETED				
RPS21	719QWU	18580	07/23/2019 TRA	1 LABOUR	Labour		0	
RPS21	719QWU	18580	07/23/2019 TRA	0 LABOUR	MECH1	Labour - Internal		
RPS21	719QWU	18580	07/23/2019 TRA	0 LABOUR	APPREN	Labour - Internal		
RPS21	719QWU	18580	07/23/2019 TRA	16 CON		YAT Consumables		
				SERVICE COMPLET ED FITTED FIRE EXTINGUI SHER AS REQUIRED				
RPS21	719QWU	18580	07/23/2019 TRA					
RPS21	719QWU	18852	07/24/2019 FRIVANA	1 LABCON	BRIVAL01	EX00010048	LABOUR & CONSUMABLES,RP21	
RPS21	719QWU	18852	07/24/2019 FRIVANA	SERVICE COMPLETED				
RPS21	719QWU	18852	07/24/2019 FRIVANA	1 LABCON	BRIVAL01	615	LABOUR & CONSUMABLES,RP21	
RPS21	719QWU	18947	07/29/2019 FRIVANSE	1 LABEXT	BRIVAL01	EX00010119	Labour External,RP21	
RPS21	719QWU	18947	07/29/2019 FRIVANSE	1 FILKIT	BRIVAL01	EX00010119	FILTER KIT FRIDGE,RP21	
							Consuma bles ,RP21	
RPS21	719QWU	18947	07/29/2019 FRIVANSE	1 CON	BRIVAL01	EX00010119		
				BVR - SERVICE COMPLET ED CALIBRAT ED UNIT				
RPS21	719QWU	18947	07/29/2019 FRIVANSE					
RPS21	719QWU	18947	07/29/2019 FRIVANSE	40 3413005	YAT	OIL 15W-40, CK 4/E9		
							Consuma bles ,RP21	
RPS21	719QWU	18947	07/29/2019 FRIVANSE	1 CON	BRIVAL01	621		
RPS21	719QWU	18947	07/29/2019 FRIVANSE	1 FILKIT	BRIVAL01	621	FILTER KIT FRIDGE,RP21	
RPS21	719QWU	18947	07/29/2019 FRIVANSE	1 LABEXT	BRIVAL01	621	Labour External,RP21	
RPS21	719QWU	19216	08/06/2019 FRIVANA	SERVICE COMPLETED				
RPS21	719QWU	19316	08/09/2019 GEN	39 LABEXT	BRIVAL01	EX00010247	Labour External,RP21 CREDIT	
RPS21	719QWU	19316	08/09/2019 GEN	39 FILKIT	BRIVAL01	EX00010247	FILTER KIT FRIDGE,RP21 CREDIT	

RPS21	719QWU	19316	08/09/2019 GEN	39 CON	BRIVAL01	EX00010247	Consumables,RP21 CREDIT
RPS21	719QWU	19316	08/09/2019 GEN	CREDIT FOR DOUBLED UP WORK INV 621			Consumables,RP21 CREDIT
RPS21	719QWU	19316	08/09/2019 GEN	39 CON	BRIVAL01	663	Consumables,RP21 CREDIT
RPS21	719QWU	19316	08/09/2019 GEN	39 FILKIT	BRIVAL01	663	FILTER KIT FRIDGE,RP21 CREDIT
RPS21	719QWU	19316	08/09/2019 GEN	39 LABEXT	BRIVAL01	663	Labour External,RP21 CREDIT
RPS21	719QWU	19538	08/13/2019 FRIVANA	SERVICE COMPLETED			
RPS21	719QWU	22056	08/19/2019 GEN	39 LAB	TRASAL01	EX00011520	Labour,RP21
RPS21	719QWU	22056	08/19/2019 GEN	39 STEEL	TRASAL01	EX00011520	STEEL MATERIALS,RP21
RPS21	719QWU	22056	08/19/2019 GEN	39 WI97965	TRASAL01	EX00011520	SIKAFLEX 221 GREY 600G,RP21
RPS21	719QWU	22056	08/19/2019 GEN	39 WZ0412	TRASAL01	EX00011520	1/4 MAGNABULB,RP21
RPS21	719QWU	22056	08/19/2019 GEN	39 WI97964	TRASAL01	EX00011520	SIKAFLEX 221 WHITE 600G,RP21
RPS21	719QWU	22056	08/19/2019 GEN	39 WG0210	TRASAL01	EX00011520	LAMINATING RESIN SUMMER/WINTER,RP21
RPS21	719QWU	22056	08/19/2019 GEN	39 WG1945	TRASAL01	EX00011520	CHOPPEDSTRAND MATTING 450 CSM,RP21
RPS21	719QWU	22056	08/19/2019 GEN	39 WK4012	TRASAL01	EX00011520	FOAM 40MM,RP21
RPS21	719QWU	22056	08/19/2019 GEN	39 WIP0070	TRASAL01	EX00011520	ADHESIVE PLEXUS MA425 380ML,RP21
RPS21	719QWU	22056	08/19/2019 GEN	39 WIP0071	TRASAL01	EX00011520	PLEXUS CARTRIDGE NOZZLE 10:1,RP21
RPS21	719QWU	22056	08/19/2019 GEN	39 WZ0412	TRASAL01	EX00011520	1/4 MAGNABULB,RP21
RPS21	719QWU	22056	08/19/2019 GEN	39 W01661-	TRASAL01	EX00011520	3/16 AVDEL RIVET,RP21
RPS21	719QWU	22056	08/19/2019 GEN	39 FQ0309	TRASAL01	EX00011520	END CASTING F TRACK SHORT STYLE,RP21
RPS21	719QWU	22056	08/19/2019 GEN	39 WIP1590	TRASAL01	EX00011520	STRAIGHT WHITE,RP21
RPS21	719QWU	22056	08/19/2019 GEN	39 WIP1591	TRASAL01	EX00011520	STRAIGHT WHITE HARDENER,RP21
RPS21	719QWU	22056	08/19/2019 GEN	39 WIP0101	TRASAL01	EX00011520	2K GP THINNERS,RP21
RPS21	719QWU	22056	08/19/2019 GEN	39 WIP9003	TRASAL01	EX00011520	ETCH PRIMER,RP21
RPS21	719QWU	22056	08/19/2019 GEN	39 ENVLEV	TRASAL01	EX00011520	ENVIRONMENTAL LEVY,RP21
RPS21	719QWU	22056	08/19/2019 GEN	39 CON	TRASAL01	EX00011520	Consumables,RP21

				AND REPLACE VERTICAL REAR FRAME FLANGE REMOVE AND RE FIT D/L TRACK REMOVE AND RE FIT F TRACK CUT OUT AND REBUILD REAR OF L/H SIDE WALL STRAIGHT EN L/H VERTICAL REAR FRAME POST REPLACE			
RPS21	719QWU	22056	08/19/2019 GEN				
RPS21	719QWU	22056	08/19/2019 GEN	39 LAB	TRASAL01	614326	Labour,RP21
RPS21	719QWU	22056	08/19/2019 GEN	39 STEEL	TRASAL01	614326	STEEL MATERIALS,RP21
RPS21	719QWU	22056	08/19/2019 GEN	39 WI97965	TRASAL01	614326	SIKAFLEX 221 GREY 600G,RP21
RPS21	719QWU	22056	08/19/2019 GEN	39 WZ0412	TRASAL01	614326	1/4 MAGNABULB,RP21
RPS21	719QWU	22056	08/19/2019 GEN	39 WI97964	TRASAL01	614326	SIKAFLEX 221 WHITE 600G,RP21
RPS21	719QWU	22056	08/19/2019 GEN	39 WG0210	TRASAL01	614326	LAMINATING RESIN SUMMER/WINTER,RP21
RPS21	719QWU	22056	08/19/2019 GEN	39 WG1945	TRASAL01	614326	CHOPPEDSTRAND MATTING 450 CSM,RP21
RPS21	719QWU	22056	08/19/2019 GEN	39 WK4012	TRASAL01	614326	FOAM 40MM,RP21
RPS21	719QWU	22056	08/19/2019 GEN	39 WIP0070	TRASAL01	614326	ADHESIVE PLEXUS MA425 380ML,RP21
RPS21	719QWU	22056	08/19/2019 GEN	39 WIP0071	TRASAL01	614326	PLEXUS CARTRIDGE NOZZLE 10:1,RP21

RPS21	719QWU	22056	08/19/2019 GEN	39 WZ0412	TRASAL01	614326	1/4 MAGNABULB,RP21
RPS21	719QWU	22056	08/19/2019 GEN	39 W01661-	TRASAL01	614326	3/16 AVDEL RIVET,RP21
RPS21	719QWU	22056	08/19/2019 GEN	39 FQ0309	TRASAL01	614326	END CASTING F TRACK SHORT STYLE,RP21
RPS21	719QWU	22056	08/19/2019 GEN	39 WIP1590	TRASAL01	614326	STRAIGHT WHITE,RP21
RPS21	719QWU	22056	08/19/2019 GEN	39 WIP1591	TRASAL01	614326	STRAIGHT WHITE HARDENER,RP21
RPS21	719QWU	22056	08/19/2019 GEN	39 WIP0101	TRASAL01	614326	2K GP THINNERS,RP21
RPS21	719QWU	22056	08/19/2019 GEN	39 WIP9003	TRASAL01	614326	ETCH PRIMER,RP21
RPS21	719QWU	22056	08/19/2019 GEN	39 ENVLEV	TRASAL01	614326	ENVIRONMENTAL LEVY,RP21
RPS21	719QWU	22056	08/19/2019 GEN	39 CON	TRASAL01	614326	Consumables,RP21
RPS21	719QWU	19743	08/21/2019 FRIVANA	SERVICE COMPLETED			
RPS21	719QWU	19688	08/26/2019 GEN	39 LABEXT	BRIVAL01	EX00010440	Labour External,RP21
RPS21	719QWU	19688	08/26/2019 GEN	39 78-1360	BRIVAL01	EX00010440	ALTERNATOR BELT FRIDGE,RP21
RPS21	719QWU	19688	08/26/2019 GEN	39 CON	BRIVAL01	EX00010440	Consumables,RP21
RPS21	719QWU	19688	08/26/2019 GEN	BVR - R&R U/S ALTERNATOR BELT, CLEANED SURFACE RUST OFF PULLEYS, SECURED LOOSE PANELS			
RPS21	719QWU	19688	08/26/2019 GEN	39 CON	BRIVAL01	712	Consumables,RP21
RPS21	719QWU	19688	08/26/2019 GEN	39 78-1360	BRIVAL01	712	ALTERNATOR BELT FRIDGE,RP21
RPS21	719QWU	19688	08/26/2019 GEN	39 LABEXT	BRIVAL01	712	Labour External,RP21
RPS21	719QWU	20025	08/30/2019 FRIVANA	SERVICE COMPLETED			
RPS21	719QWU	19897	08/30/2019 GEN	39 LABEXT	BRIVAL01	EX00010561	Labour External,RP21
RPS21	719QWU	19897	08/30/2019 GEN	39 CON	BRIVAL01	EX00010561	Consumables,RP21
RPS21	719QWU	19897	08/30/2019 GEN	39 92-0374	BRIVAL01	EX00010561	SLAM LATCH FRIDGE,RP21
RPS21	719QWU	19897	08/30/2019 GEN	BVR - REPLACED U/S LATCHES			
RPS21	719QWU	19897	08/30/2019 GEN	39 92-0374	BRIVAL01	778	SLAM LATCH FRIDGE,RP21
RPS21	719QWU	19897	08/30/2019 GEN	39 CON	BRIVAL01	778	Consumables,RP21
RPS21	719QWU	19897	08/30/2019 GEN	39 LABEXT	BRIVAL01	778	Labour External,RP21
RPS21	719QWU	19870	09/04/2019 TRA	1 LABOUR	Labour		0
RPS21	719QWU	19870	09/04/2019 TRA	0 LABOUR	MECH1	Labour - Internal	
RPS21	719QWU	19870	09/04/2019 TRA	0 LABOUR	APPREN	Labour - Internal	
RPS21	719QWU	19870	09/04/2019 TRA	13 2689 001 061	YAT	TRACK-F SERIES PER 5.8 MTR	
RPS21	719QWU	19870	09/04/2019 TRA	16 CON	YAT	Consumables	

RPS21	719QWU	19870	09/04/2019 TRA	SERVICE COMPLET ED REPLACED POGO RAIL TOP LEFT RAIL INSIDE VAN					
RPS21	719QWU	20401	09/21/2019 GEN	39 LABOUR	Labour				0
RPS21	719QWU	20401	09/21/2019 GEN	0 LABOUR	MECH1	Labour - Internal			
RPS21	719QWU	20401	09/21/2019 GEN	13 MG630-R		YAT	MUDGUARD RED		
RPS21	719QWU	20401	09/21/2019 GEN	16 CON		YAT	Consumables		

RPS21	719QWU	20401	09/21/2019 GEN	SERVICE COMPLET ED FITTED NEW GUARD AS REQUIRED , REPLACED 2 x MUDGUA RD BRACKETS (2ND HAND) HAD TO STRAIGHT EN SHAZZY WHERE MUDGUA RD POLE BOLTS TO AS IT WAS BENT					
RPS21	719QWU	20959	09/30/2019 FRIVANA	1 LABCON		BRIVAL01	EX00011120	LABOUR & CONSUMABLES,RP21	
RPS21	719QWU	20959	09/30/2019 FRIVANA	SERVICE COMPLETED BVR 30.09.2019					
RPS21	719QWU	20959	09/30/2019 FRIVANA	1 LABCON		BRIVAL01	938	LABOUR & CONSUMABLES,RP21	
RPS21	719QWU	20951	10/16/2019 TRA	1 LABOUR	Labour			0	
RPS21	719QWU	20951	10/16/2019 TRA	0 LABOUR	MECH1	Labour - Internal			

RPS21	719QWU	20951	10/16/2019 TRA	16 CON	YAT	Consumables	
RPS21	719QWU	20951	10/16/2019 TRA	SERVICE COMPLETED			
RPS21	719QWU	21192	10/16/2019 TYRES	15 77000180	BRIAUS01	EX00011226	CASE STOCK 11-22.5,RP21
RPS21	719QWU	21192	10/16/2019 TYRES	15 11001464	YAT	TYRE 11R22.5 148/145L 16 BS R187	
RPS21	719QWU	21192	10/16/2019 TYRES	15 33000084	YAT	FIT TBR TYRE	
RPS21	719QWU	21192	10/16/2019 TYRES	R&R TYRES 29,30			
RPS21	719QWU	21192	10/16/2019 TYRES	15 77000180	BRIAUS01	97448413	CASE STOCK 11-22.5,RP21
RPS21	719QWU	21483	10/17/2019 GEN	39 LABEXT	BRIVAL01	EX00011279	Labour External,RP21
							Consumables,RP21
RPS21	719QWU	21483	10/17/2019 GEN	39 CON	BRIVAL01	EX00011279	
RPS21	719QWU	21483	10/17/2019 GEN	39 914043	BRIVAL01	EX00011279	SNUBBER ENGINE MOUNT FRIDGE SB310,RP21
RPS21	719QWU	21483	10/17/2019 GEN	39 914159	BRIVAL01	EX00011279	VIBRATION ENGINE MOUNT FRIDGE SB310,RP21
RPS21	719QWU	21483	10/17/2019 GEN	39 917709	BRIVAL01	EX00011279	ISOLATOR ENGINE MOUNT FRIDGE SB310,RP21
RPS21	719QWU	21483	10/17/2019 GEN	BVR - R&R WORN ENGINE MOUNTS, PASSED PRETRIP			
RPS21	719QWU	21483	10/17/2019 GEN	39 917709	BRIVAL01	1026	ISOLATOR ENGINE MOUNT FRIDGE SB310,RP21
RPS21	719QWU	21483	10/17/2019 GEN	39 914159	BRIVAL01	1026	VIBRATION ENGINE MOUNT FRIDGE SB310,RP21
RPS21	719QWU	21483	10/17/2019 GEN	39 914043	BRIVAL01	1026	SNUBBER ENGINE MOUNT FRIDGE SB310,RP21
							Consumables,RP21
RPS21	719QWU	21483	10/17/2019 GEN	39 CON	BRIVAL01	1026	
RPS21	719QWU	21483	10/17/2019 GEN	39 LABEXT	BRIVAL01	1026	Labour External,RP21
RPS21	719QWU	21078	10/18/2019 FRIVANA	1 LABCON	BRIVAL01	EX00011157	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	21078	10/18/2019 FRIVANA	SERVICE COMPLETED BVR 16.10.2019			
RPS21	719QWU	21078	10/18/2019 FRIVANA	1 LABCON	BRIVAL01	1031	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	21340	10/22/2019 FRIVANA	1 LABCON	BRIVAL01	EX00011267	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	21340	10/22/2019 FRIVANA	SERVICE COMPLETED BVR 21.10.2019			
RPS21	719QWU	21340	10/22/2019 FRIVANA	1 LABCON	BRIVAL01	1043	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	21532	10/23/2019 FRIVANA	1 LABCON	BRIVAL01	EX00011319	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	21532	10/23/2019 FRIVANA	SERVICE COMPLETED BVR 22.10.2019			
RPS21	719QWU	21532	10/23/2019 FRIVANA	1 LABCON	BRIVAL01	1054	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	22810	10/25/2019 FRIVANA	1 LABCON	BRIVAL01	EX00011828	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	22810	10/25/2019 FRIVANA	SERVICE COMPLETED BVR 23.10.2019			
RPS21	719QWU	22810	10/25/2019 FRIVANA	1 LABCON	BRIVAL01	1057	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	21588	10/25/2019 WEICAL	0 LABOUR Labour			0

				AIR GAUGE - 20.00 ADJUSTED - NA WEIGHBRI DGE - NA NOT CORRECT					
RPS21	719QWU	21588	10/25/2019 WEICAL						
RPS21	719QWU	21752	10/31/2019 EXOINS	1 LABOUR	Labour			0	
RPS21	719QWU	21752	10/31/2019 EXOINS	0 LABOUR	MECH1	Labour - Internal			
RPS21	719QWU	21752	10/31/2019 EXOINS	PASSED 1ST INSPECTION					
RPS21	719QWU	22826	10/31/2019 FRIVANA	1 LABCON	BRIVAL01	EX00011829		LABOUR & CONSUMABLES,RP21	
RPS21	719QWU	22826	10/31/2019 FRIVANA	SERVICE COMPLETED BVR 31.10.2019					
RPS21	719QWU	22826	10/31/2019 FRIVANA	1 LABCON	BRIVAL01	1101		LABOUR & CONSUMABLES,RP21	
RPS21	719QWU	21751	10/31/2019 TRA	1 LABOUR	Labour			0	
RPS21	719QWU	21751	10/31/2019 TRB	1 LABOUR	Labour			0	
RPS21	719QWU	21751	10/31/2019 TRC	1 LABOUR	Labour			0	
RPS21	719QWU	21751	10/31/2019 TRC	0 LABOUR	MECH1	Labour - Internal			
RPS21	719QWU	21751	10/31/2019 TRC	16 CON	YAT	Consumables			
				SERVICE COMPLET ED ADJUST ALL WHEEL BEARINGS , U-BOLTS, SHOCKS, KING PIN					
RPS21	719QWU	21751	10/31/2019 TRC						
RPS21	719QWU	22192	11/07/2019 WEICAL	0 LABOUR	Labour			0	

				AIR GAUGE: 16.000 ADJUSTED :16.750 WEIGHBRI DGE:16.35 0			
				CALIBRATI ON COMPLET ED CORRECTL Y			
RPS21	719QWU	22192	11/07/2019 WEICAL				
RPS21	719QWU	22454	11/12/2019 FRIVANA	1 LABCON	BRIVAL01	EX00011674	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	22454	11/12/2019 FRIVANA	SERVICE COMPLETED BVR 07.11.2019			
RPS21	719QWU	22454	11/12/2019 FRIVANA	1 LABCON	BRIVAL01	1154	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	23291	11/22/2019 FVPRE	1 LABCON	BRIVAL01	EX00012061	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	23291	11/22/2019 FVPRE	SERVICE COMPLETED BY BVR 15.11.2019			
RPS21	719QWU	23291	11/22/2019 FVPRE	1 LABCON	BRIVAL01	1212	LABOUR & CONSUMABLES,RP21
				FRIDGE VAN PRE- CHECK COMPLET ED			
				PRE- CHECK COMPLET ED BY BVR			
RPS21	719QWU	23323	11/26/2019 FVPRE	.			
RPS21	719QWU	23674	11/26/2019 TRB	B SERVICE			
RPS21	719QWU	23696	11/26/2019 TRB	1 LAB	BRIVAL01	EX00012281	Labour,RP21
RPS21	719QWU	23696	11/26/2019 TRB	1 LABCON	BRIVAL01	EX00012281	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	23696	11/26/2019 TRB	1 FILKIT	BRIVAL01	EX00012281	FILTER KIT FRIDGE,RP21
RPS21	719QWU	23696	11/26/2019 TRB	1 FILKIT	BRIVAL01	1227	FILTER KIT FRIDGE,RP21
RPS21	719QWU	23696	11/26/2019 TRB	1 LABCON	BRIVAL01	1227	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	23696	11/26/2019 TRB	1 LAB	BRIVAL01	1227	Labour,RP21
RPS21	719QWU	23236	12/20/2019 DEFECT	1 LABOUR	MECH	Labour	

Defect :-
Defect
Code :
00003406
Defect
Reference
: 05214
Date :
11/12/20
19
Description
of
Defect :
LEGS
BENT &
NOT
GOING
INTO
GEAR
PROPERLY
.

DEFECT
CLEARED
BY BEN
20.12.19 -
WORK

RPS21

719QWU

23236

12/20/2019 DEFECT

RPS21

719QWU

23236

12/20/2019 TRA

1 LABOUR Labour

0

				SERVICE COMPLET ED BEN / BILLY 20.12.19				
				REPLACED F TRACK / POGO RAILS IN SIDE VAN AS REQUIRED A SERVICE COMPLET ED				
RPS21	719QWU	23236	12/20/2019 TRA					
RPS21	719QWU	23236	12/20/2019 TRA	0 LABOUR	MECH1	Labour - Internal		
RPS21	719QWU	23236	12/20/2019 TRA	0 LABOUR	MECH1	Labour - Internal		
RPS21	719QWU	23236	12/20/2019 TRA	16 CON		YAT Consumables		
RPS21	719QWU	23715	01/08/2020 GEN	15 33000517		BRI AUS01	EX00012310	RP21,REMOVAL: CUSTOMER PULL POINT
RPS21	719QWU	23715	01/08/2020 GEN	15 33000085		BRI AUS01	EX00012310	RP21,ROTATE TBR TYRE
RPS21	719QWU	23715	01/08/2020 GEN	15 77000180		BRI AUS01	EX00012310	RP21,CASE STOCK 11-22.5
RPS21	719QWU	23715	01/08/2020 GEN	15 11001464		BRI AUS01	EX00012310	RP21,TYRE 11R22.5 148/145L 16 BS R187
RPS21	719QWU	23715	01/08/2020 GEN	15 33000084		BRI AUS01	EX00012310	RP21,FIT TBR TYRE
				COMPLET ED BY BRIDGEST ONE 08.01.202 0 INVOICE # 97879589				
RPS21	719QWU	23715	01/08/2020 GEN					
RPS21	719QWU	23715	01/08/2020 GEN	15 33000084		BRI AUS01	97879589	RP21,FIT TBR TYRE
RPS21	719QWU	23715	01/08/2020 GEN	15 11001464		BRI AUS01	97879589	RP21,TYRE 11R22.5 148/145L 16 BS R187
RPS21	719QWU	23715	01/08/2020 GEN	15 77000180		BRI AUS01	97879589	RP21,CASE STOCK 11-22.5
RPS21	719QWU	23715	01/08/2020 GEN	15 33000085		BRI AUS01	97879589	RP21,ROTATE TBR TYRE
RPS21	719QWU	23715	01/08/2020 GEN	15 33000517		BRI AUS01	97879589	RP21,REMOVAL: CUSTOMER PULL POINT

RPS21	719QWU	24224	01/30/2020 FVGEN	13 78-603	BRIVAL01	EX00012670	RP21,SB Fridge Fan belt
RPS21	719QWU	24224	01/30/2020 FVGEN	13 78-629	BRIVAL01	EX00012670	RP21,BELT
RPS21	719QWU	24224	01/30/2020 FVGEN	13 78-1360	BRIVAL01	EX00012670	RP21,ALTERNATOR BELT FRIDGE
RPS21	719QWU	24224	01/30/2020 FVGEN	16 CON	BRIVAL01	EX00012670	RP21,
RPS21	719QWU	24224	01/30/2020 FVGEN	13 LABEXT	BRIVAL01	EX00012670	RP21,

COMPLET
ED BY BVR
30.01.202
0
INVOICE #
00001542

REPLACED
UNSERVIC
EABLE
BELTS
UNIT RUN
ON TEST
PRETRIP
PASSED

RPS21	719QWU	24224	01/30/2020 FVGEN
-------	--------	-------	------------------

RPS21	719QWU	24224	01/30/2020 FVGEN	13 LABEXT	BRIVAL01	1542	RP21,
RPS21	719QWU	24224	01/30/2020 FVGEN	16 CON	BRIVAL01	1542	RP21,
RPS21	719QWU	24224	01/30/2020 FVGEN	13 78-1360	BRIVAL01	1542	RP21,ALTERNATOR BELT FRIDGE
RPS21	719QWU	24224	01/30/2020 FVGEN	13 78-629	BRIVAL01	1542	RP21,BELT
RPS21	719QWU	24224	01/30/2020 FVGEN	13 78-603	BRIVAL01	1542	RP21,SB Fridge Fan belt
RPS21	719QWU	24232	01/31/2020 TRA	1 LABOUR	Labour		0

REPLACED
FIRE
EXTINGUI
SHER
REPLACED
REAR
REFLECTIV
E SIGNS

RPS21	719QWU	24232	01/31/2020 TRA
RPS21	719QWU	24232	01/31/2020 TRA
RPS21	719QWU	24232	01/31/2020 TRA
RPS21	719QWU	24232	01/31/2020 TRA
RPS21	719QWU	24232	01/31/2020 TRA
RPS21	719QWU	25268	02/05/2020 FVPR
RPS21	719QWU	25268	02/05/2020 FVPR
RPS21	719QWU	25268	02/05/2020 FVPR
RPS21	719QWU	24517	02/12/2020 FVGI
RPS21	719QWU	24517	02/12/2020 FVGI
RPS21	719QWU	24517	02/12/2020 FVGI

0 LABOUR	MECH1	Labour - Internal	
0 LABOUR	MECH	Labour - Internal	
16 CON		YAT	Consumables
13	1808	YAT	PLATE MARKER
13	1806	YAT	PLATE MARKER
1 LABCON		BRIVAL01	EX00013225
SERVICE COMPLETED BY BVR 29.01.2020			
1 LABCON		BRIVAL01	1563
13 78-1362		BRIVAL01	EX00012833
16 CON		BRIVAL01	EX00012833
13 LABEXT		BRIVAL01	EX00012833

LABOUR & CONSUMABLES,RP21
LABOUR & CONSUMABLES,RP21
RP21,EVAPORTAOR FAN
RP21,
RP21,

				COMPLET ED BY BVR 12.02.202 0 INVOICE # 00001608
				UNIT FOUND WITH CODE 112 TRACED TO ZONE 2 FAULTY EVAP FAN 3 REMOVED AND REPLACED UNIT RUN ON TEST PRETRIP PASSED
RPS21	719QWU	24517	02/12/2020 FVGEN	

RPS21	719QWU	24517	02/12/2020 FVGEN	13 LABEXT	BRIVAL01	1608	RP21,
RPS21	719QWU	24517	02/12/2020 FVGEN	16 CON	BRIVAL01	1608	RP21,
RPS21	719QWU	24517	02/12/2020 FVGEN	13 78-1362	BRIVAL01	1608	RP21,EVAPORTAOR FAN
RPS21	719QWU	25146	02/13/2020 FVPRE	1 LABCON	BRIVAL01	EX00013196	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	25537	02/13/2020 FVPRE	1 LABCON	BRIVAL01	EX00013331	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	25146	02/13/2020 FVPRE	SERVICE COMPLETED BY BVR 10.02.2020			
RPS21	719QWU	25537	02/13/2020 FVPRE	SERVICE COMPLETED BY BVR 10.02.2020			
RPS21	719QWU	25146	02/13/2020 FVPRE	1 LABCON	BRIVAL01	1624	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	24570	02/14/2020 FVGEN	13 40-0974	BRIVAL01	EX00012848	RP21,GRADED SENSOR
RPS21	719QWU	24570	02/14/2020 FVGEN	16 CON	BRIVAL01	EX00012848	RP21,
RPS21	719QWU	24570	02/14/2020 FVGEN	13 LABEXT	BRIVAL01	EX00012848	RP21,

RPS21	719QWU	24570	02/14/2020 FVGEN	COMPLET ED BY BVR 14.02.202 0 INVOICE # 00001631 UNIT HAD RETURN AIR SENSOR CODES IN ZONE 2 REPLACED FAULTY SENSOR SET GRADES UNIT RUN ON TEST PRETRIP PASSED
-------	--------	-------	------------------	---

RPS21	719QWU	24570	02/14/2020 FVGEN	13 LABEXT	BRIVAL01	1631	RP21,
RPS21	719QWU	24570	02/14/2020 FVGEN	16 CON	BRIVAL01	1631	RP21,
RPS21	719QWU	24570	02/14/2020 FVGEN	13 40-0974	BRIVAL01	1631	RP21,GRADED SENSOR
RPS21	719QWU	24611	02/15/2020 GEN	15 33000517	BRI AUS01	EX00012882	RP21,REMOVAL: CUSTOMER PULL POINT
RPS21	719QWU	24611	02/15/2020 GEN	15 77000180	BRI AUS01	EX00012882	RP21,CASE STOCK 11-22.5
RPS21	719QWU	24611	02/15/2020 GEN	15 11001464	BRI AUS01	EX00012882	RP21,TYRE 11R22.5 148/145L 16 BS R187
RPS21	719QWU	24611	02/15/2020 GEN	15 33000084	BRI AUS01	EX00012882	RP21,FIT TBR TYRE
RPS21	719QWU	24611	02/15/2020 GEN	15 33000085	BRI AUS01	EX00012882	RP21,ROTATE TBR TYRE

				COMPLET ED BY BRIDGEST ONE 15.02.202 0 INVOICE # 98081661				
RPS21	719QWU	24611	02/15/2020 GEN					
RPS21	719QWU	24611	02/15/2020 GEN	15 33000085	BRIAUS01	98081661	RP21,ROTATE TBR TYRE	
RPS21	719QWU	24611	02/15/2020 GEN	15 33000084	BRIAUS01	98081661	RP21,FIT TBR TYRE	
RPS21	719QWU	24611	02/15/2020 GEN	15 11001464	BRIAUS01	98081661	RP21,TYRE 11R22.5 148/145L 16 BS R187	
RPS21	719QWU	24611	02/15/2020 GEN	15 77000180	BRIAUS01	98081661	RP21,CASE STOCK 11-22.5	
RPS21	719QWU	24611	02/15/2020 GEN	15 33000517	BRIAUS01	98081661	RP21,REMOVAL: CUSTOMER PULL POINT	
RPS21	719QWU	25326	02/18/2020 FVPRE	1 LABCON	BRIVAL01	EX00013254	LABOUR & CONSUMABLES,RP21	
RPS21	719QWU	25327	02/18/2020 FVPRE	1 LABCON	BRIVAL01	EX00013255	LABOUR & CONSUMABLES,RP21	
				SERVICE COMPLET ED BY BVR 13.02.202 0 PLEASE DISREGAR D WORK ORDER # 25314				
RPS21	719QWU	25326	02/18/2020 FVPRE					
RPS21	719QWU	25327	02/18/2020 FVPRE	SERVICE COMPLETED BY BVR 11.02.2020				
RPS21	719QWU	25326	02/18/2020 FVPRE	1 LABCON	BRIVAL01	1652	LABOUR & CONSUMABLES,RP21	
RPS21	719QWU	24731	02/24/2020 FVGEN	13 61-3401	BRIVAL01	EX00012953	RP21,HOT GAS VALVE	
RPS21	719QWU	24731	02/24/2020 FVGEN	13 PART	BRIVAL01	EX00012953	RP21,BROWN TIP SOLDER	
RPS21	719QWU	24731	02/24/2020 FVGEN	16 CON	BRIVAL01	EX00012953	RP21,	
RPS21	719QWU	24731	02/24/2020 FVGEN	13 LABEXT	BRIVAL01	EX00012953	RP21,	

ED BY BVR
24.02.202
0
INVOICE #
00001692

UNIT
FAILING
TO PULL
TO TEMP
ON
FRONT
ZONE
PUMPED
DOWN
SYSTEM
REPLACED
UNSERVIC
ABLE HOT
GAS
VALVE
VACCED
OUT UNIT
UNIT RUN
ON TEST
PRETRIP
PASSED

RPS21	719QWU	24731	02/24/2020 FVGEN
-------	--------	-------	------------------

RPS21	719QWU	24731	02/24/2020 FVGEN	13 LABEXT	BRIVAL01	1692	RP21,
RPS21	719QWU	24731	02/24/2020 FVGEN	16 CON	BRIVAL01	1692	RP21,
RPS21	719QWU	24731	02/24/2020 FVGEN	13 PART	BRIVAL01	1692	RP21,BROWN TIP SOLDER
RPS21	719QWU	24731	02/24/2020 FVGEN	13 61-3401	BRIVAL01	1692	RP21,HOT GAS VALVE
RPS21	719QWU	25062	03/05/2020 FVGEN	13 40-974	BRIVAL01	EX00013140	RP21,GRADED AIR SENSOR
RPS21	719QWU	25062	03/05/2020 FVGEN	16 CON	BRIVAL01	EX00013140	RP21,
RPS21	719QWU	25062	03/05/2020 FVGEN	13 LABEXT	BRIVAL01	EX00013140	RP21,

				COMPLET ED BY BVR 05.03.202 0 INVOICE # 00001737
				UNIT FOUND WITH SENSOR CODES TRACED FAULT TO FAULTY RETURN AIR SENSOR REPLACED UNSERVIC EABLE SENSOR UNIT RUN ON TEST PRETRIP PASSED
RPS21	719QWU	25062	03/05/2020 FVGEN	

RPS21	719QWU	25062	03/05/2020 FVGEN	13 LABEXT	BRIVAL01	1737	RP21,
RPS21	719QWU	25062	03/05/2020 FVGEN	16 CON	BRIVAL01	1737	RP21,
RPS21	719QWU	25062	03/05/2020 FVGEN	13 40-974	BRIVAL01	1737	RP21,GRADED AIR SENSOR
RPS21	719QWU	25302	03/16/2020 GEN	13 LABEXT	BRAAUT01	EX00013248	Labour External,RP21
RPS21	719QWU	25302	03/16/2020 GEN	13 N70 BATTERY	BRAAUT01	EX00013248	N70 BATTERY,RP21

				COMPLET ED BY BRADS AUTO ELECTRIC AL 16.03.202 0 INVOICE # 4273			
RPS21	719QWU	25302	03/16/2020 GEN	REPLACE BATTERY			
RPS21	719QWU	25302	03/16/2020 GEN	13 N70 BATTERY	BRAAUT01	4273	N70 BATTERY,RP21
RPS21	719QWU	25302	03/16/2020 GEN	13 LABEXT	BRAAUT01	4273	Labour External,RP21
RPS21	719QWU	25895	04/02/2020 TRA	1 LABOUR Labour			0
				COMPLET ED BY MICK / BILLY 02.04.202 0			
				FITTED FRIDGE DOOR LATCH FITTED REVERSE BEEPER FITTED ROPE SYSTEM TO HOLD CORE FLUTE			
				NO MAINTEN ANCE LABEL - HAVE EMAILED			
RPS21	719QWU	25895	04/02/2020 TRA				

RPS21	719QWU	25895	04/02/2020 TRA	0 LABOUR	MECH	Labour - Internal		
RPS21	719QWU	25895	04/02/2020 TRA	0 LABOUR	MECH1	Labour - Internal		
RPS21	719QWU	25895	04/02/2020 TRA	14	72602	YAT	Reverse Beeper (Narva)	
RPS21	719QWU	25895	04/02/2020 TRA	16	CON	YAT	Consumables	
RPS21	719QWU	26004	04/07/2020 FVGEN	13	44-9181	BRIVAL01	EX00013552	SPEED SOLENOID,RP21
								Consumables
RPS21	719QWU	26004	04/07/2020 FVGEN	16	CON	BRIVAL01	EX00013552	,RP21
RPS21	719QWU	26004	04/07/2020 FVGEN	13	LABEXT	BRIVAL01	EX00013552	Labour External,RP21
				ED BY BVR				
				07.04.202				
				0				
				INVOICE #				
				00001963				
				UNIT				
				SHUTTING				
				DOWN				
				ON				
				MULTIPLE				
				CODES				
				TRACED				
				FAULT TO				
				HOT GAS				
				VALVE				
				STICKING				
				PUMP				
				DOWN				
				UNIT				
				DE-				
				ASSEMBLE				
				D HOT				
				GAS				
				VALVE				
RPS21	719QWU	26004	04/07/2020 FVGEN	SOLENOID				
				WAS				

RPS21	719QWU	26004	04/07/2020 FVGEN	13 LABEXT	BRIVAL01	1963	Labour External,RP21
							Consumables
RPS21	719QWU	26004	04/07/2020 FVGEN	16 CON	BRIVAL01	1963	,RP21
RPS21	719QWU	26004	04/07/2020 FVGEN	13 44-9181	BRIVAL01	1963	SPEED SOLENOID,RP21
RPS21	719QWU	26730	04/24/2020 FVPRE	1 LABCON	BRIVAL01	EX00013903	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	26730	04/24/2020 FVPRE	SERVICE COMPLETED BY BVR 23.04.2020			
RPS21	719QWU	26730	04/24/2020 FVPRE	1 LABCON	BRIVAL01	2105	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	26783	05/05/2020 FVPRE	1 LABCON	BRIVAL01	EX00013910	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	26783	05/05/2020 FVPRE	SERVICE COMPLETED BY BVR 29.04.2020			
RPS21	719QWU	26783	05/05/2020 FVPRE	1 LABCON	BRIVAL01	2159	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	27055	05/07/2020 WEICAL	0 LABOUR	Labour		0
				AIR GAUGE: 13.5 ADJUSTED : 14.25 WEIGHBRI DGE: 13.95			
				AIR GAUGE CALIBRATION COMPLETED CORRECTLY.			
RPS21	719QWU	27055	05/07/2020 WEICAL				
RPS21	719QWU	27092	05/13/2020 FVPRE	1 LABCON	BRIVAL01	EX00014059	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	27092	05/13/2020 FVPRE	SERVICE COMPLETED BY BVR 07.05.2020			
RPS21	719QWU	27092	05/13/2020 FVPRE	1 LABCON	BRIVAL01	2251	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	27699	06/08/2020 WEICAL	0 LABOUR	Labour		0

AIR
GAUGE
CALIBRATI
ON
COMPLET
ED
CORRECTL
Y.

Y.

39 LABOUR Labour
REPAIR COMPLETED.

1 LABOUR Labour
SERVICE COMPLETED.

RPS21	719QWU	27809	06/15/2020 TRA
-------	--------	-------	----------------

RPS21	719QWU	27809	06/15/2020 TRA	0 LABOUR	MECH1	Labour - Internal		
RPS21	719QWU	27809	06/15/2020 TRA	16 CON		YAT	Consumables	
RPS21	719QWU	28161	06/24/2020 FRIVANA	SERVICE COMPLETED BVR 15/06/2020				
RPS21	719QWU	28472	06/24/2020 FRIVANA	1 LABCON		BRIVAL01	EX00014518	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	28472	06/24/2020 FRIVANA	1 LABCON		BRIVAL01	2573	LABOUR & CONSUMABLES,RP21

RPS21	719QWU	28811	07/07/2020 FRIVANA	1 LABCON	BRIVAL01	EX00014807	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	28811	07/07/2020 FRIVANA	1 LABCON	BRIVAL01	2678	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	28811	07/07/2020 FRIVANA	SERVICE COMPLETED BVR			
RPS21	719QWU	28921	07/07/2020 GEN	1 LABCON	BRIVAL01	EX00014823	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	28921	07/07/2020 GEN	1 LABCON	BRIVAL01	2669	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	28923	07/09/2020 GEN	1 LABCON	BRIVAL01	EX00014825	LABOUR & CONSUMABLES,
RPS21	719QWU	28923	07/09/2020 GEN	1 LABCON	BRIVAL01	2679	LABOUR & CONSUMABLES,
RPS21	719QWU	28923	07/09/2020 GEN	SERVICE COMPLETED BVR			
RPS21	719QWU	28563	07/13/2020 TRA	1 LABOUR	Labour		0
RPS21	719QWU	28563	07/13/2020 TRA	SERVICE COMPLETED.			
RPS21	719QWU	28563	07/13/2020 TRB	1 LABOUR	MECH1	Labour - Internal - Duane	
				SERVICE COMPLETED.			
				REPLACED INTERIOR LIGHT SWITCH ON FRONT OF TRAILER WITH SECOND HAND HOUSING.			
RPS21	719QWU	28563	07/13/2020 TRB				
RPS21	719QWU	28563	07/13/2020 TRB	0 LABOUR	APPREN	Labour - Internal - Keiran	
RPS21	719QWU	28563	07/13/2020 TRB	16 CON	YAT	Consumables	
RPS21	719QWU	28861	07/16/2020 FRIVANA	1 LABCON	BRIVAL01	EX00014813	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	28861	07/16/2020 FRIVANA	1 LABCON	BRIVAL01	2759	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	28861	07/16/2020 FRIVANA	SERVICE COMPLETED BVR			
RPS21	719QWU	28867	07/16/2020 FRIVANB	1 LABCON	BRIVAL01	EX00014814	LABOUR & CONSUMABLES,
RPS21	719QWU	28867	07/16/2020 FRIVANB	1 LABCON	BRIVAL01	2739	LABOUR & CONSUMABLES,
RPS21	719QWU	28867	07/16/2020 FRIVANB	SERVICE COMPLETED BVR			
RPS21	719QWU	29541	07/28/2020 GEN	1 LABCON	BRIVAL01	EX00015175	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	29541	07/28/2020 GEN	FLEET CHECK COMPLETED BY BVR 28.07.2020			
RPS21	719QWU	29541	07/28/2020 GEN	1 LABCON	BRIVAL01	2901	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	29441	08/12/2020 TRA	1 LABOUR	MECH	Labour	

REPLACED
TOP LHS
REAR
MARKER
LIGHT
REPLACED
LIGHT
PLUG ON
FRONT OF
TRAILER

RPS21	719QWU	29441	08/12/2020 TRA
RPS21	719QWU	29441	08/12/2020 TRA
RPS21	719QWU	29441	08/12/2020 TRA
RPS21	719QWU	29441	08/12/2020 TRA
RPS21	719QWU	29803	08/24/2020 FRIV
RPS21	719QWU	29803	08/24/2020 FRIV
RPS21	719QWU	29803	08/24/2020 FRIV

AIR
GAUGE:
21.00
ADJUSTED
: 21.25
WEIGHBRI
DGE:
20.80

RPS21	719QWU	30878	09/24/2020 WEICAL
-------	--------	-------	-------------------

RPS21	719QWU	30839	09/29/2020 TRA	1 LABOUR	MECH1	Labour
						SERVICE COMPLET ED BY JESSE 29.09.202 0
						HUBO NOT WORKING REPLACED FIRE EXTINGUI SHER RE-HUNG A/C SHOOT RE-HUNG METAL A/C COVER LINES.
RPS21	719QWU	30839	09/29/2020 TRA			

RPS21	719QWU	30839	09/29/2020 TRA	16 CON	YAT	Consumables	
RPS21	719QWU	30962	09/30/2020 FRIVANA	1 LABCON	BRIVAL01	EX00015841	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	30962	09/30/2020 FRIVANA	1 LABCON	BRIVAL01	3499	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	30947	09/30/2020 GEN	1 44-9298	BRIVAL01	EX00015836	RPM SENSOR, FRIDGE MOTOR,
RPS21	719QWU	30947	09/30/2020 GEN	1 LABCON	BRIVAL01	EX00015836	LABOUR & CONSUMABLES,
RPS21	719QWU	30947	09/30/2020 GEN	1 LABCON	BRIVAL01	3495	LABOUR & CONSUMABLES,
RPS21	719QWU	30947	09/30/2020 GEN	1 44-9298	BRIVAL01	3495	RPM SENSOR, FRIDGE MOTOR,
RPS21	719QWU	31191	10/07/2020 FRIVANA	1 LABCON	BRIVAL01	EX00015951	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	31191	10/07/2020 FRIVANA	1 LABCON	BRIVAL01	3551	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	31375	10/14/2020 FRIVANA	1 LABCON	BRIVAL01	EX00016064	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	31375	10/14/2020 FRIVANA	1 LABCON	BRIVAL01	3605	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	31398	10/15/2020 TYRES	15 33000096	BRIAUS01	EX00016066	PUNCTURE REPAIR TBR,
RPS21	719QWU	31398	10/15/2020 TYRES	15 33000096	BRIAUS01	99304158	PUNCTURE REPAIR TBR,
RPS21	719QWU	31892	10/28/2020 FRIVANA	1 LABCON	BRIVAL01	EX00016243	LABOUR & CONSUMABLES,RP21

RPS21	719QWU	31892	10/28/2020 FRIVANA	1 LABCON	BRIVAL01	3740	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	31870	10/28/2020 FVGEN	35 42-0100	BRIVAL01	EX00016241	STOP FUEL SOLENOID, FRIDGE MOTORS,
RPS21	719QWU	31870	10/28/2020 FVGEN	35 LABCON	BRIVAL01	EX00016241	LABOUR & CONSUMABLES,
RPS21	719QWU	31870	10/28/2020 FVGEN	35 LABCON	BRIVAL01	3739	LABOUR & CONSUMABLES,
RPS21	719QWU	31870	10/28/2020 FVGEN	35 42-0100	BRIVAL01	3739	STOP FUEL SOLENOID, FRIDGE MOTORS,
RPS21	719QWU	31967	10/29/2020 GEN	39 LAB	DJTRAN01	EX00016282	Labour,RP21
RPS21	719QWU	31967	10/29/2020 GEN	39 PART	DJTRAN01	EX00016282	GENERAL PART CODE,RP21
RPS21	719QWU	31967	10/29/2020 GEN	39 PART	DJTRAN01	EX00016282	GENERAL PART CODE,RP21
							Consuma
							bles
RPS21	719QWU	31967	10/29/2020 GEN	39 CON	DJTRAN01	EX00016282	,
RPS21	719QWU	31967	10/29/2020 GEN	SERVICE COMPLETED BY DJ MORGAN TRANSPORT			
							Consuma
							bles
RPS21	719QWU	31967	10/29/2020 GEN	39 CON	DJTRAN01	16918	,
RPS21	719QWU	31967	10/29/2020 GEN	39 PART	DJTRAN01	16918	GENERAL PART CODE,RP21
RPS21	719QWU	31967	10/29/2020 GEN	39 PART	DJTRAN01	16918	GENERAL PART CODE,RP21
RPS21	719QWU	31967	10/29/2020 GEN	39 LAB	DJTRAN01	16918	Labour,RP21
RPS21	719QWU	32274	11/04/2020 EXOINS	1 LABOUR	MECH	Labour	
				VEHICLE PASSED ANNUAL ROADWO RTHY INSPECTIO N. ATTEMPT #			
				INSPECTIO N COMPLET			
RPS21	719QWU	32274	11/04/2020 EXOINS	ED BY			
RPS21	719QWU	32274	11/04/2020 GEN	39 LAB	DIESER01	EX00016478	Labour,RP21
RPS21	719QWU	32274	11/04/2020 GEN	39 LAB	DIESER01	EX00016478	TOWING CHARGE,RP21
RPS21	719QWU	32274	11/04/2020 GEN	39 PART	DIESER01	EX00016478	GENERAL PART CODE,RP21
							Consuma
							bles
RPS21	719QWU	32274	11/04/2020 GEN	39 CON	DIESER01	EX00016478	,RP21
RPS21	719QWU	32274	11/04/2020 GEN	SERVICE COMPLETED BY DIESEL SERVICES 04/11/20			

							Consumables,RP21
RPS21	719QWU	32274	11/04/2020 GEN	39 CON	DIESER01	25830	
RPS21	719QWU	32274	11/04/2020 GEN	39 PART	DIESER01	25830	GENERAL PART CODE,RP21
RPS21	719QWU	32274	11/04/2020 GEN	39 LAB	DIESER01	25830	TOWING CHARGE,RP21
RPS21	719QWU	32274	11/04/2020 GEN	39 LAB	DIESER01	25830	Labour,RP21
RPS21	719QWU	32274	11/04/2020 TRA	1 LABOUR MECH	Labour		
RPS21	719QWU	32274	11/04/2020 TRA	SERVICE COMPLETED.			
RPS21	719QWU	32274	11/04/2020 TRB	1 LABOUR MECH	Labour		
RPS21	719QWU	32274	11/04/2020 TRB	SERVICE COMPLETED.			
				COMPLET			
				ED BY			
				DIESEL			
				SERVICES			
				04/11/20			
				C & D			
				SERVICE -			
				NO			
				GREASE			
				REPLACE			
				FRONET			
				AIRLINE			
				FITTINGS			
				7 PIN			
				PLUG			
				LOADING			
				DOCK			
				AND KING			
				PIN			
				LABOUR			
				MATERIALS			
				ADJUSTED			
				LHS IST			
				AXLE AND			
RPS21	719QWU	32274	11/04/2020 TRC	BOTH 2ND			

RPS21	719QWU	32274	11/04/2020 TRC	16 KZ1012.01	YAT	50MM BOLT IN KING PIN	
RPS21	719QWU	32274	11/04/2020 TRC	31 CON	YAT	FEMALE AIR CONNECTOR	
RPS21	719QWU	32274	11/04/2020 TRC	31 CON	YAT	MALE AIR CONNECTOR	
RPS21	719QWU	32274	11/04/2020 TRC	16 CON	YAT	7 PIN	
RPS21	719QWU	32274	11/04/2020 TRC	16 CON	YAT	CARTRIDGE GREASE	
RPS21	719QWU	32210	11/09/2020 FRIVANA	1 LABCON	BRIVAL01	EX00016430	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	32210	11/09/2020 FRIVANA	1 LABCON	BRIVAL01	3876	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	32342	11/13/2020 FVGEN	35 PART	BRIVAL01	EX00016512	GENERAL PART CODE,VOLTAGE REGULATOR
RPS21	719QWU	32342	11/13/2020 FVGEN	35 LABCON	BRIVAL01	EX00016512	LABOUR & CONSUMABLES,
RPS21	719QWU	32342	11/13/2020 FVGEN	35 LABCON	BRIVAL01	3952	LABOUR & CONSUMABLES,
RPS21	719QWU	32342	11/13/2020 FVGEN	35 PART	BRIVAL01	3952	GENERAL PART CODE,VOLTAGE REGULATOR
RPS21	719QWU	32342	11/13/2020 FVGEN	35 PART	BRIVAL01	EX00016512	GENERAL PART CODE,VOLTAGE REGULATOR
RPS21	719QWU	32342	11/13/2020 FVGEN	35 LABCON	BRIVAL01	EX00016512	LABOUR & CONSUMABLES,
RPS21	719QWU	32509	11/19/2020 TRA	1 LABOUR	MECH	Labour	
				SERVICE COMPLET ED MICK & KEIRAN 19.11.202 0.			
				FIRE EXTINGUI SHER APRIL 2021. REFITTED LH TRIM INSIDE FOR REAR FRIDGE			
RPS21	719QWU	32509	11/19/2020 TRA				
RPS21	719QWU	32509	11/19/2020 TRA	0 LABOUR	APPREN	Labour - Internal	
RPS21	719QWU	32509	11/19/2020 TRA	16 CON	YAT	Consumables	
RPS21	719QWU	32589	11/23/2020 TYRES	15 33000517	BRIAUS01	EX00016663	REMOVAL: CUSTOMER PULL POINT,
RPS21	719QWU	32589	11/23/2020 TYRES	15 33000085	BRIAUS01	EX00016663	ROTATE TBR TYRE,
RPS21	719QWU	32589	11/23/2020 TYRES	15 77000180	BRIAUS01	EX00016663	CASE STOCK 11-22.5,

RPS21	719QWU	32589	11/23/2020 TYRES	15	11001464	BRIAUS01	EX00016663	TYRE 11R22.5 148/145L 16 BS R187,
RPS21	719QWU	32589	11/23/2020 TYRES	15	33000084	BRIAUS01	EX00016663	FIT TBR TYRE,
RPS21	719QWU	32589	11/23/2020 TYRES	15	33000084	BRIAUS01	99503254	FIT TBR TYRE,
RPS21	719QWU	32589	11/23/2020 TYRES	15	11001464	BRIAUS01	99503254	TYRE 11R22.5 148/145L 16 BS R187,
RPS21	719QWU	32589	11/23/2020 TYRES	15	77000180	BRIAUS01	99503254	CASE STOCK 11-22.5,
RPS21	719QWU	32589	11/23/2020 TYRES	15	33000085	BRIAUS01	99503254	ROTATE TBR TYRE,
RPS21	719QWU	32589	11/23/2020 TYRES	15	33000517	BRIAUS01	99503254	REMOVAL: CUSTOMER PULL POINT,
RPS21	719QWU	32911	12/03/2020 FRIVANA	1	LABCON	BRIVAL01	EX00016839	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	32911	12/03/2020 FRIVANA	1	LABCON	BRIVAL01	4126	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	32888	12/07/2020 FRIVANA	1	LABCON	BRIVAL01	EX00016834	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	32895	12/07/2020 FRIVANA	1	LABCON	BRIVAL01	EX00016835	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	32888	12/07/2020 FRIVANA	1	LABCON	BRIVAL01	4173	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	32895	12/07/2020 FRIVANA	1	LABCON	BRIVAL01	4055	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	33084	12/10/2020 GEN	0	LABOUR APPREN	Labour		

REPAIR
COMPLET
ED
BEN/MICK

REPAVED
REAR RHS
GAURD
AND
PANEL
BEAT
BRACKETS
THAT
MOUNT
TO THE
CHASIS

RPS21 719QWU 33084 12/10/2020 GEN

RPS21	719QWU	33084	12/10/2020 GEN	0	LABOUR MECH	Labour - Internal		
RPS21	719QWU	33084	12/10/2020 GEN	16	CON	YAT Consumables		
RPS21	719QWU	33084	12/10/2020 GEN	13	K127-1116-10A	YAT FENDER L/B	BLUE SPRAYSAFE	
RPS21	719QWU	33443	12/30/2020 FRIVANA	1	LABCON	BRIVAL01	EX00017098	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	33443	12/30/2020 FRIVANA	SERVICE COMPLETED BY BVR 29/12/2020.				
RPS21	719QWU	33443	12/30/2020 FRIVANA	1	LABCON	BRIVAL01	4382	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	33603	01/08/2021 TYRES	15	33000096	BRIAUS01	EX00017182	PUNCTURE REPAIR TBR,719QWU

				SERVICE COMPLET ED BY BRIDGEST ONE			
				POS 33 INV 48102197 39			
RPS21	719QWU	33603	01/08/2021 TYRES				
RPS21	719QWU	33603	01/08/2021 TYRES	15 33000096	BRIAUS01	4.81E+09	PUNCTURE REPAIR TBR,719QWU
RPS21	719QWU	33763	01/15/2021 TRA	0 LABOUR APPREN	Labour		
RPS21	719QWU	33763	01/15/2021 TRA	SERVICE COMPLETED BY KEIRAN			
RPS21	719QWU	33763	01/15/2021 TRA	16 CON	YAT	Consumables	
RPS21	719QWU	33960	01/18/2021 FVGEN	39 PART	BRIVAL01	EX00017409	61-9093 HOT GAS SOLENOID VALVE,RP21
RPS21	719QWU	33960	01/18/2021 FVGEN	39 PART	BRIVAL01	EX00017409	BROWN TIP SOLDER,RP21
							Consuma bles
RPS21	719QWU	33960	01/18/2021 FVGEN	39 CON	BRIVAL01	EX00017409	,RP21
RPS21	719QWU	33960	01/18/2021 FVGEN	39 LAB	BRIVAL01	EX00017409	Labour,RP21
RPS21	719QWU	33960	01/18/2021 FVGEN	SERVICE COMPLETED BY BVR 14/01/2021.			
RPS21	719QWU	33960	01/18/2021 FVGEN	39 LAB	BRIVAL01	4585	Labour,RP21
							Consuma bles
RPS21	719QWU	33960	01/18/2021 FVGEN	39 CON	BRIVAL01	4585	,RP21
RPS21	719QWU	33960	01/18/2021 FVGEN	39 PART	BRIVAL01	4585	BROWN TIP SOLDER,RP21
RPS21	719QWU	33960	01/18/2021 FVGEN	39 PART	BRIVAL01	4585	61-9093 HOT GAS SOLENOID VALVE,RP21
RPS21	719QWU	34706	01/18/2021 TYRES	15 77000180	BRIAUS01	EX00017734	CASE STOCK 11-22.5,RP21
RPS21	719QWU	34706	01/18/2021 TYRES	15 77000180	BRIAUS01	85242435	CASE STOCK 11-22.5,RP21
RPS21	719QWU	34002	01/20/2021 FRIVANA	1 LABCON	BRIVAL01	EX00017424	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	34002	01/20/2021 FRIVANA	SERVICE COMPLETED BY BVR 18/01/2021.			
RPS21	719QWU	34002	01/20/2021 FRIVANA	1 LABCON	BRIVAL01	4620	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	34494	01/25/2021 FRIVANA	1 LABCON	BRIVAL01	EX00017559	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	34494	01/25/2021 FRIVANA	SERVICE COMPLETED BY BVR 22/01/2021.			
RPS21	719QWU	34494	01/25/2021 FRIVANA	1 LABCON	BRIVAL01	4690	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	34191	01/28/2021 FVGEN	39 R404A	BRIVAL01	EX00017494	GAS R404A,RP21
RPS21	719QWU	34599	01/28/2021 FVGEN	39 R404A	BRIVAL01	EX00017639	GAS R404A,RP21
							Consuma bles
RPS21	719QWU	34191	01/28/2021 FVGEN	39 CON	BRIVAL01	EX00017494	,RP21

RPS21	719QWU	34599	01/28/2021 FVGEN	39 CON	BRIVAL01	EX00017639	Consumables,RP21
RPS21	719QWU	34191	01/28/2021 FVGEN	39 LAB	BRIVAL01	EX00017494	Labour,RP21
RPS21	719QWU	34599	01/28/2021 FVGEN	39 LAB	BRIVAL01	EX00017639	Labour,RP21
RPS21	719QWU	34191	01/28/2021 FVGEN	SERVICED COMPLETED BY BVR 18/01/2021.			
RPS21	719QWU	34599	01/28/2021 FVGEN	SERVICE COMPLETED BY BVR 18/01/2021.			
RPS21	719QWU	34599	01/28/2021 FVGEN	39 LAB	BRIVAL01	4616	Labour,RP21
							Consumables,RP21
RPS21	719QWU	34599	01/28/2021 FVGEN	39 CON	BRIVAL01	4616	
RPS21	719QWU	34599	01/28/2021 FVGEN	39 R404A	BRIVAL01	4616	GAS R404A,RP21
RPS21	719QWU	34530	01/29/2021 FRIVANA	1 LABCON	BRIVAL01	EX00017560	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	34547	01/29/2021 FRIVANA	1 LABCON	BRIVAL01	EX00017561	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	34530	01/29/2021 FRIVANA	SERVICE COMPLETED BY BVR 27/01/2021.			
RPS21	719QWU	34547	01/29/2021 FRIVANA	SERVICE COMPLETED BY BVR 28/01/2021.			
RPS21	719QWU	34530	01/29/2021 FRIVANA	1 LABCON	BRIVAL01	4728	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	34547	01/29/2021 FRIVANA	1 LABCON	BRIVAL01	4729	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	34374	01/29/2021 FRIVANB	39 10-417	BRIVAL01	EX00017557	FILTER KIT (FRIDGE MOTOR),RP21
RPS21	719QWU	34374	01/29/2021 FRIVANB	39 Nov-38	BRIVAL01	EX00017557	VALVE OIL DRAIN,RP21
							Consumables,RP21
RPS21	719QWU	34374	01/29/2021 FRIVANB	39 CON	BRIVAL01	EX00017557	
RPS21	719QWU	34374	01/29/2021 FRIVANB	39 LAB	BRIVAL01	EX00017557	Labour,RP21
RPS21	719QWU	34374	01/29/2021 FRIVANB	SERVICE COMPLETED BY BVR 28/01/2021.			
RPS21	719QWU	34374	01/29/2021 FRIVANB	39 10-417	BRIVAL01	4723	FILTER KIT (FRIDGE MOTOR),RP21
RPS21	719QWU	34374	01/29/2021 FRIVANB	39 Nov-38	BRIVAL01	4723	VALVE OIL DRAIN,RP21
							Consumables,RP21
RPS21	719QWU	34374	01/29/2021 FRIVANB	39 CON	BRIVAL01	4723	
RPS21	719QWU	34374	01/29/2021 FRIVANB	39 LAB	BRIVAL01	4723	Labour,RP21
RPS21	719QWU	34129	02/01/2021 GEN	0 LABOUR	MECH1 Labour		

				REPAIR COMPLET ED BY SEAN AND BEN			
				FITTED EBS DUMMY SOCKET ON FRONT OF TRAILER REPLACED MARKER LIGHT RHS			
RPS21	719QWU	34129	02/01/2021 GEN				
RPS21	719QWU	34129	02/01/2021 GEN	0 LABOUR	APPREN	Labour - Internal	
RPS21	719QWU	34129	02/01/2021 GEN	16 CON	YAT	Consumables	
RPS21	719QWU	34129	02/01/2021 GEN	14 91700BL	YAT	Clearance Light, LED Amber, Narva	
RPS21	719QWU	34129	02/01/2021 GEN	14 1449 105 015	YAT	EBS/ABS DUMMY PARKING SOCK	
RPS21	719QWU	34331	02/02/2021 FRIVANA	1 LABCON	BRIVAL01	EX00017513	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	34331	02/02/2021 FRIVANA	SERVICE COMPLETED BY BVR 29/01/2021.			
RPS21	719QWU	34331	02/02/2021 FRIVANA	1 LABCON	BRIVAL01	4751	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	35312	02/16/2021 FRIVANA	1 LABCON	BRIVAL01	EX00017976	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	35312	02/16/2021 FRIVANA	SERVICE COMPLETED BY BVR 11/02/2021.			
RPS21	719QWU	35312	02/16/2021 FRIVANA	1 LABCON	BRIVAL01	4901	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	35379	02/25/2021 FRIVANA	1 LABCON	BRIVAL01	EX00017980	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	35390	02/25/2021 FRIVANA	1 LABCON	BRIVAL01	EX00017980	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	35434	02/25/2021 FRIVANA	1 LABCON	BRIVAL01	EX00017983	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	35379	02/25/2021 FRIVANA	SERVICE COMPLETED BY BVR 22/02/2021.			
RPS21	719QWU	35390	02/25/2021 FRIVANA	SERVICE COMPLETED BY BVR 22/02/2021.			
RPS21	719QWU	35434	02/25/2021 FRIVANA	SERVICE COMPLETED BY BVR 23/02/2021.			
RPS21	719QWU	35379	02/25/2021 FRIVANA	1 LABCON	BRIVAL01	5014	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	35390	02/25/2021 FRIVANA	1 LABCON	BRIVAL01	5014	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	35434	02/25/2021 FRIVANA	1 LABCON	BRIVAL01	5021	LABOUR & CONSUMABLES,RP21
							Consuma bles ,RP21
RPS21	719QWU	35072	02/25/2021 FVGEN	39 CON	BRIVAL01	EX00017904	
RPS21	719QWU	35072	02/25/2021 FVGEN	39 LAB	BRIVAL01	EX00017904	Labour,RP21
RPS21	719QWU	35072	02/25/2021 FVGEN	SERVICE COMPLETED BY BVR 22/02/2021.			
RPS21	719QWU	35072	02/25/2021 FVGEN	39 LAB	BRIVAL01	5040	Labour,RP21

RPS21	719QWU	35072	02/25/2021 FVGEN	39 CON	BRIVAL01	5040	Consumables,RP21
RPS21	719QWU	35160	02/25/2021 TYRES	15 77000180	BRI AUS01	EX00017934	CASE STOCK 11-22.5,RP21
RPS21	719QWU	35160	02/25/2021 TYRES	15 77000180	BRI AUS01	85454071	CASE STOCK 11-22.5,RP21
RPS21	719QWU	35786	03/08/2021 FRIVANA	1 LABCON	BRIVAL01	EX00018129	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	35786	03/08/2021 FRIVANA	SERVICE COMPLETED BY BVR 04/03/2021.			
RPS21	719QWU	35786	03/08/2021 FRIVANA	1 LABCON	BRIVAL01	5179	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	35643	03/11/2021 tra	0 LABOUR	MECH1 Labour		
RPS21	719QWU	35643	03/11/2021 tra	SERVICE COMPLETED. BY SEAN AND BEN			
RPS21	719QWU	35643	03/11/2021 tra	0 LABOUR	APPREN Labour - Internal		
RPS21	719QWU	35643	03/11/2021 tra	16 CON	YAT Consumables		
			AIR GAUGE: 18500 ADJUSTED : 19000 WEIGHBRI DGE: 18600				
			AIR GAUGE CALIBRATION COMPLETED CORRECTLY.				
RPS21	719QWU	35893	03/15/2021 WEICAL				
RPS21	719QWU	36205	03/22/2021 FRIVANA	1 LABCON	BRIVAL01	EX00018301	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	36234	03/22/2021 FRIVANA	1 LABCON	BRIVAL01	EX00018303	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	36244	03/22/2021 FRIVANA	1 LABCON	BRIVAL01	EX00018303	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	36205	03/22/2021 FRIVANA	SERVICE COMPLETED BY BVR 17/03/2021			
RPS21	719QWU	36234	03/22/2021 FRIVANA	SERVICE COMPLETED BY BVR 19/03/2021			
RPS21	719QWU	36244	03/22/2021 FRIVANA	SERVICE COMPLETED BY BVR 19/03/2021			
RPS21	719QWU	36205	03/22/2021 FRIVANA	1 LABCON	BRIVAL01	5350	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	36234	03/22/2021 FRIVANA	1 LABCON	BRIVAL01	5376	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	36244	03/22/2021 FRIVANA	1 LABCON	BRIVAL01	5376	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	36134	03/22/2021 FVGEN	39 PART	BRIVAL01	EX00018261	40-0985 LED STATUS LIGHT,RP21

RPS21	719QWU	36160	03/22/2021 FVGEN	39 CON	BRIVAL01	EX00018265	Consumables,RP21
RPS21	719QWU	36134	03/22/2021 FVGEN	39 CON	BRIVAL01	EX00018261	Consumables,RP21
RPS21	719QWU	36160	03/22/2021 FVGEN	39 LAB	BRIVAL01	EX00018265	Labour,RP21
RPS21	719QWU	36134	03/22/2021 FVGEN	39 LAB	BRIVAL01	EX00018261	Labour,RP21
RPS21	719QWU	36160	03/22/2021 FVGEN	SERVICE COMPLETED BY BVR 19/03/2021			
RPS21	719QWU	36134	03/22/2021 FVGEN	SERVICE COMPLETED BY BVR 17/03/2021			
RPS21	719QWU	36160	03/22/2021 FVGEN	39 LAB	BRIVAL01	5379	Labour,RP21
RPS21	719QWU	36134	03/22/2021 FVGEN	39 LAB	BRIVAL01	5343	Labour,RP21
RPS21	719QWU	36160	03/22/2021 FVGEN	39 CON	BRIVAL01	5379	Consumables,RP21
RPS21	719QWU	36134	03/22/2021 FVGEN	39 CON	BRIVAL01	5343	Consumables,RP21
RPS21	719QWU	36134	03/22/2021 FVGEN	39 PART	BRIVAL01	5343	40-0985 LED STATUS LIGHT,RP21
RPS21	719QWU	36363	03/29/2021 FRIVANA	1 LABCON	BRIVAL01	EX00018318	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	36363	03/29/2021 FRIVANA	SERVICE COMPLETED BY BVR 24/03/2021.			
RPS21	719QWU	36363	03/29/2021 FRIVANA	1 LABCON	BRIVAL01	5431	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	36369	03/29/2021 FVGEN	39 R404A	BRIVAL01	EX00018341	GAS R404A,RP21
RPS21	719QWU	36369	03/29/2021 FVGEN	39 CON	BRIVAL01	EX00018341	Consumables,RP21
RPS21	719QWU	36369	03/29/2021 FVGEN	39 LAB	BRIVAL01	EX00018341	Labour,RP21
RPS21	719QWU	36369	03/29/2021 FVGEN	SERVICE COMPLETED BY BVR 24/03/2021.			
RPS21	719QWU	36369	03/29/2021 FVGEN	39 LAB	BRIVAL01	5446	Labour,RP21
RPS21	719QWU	36369	03/29/2021 FVGEN	39 CON	BRIVAL01	5446	Consumables,RP21
RPS21	719QWU	36369	03/29/2021 FVGEN	39 R404A	BRIVAL01	5446	GAS R404A,RP21

Reported
Defect :-
Defect
Code :
00005599
Defect
Reference
: 08170
Date :
10/11/20
20
Description
of
Defect :
T
INDICATO
R FOR
FRIDGE
MOTOR
NOT
WORKING

HAS BEEN
REPLACED

RPS21 719QWU 37265 04/29/2021 DEFECT

RPS21	719QWU	37265	04/29/2021 TRA	1 LABOUR	Labour	
RPS21	719QWU	37265	04/29/2021 TRA	SERVICE COMPLETED.		
RPS21	719QWU	37265	04/29/2021 TRB	0 LABOUR	MECH1	Labour

0

				COMPLET ED BY SEAN AND RYAN				
				FITTED A FEW BOLTS ON THE FRIDGE COVER STRAIGHT ENED THE DOOR FRAME AND WELDED IT TENSIONE D ALL UBOLTS ADJUSTED ALL WHEEL BEARINGS AND TENSIONE				
RPS21	719QWU	37265	04/29/2021 TRB					
RPS21	719QWU	37265	04/29/2021 TRB	0 LABOUR	MECH1	Labour - Internal		
RPS21	719QWU	37265	04/29/2021 TRB	16 CON		YAT Consumables		
RPS21	719QWU	37500	05/07/2021 FRIVANA	1 LABCON		BRIVAL01	EX00018845	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	37503	05/07/2021 FRIVANA	1 LABCON		BRIVAL01	EX00018846	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	37500	05/07/2021 FRIVANA	SERVICE COMPLETED BY BVR 04/05/2021				
RPS21	719QWU	37503	05/07/2021 FRIVANA	SERVICE COMPLETED BY BVR 05/05/2021				
RPS21	719QWU	37500	05/07/2021 FRIVANA	1 LABCON		BRIVAL01	5878	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	37503	05/07/2021 FRIVANA	1 LABCON		BRIVAL01	5879	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	37436	05/07/2021 FVGEN	39 PART		BRIVAL01	EX00018840	BLUE TIP SILVER SOLDER,RP21
RPS21	719QWU	37437	05/07/2021 FVGEN	39 PART		BRIVAL01	EX00018841	DEFROST ASSESSMBLY,RP21
RPS21	719QWU	37436	05/07/2021 FVGEN	39 R404A		BRIVAL01	EX00018840	GAS R404A,RP21
								Consuma
								bles
RPS21	719QWU	37437	05/07/2021 FVGEN	39 CON		BRIVAL01	EX00018841	,RP21

RPS21	719QWU	37436	05/07/2021 FVGEN	39 91-0372	BRIVAL01	EX00018840	CLAMP TUBE, FRIDGE MOTOR,RP21
RPS21	719QWU	37437	05/07/2021 FVGEN	39 LAB	BRIVAL01	EX00018841	Labour,RP21
RPS21	719QWU	37436	05/07/2021 FVGEN	39 PART	BRIVAL01	EX00018840	FAN SHAFT,RP21
RPS21	719QWU	37437	05/07/2021 FVGEN	SERVICE COMPLETED BY BVR 04/05/2021			Consumables,RP21
RPS21	719QWU	37436	05/07/2021 FVGEN	39 CON	BRIVAL01	EX00018840	
RPS21	719QWU	37437	05/07/2021 FVGEN	39 LAB	BRIVAL01	5871	Labour,RP21
RPS21	719QWU	37436	05/07/2021 FVGEN	39 LAB	BRIVAL01	EX00018840	Labour,RP21
							Consumables,RP21
RPS21	719QWU	37437	05/07/2021 FVGEN	39 CON	BRIVAL01	5871	
RPS21	719QWU	37436	05/07/2021 FVGEN	SERVICE COMPLETED BY BVR 04/05/2021			
RPS21	719QWU	37437	05/07/2021 FVGEN	39 PART	BRIVAL01	5871	DEFROST ASSESSMBLY,RP21
RPS21	719QWU	37436	05/07/2021 FVGEN	39 LAB	BRIVAL01	5859	Labour,RP21
							Consumables,RP21
RPS21	719QWU	37436	05/07/2021 FVGEN	39 CON	BRIVAL01	5859	
RPS21	719QWU	37436	05/07/2021 FVGEN	39 PART	BRIVAL01	5859	FAN SHAFT,RP21
RPS21	719QWU	37436	05/07/2021 FVGEN	39 91-0372	BRIVAL01	5859	CLAMP TUBE, FRIDGE MOTOR,RP21
RPS21	719QWU	37436	05/07/2021 FVGEN	39 R404A	BRIVAL01	5859	GAS R404A,RP21
RPS21	719QWU	37436	05/07/2021 FVGEN	39 PART	BRIVAL01	5859	BLUE TIP SILVER SOLDER,RP21
RPS21	719QWU	37540	05/11/2021 FRIVANA	1 LABCON	BRIVAL01	EX00018847	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	37540	05/11/2021 FRIVANA	SERVICE COMPLETED BY BVR 07/05/2021			
RPS21	719QWU	37540	05/11/2021 FRIVANA	1 LABCON	BRIVAL01	5904	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	37640	05/17/2021 FRIVANA	1 LABCON	BRIVAL01	EX00018924	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	37640	05/17/2021 FRIVANA	SERVICE COMPLETED BY BVR 10/05/2021			
RPS21	719QWU	37640	05/17/2021 FRIVANA	1 LABCON	BRIVAL01	5930	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	37970	05/28/2021 FRIVANA	1 LABCON	BRIVAL01	EX00019090	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	37970	05/28/2021 FRIVANA	SERVICE COMPLETED BY BVR 24/05/2021			
RPS21	719QWU	37970	05/28/2021 FRIVANA	1 LABCON	BRIVAL01	6124	LABOUR & CONSUMABLES,RP21
							Consumables,RP21
RPS21	719QWU	37960	05/28/2021 FVGEN	39 CON	BRIVAL01	EX00019083	
RPS21	719QWU	37966	05/28/2021 FVGEN	39 PART	BRIVAL01	EX00019088	61-9093 HOT GAS SOLENOID VALVE,RP21
RPS21	719QWU	37960	05/28/2021 FVGEN	39 LAB	BRIVAL01	EX00019083	Labour,RP21
RPS21	719QWU	37966	05/28/2021 FVGEN	39 R404A	BRIVAL01	EX00019088	GAS R404A,RP21
RPS21	719QWU	37960	05/28/2021 FVGEN	SERVICE COMPLETED BY BVR 24/05/2021			Consumables,RP21
RPS21	719QWU	37966	05/28/2021 FVGEN	39 CON	BRIVAL01	EX00019088	
RPS21	719QWU	37960	05/28/2021 FVGEN	39 LAB	BRIVAL01	6109	Labour,RP21

RPS21	719QWU	37966	05/28/2021 FVGEN	39 LAB	BRIVAL01	EX00019088	Labour,RP21
RPS21	719QWU	37960	05/28/2021 FVGEN	39 CON	BRIVAL01	6109	Consumables,RP21
RPS21	719QWU	37966	05/28/2021 FVGEN	SERVICE COMPLETED BY BVR 26/05/2021			
RPS21	719QWU	37966	05/28/2021 FVGEN	39 LAB	BRIVAL01	6086	Labour,RP21
							Consumables,RP21
RPS21	719QWU	37966	05/28/2021 FVGEN	39 CON	BRIVAL01	6086	
RPS21	719QWU	37966	05/28/2021 FVGEN	39 R404A	BRIVAL01	6086	GAS R404A,RP21
RPS21	719QWU	37966	05/28/2021 FVGEN	39 PART	BRIVAL01	6086	61-9093 HOT GAS SOLENOID VALVE,RP21
RPS21	719QWU	38060	05/31/2021 FRIVANA	1 LABCON	BRIVAL01	EX00019120	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	38060	05/31/2021 FRIVANA	SERVICE COMPLETED BY BVR 27/05/2021			
RPS21	719QWU	38060	05/31/2021 FRIVANA	1 LABCON	BRIVAL01	6137	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	38297	06/08/2021 TRA	0 LABOUR	MECH1	Labour	
RPS21	719QWU	38297	06/08/2021 TRA	SERVICE COMPLETED BY SEAN AND BEN			
RPS21	719QWU	38297	06/08/2021 TRA	0 LABOUR	APPREN	1 85 85	
RPS21	719QWU	38297	06/08/2021 TRA	16 CON	YAT	Consumables	
RPS21	719QWU	38510	06/09/2021 TYRES	15 77000180	BRIAUS01	EX00019317	CASE STOCK 11-22.5,RP21
RPS21	719QWU	38510	06/09/2021 TYRES	15 33000096	BRIAUS01	EX00019317	PUNCTURE REPAIR TBR,RP21
RPS21	719QWU	38510	06/09/2021 TYRES	15 33000096	BRIAUS01	86006981	PUNCTURE REPAIR TBR,RP21
RPS21	719QWU	38510	06/09/2021 TYRES	15 77000180	BRIAUS01	86006981	CASE STOCK 11-22.5,RP21
RPS21	719QWU	38416	06/10/2021 FRIVANA	1 LABCON	BRIVAL01	EX00019287	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	38416	06/10/2021 FRIVANA	SERVICE COMPLETED BY BVR 08/06/2021			
RPS21	719QWU	38416	06/10/2021 FRIVANA	1 LABCON	BRIVAL01	6263	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	38412	06/10/2021 FVGEN	39 Nov-42	BRIVAL01	EX00019284	FUEL FILTER, FRIDGE MOTOR,RP21
RPS21	719QWU	38412	06/10/2021 FVGEN	39 PART	BRIVAL01	EX00019284	11-9300 TRAILER AIR FILTER,RP21
RPS21	719QWU	38412	06/10/2021 FVGEN	39 42-0100	BRIVAL01	EX00019284	STOP FUEL SOLENOID, FRIDGE MOTORS,RP21
RPS21	719QWU	38412	06/10/2021 FVGEN	39 91-0373	BRIVAL01	EX00019284	CLAMP TUBE FRIDGE MOTOR,RP21
RPS21	719QWU	38412	06/10/2021 FVGEN	39 91-0372	BRIVAL01	EX00019284	CLAMP TUBE, FRIDGE MOTOR,RP21
RPS21	719QWU	38412	06/10/2021 FVGEN	39 55-2208	BRIVAL01	EX00019284	COPPER WASHER,RP21
							Consumables,RP21
RPS21	719QWU	38412	06/10/2021 FVGEN	39 CON	BRIVAL01	EX00019284	
RPS21	719QWU	38412	06/10/2021 FVGEN	39 LAB	BRIVAL01	EX00019284	Labour,RP21
RPS21	719QWU	38412	06/10/2021 FVGEN	SERVICE COMPLETED BY BVR 07/06/2021			
RPS21	719QWU	38412	06/10/2021 FVGEN	39 LAB	BRIVAL01	6266	Labour,RP21
							Consumables,RP21
RPS21	719QWU	38412	06/10/2021 FVGEN	39 CON	BRIVAL01	6266	
RPS21	719QWU	38412	06/10/2021 FVGEN	39 55-2208	BRIVAL01	6266	COPPER WASHER,RP21
RPS21	719QWU	38412	06/10/2021 FVGEN	39 91-0372	BRIVAL01	6266	CLAMP TUBE, FRIDGE MOTOR,RP21

RPS21	719QWU	38412	06/10/2021	FVGEN	39 91-0373	BRIVAL01	6266	CLAMP TUBE FRIDGE MOTOR,RP21
RPS21	719QWU	38412	06/10/2021	FVGEN	39 42-0100	BRIVAL01	6266	STOP FUEL SOLENOID, FRIDGE MOTORS,RP21
RPS21	719QWU	38412	06/10/2021	FVGEN	39 PART	BRIVAL01	6266	11-9300 TRAILER AIR FILTER,RP21
RPS21	719QWU	38412	06/10/2021	FVGEN	39 Nov-42	BRIVAL01	6266	FUEL FILTER, FRIDGE MOTOR,RP21
RPS21	719QWU	38474	06/11/2021	FRIVANA	1 LABCON	BRIVAL01	EX00019295	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	38474	06/11/2021	FRIVANA	SERVICE COMPLETED BY BVR 09.06.2021			
RPS21	719QWU	38474	06/11/2021	FRIVANA	1 LABCON	BRIVAL01	6300	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	38598	06/16/2021	FRIVANA	1 LABCON	BRIVAL01	EX00019362	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	38598	06/16/2021	FRIVANA	1 LABCON	BRIVAL01	6318	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	38564	06/16/2021	FRIVANB	39 PART	BRIVAL01	EX00019360	HEAD GASKET,RP21
RPS21	719QWU	38564	06/16/2021	FRIVANB	39 PART	BRIVAL01	EX00019360	13-0385 TIER 2 THERMOSTAT,RP21
RPS21	719QWU	38564	06/16/2021	FRIVANB	39 13-2268	BRIVAL01	EX00019360	PUMP WATER TK486,RP21
RPS21	719QWU	38564	06/16/2021	FRIVANB	39 PART	BRIVAL01	EX00019360	42-0541 COOLANT TEMP SENSOR,RP21
RPS21	719QWU	38564	06/16/2021	FRIVANB	39 PART	BRIVAL01	EX00019360	ANTI-FREEZE COOLANT,RP21
RPS21	719QWU	38564	06/16/2021	FRIVANB	39 PART	BRIVAL01	EX00019360	10-0417 FILTER KIT TRAILER,RP21
RPS21	719QWU	38564	06/16/2021	FRIVANB	39 CON	BRIVAL01	EX00019360	Consumables,RP21
RPS21	719QWU	38564	06/16/2021	FRIVANB	39 LAB	BRIVAL01	EX00019360	Labour,RP21
RPS21	719QWU	38564	06/16/2021	FRIVANB	SERVICE COMPLETED BY BVR 09/06/2021			
RPS21	719QWU	38564	06/16/2021	FRIVANB	39 LAB	BRIVAL01	6329	Labour,RP21
RPS21	719QWU	38564	06/16/2021	FRIVANB	39 CON	BRIVAL01	6329	Consumables,RP21
RPS21	719QWU	38564	06/16/2021	FRIVANB	39 PART	BRIVAL01	6329	10-0417 FILTER KIT TRAILER,RP21
RPS21	719QWU	38564	06/16/2021	FRIVANB	39 PART	BRIVAL01	6329	ANTI-FREEZE COOLANT,RP21
RPS21	719QWU	38564	06/16/2021	FRIVANB	39 PART	BRIVAL01	6329	42-0541 COOLANT TEMP SENSOR,RP21
RPS21	719QWU	38564	06/16/2021	FRIVANB	39 13-2268	BRIVAL01	6329	PUMP WATER TK486,RP21
RPS21	719QWU	38564	06/16/2021	FRIVANB	39 PART	BRIVAL01	6329	13-0385 TIER 2 THERMOSTAT,RP21
RPS21	719QWU	38564	06/16/2021	FRIVANB	39 PART	BRIVAL01	6329	HEAD GASKET,RP21
RPS21	719QWU	38728	06/17/2021	FRIVANA	1 LABCON	BRIVAL01	EX00019391	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	38728	06/17/2021	FRIVANA	SERVICE COMPLETED BY BVR 15/06/2021			
RPS21	719QWU	38728	06/17/2021	FRIVANA	1 LABCON	BRIVAL01	6346	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	39022	06/24/2021	FRIVANA	1 LABCON	BRIVAL01	EX00019550	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	39073	06/24/2021	FRIVANA	1 LABCON	BRIVAL01	EX00019578	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	39101	06/24/2021	FRIVANA	1 LABCON	BRIVAL01	EX00019579	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	39022	06/24/2021	FRIVANA	SERVICE COMPLETED BY BVR 17.06.2021			
RPS21	719QWU	39073	06/24/2021	FRIVANA	SERVICE COMPLETED BY BVR 18.06.2021			
RPS21	719QWU	39101	06/24/2021	FRIVANA	SERVICE COMPLETED BY BVR 21.06.2021			
RPS21	719QWU	39022	06/24/2021	FRIVANA	1 LABCON	BRIVAL01	6339	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	39073	06/24/2021	FRIVANA	1 LABCON	BRIVAL01	6381	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	39101	06/24/2021	FRIVANA	1 LABCON	BRIVAL01	6409	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	38956	06/24/2021	FVGEN	39 78-1886	BRIVAL01	EX00019517	FAN BLOWER MOTOR 14V,RP21

RPS21	719QWU	38957	06/24/2021 FVGEN	39 Nov-05	BRIVAL01	EX00019528	HOSE, FRIDGE MOTOR,RP21
RPS21	719QWU	38956	06/24/2021 FVGEN	39 CON	BRIVAL01	EX00019517	Consumables,RP21
RPS21	719QWU	38957	06/24/2021 FVGEN	39 CON	BRIVAL01	EX00019528	Consumables,RP21
RPS21	719QWU	38956	06/24/2021 FVGEN	39 LAB	BRIVAL01	EX00019517	Labour,RP21
RPS21	719QWU	38957	06/24/2021 FVGEN	39 LAB	BRIVAL01	EX00019528	Labour,RP21
RPS21	719QWU	38956	06/24/2021 FVGEN	SERVICE COMPLETED BY BVR 17.06.2021			
RPS21	719QWU	38957	06/24/2021 FVGEN	SERVICE COMPLETED BY BVR 18.06.2021			
RPS21	719QWU	38956	06/24/2021 FVGEN	39 LAB	BRIVAL01	6350	Labour,RP21
RPS21	719QWU	38957	06/24/2021 FVGEN	39 LAB	BRIVAL01	6375	Labour,RP21
RPS21	719QWU	38956	06/24/2021 FVGEN	39 CON	BRIVAL01	6350	Consumables,RP21
RPS21	719QWU	38957	06/24/2021 FVGEN	39 CON	BRIVAL01	6375	Consumables,RP21
RPS21	719QWU	38956	06/24/2021 FVGEN	39 78-1886	BRIVAL01	6350	FAN BLOWER MOTOR 14V,RP21
RPS21	719QWU	38957	06/24/2021 FVGEN	39 Nov-05	BRIVAL01	6375	HOSE, FRIDGE MOTOR,RP21
RPS21	719QWU	39133	06/28/2021 FRIVANA	1 LABCON	BRIVAL01	EX00019580	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	39162	06/28/2021 FRIVANA	1 LABCON	BRIVAL01	EX00019581	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	39133	06/28/2021 FRIVANA	SERVICE COMPLETED BY BVR 23.06.2021			
RPS21	719QWU	39162	06/28/2021 FRIVANA	SERVICE COMPLETED BY BVR 24.06.2021			
RPS21	719QWU	39133	06/28/2021 FRIVANA	1 LABCON	BRIVAL01	6429	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	39162	06/28/2021 FRIVANA	1 LABCON	BRIVAL01	6430	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	39429	07/08/2021 FRIVANA	1 LABCON	BRIVAL01	EX00019679	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	39429	07/08/2021 FRIVANA	SERVICE COMPLETED BY BVR 05/07/2021			
RPS21	719QWU	39429	07/08/2021 FRIVANA	1 LABCON	BRIVAL01	6592	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	39490	07/09/2021 TRA	0 LABOUR APPREN	Labour		
RPS21	719QWU	39490	07/09/2021 TRA	SERVICE COMPLETED BY BEN			
RPS21	719QWU	39490	07/09/2021 TRA	16 CON	YAT	Consumables	
RPS21	719QWU	39664	07/13/2021 FRIVANA	1 LABCON	BRIVAL01	EX00019797	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	39746	07/13/2021 FRIVANA	1 LABCON	BRIVAL01	EX00019829	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	39764	07/13/2021 FRIVANA	1 LABCON	BRIVAL01	EX00019830	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	39664	07/13/2021 FRIVANA	SERVICE COMPLETED BY BVR 07/07/2021			
RPS21	719QWU	39746	07/13/2021 FRIVANA	SERVICE COMPLETED BVR 08/07/2021			
RPS21	719QWU	39764	07/13/2021 FRIVANA	SERVICE COMPLETED BVR 09/07/2021			
RPS21	719QWU	39664	07/13/2021 FRIVANA	1 LABCON	BRIVAL01	6607	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	39746	07/13/2021 FRIVANA	1 LABCON	BRIVAL01	6608	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	39764	07/13/2021 FRIVANA	1 LABCON	BRIVAL01	6613	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	40001	07/23/2021 FRIVANA	1 LABCON	BRIVAL01	EX00019933	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	40045	07/23/2021 FRIVANA	1 LABCON	BRIVAL01	EX00019935	LABOUR & CONSUMABLES,RP21

RPS21	719QWU	40001	07/23/2021 FRIVANA	SERVICE COMPLETED BY BVR 21/07/2021			
RPS21	719QWU	40045	07/23/2021 FRIVANA	SERVICE COMPLETED BY BVR 19/07/2021			
RPS21	719QWU	40001	07/23/2021 FRIVANA	1 LABCON	BRIVAL01	6771	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	40045	07/23/2021 FRIVANA	1 LABCON	BRIVAL01	6756	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	40243	07/30/2021 FRIVANA	1 LABCON	BRIVAL01	EX00020054	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	40380	07/30/2021 FRIVANA	1 LABCON	BRIVAL01	EX00020055	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	40243	07/30/2021 FRIVANA	SERVICE COMPLETED BY BVR 22.07.2021			
RPS21	719QWU	40380	07/30/2021 FRIVANA	SERVICE COMPLETED BY BVR 23/07/2021			
RPS21	719QWU	40243	07/30/2021 FRIVANA	1 LABCON	BRIVAL01	6820	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	40380	07/30/2021 FRIVANA	1 LABCON	BRIVAL01	6821	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	41433	08/30/2021 FRIVANA	1 LABCON	BRIVAL01	EX00020399	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	41433	08/30/2021 FRIVANA	SERVICE COMPLETED BY BVR 30/08/2021			
RPS21	719QWU	41433	08/30/2021 FRIVANA	1 LABCON	BRIVAL01	7308	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	41278	08/30/2021 TRA	0 LABOUR	MECH1 Labour		
				SERVICE COMPLET ED BY SEAN			
				RIVETS FROM TOP RHS INSIDE MISSING			
RPS21	719QWU	41278	08/30/2021 TRA				
RPS21	719QWU	41278	08/30/2021 TRA	16 CON	YAT Consumables		
RPS21	719QWU	41615	09/02/2021 FRIVANA	1 LABCON	BRIVAL01	EX00020473	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	41615	09/02/2021 FRIVANA	SERVICE COMPLETED BY BVR 01/09/2021			
RPS21	719QWU	41615	09/02/2021 FRIVANA	1 LABCON	BRIVAL01	7332	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	42158	09/13/2021 FRIVANA	1 LABCON	BRIVAL01	EX00020647	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	42158	09/13/2021 FRIVANA	SERVICE COMPLETED BY BVR 13/09/2021			
RPS21	719QWU	42158	09/13/2021 FRIVANA	1 LABCON	BRIVAL01	7499	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	42169	09/16/2021 FRIVANA	1 LABCON	BRIVAL01	EX00020650	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	42169	09/16/2021 FRIVANA	SERVICE COMPLETED BY BVR 16/09/2021			
RPS21	719QWU	42169	09/16/2021 FRIVANA	1 LABCON	BRIVAL01	7544	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	42599	10/05/2021 FRIVANA	1 LABCON	BRIVAL01	EX00020803	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	42599	10/05/2021 FRIVANA	SERVICE COMPLETED BY BVR 05/10/2021			
RPS21	719QWU	42599	10/05/2021 FRIVANA	1 LABCON	BRIVAL01	7813	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	42906	10/12/2021 FVGEN	39 LAB	BRIVAL01	EX00020933	Labour,RP21
RPS21	719QWU	42906	10/12/2021 FVGEN	39 R404A	BRIVAL01	EX00020933	GAS R404A,RP21
RPS21	719QWU	42906	10/12/2021 FVGEN	SERVICE COMPLETED BY BVR 12/10/2021			
RPS21	719QWU	42906	10/12/2021 FVGEN	39 R404A	BRIVAL01	7977	GAS R404A,RP21
RPS21	719QWU	42906	10/12/2021 FVGEN	39 LAB	BRIVAL01	7977	Labour,RP21
RPS21	719QWU	42916	10/13/2021 FRIVANA	1 LABCON	BRIVAL01	EX00020935	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	42916	10/13/2021 FRIVANA	SERVICE COMPLETED BY BVR 13/10/2021			
RPS21	719QWU	42916	10/13/2021 FRIVANA	1 LABCON	BRIVAL01	7946	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	42905	10/13/2021 FVGEN	39 PART	BRIVAL01	EX00020932	67-2218 Condenser Coil,RP21

RPS21	719QWU	42905	10/13/2021 FVGEN	39 910372	BRIVAL01	EX00020932	CLAMP TUBE - FRIDGE MOTOR,RP21
RPS21	719QWU	42905	10/13/2021 FVGEN	39 PART	BRIVAL01	EX00020932	11-8480 SB Coolant Hose,RP21
RPS21	719QWU	42905	10/13/2021 FVGEN	39 PART	BRIVAL01	EX00020932	BROWN TIP SOLDER,RP21
RPS21	719QWU	42905	10/13/2021 FVGEN	39 PART	BRIVAL01	EX00020932	Anti-Freeze Coolant,RP21
RPS21	719QWU	42905	10/13/2021 FVGEN	39 R404A	BRIVAL01	EX00020932	GAS R404A,RP21
							Consumables
RPS21	719QWU	42905	10/13/2021 FVGEN	39 CON	BRIVAL01	EX00020932	,RP21
RPS21	719QWU	42905	10/13/2021 FVGEN	39 LAB	BRIVAL01	EX00020932	Labour,RP21
RPS21	719QWU	42905	10/13/2021 FVGEN	SERVICE COMPLETED BY BVR 13/10/2021			
RPS21	719QWU	42905	10/13/2021 FVGEN	39 LAB	BRIVAL01	7950	Labour,RP21
							Consumables
RPS21	719QWU	42905	10/13/2021 FVGEN	39 CON	BRIVAL01	7950	,RP21
RPS21	719QWU	42905	10/13/2021 FVGEN	39 R404A	BRIVAL01	7950	GAS R404A,RP21
RPS21	719QWU	42905	10/13/2021 FVGEN	39 PART	BRIVAL01	7950	Anti-Freeze Coolant,RP21
RPS21	719QWU	42905	10/13/2021 FVGEN	39 PART	BRIVAL01	7950	BROWN TIP SOLDER,RP21
RPS21	719QWU	42905	10/13/2021 FVGEN	39 PART	BRIVAL01	7950	11-8480 SB Coolant Hose,RP21
RPS21	719QWU	42905	10/13/2021 FVGEN	39 910372	BRIVAL01	7950	CLAMP TUBE - FRIDGE MOTOR,RP21
RPS21	719QWU	42905	10/13/2021 FVGEN	39 PART	BRIVAL01	7950	67-2218 Condenser Coil,RP21
RPS21	719QWU	43235	10/25/2021 FRIVANA	1 LABCON	BRIVAL01	EX00021080	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	43235	10/25/2021 FRIVANA	SERVICE COMPLETED BY BVR 25/10/2021			
RPS21	719QWU	43235	10/25/2021 FRIVANA	1 LABCON	BRIVAL01	8062	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	43433	11/02/2021 FRIVANA	1 LABCON	BRIVAL01	EX00021177	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	43433	11/02/2021 FRIVANA	SERVICE COMPLETED BY BVR 02/11/2021			
RPS21	719QWU	43433	11/02/2021 FRIVANA	1 LABCON	BRIVAL01	8124	LABOUR & CONSUMABLES,RP21
RPS21	719QWU	43362	11/02/2021 TRA	1 LABOUR	Labour		0
				SERVICE COMPLETED BY MICK, BEN & KEIRAN			
				FITTED TRACKER			
RPS21	719QWU	43362	11/02/2021 TRA				
RPS21	719QWU	43362	11/02/2021 TRA	0 LABOUR	MECH	Labour - Internal	
RPS21	719QWU	43362	11/02/2021 TRA	0 LABOUR	APPREN	Labour - Internal	
RPS21	719QWU	43362	11/02/2021 TRA	0 LABOUR	APPREN	1 85 85	
RPS21	719QWU	43362	11/02/2021 TRA	16 CON	YAT	Consumables	
RPS21	719QWU	43973	12/01/2021 GEN	39 45-2699	BRIVAL01	EX00021494	ALTERNATOR 120A NO FAN,RP21
							Consumables
RPS21	719QWU	43973	12/01/2021 GEN	39 CON	BRIVAL01	EX00021494	,RP21

RPS21	719QWU	43973	12/01/2021 GEN	39 LAB	BRIVAL01	EX00021494	Labour,RP21
RPS21	719QWU	43973	12/01/2021 GEN	39 LAB	BRIVAL01	8459	Labour,RP21
RPS21	719QWU	43973	12/01/2021 GEN	39 CON	BRIVAL01	8459	Consumables,RP21
RPS21	719QWU	43973	12/01/2021 GEN	39 45-2699	BRIVAL01	8459	ALTERNATOR 120A NO FAN,RP21
RPS21	719QWU	44279	12/15/2021 TRA	0 LABOUR	APPREN Labour		
RPS21	719QWU	44279	12/15/2021 TRA	SERVICE COMPLETED BY BEN AND MICK			
RPS21	719QWU	44279	12/15/2021 TRA	0 LABOUR	MECH	1 85 85	
RPS21	719QWU	44279	12/15/2021 TRA	16 CON	YAT	Consumables	
RPS21	719QWU	44363	12/16/2021 EXOINS	1 LABOUR	MECH Labour		
				VEHICLE PASSED ANNUAL ROADWORK RTHY INSPECTION. ATTEMPT # 1			
				INSPECTION COMPLETED BY DIESEL SERVICES			
RPS21	719QWU	44363	12/16/2021 EXOINS				
RPS21	719QWU	44363	12/16/2021 GEN	39 PART	DIESER01	EX00021966	GENERAL PART CODE,RM21
RPS21	719QWU	44363	12/16/2021 GEN	39 PART	DIESER01	EX00021966	GENERAL PART CODE,RP21
RPS21	719QWU	44363	12/16/2021 GEN	39 LAB	DIESER01	EX00021966	Labour,RP21
RPS21	719QWU	44363	12/16/2021 GEN	39 LAB	DIESER01	EX00021966	Labour,RP21
RPS21	719QWU	44363	12/16/2021 GEN	39 LAB	DIESER01	EX00021966	Labour,RP21
RPS21	719QWU	44363	12/16/2021 GEN	39 CON	DIESER01	EX00021966	Consumables,RP21
RPS21	719QWU	44363	12/16/2021 GEN	39 CON	DIESER01	27110	Consumables,RP21
RPS21	719QWU	44363	12/16/2021 GEN	39 LAB	DIESER01	27110	Labour,RP21
RPS21	719QWU	44363	12/16/2021 GEN	39 LAB	DIESER01	27110	Labour,RP21
RPS21	719QWU	44363	12/16/2021 GEN	39 LAB	DIESER01	27110	Labour,RP21

RPS21	719QWU	44363	12/16/2021 GEN	39 PART	DIESER01	27110	GENERAL PART CODE,RP21
RPS21	719QWU	44363	12/16/2021 GEN	39 PART	DIESER01	27110	GENERAL PART CODE,RM21
RPS21	719QWU	44363	12/16/2021 TRA	1 LABOUR Labour			0
RPS21	719QWU	44363	12/16/2021 TRA	SERVICE COMPLETED.			
RPS21	719QWU	44363	12/16/2021 TRB	1 LABOUR Labour			0
RPS21	719QWU	44363	12/16/2021 TRB	SERVICE COMPLETED.			
RPS21	719QWU	44363	12/16/2021 trc	1 LABOUR Labour			0

SERVICE
COMPLET
ED BY
DIESEL
SERVICES
INV#

C&D
SERVICE
WITH
BEARINGS
PACK ALL
BEARINGS
SET ALL
BEARINGS
REPLACE 7
PIN
TRAILER
SOCKET
REPLACE
KING PIN
DEGREASE
AND
DROP
BACK TO
YARD

RPS21	719QWU	44363	12/16/2021 trc
-------	--------	-------	----------------

RPS21	719QWU	44421	12/22/2021 GEN	39 KZ1012.01	GIBBS01	EX00021819	50MM BOLT IN KING PIN,RP21
RPS21	719QWU	44421	12/22/2021 GEN	39 2.57E+08	GIBBS01	EX00021819	Hub Seal Grease, BPW, Eco Plus,RP21
RPS21	719QWU	44421	12/22/2021 GEN	39 2.57E+08	GIBBS01	1604141	Hub Seal Grease, BPW, Eco Plus,RP21
RPS21	719QWU	44421	12/22/2021 GEN	39 KZ1012.01	GIBBS01	1604141	50MM BOLT IN KING PIN,RP21
RPS21	719QWU	44656	01/12/2022 FRIVANSE	39 PART	BRIVAL01	EX00022003	GENERAL PART CODE,RP21
RPS21	719QWU	44656	01/12/2022 FRIVANSE	39 PART	BRIVAL01	EX00022003	GENERAL PART CODE,RP21

RPS21	719QWU	44656	01/12/2022 FRIVANSE	39 CON	BRIVAL01	EX00022003	Consumables,RP21
RPS21	719QWU	44656	01/12/2022 FRIVANSE	39 LAB	BRIVAL01	EX00022003	Labour,RP21
RPS21	719QWU	44656	01/12/2022 FRIVANSE	39 LAB	BRIVAL01	8858	Labour,RP21
RPS21	719QWU	44656	01/12/2022 FRIVANSE	39 CON	BRIVAL01	8858	Consumables,RP21
RPS21	719QWU	44656	01/12/2022 FRIVANSE	39 PART	BRIVAL01	8858	GENERAL PART CODE,RP21
RPS21	719QWU	44656	01/12/2022 FRIVANSE	39 PART	BRIVAL01	8858	GENERAL PART CODE,RP21
RPS21	719QWU	44752	01/18/2022 TRA	1 LABOUR	APPREN	Labour	
				SERVICE COMPLETED KEIRAN-REVITTED PORTION OF F TRACK			
RPS21	719QWU	44752	01/18/2022 TRA				
RPS21	719QWU	44752	01/18/2022 TRA	16 CON	YAT	Consumables	
RPS21	719QWU	44897	01/21/2022 GEN	39 40-0974	BRIVAL01	EX00022163	GRADED SENSOR,RP21
RPS21	719QWU	44897	01/21/2022 GEN	39 CON	BRIVAL01	EX00022163	Consumables,RP21
RPS21	719QWU	44897	01/21/2022 GEN	39 LAB	BRIVAL01	EX00022163	Labour,RP21
RPS21	719QWU	44897	01/21/2022 GEN	39 LAB	BRIVAL01	9035	Labour,RP21
RPS21	719QWU	44897	01/21/2022 GEN	39 CON	BRIVAL01	9035	Consumables,RP21
RPS21	719QWU	44897	01/21/2022 GEN	39 40-0974	BRIVAL01	9035	GRADED SENSOR,RP21
RPS21	719QWU	45566	02/17/2022 TRA	0 LABOUR	MECH1	Labour	
				SERVICE COMPLETED BY IAN			
				REPLACE MISSING ROOF LIGHT			
RPS21	719QWU	45566	02/17/2022 TRA				

RPS21	719QWU	45566	02/17/2022 TRA	16 CON	YAT	Consumables	
RPS21	719QWU	45566	02/17/2022 TRA	14 91700BL	YAT	Clearance Light, LED Amber, Narva	
RPS21	719QWU	46025	03/09/2022 GEN	39 CON	BRIVAL01	EX00022878	Consumables,RP21
RPS21	719QWU	46025	03/09/2022 GEN	39 LAB	BRIVAL01	EX00022878	Labour,RP21
RPS21	719QWU	46025	03/09/2022 GEN	SERVICE COMPLETED BY 09.03.2022			
RPS21	719QWU	46025	03/09/2022 GEN	39 LAB	BRIVAL01	9583	Labour,RP21
RPS21	719QWU	46025	03/09/2022 GEN	39 CON	BRIVAL01	9583	Consumables,RP21
RPS21	719QWU	46284	03/23/2022 DEFECT	0 LABOUR	SUBMEC	Labour	
RPS21	719QWU	46284	03/23/2022 DEFECT	DEFECT CLEARED BY BRENDAN 23/03/20222			
				Reported Defect :- Defect Code : 00006898 Defect Reference : WO41278 Date : 30/08/20 21 Descriptio n of Defect : RIVETS FROM TOP RHS INSIDE MISSING			
RPS21	719QWU	46284	03/23/2022 DEFECT				
RPS21	719QWU	46284	03/23/2022 TRA	0 LABOUR	SUBMEC	Labour	

				SERVICE COMPLET ED BY BRENDAN AND TYLER				
				EBS SYSTEM ALL CHECKED				
RPS21	719QWU	46284	03/23/2022 TRA					
RPS21	719QWU	46284	03/23/2022 TRA	0 LABOUR	APPREN	Labour - Internal		
RPS21	719QWU	46284	03/23/2022 TRA	16 CON		YAT Consumables		
RPS21	719QWU	46490	03/25/2022 FRIVANSE	39	100417	BRIVAL01	EX00023122	Filter Service Kit, Fridge Motor, SLX-400,RP21
RPS21	719QWU	46490	03/25/2022 FRIVANSE	39	781360	BRIVAL01	EX00023122	FAN BELT, QTK FRIDGE MOTOR,RP21
RPS21	719QWU	46490	03/25/2022 FRIVANSE	39	CON	BRIVAL01	EX00023122	Consumables,RP21
RPS21	719QWU	46490	03/25/2022 FRIVANSE	39	LAB	BRIVAL01	EX00023122	Labour,RP21
RPS21	719QWU	46490	03/25/2022 FRIVANSE	SERVICE COMPLETED BY BVR 24.03.2022				
RPS21	719QWU	46490	03/25/2022 FRIVANSE	39	LAB	BRIVAL01	9876	Labour,RP21
RPS21	719QWU	46490	03/25/2022 FRIVANSE	39	CON	BRIVAL01	9876	Consumables,RP21
RPS21	719QWU	46490	03/25/2022 FRIVANSE	39	781360	BRIVAL01	9876	FAN BELT, QTK FRIDGE MOTOR,RP21
RPS21	719QWU	46490	03/25/2022 FRIVANSE	39	100417	BRIVAL01	9876	Filter Service Kit, Fridge Motor, SLX-400,RP21
RPS21	719QWU	47153	04/22/2022 TRA	0 LABOUR	MECH1	Labour		

				COMPLET ED BY IAN, BRENDAN AND TYLER				
				REPAIR REAR ENTRY LADDER REPLACE 1X REAR RED REFLECTO R				
				SAFETY RAILS SURROUN DING REAR EVAPORA TOR REQUIRE REPAIR NEXT SERVICE				
RPS21	719QWU	47153	04/22/2022 TRA					
RPS21	719QWU	47153	04/22/2022 TRA	0 LABOUR	SUBMEC	Labour - Internal		
RPS21	719QWU	47153	04/22/2022 TRA	0 LABOUR	TRADEA	Labour - Internal		
RPS21	719QWU	47153	04/22/2022 TRA	16 CON		YAT Consumables		
RPS21	719QWU	47153	04/22/2022 TRA	11 84022BL		YAT RED REFLECTOR CENTRE		
RPS21	719QWU	47244	04/29/2022 TYRES	15 11001573		BRIAUS01 EX00023461		TYRE 11R22.5 148/145L 16 FS T559,719QWU
RPS21	719QWU	47244	04/29/2022 TYRES	15 11001573		BRIAUS01 4.81E+09		TYRE 11R22.5 148/145L 16 FS T559,719QWU
RPS21	719QWU	47454	05/05/2022 GEN	39 132572		BRIVAL01 EX00023572		PUMP WATER TK486 W/GASKET FRIDGE,RP21
RPS21	719QWU	47454	05/05/2022 GEN	39 PART		BRIVAL01 EX00023572		GENERAL PART CODE,RP21
RPS21	719QWU	47454	05/05/2022 GEN	39 416538		BRIVAL01 EX00023572		WATER TEMP SENSOR,RP21
								Consuma bles ,RP21
RPS21	719QWU	47454	05/05/2022 GEN	39 CON		BRIVAL01 EX00023572		

RPS21	719QWU	47454	05/05/2022 GEN	39 LAB	BRIVAL01	EX00023572	Labour,RP21
RPS21	719QWU	47454	05/05/2022 GEN	SERVICE COMPLETED BY BVR 05.05.2022			
RPS21	719QWU	47454	05/05/2022 GEN	39 132572	BRIVAL01	10526	PUMP WATER TK486 W/GASKET FRIDGE,RP21
RPS21	719QWU	47454	05/05/2022 GEN	39 PART	BRIVAL01	10526	GENERAL PART CODE,RP21
RPS21	719QWU	47454	05/05/2022 GEN	39 416538	BRIVAL01	10526	WATER TEMP SENSOR,RP21
							Consumables
RPS21	719QWU	47454	05/05/2022 GEN	39 CON	BRIVAL01	10526	,RP21
RPS21	719QWU	47454	05/05/2022 GEN	39 LAB	BRIVAL01	10526	Labour,RP21
				AIR GAUGE: 20.9 ADJUSTED :20.8 WEIGHBRI DGE: 20.5			
				AIR GAUGE CALIBRATION COMPLETED CORRECTLY.			
RPS21	719QWU	48128	05/30/2022 WEICAL				
RPS21	719QWU	48240	06/09/2022 TYRES	15 77000180	BRIAUS01	EX00023982	CASE STOCK 11-22.5,RP21
RPS21	719QWU	48240	06/09/2022 TYRES	15 77000180	BRIAUS01	87865501	CASE STOCK 11-22.5,RP21
RPS21	719QWU	48775	07/05/2022 TRA	1 LABOUR	Labour		0
RPS21	719QWU	48775	07/05/2022 TRA	SERVICE COMPLETED.			
RPS21	719QWU	48775	07/05/2022 trb	0 LABOUR	APPRENB Labour		

				SERVICE COMPLET ED BY BEN			
				ALL WHEEL BEARINGS WENT UP 1/2 TURN INSPECTE D LHS MIDDLE WHEL BEARING - OK			
RPS21	719QWU	48775	07/05/2022 trb				
RPS21	719QWU	48775	07/05/2022 trb	16 CON	YAT	Consumables	
RPS21	719QWU	48833	07/07/2022 GEN	39 45-2258	BRIVAL01	EX00024301	120 AMP ALTERNATOR,RP21
							Consuma bles
RPS21	719QWU	48833	07/07/2022 GEN	39 CON	BRIVAL01	EX00024301	,RP21
RPS21	719QWU	48833	07/07/2022 GEN	39 LAB	BRIVAL01	EX00024301	Labour,RP21

				SERVICE COMPLET ED BY BVR 7.7.2022				
				FOUND UNIT NOT CHARGIN G, TRACED TO FAULTY ALTERNAT OR REMOVE AND REPLACE UNSERVIC ABLE ALTERNAT OR AS REQUIRED				
RPS21	719QWU	48833	07/07/2022 GEN					
RPS21	719QWU	48833	07/07/2022 GEN	39 45-2258	BRIVAL01	10803	120 AMP ALTERNATOR,RP21	
RPS21	719QWU	48833	07/07/2022 GEN	39 CON	BRIVAL01	10803	Consumables,RP21	
RPS21	719QWU	48833	07/07/2022 GEN	39 LAB	BRIVAL01	10803	Labour,RP21	
RPS21	719QWU	49314	07/23/2022 GEN	0 LABOUR	APPRENB Labour			
				REPAIR COMPLET ED BY BEN				
				RE- ATTACHE D POGO RAIL RHS MIDDLE				
RPS21	719QWU	49314	07/23/2022 GEN					
RPS21	719QWU	49314	07/23/2022 GEN	16 CON	YAT	Consumables		

RPS21	719QWU	49738	08/08/2022 TRA	0 LABOUR APPRENB	Labour		
RPS21	719QWU	49738	08/08/2022 TRA	SERVICE COMPLETED BY BEN			
RPS21	719QWU	49738	08/08/2022 TRA	16 CON	YAT	Consumables	
RPS21	719QWU	49898	08/15/2022 TYRES	15 77000180	BRI AUS01	EX00024773	CASE STOCK 11-22.5,RP21
RPS21	719QWU	49898	08/15/2022 TYRES	15 33000096	BRI AUS01	EX00024773	PUNCTURE REPAIR TBR,RP21
RPS21	719QWU	49898	08/15/2022 TYRES	15 33000096	BRI AUS01	88209310	PUNCTURE REPAIR TBR,RP21
RPS21	719QWU	49898	08/15/2022 TYRES	15 77000180	BRI AUS01	88209310	CASE STOCK 11-22.5,RP21
RPS21	719QWU	50444	09/06/2022 TRA	0 LABOUR APPRENB	Labour		
RPS21	719QWU	50444	09/06/2022 TRA	SERVICE COMPLETED BY BEN			
RPS21	719QWU	50444	09/06/2022 TRA	16 CON	YAT	Consumables	
RPS21	719QWU	50793	09/21/2022 GEN	39 78-0603	BRIVAL01	EX00025243	SB Series Fridge motor fanbelt,RP21
RPS21	719QWU	50793	09/21/2022 GEN	39 78-0629	BRIVAL01	EX00025243	SB series fridge motor fanbelt,RP21
RPS21	719QWU	50793	09/21/2022 GEN	39 LAB	BRIVAL01	EX00025243	Labour,RP21
							Consumables
RPS21	719QWU	50793	09/21/2022 GEN	39 CON	BRIVAL01	EX00025243	,RP21
				SERVICE COMPLETED BY BVR			
				21.09.2022			
				TRAVEL TO SITE AND INSOECT UNIT - REMOVE AND REPLACE NOISY AND WORN FAN BELTS AND RUN UNIT TO TEMPERATURE			
RPS21	719QWU	50793	09/21/2022 GEN				
							Consumables
RPS21	719QWU	50793	09/21/2022 GEN	39 CON	BRIVAL01	12345	,RP21

RPS21	719QWU	50793	09/21/2022 GEN	39 LAB	BRIVAL01	12345	Labour,RP21
RPS21	719QWU	50793	09/21/2022 GEN	39 78-0629	BRIVAL01	12345	SB series fridge motor fanbelt,RP21
RPS21	719QWU	50793	09/21/2022 GEN	39 78-0603	BRIVAL01	12345	SB Series Fridge motor fanbelt,RP21
				AIR			
				GAUGE:			
				19.50			
				ADJUSTED			
				: 19.00			
				WEIGHBRI			
				DGE:			
				19.50			
				AIR			
				GAUGE			
				CALIBRATI			
				ON			
				COMPLET			
				ED			
				CORRECTL			
RPS21	719QWU	50965	09/29/2022 WEICAL	Y.			

RPS21	719QWU	51503	10/18/2022 DEFECT	Reported Defect :- Defect Code : 00007525 Defect Reference : WO47153 Date : 21/04/20 22 Descriptio n of Defect : SAFETY RAILS SURROUN DING REAR EVAPORA TOR REQUIRE REPAIR NEXT SERVICE
-------	--------	-------	-------------------	--

				Defect :-
				Defect
				Code :
				00008049
				Defect
				Reference
				: 42085
				Date :
				10/09/20
				22
				Description of
				Defect :
				REAR
				MOTOR
				FAULT
				AND
				COVER
				DAMAGE
				D, REAR
				SHOCK -
				LEFT
				MISSING
				STRAP -
				RIGHT
				STRAP
RPS21	719QWU	51503	10/18/2022 DEFECT	LOOSE

Defect :-
Defect
Code :
00008088
Defect
Reference
: 37353
Date :
09/09/20
22
Descriptio
n of
Defect :
ALARM -
REAR FAN
MALFUNC
TION,
REAR FAN
HAS BEEN
DAMAGE
D - WAS
NOT IN
THIS
CONDITIO
N LAST
TIME I
LOADED

RPS21 719QWU 51503 10/18/2022 DEFECT

RPS21 719QWU 51503 10/18/2022 TRA 0 LABOUR APPRENB Labour

				SERVICE COMPLET ED BY BEN, TYLER AND FLYNN				
				BOLTED TWO LOCKS TO THE ROOF SUPPORT HOLDING THE SAFETY RAILS TO THE REAR EVAPORA TOR BVR DONE REPAIRS TO THE FRIDGE MOTOR				
RPS21	719QWU	51503	10/18/2022 TRA					
RPS21	719QWU	51503	10/18/2022 TRA	0 LABOUR	APPREN	Labour - Internal		
RPS21	719QWU	51503	10/18/2022 TRA	0 LABOUR	APPREN	Labour - Internal		
RPS21	719QWU	51503	10/18/2022 TRA	16 CON		YAT Consumables		
RPS21	719QWU	51565	10/21/2022 FVGEN	39 PART		BRIVAL01 EX00025601	GENERAL PART CODE,RP21	
RPS21	719QWU	51565	10/21/2022 FVGEN	39 CON		BRIVAL01 EX00025601	Consumables,RP21	
RPS21	719QWU	51565	10/21/2022 FVGEN	39 LAB		BRIVAL01 EX00025601	Labour,RP21	
RPS21	719QWU	51565	10/21/2022 FVGEN	TRAVEL TO SITE AND INSPECT UNIT, REMOVE AND REPLACE FLAT BATTERY				
RPS21	719QWU	51565	10/21/2022 FVGEN	39 LAB		BRIVAL01 12691	Labour,RP21	
							Consumables,RP21	
RPS21	719QWU	51565	10/21/2022 FVGEN	39 CON		BRIVAL01 12691		
RPS21	719QWU	51565	10/21/2022 FVGEN	39 PART		BRIVAL01 12691	GENERAL PART CODE,RP21	

AIR
GAUGE:
19250
ADJUSTED
: 18750
WEIGHBRI
DGE:
18500

AIR
GAUGE
CALIBRATI
ON
COMPLET
ED
CORRECTL
Y.

RPS21	719QWU	51775	10/28/2022 WEICAL			
RPS21	719QWU	53158	01/05/2023 FRIVCAL	1 LABOUR	MECH	Labour
RPS21	719QWU	53164	01/06/2023 FRIVANB	0 LABOUR	MECH	Labour

					VAN "B" SERVICE COMPLET ED.
					FRIDGE VAN UNIT CALIBRAT ED @ SERVICE.
					SERVICE COMPLET ED BY BVR.
					OIL 14L (Customer Supplied) CALIBRATI ON CERTIFICA TE R+R ENGINE OIL R+R
RPS21	719QWU	53164	01/06/2023	FRIVANB	

RPS21	719QWU	53164	01/06/2023 FVGEN	35 10-417	BRIVAL01	EX00026594	FILTER KIT (FRIDGE MOTOR), Consumables
RPS21	719QWU	53164	01/06/2023 FVGEN	35 CON	BRIVAL01	EX00026594	,
RPS21	719QWU	53164	01/06/2023 FVGEN	35 CALCERT	BRIVAL01	EX00026594	CALIBRATE UNIT,
RPS21	719QWU	53164	01/06/2023 FVGEN	35 42-0100	BRIVAL01	EX00026594	STOP FUEL SOLENOID, FRIDGE MOTORS,
RPS21	719QWU	53164	01/06/2023 FVGEN	35 15W40	BRIVAL01	EX00026594	ENGINE OIL,
RPS21	719QWU	53164	01/06/2023 FVGEN	35 LABEXT	BRIVAL01	EX00026594	Labour External,
RPS21	719QWU	53164	01/06/2023 FVGEN	35 33-2230	BRIVAL01	EX00026594	SOLENOID O-RING FRIDGE MOTORS,
RPS21	719QWU	53164	01/06/2023 FVGEN	35 33-2230	BRIVAL01	13806	SOLENOID O-RING FRIDGE MOTORS,
RPS21	719QWU	53164	01/06/2023 FVGEN	35 LABEXT	BRIVAL01	13806	Labour External,
RPS21	719QWU	53164	01/06/2023 FVGEN	35 15W40	BRIVAL01	13806	ENGINE OIL,
RPS21	719QWU	53164	01/06/2023 FVGEN	35 42-0100	BRIVAL01	13806	STOP FUEL SOLENOID, FRIDGE MOTORS,
RPS21	719QWU	53164	01/06/2023 FVGEN	35 CALCERT	BRIVAL01	13806	CALIBRATE UNIT, Consumables
RPS21	719QWU	53164	01/06/2023 FVGEN	35 CON	BRIVAL01	13806	,
RPS21	719QWU	53164	01/06/2023 FVGEN	35 10-417	BRIVAL01	13806	FILTER KIT (FRIDGE MOTOR),
RPS21	719QWU	53286	01/09/2023 EXOINS	1 LABOUR	MECH Labour		VEHICLE PASSED ANNUAL ROADWORK RTHY INSPECTION. ATTEMPT # INSPECTION COMPLETED BY
RPS21	719QWU	53286	01/09/2023 EXOINS				
RPS21	719QWU	53287	01/10/2023 TRA	1 LABOUR	MECH	Labour	
RPS21	719QWU	53287	01/10/2023 TRA	SERVICE COMPLETED.			
RPS21	719QWU	53287	01/10/2023 TRB	1 LABOUR	MECH	Labour	
RPS21	719QWU	53287	01/10/2023 TRB	SERVICE COMPLETED.			
RPS21	719QWU	53287	01/10/2023 TRC	1 LABOUR	MECH	Labour	

				SERVICE COMPLET ED. DIESEL SERVICES IN 28171			
				ADJUST WHEEL BEARINGS TENSION SUSPENS ION POINTS ADJUST BRAKES REPLACE HUB CAP O RING TENSION HUBCAP DEGREASE AND DROP BACK			
RPS21	719QWU	53287	01/10/2023 TRC				
RPS21	719QWU	53287	01/10/2023 TRC	1 LABEXT	DIESER01	EX00026684	Labour External, Consumables
RPS21	719QWU	53287	01/10/2023 TRC	1 CON	DIESER01	EX00026684	,
RPS21	719QWU	53287	01/10/2023 TRC	1 LABEXT	DIESER01	28171	Labour External, Consumables
RPS21	719QWU	53287	01/10/2023 TRC	1 CON	DIESER01	28171	,
RPS21	719QWU	53277	01/10/2023 TYRES	15 11002822	BRIAUS01	EX00026649	11R2.5 148L 16 BS R168,
RPS21	719QWU	53277	01/10/2023 TYRES	15 33000084	BRIAUS01	EX00026649	FIT TBR TYRE,
RPS21	719QWU	53277	01/10/2023 TYRES	15 33000241	BRIAUS01	EX00026649	SCRAP TYRES TBR,
RPS21	719QWU	53277	01/10/2023 TYRES	15 33000125	BRIAUS01	EX00026649	ETA MIN FEE,
RPS21	719QWU	53277	01/10/2023 TYRES	15 33000125	BRIAUS01	88979066	ETA MIN FEE,

RPS21	719QWU	53277	01/10/2023 TYRES	15 33000241	BRIAUS01	88979066	SCRAP TYRES TBR,
RPS21	719QWU	53277	01/10/2023 TYRES	15 33000084	BRIAUS01	88979066	FIT TBR TYRE,
RPS21	719QWU	53277	01/10/2023 TYRES	15 11002822	BRIAUS01	88979066	11R2.5 148L 16 BS R168,
							Consuma
							bles
RPS21	719QWU	53645	01/25/2023 FVGEN	39 CON	BRIVAL01	EX00026861	,RP21
RPS21	719QWU	53645	01/25/2023 FVGEN	39 LAB	BRIVAL01	EX00026861	Labour,RP21
RPS21	719QWU	53645	01/25/2023 FVGEN	Service completed by BVR 19/01/2023 - Travelled to site and fit missing panel (supplied by customer) - Unit run on test - Pretrip passed.			
RPS21	719QWU	53645	01/25/2023 FVGEN	39 LAB	BRIVAL01	14136	Labour,RP21
							Consuma
							bles
RPS21	719QWU	53645	01/25/2023 FVGEN	39 CON	BRIVAL01	14136	,RP21
				ATTEND			
				AFTER			
				HOURS			
				CALL OUT.			
				CHECK			
				OVER			
				HOLLAND			
				TURNTAB			
				LE.			
				CHECK			
				PIN ON			
				TRAILER			
				ADJUST			
				TRAILER			
				BRAKES			
				NO			
				VISUAL			
				FAULTS			
				FOUND			
				NOTE:			
				TURNTAB			
				LE JAWS			
				AND KING			
				PIN			
RPS21	719QWU	53601	01/25/2023 GEN	WORN			

RPS21	719QWU	53601	01/25/2023 GEN	39 LABEXT	AUTELE01	EX00026819	Labour External,
RPS21	719QWU	53601	01/25/2023 GEN	39 CALL OUT FEE	AUTELE01	EX00026819	Call Out After Hours/Off Site,
RPS21	719QWU	53601	01/25/2023 GEN	39 CALL OUT FEE	AUTELE01	9665	Call Out After Hours/Off Site,
RPS21	719QWU	53601	01/25/2023 GEN	39 LABEXT	AUTELE01	9665	Labour External,
RPS21	719QWU	54462	02/22/2023 TYRES	15 11004117	BRIAUS01	EX00027378	11R22.5 148/145L FS FT469,
RPS21	719QWU	54462	02/22/2023 TYRES	15 77000180	BRIAUS01	EX00027378	CASE STOCK 11-22.5,
RPS21	719QWU	54462	02/22/2023 TYRES	15 33000084	BRIAUS01	EX00027378	FIT TBR TYRE,
RPS21	719QWU	54462	02/22/2023 TYRES	15 33000114	BRIAUS01	EX00027378	RE-TORQUE TRUCK WHEEL EA WHEEL,
RPS21	719QWU	54462	02/22/2023 TYRES	15 33000517	BRIAUS01	EX00027378	REMOVAL: CUSTOMER PULL POINT,
RPS21	719QWU	54462	02/22/2023 TYRES	15 33000517	BRIAUS01	89214359	REMOVAL: CUSTOMER PULL POINT,
RPS21	719QWU	54462	02/22/2023 TYRES	15 33000114	BRIAUS01	89214359	RE-TORQUE TRUCK WHEEL EA WHEEL,
RPS21	719QWU	54462	02/22/2023 TYRES	15 33000084	BRIAUS01	89214359	FIT TBR TYRE,
RPS21	719QWU	54462	02/22/2023 TYRES	15 77000180	BRIAUS01	89214359	CASE STOCK 11-22.5,
RPS21	719QWU	54462	02/22/2023 TYRES	15 11004117	BRIAUS01	89214359	11R22.5 148/145L FS FT469,
RPS21	719QWU	55089	03/23/2023 TYRES	15 11004117	BRIAUS01	EX00027728	11R22.5 148/145L FS FT469,
RPS21	719QWU	55089	03/23/2023 TYRES	15 77000180	BRIAUS01	EX00027728	CASE STOCK 11-22.5,
RPS21	719QWU	55089	03/23/2023 TYRES	15 33000517	BRIAUS01	EX00027728	REMOVAL: CUSTOMER PULL POINT,
RPS21	719QWU	55089	03/23/2023 TYRES	15 33000517	BRIAUS01	EX00027728	REMOVAL: CUSTOMER PULL POINT,
RPS21	719QWU	55089	03/23/2023 TYRES	15 33000085	BRIAUS01	EX00027728	ROTATE TBR TYRE,
RPS21	719QWU	55089	03/23/2023 TYRES	15 33000085	BRIAUS01	89377786	ROTATE TBR TYRE,
RPS21	719QWU	55089	03/23/2023 TYRES	15 33000517	BRIAUS01	89377786	REMOVAL: CUSTOMER PULL POINT,
RPS21	719QWU	55089	03/23/2023 TYRES	15 33000517	BRIAUS01	89377786	REMOVAL: CUSTOMER PULL POINT,
RPS21	719QWU	55089	03/23/2023 TYRES	15 77000180	BRIAUS01	89377786	CASE STOCK 11-22.5,
RPS21	719QWU	55089	03/23/2023 TYRES	15 11004117	BRIAUS01	89377786	11R22.5 148/145L FS FT469,
RPS21	719QWU	55150	03/27/2023 DEFECT	1 LABOUR	MECH	Labour	
RPS21	719QWU	55150	03/27/2023 DEFECT				
RPS21	719QWU	55150	03/27/2023 DEFECT	DEFECT CLEARED.			

RPS21	719QWU	55520	04/12/2023 FVGEN	39 LAB	BRIVAL01	EX00028007	Labour,RP21
RPS21	719QWU	55520	04/12/2023 FVGEN	Service completed by BVR 31/03/2023 - Download data as per BVR specifications			
RPS21	719QWU	55520	04/12/2023 FVGEN	39 LAB	BRIVAL01	15423	Labour,RP21
							Consumables
RPS21	719QWU	55520	04/12/2023 FVGEN	39 CON	BRIVAL01	15423	,RP21
				AIR GAUGE: 20000 ADJUSTED : 20600 WEIGHBRI DGE:20300			
				AIR GAUGE CALIBRATION COMPLETED CORRECTLY.			
RPS21	719QWU	55695	04/17/2023 WEICAL				
RPS21	719QWU	57116	06/12/2023 DEFECT	1 LABOUR	MECH	Labour	
RPS21	719QWU	57116	06/12/2023 DEFECT				
RPS21	719QWU	57116	06/12/2023 DEFECT	DEFECT CLEARED.			

Reported
Defect :-
Defect
Code :
00009317
Defect
Reference
: 10857
Date :
04/06/20
23
Descriptio
n of
Defect :
FRONT
LIGHT
PLUG
NEEDS RE
WIRING
AND RE
ATTACHIN
G.

RPS21 719QWU 57116 06/12/2023 DEFECT

RPS21 719QWU 57116 06/12/2023 TRA 0 LABOUR MECH Labour

				SERVICE COMPLET ED. RH FRONT SLCK ADJUSTER NEEDS REPLACIN G ELEC PLUG HAS BEEN REPLACE NO TIME TO ADDRESS DEFECTS LOEADED FOR MARKET					
RPS21	719QWU	57116	06/12/2023 TRA						
RPS21	719QWU	57116	06/12/2023 TRA	0 LABOUR	MECH 3	Labour - Internal			
RPS21	719QWU	57116	06/12/2023 TRA	0 LABOUR	APPRENF	Labour - Internal			
RPS21	719QWU	57116	06/12/2023 TRA	16 CON		YAT Consumables			
								Consuma bles ,RP21	
RPS21	719QWU	57197	06/13/2023 FVGEN	39 CON		BRIVAL01	EX00029057		
RPS21	719QWU	57197	06/13/2023 FVGEN	39 LAB		BRIVAL01	EX00029057	Labour,RP21	
RPS21	719QWU	57197	06/13/2023 FVGEN	39 78-1360		BRIVAL01	EX00029057	ALTERNATOR BELT FRIDGE,RP21	
RPS21	719QWU	57197	06/13/2023 FVGEN	39 92-1136		BRIVAL01	EX00029057	Hinge Panel R/S SS,RP21	
RPS21	719QWU	57197	06/13/2023 FVGEN	Service completed by BVR 08/06/2023 - Travel to site and inspect unit - Remove and replace worn alternator belt as required - Fit missing compressor side pane					
								Consuma bles ,RP21	
RPS21	719QWU	57197	06/13/2023 FVGEN	39 CON		BRIVAL01	16508		
RPS21	719QWU	57197	06/13/2023 FVGEN	39 LAB		BRIVAL01	16508	Labour,RP21	
RPS21	719QWU	57197	06/13/2023 FVGEN	39 78-1360		BRIVAL01	16508	ALTERNATOR BELT FRIDGE,RP21	
RPS21	719QWU	57197	06/13/2023 FVGEN	39 92-1136		BRIVAL01	16508	Hinge Panel R/S SS,RP21	
RPS21	719QWU	57433	06/22/2023 DEFECT	1 LABOUR	MECH	Labour			
RPS21	719QWU	57433	06/22/2023 DEFECT						
RPS21	719QWU	57433	06/22/2023 DEFECT	DEFECT CLEARED.					
RPS21	719QWU	57433	06/22/2023 DEFECT	40	3413005	YAT	OIL 15W-40, CK 4/E9		

RPS21	719QWU	57433	06/22/2023 DEFECT	Service completed by BVR 23/06/23 - Carry out B Service as per BVR Specifications		
RPS21	719QWU	57433	06/22/2023 FRIVANB	0	LABOUR	MECH Labour
				VAN "B"		
				SERVICE		
				COMPLET		
				ED.		
				FRIDGE		
				VAN UNIT		
				CALIBRAT		
				ED @		
				SERVICE.		
				SERVICE		
				COMPLET		
				ED BY		
				BVR.		
				OIL 14L		
				(Customer		
				Supplied)		
				CALIBRATI		
				ON		
				CERTIFICA		
				TE		
				R+R		
				ENGINE		
				OIL		
RPS21	719QWU	57433	06/22/2023 FRIVANB	R+R		

RPS21	719QWU	57433	06/22/2023 FRIVANB	39 CON	BRIVAL01	EX00029241	Consumables,RP21
RPS21	719QWU	57433	06/22/2023 FRIVANB	39 CC	BRIVAL01	EX00029241	CALIBRATION CETIFICATE,RP21
RPS21	719QWU	57433	06/22/2023 FRIVANB	39 100417	BRIVAL01	EX00029241	Filter Service Kit, Fridge Motor, SLX-400,RP21
RPS21	719QWU	57433	06/22/2023 FRIVANB	39 LAB	BRIVAL01	EX00029241	Labour,RP21
RPS21	719QWU	57433	06/22/2023 FRIVANB	39 CON	BRIVAL01	16670	Consumables,RP21
RPS21	719QWU	57433	06/22/2023 FRIVANB	39 CC	BRIVAL01	16670	CALIBRATION CETIFICATE,RP21
RPS21	719QWU	57433	06/22/2023 FRIVANB	39 100417	BRIVAL01	16670	Filter Service Kit, Fridge Motor, SLX-400,RP21
RPS21	719QWU	57433	06/22/2023 FRIVANB	39 LAB	BRIVAL01	16670	Labour,RP21
RPS21	719QWU	57433	06/22/2023 FRIVCAL	1 LABOUR MECH	Labour		
			AIR GAUGE: 8000 ADJUSTED :8500 WEIGHBRI DGE:8120				
			AIR GAUGE CALIBRATION COMPLETED CORRECTLY.				
RPS21	719QWU	57852	07/03/2023 WEICAL				
RPS21	719QWU	57888	07/10/2023 FVGEN	39 CON	BRIVAL01	EX00029441	Consumables,RP21
RPS21	719QWU	57888	07/10/2023 FVGEN	39 13-0385	BRIVAL01	EX00029441	TIER 2 THERMOSTAT,RP21
RPS21	719QWU	57888	07/10/2023 FVGEN	39 Anti-Freeze Coolant	BRIVAL01	EX00029441	Anti-Freeze Coolant,RP21

RPS21	719QWU	57888	07/10/2023 FVGEN	39 33-2767	BRIVAL01	EX00029441	THERMOSTAT GASKET,RP21
RPS21	719QWU	57888	07/10/2023 FVGEN	39 LAB	BRIVAL01	EX00029441	Labour,RP21
RPS21	719QWU	57888	07/10/2023 FVGEN	Service completed by BVR 03/07/2023 - Travel to site and inspect unit for running hot 94c - Check over unit for repairs - Have trailer moved to wash bay - Thoro			
							Consumables,RP21
RPS21	719QWU	57888	07/10/2023 FVGEN	39 CON	BRIVAL01	16871	
RPS21	719QWU	57888	07/10/2023 FVGEN	39 13-0385	BRIVAL01	16871	TIER 2 THERMOSTAT,RP21
RPS21	719QWU	57888	07/10/2023 FVGEN	39 Anti-Freeze Coolant	BRIVAL01	16871	Anti-Freeze Coolant,RP21
RPS21	719QWU	57888	07/10/2023 FVGEN	39 33-2767	BRIVAL01	16871	THERMOSTAT GASKET,RP21
RPS21	719QWU	57888	07/10/2023 FVGEN	39 LAB	BRIVAL01	16871	Labour,RP21
							Consumables,RP21
RPS21	719QWU	58583	07/31/2023 FVGEN	39 CON	BRIVAL01	EX00029784	
RPS21	719QWU	58583	07/31/2023 FVGEN	39 132572	BRIVAL01	EX00029784	PUMP WATER TK486 W/GASKET FRIDGE,RP21
RPS21	719QWU	58583	07/31/2023 FVGEN	39 Anti-Freeze Coolant	BRIVAL01	EX00029784	Anti-Freeze Coolant,RP21
RPS21	719QWU	58583	07/31/2023 FVGEN	39 LAB	BRIVAL01	EX00029784	Labour,RP21
RPS21	719QWU	58583	07/31/2023 FVGEN	39 13-0385	BRIVAL01	EX00029784	TIER 2 THERMOSTAT,RP21
RPS21	719QWU	58583	07/31/2023 FVGEN	Service completed by BVR 31/07/2023 - Travel to site and inspect unit for coolant leak - Locate leak - Remove and replace u/s water pump and thermostat - Re			
							Consumables,RP21
RPS21	719QWU	58583	07/31/2023 FVGEN	39 CON	BRIVAL01	17309	
RPS21	719QWU	58583	07/31/2023 FVGEN	39 132572	BRIVAL01	17309	PUMP WATER TK486 W/GASKET FRIDGE,RP21
RPS21	719QWU	58583	07/31/2023 FVGEN	39 Anti-Freeze Coolant	BRIVAL01	17309	Anti-Freeze Coolant,RP21
RPS21	719QWU	58583	07/31/2023 FVGEN	39 LAB	BRIVAL01	17309	Labour,RP21
RPS21	719QWU	58583	07/31/2023 FVGEN	39 13-0385	BRIVAL01	17309	TIER 2 THERMOSTAT,RP21
RPS21	719QWU	58513	08/02/2023 DEFECT	1 LABOUR	MECH	Labour	
RPS21	719QWU	58513	08/02/2023 DEFECT	DEFECT CLEARED 31/07/2023			
				RAISED LOWER VALVE NOT LEAKING.			
RPS21	719QWU	58513	08/02/2023 DEFECT				

				Reported Defect :- Defect Code : 00009121 Defect Reference : RP21 Date : 02/05/20 23 Descriptio n of Defect : RAIRSED LOWER VALVE LEAKING AIR			
RPS21	719QWU	58513	08/02/2023 DEFECT				
RPS21	719QWU	58513	08/02/2023 TRA	1 LABOUR	MECH	Labour	
RPS21	719QWU	58513	08/02/2023 TRA	SERVICE COMPLETED.			
RPS21	719QWU	58513	08/02/2023 TRB	1 LABOUR	APPRENB	Labour	

				SERVICE COMPLET ED BY BEN & TYLER ON 31/07/20 23.				
				REPLACED RHS REAR O-RING FOR HUB CAP.				
				RAISED LOWER VALVE - NOT LEAKING.				
RPS21	719QWU	58513	08/02/2023 TRB					
RPS21	719QWU	58513	08/02/2023 TRB	0 LABOUR	APPREN	Labour - Internal		
RPS21	719QWU	58513	08/02/2023 TRB	16 CON		YAT Consumables		
RPS21	719QWU	59975	09/18/2023 DEFECT	1 LABOUR	MECH	Labour		
RPS21	719QWU	59975	09/18/2023 DEFECT					
RPS21	719QWU	59975	09/18/2023 DEFECT	DEFECT CLEARED.				
RPS21	719QWU	59975	09/18/2023 TRA	1 LABOUR	MECH 3	Labour		
RPS21	719QWU	59975	09/18/2023 TRA	SERVICE COMPLETED BY MATT & JOE ON 18/09/2023.				
RPS21	719QWU	59975	09/18/2023 TRA	0 LABOUR	APPRENJ	Labour - Internal		
RPS21	719QWU	59975	09/18/2023 TRA	16 CON		YAT Consumables		
							Consuma bles	
RPS21	719QWU	60277	09/19/2023 FVGEN	39 CON		BRIVAL01	EX00030682	,RP21
RPS21	719QWU	60277	09/19/2023 FVGEN	39 NITRO		BRIVAL01	EX00030682	NITROGEN HIGH PURITY,RP21
RPS21	719QWU	60277	09/19/2023 FVGEN	39 22-1160		BRIVAL01	EX00030682	OIL PUMP ASSEMBLY FRIDGE,RP21
RPS21	719QWU	60277	09/19/2023 FVGEN	39 61-0600		BRIVAL01	EX00030682	RECIEVER DRIER, FRIDGE MOTOR,RP21
RPS21	719QWU	60277	09/19/2023 FVGEN	39 77-2856		BRIVAL01	EX00030682	Bush Drive Coupling,RP21
RPS21	719QWU	60277	09/19/2023 FVGEN	39 41-3669		BRIVAL01	EX00030682	SWITCH HPCO,RP21
RPS21	719QWU	60277	09/19/2023 FVGEN	39 LAB		BRIVAL01	EX00030682	Labour,RP21
RPS21	719QWU	60277	09/19/2023 FVGEN	Service completed by BVR 19/09/2023 - Travel to site and inspect unit - Pump down system and remove compressor - Remove and replace worn drive bushes, v				

RPS21	719QWU	60277	09/19/2023 FVGEN	39 LAB	BRIVAL01	INV-00017871	Labour,RP21
RPS21	719QWU	60277	09/19/2023 FVGEN	39 41-3669	BRIVAL01	INV-00017871	SWITCH HPCO,RP21
RPS21	719QWU	60277	09/19/2023 FVGEN	39 77-2856	BRIVAL01	INV-00017871	Bush Drive Coupling,RP21
RPS21	719QWU	60277	09/19/2023 FVGEN	39 61-0600	BRIVAL01	INV-00017871	RECIEVER DRIER, FRIDGE MOTOR,RP21
RPS21	719QWU	60277	09/19/2023 FVGEN	39 22-1160	BRIVAL01	INV-00017871	OIL PUMP ASSEMBLY FRIDGE,RP21
RPS21	719QWU	60277	09/19/2023 FVGEN	39 NITRO	BRIVAL01	INV-00017871	NITROGEN HIGH PURITY,RP21
RPS21	719QWU	60277	09/19/2023 FVGEN	39 CON	BRIVAL01	INV-00017871	Consumables,RP21
RPS21	719QWU	60633	10/10/2023 DEFECT	1 LABOUR	MECH	Labour	
RPS21	719QWU	60633	10/10/2023 DEFECT				
RPS21	719QWU	60633	10/10/2023 DEFECT	DEFECT CLEARED.			
RPS21	719QWU	60633	10/10/2023 TRA	1 LABOUR	MECH 3	Labour	
				SERVICE COMPLETED BY MATT ON 10/10/2023.			
				REPLACE RH FRONT SLACK ADJUSTER / SIDE PLATE HAD COME APART FROM MAIN BODY			
RPS21	719QWU	60633	10/10/2023 TRA				
RPS21	719QWU	60633	10/10/2023 TRA	16 CON	YAT	Consumables	
RPS21	719QWU	60633	10/10/2023 TRA	3 WT5022	YAT	SLACK ADJUSTER BPW	
RPS21	719QWU	61146	10/20/2023 TYRES	15 11004117	BRIAUS01	EX00031046	11R22.5 148/145L FS FT469,
RPS21	719QWU	61146	10/20/2023 TYRES	15 77000180	BRIAUS01	EX00031046	CASE STOCK 11-22.5,
RPS21	719QWU	61146	10/20/2023 TYRES	15 33000084	BRIAUS01	EX00031046	FIT TBR TYRE,
RPS21	719QWU	61146	10/20/2023 TYRES	15 33000517	BRIAUS01	EX00031046	REMOVAL: CUSTOMER PULL POINT,
RPS21	719QWU	61146	10/20/2023 TYRES	15 33000522	BRIAUS01	EX00031046	REMOVAL: PUNCTURED,
RPS21	719QWU	61146	10/20/2023 TYRES	15 33000118	BRIAUS01	EX00031046	SCHEDULED DEPOT SERVICE 15MIN,
RPS21	719QWU	61146	10/20/2023 TYRES	15 11004117	BRIAUS01	1.88E+08	11R22.5 148/145L FS FT469,

RPS21	719QWU	61146	10/20/2023 TYRES	15 77000180	BRIAUS01	1.88E+08	CASE STOCK 11-22.5,
RPS21	719QWU	61146	10/20/2023 TYRES	15 33000084	BRIAUS01	1.88E+08	FIT TBR TYRE,
RPS21	719QWU	61146	10/20/2023 TYRES	15 33000517	BRIAUS01	1.88E+08	REMOVAL: CUSTOMER PULL POINT,
RPS21	719QWU	61146	10/20/2023 TYRES	15 33000522	BRIAUS01	1.88E+08	REMOVAL: PUNCTURED,
RPS21	719QWU	61146	10/20/2023 TYRES	15 33000118	BRIAUS01	1.88E+08	SCHEDULED DEPOT SERVICE 15MIN,
				AIR GAUGE: 18250 ADJUSTED : 18500 WEIGHBRI DGE: 18100			
				AIR GAUGE CALIBRATI ON COMPLET ED CORRECTL Y.			
RPS21	719QWU	61400	10/22/2023 WEICAL				
RPS21	719QWU	61027	10/24/2023 FVGEN	39 CALL OUT FEE	BRIVAL01	EX00031010	CALL OUT FEE,
RPS21	719QWU	61027	10/24/2023 FVGEN	39 PART	BRIVAL01	EX00031010	GENERAL PART CODE,BELT
RPS21	719QWU	61027	10/24/2023 FVGEN	39 LABEXT	BRIVAL01	EX00031010	Labour External - BY YETI'S REFRIGERATION & ELECTRICAL P/L,DIAGNOSED AND
RPS21	719QWU	61027	10/24/2023 FVGEN	39 CALL OUT FEE	BRIVAL01	INV-00018256	CALL OUT FEE,
RPS21	719QWU	61027	10/24/2023 FVGEN	39 PART	BRIVAL01	INV-00018256	GENERAL PART CODE,BELT
RPS21	719QWU	61027	10/24/2023 FVGEN	39 LABEXT	BRIVAL01	INV-00018256	Labour External - BY YETI'S REFRIGERATION & ELECTRICAL P/L,DIAGNOSED AND
RPS21	719QWU	61361	10/26/2023 FVGEN	39 CON	BRIVAL01	EX00031189	Consumables ,RP21
RPS21	719QWU	61361	10/26/2023 FVGEN	39 66-7636	BRIVAL01	EX00031189	PILOT SOLENOID,RP21
RPS21	719QWU	61361	10/26/2023 FVGEN	39 LAB	BRIVAL01	EX00031189	Labour,RP21

				SERVICE COMPLET ED BY BVR ON 26.10.202 3 TRAVEL TO SITE AND INSPECT UNIT - REMOVE AND REPLACE LEAKING BATTERY (CUSTOM ER SUPPLIED) - REMOVE AND REPLACE U/S PILOT SOLENOID - UNIT RAN ON TEST				
RPS21	719QWU	61361	10/26/2023 FVGEN					
RPS21	719QWU	61361	10/26/2023 FVGEN	39 CON	BRIVAL01	INV-00018365	Consuma bles ,RP21	
RPS21	719QWU	61361	10/26/2023 FVGEN	39 66-7636	BRIVAL01	INV-00018365	PILOT SOLENOID,RP21	
RPS21	719QWU	61361	10/26/2023 FVGEN	39 LAB	BRIVAL01	INV-00018365	Labour,RP21 Consuma bles ,RP21	
RPS21	719QWU	61523	10/30/2023 FVGEN	39 CON	BRIVAL01	EX00031208		
RPS21	719QWU	61523	10/30/2023 FVGEN	39 45-2258	BRIVAL01	EX00031208	120 AMP ALTERNA TOR,RP21	
RPS21	719QWU	61523	10/30/2023 FVGEN	39 LAB	BRIVAL01	EX00031208	Labour,RP21	
RPS21	719QWU	61523	10/30/2023 FVGEN	Service completed by BVR 30/10/023 - Travel to site and inspect unit - remove and replace u/s alternator - repair wire worn down on metal bracket - unit ran or				

RPS21	719QWU	61523	10/30/2023 FVGEN	39 CON	BRIVAL01	INV-00018407	Consumables,RP21
RPS21	719QWU	61523	10/30/2023 FVGEN	39 45-2258	BRIVAL01	INV-00018407	120 AMP ALTERNATOR,RP21
RPS21	719QWU	61523	10/30/2023 FVGEN	39 LAB	BRIVAL01	INV-00018407	Labour,RP21
RPS21	719QWU	61335	10/30/2023 GEN	15 11002822	BRI AUS01	EX00031157	11R2.5 148L 16 BS R168,
RPS21	719QWU	61335	10/30/2023 GEN	15 33000084	BRI AUS01	EX00031157	FIT TBR TYRE,
RPS21	719QWU	61335	10/30/2023 GEN	15 33000116	BRI AUS01	EX00031157	SVC CALL OUT AFTER HOURS/15MINS,
RPS21	719QWU	61335	10/30/2023 GEN	15 33000241	BRI AUS01	EX00031157	SCRAP TYRES TBR,
RPS21	719QWU	61335	10/30/2023 GEN	15 11002822	BRI AUS01	4.81E+09	11R2.5 148L 16 BS R168,
RPS21	719QWU	61335	10/30/2023 GEN	15 33000084	BRI AUS01	4.81E+09	FIT TBR TYRE,
RPS21	719QWU	61335	10/30/2023 GEN	15 33000116	BRI AUS01	4.81E+09	SVC CALL OUT AFTER HOURS/15MINS,
RPS21	719QWU	61335	10/30/2023 GEN	15 33000241	BRI AUS01	4.81E+09	SCRAP TYRES TBR,
RPS21	719QWU	61542	10/31/2023 DEFECT	1 LABOUR	MECH	Labour	
RPS21	719QWU	61548	10/31/2023 DEFECT	1 LABOUR	MECH	Labour	
RPS21	719QWU	61542	10/31/2023 DEFECT				
RPS21	719QWU	61548	10/31/2023 DEFECT				
RPS21	719QWU	61542	10/31/2023 DEFECT	DEFECT CLEARED.			
RPS21	719QWU	61548	10/31/2023 DEFECT	DEFECT CLEARED.			
RPS21	719QWU	61548	10/31/2023 EXOINS	1 LABOUR	MECH	Labour	
				VEHICLE PASSED ANNUAL ROADWORK RTHY INSPECTION. ATTEMPT # 1			
				INSPECTION COMPLETED BY DIESEL SERVICES 31/10/2023			
RPS21	719QWU	61548	10/31/2023 EXOINS				
RPS21	719QWU	61542	10/31/2023 TRA	1 LABOUR	MECH	Labour	

RPS21	719QWU	61542	10/31/2023 TRA	SERVICE COMPLETED.			
RPS21	719QWU	61542	10/31/2023 TRB	1 LABOUR MECH	Labour		
RPS21	719QWU	61542	10/31/2023 TRB	SERVICE COMPLETED.			
RPS21	719QWU	61542	10/31/2023 TRC	1 LABOUR MECH	Labour		

				SERVICE			
				COMPLET			
				ED BY			
				DIESEL			
				SERVICES			
				AS PER			
				SERVICE			
				SHEET			
				WITHOUT			
				BEARINGS			
				.			
				RETENTIO			
				N ALL			
				FASTNERS			
				TO			
				FACTORY			
				TORQUE			
				SETTINGS			
				AND			
				GREASE			
				ALL			
				POINTS,			
				ADJUST			
				ALL			
				BRAKES			
				AND			
RPS21	719QWU	61542	10/31/2023 TRC	CHECK			
RPS21	719QWU	61542	10/31/2023 TRC	39 CON	DIESER01	EX00031218	DEGREASER,
RPS21	719QWU	61542	10/31/2023 TRC	39 LAB	DIESER01	EX00031218	Labour,
RPS21	719QWU	61542	10/31/2023 TRC	39 MATERIALS	DIESER01	EX00031218	MATERIALS,
RPS21	719QWU	61542	10/31/2023 TRC	39 MATERIALS	DIESER01	29003	MATERIALS,
RPS21	719QWU	61542	10/31/2023 TRC	39 LAB	DIESER01	29003	Labour,
RPS21	719QWU	61542	10/31/2023 TRC	39 CON	DIESER01	29003	DEGREASER,
RPS21	719QWU	61816	11/02/2023 FVGEN	39 LABEXT	BRIVAL01	EX00031371	Labour External - ICEMAN TRANSPORT REFRIGATION,RP21
RPS21	719QWU	61816	11/02/2023 FVGEN	39 SUND	BRIVAL01	EX00031371	SUNDRIES INCL.EPA CHARGE (TVL),RP21

				complete d by BVR 02/11/20 23 - ICEMAN TRANSP RT REFRIGATI ON			
				ALARM#2 5...A/HOU RS...CALL OUT...LOA DED. ..@ MT. SAINT JOHN AFTER HOURS CALLOUT			
				TRAVELLE D TO SITE - CHECKED UNIT FOR REPORTE			
RPS21	719QWU	61816	11/02/2023 FVGEN				
RPS21	719QWU	61816	11/02/2023 FVGEN	39 LABEXT	BRIVAL01	INV-00018487	Labour External - ICEMAN TRANSPORT REFRIGATION,RP21
RPS21	719QWU	61816	11/02/2023 FVGEN	39 SUND	BRIVAL01	INV-00018487	SUNDRIES INCL.EPA CHARGE (TVL),RP21
RPS21	719QWU	61970	11/07/2023 FVGEN	39 CON	BRIVAL01	EX00031420	Consumables,RP21
RPS21	719QWU	61970	11/07/2023 FVGEN	39 1000CCA	BRIVAL01	EX00031420	Heavy Duty Battery - 1000CCA,RP21

RPS21	719QWU	61970	11/07/2023 FVGEN	39 CALL OUT FEE	BRIVAL01	EX00031420	Call Out After Hours/Off Site,RP21
RPS21	719QWU	61970	11/07/2023 FVGEN	39 41-0213	BRIVAL01	EX00031420	ALTERNATOR HARNESS,RP21
				complete d by BVR 07/11/20 23 - CALLOUT			
				Travel to Gatton and inspect unit for reported not charging - Remove and replace u/s battery - Found excite and sensor intermitte ntly working - Remove and			
RPS21	719QWU	61970	11/07/2023 FVGEN				
RPS21	719QWU	61970	11/07/2023 FVGEN	39 41-0213	BRIVAL01	INV-00018542	ALTERNATOR HARNESS,RP21
RPS21	719QWU	61970	11/07/2023 FVGEN	39 CALL OUT FEE	BRIVAL01	INV-00018542	Call Out After Hours/Off Site,RP21
RPS21	719QWU	61970	11/07/2023 FVGEN	39 1000CCA	BRIVAL01	INV-00018542	Heavy Duty Battery - 1000CCA,RP21
							Consumables
RPS21	719QWU	61970	11/07/2023 FVGEN	39 CON	BRIVAL01	INV-00018542	,RP21
RPS21	719QWU	62272	11/27/2023 GEN	15 33000096	BRIAUS01	EX00031613	PUNCTURE REPAIR TBR,
RPS21	719QWU	62272	11/27/2023 GEN	15 33000096	BRIAUS01	1.88E+08	PUNCTURE REPAIR TBR,
RPS21	719QWU	62231	11/28/2023 DEFECT	1 LABOUR MECH	Labour		
RPS21	719QWU	62231	11/28/2023 DEFECT				
RPS21	719QWU	62231	11/28/2023 DEFECT	DEFECT CLEARED.			
RPS21	719QWU	62231	11/28/2023 TRA	1 LABOUR APPREN	Labour		

				SERVICE COMPLET ED BY TYLER & JOE ON 28/11/20 23. PUT A FEW RIVETS IN THE 'F' TRACK DUE TO OLD ONES COMING OUT SILICONE D LH BOTTOM FIBREGLA SS PANEL INSIDE OF TRAILER DUE TO IT BEING RIPPED OFF			
RPS21	719QWU	62231	11/28/2023 TRA				
RPS21	719QWU	62231	11/28/2023 TRA	0 LABOUR	APPRENJ	Labour - Internal	
RPS21	719QWU	62231	11/28/2023 TRA	16 CON		YAT	Consumables
RPS21	719QWU	62535	12/06/2023 FRIVANB	0 LABOUR	MECH	Labour	

RPS21	719QWU	62535	12/06/2023 FRIVANB	VAN "B" SERVICE COMPLET ED. FRIDGE VAN UNIT CALIBRAT ED @ SERVICE. SERVICE COMPLET ED BY BVR. OIL 14L (Customer Supplied) CALIBRATI ON CERTIFICA TE R+R ENGINE OIL R+R
-------	--------	-------	--------------------	--

RPS21	719QWU	62535	12/06/2023 FRIVANB	39 CON	BRIVAL01	EX00031751	Consumables,RP21
RPS21	719QWU	62535	12/06/2023 FRIVANB	39 CC	BRIVAL01	EX00031751	CALIBRATION CETIFICATE,RP21
RPS21	719QWU	62535	12/06/2023 FRIVANB	39 100417	BRIVAL01	EX00031751	Filter Service Kit, Fridge Motor, SLX-400,RP21
RPS21	719QWU	62535	12/06/2023 FRIVANB	39 LAB	BRIVAL01	EX00031751	Labour,RP21
RPS21	719QWU	62535	12/06/2023 FRIVANB	40 3413005	YAT OIL 15W-40, CK 4/E9		
RPS21	719QWU	62535	12/06/2023 FRIVANB	Service completed by BVR 29/11/2023 - Carry out B Service as per BVR Specifications			Consumables,RP21
RPS21	719QWU	62535	12/06/2023 FRIVANB	39 CON	BRIVAL01	INV-00018880	CALIBRATION CETIFICATE,RP21
RPS21	719QWU	62535	12/06/2023 FRIVANB	39 CC	BRIVAL01	INV-00018880	Filter Service Kit, Fridge Motor, SLX-400,RP21
RPS21	719QWU	62535	12/06/2023 FRIVANB	39 100417	BRIVAL01	INV-00018880	
RPS21	719QWU	62535	12/06/2023 FRIVANB	39 LAB	BRIVAL01	INV-00018880	Labour,RP21
RPS21	719QWU	63230	01/04/2024 GEN	16 PART	NABQAN01	EX00032111	FUEL CAP - BRASS SCREW ON 60MM THREAD,
RPS21	719QWU	63230	01/04/2024 GEN	16 PART	NABQAN01	6260044A	FUEL CAP - BRASS SCREW ON 60MM THREAD,
RPS21	719QWU	63261	01/08/2024 DEFECT	1 LABOUR	MECH	Labour	
RPS21	719QWU	63261	01/08/2024 DEFECT				
RPS21	719QWU	63261	01/08/2024 DEFECT	DEFECT CLEARED.			
RPS21	719QWU	63261	01/08/2024 TRA	1 LABOUR	MECH 3	Labour	

				SERVICE COMPLET ED BY MATT & JOSEPH ON 08/01/20 24.					
				NOTED: INTERIOR LIGHT SWITCH @ FRONT OF TRAILER REQUIRES REPLACE MENT WHEN AVAILABL E DEFECT NO. 00010587 CREATED					
RPS21	719QWU	63261	01/08/2024 TRA						
RPS21	719QWU	63261	01/08/2024 TRA	0 LABOUR	APPRENJ	Labour - Internal			
RPS21	719QWU	63261	01/08/2024 TRA	16 CON		YAT Consumables			
RPS21	719QWU	63595	01/12/2024 FVGEN	39 CON		BRIVAL01	EX00032252	Consuma bles ,RP21	
RPS21	719QWU	63595	01/12/2024 FVGEN	39 LAB		BRIVAL01	EX00032252	Labour,RP21	
RPS21	719QWU	63595	01/12/2024 FVGEN	39 LABEXT		BRIVAL01	EX00032252	Labour External,RP21	
RPS21	719QWU	63595	01/12/2024 FVGEN	39 CALL OUT FEE		BRIVAL01	EX00032252	Call Out After Hours/Off Site,RP21	
RPS21	719QWU	63595	01/12/2024 FVGEN	39 R404A		BRIVAL01	EX00032252	GAS R404A,RP21	

RPS21	719QWU	63595	01/12/2024 FVGEN	complete d by BVR 12/01/20 24 - Travel to site and inspect unit for reported purge valve circuit alarm code - Clean and grease board plugs - Pretrip failed on purge valve circuit - Test purge valve solenoid, ok - Check
-------	--------	-------	------------------	--

RPS21	719QWU	63595	01/12/2024 FVGEN	39 CON	BRIVAL01	INV-00019402	Consumables ,RP21
RPS21	719QWU	63595	01/12/2024 FVGEN	39 LAB	BRIVAL01	INV-00019402	Labour,RP21
RPS21	719QWU	63595	01/12/2024 FVGEN	39 LABEXT	BRIVAL01	INV-00019402	Labour External,RP21
RPS21	719QWU	63595	01/12/2024 FVGEN	39 CALL OUT FEE	BRIVAL01	INV-00019402	Call Out After Hours/Off Site,RP21
RPS21	719QWU	63595	01/12/2024 FVGEN	39 R404A	BRIVAL01	INV-00019402	GAS R404A,RP21

RPS21	719QWU	64174	01/24/2024 FVGEN	39 CON	BRIVAL01	EX00032585	Consumables,RP21
RPS21	719QWU	64174	01/24/2024 FVGEN	39 NITRO	BRIVAL01	EX00032585	NITROGEN HIGH PURITY,RP21
RPS21	719QWU	64174	01/24/2024 FVGEN	39 R404A	BRIVAL01	EX00032585	GAS R404A,RP21
RPS21	719QWU	64174	01/24/2024 FVGEN	39 TIP BLUE	BRIVAL01	EX00032585	Blue Tip Silver Solder,RP21
RPS21	719QWU	64174	01/24/2024 FVGEN	39 LAB	BRIVAL01	EX00032585	Labour,RP21
RPS21	719QWU	64174	01/24/2024 FVGEN	Service completed by BVR 24/01/2024 - Travel to site and inspect unit for reported low on gas - Remove panels and leak check whole unit - Located leaking join			
RPS21	719QWU	64174	01/24/2024 FVGEN	39 CON	BRIVAL01	INV-00019581	Consumables,RP21
RPS21	719QWU	64174	01/24/2024 FVGEN	39 NITRO	BRIVAL01	INV-00019581	NITROGEN HIGH PURITY,RP21
RPS21	719QWU	64174	01/24/2024 FVGEN	39 R404A	BRIVAL01	INV-00019581	GAS R404A,RP21
RPS21	719QWU	64174	01/24/2024 FVGEN	39 TIP BLUE	BRIVAL01	INV-00019581	Blue Tip Silver Solder,RP21
RPS21	719QWU	64174	01/24/2024 FVGEN	39 LAB	BRIVAL01	INV-00019581	Labour,RP21
RPS21	719QWU	64251	02/05/2024 DEFECT	1 LABOUR	MECH	Labour	
RPS21	719QWU	64251	02/05/2024 DEFECT	DEFECT CLEARED.			
RPS21	719QWU	64251	02/05/2024 DEFECT	1 LABOUR	MECH 3	Labour	
RPS21	719QWU	64251	02/05/2024 TRA	SERVICE COMPLETED BY MATT & JOSEPH ON 05/02/2024.			
RPS21	719QWU	64251	02/05/2024 TRA	FIXED LEG AND REPLACED TUBE BETWEEN LEGS			
RPS21	719QWU	64251	02/05/2024 TRA	0 LABOUR	APPRENT	Labour - Internal	
RPS21	719QWU	64251	02/05/2024 TRA	16 CON	YAT	Consumables	
RPS21	719QWU	65227	03/07/2024 DEFECT	1 LABOUR	MECH	Labour	
RPS21	719QWU	65227	03/07/2024 DEFECT	DEFECT CLEARED.			
RPS21	719QWU	65227	03/07/2024 DEFECT				

RPS21	719QWU	65227	03/07/2024 DEFECT	Reported Defect :- Defect Code : 00010587 Defect Reference : RP21 Date : 08/01/20 24 Description of Defect : INTERIOR LIGHT SWITCH @ FRONT OF TRAILER REQUIRES REPLACE MENT WHEN AVAILABL E					
RPS21	719QWU	65227	03/07/2024 TRA		1 LABOUR	APPRENB	Labour		

				SERVICE COMPLET ED BY BEN, JOSEPH & NICK ON 07/03/20 24. REPLACED SIDE MARKER LIGHT REPLACED INTERIOR LIGHT SWITCH INDICATO R					
RPS21	719QWU	65227	03/07/2024 TRA						
RPS21	719QWU	65227	03/07/2024 TRA	0 LABOUR	APPRENJ	Labour - Internal			
RPS21	719QWU	65227	03/07/2024 TRA	0 LABOUR	MECH 1	Labour - Internal			
RPS21	719QWU	65227	03/07/2024 TRA	16 CON		YAT Consumables			
RPS21	719QWU	65227	03/07/2024 TRA	14 91700BL		YAT Clearance Light, LED Amber, Narva			
RPS21	719QWU	65648	03/20/2024 GEN	15 11004117	BRIAUS01	EX00033386	11R22.5 148/145L FS FT469,		
RPS21	719QWU	65648	03/20/2024 GEN	15 77000180	BRIAUS01	EX00033386	CASE STOCK 11-22.5,		
RPS21	719QWU	65648	03/20/2024 GEN	15 33000084	BRIAUS01	EX00033386	FIT TBR TYRE,		
RPS21	719QWU	65648	03/20/2024 GEN	15 33000517	BRIAUS01	EX00033386	REMOVAL: CUSTOMER PULL POINT,		
RPS21	719QWU	65648	03/20/2024 GEN	15 33000118	BRIAUS01	EX00033386	SCHEDULED DEPOT SERVICE 15MIN,		
RPS21	719QWU	65648	03/20/2024 GEN	15 11004117	BRIAUS01	1.88E+08	11R22.5 148/145L FS FT469,		
RPS21	719QWU	65648	03/20/2024 GEN	15 77000180	BRIAUS01	1.88E+08	CASE STOCK 11-22.5,		
RPS21	719QWU	65648	03/20/2024 GEN	15 33000084	BRIAUS01	1.88E+08	FIT TBR TYRE,		
RPS21	719QWU	65648	03/20/2024 GEN	15 33000517	BRIAUS01	1.88E+08	REMOVAL: CUSTOMER PULL POINT,		
RPS21	719QWU	65648	03/20/2024 GEN	15 33000118	BRIAUS01	1.88E+08	SCHEDULED DEPOT SERVICE 15MIN,		
RPS21	719QWU	66211	04/09/2024 DEFECT	1 LABOUR	MECH	Labour			
RPS21	719QWU	66211	04/09/2024 DEFECT						
RPS21	719QWU	66211	04/09/2024 DEFECT	DEFECT CLEARED.					

Defect :-

Defect

Code :

00011233

Defect

Reference

: 13871

Date :

07/04/20

24

Description

n of

Defect :

REAR

DOOR

HINGE IS

STUFFED.

FRIDGE

INDICATO

R LIGHT

NOT

SHOWING

(WHITE

'T')

DEFECT

CLEARED

RPS21

719QWU

66211

04/09/2024 DEFECT

RPS21

719QWU

66211

04/09/2024 TRA

1 LABOUR MECH 4 Labour

RPS21	719QWU	66211	04/09/2024 TRA	'A' SERVICE COMPLET ED BY ETHAN, TYSON & BEN ON 09/04/20 24. REPLACED DOOR HINGE BRACKET					
RPS21	719QWU	66211	04/09/2024 TRA		0 LABOUR	APPRENT2	Labour - Internal		
RPS21	719QWU	66211	04/09/2024 TRA		0 LABOUR	APPRENB	Labour - Internal		
RPS21	719QWU	66211	04/09/2024 TRA		16 CON		YAT Consumables		
RPS21	719QWU	66211	04/09/2024 TRA		31 1280 012 002		YAT REAR HINGE WITH BRACKET		
RPS21	719QWU	67237	05/15/2024 GEN		15 33000084	BRIAUS01	EX00034293	FIT TBR TYRE,	
RPS21	719QWU	67237	05/15/2024 GEN		15 33000241	BRIAUS01	EX00034293	SCRAP TYRES TBR,	
RPS21	719QWU	67237	05/15/2024 GEN		15 33000125	BRIAUS01	EX00034293	ETA MIN FEE,	
RPS21	719QWU	67237	05/15/2024 GEN		15 33000125	BRIAUS01	4.72E+09	ETA MIN FEE,	
RPS21	719QWU	67237	05/15/2024 GEN		15 33000241	BRIAUS01	4.72E+09	SCRAP TYRES TBR,	
RPS21	719QWU	67237	05/15/2024 GEN		15 33000084	BRIAUS01	4.72E+09	FIT TBR TYRE,	
								Consuma bles	
RPS21	719QWU	68551	05/22/2024 GEN		39 CON	TRASAL01	EX00034923	,	
RPS21	719QWU	68551	05/22/2024 GEN		39 WI97965	TRASAL01	EX00034923	SIKAFLEX 221 GREY 600G,	
RPS21	719QWU	68551	05/22/2024 GEN		39 LAB	TRASAL01	EX00034923	Labour,	
RPS21	719QWU	68551	05/22/2024 GEN		39 PART	TRASAL01	EX00034923	DOOR SEAL,	
								Consuma bles	
RPS21	719QWU	68551	05/22/2024 GEN		39 CON	TRASAL01	EX00034923	,	
								Consuma bles	
RPS21	719QWU	68551	05/22/2024 GEN		39 CON	TRASAL01	EX00034923	,	
								Consuma bles	
RPS21	719QWU	68551	05/22/2024 GEN		39 CON	TRASAL01	EX00034923	,	

[illegible]

RPS21	719QWU	68551	05/22/2024 GEN	39 CON	TRASAL01	EX00034923	Consumables ,
RPS21	719QWU	68551	05/22/2024 GEN	39 CON	TRASAL01	EX00034923	Consumables ,
RPS21	719QWU	68551	05/22/2024 GEN	39 PART	TRASAL01	EX00034923	DOOR SEAL,
RPS21	719QWU	68551	05/22/2024 GEN	39 ENVLEV	TRASAL01	EX00034923	ENVIRONMENTAL LEVY, Consumables
RPS21	719QWU	68551	05/22/2024 GEN	39 CON	TRASAL01	EX00034923	,
RPS21	719QWU	68551	05/22/2024 GEN	39 WIP0070 COMPLETED BY TRAILER SALES 22/05/2024 Set up unit. Disconnect and reconnect L/H side lights. Remove front half of L/H bottom rail. Weld broken parts of rail. Repair damage to wall flange.	TRASAL01	EX00034923	ADHESIVE PLEXUS MA425 380ML,
RPS21	719QWU	68551	05/22/2024 GEN				

							Consumables
RPS21	719QWU	68551	05/22/2024 GEN	39 CON	TRASAL01	791281	,
RPS21	719QWU	68551	05/22/2024 GEN	39 WI97965	TRASAL01	791281	SIKAFLEX 221 GREY 600G,
RPS21	719QWU	68551	05/22/2024 GEN	39 LAB	TRASAL01	791281	Labour,
RPS21	719QWU	68551	05/22/2024 GEN	39 PART	TRASAL01	791281	DOOR SEAL,
							Consumables
RPS21	719QWU	68551	05/22/2024 GEN	39 CON	TRASAL01	791281	,
RPS21	719QWU	68551	05/22/2024 GEN	39 PART	TRASAL01	791281	LED SIDE MARKER,
							Consumables
RPS21	719QWU	68551	05/22/2024 GEN	39 CON	TRASAL01	791281	,
							Consumables
RPS21	719QWU	68551	05/22/2024 GEN	39 CON	TRASAL01	791281	,
							Consumables
RPS21	719QWU	68551	05/22/2024 GEN	39 CON	TRASAL01	791281	,
							Consumables
RPS21	719QWU	68551	05/22/2024 GEN	39 CON	TRASAL01	791281	,
							Consumables
RPS21	719QWU	68551	05/22/2024 GEN	39 CON	TRASAL01	791281	,
RPS21	719QWU	68551	05/22/2024 GEN	39 PART	TRASAL01	791281	FLOKOTE, MAXICUDBE BLUE,
RPS21	719QWU	68551	05/22/2024 GEN	39 PART	TRASAL01	791281	SCUFF BAND,

RPS21	719QWU	68551	05/22/2024 GEN	39 CON	TRASAL01	791281	Consumables
RPS21	719QWU	68551	05/22/2024 GEN	39 WI97965	TRASAL01	791281	,
RPS21	719QWU	68551	05/22/2024 GEN	39 WIP0070	TRASAL01	791281	SIKAFLEX 221 GREY 600G,
							ADHESIVE PLEXUS MA425 380ML,
							Consumables
RPS21	719QWU	68551	05/22/2024 GEN	39 CON	TRASAL01	791281	,
							Consumables
RPS21	719QWU	68551	05/22/2024 GEN	39 CON	TRASAL01	791281	,
							Consumables
RPS21	719QWU	68551	05/22/2024 GEN	39 CON	TRASAL01	791281	,
							Consumables
RPS21	719QWU	68551	05/22/2024 GEN	39 CON	TRASAL01	791281	,
							Consumables
RPS21	719QWU	68551	05/22/2024 GEN	39 CON	TRASAL01	791281	,
							Consumables
RPS21	719QWU	68551	05/22/2024 GEN	39 CON	TRASAL01	791281	,
							Consumables
RPS21	719QWU	68551	05/22/2024 GEN	39 CON	TRASAL01	791281	,
							Consumables
RPS21	719QWU	68551	05/22/2024 GEN	39 CON	TRASAL01	791281	,
							Consumables
RPS21	719QWU	68551	05/22/2024 GEN	39 CON	TRASAL01	791281	,
							Consumables
RPS21	719QWU	68551	05/22/2024 GEN	39 PART	TRASAL01	791281	DOOR SEAL,
RPS21	719QWU	68551	05/22/2024 GEN	39 ENVLEV	TRASAL01	791281	ENVIRONMENTAL LEVY,

RPS21	719QWU	68551	05/22/2024 GEN	39 CON		TRASAL01	791281	Consumables
RPS21	719QWU	68551	05/22/2024 GEN	39 WIP0070		TRASAL01	791281	
RPS21	719QWU	68381	06/19/2024 DEFECT	1 LABOUR	MECH	Labour		ADHESIVE PLEXUS MA425 380ML,
RPS21	719QWU	68381	06/19/2024 DEFECT					
RPS21	719QWU	68381	06/19/2024 DEFECT	DEFECT CLEARED.				
RPS21	719QWU	68381	06/19/2024 TRA	1 LABOUR	MECH 1	Labour		
				'A'				
				SERVICE				
				COMPLET				
				ED BY				
				NICK &				
				JOSEPH				
				ON				
				19/06/20				
				24.				
				REPLACED				
				RH REAR				
				AIR BAG				
				REPLACED				
				RIGHT				
RPS21	719QWU	68381	06/19/2024 TRA	REAR LED.				
RPS21	719QWU	68381	06/19/2024 TRA	0 LABOUR	APPRENJ	Labour - Internal		
RPS21	719QWU	68381	06/19/2024 TRA	16 CON		YAT Consumables		
RPS21	719QWU	68381	06/19/2024 TRA	10 SP0022ASPM		YAT AIRBAG ASSBLY D36 PLASTIC PISTON		
								Consumables
RPS21	719QWU	68569	06/20/2024 FVGEN	39 CON		BRIVAL01	EX00034931	,RPS21
RPS21	719QWU	68569	06/20/2024 FVGEN	39 LAB		BRIVAL01	EX00034931	Labour,RPS21
RPS21	719QWU	68569	06/20/2024 FVGEN	Service completed by BVR 20/06/2024 - Travel to site and inspect unit - Check operation as unit has been sitting for a while - Tighten belts - Top up engine oil - L				
								Consumables
RPS21	719QWU	68569	06/20/2024 FVGEN	39 CON		BRIVAL01	INV-00021613	,RPS21
RPS21	719QWU	68569	06/20/2024 FVGEN	39 LAB		BRIVAL01	INV-00021613	Labour,RPS21

				AIR GAUGE: 14750 ADJUSTED : 15500 WEIGHBRI DGE: 15180				
				AIR GAUGE CALIBRATI ON COMPLET ED CORRECTL Y.				
RPS21	719QWU	68519	06/20/2024 WEICAL					
								Consumables
RPS21	719QWU	68740	06/28/2024 FVGEN	39 CON	BRIVAL01	EX00035025		,RPS21
RPS21	719QWU	68740	06/28/2024 FVGEN	39 LAB	BRIVAL01	EX00035025		Labour,RPS21
RPS21	719QWU	68740	06/28/2024 FVGEN	Service completed by BVR 28/06/2024 - Travel to site and inspect unit for reported leaking water form rear zone onto pallets - Found section of drain hose rubb				
								Consumables
RPS21	719QWU	68740	06/28/2024 FVGEN	39 CON	BRIVAL01	INV-00021726		,RPS21
RPS21	719QWU	68740	06/28/2024 FVGEN	39 LAB	BRIVAL01	INV-00021726		Labour,RPS21
RPS21	719QWU	69758	08/06/2024 DEFECT	1 LABOUR	MECH	Labour		
RPS21	719QWU	70687	08/06/2024 DEFECT	1 LABOUR	MECH	Labour		
RPS21	719QWU	69758	08/06/2024 DEFECT					
RPS21	719QWU	70687	08/06/2024 DEFECT					
RPS21	719QWU	69758	08/06/2024 DEFECT	DEFECT CLEARED.				
RPS21	719QWU	70687	08/06/2024 DEFECT	DEFECT CLEARED.				

				Defect :- Defect Code : 00010718 Defect Reference : 41791 Date : 12/01/20 24 Description n of Defect : HANDLE & LEGS ARE FUCKING HARD TO WIND DOWN AND UP. HANDLES ON DOOR ARE STIFF DEFECT CLEARED ON				
RPS21	719QWU	69758	08/06/2024	DEFECT				
RPS21	719QWU	69758	08/06/2024	TRA	1	LABOUR	MECH	Labour
RPS21	719QWU	70687	08/06/2024	TRA	1	LABOUR	MECH	Labour
RPS21	719QWU	69758	08/06/2024	TRA	SERVICE COMPLETED.			
RPS21	719QWU	70687	08/06/2024	TRA	'A' SERVICE COMPLETED BY COREY (WORKSHOP) ON 06/08/2024.			
RPS21	719QWU	70687	08/06/2024	TRA	0	LABOUR	MECH 6	Labour - Internal
RPS21	719QWU	70687	08/06/2024	TRA	16	CON	YAT	Consumables
RPS21	719QWU	69758	08/06/2024	TRB	1	LABOUR	APPRENA	Labour

				SERVICE COMPLET ED BY ALEX & COREY (WORKSH OP) ON 06/08/20 24.			
				FITTED NEW 2.5KG FIRE EXTINGUI SHER FITED 3 MARKER LIGHTS TO RH REAR SIDE, AS ALL ARE MISSING AND FIXED WIRING. NEW			
RPS21	719QWU	69758	08/06/2024 TRB				
RPS21	719QWU	69758	08/06/2024 TRB	0 LABOUR	MECH 6	Labour - Internal	
RPS21	719QWU	69758	08/06/2024 TRB	16 CON		YAT	Consumables
RPS21	719QWU	69758	08/06/2024 TRB	14 91700BL		YAT	Clearance Light, LED Amber, Narva
RPS21	719QWU	69758	08/06/2024 TRB	19 FIREEXT2.5KG		YAT	2.5KG FIRE EXTINGUISHER
RPS21	719QWU	70455	08/30/2024 FRIVANB	0 LABOUR	MECH	Labour	

RPS21	719QWU	70455	08/30/2024 FRIVANB	VAN "B" SERVICE COMPLET ED. FRIDGE VAN UNIT CALIBRAT ED @ SERVICE. SERVICE COMPLET ED BY BVR. OIL 14L (Customer Supplied) CALIBRATI ON CERTIFICA TE R+R ENGINE OIL R+R
-------	--------	-------	--------------------	--

RPS21	719QWU	70455	08/30/2024 FRIVANB	39 CON	BRIVAL01	EX00035964	Consumables, RPS21
RPS21	719QWU	70455	08/30/2024 FRIVANB	39 CC	BRIVAL01	EX00035964	CALIBRATION CETIFICATE, RPS21
RPS21	719QWU	70455	08/30/2024 FRIVANB	39 100417	BRIVAL01	EX00035964	Filter Service Kit, Fridge Motor, SLX-400, RPS21
RPS21	719QWU	70455	08/30/2024 FRIVANB	39 41-9181	BRIVAL01	EX00035964	Engine Speed Solinoid, RPS21
RPS21	719QWU	70455	08/30/2024 FRIVANB	39 LAB	BRIVAL01	EX00035964	Labour, RPS21
RPS21	719QWU	70455	08/30/2024 FRIVANB	40 3413005	YAT	OIL 15W-40, CK 4/E9	
RPS21	719QWU	70455	08/30/2024 FRIVANB	Service completed by BVR 26/08/2024 - Carry out B Service as per BVR Specifications - Remove and replace worn speed solenoid - Tighten alt belt			
RPS21	719QWU	70455	08/30/2024 FRIVANB	39 CON	BRIVAL01	INV-00022586	Consumables, RPS21
RPS21	719QWU	70455	08/30/2024 FRIVANB	39 CC	BRIVAL01	INV-00022586	CALIBRATION CETIFICATE, RPS21
RPS21	719QWU	70455	08/30/2024 FRIVANB	39 100417	BRIVAL01	INV-00022586	Filter Service Kit, Fridge Motor, SLX-400, RPS21
RPS21	719QWU	70455	08/30/2024 FRIVANB	39 41-9181	BRIVAL01	INV-00022586	Engine Speed Solinoid, RPS21
RPS21	719QWU	70455	08/30/2024 FRIVANB	39 LAB	BRIVAL01	INV-00022586	Labour, RPS21
RPS21	719QWU	70455	08/30/2024 FRIVCAL	1 LABOUR MECH	Labour		
RPS21	719QWU	71007	09/11/2024 FVGEN	39 41-3669	BRIVAL01	EX00036198	SWITCH HPCO 470 PSI 1/8 NPT, RPS21
RPS21	719QWU	71007	09/11/2024 FVGEN	39 ENVLEV	BRIVAL01	EX00036198	W-S MATERIALS/ENVIRONMENTAL LEVY, RPS21
RPS21	719QWU	71007	09/11/2024 FVGEN	39 BREAKDOWN	BRIVAL01	EX00036198	AH BREAKDOWN ASSISTANCE, RPS21
RPS21	719QWU	71007	09/11/2024 FVGEN	39 LABEXT	BRIVAL01	EX00036198	Labour External, RPS21

				complete d by BVR 11/09/20 24 - THERMAL MARK TRANSPO RT REFRIGER ATION				
				Afterhour s onsite assistance requested - Arrive onsite and locate vehicle - Upon inspection found alarm 10 active - clear codes and carry out				
RPS21	719QWU	71007	09/11/2024 FVGEN					
RPS21	719QWU	71007	09/11/2024 FVGEN	39 LABEXT	BRIVAL01	INV-00022836	Labour External,RPS21	
RPS21	719QWU	71007	09/11/2024 FVGEN	39 BREAKDOWN	BRIVAL01	INV-00022836	AH BREAKDOWN ASSISTANCE,RPS21	
RPS21	719QWU	71007	09/11/2024 FVGEN	39 ENVLEV	BRIVAL01	INV-00022836	W-S MATERIALS/ENVIRONMENTAL LEVY,RPS21	
RPS21	719QWU	71007	09/11/2024 FVGEN	39 41-3669	BRIVAL01	INV-00022836	SWITCH HPCO 470 PSI 1/8 NPT,RPS21	
RPS21	719QWU	70958	09/16/2024 DEFECT	1 LABOUR	MECH	Labour		
RPS21	719QWU	70958	09/16/2024 DEFECT					
RPS21	719QWU	70958	09/16/2024 DEFECT	DEFECT CLEARED.				
RPS21	719QWU	70958	09/16/2024 TRA	1 LABOUR	APPRENJ	Labour		

				'A' SERVICE COMPLET ED BY JOSEPH, COREY & JOSH (WORKSH OP) ON 16/09/20 24. REPLACED LIGHT SWITCH AT FRONT OF TRAILER FOR INTERIOR LIGHTS				
RPS21	719QWU	70958	09/16/2024 TRA					
RPS21	719QWU	70958	09/16/2024 TRA	0 LABOUR	MECH 6	Labour - Internal		
RPS21	719QWU	70958	09/16/2024 TRA	0 LABOUR	APPRENC	Labour - Internal		
RPS21	719QWU	70958	09/16/2024 TRA	16 CON		YAT Consumables		
				TRAILER SANITISAT ION COMPLET ED ON 23.09.202 4				
				AT LOCATION : TULLY				
RPS21	719QWU	72590	09/23/2024 SANI					
RPS21	719QWU	71396	09/24/2024 TYRES	15 99015526	BRIAUS01	EX00036347	RUNOUT TYRE,	
RPS21	719QWU	71396	09/24/2024 TYRES	15 77000180	BRIAUS01	EX00036347	CASE STOCK 11-22.5,	
RPS21	719QWU	71396	09/24/2024 TYRES	15 33000084	BRIAUS01	EX00036347	FIT TBR TYRE,	
RPS21	719QWU	71396	09/24/2024 TYRES	15 33000517	BRIAUS01	EX00036347	REMOVAL: CUSTOMER PULL POINT,	
RPS21	719QWU	71396	09/24/2024 TYRES	15 99015526	BRIAUS01	1.89E+08	RUNOUT TYRE,	
RPS21	719QWU	71396	09/24/2024 TYRES	15 77000180	BRIAUS01	1.89E+08	CASE STOCK 11-22.5,	
RPS21	719QWU	71396	09/24/2024 TYRES	15 33000084	BRIAUS01	1.89E+08	FIT TBR TYRE,	
RPS21	719QWU	71396	09/24/2024 TYRES	15 33000517	BRIAUS01	1.89E+08	REMOVAL: CUSTOMER PULL POINT,	
RPS21	719QWU	72054	10/09/2024 TYRES	15 33000084	BRIAUS01	EX00036565	FIT TBR TYRE,	
RPS21	719QWU	72054	10/09/2024 TYRES	15 33000241	BRIAUS01	EX00036565	SCRAP TYRES TBR,	

RPS21	719QWU	72054	10/09/2024 TYRES	15 33000084	BRIAUS01	4.81E+09	FIT TBR TYRE,
RPS21	719QWU	72054	10/09/2024 TYRES	15 33000241	BRIAUS01	4.81E+09	SCRAP TYRES TBR,
				TRAILER SANITISAT ION COMPLET ED ON 13.10.202 4			
				AT LOCATION : TULLY			
RPS21	719QWU	72836	10/13/2024 SANI				
RPS21	719QWU	72726	10/18/2024 DEFECT	1 LABOUR	MECH	Labour	
RPS21	719QWU	72726	10/18/2024 DEFECT				
RPS21	719QWU	72726	10/18/2024 DEFECT	DEFECT CLEARED.			
RPS21	719QWU	72726	10/18/2024 TRA	1 LABOUR	APPRENC	Labour	
				'A' SERVICE COMPLET ED BY JOSH, NICK & COREY (W/SHOP) ON 18/10/20 24.			
				FITTED REVERSE SWITCH REPLACED FRONT LIGHT PLUG			
RPS21	719QWU	72726	10/18/2024 TRA				
RPS21	719QWU	72726	10/18/2024 TRA	0 LABOUR	MECH 1	Labour - Internal	
RPS21	719QWU	72726	10/18/2024 TRA	0 LABOUR	MECH 6	Labour - Internal	
RPS21	719QWU	72726	10/18/2024 TRA	16 CON		YAT Consumables	
RPS21	719QWU	73555	11/19/2024 GEN	39 LABEXT		RCCLOW01 EX00037284	REMOVE AND REPLACE LEAKING AIRBAG FRONT AXLE RIGHT SIDE, REMOVE ANI

RPS21	719QWU	73555	11/19/2024 GEN	10 AIRBAG	RCCLOW01	EX00037284	AIRBAG,
RPS21	719QWU	73555	11/19/2024 GEN	13 PART	RCCLOW01	EX00037284	DOCKING VALVE,
RPS21	719QWU	73555	11/19/2024 GEN	16 CON	RCCLOW01	EX00037284	THRUST RING M12,
RPS21	719QWU	73555	11/19/2024 GEN	16 CON	RCCLOW01	EX00037284	O'RING M12,
RPS21	719QWU	73555	11/19/2024 GEN	16 CON	RCCLOW01	EX00037284	O'RING M16,
RPS21	719QWU	73555	11/19/2024 GEN	16 CON	RCCLOW01	EX00037284	THRUST RING M16,
							Consumables
RPS21	719QWU	73555	11/19/2024 GEN	16 CON	RCCLOW01	EX00037284	,
RPS21	719QWU	73555	11/19/2024 GEN	16 ENVLEV	RCCLOW01	EX00037284	ENVIRONMENTAL LEVY,
RPS21	719QWU	73555	11/19/2024 GEN	16 ENVLEV	RCCLOW01	39069	ENVIRONMENTAL LEVY,
							Consumables
RPS21	719QWU	73555	11/19/2024 GEN	16 CON	RCCLOW01	39069	,
RPS21	719QWU	73555	11/19/2024 GEN	16 CON	RCCLOW01	39069	THRUST RING M16,
RPS21	719QWU	73555	11/19/2024 GEN	16 CON	RCCLOW01	39069	O'RING M16,
RPS21	719QWU	73555	11/19/2024 GEN	16 CON	RCCLOW01	39069	O'RING M12,
RPS21	719QWU	73555	11/19/2024 GEN	16 CON	RCCLOW01	39069	THRUST RING M12,
RPS21	719QWU	73555	11/19/2024 GEN	13 PART	RCCLOW01	39069	DOCKING VALVE,
RPS21	719QWU	73555	11/19/2024 GEN	10 AIRBAG	RCCLOW01	39069	AIRBAG,
RPS21	719QWU	73555	11/19/2024 GEN	39 LABEXT	RCCLOW01	39069	REMOVE AND REPLACE LEAKING AIRBAG FRONT AXLE RIGHT SIDE, REMOVE ANI
RPS21	719QWU	73728	11/26/2024 DEFECT	1 LABOUR	MECH	Labour	
RPS21	719QWU	73729	11/26/2024 DEFECT	1 LABOUR	MECH	Labour	
RPS21	719QWU	73728	11/26/2024 DEFECT				
RPS21	719QWU	73729	11/26/2024 DEFECT				
RPS21	719QWU	73728	11/26/2024 DEFECT	DEFECT CLEARED.			
RPS21	719QWU	73729	11/26/2024 DEFECT	DEFECT CLEARED.			

				VEHICLE PASSED ANNUAL ROADWO RTHY INSPECTIO N. ATTEMPT # 1			
				INSPECTIO N COMPLET ED BY DIESEL SERVICES QLD ON 26/11/20 24 INVOICE NO. 00029943			
RPS21	719QWU	73729	11/26/2024 EXOINS	NO DEFECTS IDENTIFIE D			
RPS21	719QWU	73729	11/26/2024 EXOINS	1 LABEXT	DIESER01	EX00037400	CARRY OUT C & D SERVICE WITH BEARINGS & GREASE,
RPS21	719QWU	73729	11/26/2024 EXOINS	16 DEGREASER	DIESER01	EX00037400	DEGREASER, Consuma bles
RPS21	719QWU	73729	11/26/2024 EXOINS	16 CON	DIESER01	EX00037400	,
RPS21	719QWU	73729	11/26/2024 EXOINS	16 CON	DIESER01	29943	Consuma bles ,
RPS21	719QWU	73729	11/26/2024 EXOINS	16 DEGREASER	DIESER01	29943	DEGREASER,
RPS21	719QWU	73729	11/26/2024 EXOINS	1 LABEXT	DIESER01	29943	CARRY OUT C & D SERVICE WITH BEARINGS & GREASE,
RPS21	719QWU	73728	11/26/2024 TRA	1 LABOUR MECH	Labour		

RPS21	719QWU	73728	11/26/2024 TRA	SERVICE COMPLETED.			
RPS21	719QWU	73728	11/26/2024 TRB	1 LABOUR	MECH	Labour	
RPS21	719QWU	73728	11/26/2024 TRB	SERVICE COMPLETED.			
				SERVICE COMPLET ED BY DIESEL SERVICES QLD ON 26/11/20 24. INVOICE NO. 00029943			
				C and D service with bearings and grease. Remove, replace all bearings and seals, clean and repack all hubs. Retention			
RPS21	719QWU	73728	11/26/2024 TRC				
RPS21	719QWU	73728	11/26/2024 TRC	11 0980107040TSSC	YAT	KIT W/BRG & SEAL 10T ECO	
RPS21	719QWU	73728	11/26/2024 TRC	11 0321225310C	YAT	HCAP CHROME 136x2.5 E/PLUS	
RPS21	719QWU	73728	11/26/2024 TRC	11 2.57E+08	YAT	Hub Seal Grease, BPW, Eco Plus	
RPS21	719QWU	73728	11/26/2024 TRC	11 2.57E+08	YAT	O-RING	
RPS21	719QWU	73886	11/30/2024 GEN	39 LABEXT	RCLOW01	EX00037506	TRAVEL TO SUPPLIER TO SOURCE RIDE HEIGHT VALVE, CONTINUE ON TO EXOD/

RPS21	719QWU	73886	11/30/2024 GEN	10 PART	RCCLOW01	EX00037506	RIDE HEIGHT VALVE,
RPS21	719QWU	73886	11/30/2024 GEN	39 CALL OUT FEE	RCCLOW01	EX00037506	Call Out After Hours/Off Site,
							Consumables
RPS21	719QWU	73886	11/30/2024 GEN	16 CON	RCCLOW01	EX00037506	,
							Consumables
RPS21	719QWU	73886	11/30/2024 GEN	16 CON	RCCLOW01	39200	,
RPS21	719QWU	73886	11/30/2024 GEN	39 CALL OUT FEE	RCCLOW01	39200	Call Out After Hours/Off Site,
RPS21	719QWU	73886	11/30/2024 GEN	10 PART	RCCLOW01	39200	RIDE HEIGHT VALVE,
RPS21	719QWU	73886	11/30/2024 GEN	39 LABEXT	RCCLOW01	39200	TRAVEL TO SUPPLIER TO SOURCE RIDE HEIGHT VALVE, CONTINUE ON TO EXOD/
RPS21	719QWU	74447	12/16/2024 FVGEN	39 SUND	ICEGRO01	EX00037876	SUNDRIES,RPS21
RPS21	719QWU	74447	12/16/2024 FVGEN	39 LAB	ICEGRO01	EX00037876	Labour,RPS21
RPS21	719QWU	74447	12/16/2024 FVGEN	39 PART	ICEGRO01	EX00037876	SB FANSHAFT REBUILD KIT,RPS21
RPS21	719QWU	74447	12/16/2024 FVGEN	39 PART	ICEGRO01	EX00037876	BELT - MAIN DRIVE LOWER SB,RPS21
RPS21	719QWU	74447	12/16/2024 FVGEN	39 PART	ICEGRO01	EX00037876	LIGHT BAR KIT TK,RPS21
RPS21	719QWU	74447	12/16/2024 FVGEN	39 363636-005	ICEGRO01	EX00037876	LONGLIFE COOLANT PREMIX,RPS21
RPS21	719QWU	74447	12/16/2024 FVGEN	Service completed by Iceman 16/12/2024 - Inspected unit forreported high head pressure alarm codes - Found jackshaft failed and snapped lower belt - Removi			
RPS21	719QWU	74447	12/16/2024 FVGEN	39 SUND	ICEGRO01	893219	SUNDRIES,RPS21
RPS21	719QWU	74447	12/16/2024 FVGEN	39 LAB	ICEGRO01	893219	Labour,RPS21
RPS21	719QWU	74447	12/16/2024 FVGEN	39 PART	ICEGRO01	893219	SB FANSHAFT REBUILD KIT,RPS21
RPS21	719QWU	74447	12/16/2024 FVGEN	39 PART	ICEGRO01	893219	BELT - MAIN DRIVE LOWER SB,RPS21
RPS21	719QWU	74447	12/16/2024 FVGEN	39 PART	ICEGRO01	893219	LIGHT BAR KIT TK,RPS21
RPS21	719QWU	74447	12/16/2024 FVGEN	39 363636-005	ICEGRO01	893219	LONGLIFE COOLANT PREMIX,RPS21
							Consumables
RPS21	719QWU	74915	01/15/2025 FVGEN	39 CON	ICEGRO01	EX00038105	,RPS21
RPS21	719QWU	74915	01/15/2025 FVGEN	39 LAB	ICEGRO01	EX00038105	Labour,RPS21
RPS21	719QWU	74915	01/15/2025 FVGEN	Service completed by Iceman 15/01/2025 - Travelled to site and inspected unit - Found interior lights left on - Jump started as required - Checked operation - Ur			
							Consumables
RPS21	719QWU	74915	01/15/2025 FVGEN	39 CON	ICEGRO01	895083	,RPS21

RPS21	719QWU	74915	01/15/2025 FVGEN	39 LAB		ICEGRO01	895083	Labour,RPS21
RPS21	719QWU	75304	01/31/2025 DEFECT	1 LABOUR	MECH	Labour		
RPS21	719QWU	75304	01/31/2025 DEFECT					
RPS21	719QWU	75304	01/31/2025 DEFECT	DEFECT CLEARED.				

Reported

Defect :-

Defect

Code :

00013244

Defect

Reference

: RPS21

Date :

30/12/20

24

Description of

Defect :

LOAD

LOCKER

BAR

NEEDS

RPS21	719QWU	75304	01/31/2025 DEFECT	FIXING				
-------	--------	-------	-------------------	--------	--	--	--	--

				Reported Defect :- Defect Code : 00012961 Defect Reference : RPS21 Date : 18/11/20 24 Descriptio n of Defect : ROAD TRAIN SIGN BARELY VISIBLE				
RPS21	719QWU	75304	01/31/2025 DEFECT					
								Consuma bles ,RPS21
RPS21	719QWU	75391	01/31/2025 FVGEN	39 CON	ICEGRO01	EX00038364		
RPS21	719QWU	75391	01/31/2025 FVGEN	39 LAB	ICEGRO01	EX00038364		Labour,RPS21
RPS21	719QWU	75391	01/31/2025 FVGEN	Service completed by Iceman 31/01/2025 - Inspected unit - Replaced u/s battery (customer supplied) - Checked operation - Unit ran on test				
								Consuma bles ,RPS21
RPS21	719QWU	75391	01/31/2025 FVGEN	39 CON	ICEGRO01	896058		
RPS21	719QWU	75391	01/31/2025 FVGEN	39 LAB	ICEGRO01	896058		Labour,RPS21
RPS21	719QWU	75304	01/31/2025 TRA	1 LABOUR	MECH 6	Labour		

RPS21 719QWU 75304 01/31/2025 TRA

719QWU

01/31/2025 TRA

719QWU

01/31/2025 TRA

719QWU

01/31/2025 TRA

719QWU

01/31/2025 TRA

719QWU

01/31/2025 TRA

0 LABOUR APPRENJC Labour - Internal

16 CON	YAT	Consumables
--------	-----	-------------

13 MSRTLVCOMBO	YAT	2 PCE LONG VEHICLE & ROAD TRAIN SIGN
----------------	-----	--------------------------------------

				AIR GAUGE: 16.94 ADJUSTED : 16.64 WEIGHBRI DGE: 16.34			
RPS21	719QWU	75643	02/06/2025 WEICAL	Y.	AIR GAUGE CALIBRATI ON COMPLET ED CORRECTL		
RPS21	719QWU	75844	02/19/2025 FVGEN	39 CON	ICEGRO01	EX00038578	Consumables ,RPS21
RPS21	719QWU	75844	02/19/2025 FVGEN	39 33-2805-10	ICEGRO01	EX00038578	DISCHARGE GASKET,RPS21
RPS21	719QWU	75844	02/19/2025 FVGEN	39 R404A	ICEGRO01	EX00038578	GAS R404A,RPS21
RPS21	719QWU	75844	02/19/2025 FVGEN	39 NITRO	ICEGRO01	EX00038578	NITROGEN HIGH PURITY,RPS21
RPS21	719QWU	75844	02/19/2025 FVGEN	39 LAB	ICEGRO01	EX00038578	Labour,RPS21
RPS21	719QWU	75844	02/19/2025 FVGEN	39 61-0600-20	ICEGRO01	EX00038578	DRIER,RPS21
RPS21	719QWU	75844	02/19/2025 FVGEN	Service completed by Iceman 19/02/2025 - Inspected unit - Re-ran harness to high speed - Replaced blown fuse - Replaced u/s earth terminals - Checked operat			
RPS21	719QWU	75844	02/19/2025 FVGEN	39 CON	ICEGRO01	897396	Consumables ,RPS21
RPS21	719QWU	75844	02/19/2025 FVGEN	39 33-2805-10	ICEGRO01	897396	DISCHARGE GASKET,RPS21
RPS21	719QWU	75844	02/19/2025 FVGEN	39 R404A	ICEGRO01	897396	GAS R404A,RPS21
RPS21	719QWU	75844	02/19/2025 FVGEN	39 NITRO	ICEGRO01	897396	NITROGEN HIGH PURITY,RPS21
RPS21	719QWU	75844	02/19/2025 FVGEN	39 LAB	ICEGRO01	897396	Labour,RPS21
RPS21	719QWU	75844	02/19/2025 FVGEN	39 61-0600-20	ICEGRO01	897396	DRIER,RPS21
RPS21	719QWU	75974	02/24/2025 FVGEN	39 R404A	ICEGRO01	EX00038649	GAS R404A,RPS21
RPS21	719QWU	75974	02/24/2025 FVGEN	39 SUND	ICEGRO01	EX00038649	SUNDRIES INCL. EPA CHARGE,RPS21

RPS21	719QWU	75974	02/24/2025 FVGEN	----- 39 LAB complete d by Iceman 24/02/20 25 - REPAIRS..L OADED.. @ TRUGANI NA WORKSH OP Inspected unit - Cooling cycle fault - Installed guages - Checked refrigeran t level & pressures - Topped up refrigeran t level - Rechecke	ICEGRO01	EX00038649	Labour,RPS21
RPS21	719QWU	75974	02/24/2025 FVGEN				
RPS21	719QWU	75974	02/24/2025 FVGEN	39 R404A	ICEGRO01	897800	GAS R404A,RPS21
RPS21	719QWU	75974	02/24/2025 FVGEN	39 SUND	ICEGRO01	897800	SUNDRIES INCL. EPA CHARGE,RPS21
RPS21	719QWU	75974	02/24/2025 FVGEN	39 LAB	ICEGRO01	897800	Labour,RPS21
RPS21	719QWU	75979	02/27/2025 DEFECT	1 LABOUR	MECH	Labour	
RPS21	719QWU	75979	02/27/2025 DEFECT	DEFECT CLEARED.			

				Defect :- Defect Code : 00008911 Defect Reference : 36195 Date : 12/03/20 23 Description n of Defect : MISSING R FRIDGE DOOR INTERNAL LIGHT SWITCH DAMAGE D & BROKEN DEFECT CLEARED ON 27/02/20				
RPS21	719QWU	75979	02/27/2025	DEFECT				
RPS21	719QWU	76102	02/27/2025	FVGEN	39 NITRO	ICEGRO01	EX00038717	NITROGEN HIGH PURITY,RPS21
RPS21	719QWU	76102	02/27/2025	FVGEN	39 CON	ICEGRO01	EX00038717	Consumables ,RPS21
RPS21	719QWU	76102	02/27/2025	FVGEN	39 LAB	ICEGRO01	EX00038717	Labour,RPS21
RPS21	719QWU	76102	02/27/2025	FVGEN	39 R404A	ICEGRO01	EX00038717	GAS R404A,RPS21
RPS21	719QWU	76102	02/27/2025	FVGEN	39 PART	ICEGRO01	EX00038717	WELDING & MATERIALS,RPS21
RPS21	719QWU	76102	02/27/2025	FVGEN	Service completed by Iceman 25/02/2025 - Inspected unit and attached guages - Carried out leak test - Found leak at capillary manifold - Removed gas from the			

RPS21	719QWU	76102	02/27/2025 FVGEN	39 NITRO	ICEGRO01	898030	NITROGEN HIGH PURITY,RPS21
RPS21	719QWU	76102	02/27/2025 FVGEN	39 CON	ICEGRO01	898030	Consumables,RPS21
RPS21	719QWU	76102	02/27/2025 FVGEN	39 LAB	ICEGRO01	898030	Labour,RPS21
RPS21	719QWU	76102	02/27/2025 FVGEN	39 R404A	ICEGRO01	898030	GAS R404A,RPS21
RPS21	719QWU	76102	02/27/2025 FVGEN	39 PART	ICEGRO01	898030	WELDING & MATERIALS,RPS21
RPS21	719QWU	75979	02/27/2025 TRA	1 LABOUR	MECH 5	Labour - Internal	
				COMPLETED BY BEN, TYLER & JOSH (WORKSHOP) ON 27/02/2025.			
				FITTED RRR LHS REAR BAR INTERIOR LIGHT SWITCH HAS BEEN REPAIRED. R CLIP HAS BEEN FITTED TO FRIDGE DOORS TIGHTENED REAR AIR TANK BOLTS			
RPS21	719QWU	75979	02/27/2025 TRA	16 CON	YAT	Consumables	
RPS21	719QWU	75979	02/27/2025 TRA	0 LABOUR	APPRENTICE	Labour - Internal	
RPS21	719QWU	75979	02/27/2025 TRA	0 LABOUR	APPRENTICE	Labour - Internal	

RPS21	719QWU	76405	03/17/2025 TYRES	15	33000114	BRIAUS01	EX00038950	RE-TORQUE TRUCK WHEEL EA WHEEL,
RPS21	719QWU	76405	03/17/2025 TYRES	15	33000096	BRIAUS01	EX00038950	PUNCTURE REPAIR TBR,
RPS21	719QWU	76405	03/17/2025 TYRES	15	33000114	BRIAUS01	1.9E+08	RE-TORQUE TRUCK WHEEL EA WHEEL,
RPS21	719QWU	76405	03/17/2025 TYRES	15	33000096	BRIAUS01	1.9E+08	PUNCTURE REPAIR TBR,
RPS21	719QWU	76883	04/07/2025 GEN	39	PART	FNQAUT01	EX00039274	GENERAL PART CODE,
RPS21	719QWU	76883	04/07/2025 GEN	39	PART	FNQAUT01	EX00039274	GENERAL PART CODE,
RPS21	719QWU	76883	04/07/2025 GEN	39	LAB	FNQAUT01	EX00039274	Labour,
RPS21	719QWU	76883	04/07/2025 GEN	39	LAB	FNQAUT01	EX00039274	Labour,
RPS21	719QWU	76883	04/07/2025 GEN	39	PART	FNQAUT01	51885	GENERAL PART CODE,
RPS21	719QWU	76883	04/07/2025 GEN	39	PART	FNQAUT01	51885	GENERAL PART CODE,
RPS21	719QWU	76883	04/07/2025 GEN	39	LAB	FNQAUT01	51885	Labour,
RPS21	719QWU	76883	04/07/2025 GEN	39	LAB	FNQAUT01	51885	Labour,
RPS21	719QWU	77455	05/02/2025 DEFECT	1	LABOUR	MECH	Labour	
RPS21	719QWU	77455	05/02/2025 DEFECT	DEFECT CLEARED.				
RPS21	719QWU	77455	05/02/2025 TRA	1	LABOUR	APPREN	Labour - Internal	
				A SERVICE COMPLET ED BY WORKSH OP 01/05/20 25				
				FIRE EXT EXP: AUGUST 2025				
				REPLACED RHS CLEARANC E LIGHT FITTED R CLIPS TO FRIDGE DOORS				
RPS21	719QWU	77455	05/02/2025 TRA					
RPS21	719QWU	77455	05/02/2025 TRA	16	CON	YAT	Consumables	
RPS21	719QWU	77455	05/02/2025 TRA	0	LABOUR	APPRENJ	Labour - Internal	
RPS21	719QWU	77455	05/02/2025 TRA	0	LABOUR	APPRENJC	Labour - Internal	
RPS21	719QWU	77455	05/02/2025 TRA	16	91700BL	YAT	Clearance Light, LED Amber, Narva	

RPS21	719QWU	77675	05/14/2025 FRIVANB	----- 0 LABOUR	MECH	Labour
				VAN "B"		
				SERVICE		
				COMPLET		
				ED.		
				FRIDGE		
				VAN UNIT		
				CALIBRAT		
				ED @		
				SERVICE.		
				SERVICE		
				COMPLET		
				ED BY		
				BVR.		
				OIL 14L		
				(Customer		
				Supplied)		
				CALIBRATI		
				ON		
				CERTIFICA		
				TE		
				R+R		
				ENGINE		
				OIL		
RPS21	719QWU	77675	05/14/2025 FRIVANB	R+R		

RPS21	719QWU	77675	05/14/2025 FRIVANB	39 CON	ICEGRO01	EX00039836	Consumables ,RPS21
RPS21	719QWU	77675	05/14/2025 FRIVANB	39 CC	ICEGRO01	EX00039836	CALIBRATION CETIFICATE,RPS21
RPS21	719QWU	77675	05/14/2025 FRIVANB	39 100417	ICEGRO01	EX00039836	Filter Service Kit, Fridge Motor, SLX-400,RPS21
RPS21	719QWU	77675	05/14/2025 FRIVANB	39 LAB	ICEGRO01	EX00039836	Labour,RPS21
RPS21	719QWU	77675	05/14/2025 FRIVANB	6 COOLANT	YAT COOLANT		
RPS21	719QWU	77675	05/14/2025 FRIVANB	Service completed by Iceman 01/05/2025 - Carried out B Service as per Iceman Specifications - Topped up 1L coolant (customer supplied)			
RPS21	719QWU	77675	05/14/2025 FRIVANB	39 CON	ICEGRO01	902271	Consumables ,RPS21
RPS21	719QWU	77675	05/14/2025 FRIVANB	39 CC	ICEGRO01	902271	CALIBRATION CETIFICATE,RPS21
RPS21	719QWU	77675	05/14/2025 FRIVANB	39 100417	ICEGRO01	902271	Filter Service Kit, Fridge Motor, SLX-400,RPS21
RPS21	719QWU	77675	05/14/2025 FRIVANB	39 LAB	ICEGRO01	902271	Labour,RPS21
RPS21	719QWU	77675	05/14/2025 FRIVCAL	1 LABOUR MECH	Labour		
RPS21	719QWU	77675	05/14/2025 FRIVCAL	FRIDGE VAN CALIBRATION COMPLETED			
RPS21	719QWU	77973	05/15/2025 TYRES	15 11002821	BRIAUS01	EX00040027	11R22.5 148/145L BS R119 ECO,
RPS21	719QWU	77973	05/15/2025 TYRES	15 77000232	BRIAUS01	EX00040027	CASE STOCK 11R22.5 ECOPIA,
RPS21	719QWU	77973	05/15/2025 TYRES	15 33000084	BRIAUS01	EX00040027	FIT TBR TYRE,
RPS21	719QWU	77973	05/15/2025 TYRES	15 33000517	BRIAUS01	EX00040027	REMOVAL: CUSTOMER PULL POINT,
RPS21	719QWU	77973	05/15/2025 TYRES	15 33000085	BRIAUS01	EX00040027	ROTATE TBR TYRE,
RPS21	719QWU	77973	05/15/2025 TYRES	15 33000118	BRIAUS01	EX00040027	SCHEDULED DEPOT SERVICE 15MIN,
RPS21	719QWU	77973	05/15/2025 TYRES	15 11002821	BRIAUS01	1.91E+08	11R22.5 148/145L BS R119 ECO,
RPS21	719QWU	77973	05/15/2025 TYRES	15 77000232	BRIAUS01	1.91E+08	CASE STOCK 11R22.5 ECOPIA,
RPS21	719QWU	77973	05/15/2025 TYRES	15 33000084	BRIAUS01	1.91E+08	FIT TBR TYRE,
RPS21	719QWU	77973	05/15/2025 TYRES	15 33000517	BRIAUS01	1.91E+08	REMOVAL: CUSTOMER PULL POINT,
RPS21	719QWU	77973	05/15/2025 TYRES	15 33000085	BRIAUS01	1.91E+08	ROTATE TBR TYRE,
RPS21	719QWU	77973	05/15/2025 TYRES	15 33000118	BRIAUS01	1.91E+08	SCHEDULED DEPOT SERVICE 15MIN,
RPS21	719QWU	78348	06/04/2025 DEFECT	1 LABOUR MECH	Labour		
RPS21	719QWU	78348	06/04/2025 DEFECT	DEFECT CLEARED.			
RPS21	719QWU	78348	06/04/2025 TRA	1 LABOUR APPREN	Labour - Internal		

				A SERVICE COMPLET ED BY WORKSH OP 04.06.202 5		
				FIRE EXT EXP: AUGUST 2025		
				ADJUSTED RIDE HEIGHT REPLACED BOTH FRONT SHOCKS		
RPS21	719QWU	78348	06/04/2025 TRA			
RPS21	719QWU	78348	06/04/2025 TRA	16 CON	YAT	Consumables
RPS21	719QWU	78348	06/04/2025 TRA	16 F5002	YAT	SHOCK ABSORBER, BPW LONG
				WEIGHBRI DGE:1730 0 AIR GAUGE:17 000 ADJUSTED : 17300		
				AIR GAUGE CALIBRATI ON COMPLET ED CORRECTL Y.		
RPS21	719QWU	81722	06/30/2025 WEICAL			

RPS21	719QWU	79458	07/22/2025 DEFECT	1 LABOUR	MECH	Labour
RPS21	719QWU	79458	07/22/2025 DEFECT	DEFECT CLEARED.		
				Reported Defect :- Defect Code : 00014042 Defect Reference : RPS21 Date : 16/04/20 25 Description n of Defect : PLEASE CHECK REAR EVAPORA TOR/LEAK S IN REAR PIPE FOLLOWI NG WATER DAMAGE TO STOCK.		
RPS21	719QWU	79458	07/22/2025 DEFECT			
RPS21	719QWU	79458	07/22/2025 TRA	1 LABOUR	MECH	Labour - Internal
				A SERVICE COMPLET ED.		
RPS21	719QWU	79458	07/22/2025 TRA	FIRE EXT EXP:		
RPS21	719QWU	79458	07/22/2025 TRA	16 CON	YAT	Consumables

RPS21	719QWU	79458	07/22/2025 TRB	-----1 LABOUR	MECH 1	Labour - Internal	
				COMPLET			
				ED BY			
				WORKSH			
				OP			
				22/7/202			
				5			
				FIRE EXT			
				EXP:			
				AUGUST			
				2025			
				REPLACED			
				TOGGLE			
				SWITCH			
				FOR			
				REVERSE			
				BEEPER			
				REPLACED			
				SEAL IN			
				FEMALE			
				FITTING			
				REFIT			
				REAR OF			
				AIR			
RPS21	719QWU	79458	07/22/2025 TRB	SHOOT			
				DUE TO			
RPS21	719QWU	79458	07/22/2025 TRB	16 CON	YAT	Consumables	
RPS21	719QWU	79458	07/22/2025 TRB	0 LABOUR	APPRENJC	Labour - Internal	
RPS21	719QWU	79458	07/22/2025 TRB	0 LABOUR	APPREND	Labour - Internal	
RPS21	719QWU	79458	07/22/2025 TRB	0 LABOUR	APPREN	Labour - Internal	
RPS21	719QWU	79458	07/22/2025 TRB	16 60060BL	YAT	SWITCH TOGGLE ON/OFF	
RPS21	719QWU	80211	08/18/2025 TYRES	15 11004118	BRIAUS01	EX00041584	11R22.5 148/145L BS R1668II,
RPS21	719QWU	80211	08/18/2025 TYRES	15 33000084	BRIAUS01	EX00041584	FIT TBR TYRE,
RPS21	719QWU	80211	08/18/2025 TYRES	15 33000241	BRIAUS01	EX00041584	SCRAP TYRES TBR,
RPS21	719QWU	80211	08/18/2025 TYRES	15 33000125	BRIAUS01	EX00041584	ETA MIN FEE,
RPS21	719QWU	80211	08/18/2025 TYRES	15 33000116	BRIAUS01	EX00041584	SVC CALL OUT AFTER HOURS/15MINS,
RPS21	719QWU	80211	08/18/2025 TYRES	15 33000237	BRIAUS01	EX00041584	POS 27,28 CALLOUT TO BRUCE HIGHWAY,

RPS21	719QWU	80211	08/18/2025 TYRES	15 11004118	BRIAUS01	1.91E+08	11R22.5 148/145L BS R1668II,
RPS21	719QWU	80211	08/18/2025 TYRES	15 33000084	BRIAUS01	1.91E+08	FIT TBR TYRE,
RPS21	719QWU	80211	08/18/2025 TYRES	15 33000241	BRIAUS01	1.91E+08	SCRAP TYRES TBR,
RPS21	719QWU	80211	08/18/2025 TYRES	15 33000125	BRIAUS01	1.91E+08	ETA MIN FEE,
RPS21	719QWU	80211	08/18/2025 TYRES	15 33000116	BRIAUS01	1.91E+08	SVC CALL OUT AFTER HOURS/15MINS,
RPS21	719QWU	80211	08/18/2025 TYRES	15 33000237	BRIAUS01	1.91E+08	POS 27,28 CALLOUT TO BRUCE HIGHWAY,
							Consumables
RPS21	719QWU	80288	08/21/2025 FVGEN	39 CON	icegro01	EX00041639	,RPS21
							Consumables
RPS21	719QWU	80687	08/21/2025 FVGEN	39 CON	ICEGRO01	EX00041886	,RPS21
RPS21	719QWU	80288	08/21/2025 FVGEN	39 R404A	icegro01	EX00041639	GAS R404A,RPS21
RPS21	719QWU	80687	08/21/2025 FVGEN	39 R404A	ICEGRO01	EX00041886	GAS R404A,RPS21
RPS21	719QWU	80288	08/21/2025 FVGEN	39 LAB	icegro01	EX00041639	Labour,RPS21
RPS21	719QWU	80687	08/21/2025 FVGEN	39 LAB	ICEGRO01	EX00041886	Labour,RPS21
				COMPLETED BY ICEMAN 21/08/2025 INSPECTED UNIT...FOUND UNDERSMALL LEAK FROM CHECK VALVE RETENSIONED BOLTS AND CHECKED.. .OK TOPPED UP GAS CHECKED OPERATION...UNIT RAN ON TEST			
RPS21	719QWU	80288	08/21/2025 FVGEN				

RPS21	719QWU	80687	08/21/2025 FVGEN	SERVICE COMPLETED BY ICEMAN 21/08/2025 - INSPECTED UNIT...FOUND SMALL LEAK FROM CHECK VALVE - RETENSIONED BOLTS AND CHECKED...OK - TOPPED				
RPS21	719QWU	80687	08/21/2025 FVGEN	39 CON	ICEGRO01	909429	Consumables,RPS21	
RPS21	719QWU	80687	08/21/2025 FVGEN	39 R404A	ICEGRO01	909429	GAS R404A,RPS21	
RPS21	719QWU	80687	08/21/2025 FVGEN	39 LAB	ICEGRO01	909429	Labour,RPS21	
RPS21	719QWU	80209	08/21/2025 GEN	39 LABOUR	MECH 5	Labour		
				REPAIR COMPLETED BY WORKSHOP 21/8/2025				
				REPAIRED MUDGUARD BRACKETS AND REPLACED ALL MUDGUARDS ON LHS				
RPS21	719QWU	80209	08/21/2025 GEN					
RPS21	719QWU	80209	08/21/2025 GEN	16 CON	YAT	Consumables		
RPS21	719QWU	80209	08/21/2025 GEN	0 LABOUR	APPRENC	Labour - Internal		
RPS21	719QWU	80209	08/21/2025 GEN	0 LABOUR	APPREN	Labour - Internal		
RPS21	719QWU	80209	08/21/2025 GEN	16 K127-1116-08A	YAT	Mudguard Red		
RPS21	719QWU	80409	08/28/2025 DEFECT	1 LABOUR	MECH	Labour		
RPS21	719QWU	80409	08/28/2025 DEFECT	DEFECT CLEARED.				
RPS21	719QWU	80409	08/28/2025 TRA	1 LABOUR	MECH	Labour - Internal		

				A SERVICE COMPLET ED BY NQFM 28/8/202 5			
				FIRE EXT EXP: FEBRUARY 2026			
RPS21	719QWU	80409	08/28/2025 TRA	INVOICE #41242			
RPS21	719QWU	80409	08/28/2025 TRA	16 CON	YAT	Consumables	
RPS21	719QWU	80409	08/28/2025 TRA	1 LABEXT	RCCLOW01	EX00041719	Labour External,
RPS21	719QWU	80409	08/28/2025 TRA	1 LABEXT	RCCLOW01	EX00041719	Labour External,REPLACE SIDE LIGHT - BOTTOM LEFT SIDE SECOND FROM REAR
RPS21	719QWU	80409	08/28/2025 TRA	1 TEST	RCCLOW01	EX00041719	TEST AND TAG FIRE EXTINGUISHER,
RPS21	719QWU	80409	08/28/2025 TRA	1 GREASE	RCCLOW01	EX00041719	GREASE,
RPS21	719QWU	80409	08/28/2025 TRA	1 BAG	RCCLOW01	EX00041719	BAG FIRE,
							Consuma bles
RPS21	719QWU	80409	08/28/2025 TRA	1 CON	RCCLOW01	EX00041719	,
RPS21	719QWU	80409	08/28/2025 TRA	1 ENVLEV	RCCLOW01	EX00041719	ENVIRONMENTAL LEVY,
RPS21	719QWU	80409	08/28/2025 TRA	1 GENERAL PARTS	RCCLOW01	EX00041719	Parts Supplied,AMBER SIDE LIGHT
RPS21	719QWU	80409	08/28/2025 TRA	1 LABEXT	RCCLOW01	41242	Labour External,
RPS21	719QWU	80409	08/28/2025 TRA	1 LABEXT	RCCLOW01	41242	Labour External,REPLACE SIDE LIGHT - BOTTOM LEFT SIDE SECOND FROM REAR
RPS21	719QWU	80409	08/28/2025 TRA	1 TEST	RCCLOW01	41242	TEST AND TAG FIRE EXTINGUISHER,
RPS21	719QWU	80409	08/28/2025 TRA	1 GREASE	RCCLOW01	41242	GREASE,
RPS21	719QWU	80409	08/28/2025 TRA	1 BAG	RCCLOW01	41242	BAG FIRE,
							Consuma bles
RPS21	719QWU	80409	08/28/2025 TRA	1 CON	RCCLOW01	41242	,
RPS21	719QWU	80409	08/28/2025 TRA	1 ENVLEV	RCCLOW01	41242	ENVIRONMENTAL LEVY,
RPS21	719QWU	80409	08/28/2025 TRA	1 GENERAL PARTS	RCCLOW01	41242	Parts Supplied,AMBER SIDE LIGHT
RPS21	719QWU	81550	10/18/2025 DEFECT	1 LABOUR MECH	Labour		
RPS21	719QWU	81550	10/18/2025 DEFECT	DEFECT CLEARED.			

				Reported Defect :- Defect Code : 00015395 Defect Reference : 10642 Date : 18/10/20 25 Description n of Defect : NEED DIESEL LID				
RPS21	719QWU	81550	10/18/2025 DEFECT					
RPS21	719QWU	81550	10/18/2025 GEN	39 LABOUR	APPREN	Labour		
				REPAIR COMPLET ED BY WORKSH OP 18/10/20 25				
RPS21	719QWU	81550	10/18/2025 GEN	REPLACED MISSING FUEL CAP				
RPS21	719QWU	81550	10/18/2025 GEN	16 CON		YAT	Consumables	
RPS21	719QWU	82086	10/31/2025 FRIVANB	0 LABOUR	MECH	Labour		

RPS21	719QWU	82086	10/31/2025 FRIVANB	VAN "B" SERVICE COMPLET ED. FRIDGE VAN UNIT CALIBRAT ED @ SERVICE. SERVICE COMPLET ED BY ICEMAN OIL 14L (Customer Supplied) CALIBRATI ON CERTIFICA TE R+R ENGINE OIL R+R
-------	--------	-------	--------------------	---

RPS21	719QWU	82086	10/31/2025 FRIVANB	39 CON	ICEGRO01	EX00042816	Consumables,RPS21
RPS21	719QWU	82086	10/31/2025 FRIVANB	39 CC	ICEGRO01	EX00042816	CALIBRATION CETIFICATE,RPS21
RPS21	719QWU	82086	10/31/2025 FRIVANB	39 100417	ICEGRO01	EX00042816	Filter Service Kit, Fridge Motor, SLX-400,RPS21
RPS21	719QWU	82086	10/31/2025 FRIVANB	39 33-2805-10	ICEGRO01	EX00042816	DISCHARGE GASKET,RPS21
RPS21	719QWU	82086	10/31/2025 FRIVANB	39 R404A	ICEGRO01	EX00042816	GAS R404A,RPS21
RPS21	719QWU	82086	10/31/2025 FRIVANB	39 NITRO	ICEGRO01	EX00042816	NITROGEN HIGH PURITY,RPS21
RPS21	719QWU	82086	10/31/2025 FRIVANB	39 LAB	ICEGRO01	EX00042816	Labour,RPS21
RPS21	719QWU	82086	10/31/2025 FRIVANB	39 600298	ICEGRO01	EX00042816	THROTTLING VALVE REPAIR KIT,RPS21
RPS21	719QWU	82086	10/31/2025 FRIVANB	40 3413005	YAT OIL 15W-40, CK 4/E9		
RPS21	719QWU	82086	10/31/2025 FRIVANB	SERVICE COMPLETED BY ICEMAN 31/10/2025 - CARRIED OUT "B" SERVICE AS PER ICEMAN SPECIFICATIONS - THROTTLING VALVE LEAKING...CARRIED OUT LOW !			
RPS21	719QWU	82086	10/31/2025 FRIVANB	39 CON	ICEGRO01	913818	Consumables,RPS21
RPS21	719QWU	82086	10/31/2025 FRIVANB	39 CC	ICEGRO01	913818	CALIBRATION CETIFICATE,RPS21
RPS21	719QWU	82086	10/31/2025 FRIVANB	39 100417	ICEGRO01	913818	Filter Service Kit, Fridge Motor, SLX-400,RPS21
RPS21	719QWU	82086	10/31/2025 FRIVANB	39 33-2805-10	ICEGRO01	913818	DISCHARGE GASKET,RPS21
RPS21	719QWU	82086	10/31/2025 FRIVANB	39 R404A	ICEGRO01	913818	GAS R404A,RPS21
RPS21	719QWU	82086	10/31/2025 FRIVANB	39 NITRO	ICEGRO01	913818	NITROGEN HIGH PURITY,RPS21
RPS21	719QWU	82086	10/31/2025 FRIVANB	39 LAB	ICEGRO01	913818	Labour,RPS21
RPS21	719QWU	82086	10/31/2025 FRIVANB	39 600298	ICEGRO01	913818	THROTTLING VALVE REPAIR KIT,RPS21
RPS21	719QWU	82086	10/31/2025 FRIVCAL	1 LABOUR MECH	Labour		
RPS21	719QWU	82086	10/31/2025 FRIVCAL	FRIDGE VAN CALIBRATION COMPLETED			
			Total for Asset	#####			
			Total for Report	#####			

Options:
Sort By
-
AssetCode
Starting
Asset
Code -
RPS21
To
- RPS21
Starting
Registrati
on -
To
-
Starting
Operation
s No -
To
-
From:
Work
Order
Location -
To
-
From:

LTS REPLACED DRIER - PERFORMED SYTEM CHECKS AS PER CHECK SHEET. RAN UNIT- CALIBRATED UNIT - UNIT

AND REPALCED ALL BELTS REPLACED DRIER - PERFORMED SYTEM CHECKS AS PER CHECK SHEET. RAN UNIT- CALIBRATED UNIT - UNIT

I - REPAIR

anel with new hinges - Unit run on t

oroughly wash condenser coil - Still running warn but not hot - Drain coolant - Remove and replace u/s thermostat and replace coolant - Check over, engine running at a good temp - Run unit to 7c - Unit run on t

Replace coolant - Test operation - Unit run on t

s, worn compressor oil pump (as key and shaft are extremely worn/have play - Refit compressor - Remove and replace cracked HP switches - Replace drier - Vac out unit - Unit run on tr

.ND REPLACED ALTERNATOR BE

.ND REPLACED ALTERNATOR BE

oin off of distributor block - Pump down unit and repair leak as required - Pressure test system - Vac out unit and regas system - Top up gas - Run to 0o in both zones and check gas level - Unit run on ti

I - Unit run on t

Jobbed through - Re-seal hose as required - Unit run on t

AND REPLACE LEAKING DOCK VAL'

AND REPLACE LEAKING DOCK VAL'

DDAS DEPOT TO LOOK AT TRAILER RIDE HEIGHT VALVE. PLASTIC IS FLOPPED OUT, REPLACED VALVE AND SET RIDE HEIGHT AS REQUIRE

DDAS DEPOT TO LOOK AT TRAILER RIDE HEIGHT VALVE. PLASTIC IS FLOPPED OUT, REPLACED VALVE AND SET RIDE HEIGHT AS REQUIRE

oved jackshaft and rebuilt with new bearings - Reinstalled jackshaft , replaced u/s lower belt - Topped up coolant - Replaced u/s status light - Run unit down to 0c - Unit ran to tesst - All

- Unit ran on t

ation of high speed, ok - Installed guages - Checked refrigerant level & pressures - Replaced leaking drier - Pumped system down- Replaced leaking drier - Removed discharge service valve - Sealed leaking HP switches - Refitted valve and new gaskets - P

the system - Carried out repair on cracked pipe - Repaired small leak on drain heater pipe - Vac out and regas system - Unit faulting on drain heater zone 2 - Found and repaired wiring on drain heaters - Resecured zone 2 drain pipe onto wall - Unit ran on

'ED UP GAS - CHECKED OPERATION...UNIT RAN ON TE

W SIDE PUMP DOWN - REBUILT THROTTLING VALVE - REPLACED DISCHARGE GASKET - PRESSURE TESTED COMPRESSOR AND CHECKED - VAC OUT UNIT AND REGASSED SYSTEM - CHECKED OPERATION...UNIT RAN ON TE

ressure tested system with nitrogen, ok - Vac out unit and regassed system - Checked operation - Unit ran on te

