

W/O No	Asset No	Asset Description	Description	Job Type	Finished Date/Time	Downtime	Repair Time	Component Code	Department	Parent Asset	Labour Costs	Material Costs	Other Costs
1027	I368	Mack Super-Liner Day Cab - 6x4	A Service - Trucks A Service was completed.	PM	03/10/2017	2	2		Hemmant	General Freight	0	126.41	0
1532	I368	Mack Super-Liner Day Cab - 6x4	B Service - Mack MP8 and MP10	PM	10/05/2017	0	0		Toowoomba	General Freight	0	948.55	0
1696	I368	Mack Super-Liner Day Cab - 6x4	A Service - Trucks A Service Completed	PM	11/08/2017	0	0		Toowoomba	General Freight	0	92.1	0
1739	I368	Mack Super-Liner Day Cab - 6x4	Actual KMS 180241 A Service - Trucks A Service Completed	PM	11/28/2017	0	0		Hemmant	General Freight	0	79.1	0
1889	I368	Mack Super-Liner Day Cab - 6x4	Actual KMS 193082	PM	01/24/2018	0	0		Hemmant	General Freight	97.5	100.75	0
2205	I368	Mack Super-Liner Day Cab - 6x4	TRUCK ADBLUE- A Service-10,000KMS TRUCK ADBLUE- A Service-10,000KMS A Service completed Actual 220128kms	PM	04/04/2018	0	0		Hemmant	General Freight	97.5	87.1	0
2283	I368	Mack Super-Liner Day Cab - 6x4	TRUCK ADBLUE- A Service-10,000KMS A Service completed	PM	04/26/2018	0	0		Hemmant	General Freight	97.5	87.1	0
2321	I368	Mack Super-Liner Day Cab - 6x4	Actual 235475kms TRUCK ADBLUE- C Service -120,000KMS C Service completed	PM	05/26/2018	0	0		Toowoomba	General Freight	52.5	87.1	0
2373	I368	Mack Super-Liner Day Cab - 6x4	Actual 241865kms TRUCK ADBLUE- A Service-10,000KMS A Service Completed	PM	06/11/2018	0	0		Hemmant	General Freight	650	1768.85	0
2670	I368	Mack Super-Liner Day Cab - 6x4	Actual 269817kms TRUCK ADBLUE- B Service- 40,000KMS B Service completed	PM	08/22/2018	0	0		Hemmant	General Freight	52.5	87.1	0
3477	I368	Mack Super-Liner Day Cab - 6x4	Actual 280274kms TRUCK ADBLUE- A Service-10,000KMS A Service Completed	PM	10/03/2018	0	0		Hemmant	General Freight	292.5	948.55	0
3634	I368	Mack Super-Liner Day Cab - 6x4	Actual 290476kms	PM	11/20/2018	0	0		Hemmant	General Freight	97.5	108.3	0
4137	I368	Mack Super-Liner Day Cab - 6x4	Change Tyre	R & M	12/21/2018	0	0		Hemmant	General Freight	100	0	0
4577	I368	Mack Super-Liner Day Cab - 6x4	Load on to Float	R & M	01/24/2019	0	0		Toowoomba	General Freight	200	0	0
5538	I368	Mack Super-Liner Day Cab - 6x4	Get vehicle ready to run engine. Look over engine and starting system, to determine work required b ...	R & M	03/26/2019	0	0		Hemmant	General Freight	260	189.5	0
5541	I368	Mack Super-Liner Day Cab - 6x4	Get truck ready to start, cut off broken fan shroud, fit fuel banjo bolt, check intake for oil and ...	R & M	03/26/2019	0	0		Hemmant	General Freight	175	241.16	0
5557	I368	Mack Super-Liner Day Cab - 6x4	27/03 TomM and TomP- Go to ops and check if the key had arrived from Toowoomba. Turn engine over mu ...	R & M	03/27/2019	0	0		Hemmant	General Freight	-4028.75	25	0
5604	I368	Mack Super-Liner Day Cab - 6x4	Air truck up with 3/8" fitting into air fdryer, no governor valve on dryer so would not take over, f ...	R & M	03/29/2019	0	0		Hemmant	General Freight	230	34.26	0
6098	I368	Mack Super-Liner Day Cab - 6x4	Assess aprts which have been removed from Truck. Remove & strip bonnet, headlights etc, degrease &	R & M	05/07/2019	0	0		Hemmant	General Freight	520	0	0
6109	I368	Mack Super-Liner Day Cab - 6x4	Help take off bonnet of 368 and gave it a good wash down.	R & M	05/07/2019	0	0		Hemmant	General Freight	122.5	0	0
6139	I368	Mack Super-Liner Day Cab - 6x4	Looked over & reviewed both repair quotes, realised chassis still hadnt been drop tested. Removed t ...	R & M	05/08/2019	0	0		Hemmant	General Freight	260	0	0
6159	I368	Mack Super-Liner Day Cab - 6x4	Find driveshaft, clean up flanges & slip joint, fit driveshaft. Clean out cab, throw rubbish, vaccu ...	R & M	05/09/2019	0	0		Hemmant	General Freight	536.25	0	0
6175	I368	Mack Super-Liner Day Cab - 6x4	Start stripping down cab with Tom M	R & M	05/09/2019	0	0		Hemmant	General Freight	65	0	0
6177	I368	Mack Super-Liner Day Cab - 6x4	Look for ilde pulley bracket.	R & M	05/09/2019	0	0		Hemmant	General Freight	32.5	0	0
6192	I368	Mack Super-Liner Day Cab - 6x4	Finish fitting air comps receiver dryer, pickup fittings from Pirtek. Fit A/c Compressor, Fit drive ...	R & M	05/10/2019	0	0		Hemmant	General Freight	585	0	0
6220	I368	Mack Super-Liner Day Cab - 6x4	Fit intake pipe, Fit transmission fitting, fit exhaust flex, Call around and find tensioner & space ...	R & M	05/13/2019	0	0		Hemmant	General Freight	422.5	0	0
6238	I368	Mack Super-Liner Day Cab - 6x4	Strip cab for removal, strip firewall, air lines, wirring harness, cab shockes & mounts etc. Remove ...	R & M	05/14/2019	0	0		Hemmant	General Freight	633.75	0	0



7852	I368	Assemble last mudguard, Install chrome strips on Mack Super-Liner Day Cab - 6x4guards.	R & M	08/24/2019	0	0	Hemmant	General Freight	240	0	0
7859	I368	Mack Super-Liner Day Cab - 6x4Help set up mudguard poles, lights for the new truck.	R & M	08/22/2019	0	0	Hemmant	General Freight	120	0	0
7867	I368	Remove turntable feet off # 275 wreck down the Mack Super-Liner Day Cab - 6x4back. P/U bolts for turntable and base plate. Fabric ...	R & M	08/26/2019	0	0	Hemmant	General Freight	627.5	0	0
7875	I368	Look at turntable leg length of Superliners, Drive to Mack Super-Liner Day Cab - 6x4Boltbiz, wait for them to get bolts. Lift tur ...	R & M	08/26/2019	0	0	Hemmant	General Freight	120	0	0
7894	I368	Installing hood lockers, cutting and fitting indicator Mack Super-Liner Day Cab - 6x4brackets, installing guards and guard holder ...	R & M	08/23/2019	0	0	Hemmant	General Freight	245	0	0
7895	I368	Assemble turntable too stick plate then bolt skid Mack Super-Liner Day Cab - 6x4plate onto truck. Tension up all bolt tight. Star ...	R & M	08/27/2019	0	0	Hemmant	General Freight	1207.5	0	0
7916	I368	Bonnet Repair - Fibre glass repairs, sanding buck Mack Super-Liner Day Cab - 6x4cracks in bonnet and smoothing out, ready for fib ...	R & M	08/29/2019	0	0	Hemmant	General Freight	280	0	0
7921	I368	Help with new tail shaft bolts, pick up PTO valve and Mack Super-Liner Day Cab - 6x4shocks from Gibbs, hood clips, tightening all ...	R & M	08/28/2019	0	0	Hemmant	General Freight	280	0	0
7931	I368	Drain and remove adblue tank. Start wiring rear Mack Super-Liner Day Cab - 6x4lights - sanding for fibreglass repairs to bonnet a ... - Help Morgan set up tail light, had a problem with the break lights couldnt figure it out.	R & M	08/28/2019	0	0	Hemmant	General Freight	380	0	0
7942	I368	Mack Super-Liner Day Cab - 6x4- Drai ...	R & M	08/28/2019	0	0	Hemmant	General Freight	100	0	0
7959	I368	Swept around truck, clean down chrome, pulled down bumper to polish, took off adblue tank straps, Mack Super-Liner Day Cab - 6x4...	R & M	08/29/2019	0	0	Hemmant	General Freight	232.5	0	0
7991	I368	Install front bumper, swap out bent, bumper bracket. Mack Super-Liner Day Cab - 6x4Polish bumper. Drop off wrong adblue tank/ ord ... P/U paint brushes from Boltbiz, make up mix and	R & M	08/30/2019	0	0	Hemmant	General Freight	370	0	0
8004	I368	Mack Super-Liner Day Cab - 6x4fibreglass bonnet.	R & M	09/02/2019	0	0	Hemmant	General Freight	240	0	0
8028	I368	Mack Super-Liner Day Cab - 6x4Repairs/ Fibreglassing/ sanding.	R & M	09/03/2019	0	0	Hemmant	General Freight	180	0	0
8048	I368	Mack Super-Liner Day Cab - 6x4Bog, sanding and fibre glassing repairs.	R & M	09/04/2019	0	0	Hemmant	General Freight	315	0	0
8071	I368	Mack Super-Liner Day Cab - 6x4Installing Adblue tank and straps.	R & M	09/05/2019	0	0	Hemmant	General Freight	110	0	0
8072	I368	Mack Super-Liner Day Cab - 6x4Bog, sanding, bog, sanding, bog, sanding.	R & M	09/05/2019	0	0	Hemmant	General Freight	380	0	0
8089	I368	Mack Super-Liner Day Cab - 6x4Bog, sanding and sikaflex under bonnet.	R & M	09/06/2019	0	0	Hemmant	General Freight	340	0	0
8189	I368	Mack Super-Liner Day Cab - 6x4Put exhaust cover on Sanding, bog repair. Well RHS mirror bracket. P/U	R & M	09/11/2019	0	0	Hemmant	General Freight	82.5	0	0
8215	I368	Mack Super-Liner Day Cab - 6x4sanding discs from boltbiz.	R & M	09/12/2019	0	0	Hemmant	General Freight	380	0	0
8243	I368	Bog and sand light hosing, sikaflex. Bonnet/mudguard where they split. Install front cab Mack Super-Liner Day Cab - 6x4shocky's. ...	R & M	09/13/2019	0	0	Hemmant	General Freight	300	0	0
8280	I368	Drain fuel tank, remove tank locktight. Drive shaft Mack Super-Liner Day Cab - 6x4bolts tighten up. Sanding, bog repairs.	R & M	09/16/2019	0	0	Hemmant	General Freight	520	0	0
8328	I368	Bog Repairs, assemble steps on new fuel tank, paint Mack Super-Liner Day Cab - 6x4up. tank straps, put on traps and rubber.	R & M	09/17/2019	0	0	Hemmant	General Freight	380	0	0
8345	I368	Paint up tank straps, Install fuel tank, bog and sand. Mack Super-Liner Day Cab - 6x4Repairs on bonnett, sand back RHS wheel arch ...	R & M	09/18/2019	0	0	Hemmant	General Freight	440	0	0
8412	I368	Mack Super-Liner Day Cab - 6x4Tape up bonnet and cover truck ready for paint	R & M	09/20/2019	0	0	Hemmant	General Freight	60	0	0
8746	I368	Remove bonnet drive up top to warehouse get pallets drive back down to to workshop, fit bonnet on Mack Super-Liner Day Cab - 6x4p ...	R & M	10/04/2019	0	0	Hemmant	General Freight	190	0	0
8888	I368	Set up bonnet for paint, set up pallets and place Mack Super-Liner Day Cab - 6x4bonnet on top	R & M	10/14/2019	0	0	Hemmant	General Freight	75	0	0
9129	I368	Mack Super-Liner Day Cab - 6x4Cleaning and polishing grill, installing chrome.	R & M	10/22/2019	0	0	Hemmant	General Freight	70	0	0
9161	I368	Clean down head light and put them on right side Mack Super-Liner Day Cab - 6x4had no bracket.	R & M	10/22/2019	0	0	Hemmant	General Freight	20	0	0
9213	I368	Put Bonnety stays on bolt on bulldog polish wheels, Mack Super-Liner Day Cab - 6x4tips, tanks	R & M	10/24/2019	0	0	Hemmant	General Freight	140	0	0
9216	I368	Mack Super-Liner Day Cab - 6x4Polish and clean up tools	R & M	10/24/2019	0	0	Hemmant	General Freight	20	0	0
9257	I368	Unhook all batteries for load testing. Fit safety valve Mack Super-Liner Day Cab - 6x4on compressor charge pipe. Tidy up light wi ...	R & M	10/25/2019	0	0	Hemmant	General Freight	60	0	0

9266 I368	Mack Super-Liner Day Cab - R/R batteries, Repair air leak, Check boosters, Repair 6x4air leak in seat.	R & M	10/26/2019	0	0	Hemmant	General Freight	337.5	0	0
9278 I368	Mack Super-Liner Day Cab - Took off batteries, Top up on engine oil and gear box 6x4oil, Drain defs and refill them, change gearb ...	R & M	10/28/2019	0	0	Hemmant	General Freight	177.5	540.31	0
9297 I368	Mack Super-Liner Day Cab - 6x4Help align bonnet	R & M	10/28/2019	0	0	Hemmant	General Freight	37.5	0	0
9304 I368	Mack Super-Liner Day Cab - Clean up bonnet, fabricate light mount for main 6x4lights to sit in and replace if need be. Light moun ...	R & M	10/28/2019	0	0	Hemmant	General Freight	122.5	0	0
9334 I368	Mack Super-Liner Day Cab - Detailing starts, interior, Cab, windows, hood and 6x4bumper, Rear and chassis and 2 x back drive tyr ...	R & M	10/29/2019	0	0	Hemmant	General Freight	280	0	0
9390 I368	Mack Super-Liner Day Cab - Repair cabin fan, Repair light 6x4fittings.	R & M	10/31/2019	0	0	Hemmant	General Freight	205	0	0
9422 I368	Mack Super-Liner Day Cab - Cab fan not working, missing fuses, Replace air 6x4Continue truck fitout.	R & M	10/28/2019	0	0	Hemmant	General Freight	187.5	0	0
9436 I368	Mack Super-Liner Day Cab - Replace RHR Brake booster 6x4Replace RHR Brake booster	R & M	11/01/2019	0	0	Hemmant	General Freight	20	0	0
9450 I368	Mack Super-Liner Day Cab - Installing lights on exhaust/ got told wrong place by 6x4Ben after doing it.	R & M	11/01/2019	0	0	Hemmant	General Freight	43.75	0	0
9451 I368	Mack Super-Liner Day Cab - Helping Morgan with Brake Booster 6x4Helping Morgan with Brake Booster	R & M	11/01/2019	0	0	Hemmant	General Freight	35	0	0
9497 I368	Mack Super-Liner Day Cab - Install light, on the back of 368. Move truck from Workshop bay to tyre bay, had to 6x4clear room in ...	R & M	11/04/2019	0	0	Hemmant	General Freight	160	0	0
9920 I368	Mack Super-Liner Day Cab - Check over machine 6x4joiner.	R & M	11/25/2019	0	0	Hemmant	General Freight	65	0	0
9923 I368	Mack Super-Liner Day Cab - Check over truck plug in computer. Replace hose 6x4Put together duetz clips on rear of truck	R & M	11/25/2019	0	0	Hemmant	General Freight	40	50	0
9936 I368	Mack Super-Liner Day Cab - Test Drive, tank take trailer to snake pit. 6x4Adjust wipers	R & M	11/25/2019	0	0	Hemmant	General Freight	56.25	0	0
9938 I368	Mack Super-Liner Day Cab - 6x4Added new number plates	R & M	11/25/2019	0	0	Hemmant	General Freight	20	0	0
9963 I368	Mack Super-Liner Day Cab - Solder in number plate light, p/u P clamps for stock 6x4and truck, tidy up wiring with conjue and zip ...	R & M	11/26/2019	0	0	Hemmant	General Freight	100	50	0
9976 I368	Mack Super-Liner Day Cab - 6x4Fix Coolant leak put split pin in front D Shackle	R & M	11/26/2019	0	0	Hemmant	General Freight	20	25	0
10026 I368	Mack Super-Liner Day Cab - Repair electrical plug & fuse (use 7 pin male) 6x4Repair lights, Repair trailer plug	R & M	12/06/2019	0	0	Hemmant	General Freight	75	0	0
10180 I368	Mack Super-Liner Day Cab - 6x4Fit suzi coil fittings both red & blue hose	R & M	11/22/2019	0	0	Hemmant	General Freight	48.75	0	0
10187 I368	Mack Super-Liner Day Cab - 6x4Break Test	R & M	11/22/2019	0	0	Hemmant	General Freight	65	0	0
10729 I368	Mack Super-Liner Day Cab - 6x4Fit new seatbelt	R & M	12/20/2019	0	0	Hemmant	General Freight	227.5	262.02	0
10747 I368	Mack Super-Liner Day Cab - TRUCK ADBLUE- C Service -90,000KMS C Service Completed	PM	01/06/2020	0	0	Hemmant	General Freight	420	1002.1	0
10755 I368	Mack Super-Liner Day Cab - 6x4Actual 301711kms. Change all oils, & Calibra ...	R & M	01/06/2020	0	0	Hemmant	General Freight	75	25	0
10767 I368	Mack Super-Liner Day Cab - 6x4Pick up parts, Mount camera	R & M	01/06/2020	0	0	Hemmant	General Freight	75	25	0
10784 I368	Mack Super-Liner Day Cab - Fit seat belt LH side, Check king pins & wheel 6x4bearings ok, Test drive.	R & M	12/20/2020	0	0	Hemmant	General Freight	287.5	0	0
10784 I368	Mack Super-Liner Day Cab - 6x4Install 2 x rear sidelight, Broken off	R & M	12/24/2019	0	0	Hemmant	General Freight	40	18.8	0
10786 I368	Mack Super-Liner Day Cab - Take washer bottle hose off 325, Top up water more 6x4wiring for lights on air intake cover, Replace i ...	R & M	12/24/2019	0	0	Hemmant	General Freight	390	62.89	0
10797 I368	Mack Super-Liner Day Cab - 6x4Drill out holes and install over size signs	R & M	12/27/2019	0	0	Hemmant	General Freight	80	82.03	0
11052 I368	Mack Super-Liner Day Cab - 6x4Whiper blade issue	R & M	01/15/2020	0	0	Hemmant	General Freight	32.5	0	0
11475 I368	Mack Super-Liner Day Cab - 6x4Repair air leak	R & M	12/23/2019	0	0	Hemmant	General Freight	75	0	0
12101 I368	Mack Super-Liner Day Cab - Puncher repair done on POS 7 and valve 6x4replacement on trailer rim.	Tyre - S/S	02/03/2020	0	0	Hemmant	General Freight	35	0	0
13747 I368	Mack Super-Liner Day Cab - TRUCK ADBLUE- A Service -10,000KMS A Service Completed	PM	04/03/2020	0	0	Hemmant	General Freight	60	72.71	0
14129 I368	Mack Super-Liner Day Cab - 6x4Actual 313400kms.	R & M	04/23/2020	0	0	Hemmant	General Freight	80	0	0
14134 I368	Mack Super-Liner Day Cab - 6x4defects	R & M	04/23/2020	0	0	Hemmant	General Freight	65.090285	0	0
14177 I368	Mack Super-Liner Day Cab - Tighten mud guards 6x4Fix D/S rear light	R & M	04/23/2020	0	0	Hemmant	General Freight	37.5	0	0
14251 I368	Mack Super-Liner Day Cab - 6x4Check height control on passenger side	R & M	04/27/2020	0	0	Hemmant	General Freight	37.5	0	0
14251 I368	Mack Super-Liner Day Cab - P/u truck from snakepit. Fit up new height control 6x4valve too truck weld on broken arm to valve.Test ...	R & M	04/27/2020	0	0	Hemmant	General Freight	230	0	0
14258 I368	Mack Super-Liner Day Cab - 6x4Breakdown airbag issue	R & M	04/27/2020	0	0	Hemmant	General Freight	32.6625	0	0

Go to mack pick up parts remove and replace height											
14297	I368	Mack Super-Liner Day Cab - 6x4contol for air bags tested oknow	R & M	04/28/2020	0	0	Hemmant	General Freight	187.5	0	0
14300	I368	Mack Super-Liner Day Cab - 6x4mudguard and faults	R & M	04/28/2020	0	0	Hemmant	General Freight	40	25	0
14301	I368	Mack Super-Liner Day Cab - 6x4Pick up trailer from victoria point	R & M	04/28/2020	0	0	Hemmant	General Freight	225	0	0
14976	I368	Mack Super-Liner Day Cab - 6x4Repair lights	R & M	05/15/2020	0	0	Hemmant	General Freight	75	0	0
15058	I368	Mack Super-Liner Day Cab - 6x4Remove & repalce headlights, repair lights. Clean out engine break switch	R & M	05/19/2020	0	0	Hemmant	General Freight	150	0	0
15488	I368	Mack Super-Liner Day Cab - 6x4	R & M	06/15/2020	0	0	Hemmant	General Freight	31.5791645	25	0
15573	I368	Mack Super-Liner Day Cab - 6x4TRUCK ADBLUE & EGR- D Service - 12 Monthly	PM	06/12/2020	0	0	Hemmant	General Freight	170	87.76	0
15574	I368	Mack Super-Liner Day Cab - 6x4TRUCK ADBLUE- A Service-10,000KMS	PM	06/12/2020	0	0	Hemmant	General Freight	170	105.41	0
15575	I368	Mack Super-Liner Day Cab - 6x4TRUCK ADBLUE & EGR- D Service - 12 Monthly	PM	06/12/2020	0	0	Hemmant	General Freight	85	87.76	0
15660	I368	Mack Super-Liner Day Cab - 6x4Re install driver cam	R & M	06/30/2020	0	0	Hemmant	General Freight	42.5	25	0
18224	I368	Mack Super-Liner Day Cab - 6x4check / test engine break function A service	R & M	11/19/2020	0	0	Toowoomba	General Freight	85	0	0
18417	I368	Mack Super-Liner Day Cab - 6x4Klms - 371669 SWAP LEAD TRAILERS, HOOK UP ROAD TRAIN, HOOK UP TRIPLE,	PM	11/26/2020	0	0	Toowoomba	General Freight	170	0	0
19482	I368	Mack Super-Liner Day Cab - 6x4SPLIT ROAD TRAIN IN SHED B-svc	R & M	01/11/2021	0	0	Toowoomba	General Freight	85	0	0
21211	I368	Mack Super-Liner Day Cab - 6x4fuel filter water seperater bowl, RH c ... Breakdown at southbrook, charge pipe hose blown off, replace complete charge pipe with updated pipe	Scheduled	03/23/2021	0	0	Toowoomba	General Freight	467.5	794.98	0
21596	I368	Mack Super-Liner Day Cab - 6x4...	Wear/Tear	04/07/2021	0	0	Toowoomba	General Freight	170	0	0
21601	I368	Mack Super-Liner Day Cab - 6x4pickup bolts industrial, rhs steer tyre spin on rim ... Cut out and mount spotlight bars in bumper bar,	Scheduled	04/07/2021	0	0	Toowoomba	General Freight	340	0	0
21627	I368	Mack Super-Liner Day Cab - 6x4fit deutsch plugs to each end, run in conduit ...	Scheduled	04/08/2021	0	0	Toowoomba	General Freight	425	25	0
23909	I368	Mack Super-Liner Day Cab - 6x4Repair ad blue fault Truck A Service	Scheduled	07/08/2021	0	0	Toowoomba	General Freight	42.5	0	0
24409	I368	Mack Super-Liner Day Cab - 6x4svc by wtg at toowoomba 19.7.21 421535 Truck A Service SVC BY WTG 21.7.21 Invoice Date.....: 21/07/21	PM	07/28/2021	0	0	Hemmant	General Freight	0	0	0
24737	I368	Mack Super-Liner Day Cab - 6x4 UNIT REPORTED AS SLUGGISH TO START, TESTED BATTERIES AND FOUND 1 FAILED LOAD TEST 3 TO BE	PM	07/21/2021	0	0	Hemmant	General Freight	0	0	0
24806	I368	Mack Super-Liner Day Cab - 6x4OKAY, CHA ... Ticking noise reported from dash when AC put to recirculate. Removed panel and venting to access re	Wear/Tear	08/13/2021	0	0	Toowoomba	General Freight	85	482.32	0
25822	I368	Mack Super-Liner Day Cab - 6x4...		09/23/2021	0	0	Toowoomba	General Freight	85	0	0
25952	I368	Mack Super-Liner Day Cab - 6x4Carry out C service. Complete service, 53 litres of engine oil, 1 x 85114535 filer kit. Drain and replace oil and change	Scheduled	09/29/2021	0	0	Toowoomba	General Freight	425	0	0
25955	I368	Mack Super-Liner Day Cab - 6x4...	Scheduled	09/29/2021	0	0	Toowoomba	General Freight	127.5	0	0
26412	I368	Mack Super-Liner Day Cab - 6x4km 449805 Truck C Service	PM	09/24/2021	0	0	Hemmant	General Freight	425	0	0
27276	I368	Mack Super-Liner Day Cab - 6x4causing driver distraction. Disconnected camer ... Camera not working in cabin, repeatedly flashing red	Wear/Tear	11/22/2021	0	0	Toowoomba	General Freight	85	0	0
30840	I368	Mack Super-Liner Day Cab - 6x4repair door lock and straighten door skin diagnose coolant leak coming from L shaped hard	DA	04/26/2022	0	0	Hemmant	General Freight	480	0	0
31084	I368	Mack Super-Liner Day Cab - 6x4line on top of header tank	Wear/Tear	05/09/2022	0	0	Toowoomba	General Freight	42.5	0	0
32173	I368	Mack Super-Liner Day Cab - 6x4Replace front steering tires.	Wear/Tear	06/11/2022	0	0	Toowoomba	General Freight	637.5	0	0
32449	I368	Mack Super-Liner Day Cab - 6x4L/H headlight mounting loose & bulb blown	Wear/Tear	10/14/2022	0	0	Toowoomba	General Freight	42.5	25	0
32519	I368	Mack Super-Liner Day Cab - 6x4Truck B service	PM	06/08/2022	0	0	Toowoomba	General Freight	680	178.13	0
33224	I368	Mack Super-Liner Day Cab - 6x4KM Check	Scheduled	07/22/2022	0	0	Toowoomba	General Freight	0	0	0
35311	I368	Mack Super-Liner Day Cab - 6x4KM Check	Scheduled	09/19/2022	0	0	Toowoomba	General Freight	0	0	0
35360	I368	Mack Super-Liner Day Cab - 6x4KM Check	Scheduled	09/23/2022	0	0	Toowoomba	General Freight	0	0	0
35612	I368	Mack Super-Liner Day Cab - 6x4KM Check	Scheduled	10/05/2022	0	0	Toowoomba	General Freight	0	0	0
35827	I368	Mack Super-Liner Day Cab - 6x4KM Check	Scheduled	10/14/2022	0	0	Toowoomba	General Freight	0	0	0
36218	I368	Mack Super-Liner Day Cab - 6x4KM Check	Scheduled	10/28/2022	0	0	Hemmant	General Freight	0	0	0
36313	I368	Mack Super-Liner Day Cab - 6x4Low coolant	Wear/Tear	11/03/2022	0	0	Toowoomba	General Freight	42.5	7.7	0
36392	I368	Mack Super-Liner Day Cab - 6x4KM Check	Scheduled	11/07/2022	0	0	Toowoomba	General Freight	21.25	0	0
36744	I368	Mack Super-Liner Day Cab - 6x4KM check	Scheduled	11/11/2022	0	0	Toowoomba	General Freight	0	0	0
36807	I368	Mack Super-Liner Day Cab - 6x4c/o C Service - Truck - 568022 km 10540.4hours	PM	12/06/2022	0	0	Toowoomba	General Freight	1020	348.24	0
36818	I368	Mack Super-Liner Day Cab - 6x4Truck - C Service	PM	11/21/2022	0	0	Hemmant	General Freight	1020	0	0

36819 I368	Mack Super-Liner Day Cab - 6x4Truck - B service	PM	11/21/2022	0	0	Hemmant	General Freight	1020	7.7	0
36852 I368	Mack Super-Liner Day Cab - 6x4New turbo, New Manifold, Valve adjustment	Wear/Tear	11/23/2022	0	0	Toowoomba	General Freight	722.5	0	0
36857 I368	Mack Super-Liner Day Cab - 6x4New stacks, Turn table rebuild, Wash truck, Road test	Wear/Tear	07/07/2023	0	0	Toowoomba	General Freight	0	0	0
37543 I368	Mack Super-Liner Day Cab - 6x4low coolant light on	Unsched.	12/19/2022	0	0	Toowoomba	General Freight	382.5	0	0
37547 I368	Mack Super-Liner Day Cab - 6x4pick up parts from wtg and truck line	Workshop	12/19/2022	0	0	Toowoomba	General Freight	85	0	0
38146 I368	Mack Super-Liner Day Cab - 6x4brake down wyaga rest stop	DA	01/17/2023	0	0	Toowoomba	General Freight	382.5	0	0
38578 I368	Mack Super-Liner Day Cab - 6x4high warning in truck	PM	02/01/2023	0	0	Hemmant	General Freight	680	0	0
38741 I368	Mack Super-Liner Day Cab - 6x4Ass ...	Wear/Tear	02/09/2023	0	0	Toowoomba	General Freight	1827.5	0	0
38805 I368	Mack Super-Liner Day Cab - 6x4-broken driver side alloy step	Wear/Tear	02/09/2023	0	0	Hemmant	General Freight	170	0	0
39321 I368	Mack Super-Liner Day Cab - 6x4V-DAQ installation req'd	Scheduled	03/10/2023	0	0	Toowoomba	General Freight	42.5	0	0
39344 I368	Mack Super-Liner Day Cab - 6x4no blinkers	Unsched.	03/01/2023	0	0	Toowoomba	General Freight	127.5	0	0
39414 I368	Mack Super-Liner Day Cab - 6x4replace roof lights out x3 change fuel tank breather Boost cutting out under load.	Unsched.	03/04/2023	0	0	Toowoomba	General Freight	85	0	0
39565 I368	Mack Super-Liner Day Cab - 6x4[FR 2283 - 13/3/23]	DA	03/10/2023	0	0	Toowoomba	General Freight	722.5	0	0
39829 I368	Mack Super-Liner Day Cab - 6x4B Service - Truck + Reminder [FR 1649 - 4/4/23]	PM	07/11/2023	0	0	Hemmant	General Freight	340	0	0
39859 I368	Mack Super-Liner Day Cab - 6x4headlight out	Wear/Tear	03/23/2023	0	0	Toowoomba	General Freight	59.5	0	0
40033 I368	Mack Super-Liner Day Cab - 6x4cab ride high valve leaking	Unsched.	03/29/2023	0	0	Toowoomba	General Freight	85	0	0
40266 I368	Mack Super-Liner Day Cab - 6x4r/h window slo ...	DA	04/12/2023	0	0	Toowoomba	General Freight	170	0	0
40750 I368	Mack Super-Liner Day Cab - 6x4[FR 2286 - 3/5/23]	Wear/Tear	06/29/2023	0	0	Toowoomba	General Freight	0	0	0
40856 I368	Mack Super-Liner Day Cab - 6x4[FR 11098 - 8/5 ...	Wear/Tear	06/27/2023	0	0	Toowoomba	General Freight	85	0	0
40880 I368	Mack Super-Liner Day Cab - 6x4brakedown carpendale derate shut down spin steer tyres on rims	Unsched.	05/08/2023	0	0	Toowoomba	General Freight	765	0	0
40955 I368	Mack Super-Liner Day Cab - 6x4fit adblue sender	Scheduled	05/10/2023	0	0		General Freight	127.5	0	0
41152 I368	Mack Super-Liner Day Cab - 6x4truck only. Driver - brakes got really hot for no re ...	Unsched.	05/19/2023	0	0	Toowoomba	General Freight	1020	0	0
41245 I368	Mack Super-Liner Day Cab - 6x4[FR 2289 - 23 ...	MFD	05/23/2023	0	0	Toowoomba	General Freight	170	0	0
41267 I368	Mack Super-Liner Day Cab - 6x4finsh off putting truck back on road from service	MFD	05/24/2023	0	0	Toowoomba	General Freight	170	0	0
41283 I368	Mack Super-Liner Day Cab - 6x4[FR 2289 - 23/5/23]	Wear/Tear	06/27/2023	0	0	Toowoomba	General Freight	127.5	0	0
41331 I368	Mack Super-Liner Day Cab - 6x4rear brakes still locking on	M/Request	05/26/2023	0	0	Toowoomba	General Freight	297.5	0	0
41565 I368	Mack Super-Liner Day Cab - 6x4[FR 10402 - 6/6/23]	Wear/Tear	07/11/2023	0	0	Toowoomba	General Freight	0	0	0
41572 I368	Mack Super-Liner Day Cab - 6x4fit tablet	M/Request	06/05/2023	0	0	Toowoomba	General Freight	85	0	0
41710 I368	Mack Super-Liner Day Cab - 6x4air dumping out of safty vavle	Unsched.	06/09/2023	0	0	Toowoomba	General Freight	382.5	0	0
42109 I368	Mack Super-Liner Day Cab - 6x4replaced right hand exhaust elbow	Wear/Tear	06/22/2023	0	0	Toowoomba	General Freight	212.5	0	0
42144 I368	Mack Super-Liner Day Cab - 6x4take truck and ct209 to bris to pick up i492	M/Request	06/23/2023	0	0	Toowoomba	General Freight	595	0	0
42189 I368	Mack Super-Liner Day Cab - 6x4- broken upright muffler mounting bolt	DA	06/26/2023	0	0	Hemmant	General Freight	1062.5	0	0
42270 I368	Mack Super-Liner Day Cab - 6x4...	Scheduled	07/13/2023	0	0	Hemmant	General Freight	85	0	0
42749 I368	Mack Super-Liner Day Cab - 6x4poor aceleration only going 1200 RPM KM632440	Unsched.	07/11/2023	0	0	Hemmant	General Freight	807.5	0	0
42977 I368	Mack Super-Liner Day Cab - 6x4when applied. ....	Wear/Tear	10/25/2023	0	0	Hemmant	General Freight	340	0	0
43413 I368	Mack Super-Liner Day Cab - 6x4[FR 2294 - 31/7/23 + FR 22 ...	DA	08/18/2023	0	0	Hemmant	General Freight	212.5	0	0
43457 I368	Mack Super-Liner Day Cab - 6x4[FR 2296 - 1/ ...	Tyres - UN	08/02/2023	0	0	Brisbane Port Tyres	General Freight	340	0	0

		Breakdown - truck not starting.										
43458	I368	Mack Super-Liner Day Cab - 6x4[FR 2296 - 1/8/23]	Unsched.	08/24/2023	0	0	Hemmant	General Freight	170	0	0	
43464	I368	Mack Super-Liner Day Cab - 6x4Truck wont start.	Unsched.	08/02/2023	0	0	Hemmant	General Freight	680	644	0	
		Air leak - Coming from tank under cab. NO details of size of leak.										
43827	I368	Mack Super-Liner Day Cab - 6x4[FR 2297 - 11/8/23]	Wear/Tear	08/15/2023	0	0	Hemmant	General Freight	85	0	0	
		UHF radio - not working.										
43830	I368	Mack Super-Liner Day Cab - 6x4[FR 16704 - 11/8/23]	Wear/Tear	08/11/2023	0	0	Hemmant	General Freight	340	0	0	
		Steering wheel - Wheel is wrapped in tape to hold it together. This is not acceptable.										
43929	I368	Mack Super-Liner Day Cab - 6x4[FR 16705 - ...]	Wear/Tear	08/28/2023	0	0	Hemmant	General Freight	255	0	0	
		Windscreen wiper - R/H blade has detached from arm.										
44158	I368	Mack Super-Liner Day Cab - 6x4[FR 16706 - 24/8/23]	Unsched.	08/24/2023	0	0	Hemmant	General Freight	85	0	0	
		Trailer lights - R/H not working.										
44164	I368	Mack Super-Liner Day Cab - 6x4[FR 16707 - 25/8/23]	Unsched.	08/30/2023	0	0	Hemmant	General Freight	1232.5	0	0	
44196	I368	Mack Super-Liner Day Cab - 6x4B Service - Truck	PM	08/29/2023	0	0	Hemmant	General Freight	510	0	0	
		Air leak - Air line [Suzy?] to trailer leaking.										
44209	I368	Mack Super-Liner Day Cab - 6x4[FR 8433 - 25/8/23]	Wear/Tear	08/28/2023	0	0	Hemmant	General Freight	85	0	0	
		Starting issue - Breakdown at DGL Acacia Ridge - truck would not restart.										
44219	I368	Mack Super-Liner Day Cab - 6x4[FR ???? - 25/8/23]	Unsched.	08/28/2023	0	0	Hemmant	General Freight	1487.5	0	0	
		R/H window not working proper										
44268	I368	Mack Super-Liner Day Cab - 6x4plate light	Unsched.	08/29/2023	0	0	Hemmant	General Freight	297.5	0	0	
44269	I368	Mack Super-Liner Day Cab - 6x4Steering unis worn.	MFD	08/28/2023	0	0	Hemmant	General Freight	340	0	0	
		Door alarm - Always going off when opening door.										
44441	I368	Mack Super-Liner Day Cab - 6x4[FR 16709 - 4/9/23 + 16711 - 6/9/23]	Wear/Tear	09/07/2023	0	0	Hemmant	General Freight	255	0	0	
		Tyre req'd - Axle 2 L/H Outer - Tyre described as punctured.										
44444	I368	Mack Super-Liner Day Cab - 6x4[FR 16710 - 4/9/23]	Tyres - UN	09/04/2023	0	0	Brisbane Port Tyres	General Freight	85	0	0	
		Turntable - Breakdown at Arnott's Virginia - turntable handle had come off.										
44500	I368	Mack Super-Liner Day Cab - 6x4NO FR	Unsched.	09/06/2023	0	0	Hemmant	General Freight	255	0	0	
		Door alarm - alarm malfunction, horn going off. Re-occurrence of issue.										
44682	I368	Mack Super-Liner Day Cab - 6x4[FR 16713 - 12/9/23]	Wear/Tear	09/21/2023	0	0	Hemmant	General Freight	0	0	0	
		Trailer lead - trailer lights working intermittently.										
44683	I368	Mack Super-Liner Day Cab - 6x4Come on when brakes applied or truck put in g ...	DA	09/21/2023	0	0	Hemmant	General Freight	0	0	0	
		break down truck not starting and no clearance lights										
44951	I368	Mack Super-Liner Day Cab - 6x4on trailer 640768klm	Unsched.	09/26/2023	0	0	Hemmant	General Freight	510	0	0	
		Air leak - Pos'n of leak not specified. Lightning bolt displaying on dash.										
		[FR 16715 - 7/10/23].										
45237	I368	Mack Super-Liner Day Cab - 6x4	Wear/Tear	12/13/2023	0	0	Hemmant	General Freight	0	0	0	
		Mudguards - Damage - L/H & R/H conveyor belt mudguards have been hooked on the underside of										
45292	I368	Mack Super-Liner Day Cab - 6x4the tra ...	DA	10/10/2023	0	0	Hemmant	General Freight	1062.5	0	0	
45357	I368	Mack Super-Liner Day Cab - 6x4remount suzi lines and power leads	M/Request	10/16/2023	0	0	Hemmant	General Freight	1530	0	0	
45514	I368	Mack Super-Liner Day Cab - 6x4Horn not working	MFD	10/16/2023	0	0	Hemmant	General Freight	255	0	0	
45516	I368	Mack Super-Liner Day Cab - 6x4Over size sign worn	MFD	10/16/2023	0	0	Hemmant	General Freight	170	0	0	
45774	I368	Mack Super-Liner Day Cab - 6x4brake system problems	MFD	10/26/2023	0	0	Hemmant	General Freight	510	0	0	
		Starting issue - Breakdown - 68 warehouse area. next to old workshop. truck won't start.										
46099	I368	Mack Super-Liner Day Cab - 6x4NO FR sup ...	Unsched.	11/10/2023	0	0	Hemmant	General Freight	1284.916661	0	0	
		Warning message - 'Check Gearbox at next stop' message displaying.										
46219	I368	Mack Super-Liner Day Cab - 6x4[FR 18209 - 16/11/23]	Unsched.	12/13/2023	0	0	Hemmant	General Freight	0	0	0	
		Power Harness from Truck to Trailer.										
46483	I368	Mack Super-Liner Day Cab - 6x4NO FR supplied.	MFD	02/27/2024	0	0	Hemmant	General Freight	42.5	0	0	
46760	I368	Mack Super-Liner Day Cab - 6x4washed for sale inspection	Workshop	12/08/2023	0	0	Hemmant	General Freight	127.5	0	0	
46962	I368	Mack Super-Liner Day Cab - 6x4Air leak from airlines near turbo	R/Request	12/18/2023	0	0	Hemmant	General Freight	977.5	0	0	
46983	I368	Mack Super-Liner Day Cab - 6x4Picking up valve from Mack	R/Request	12/19/2023	0	0	Hemmant	General Freight	85	0	0	
		Pogo stick - Stick dislodged, has been hit by trailer because it sits too far back on chassis.										
47510	I368	Mack Super-Liner Day Cab - 6x4[FR ...	DA	01/15/2024	0	0	Hemmant	General Freight	340	0	0	



		Air lines - Damage - Breakdown at Narangba. Suzi lines ripped out.										
54791 I368	Mack Super-Liner Day Cab - 6x4NO FR Supplied.		Unsched.	10/30/2024	0	0	Hemmant	General Freight	510	0	0	
54901 I368	Mack Super-Liner Day Cab - 6x4Starting issue - Not starting, jump start		R/Request	11/04/2024	0	0	Hemmant	General Freight	85	0	0	
		Warning message - Lightning bolt displaying on dash. Indicator - R/H repeater indicator near door not working.										
55084 I368	Mack Super-Liner Day Cab - 6x4Truck would not turn over after being turned o ...		Wear/Tear	12/03/2024	0	0	Hemmant	General Freight	340	0	0	
		Indicator - R/H repeater indicator near door not working.										
55085 I368	Mack Super-Liner Day Cab - 6x4[FR 16724 - 12/11/24]		Wear/Tear	02/03/2025	0	0	Hemmant	General Freight	42.5	0	0	
		problem with trailer plug.										
55766 I368	Mack Super-Liner Day Cab - 6x4NO FR Supplied.		Unsched.	12/05/2024	0	0	Hemmant	General Freight	85	0	0	
		Air tank - L/H tank drain valve cord missing.										
55896 I368	Mack Super-Liner Day Cab - 6x4[FR 16729 - 11/12/24]		Wear/Tear	02/03/2025	0	0	Hemmant	General Freight	170	0	0	
		Window - R/H door window is cracked.										
55897 I368	Mack Super-Liner Day Cab - 6x4[FR 16730 - 11/12/24]		DA	02/03/2025	0	0	Hemmant	General Freight	42.5	0	0	
		Indicator - R/H wheel arch indicator working intermittently.										
56056 I368	Mack Super-Liner Day Cab - 6x4[FR 16731 - 18/12/24]		Wear/Tear	02/03/2025	0	0	Hemmant	General Freight	340	0	0	
		Electrical lead - Lead from truck to trailers damaged.										
56132 I368	Mack Super-Liner Day Cab - 6x4[FR 16733 - 20/12/24 + FR 17938 - 13/01/202 ...		DA	02/03/2025	0	0	Hemmant	General Freight	0	0	0	
		Air lines - Bracket holding the air lines needs to be fixed [? may need to be secured.]										
56664 I368	Mack Super-Liner Day Cab - 6x4[FR 16735 ...		Wear/Tear	01/29/2025	0	0	Hemmant	General Freight	85	0	0	
		A/D Service - Truck - Brisbane General Fleet [Updated										
56851 I368	Mack Super-Liner Day Cab - 6x431/7/24]		PM	02/03/2025	0	0	Hemmant	General Freight	170	0	0	
56855 I368	Mack Super-Liner Day Cab - 6x4noise from ac pully		MFD	01/29/2025	0	0	Hemmant	General Freight	425	0	0	

Sum = \$75,587.51 Sum = \$10,299.79 Sum = \$0.00