



1731 Main Street N.  
 Moose Jaw, SK S6J 1L6  
 Phone: 306-692-2371  
 www.southcountry.ca

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



JOHN DEERE

**SERVICE INVOICE**

Invoice To Account No: [REDACTED]	Deliver To: [REDACTED]	<b>Invoice Number:</b> [REDACTED]
[REDACTED]	[REDACTED]	Invoice Date: 9/16/2024
[REDACTED]	[REDACTED]	Location: [REDACTED]
Bus Phone:	Bus Phone:	Work Order Number: [REDACTED]
Prv Phone:	Prv Phone:	Payment Type: [REDACTED]
		Page: 1 of 8

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2012 JD 615P PICKUP PLATFORM		1H00615PPC0745390	1H00615PPC0745390	

**/HEADER615P F Internal**  
 COMPLAINT:  
 01 GREENLIGHT SERVICE INSPECTION HEADER

CORRECTION:

<b>Labor: \$265.50</b>	<b>Parts: \$0.00</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$0.00</b>	<b>Sub-Total: \$265.50</b>
------------------------	----------------------	-------------------------	---------------------	----------------------------

**Gen2- Internal**  
 COMPLAINT:  
 02 REPLACE 11 PICK UP FINGERS & STRAIGHTEN TWISTED ONES

CORRECTION:  
 -replaced 11 fingers straightened 5 of them



Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
A-1000378	Bolt W/Nut	11.00	0.63	0.63	\$6.93	N
A-1000379	Tine (H86248)	11.00	2.38	2.38	\$26.18	N
H216409	Concave Washer	11.00	9.67	9.67	\$106.37	N
H222306	BOLT	10.00	3.51	3.51	\$35.10	N
N10217	Lock Nut 1/4"	11.00	1.02	1.02	\$11.22	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	10.62	10.62	\$10.62	N

<b>Labor: \$177.00</b>	<b>Parts: \$185.80</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$10.62</b>	<b>Sub-Total: \$373.42</b>
------------------------	------------------------	-------------------------	----------------------	----------------------------

**Gen3- Internal**  
 COMPLAINT:  
 03 REPAIR FOR HEADER WON'T CALIBRATE

CORRECTION:



1731 Main Street N.  
 Moose Jaw, SK S6J 1L6  
 Phone: 306-692-2371  
[www.southcountry.ca](http://www.southcountry.ca)

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: [REDACTED]	Deliver To: [REDACTED]	<b>Invoice Number:</b> [REDACTED]
[REDACTED]	[REDACTED]	Invoice Date: 9/16/2024
[REDACTED]	[REDACTED]	Location: [REDACTED]
Bus Phone: [REDACTED]	Bus Phone: [REDACTED]	Work Order Number: [REDACTED]
Prv Phone: [REDACTED]	Prv Phone: [REDACTED]	Payment Type: [REDACTED]
		Page: 2 of 8

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2012 JD 615P PICKUP PLATFORM		1H00615PPC0745390	1H00615PPC0745390	

**Gen3- Internal**

-added air but arm snapped off and had to fix it then it calibrated

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
RE261356	SENSOR	1.00	279.80	279.80	\$279.80	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	5.31	5.31	\$5.31	N

**Labor: \$88.50      Parts: \$279.80      OL&M: \$0.00      Misc: \$5.31      Sub-Total: \$373.61**

**Gen4- Internal**

COMPLAINT:  
 04 REPLACE 1 WINDROW HOLD DOWNS - BROKEN

CORRECTION:  
 -replaced one hold down

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
14M7298	Flange Nut M8	1.00	1.45	1.45	\$1.45	N
AH231461	FINGER	1.00	43.79	43.79	\$43.79	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	2.66	2.66	\$2.66	N

**Labor: \$44.25      Parts: \$45.24      OL&M: \$0.00      Misc: \$2.66      Sub-Total: \$92.15**

**Gen5- Internal**

COMPLAINT:  
 05 REPAIR FOR WARNING LIGHT BRACKETS LOOSE

CORRECTION:  
 - tightened bracket



1731 Main Street N.  
 Moose Jaw, SK S6J 1L6  
 Phone: 306-692-2371  
 www.southcountry.ca

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: [REDACTED]	Deliver To: [REDACTED]	<b>Invoice Number:</b> [REDACTED]
[REDACTED]	[REDACTED]	Invoice Date: 9/16/2024
[REDACTED]	[REDACTED]	Location: [REDACTED]
Bus Phone:	Bus Phone:	Work Order Number: [REDACTED]
Prv Phone:	Prv Phone:	Payment Type: [REDACTED]
		Page: 3 of 8

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2012 JD 615P PICKUP PLATFORM		1H00615PPC0745390	1H00615PPC0745390	

**Gen5- Internal**

<b>Labor:</b> \$44.25	<b>Parts:</b> \$0.00	<b>OL&amp;M:</b> \$0.00	<b>Misc:</b> \$0.00	<b>Sub-Total:</b> \$44.25
-----------------------	----------------------	-------------------------	---------------------	---------------------------

**Gen6- Internal**

COMPLAINT:  
 06 REPAIR FOR LH WARNING LIGHT NOT WORKING

CORRECTION:  
 -replaced light



<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AXE52986	Lamp	1.00	78.40	78.40	\$78.40	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	10.62	10.62	\$10.62	N
<b>Labor:</b> \$177.00	<b>Parts:</b> \$78.40	<b>OL&amp;M:</b> \$0.00	<b>Misc:</b> \$10.62	<b>Sub-Total:</b> \$266.02		

**/140621615P F Internal**

COMPLAINT:  
 07 GREASE HEADER

CORRECTION:  
 -greased floater



<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
T460	POLYUREA GREASE	1.00	10.89	10.89	\$10.89	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>



1731 Main Street N.  
 Moose Jaw, SK S6J 1L6  
 Phone: 306-692-2371  
 www.southcountry.ca

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: [REDACTED]

Deliver To: [REDACTED]

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> [REDACTED] <b>Invoice Date:</b> 9/16/2024 <b>Location:</b> [REDACTED] <b>Work Order Number:</b> [REDACTED] <b>Payment Type:</b> [REDACTED]  <b>Page:</b> 4 of 8
--------------------------	--------------------------	--

<b>Make/Model:</b>	<b>Meter:</b>	<b>Serial Number:</b>	<b>Eq ID:</b>	<b>Fleet No:</b>
JOHN DEERE 2012 JD 615P PICKUP PLATFORM		1H00615PPC0745390	1H00615PPC0745390	

<b>/140621615P F Internal</b>						
SERVACCESS	SERVICE ACCESSORIES	1.00	3.50	3.50	\$3.50	N
<b>Labor: \$58.41</b>	<b>Parts: \$10.89</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$3.50</b>	<b>Sub-Total: \$72.80</b>		

**/120637615P Internal**  
 COMPLAINT:  
 08 TENSION FEED DRUM DRIVE CHAIN & LUBE

CORRECTION:  
 -tensioned belts to spec

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
TY26350	CHAIN LUBE	1.00	14.23	13.82	\$13.82	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	4.25	4.25	\$4.25	N
<b>Labor: \$70.80</b>	<b>Parts: \$13.82</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$4.25</b>	<b>Sub-Total: \$88.87</b>		

**/170052615P F Internal**  
 COMPLAINT:  
 09 ADJUST AIR BAG PRESSURE - ADD

CORRECTION:  
 -added air to spec

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	2.66	2.66	\$2.66	N
<b>Labor: \$44.25</b>	<b>Parts: \$0.00</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$2.66</b>	<b>Sub-Total: \$46.91</b>		

**/140561615P Internal**  
 COMPLAINT:



1731 Main Street N.  
 Moose Jaw, SK S6J 1L6  
 Phone: 306-692-2371  
 www.southcountry.ca

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: [REDACTED]	Deliver To: [REDACTED]	<b>Invoice Number:</b> [REDACTED]
[REDACTED]	[REDACTED]	Invoice Date: 9/16/2024
[REDACTED]	[REDACTED]	Location: [REDACTED]
[REDACTED]	[REDACTED]	Work Order Number: [REDACTED]
[REDACTED]	[REDACTED]	Payment Type: [REDACTED]
Prv Phone: [REDACTED]	Bus Phone: [REDACTED]	Page: 5 of 8
Prv Phone: [REDACTED]	Prv Phone: [REDACTED]	

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2012 JD 615P PICKUP PLATFORM		1H00615PPC0745390	1H00615PPC0745390	

**/140561615P Internal**  
 10 ADJUST ALL DRAPER TENSIONS

CORRECTION:  
 -adjusted to spec

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	7.97	7.97	\$7.97	N
<b>Labor: \$132.75</b>	<b>Parts: \$0.00</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$7.97</b>	<b>Sub-Total: \$140.72</b>		

**/150056615P F Internal**  
 COMPLAINT:  
 11 ADJUST BELT TRACKING - BOTH SETS GO HARD TO THE LEFT

CORRECTION:  
 -belt runs straight as possible with bad belt still on there

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	6.37	6.37	\$6.37	N
<b>Labor: \$106.20</b>	<b>Parts: \$0.00</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$6.37</b>	<b>Sub-Total: \$112.57</b>		

**/140288615P F Internal**  
 COMPLAINT:  
 12 REPLACE PICKUP BELT (PER BELT) - LH SIDE HAS 1/2" WORN OFF

\*\*\*\*\* DID NOT WANT DONE \*\*\*\*\*

CORRECTION:

<b>Labor: \$0.00</b>	<b>Parts: \$0.00</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$0.00</b>	<b>Sub-Total: \$0.00</b>		
----------------------	----------------------	-------------------------	---------------------	--------------------------	--	--



1731 Main Street N.  
 Moose Jaw, SK S6J 1L6  
 Phone: 306-692-2371  
 www.southcountry.ca

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: [REDACTED]	Deliver To: [REDACTED]	<b>Invoice Number:</b> [REDACTED]
[REDACTED]	[REDACTED]	Invoice Date: 9/16/2024
[REDACTED]	[REDACTED]	Location: [REDACTED]
Bus Phone:	Bus Phone:	Work Order Number: [REDACTED]
Prv Phone:	Prv Phone:	Payment Type: [REDACTED]
		Page: 6 of 8

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2012 JD 615P PICKUP PLATFORM		1H00615PPC0745390	1H00615PPC0745390	

**GEN13- Internal**

COMPLAINT:  
 13 REPLACE SMOOTH BELT - LH SIDE HAS 1/2" WORN OFF

\*\*\* DID NOT WANT DONE \*\*\*

CORRECTION:

Labor: \$0.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$0.00
---------------	---------------	--------------	--------------	-------------------

**/GLOPCLEAN615P Internal**

COMPLAINT:  
 14 GREENLIGHT/RECONDITIONING CLEANING CHECKLIST

still needs a wash

CORRECTION:

Labor: \$0.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$0.00
---------------	---------------	--------------	--------------	-------------------

**GEN15- Internal**

COMPLAINT:  
 15 REPAIR FOR ORING IN SINGLE POINT COUPLER POPPED OUT

CORRECTION:

-noticed when picking up the pick up that the one bottom middle fitting on the multi coupler was in bad condition  
 - replaced coupler

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AXE60986	Hydr. Quick Coupler 3/8"	1.00	231.77	231.77	\$231.77	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind



1731 Main Street N.  
 Moose Jaw, SK S6J 1L6  
 Phone: 306-692-2371  
 www.southcountry.ca

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: [REDACTED]	Deliver To: [REDACTED]	<b>Invoice Number:</b> [REDACTED]
[REDACTED]	[REDACTED]	Invoice Date: 9/16/2024
[REDACTED]	[REDACTED]	Location: [REDACTED]
[REDACTED]	[REDACTED]	Work Order Number: [REDACTED]
[REDACTED]	[REDACTED]	Payment Type: [REDACTED]
Bus Phone:	Bus Phone:	Page: 7 of 8
Prv Phone:	Prv Phone:	


Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2012 JD 615P PICKUP PLATFORM		1H00615PPC0745390	1H00615PPC0745390	

<b>GEN15- Internal</b>	SERVACCESS	SERVICE ACCESSORIES	1.00	5.31	5.31	\$5.31	N
<b>Labor: \$88.50</b>		<b>Parts: \$231.77</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$5.31</b>	<b>Sub-Total: \$325.58</b>		

**GEN16- Internal**  
 COMPLAINT:  
 16 REPAIR BROKEN MOUNT PIN FOR WINDSCREEN SUPPORT ON RH SIDE

CORRECTION:  
 -while calibrating the pick up, the right windrow arm snapped the pin that makes it work  
 -seized due to rust  
 -had to press the pin out of the tube  
 -cleaned everything up nice so pin moves easy in the tube  
 -welded the pin back to the pick up  
 -primed and painted  
 -then installed everything back together  
 -tested worked good and calibrated after

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
TY26268	BUFF PRIMER SPRAY	1.00	17.64	17.64	\$17.64	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
EF25	ENVIRO FEE	1.00	0.25	0.25	\$0.25	N





1731 Main Street N.  
 Moose Jaw, SK S6J 1L6  
 Phone: 306-692-2371  
 www.southcountry.ca

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: [REDACTED]	Deliver To: [REDACTED]	<b>Invoice Number:</b> [REDACTED]
[REDACTED]	[REDACTED]	Invoice Date: 9/16/2024
[REDACTED]	[REDACTED]	Location: [REDACTED]
Bus Phone: [REDACTED]	Bus Phone: [REDACTED]	Work Order Number: [REDACTED]
Prv Phone: [REDACTED]	Prv Phone: [REDACTED]	Payment Type: [REDACTED]
		Page: 8 of 8

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2012 JD 615P PICKUP PLATFORM		1H00615PPC0745390	1H00615PPC0745390	

<b>GEN16- Internal</b>								
SERVACCESS	SERVICE ACCESSORIES	1.00	27.93	27.93	\$27.93	N		
<b>Labor: \$465.22</b>	<b>Parts: \$17.64</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$28.18</b>	<b>Sub-Total: \$511.04</b>				

INVOICE CONTAINS \$0.41 DISCOUNT

**Customer PO No:** [REDACTED]  
**Tax Exempt No:** [REDACTED]  
**Advisor:** [REDACTED]

<b>Labor:</b>	\$1,762.63
<b>Parts:</b>	\$863.36
<b>OL&amp;M:</b>	\$0.00
<b>Misc:</b>	\$87.45
<b>Grand Total:</b>	<b>\$2,713.44</b>

\*\*\* DOCUMENT COPY \*\*\*

GST Registration No. [REDACTED]

G/L Entries	Br	Dpt	Acct	Sub	Ref	Description
00	00	160	1		147345	USED AG EQUIPMENT
01	40	382	1		783768	INTERNAL LABOR-AG
00	00	178	11		783768	WORK IN PROCESS PARTS -MJ
01	40	482	1		783768	COS INTERNAL LABOR-AG
01	30	366	2		783768	JD PARTS-COUNTER
00	00	166	1		783768	JD PARTS-MOOSE JAW
01	40	544	1		783768	SUPPLIES EXPENSE
01	30	372	2		783768	OTHER MFR PARTS-CNTR
00	00	172	1		783768	OTHER PARTS-MOOSE JAW
01	30	375	3		783768	PARTS SPECIAL HANDLING
01	30	466	2		783768	JD PARTS-COUNTER
01	30	472	2		783768	OTHER MFR PARTS-CNTR

**TERMS AND CONDITIONS**

Terms: Cash, Visa, Mastercard, AgriCard, John Deere Financial.

I hereby authorize the above repair work be done along with the use of necessary materials. You and your employees may operate the above machine for purposes of testing, inspection or delivery. I agree to pay cash for such repair parts and labour on delivery of machine(s) or on terms satisfactory to you, and until paid in full, any unpaid balance shall constitute a lien on this machinery. I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft or other causes beyond your control.

Received by: .....Date: .....