

		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	
30853	Clean/wash for demob and sale	28-Oct-25	28-Oct-25			
1	Clean/wash for demob and sale					
30817	Swap pos 2/3 tyres	23-Oct-25	23-Oct-25			
1	Swap pos 2/3 tyres					
30291	Repair exhaust leaks	23-Jul-25	23-Jul-25	12822		
1	Repair exhaust leaks					
30195	250 hour service	08-Jul-25	08-Jul-25	12732		
250h	r Service					
30042	Replace UHF aerial	18-Jun-25	18-Jun-25			
1	Replace UHF aerial					
29954	Replace u/s edges	03-Jun-25	03-Jun-25	12526		
1	Replace u/s edges					
29943	Cab rust repairs to stop water leaks	02-Jun-25	02-Jun-25	12516		
1	. Cab rust repairs to stop water leal	ks				
29942	Inflate pos 5 tyre and repair valve leak	02-Jun-25	02-Jun-25	12516		
1	Inflate pos 5 tyre and repair valve	leak				
29763	500 hr service	24-Apr-25	24-Apr-25			
500h	r Service					
29757	Replace worn yoke bushes and ball stud	17-Apr-25	17-Apr-25			
1	Replave worn yoke bushes and ba	ıll stud				
29736	Fuel pump leak	15-Apr-25	15-Apr-25			
1	Fuel pump leak					



				JIVIE GIAGO		
		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
29690	Replace GPS antenna	04-Apr-25	04-Apr-25			
	1 Replace GPS antenna					
29657	Repair arm rests	01-Apr-25	01-Apr-25	12368		
	1 Repair arm rests					
29628	Reshim circle	28-Mar-25	28-Mar-25			
	1 Reshim circle					
29603	Replace scarifiers	25-Mar-25	25-Mar-25	12313		
	1 Replace scarifiers					
29549	250 hour service	18-Mar-25	18-Mar-25	12273		
250	hr Service					
29530	Seal leak in roof	13-Mar-25	13-Mar-25	12238		
	1 Seal leak in roof					
29430	LH reverse light not working	25-Feb-25	25-Feb-25	12169		
	1 LH reverse light not working					
	2 Repair lights					
29396	Sideshift lockout fault	20-Feb-25	20-Feb-25			
	1 Sideshift lockout fault					
29252	Replace u/s blade slides/guides	23-Jan-25	23-Jan-25	12012		
	1 Replace u/s blade slides/guides					
29165	Tyre report	10-Jan-25	10-Jan-25	11948		
	1 Tyre report					
29154	Replace u/s edges	07-Jan-25	07-Jan-25	11947		
	1 Replace u/s edges					



		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
29149	2000 hour service	07-Jan-25	07-Jan-25	11945		
200	Ohr Service					
29095	Replace cracked hydraulic tube	13-Dec-24	13-Dec-24			
	1 Replace cracked hydraulic tube					
29032	Drop and clean out belly plates	29-Nov-24	29-Nov-24			
	1 Drop and clean out belly plates					
29010	Replace u/s arm rests	26-Nov-24	26-Nov-24	11853		
	1 Replace u/s arm rests					
29008	Inspect hydraulic oil leak	26-Nov-24	26-Nov-24	11852		
	1 Inspect hydraulic oil leak					
29005	Replace blown light globes	25-Nov-24	25-Nov-24			
	1 Replace blown light globes					
29004	Reseal leak around RH front wheel end	25-Nov-24	25-Nov-24			
	1 Reseal leak around RH front whee	el end				
28758	Reseal leaking transmission solenoid	17-Oct-24	17-Oct-24	11752		
	1 Reseal leaking transmission solen	oid				
28720	250 hour service	08-Oct-24	08-Oct-24	11722		
250	hr Service					
28478	Install new scarrifier keepers and shank	24-Jul-24	24-Jul-24	11484		
	1 Install new scarrifier keepers and	shank				
28465	500 hour service	18-Jul-24	18-Jul-24	11455		
500	hr Service					



		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading		
28369	Replace blade edges	20-Jun-24	20-Jun-24	11399		İ	
	1 Replace blade edges						
28264	Blade pivot repairs	14-May-24	14-May-24				
	1 Blade pivot repairs						
28108	250 hour service	02-Apr-24	02-Apr-24				
250	hr Service						
28105	Replace uhf	02-Apr-24	02-Apr-24				
	1 Replace uhf						
	2 Replace faulty light globes						
28099	Replace u/s batteries	28-Mar-24	28-Mar-24				
	1 Replace u/s batteries						
28061	Inflate tyres	21-Mar-24	21-Mar-24				
	1 Inflate tyres						
28027	Adjust blade slides	07-Mar-24	07-Mar-24				
	1 Adjust blade slides						
27947	Diagnose temperature sensor fault	14-Feb-24	14-Feb-24				
	1 Diagnose temp sesnor fault						
27915	Replace trans hose	06-Feb-24	06-Feb-24				
	1 Replace trans hose						
27879	1000 hour service	31-Jan-24	31-Jan-24				
100	Ohr Service						
27874	Replace 4 rear tyres	30-Jan-24	30-Jan-24				
	1 replace 4 rear tyres						



		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
27832	Replace u/s auto level switch	18-Jan-24	18-Jan-24			
	1 Replace u/s auto level switch					
27730	Service defects	12-Dec-23	12-Dec-23			
	1 Transmission oil leak					
	Reseal leaking hose (rh front)					
	Repair oil leak at high pressure pu	ımp				
•	4 RH front tandem wheel leak					
	5 Sump gasket leak					
	Replace u/s drawbar lift balls/cup	s/bearings				
	Replace rubbed hose on drawbar					
27690	Tyre report	29-Nov-23	29-Nov-23			
	1 Tyre report					
27679	Faulty Slope Sensor Harness	28-Nov-23	28-Nov-23			
	1 Faulty Slope Sensor Harness					
27658	10750 hr service	23-Nov-23	23-Nov-23			
250h	nr Service					
27654	Replace engine harness	23-Nov-23	23-Nov-23			
	Replace engine harness					
27620	Trouble Shoot GPS Fault	16-Nov-23	16-Nov-23			
	1 Trouble Shoot GPS Fault					
27574	Faulty Rotaion Sensor	06-Nov-23	06-Nov-23			
	1 Faulty Rotaion Sensor					



		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
	Replace Worn blade slides and adjust	30-Oct-23	30-Oct-23			
1	Replace Worn blade slides and ad	just				
27520	Repair A frame ball	24-Oct-23	24-Oct-23			
1	Repair A frame ball					
27507	Replace cutting edges	20-Oct-23	20-Oct-23			
1	Replace cutting edges					
27461	10500hr service defects	09-Oct-23	09-Oct-23	10445		
1	hose out cooler pack					
27441	500hr service	03-Oct-23	03-Oct-23	10445		
500hr	r Service					
27338	10250hr service Defects	11-Sep-23	11-Sep-23	10252		
1	Inspect minor leak near injector p	ump				Injector harness leaking
2	replace leaking hydralic filter drai	n valve				
3	Replace cooler pack door latch AS	3				
27332	Replace injectors	08-Sep-23	08-Sep-23			
1	Replace injectors					
27307	Supply 4 x 17.5 R25 XHA2	01-Sep-23	01-Sep-23			
1	Supply 4 x 17.5 R25 XHA2					
27305	Replace U/S engine ECM	01-Sep-23	01-Sep-23			
1	Replace U/S engine ECM					
27263	250hr service	23-Aug-23	23-Aug-23	10252		
250hr	r Service					



WO Date Created Scheduled Meter Reading Meter Reading Reading Notes 27253 Replace U/S fire extinguishers 21-Aug-23	
1 Replace U/S fire extinguishers 27205 Repair window washers 1 Repair window washers 27203 Replace worn RHS Rod end Artic cylinder bearing 1 Replace worn RHS Rod end steer cylinder bearing	
27205 Repair window washers 02-Aug-23 02-Aug-23 1 Repair window washers 27203 Replace worn RHS Rod end Artic cylinder bearing 1 Replace worn RHS Rod end steer cylinder bearing	
1 Repair window washers 27203 Replace worn RHS Rod end Artic 02-Aug-23 02-Aug-23 cylinder bearing 1 Replace worn RHS Rod end steer cylinder bearing	
27203 Replace worn RHS Rod end Artic cylinder bearing 02-Aug-23 02-Aug-23 1 Replace worn RHS Rod end steer cylinder bearing	
cylinder bearing 1 Replace worn RHS Rod end steer cylinder bearing	
27198 Complete Circle set & worn shoe 02-Aug-23 02-Aug-23 replacement	
1 Complete Circle set & worn shoe replacement	
27166 Complete 10,000hr DPF filter 26-Jul-23 26-Jul-23 service	
1 Complete 10,000hr DPF filter service	
27145 Replace U/S hydraulic hoses 21-Jul-23 21-Jul-23	
1 Replace U/S hydraulic hoses	
27113 Replace blown reverse light 14-Jul-23 14-Jul-23 Globes	
1 Replace blown reverse light Globes	
27102 Replace U/S A/C pressure switch 12-Jul-23 12-Jul-23 (high)	
1 Replace U/S A/C pressure switch (high)	
27100 Repair oil leak from hydraulic 12-Jul-23 12-Jul-23 control valve	
1 repair oil leak	



		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
27099	Diagnose & repair engine missfire	12-Jul-23	12-Jul-23			
	Diagnose & repair engine missfire	2				
29	Diagnose & repair engine missfire					
27027	Upgrade GCS900 to Earthworks System	28-Jun-23	28-Jun-23			
	Upgrade GCS900 to Earthworks S	ystem				
26969	Repair coolant leak, Replace worn hyd hoses and fuel hose	13-Jun-23	13-Jun-23	10030		
	1 Repair coolant leak					
	Replace worn hyd hose					
	Replace worn fuel hose					
26905	2000hr service	30-May-23	30-May-23			
2000	Ohr Service					
26787	GET	19-Apr-23	19-Apr-23			
	1 GET					
26761	Reshim blade	12-Apr-23	12-Apr-23			
	1 reshim blade					
26725	250hr service	27-Mar-23	27-Mar-23			
250	nr Service					
26703	Cutting edges	20-Mar-23	20-Mar-23			
	1 Cutting edges					
26628	Replace scarafier tips	02-Mar-23	02-Mar-23	9609		
	1 Scarafier tips					



		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
26615	Replace sensor bolts	23-Feb-23	23-Feb-23			
2	Replace sensor bolts					
26540	500hr service	01-Feb-23	01-Feb-23			
500h	r Service					
26398	Replace cutting edges	05-Dec-22	05-Dec-22	9254		
-	Cutting edges					
26349	250hr service	22-Nov-22	22-Nov-22	9190		
250h	r Service					
26342	Replace cutting edges	17-Nov-22	17-Nov-22	9177		
-	Cutting edges					
26257	Repair hyd oil leak	12-Oct-22	12-Oct-22			
-	L Oil leak					
26171	Replace cutting edges	12-Sep-22	12-Sep-22			
-	Replace cutting edges					
26147	Replace cutting edge	31-Aug-22	31-Aug-22	8956		
-	Cutting edges					
26146	1000hr service	30-Aug-22	30-Aug-22			
1000	hr Service					
26116	Repair rear work light	22-Aug-22	22-Aug-22	8916		
-	L Work light					
26115	Injector fault code	22-Aug-22	22-Aug-22	8916		
-	I Injector code					
26014	Replace grease nipples	14-Jul-22	14-Jul-22			
-	Replace grease nipples					



		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
26010	750hr service	13-Jul-22	13-Jul-22		8771	
2501	nr Service					
25970	Replace drive tyres	28-Jun-22	28-Jun-22			
	Replace drive tyres					
25966	Replace scarafiers	24-Jun-22	24-Jun-22			
	Replace worn scarafiers					
25958	Repair blade slides	23-Jun-22	23-Jun-22			
	1 Repair blade slides					
25841	Repair parking brake	19-May-22	19-May-22			
	1 Repair parking brake					
25838	Install GPS mast	19-May-22	19-May-22			
	1 Install GPS mast					
25826	Replace cutting edges	13-May-22	13-May-22			
	1 Cutting edges					
25825	Worn fan mounts	13-May-22	13-May-22	8941		
	1 Worn fan mounts					
25806	Repair kingpin movement	09-May-22	09-May-22	8491		
	Repair kingpin movement					
25805	Repair centre shift movement	09-May-22	09-May-22	8491		
	Repair centre shift movement					
25804	Repair oil leaks at control valve	09-May-22	09-May-22	8491		
	Repair oil leaks at control valve					
25802	Transmission oil leaks	09-May-22	09-May-22	8491		
	1 Transmission oil leaks					



		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
25801	Engine oil leak	09-May-22	09-May-22	8491		
	1 Engine oil leak					
25796	Repair circle adjustment	09-May-22	09-May-22			
	1 Repair circle adjustment					
25769	Blade slides	02-May-22	02-May-22			
	1 Blades slides					
25768	Hyd oil leak at valve block	02-May-22	02-May-22			
	1 Hyd oil leak					
25760	DPF fan fault	27-Apr-22	27-Apr-22			
	1 DPF fan fault					
25759	500hr service	26-Apr-22	26-Apr-22		8485	
500h	nr Service					
25715	Replace cutting edges	12-Apr-22	12-Apr-22			
	1 Cutting edges					
25711	Inspect greasing points at front rhs	11-Apr-22	11-Apr-22			
	Inspect greasing points at front rh	IS				
25682	GPS mast	04-Apr-22	04-Apr-22			
	1 Remove gps mast					
25636	Annual pressure vessel inspection	22-Mar-22	22-Mar-22			
12 N	Nonthly pressure vessel inspection					
25603	103 Inspection	11-Mar-22	11-Mar-22	8410		
	1 103 Inspection					



		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
25546	Tyre inspectiopn	21-Feb-22	21-Feb-22	3894		
	1 Tyre inspection					
25514	Repair mirror	10-Feb-22	10-Feb-22			
	1 Repair mirror					
25461	250hr service	24-Jan-22	24-Jan-22		8320	
2501	nr Service					
25399	Repair engine overheating	17-Dec-21	17-Dec-21			
	1 Engine overheating					
25381	Replace worn cutting edges	08-Dec-21	08-Dec-21			
	1 Replace worn cutting edges					
25304	Blocked DPF	05-Nov-21	05-Nov-21			
	1 Blocked DPF					
25276	Change over rippers	28-Oct-21	28-Oct-21			
	1 Change over rippers					
25271	Trans shift - fault	26-Oct-21	26-Oct-21	8049		
	1 Trans shift - fault					
25183	Cutting edges	17-Sep-21	17-Sep-21	7939		
	1 Cutting edges					
25176	2000hr service	14-Sep-21	14-Sep-21		7976	
2000	Ohr Service					
25033	Repair flashing light	16-Jul-21	16-Jul-21	7804		
	1 Repair flashing light					
25018	ARD fault	07-Jul-21	07-Jul-21	7779		
	1 ARD fault					



		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading			Notes	Notes	Notes
25017	Hyd oil leak at control valve	07-Jul-21	07-Jul-21	7781						
	1 Hyd oil leak at control valve									
25004	RH king pin not taking grease	25-Jun-21	25-Jun-21	7757						
	1 RH king pin not taking grease									
25003	Repair flat tyre pos 5	24-Jun-21	24-Jun-21	7757						
	1 Repair flat tyre pos 5									
25002	Repair rear wiper motor	24-Jun-21	24-Jun-21	7757						
	1 Repair rear wiper motor									
24989	250hr service	18-Jun-21	18-Jun-21		7781	1				
2501	hr Service									
24954	Replace worn edges	31-May-21	31-May-21							
	1 Replace worn edges									
24944	Change over rippers	27-May-21	27-May-21	7667						
	1 Change over rippers									
24913	Replace ripper retainers	17-May-21	17-May-21							
	1 Replace ripper retainers									
24861	Repair arm rests	04-May-21	04-May-21	7553		Ì				
	1 Repair arm rests									
24843	Replace cutting edges	28-Apr-21	28-Apr-21			ĺ				
	1 Replace cutting edges									
24841	500hr service	27-Apr-21	27-Apr-21	7500	7613	3				
5001	hr Service									
24839	Replace blade slides	27-Apr-21	27-Apr-21	7518						
	1 Replace blade slides									



		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
24775	Replace cutting edges	09-Apr-21	09-Apr-21			
-	Replace cutting edges					
24555	Fire extinguisher pressure test	21-Jan-21	21-Jan-21			
:	Fire extinguisher pressure test					
24546	Replace failed engine cooling fan - DPF	19-Jan-21	19-Jan-21			
:	Replace failed engine cooling fan					
24535	Replace blown steering hose	14-Jan-21	14-Jan-21			
:	Replace blown steering hose					
24494	103 inspection	07-Jan-21	07-Jan-21	7318		
:	1 103 inspection					
24429	12 Monthly pressure vessel inspection	10-Dec-20	10-Dec-20			
12 N	1onthly pressure vessel inspection					
24405	Replace cutting edges	01-Dec-20	01-Dec-20	7299		
-	Replace cutting edges					
24369	Replace blown hose	19-Nov-20	19-Nov-20	7269		
-	Replace blown hose					
24246	250Hr Service	16-Oct-20	16-Oct-20	7258	7258	
250h	nr Service					
24195	Swap rippers and scrafiers	01-Oct-20	01-Oct-20	7161		
:	1 Swap rippers and scrafiers					
24165	Adjust blade slides	23-Sep-20	23-Sep-20	7106		
	Adjust blade slides					



		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
24164	Tyre report	23-Sep-20	23-Sep-20	7106		
	1 Tyre report					
24162	Repair fault front window washer	22-Sep-20	22-Sep-20	7106		
	1 Repair fault front window washer					
24161	103 inspection	22-Sep-20	22-Sep-20	7106		
	1 103 inspection					
23969	Supply & fit new cutting edges - Westrac	06-Aug-20	06-Aug-20	6959		
	1 Supply & fit new cutting edges - W	Vestrac				
23924	Locate hyd leak & order hose	27-Jul-20	27-Jul-20	6959	6956	
	1 Locate hyd leak & order hose					28/07 Leak from front valve block to tank - parts ordered. Replaced leaking hose.
23923	1000hr Service	27-Jul-20	27-Jul-20	6959		
1000	Ohr Service					
23901	Replace worn artic bearings on front frame	22-Jul-20	22-Jul-20	6888		
	1 Replace worn artic bearings on fro	ont frame				Checked over machine - found artic bushes worn. 27/07 Replace RHS artic cylinder bearing
23806	Fit fire extinguisher, trans & hyd repairs	03-Jul-20	03-Jul-20	6888		
	1 Fit fire extinguisher					
	2 Check trans fault - filter in wrong	way				
	Repair oil leak at hyd valve on god	seneck				
23792	Fit 4x tyres to POS3,4,5&6	02-Jul-20	02-Jul-20	6888		
	1 Fit 4x tyres to POS3,4,5&6					



		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
23788	Check over & start machine	01-Jul-20	01-Jul-20	6888		
	1 Check over & start machine					
23733	Supply GET	23-Jun-20	23-Jun-20	6888		
	1 Supply GET					
23460	Repair isolator mount & adjust blade slides	13-May-20	13-May-20	6887		
	1 Repair isolator mount & adjust bl	ade slides				
23459	Removed & install DPF coil & plug	13-May-20	13-May-20	6887		
	1 Removed & install DPF coil & plug	S				
23456	Re-seal trans filter housing	14-May-20	14-May-20	6887		
	1 Re-seal trans filter housing					18/05 Continue re-seal of trans filter housing - pulled off housing to locate leak and repair. 19/05 Re-seal trans filter housing, fitted housing to machine - filled with oil & tested
	2 Machine inspection					
23438	Replace worn blade guides - bottom	12-May-20	12-May-20	6887		
	1 Replace worn blade guides - botte	om				
23413	Inflate POS 3 tyre	06-May-20	06-May-20	6878		
	1 Inflate POS 3 tyre					
23395	Repair DPF Fault	05-May-20	05-May-20	6859		
	1 Repair DPF Fault					Tested DPF system fault - unable to ignite.
23387	Diagnose & repair failed ARD ignitor & high DPF soot level	01-May-20	01-May-20	6845		
	1 Diagnose & repair failed ARD igni	tor & high DPF soc	ot level			



		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
23283	Replace cutting edges	14-Apr-20	14-Apr-20	6711		
1	Replace cutting edges					
23279	250hr Service	09-Apr-20	09-Apr-20	6711	6733	
250h	r Service					
23096	Transmission filter housing leaking	28-Feb-20	28-Feb-20	6576		
1	Replace filter housing					28/2 Filter housing leaking Canister found to be distorted and the threads stretched
23095	Replace hydraulic pump shuttle valve	28-Feb-20	28-Feb-20	6576		
1	. Replace shuttle valve					28/2 Found shuttle valve leaking - parts ordered
23013	Feb maintenance work order	01-Feb-20	01-Feb-20	6505		
1	Tyres					6/02 Pump up POS 3 tyre - possible leak
22977	500hr Service	28-Jan-20	28-Jan-20	6414	6509	
500h	r Service					
22950	Jan maintenance work order	06-Jan-20	06-Jan-20	6376		
1	Body work					10/01 Carry out circle set & replace top wear plates 11/01 Adjust blade slides 14/01 Tidy hoses - bolt to a-frame
2	GET					7/1 Replace cutting edges



		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
22875	Dec maintenance work order	01-Dec-19	01-Dec-19	6250		
	1 Body Work					29/11 Replace un-serviceable door cables 13/12 Replace wear strips and shims in circle
	2 Electrical					3/12 Replace AM/FM Radio 3/12 Replace EGR Differential pressure sensor 13/12 Replace Worklight
	3 Engine					2/12 EGR differential pressure sensor
	4 Service & Maintenance					2/12 Top up trans oil, repair oil weap on trans filter housing
	5 GET					5/12 Replace cutting edge
	6 Transmission					
22868	Adjust shims in blade lift & sideshift	02-Dec-19	14-Dec-19	6170		
	1 Frame & Body					14/11 Adjust blade lift and sideshift shims
22867	Remove & Clean EGR sensor	02-Dec-19	14-Nov-19	6170		
	1 Repair EGR Sensor					14/11 Remove and clean EGR sensor
22847	250hr Service	29-Nov-19	29-Nov-19	6249		
	1 250hr Service					
22755	Cab door latch sticking	01-Nov-19	01-Nov-19	6101		
	1 Replace cab door latch release wii	re				
22741	Adjust circle shims and lift rams for final trim	25-Oct-19	24-Oct-19	6087		
	1 Adjust circle shims and lift rams fo	or final trim				24/10 Adjust for final trim works 29/10 Tighten circle, adjust blade slides, remove circle drive clutch shims.
22736	Complete 103 inspection	23-Oct-19	15-Oct-19	6012		
	1 Complete 103 inspection					
2273	6 Complete inspection					



		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes			
22712	Repair Low EGR differential pressure fault	02-Oct-19	02-Oct-19	5947					
	1 Fault code E1093(1)					2/10 Inspect fault code E1093(1) low EGR diff pressure, inspect wiring harnes Remove EGR sensor & clean - Test OK			
22710	Repair steering fault	08-Oct-19	08-Oct-19	5992					
	1 Diagnose and repair steering fault					8/10 Inspect steering fault found plug in steering module corroded - replaced steering module with spare unit - Tested OK			
22705	Repair faulty GPS receiver cable	15-Oct-19	15-Oct-19						
	1 Repair faulty GPS receiver cable								
22696	Additional work for MDG15 Inspection	09-Oct-19	09-Oct-19	5777					
	1 Carry out additional works per Ca	Res MDG15 Ins	pection						
22679	2000hr service	02-Oct-19	02-Oct-19	5943	5994				
	1 2000hr service								
22662	Sep Maintenance	01-Sep-19	01-Sep-19						
	1 Engine work					8/9 Repair leaking scavenger hose			
	2 Frame & Body					10/9 Replace wheel bolt, retorque all			
	3 Tyres					11/9 Inflate pos 5 tyre			
22645	Heavy plant tyre inspections - Marathon	18-Sep-19	18-Sep-19	5851					
	1 Tyres					17/9 escort Marathon to grader, change o-ring			
22642	Install Product Link	17-Sep-19	17-Sep-19	5851					
	1 GPS					17/9 Install product link			
22599	Sept Maintenance work order	01-Sep-19	01-Sep-19						
	1 GPS work					3/9 Upgrade SNR Radio - 2.4Ghz. 10/9 Inspect GPS connection issue - Check plugs for power			
	2 Final Drives, Transmission, Tander	ns				4/9 Investigate noise in Tandems, Identified as a dry bush			



		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
3	Frame & Body repairs					6/9 Adjust cab door latches, Free up LHR engine bay door 11/9 Replace missing wheel bolt 17/9 fit new wheel bolt 23/9 Replace broken circle pad cove bolt.
4	Service & Maintenance					17/9 pick up parts and sort
5	Tyres					17/9 POS 5 Tyre O-Ring leaking 5871 hrs
22591	Decals & Unit #'s	20-Aug-19	20-Aug-19			
1	Decals & Unit #'s					
22590	Replace GPS items	30-Aug-19	30-Aug-19			
1	Replace GPS items					30/8 Replace faulty slope sensor harness, replace faulty rachet handle - GN300