



**DIESEL ENGINES**  
New, Reconditioned & Replacement Parts

**Tax Invoice**  
**6216144**

Sold To:

[Redacted Customer Name]  
[Redacted Address]  
[Redacted City]  
[Redacted State]

Job Address:

[Redacted Job Address]  
[Redacted City]  
[Redacted State]  
[Redacted Postcode]

Attention: [Redacted Name]

**Job Description:**  
Remove and refit engine

Date	Customer Code	Your Reference	ABN Number	Job Code	Page
2/04/2025	[Redacted]	TBA	[Redacted]	27250	Page 1 of 2

Code	Description	Quantity	Unit	Price	Disc%	Net Each	Total Value
	Removal of engine LABOUR SUPPLIED 2 x LKD Technicians	24.00		145.00		145.00	3,480.00
TCD3.6L04	Swap/ fit required engine parts NEW DEUTZ TCD3.6L04 ENGINE Serials.. 13035073	1.00	EACH	19,188.00		19,188.00	19,188.00
	ENGINE OIL 20 LITRE DQC IV-10LA 10W40	1.00	EACH	259.73		259.73	259.73
	COOLANT 5 LITRE RED	6.00	EACH	128.18		128.18	769.10
	MISC PARTS		EACH	0.00		0.00	0.00
	LABOUR SUPPLIED Refit engine and test	10.00		145.00		145.00	1,450.00
	LABOUR SUPPLIED 2 x LK Diesel Technicians	32.00		145.00		145.00	4,640.00

Please note  
Quotation is an estimate only

52 Woodlands Drive Braeside Victoria 3195 Telephone 03 9588 6900 Facsimile 03 9588 6999 Email info@lkdiesel.com.au www.lkdiesel.com.au  
ACN 004 826 484 ABN 72 004 826 484



Authorised Dealers





**DIESEL ENGINES**  
New, Reconditioned & Replacement Parts

**Tax Invoice**  
**6216144**

Sold To:

[Redacted Customer Name]  
[Redacted Address]  
[Redacted City]  
[Redacted State]

Job Address:

[Redacted Job Address]  
[Redacted City]  
[Redacted State]  
Attention: [Redacted Name]

**Job Description:**

Remove and refit engine

Date	Customer Code	Your Reference	ABN Number	Job Code	Page
2/04/2025	[Redacted]	TBA	[Redacted]	27250	Page 2 of 2

Code	Description	Quantity	Unit	Price	Disc%	Net Each	Total Value
------	-------------	----------	------	-------	-------	----------	-------------

Parts and labour to retro fit up new engine is an estimate only  
Engines will need to be side by side to determine works required

Quotation time for removal and refit are also an estimate only  
Based on 2 x LKD Technicians

Customer required to supply lifting aid and machine driver to assist removal  
and fitment

\*\*\* This is the only TCD 3.6 in stock and is not the correct spec engine  
We may be able to utilise our stock engine as is but still will have to change bellhousing, Engine mounts, Wiring loom for computer, All pulleys - There is also a  
possibility we will have to change water pump and manifolds.  
We will only know when the two engines are side by side

Any extra parts we have to order will be extra charge - We will advise prior

**Tax Invoice**                      **6216144**

**Payment Terms: Cash on Delivery**

[Redacted Bank Details]

Total Net Value:                      29,786.83  
Tax:    2,978.68  
**Total Value:                              32,765.51**

52 Woodlands Drive Braeside Victoria 3195 Telephone 03 9588 6900 Facsimile 03 9588 6999 Email info@lkdiesel.com.au www.lkdiesel.com.au  
ACN 004 826 484    ABN 72 004 826 484



Authorised Dealers

