



WC11 - WC11-HINO WATER CART

Location: ELDER ST SOUTH (AREA 2), HEATHERTON

Serial#: JHDFM1JLPXXX10911

Hour/Odometer: 3387.1

Next Service: 3850

Maintenance History

Type	Date	Comments
REPAIRS	30/05/2025	BOLTS
REPAIRS	30/05/2025	CAMLOCK FITTINGS
REPAIRS	21/05/2025	UHF & WATER TEMP FIXES
REPAIRS	24/04/2025	4 NEW TYRES
SERVICE	27/03/2025	WC11 SERVICE KIT
REPAIRS	21/11/2024	Air leak from switch panel for the sprays (driver control switches) Topped up half a litre Intermittent squealing of belt when running aircon. Bolt snapped on mounting bracket for the air intake pipe Need tire pressure checked Out of date June 2024
REPAIRS	7/11/2024	Overheating engine issue
REPAIRS	8/10/2024	2 x batteries
DAMAGES	3/10/2024	Damaged tyre
REPAIRS	20/09/2024	Water connection white hose reel big leak Microphone button ineffective, Uhf model GME TX4500
RECORD 360	4/09/2024	Record 360
REPAIRS	30/05/2024	Flat batterys
OTHER	6/05/2024	Water bill
REPAIRS	2/04/2024	Batterys on truck needs jumpstarting. Jumpstart truck. Let truck run for 20 minutes
REPAIRS	20/09/2023	Flat batteries
REPAIRS	9/08/2023	Flat tyre
REPAIRS	4/08/2023	Wipers torn need replacing No water permit on truck

EXTERNAL REPAIR	21/07/2023	Side wall cut on tyre
EXTERNAL REPAIR	14/07/2023	Keys locked in cab by operators
REGISTRATION	15/04/2022	vehicle registration fees
PARTS	5/04/2022	stainless steel hex cap
PARTS	24/03/2022	hydraulic oil x 2
PARTS	24/01/2022	easy seal clamp & loctite anti-seize
SERVICE/REPAIR	19/01/2022	REMOVE GPS UNIT REMOVE SOUTH EAST WATER GPS UNIT
SERVICE/REPAIR	16/12/2021	16/12/21 @2461 hrs gauges not working
SERVICE/REPAIR	26/10/2021	Wc11 Warwick Air loss Dash lights n/w
EXTERNAL SERVICE	22/09/2021	Engine overheating, track rods bushings u/s Sublet to Prestige Hino
EXTERNAL SERVICE	19/11/2020	tyre replacement and call out fee
PARTS	17/11/2020	parts for service
EXTERNAL SERVICE	10/11/2020	blocked radiator @ 490,621 kms
PARTS	16/09/2020	parts for water cart
SERVICE/REPAIR	19/02/2019	19.2.19-BATTERIES NOT WORKING SOURCE BATTERIES FROM R&J TRAVEL TO SCORESBY AND REPLACE BATTERIES LABOUR \$297.50
SERVICE/REPAIR	9/07/2018	WC11 at 1748hrs. S/Fit radiator No.3, suplied by F-gate radiators @ no charge. Fill w/ water, not coolant. Roadtest - back to w/shop then drain water out of cooling system. 10/7 at 1749hrs. Ran water through radiator (flush) + Roadtest. back to site + repeat process.
SERVICE/REPAIR	4/06/2018	WC11 at 1745 4/6/18 - Flush cooling system & fill with water, Test drive & found OK. Drain & flush system. WC11 at 1746 5/6/18 - Again, Refill with Hino coolant, retest drive & found OK. Parts - Hino Coolant 20lts genuine coolant, \$150.
SERVICE/REPAIR	23/02/2018	WC11 at 1737. Road test, still overheating radiator, no flow (old), remove radiator, found top tank blocked. Removed radiator, fit new radiator (2nd time) did not add coolant - flushed system totally - test run - all O.K. Radiator 23/2/18 - \$663.64
SERVICE/REPAIR	9/01/2018	WC11 at 1736. fault overheating, travel to site, inspect and transport truck back to dansu ct. source parts replace radiator, radiator cap, sender unit, fanbelt, ac belt, viscous cupling,and new water pump, genuine hino coolant. Road test, still runs hot, maybe fuel pump timing. Radiator 14/12/17 - \$663.64
SERVICE/REPAIR	14/12/2017	WC11 at 1724hrs. Engine Overheating. Remove, wash Radiator + coolant, road test Found lower tank split + still overheating Remove radiator for repair/replacement. Pick up all parts (hino) , travel to george st, Fit new radiator to intercooler Repair all broken bolts threads Fit new hoses/clamps etc.. add coolant Test drive - All OK.
SERVICE/REPAIR	14/08/2017	WC11 - 14.8.17 - Check general condition and repair as needed. Fit new air cleaner filters, fit rear safety signs. Hydraulic supply line, A/C belt. Remove and clean. Refit dribble bar, grease all points. Remove unused work lights + pressure washer check on levels. Instrement cluster to be fitted on arrivals tested.
SERVICE/REPAIR	23/06/2016	WC11 air valves and adaptors

SERVICE/REPAIR	13/07/2015	13/7 repairs to compressor piping,replace 1x pipe genuine 14/7 repair fabricate 2nd pipe at enzed, return to site, fit and test all ok. pressure wash entire truck, check over and transport to Warragul. 21/7 cut and shut water pressure pipe at rear of truck, source steel pipe from Warragul steel supplies, back to site and weld in pipe.
SERVICE/REPAIR	26/02/2015	WC11@1491hrs, adjust tyre pressures. check for air leak in air system, found air compressor high pressure pipes rusted out. source new pipe and washers, one pipe not available, remove for repair. Parts Prestige Hino \$147.02.
SERVICE/REPAIR	9/02/2015	WC11@1484hrs source 2x new batteries(N120P) to old dandy rd. site, fit new batteries and terminals x2,repair link cable.
SERVICE/REPAIR	7/01/2015	WC11@1476HRS CAB RELEASE ASSY SEIZED (LACK OF USE)REPAIR AS REQUIRED. RELABEL ALL WATER CONTROL SWITCHES AND DIALS,REPAIR PUMP SPED SWITCH.
SERVICE/REPAIR	11/06/2014	WC11@1270HRS SOURCE AND S/FIT 2X LED BEACONS
SERVICE/REPAIR	30/05/2014	CARRY OUT 1250HR SERVICE@1249HRS REPAIR RHF DOOR CHECK STRAP,REPAIR CAB SAFETY BAR ASSY,
SERVICE/REPAIR	23/01/2014	24.1.14@1035hrs ON SITE AT OLD DANDY RD WC11 WELDING REPAIRS TO WATER PIPE AT REAR TO WET TO WELD,CARRYOUT TEMP. REPAIR TO PIPE USING LAY FLAT HOSE AND 3X CLAMPS
SERVICE/REPAIR	20/01/2014	WC11@1026HRS ONSITE OLD DANDY RD SOURCE NEW CAB HOLD DOWN SAFETY LEVER ASSY GO TO SITE AND FIT LEVER ASSY. GREASE WATER PUMP
EXTERNAL SERVICE	29/11/2013	WC11 WATER CANNON N/W TRACE FAULT TO MULTI PLUG CORROSION REPLACE PLUG AND TEST OK
SERVICE/REPAIR	18/11/2013	WC11@944HRS REMOVE TYRE FOR REPAIR,FIT UP SPARE WHEEL AND TYRE TO KEEP TRUCK IN OPERATION,TAKE TO H,WAY TYRES,REPAIR AND RETURN TO OLD DANDY RD SITE.
SERVICE/REPAIR	24/10/2013	WC11@914HRS LITTLE OR NO WATER PRESSURE. REMOVE WATER PUMP INSPECTION PLATE,FOUND WEED AND PLASTIC BUILD UP IN IMPELLER.... REMOVE WATER PUMP,DISASSEMBLE AND REMOVE WEED AND PLASTI BUILD UP.... CHECK PTO ENGAGING,YES BUT SLIPPING AND OIL IN GEAR BOX BURNT.APPLY AIR PRESSURE TO CHECK ENGAGEMENT...NO ACTION,REMOVE PTO UNIT SOURCE NEW PTO STANDARD UNIT (NOT HOT SHIFT),FIT UP UNIT,CHANGE GEAR BOX OIL(BURNT)TEST PTO ALL OK,WRITE UP OPERATION PROCEDURE AND INSTRUCT SCOTT BRYLL. REPAIR DOOR HINGE,TAP CHECK STRAP BOLT THREADS,REPLACE BEACON GLOBE.
EXTERNAL SERVICE	4/09/2013	WC11 R&R WATER PUMP,REMOVE ELBOW FROM PUMP,CUT RUSTED THREAD OFF ELBOW,WELD ON NEW THREADED PIPE,FIT AND RESEAL TO PUMP...
EXTERNAL SERVICE	30/07/2013	WC11 WATER PUMP LEAKING WATER,MECHANICAL SEAL FAILED. PUMP RUN DRY??? REMOVE PUMP AND DISASSEMBLE,FOUND MECHANICAL SEAL BURNT OUT. SOURCE NEW SEAL...(\$221.00) REBUILD WATER PUMP.AND MOUNT TO TRUCK
SERVICE/REPAIR	16/07/2013	REPAIR EXHAUST BRAKE N/W (HOLE IN EXHAUST
SERVICE/REPAIR	15/07/2013	CARRY OUT 750HR TYPE SERVICE @800HRS REPLACE HYDRAULIC OIL FILTER
SERVICE/REPAIR	19/06/2013	WC11 768HRS TRAVEL TO OLD DANDY RD REPAIR WATER VALVE AT PUMP NOT CLOSING OFF 100%
SERVICE/REPAIR	29/04/2013	WC11 @720hrs water pump n/w,remove pump assy and dismantle for inspection.found excessive rust and electrolosis,drive shaft key way beyond repair,source entire new pump unit (aussie pumps)pick up new pump,fit pipe fittings ,valves etc to new pump assy, fit to truck and test all ok
SERVICE/REPAIR	15/02/2013	15/2/13 WC11 R&R BEACON ASSY,DISSASSEMBLE FOUND DRIVE BELT U/S...REPLACE DRIVE BELT,S/FIT NEW GLOBE REFIT WATER TANK HATCH COVER

ASSY...(NOT FITTED)

SERVICE/REPAIR	5/02/2013	5/2/13 CHECK AIR CONTROL BOX FOR AIR LEAKS
SERVICE/REPAIR	25/01/2013	CARRY OUT 500 HR SERVICE @ 519hrs SERVICE AIR FILTER,GREASE ALL POINTS,CHEK ALL FLUID LEVELS...
SERVICE/REPAIR	10/01/2013	WC11@491 HRS CHECK AND ADJUST ALL TYRE PRESSURES
SERVICE/REPAIR	18/12/2012	WATER CANNON N/W REMOVE CANNON FREE UP ELECTRIC MOTOR DRIVE, TEST SPRAY ALL OK
EXTERNAL SERVICE	28/11/2012	WC11 2X NEW DRIVE TYRES 11R22.5 REMINGTON
SERVICE/REPAIR	28/11/2012	L/H/REAR/REAR TYRES FLAT INFLATE TYRES SO AS TO TAKE TO BEUAREPAIRS FOR PUNTURE REPAIRS
SERVICE/REPAIR	10/10/2012	SOURCE PARTS,CARRY OUT SERVICE @ 385 HRS CHANGE ALL FILTERS, CHANGE ENGINE OIL, BLEED FUEL SYSTEM,GREASE ALL POINTS,ADJUST BELTS,INSPECT TRUCK
EXTERNAL SERVICE	18/09/2012	ON SITE AT OLD DANDT RD,WC11 HYDRAULIC FAN N/W,LOCATE BROKEN WIRE AND REPAIR.
SERVICE/REPAIR	31/07/2012	31/7/12 REVERSE ALARM N/W,RECTIFY SHORT AT L/H LAMP,REPLACE FUSE,TEST ALARM AND R/H LAMP ALL OK. CHECK HYD.OIL FLUID LEVEL ALL OK.
EXTERNAL SERVICE	29/05/2012	PTO,FLASHING LIGHT N/W.
SERVICE/REPAIR	23/05/2012	23.5.12 @239HRS TRAVEL OLD DANDY RD,FOUND LH NO.2 AXLE OUTERRIM DAMAGED BEYOND REPAIR.REMOVED WHEEL TO HIGHWAY TYRES. SOURCE 2X RIMS FROM HINO SOURCE 2 X TYRES HIGHWAY TYRES. RETURN TO SITE AND FIT UP ONE WHEEL ASSY, SPARE WHEEL IN SHED ON SIE
EXTERNAL SERVICE	17/04/2012	WC11 HYD FAN N/W,ELECTRIC WATER CANNON CONTROL N/W.
SERVICE/REPAIR	15/03/2012	PUNTURE REPAIR R AND LHF WHEEL TAKE TO BEAUREPAIRS CLAYTON,RETURN TO SITE AND FIT WHEEL.
SERVICE/REPAIR	11/04/2011	4998km. truck missfireing tested couldnt find problem.took it to hino dandy they found an electrical problem in the injector pump.got service done at same time.trying for warrenty just out