

 RITCHIE BROS. Diagnostic Report
Auctioneers[®]**2010 International WorkStar 7400****Test Information**

Engine	International DT466/Maxxforce DT (7.6)
Engine Serial	INT *466224240711696M07*5006277593--
VIN	1HTWGAAR1AJ204670
Driveline	Class 8 6x4
Body	Truck MDHD: Conventional
Test Time	June 30, 2025, 3:16 p.m.
File Length	33.973 s

Usage

Label	Value	Units
Engine Odometer	222,287	mi
Odometer (Instrument Cluster #1)	222,468	mi
Engine Total Hours of Operation	11,910.9	h

Engine On/Off

Engine running

Check Engine Light

No check engine lights on

Emissions Deleted/Tampered

No

Faults

<u>DM</u>	<u>Controller Name</u>	<u>SPN Name</u>	<u>FMI Name</u>	<u>Count</u>
Active	Body Controller	Manufacturer Assignable SPN	Out of Calibration	1
Active	Body Controller	Manufacturer Assignable SPN	Current Below Normal	1
Previous	Brakes - System Controller	Wheel Sensor ABS Axle 1 Right	Special Instruction	1
Previous	Brakes - System Controller	J1939 Network #1. Primary Vehicle Network	Failure	1
Previous	Instrument Cluster #1	Source Address 3	Abnormal Update Rate	2
Previous	Body Controller	Retarder Enable - Brake Assist Switch	Erratic, Intermittent, or Incorrect	6
Previous	Body Controller	Horn	Current Below Normal	4
Previous	Body Controller	Cab HVAC Mode Control Actuator	Erratic, Intermittent, or Incorrect	1
Previous	Body Controller	Operator Input device for Cab Climate Control	Erratic, Intermittent, or Incorrect	2
Previous	Body Controller	Headlamp Low Beam Right #1	Current Below Normal	126
Previous	Body Controller	Headlamp Low Beam Left #1	Current Below Normal	63
Previous	Body Controller	J1587	Abnormal Update Rate	1