

# 2015 CHEVROLET SILVERADO C1500

Pickup | 6 Cylinders | Gas

1GCNCPEH1FZ382922

Country of Assembly: United States

Last Reported Odometer: 629,978 KM



No Accident/Damage Records Found



Last Registered In:  
**Ontario (Normal)**



17 Service Records Found



No U.S. History Found



1 Open Recall Found



Not Actively Declared Stolen



No Import/Export Records Found

Questions? We're here to help.

Visit us at [support.carfax.ca](https://support.carfax.ca)



This vehicle history report is based on [information](https://www.carfax.ca/vehicle-history-data) (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of September 10, 2025 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.



# Vehicle History Report



## Accident/Damage

✓ There are no accidents/damage reported on this vehicle.



## Registration

✓ This vehicle has been registered in the province of **Ontario** in **Canada** with **Normal** branding.

*We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.*



## Service Records

DATE	ODOMETER	SOURCE	DETAILS
2016 Jan 6	28,505 KM	Service Facility Dryden, Ontario, Canada	Vehicle serviced
2016 Mar 8	57,789 KM	Service Facility Dryden, Ontario, Canada	Vehicle serviced
2016 Apr 27	88,431 KM	Service Facility Dryden, Ontario, Canada	Vehicle serviced
2016 May 26	109,770 KM	Service Facility Dryden, Ontario, Canada	Vehicle serviced
2016 Aug 19	128,495 KM	Service Facility Dryden, Ontario, Canada	Vehicle serviced
2016 Oct 15	150,277 KM	Service Facility Dryden, Ontario, Canada	Vehicle serviced
2016 Nov 2	164,275 KM	Service Facility Dryden, Ontario, Canada	Vehicle serviced
2016 Dec 29	190,013 KM	Service Facility Dryden, Ontario, Canada	Vehicle serviced
2017 Jan 13	199,364 KM	Service Facility Dryden, Ontario, Canada	Vehicle serviced
2017 Jan 23	204,642 KM	Service Facility Dryden, Ontario, Canada	Vehicle serviced
2017 Mar 13	231,216 KM	Service Facility Dryden, Ontario, Canada	Vehicle serviced
2017 Apr 18	248,666 KM	Service Facility Dryden, Ontario, Canada	Vehicle serviced
2017 Apr 26	231,225 KM	Service Facility Dryden, Ontario, Canada	Vehicle serviced



ODOMETER		SOURCE	DETAILS
2020 Oct 2	525,366 KM	Narvi's Auto Service Thunder Bay, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"><li>Engine/powertrain computer/module checked</li><li>Ignition system checked</li><li>Oil and filter changed</li></ul>
2020 Oct 29		Narvi's Auto Service Thunder Bay, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"><li>Oil and filter changed</li><li>Steering/suspension checked</li><li>Wheel bearings checked</li></ul>
2021 Feb 25	542,357 KM	A&D Brennen Motor Sales & Service Ltd Nipigon, Ontario, Canada	<b>Vehicle serviced</b>
2024 Apr 24	629,978 KM	Victory Lube 10 Minute Oil Change #2858 Sudbury, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"><li>Maintenance inspection completed</li><li>Body lubricated</li><li>Fluids checked</li><li>Oil and filter changed</li></ul>



## Open Recalls

Recall #: N202324251 | Roof Rail Air Bag Inflator May Rupture    Recall Date: 2021 Jul 01

### Recall Description

General Motors has decided that a defect which relates to motor vehicle safety exists in certain 2015–2016 model year Chevrolet Silverado and GMC Sierra vehicles. In these vehicles, the roof-rail airbag (“RRAB”) inflators, which are located on the left- and right-side roof rails above the headliner, may contain a manufacturing defect that may result in inflator end cap separation or inflator sidewall split. If the end cap separates from the RRAB inflator or a sidewall rupture occurs, the compressed gas will escape from the inflator and the end cap or other components can be propelled into the vehicle, potentially causing an occupant injury if the vehicle is occupied.

### Remedy

Dealers are to replace left and right front and rear row seat RRAB modules.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact CHEVROLET or visit [GM's website](https://my.gm.ca/gm/en/recalls). (https://my.gm.ca/gm/en/recalls)



## Stolen Vehicle Check

✔ This vehicle is not actively declared stolen.



## Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2015 Aug 20		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Previous Use: Commercial Vehicle colour noted as yellow
2016 Jan 6	28,505 KM	Service Facility Dryden, Ontario, Canada	Service Record	Vehicle serviced



	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2016 Mar 8	57,789 KM	Service Facility Dryden, Ontario, Canada	Service Record	Vehicle serviced
2016 Apr 27	88,431 KM	Service Facility Dryden, Ontario, Canada	Service Record	Vehicle serviced
2016 May 26	109,770 KM	Service Facility Dryden, Ontario, Canada	Service Record	Vehicle serviced
2016 Aug 19	128,495 KM	Service Facility Dryden, Ontario, Canada	Service Record	Vehicle serviced
2016 Sep 9		CHEVROLET	Recall	Manufacturer Recall Issued Recall # 2016007
2016 Oct 15	150,277 KM	Service Facility Dryden, Ontario, Canada	Service Record	Vehicle serviced
2016 Nov 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial
2016 Nov 2	164,275 KM	Service Facility Dryden, Ontario, Canada	Service Record	Vehicle serviced
2016 Dec 29	190,013 KM	Service Facility Dryden, Ontario, Canada	Service Record	Vehicle serviced
2017 Jan 13	199,364 KM	Service Facility Dryden, Ontario, Canada	Service Record	Vehicle serviced
2017 Jan 23	204,642 KM	Service Facility Dryden, Ontario, Canada	Service Record	Vehicle serviced
2017 Mar 13	231,216 KM	Service Facility Dryden, Ontario, Canada	Service Record	Vehicle serviced
2017 Apr 18	248,666 KM	Service Facility Dryden, Ontario, Canada	Service Record	Vehicle serviced
2017 Apr 26	231,225 KM	Service Facility Dryden, Ontario, Canada	Service Record	Vehicle serviced
2018 Sep 7		CHEVROLET	Recall	Manufacturer Recall Issued Recall # N182156820
2019 Jun 27		CHEVROLET	Recall	Manufacturer Recall Issued Recall # N192217410
2020 Oct 2	525,366 KM	Narvi's Auto Service Thunder Bay, Ontario, Canada	Service Record	Vehicle serviced
2020 Oct 29		Narvi's Auto Service Thunder Bay, Ontario, Canada	Service Record	Vehicle serviced
2020 Nov 10		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial
2021 Feb 25	542,357 KM	A&D Brennen Motor Sales & Service Ltd Nipigon, Ontario, Canada	Service Record	Vehicle serviced



ODOMETER		SOURCE	RECORD TYPE	DETAILS
2021 Jul 1		CHEVROLET	Recall	Manufacturer Recall Issued Recall # N202324251
2021 Nov 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial Vehicle colour noted as yellow
2023 Nov 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial
2024 Apr 24	629,978 KM	Victory Lube 10 Minute Oil Change #2858 Sudbury, Ontario, Canada	Service Record	Vehicle serviced



Questions? We're here to help.

Visit us at [support.carfax.ca](https://support.carfax.ca)

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada.

<https://www.carfax.ca/about-carfax/privacy-legal/conditions-of-use>

© 2025 CARFAX Canada ULC. All rights reserved.

