

Ezyquip Hire Pty Ltd

Service History Listing Active Units

Date: 12/08/2026
Time: 8:29:48AM

For Equipment Code From: DZ06029 To: DZ06029
For Date Posted From: 12/08/2026 To: 12/08/2026
Don't Show Cost

For Customer Code From: All To: All
For Branch Code From: All To: All

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: EZYQUIP							
Equip. Code: DZ06029		Description: Dozer 21t					
Make: Caterpillar		Model: D6R LGP		Serial No.: PPP00311			
277632	DECOMMISSION	BARK02	17/07/2026	Internal	9467.0	\$0.00	
275079	DEHIRE/PREP FOR HIRE	BEP07	10/06/2026	Internal	9467.0	\$0.00	
272444	Scheduled Service Job. PM Service 500 HR	XXXX	10/06/2026	Internal	9467.0	\$0.00	
274075	OFF HIRE INSPECTION	BEI01	27/05/2026	Internal	9466.0	\$0.00	
273356	REMOVE MINE RADIO	TODD01WEIPA	18/05/2026	Internal	9466.0	\$0.00	
273064	REPLACE AIR FILTER	TODD01WEIPA	13/05/2026	Internal	9436.0	\$0.00	
272539	6 MONTH FSS SERVICE	TODD01WEIPA	6/05/2026	Internal	9391.0	\$0.00	
272326	REPLACE ENGINE BELT	LAA04	4/05/2026	Internal	9336.0	\$0.00	
271907	INSPECT RHS LOOSE TRACKS	STEAO1	28/04/2026	Internal	9336.0	\$0.00	
270228	REPLACE EQ BAR BUSHES & PIN	STEAO1	3/04/2026	Internal	9239.0	\$0.00	
270193	EQ BAR CENTRE PIN LINE BORING (POST OFF HIRE)	XXXX	2/04/2026	Internal	9239.0	\$0.00	
269947	REPLACE FSS BOTTLE MOUNTING HARDWARE	XXXX	31/03/2026	Internal	9239.0	\$0.00	
269946	REPAIR BROKEN HANDRAIL	XXXX	31/03/2026	Internal	9239.0	\$0.00	
269945	RESEAL RHS LIFT CYLINDER	LAA04	31/03/2026	Internal	9239.0	\$0.00	
269943	REPLACE BROKEN IDLER CAP BOLTS	XXXX	31/03/2026	Internal	9239.0	\$0.00	
269942	EQ BAR REBUILD PART OF JN#270228	LAA04	31/03/2026	Internal	9239.0	\$0.00	
269934	REPLACE RUSTED TRANSMISSION LINES	CAPE02	31/03/2026	Internal	9239.0	\$0.00	
268103	Scheduled Service Job. PM Service 250 HR	CAPE02	27/03/2026	Internal	9260.0	\$0.00	
267137	RE-SEAL TILT CYLINDER	CAPE02	16/02/2026	Internal	9062.0	\$0.00	
266366	HAND RAIL REPAIRS	MRKU01	4/02/2026	Internal	9003.0	\$0.00	
266356	LABOUR ONLY REFER TO JN 261359	HAB04WEIPA	4/02/2026	Internal	9003.0	\$0.00	
263842	Scheduled Service Job. PM Service 9,000 HR	XXXX	2/02/2026	Internal	9003.0	\$0.00	
264856	FIRE EXTINGUISHER INSPECTION	TODD01WEIPA	11/01/2026	Internal	8866.0	\$0.00	
264386	RREPLACE 3 X WIPER BLADES	CAPE02	1/01/2026	Internal	8859.0	\$0.00	
264385	AC FAULT	CAPE02	1/01/2026	Internal	8859.0	\$0.00	
263616	REPLACE ENGINE AIR FILTERS	STEAO1	13/12/2025	Internal	8814.0	\$0.00	

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: EYZQUIP							
Equip. Code: DZ06029		Description: Dozer 21t					
Make: Caterpillar		Model: D6R LGP		Serial No.: PPP00311			
263189	REPLACE 8 X SEGMENTS	STEA01	8/12/2025	Internal	8756.0	\$0.00	
260745	Scheduled Service Job. PM Service XXXX 750 HR		2/12/2025	Internal	8756.0	\$0.00	
262723	INSPECT DUO CONE FAULT	BEI01PROJMACK	1/12/2025	Internal	8700.0	\$0.00	
261701	5 YEARLY FSS SERVICE	TODD01WEIPA	15/11/2025	Internal	8624.0	\$0.00	
261359	LEAKING TRANSMISSION HOSE	TODD01WEIPA	11/11/2025	Internal	8624.0	\$0.00	
261053	INSPECT BELTS & IDLERS	STEA01	6/11/2025	Internal	8606.0	\$0.00	
260966	FIRE SUPPRESSION SERVICE	TODD01WEIPA	6/11/2025	Internal	8606.0	\$0.00	
260800	DIAGNOSE FUEL DIALUTION FAULT	EIS02	4/11/2025	Internal	8602.0	\$0.00	
260646	AIR FILTER RESTRICTION FAULT	HAB04WEIPA	3/11/2025	Internal	8597.0	\$0.00	
258942	Scheduled Service Job. PM Service XXXX 500 HR		21/10/2025	Internal	8501.0	\$0.00	
259815	REPLACE WORN FINAL SEGMENTS	STEA01	20/10/2025	Internal	8495.0	\$0.00	
259804	REPAIR DEFECTS	STEA01	20/10/2025	Internal	8495.0	\$0.00	
259800	REPLACE GREASE NIPPLES	EIS02	20/10/2025	Internal	8495.0	\$0.00	
259491	REPLACE RUSTED A/C SERVICE PORTS	XXXX	16/10/2025	Internal	8806.0	\$0.00	
258677	DIAGNOSE OVERHEATING FAULT	STEA01	2/10/2025	Internal	8353.0	\$0.00	
258412	DIAGNOSE OVER HEATING FAULT	STEA01	30/09/2025	Internal	8353.0	\$0.00	
258116	FAULT CODES	STEA01	25/09/2025	Internal	8341.0	\$0.00	
257854	OVERHEATING FAULT	STEA01	22/09/2025	Internal	8334.0	\$0.00	
257521	EQ BAR REPAIRS	BEI01PROJMACK	16/09/2025	Internal	8288.0	\$0.00	
257003	LABOUR ONLY (256875)	BEI01	8/09/2025	Internal	8207.0	\$0.00	
255721	Scheduled 250HR PM Service	XXXX	5/09/2025	Internal	8262.0	\$0.00	
256875	REPLACE AIR FILTER	BEI01	4/09/2025	Internal	8207.0	\$0.00	
256529	TENSION TRACKS	STEA01	29/08/2025	Internal	8155.0	\$0.00	
255939	REPLACE AIR CLEANER	CAPE02	20/08/2025	Internal	8045.0	\$0.00	
255039	DIAGNOSE AC FAULT	BEI01	7/08/2025	Internal	7931.0	\$0.00	
254928	REPLACE EQ BAR / PARTS ONLY	STEA01	5/08/2025	Internal	7931.0	\$0.00	
254890	REPLACE BLADE CYLINDER HOSE	LAA04	5/08/2025	Internal	7931.0	\$0.00	
254792	REPLACE CANNON SEALS	LAA04	3/08/2025	Internal	7931.0	\$0.00	
254781	REPLACE FAILED BATTERIES	HAB04	3/08/2025	Internal	7931.0	\$0.00	
254778	REPLACE TRACKS AND ROLLERS	LAA04	3/08/2025	Internal	8016.0	\$0.00	
253563	Scheduled Service Job. PM Service XXXX 8,000 HR		27/07/2025	Internal	8016.0	\$0.00	
254054	REPLACE AM/FM RADIO	STEA01	21/07/2025	Internal	7931.0	\$0.00	
252507	REPLACE ALTERNATOR	CAPE02	27/06/2025	Internal	7767.0	\$0.00	

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: EYZQUIP							
Equip. Code: DZ06029		Description: Dozer 21t					
Make: Caterpillar		Model: D6R LGP		Serial No.: PPP00311			
251841	REPAIR DEFECTS	BEI01	18/06/2025	Internal	7747.0	\$0.00	
251719	CARRY OUT FSS INSPECTION & SERVICE	SUB	17/06/2025	Internal	7739.0	\$0.00	
251392	Scheduled Service Job. PM Service XXXX 750HR INSPECTION		17/06/2025	Internal	7739.0	\$0.00	
251478	REPLACE AIR FILTER	CAPE02	14/06/2025	Internal	7725.0	\$0.00	
250502	ENGINE FAULT CODES	CAPE02	29/05/2025	Internal	7584.0	\$0.00	
250226	REPLACE RADIATOR CAP	HAB04WEIPA	24/05/2025	Internal	7534.0	\$0.00	
248921	Scheduled Service Job. PM Service XXXX 500 HR		18/05/2025	Internal	7469.0	\$0.00	
248870	REPLACE LHS FAILED CARRIER ROLLER	CAPE02	30/04/2025	Internal	7387.0	\$0.00	
247181	REPLACE SEGMENTS & FASTNERS	STEAO1	30/03/2025	Internal	7219.0	\$0.00	
246121	Scheduled Service Job. PM Service XXXX 250 HR		28/03/2025	Internal	7219.0	\$0.00	
243798	LABOUR ONLY JN242490 PM Service	MCW04WEIPA	5/02/2025	Internal	6970.0	\$0.00	
242490	Scheduled Service Job. PM Service XXXX 7,000 HR		3/02/2025	Internal	6970.0	\$0.00	
243053	A/C REPAIRS	CAPE02	23/01/2025	Internal	6930.0	\$0.00	
242911	REPLACE MAIN POWER RELAY W/SPARE	HAB04	21/01/2025	Internal	6912.0	\$0.00	
242783	DIAGNOSE POWER LOSS FAULT	STEAO1	19/01/2025	Internal	6875.0	\$0.00	
242239	LOCKOUT 3RD GEAR	ROG02WEIPA	12/01/2025	Internal	6865.0	\$0.00	
240568	CARRY OUT FSS TESTING	SUB	14/12/2024	Internal	6766.0	\$0.00	
239453	Scheduled Service Job. PM Service XXXX 750 HR		5/12/2024	Internal	6725.0	\$0.00	
239934	DIAGNOSE AC FAULT	MCW04	28/11/2024	Internal	6693.0	\$0.00	
239649	DAIGNOSE AC FAULT	HAB04WEIPA	24/11/2024	Internal	6675.0	\$0.00	
239570	AIR RESTRICTION FAULT	HAB04WEIPA	22/11/2024	Internal	6635.0	\$0.00	
239258	PART ONLY JN239231	HAB04WEIPA	18/11/2024	Internal	6588.0	\$0.00	
239231	AIR RESTRICTION FAULT	HAB04WEIPA	17/11/2024	Internal	6588.0	\$0.00	
238978	TRACK INSPECTION	HAB04WEIPA	13/11/2024	Internal	6588.0	\$0.00	
238751	CHECK UNDERCARRIDGE & REPLACE HYDRAULIC OIL FILTER	CAPE02	9/11/2024	Internal	6578.0	\$0.00	
238737	TRACK REPLACEMENT	CAPE02	9/11/2024	Internal	6578.0	\$0.00	
238736	LABOUR ONLY JN235467	CAPE02	9/11/2024	Internal	6578.0	\$0.00	
237947	REPLACE WATER PUMP	CAPE02	29/10/2024	Internal	6518.0	\$0.00	
237923	REPLACE FAN BELT	CAPE02	29/10/2024	Internal	6506.0	\$0.00	
236952	Scheduled Service Job. PM Service XXXX 500 HR		28/10/2024	Internal	6506.0	\$0.00	
237764	AIR RESTRICTION FAULT	STEAO1	25/10/2024	Internal	6484.0	\$0.00	

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: EZYQUIP							
Equip. Code: DZ06029		Description: Dozer 21t					
Make: Caterpillar		Model: D6R LGP		Serial No.: PPP00311			
237449	TRACK INSPECTION	STEA01	21/10/2024	Internal	6397.0	\$0.00	
236848	TRACK INSPECTIONS	HAB04	10/10/2024	Internal	6354.0	\$0.00	
236743	REPLACE DRIVE BELTS	STEA01	8/10/2024	Internal	6354.0	\$0.00	
236577	REPLACE AIR FILTER (PARTS ONLY)	XXXX	4/10/2024	Internal	6292.0	\$0.00	
235493	REPLACE EQ BAR	CAPE02	16/09/2024	Internal	6240.0	\$0.00	
235467	RESEAL LIFT CYLINDER	CAPE02	16/09/2024	Internal	6240.0	\$0.00	
234648	Scheduled Service Job. PM Service	XXXX	16/09/2024	Internal	6240.0	\$0.00	250 HR
234464	RESEAL CAB SIDE WINDOWS	CAPE02	30/08/2024	Internal	6083.0	\$0.00	
234249	CLEAN AC EVAPORATOR	ROG02WEIPA	27/08/2024	Internal	6083.0	\$0.00	
233751	CHECK COOLANT LEVEL	MCW04WEIPA	19/08/2024	Internal	5987.0	\$0.00	
232691	Scheduled Service Job. PM Service	XXXX	14/08/2024	Internal	5987.0	\$0.00	6,000 HR
233338	CARRY OUT FSS INSPECTION & SERVICE	SUB	12/08/2024	Internal	5987.0	\$0.00	
232570	REPAIR INTAKE FAULT	HAB04WEIPA	31/07/2024	Internal	5893.0	\$0.00	
232116	ASSIST WITH FSS INSPECTION	FAJ05	24/07/2024	Internal	5844.0	\$0.00	
231991	REPLACE ENGINE & AC BELT	ROG02WEIPA	22/07/2024	Internal	5844.0	\$0.00	
230499	SMOKE BOMB CABIN	XXXX	15/07/2024	Internal	5797.0	\$0.00	
229216	Scheduled Service Job. PM Service	XXXX	8/07/2024	Internal	5744.0	\$0.00	750 HR
229554	REPLACE TOP TILT HOSE (W-STOCK)	CAPE02	28/06/2024	Internal	5640.0	\$0.00	
229548	REPLACE BOTTOM TILT HOSE	CAPE02	28/06/2024	Internal	5640.0	\$0.00	
228597	REPLACE SEIZED 4 POST ISOLATOR	MCW04	14/06/2024	Internal	5567.0	\$0.00	
228471	ROLLER CHANGE OUT	FAJ05	12/06/2024	Internal	5567.0	\$0.00	
228222	TESTING OIL COOLER	MCW04WEIPA	7/06/2024	Internal	5527.0	\$0.00	
228119	REPLACE ENGINE OUTER AIR CLEANER (W-STOCK)	CAPE02	5/06/2024	Internal	5527.0	\$0.00	
227912	AC FAULT	ROG02WEIPA	2/06/2024	Internal	5514.0	\$0.00	
227902	REPLACE OUTER ENGINE FILTER	CAPE02	1/06/2024	Internal	5514.0	\$0.00	
227515	RESEAL BLADE LIFT CYLINDERS	XXXX	26/05/2024	Internal	5460.0	\$0.00	
226877	Scheduled Service Job. PM Service	XXXX	26/05/2024	Internal	5460.0	\$0.00	500 HR
227300	WARRANTY - ENGINE OIL IN COOLING SYSTEM	MCW04WEIPA	21/05/2024	Internal	5460.0	\$0.00	
226364	REPAIR A/C FAULT	CAPE02	4/05/2024	Internal	5296.0	\$0.00	
224843	Scheduled Service Job. PM Service	XXXX	22/04/2024	Internal	5296.0	\$0.00	250 HR
225620	REBUILD EQ BAR	FAJ05	20/04/2024	Internal	5273.0	\$0.00	
225519	REMOVE BELLY GAURDS	HAB04	18/04/2024	Internal	5224.0	\$0.00	

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: EZYQUIP							
Equip. Code: DZ06029		Description: Dozer 21t					
Make: Caterpillar		Model: D6R LGP		Serial No.: PPP00311			
224135	SUPPLY & INSTALL AIR SEAT	DPCM01	20/03/2024	Internal	5060.0	\$0.00	
223349	CHECK WIPER OPERATION & REPAIR FUSE BOX	ROG02WEIPA	5/03/2024	Internal	4981.0	\$0.00	
222515	Scheduled Service Job. PM Service 5,000 HR	DPCM01	29/02/2024	Internal	4940.0	\$0.00	
222894	PRESSURE COOLING SYSTEM AND REPAIR LEAKS	DPCM01	28/02/2024	Internal	4940.0	\$0.00	
222886	REBUILD EQ BAR	DPCM01	27/02/2024	Internal	4940.0	\$0.00	
222879	REPLACE STARTER ISOLATOR	DPCM01	27/02/2024	Internal	4940.0	\$0.00	
222234	REPLACE FIRE EXTINGUISHER	CAPE02	14/02/2024	Internal	4861.0	\$0.00	
221788	REPLACE AM/FM RADIO	STEAO1	7/02/2024	Internal	4793.0	\$0.00	
221183	CARRY OUT LEVEL 2 FSS INSPECTION & SERVICE	SUB	29/01/2024	Internal	4745.0	\$0.00	
220837	REPLACE FLASHING LIGHT	FAJ05	22/01/2024	Internal	4722.0	\$0.00	
220407	Scheduled Service Job. PM Service 750 HR	FAJ05	22/01/2024	Internal	4722.0	\$0.00	
219684	START FAULT	STEAO1	5/01/2024	Internal	4630.0	\$0.00	
223768	REPLACE WATER PUMP CORE CREDIT	XXXX	12/12/2023	Internal	4572.0	\$0.00	
218599	REPLACE WATER PUMP	STEAO1	8/12/2023	Internal	4572.0	\$0.00	
218272	REPLACE ENGINE BELTS	HAB04WEIPA	3/12/2023	Internal	4545.0	\$0.00	
218087	DIAGNOSE FAULT WITH A/C - BV	STEAO1	29/11/2023	Internal	4545.0	\$0.00	
216880	Scheduled Service Job. PM Service 500 HR	XXXX	17/11/2023	Internal	4507.0	\$0.00	
217306	REPLACE AC CONDESOR FAN	ROG02WEIPA	16/11/2023	Internal	4425.0	\$0.00	
216899	CHANGE OUT FAN BELT	CAPE02	8/11/2023	Internal	4425.0	\$0.00	
215669	REPLACE FAILED WATERPUMP	STEAO1	17/10/2023	Internal	4276.0	\$0.00	
215656	COMPLETE SEAT INSPECTION AUDIT	CAPE02	17/10/2023	Internal	4276.0	\$0.00	
215655	REPLACE TRACKS & IDLERS	CAPE02	17/10/2023	Internal	4276.0	\$0.00	
215639	REPAIR A/C & HORN ELECTRICAL FAULT & REPLACE BLADE CYL HOSE	CAPE02	17/10/2023	Internal	4276.0	\$0.00	
215215	REPLACE FAN HUB BEARINGS & SEALS	XXXX	9/10/2023	Internal	4256.0	\$0.00	
215162	CLEAN RADIATOR & REPLACE CONDENSOR FAN FUSE	STEAO1	9/10/2023	Internal	4233.0	\$0.00	
215149	REPLACE AC BELT	CAPE02	8/10/2023	Internal	4233.0	\$0.00	
214037	Scheduled Service Job. PM Service 250 HR	XXXX	3/10/2023	Internal	4233.0	\$0.00	
214359	REPALCE FAILED COOLANT HOSE	HAB04	23/09/2023	Internal	4174.0	\$0.00	
213601	REPAIR HANDRAILS	CAPE02	12/09/2023	Internal	4108.0	\$0.00	
213337	REPLACE DOOR SEAL	XXXX	7/09/2023	Internal	4074.0	\$0.00	

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: EYZQUIP							
Equip. Code: DZ06029		Description: Dozer 21t					
Make: Caterpillar		Model: D6R LGP		Serial No.: PPP00311			
212880	REPLACE IDLER & TENSION TRACKS	CAPE02	30/08/2023	Internal	4047.0	\$0.00	
212601	INSPECT COMPARTMENT FO DIRT & RE DO SOS SAMPLES	KIB02	26/08/2023	Internal	4010.0	\$0.00	
210687	Scheduled Service Job. PM Service 4,000 HR	CAPE02	8/08/2023	Internal	3950.0	\$0.00	
211450	REPLACE FUEL/WATER SEPERATOR SENSOR	CAPE02	6/08/2023	Internal	3944.0	\$0.00	
210090	INSPECTION HANDRAILS AND WALKWAYS	CAPE02	15/07/2023	Internal	3825.0	\$0.00	
209532	REMOVE FAN BELT IDLERS & REINSTALL AFTER CLEAN	CAPE02	9/07/2023	Internal	3825.0	\$0.00	
209301	REPLACE WINDSCREEN WASHER	ROG02	4/07/2023	Internal	3809.0	\$0.00	
209661	CARRY OUT FIRE SUPPRESSION SUB AND EXTINGUISHER INSPECTIONS		26/06/2023	Internal	3775.0	\$0.00	
207254	Scheduled Service Job. PM Service 750 HR	XXXX	13/06/2023	Internal	3754.0	\$0.00	
207757	TIGHTEN A/C BELT	MCW04WEIPA	9/06/2023	Internal	3707.0	\$0.00	
207685	ROLLER & IDLER INSPECTION	HAYN01WEIPADFCAS	7/06/2023	Internal	3707.0	\$0.00	
206624	WIPER SYSTEM FAILURE	CAPE02	20/05/2023	Internal	3569.0	\$0.00	
205031	Scheduled Service Job. PM Service 500 HR	XXXX	9/05/2023	Internal	3521.0	\$0.00	
205765	REPLACE LH CARRIER ROLLER (parts only)	XXXX	4/05/2023	Internal	3476.0	\$0.00	
203875	Scheduled Service Job. PM Service 250 HR	XXXX	3/04/2023	Internal	3285.0	\$0.00	
202495	DIAGNOSE AND REPAIR MAIN SOLINOID AND RECOVER DOZER	CAPE02	27/02/2023	Internal	3081.0	\$0.00	
201547	CARRY OUT FSS INSPECTION & SERVICE	SUB	13/02/2023	Internal	3028.0	\$0.00	
201296	REPAIR BROKEN HANDRAIL -BK	CAPE02	8/02/2023	Internal	3007.0	\$0.00	
201295	DIAGNOSE MINE RADIO	ROG02	8/02/2023	Internal	3007.0	\$0.00	
200749	CHANGE ADAPTOR	MCW04WEIPA	1/02/2023	Internal	3007.0	\$0.00	
199649	Scheduled Service Job. PM Service 3,000 HR	STEA01	31/01/2023	Internal	3007.0	\$0.00	
198415	REPLACE ENGINE BELT	STEA01	8/12/2022	Internal	7207.0	\$0.00	
196891	Scheduled Service Job. PM Service 750 HR	KIB02WEIPA	5/12/2022	Internal	2748.0	\$0.00	
197043	SERVICE FIRE SUPPRESSION SYSTEM WITH HYDRA FIRE	ROG02WEIPA	14/11/2022	Internal	2595.0	\$0.00	
196404	BLOW OUT AIR CLEANERS	CAPE02	31/10/2022	Internal	2516.0	\$0.00	
195922	WARRANTY - REPLACE WATER PUMP	CAPE02	19/10/2022	Internal	2473.0	\$0.00	

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: EYZQUIP							
Equip. Code: DZ06029		Description: Dozer 21t					
Make: Caterpillar		Model: D6R LGP		Serial No.: PPP00311			
195586	REPAIR AC LEAK	HAYN01WEIPAAE2	14/10/2022	Internal	2457.0	\$0.00	
195442	CHANGE OVER DRIVE BELTS & TENSION TRACKS	CAPE02	12/10/2022	Internal	2457.0	\$0.00	
195399	500HR SERVICE (J. 193481)	KIB02WEIPA	11/10/2022	Internal	2457.0	\$0.00	
193481	Scheduled Service Job. PM Service 500 HR	CAPE02	10/10/2022	Internal	2457.0	\$0.00	
195287	WARRANTY - REPAIRS TO LEAKING FINAL DRIVE	MCW04WEIPA	9/10/2022	Internal	2438.0	\$0.00	
195285	WASHDOWN DOZER FOR WARRANTY WORK	KIB02WEIPA	9/10/2022	Internal	2438.0	\$0.00	
194598	WARRANTY - LH FINAL DRIVE DUO SEAL LEAKING	SUB	25/09/2022	Internal	2368.0	\$0.00	
194521	AIR FILETR RESTRICTION, BLOW OUT FILTER & RUN	CAPE02	23/09/2022	Internal	2368.0	\$0.00	
194227	SEAT INSPECTION	CAPE02	17/09/2022	Internal	2352.0	\$0.00	
194069	WARRANTY - RESEAL RH BLADE CYLINDER	SUB	14/09/2022	Internal	2352.0	\$0.00	
193985	REPLACE CONDES NOR	BEC08	12/09/2022	Internal	2352.0	\$0.00	
193904	REPLACE FAILED TRACKS & IDLERS	CAPE02	11/09/2022	Internal	2336.0	\$0.00	
193881	REPLACE AM/FM ANTENNA	HAYN01WEIPAAE1	11/09/2022	Internal	2336.0	\$0.00	
193203	INSPECT A/C FAULT	KIB02TRADE	27/08/2022	Internal	2294.0	\$0.00	
192724	ADJUST BLADE	STEA01	16/08/2022	Internal	2249.0	\$0.00	
191164	Scheduled Service Job. PM Service 250 HR	CAPE02	15/08/2022	Internal	2249.0	\$0.00	
192053	REPLACE ENGINE BELT	CAPE02	3/08/2022	Internal	2163.0	\$0.00	
191652	RESEAL BLADE LIFT CYLINDERS	STEA01	24/07/2022	Internal	2058.0	\$0.00	
191308	CHECK BELTS & IDLER	CAPE02	16/07/2022	Internal	2019.0	\$0.00	
189582	Scheduled Service Job. PM Service 2,000 HR	MAB01	3/07/2022	Internal	1984.0	\$0.00	
189935	REPLACE MASTERLINK BOLTS ON TRACKS	CAPE02	20/06/2022	Internal	1889.0	\$0.00	
189447	REPLACE FAILED RHS IDLER & ROLLERS (D/F)	CAPE02	9/06/2022	Internal	1808.0	\$0.00	
189403	REPLACE BELTS	CAPE02	8/06/2022	Internal	1808.0	\$0.00	
187789	Scheduled Service Job. PM Service 750 HR	CAPE02	30/05/2022	Internal	1755.0	\$0.00	
187697	RECHARGE FSS	KIB02TRADEWEIPA	3/05/2022	Internal	1514.0	\$0.00	
188668	REPLACE WORN TENSIONER & ALTERNATOR - CORE RETURN	XXXX	20/04/2022	Internal	1494.0	\$0.00	
187296	REPLACE WORN TENSIONER & ALTERNATOR	STEA01	20/04/2022	Internal	1494.0	\$0.00	
187148	REPLACE TRANMISSION HOSES	STEA01	15/04/2022	Internal	1466.0	\$0.00	
186075	Scheduled Service Job. PM Service 500 HR	SIJ02WEIPA	14/04/2022	Internal	1494.0	\$0.00	

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: EYZQUIP							
Equip. Code: DZ06029		Description: Dozer 21t					
Make: Caterpillar		Model: D6R LGP		Serial No.: PPP00311			
186986	OVERHEATING HYDRAULICS	CAPE02	12/04/2022	Internal	1466.0	\$0.00	
185475	INSPECT OIL LEAK ON ENGINE	CAPE02	8/03/2022	Internal	1172.0	\$0.00	
184629	ADJUST TRACKS	STEA01	16/02/2022	Internal	1118.0	\$0.00	
183237	Scheduled Service Job. PM Service XXXX 250 HR		16/02/2022	Internal	1243.0	\$0.00	
184476	MINE RADIO FAULT	CAPE02	13/02/2022	Internal	1086.0	\$0.00	
184248	REPLACE DOOR LATCH	CAPE02	7/02/2022	Internal	1086.0	\$0.00	
184129	WARRANTY - RESEAL LIFT CYLINDERS DUE TO DIRT INGRESS	STEA01	4/02/2022	Internal	1077.0	\$0.00	
182949	WARRANTY - FAILED WATER PUMP	SUB	9/01/2022	Internal	989.0	\$0.00	
182899	AIR CON BELT REPAIRS	CAPE02	7/01/2022	Internal	989.0	\$0.00	
180577	Scheduled Service Job. PM Service XXXX 1,000 HR		2/01/2022	Internal	989.0	\$0.00	
182730	REPLACE LH WIPER MOTOR & FAN BELT	STEA01	31/12/2021	Internal	953.0	\$0.00	
181123	REMOVE BLADE FROM MOBILISATION	CAPE02	13/12/2021	Internal	904.0	\$0.00	
181019	REPAIR UHF AERIAL	STEA01	10/12/2021	Internal	868.0	\$0.00	
180552	REPLACE WIPER MOTOR	CAPE02	30/11/2021	Internal	825.0	\$0.00	
183740	TYPE 2 FIRE SUPPRESSION SERVICE	SUB	20/11/2021	Internal	1077.0	\$0.00	
176902	Scheduled Service Job. PM Service PAN03 750 HR		12/11/2021	Internal	721.0	\$0.00	
179602	BLOW OUT AIR FILTERS & REPLACE BELT	CAPE02	10/11/2021	Internal	699.0	\$0.00	
179355	WARRANTY - REPLACE FRONT IDLER PLUGS	SUB	5/11/2021	Internal	650.0	\$0.00	
179266	ADJUST AC BELT	STEA01	4/11/2021	Internal	650.0	\$0.00	
178146	REPLACE FAN BELT	CAPE02	12/10/2021	Internal	588.0	\$0.00	
178101	WARRANTY - REPLACE RADIATOR CORES	SUB	11/10/2021	Internal	588.0	\$0.00	
177990	TOP UP FIRE SUPPRESSION	CAPE02	10/10/2021	Internal	568.0	\$0.00	
176576	RESET FIRE SUPPRESSION ALARM	CAPE02	1/10/2021	Internal	517.0	\$0.00	
176235	MODIFY INCORRECT TOW HITCHES & COMPLETE NDT TESTING	SUB	24/09/2021	External	472.0	\$848.88	MODIFY INCORRECT TOW HITCHES & COMPLETE NDT TESTING
174566	Scheduled Service Job. PM Service CAPE02 500 HR		22/09/2021	Internal	472.0	\$0.00	
174824	REPLACE FAN BELT	CAPE02	29/08/2021	Internal	297.0	\$0.00	
174775	REPOSITION MIRRORS ASSEMBLY	CAPE02	27/08/2021	Internal	297.0	\$0.00	
173343	Scheduled Service Job. PM Service CAPE02 250 HR		15/08/2021	Internal	245.0	\$0.00	

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: EZYQUIP							
Equip. Code: DZ06029		Description: Dozer 21t					
Make: Caterpillar		Model: D6R LGP		Serial No.: PPP00311			
176155	LABOUR - SUPPLY & INSTALL RAISED TOW HITCH	KIB02TRADEWEIPA	13/08/2021	External	201.0	\$720.00	
174049	PARTS - SUPPLY & INSTALL RAISED TOW HITCH	XXXX	13/08/2021	External	201.0	\$11,154.65	
173637	INSTALL RADIO	STEA01	4/08/2021	Internal	176.0	\$0.00	
172866	INSPECT & TORQUE A FRAME BOLTS	CAPE02	15/07/2021	Internal	29.0	\$0.00	
162251	DZ06029 CAPITAL ACQUISITION	XXXX	17/11/2020	Cap Prep	0.0	\$0.00	
Equipment Total:						\$12,723.53	
Customer Total:						\$12,723.53	