

Ezyquip Hire Pty Ltd

Service History Listing Active Units

Date: 12/08/2026

Time: 8:31:22AM

For Equipment Code From: DZ06037 To: DZ06037

For Customer Code From: All To: All

For Date Posted From: 12/08/2026 To: 12/08/2026

For Branch Code From: All To: All

Don't Show Cost

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: EZYQUIP							
Equip. Code: DZ06037		Description: Dozer 21t					
Make: Caterpillar		Model: D6T LGP		Serial No.: CAT00D6TKSGZ00335			
277526	REASSEMBLE BLADE TO MACHINE	BARK02	15/07/2026	Internal	11788.0	\$0.00	
277004	DECOMMISSION	SUB	8/07/2026	Internal	11788.0	\$0.00	
276172	OFF HIRE & DEMOB FROM SITE	DYNA04DF	26/06/2026	Internal	11778.0	\$0.00	
275371	REPLACE BLADE LINK AND PINS	DYNA04DF	18/06/2026	Internal	11769.0	\$0.00	
274443	Scheduled Service Job. PM Service	GAC01MRM	14/06/2026	Internal	11743.0	\$0.00	
269562	REPLACE REAR WORK LIGHTS	JOJ07PROJDARW	5/06/2026	Internal	11661.0	\$0.00	
274625	#REPLACE DAMAGED TILT CYLINDR GUARD	XXXX	3/06/2026	External	11641.0	\$0.00	
274486	#REPLACE DAMAGED BLADE TILT CYLINDER GUARD	SMJ06PROJDARW	2/06/2026	External	11641.0	\$1,970.43	
274058	TIGHTEN FIRE SUPPRESSION BOTTLE MOUNTS	JOJ07PROJDARW	27/05/2026	Internal	11595.0	\$0.00	
273977	DIAGNOSE REMOTE SHUTDOWN INPUT FAULT	JOJ07PROJDARW	26/05/2026	Internal	11595.0	\$0.00	
273079	GPS HARNESS REPAIRS	JOJ07PROJDARW	23/05/2026	Internal	11567.0	\$0.00	
273639	REPLACE COOLANT HOSES	BOUC01MRM	21/05/2026	Internal	11565.0	\$0.00	
273624	REPLACE BROKEN COOLER PACK BOLTS	BOUC01MRM	20/05/2026	Internal	11565.0	\$0.00	
273445	DIAGNOSE START FAULT	JOJ07PROJDARW	19/05/2026	Internal	11552.0	\$0.00	
272869	REPLACE HYDRAULIC TANK BREATHER	GAC01MRM	15/05/2026	Internal	11530.0	\$0.00	
272873	REPLACE LH DOOR WASHER PUMP	GAC01MRM	13/05/2026	Internal	11530.0	\$0.00	
272929	REPLACE BATTERIES	GAC01MRM	11/05/2026	Internal	11503.0	\$0.00	
272909	REPLACE CALLSIGNS RHS FRONT NOSE CONE	XXXX	11/05/2026	Internal	11503.0	\$0.00	
272901	CHANGE OUT BROKEN EXHAUST STACK	XXXX	11/05/2026	Internal	11503.0	\$0.00	
272887	REMOVE PUSHARM SHIMS	XXXX	11/05/2026	Internal	11503.0	\$0.00	
272884	REPLACE BELLY PLATE BOLT FRONT RHS	XXXX	11/05/2026	Internal	11503.0	\$0.00	
272866	INSPECT GPS FAULT	DINK02	11/05/2026	Internal	11510.0	\$0.00	
272849	REPLACE SUMP DRAIN BUNG	XXXX	11/05/2026	Internal	11503.0	\$0.00	
270843	Scheduled Service Job. PM Service	DRC01PROJDARW	11/05/2026	Internal	11509.0	\$0.00	
	500 HR						

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: EZYQUIP							
Equip. Code: DZ06037		Description: Dozer 21t					
Make: Caterpillar		Model: D6T LGP		Serial No.: CAT00D6TKSGZ00335			
272592	REPLACE FAULTY GPS CABLE	JOJ07PROJDARW	7/05/2026	Internal	11482.0	\$0.00	
271750	REPAIR SPROCKET SEGMENT	TODD01MRM	25/04/2026	Internal	11376.0	\$0.00	
271443	MACHINE INSPECTION	GIT02PROJDARW	21/04/2026	Internal	11325.0	\$0.00	
271432	REPLACE COVER FOR REAR LHS LIGHTS	XXXX	21/04/2026	Internal	11325.0	\$0.00	
271198	FLIP OVER RIPPER HYD LINES	GIT02PROJDARW	17/04/2026	Internal	11315.0	\$0.00	
270434	REPAIR RIPPER BOX	HAST06MRM	16/04/2026	Internal	11324.0	\$0.00	
270925	C/O BLUETOOTH LINK TO STANDARD	XXXX	14/04/2026	Internal	11315.0	\$0.00	
270899	TRACK BOLT REPAIRS	TODD01MRM	14/04/2026	Internal	11315.0	\$0.00	
270889	INSPECT BROKEN TRACK LINK BOLTS	GAC01MRM	14/04/2026	Internal	11315.0	\$0.00	
268800	Scheduled Service Job. PM Service 250hr	DYNA04DF	14/04/2026	Internal	11200.0	\$0.00	
270677	REPAIR ENGINE SHUT DOWN SWITCH WIRING	GAC01MRM	10/04/2026	Internal	11295.0	\$0.00	
270610	INSPECT ENGINE FAULT	GAC01MRM	9/04/2026	Internal	11283.0	\$0.00	
270411	REPLACE LH LOWER RIPPER STUD	XXXX	7/04/2026	Internal	11270.0	\$0.00	
269551	FABRICATE ROOF LIGHT MOUNTS	BOUC01MRM	25/03/2026	Internal	11184.0	\$0.00	
269541	DIAGNOSE REAR WORK LIGHT FAULT	JOJ07PROJDARW	25/03/2026	Internal	11181.0	\$0.00	
269476	INSPECT MACHINE DERATING FAULT	BOUC01	24/03/2026	Internal	11181.0	\$0.00	
269390	WELD UP CRACK IN LHS PUSH ARM	BOUC01MRM	22/03/2026	Internal	11181.0	\$0.00	
269389	STRAIGHTEN AND WELD BENT TRACK GUIDES	BOUC01MRM	22/03/2026	Internal	11181.0	\$0.00	
269382	REPLACE ROLLERS	DYNA04DF	21/03/2026	Internal	11171.0	\$0.00	
269280	REFER LABOUR TO SJ - 267407 - 267578 - 263899	TODD01MRM	19/03/2026	Internal	11171.0	\$0.00	
268961	UNDERCARRIAGE REAIRS	GAC01MRM	13/03/2026	Internal	11161.0	\$0.00	
268592	CHANGE OUT UNDERCARRIAGE	DYNA04DF	11/03/2026	Internal	11147.0	\$0.00	
268632	INSTALL NEW LOAD AND CARRIER ROLLERS,	CAB06PROJDARW	9/03/2026	Internal	11147.0	\$0.00	
268623	REPLACE MASTER LINK BOLTS	XXXX	9/03/2026	Internal	11147.0	\$0.00	
268606	REMOVE LOAD ROLLERS AND TRACKS	CAB06PROJDARW	9/03/2026	Internal	11147.0	\$0.00	
268257	INPSECT STEERING FILTER FAULT	DRC01PROJDARW	3/03/2026	Internal	11147.0	\$0.00	
267906	C/O SEAT BELT	TODD01MRM	3/03/2026	Internal	11144.0	\$0.00	
266160	REPLACE TURBO DUMP PIPE & INTAKE PIPE	TODD01MRM	3/03/2026	Internal	11144.0	\$0.00	
269009	FIRE SUPPRESSION SERVICE	SUB	24/02/2026	Internal	11171.0	\$0.00	

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: EZYQUIP							
Equip. Code: DZ06037		Description: Dozer 21t					
Make: Caterpillar		Model: D6T LGP		Serial No.: CAT00D6TKSGZ00335			
267741	RESEAL LH LIFT CYLINDER	HAST06MRM	24/02/2026	Internal	11127.0	\$0.00	
263899	RESEAL RH FINAL DRIVE	TODD01MRM	24/02/2026	Internal	11127.0	\$0.00	
267578	RESEAL BLADE TILT CYLINDER	SUB	21/02/2026	Internal	11121.0	\$0.00	
267407	REPLACE LH TRACK WITH GOOD S/HAND	TODD01MRM	20/02/2026	Internal	11127.0	\$0.00	
267327	INSPECT SEATBELT FAULT	DYNA04DF	17/02/2026	Internal	11121.0	\$0.00	
266159	REPLACE BLADE LIFT HOSES	GAC01MRM	12/02/2026	Internal	11078.0	\$0.00	
266161	REPLACE FINAL LEVEL BUNGS	XXXX	31/01/2026	Internal	11042.0	\$0.00	
266131	REPAIR GPS POWER FAULT	DINK02	31/01/2026	Internal	11042.0	\$0.00	
266080	DIAGNOSE LEFT WASHER FAULT	OCP02MRM	30/01/2026	Internal	11041.0	\$0.00	
266075	FIT VHF	DINK02	30/01/2026	Internal	11044.0	\$0.00	
265996	REPLACE HYDRAULIC HOSES	OCP02MRM	29/01/2026	Internal	11041.0	\$0.00	
265926	RESTOCK ELEC CONSUMABLES	XXXX	28/01/2026	Internal	11038.0	\$0.00	
265804	MACHINE DEFECT INSPECTION	DRC01PROJDARW	27/01/2026	Internal	11040.0	\$0.00	
265453	FIT SECOND HAND GROUSER PLATE	DRC01PROJDARW	19/01/2026	Internal	11013.0	\$0.00	
265290	INSPECT ENGINE "X" SAMPLE	CAD09PROJDARW	16/01/2026	Internal	11004.0	\$0.00	
265238	INSPECT GPS FAULT	JOJ07	16/01/2026	Internal	10990.0	\$0.00	
263796	RESEAL TILT CYLINDER	MCL10	10/01/2026	Internal	10998.0	\$0.00	
264910	REPLACE TRACK GUIDES	MCL10MRM	9/01/2026	Internal	10970.0	\$0.00	
263795	REPLACE ARMREST CUSHION	MCL10MRM	7/01/2026	Internal	10971.0	\$0.00	
264571	REPLACE STEER HOSES REF SJ# 265996	OCP02MRM	6/01/2026	Internal	10971.0	\$0.00	
263988	REPLACE LEAKING TANK BREATHER	HAST06MRM	31/12/2025	Internal	10970.0	\$0.00	
263794	RESEAL TORQUE CONVERTOR DRAIN	HAST06MRM	30/12/2025	Internal	10970.0	\$0.00	
263784	REPLACE TRANS HOSE	HAST06MRM	30/12/2025	Internal	10970.0	\$0.00	
263612	RESEAL LEAKING TRANS	HAST06MRM	30/12/2025	Internal	10970.0	\$0.00	
262797	Scheduled Service Job. PM Service 11,000 HR	HAST06MRM	30/12/2025	Internal	10970.0	\$0.00	
264169	INSPECT GPS RECEIVER FAULT	JOJ07PROJDARW	19/12/2025	Internal	10951.0	\$0.00	
263929	REMOVE ROCK FROM PUSH ARM	OCP02MRM	16/12/2025	Internal	10924.0	\$0.00	
263600	REPLACE RIPPER BOOTS	DYNA04DF	12/12/2025	Internal	10892.0	\$0.00	
263450	REPLACE SPROCKET SEGMENT	DYNA04DF	12/12/2025	Internal	10892.0	\$0.00	
263481	MACHINE DEFECT INSPECTION	OCP02MRM	11/12/2025	Internal	10889.0	\$0.00	
263137	REPLACE HOSES (STEERING/TRANS/TORQUE CONV)	OCP02MRM	10/12/2025	Internal	10892.0	\$0.00	
263117	REPLACE TRANS FILTER HOSES (REF #263137 FOR PARTS)	BOUC01MRM	5/12/2025	Internal	10871.0	\$0.00	
262581	REPLACE RH SPROCKET SEGMENT BOLTS	BOUC01MRM	27/11/2025	Internal	10834.0	\$0.00	

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: EYZQUIP							
Equip. Code: DZ06037		Description: Dozer 21t					
Make: Caterpillar		Model: D6T LGP		Serial No.: CAT00D6TKSGZ00335			
260720	Scheduled Service Job. PM Service DYN404DF 750 HR INSPECTION		27/11/2025	Internal	10843.0	\$0.00	
262045	FIRE SUPPR BOTTLE REFURB	SUB	20/11/2025	Internal	10749.0	\$0.00	
262024	REPLACE MISSING SPROCKET BOLTS	GAC01MRM	20/11/2025	Internal	10764.0	\$0.00	
261383	INSPECT FORWARD/REVERSE SWITCH FAULT	DINK02	11/11/2025	Internal	10715.0	\$0.00	
263480	REPLACE BLADE GET	HAST06MRM	10/11/2025	Internal	10982.0	\$0.00	
260761	ADJUST AND TIGHTEN RH & LH TRACKS	HAST06MRMSTANDBY	4/11/2025	Internal	10635.0	\$0.00	
260700	DIAGNOSE AND REPAIR FIRE SUPPRESSION FAULT	DINK02	2/11/2025	Internal	10635.0	\$0.00	
260725	REPLACE 2 WORK LIGHTS WITH LEDS	GAC01MRM	1/11/2025	Internal	10635.0	\$0.00	
260063	SERVICE LABOUR ONLY - REF #257929 PM Service	OCP02MRM	23/10/2025	Internal	10514.0	\$0.00	
257929	Scheduled Service Job. PM Service DYN404DF 500 HR		22/10/2025	Internal	10514.0	\$0.00	
259662	AIR CONDITIONING CHECKS	DINK02	18/10/2025	Internal	10488.0	\$0.00	
258373	#REPLACE DAMAGED TILT CYLINDER GUARD	XXXX	29/09/2025	External	10368.0	\$1,189.34	
258297	#CHANGE OUT TILT CYLINDER HOSE AND GUARD REPAIRS	DRC01PROJDARW	28/09/2025	External	10368.0	\$1,638.75	
258152	REPLACE BLADE TILT SENSOR	DRC01PROJDARW	25/09/2025	Internal	10368.0	\$0.00	
257216	REPLACE LIGHTS	DINK02	10/09/2025	Internal	10307.0	\$0.00	
256054	DPF FAULT - DPF DELETE	ALD01PROJDARW	26/08/2025	Internal	10259.0	\$0.00	
253998	Scheduled Service Job. PM Service JOH01PROJDARW 250 HR		18/08/2025	Internal	10223.0	\$0.00	
255330	RESEAL LH FINAL DRIVE MOUNTING	XXXX	11/08/2025	Internal	10157.0	\$0.00	
255843	CTS INSPECTION	SAB03MRM	7/08/2025	Internal	10223.0	\$0.00	
255114	FIRE SUPPRESSION SERVICE	SUB	7/08/2025	Internal	10157.0	\$0.00	
255072	REPLACE UHF MIC CLIP	XXXX	7/08/2025	Internal	10157.0	\$0.00	
254339	CORRECT GPS FAULT AND CALIBRATE	BEC03MRM	26/07/2025	Internal	10157.0	\$0.00	
254303	RESEAL TRANS MANIFOLD	MCL10MRM	25/07/2025	Internal	10134.0	\$0.00	
254287	DIAGNOSE GPS BLADE FAULT	DINK02	25/07/2025	Internal	10157.0	\$0.00	
254227	CLEAN AND WASH DOWN MACHINE/CHECK FOR OIL LEAKS	MCL10MRM	24/07/2025	Internal	10154.0	\$0.00	
253459	REMOVE BROKEN BOLT OUT OF WATER PUMP MOUNT	BOUC01MRM	12/07/2025	Internal	10106.0	\$0.00	
253457	REPLACE FAN BELT	BOUC01MRM	12/07/2025	Internal	10106.0	\$0.00	
251531	REPAIR COOLANT LEAK	BOUC01MRM	12/07/2025	Internal	10106.0	\$0.00	
252879	REPLACE ENGINE DOOR PINS	CHJ07MRM	30/06/2025	Internal	10106.0	\$0.00	

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: EYZQUIP							
Equip. Code: DZ06037		Description: Dozer 21t					
Make: Caterpillar		Model: D6T LGP		Serial No.: CAT00D6TKSGZ00335			
252618	REPLACE RIPPER BOOTS	DYNA04DF	29/06/2025	Internal	10028.0	\$0.00	
252812	TRANSMISSION REPAIRS AND HOSE REPLACEMENT	OCP02MRM	28/06/2025	Internal	10028.0	\$0.00	
254449	STOCK ADJUSTMENT S/J 250728 XXXX		27/06/2025	Internal	10000.0	\$0.00	
250728	Scheduled Service Job. PM Service 10,000 HR	OCP02MRM	27/06/2025	Internal	10000.0	\$0.00	
252346	DAILY CHECKS	XXXX	24/06/2025	Internal	10000.0	\$0.00	
252147	REPLACE RIPPER PINS & RETAINERS	BOUC01MRM	23/06/2025	Internal	9961.0	\$0.00	
252177	GPS CALIBRATION	BEC03	20/06/2025	Internal	9943.0	\$0.00	
251522	REPLACE IDLER PULLEY	GAC01MRM	16/06/2025	Internal	9932.0	\$0.00	
250652	REPLACE ARD HEAD	CHJ07MRM	6/06/2025	Internal	9835.0	\$0.00	
250681	DPF FAULT	ALD01PROJDARW	2/06/2025	Internal	9835.0	\$0.00	
250591	REPAIR AIR FILTER HOUSING	DYNA04DF	29/05/2025	Internal	9858.0	\$0.00	
250131	FIT GPS MUSHROOM	OCP02	22/05/2025	Internal	9801.0	\$0.00	
249889	REPLACE RH PUSHARM TO BLADE BLADE BOLTS	GAC01MRM	17/05/2025	Internal	9934.0	\$0.00	
249882	REPLACE CUTTING EDGES	CHJ07MRM	17/05/2025	Internal	9800.0	\$0.00	
249884	REPLACE BLADE TILT HOSES	JOH01PROJDARW	16/05/2025	Internal	9800.0	\$0.00	
249856	REPLACE FILTER HOUSING	CHJ07MRM	16/05/2025	Internal	9800.0	\$0.00	
248707	Scheduled Service Job. PM Service 750 HR INSPECTION	CHJ07MRM	16/05/2025	Internal	9800.0	\$0.00	
247565	REPLACE CYLINDER GUARD	CHJ07MRM	16/05/2025	Internal	9800.0	\$0.00	
249692	WORKLIGHT FAULT	BEC03MRM	14/05/2025	Internal	9798.0	\$0.00	
248980	RESEAL RH FINAL DRIVE	GAC01MRM	1/05/2025	Internal	9932.0	\$0.00	
248935	INSPECT OIL LEAK	MADE01RDFFIELD	1/05/2025	Internal	9750.0	\$0.00	
248592	GPS BLADE CALIBRATIONS	DINK02	24/04/2025	Internal	9607.0	\$0.00	
248346	REPLACE HYD HOSE	JOH01PROJDARW	24/04/2025	Internal	9617.0	\$0.00	
248343	REPLACE WASHER PUMP	GAC01MRM	24/04/2025	Internal	9617.0	\$0.00	
248334	MACHINE CHECK OVER	DYNA04DF	19/04/2025	Internal	9600.0	\$0.00	
248305	INSPECT WINDOW WASHER NOT WORKING	CHJ07MRM	17/04/2025	Internal	9599.0	\$0.00	
248287	REPLACE LIGHT GLOBES	CHJ07MRM	16/04/2025	Internal	9599.0	\$0.00	
247954	REPAIR FILTER HOUSING FOR HYD FILTER	HAST06MRMSTANDBY	13/04/2025	Internal	9573.0	\$0.00	
247941	RESEAL CANNON GUIDE ON TRACK FRAME	HAST06MRMSTANDBY	12/04/2025	Internal	9563.0	\$0.00	
247915	R/H TRACK FRAME & OIL LEAK	HAST06MRMSTANDBY	11/04/2025	Internal	9554.0	\$0.00	
245119	Scheduled Service Job. PM Service 500 HR	OCP02MRM	3/04/2025	Internal	9494.0	\$0.00	
247175	REPLACE BATTERY	BEC03MRM	29/03/2025	Internal	9462.0	\$0.00	
238640	REPLACE MISSING HINGE PIN	TODD01MRM	23/03/2025	Internal	8767.0	\$0.00	
246743	REFER JOB NUMBER 244392	CHJ07MRM	22/03/2025	Internal	9442.0	\$0.00	

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: EYZQUIP							
Equip. Code: DZ06037		Description: Dozer 21t					
Make: Caterpillar		Model: D6T LGP		Serial No.: CAT00D6TKSGZ00335			
246584	REPLACE GPS RECIEVER HARNES	DINK02	21/03/2025	Internal	9442.0	\$0.00	
246571	REPLACE SEAT SLIDES	HAST06MRMSTANDBY	19/03/2025	Internal	9425.0	\$0.00	
246412	REPAIR TILT CYLINDER GUARD	HAST06MRMSTANDBY	18/03/2025	Internal	9425.0	\$0.00	
245876	GPS CALIBRATION	BEC03MRM	9/03/2025	Internal	9354.0	\$0.00	
245413	GPS BLADE SENSOR FAULT	DINK02	8/03/2025	Internal	9354.0	\$0.00	
244891	#REPLACE BLADE TILT HOSE	DRC01PROJDARW	8/03/2025	External	9267.0	\$1,563.21	
245647	INSPECT GPS RADIO FREQUENCIES	DINK02	4/03/2025	Internal	9317.0	\$0.00	
244999	GREASE AND MACHINE CHECK OVER	JOH01PROJDARW	23/02/2025	Internal	9269.0	\$0.00	
244927	TRACK REPAIRS	JOH01PROJDARW	22/02/2025	Internal	9269.0	\$0.00	
244926	FIX BLADE BRACKET & CHANGE HOSE	DRC01PROJDARW	22/02/2025	Internal	9269.0	\$0.00	
238624	UNDERCARRIAGE REPAIRS	JOH01PROJDARW	21/02/2025	Internal	9296.0	\$0.00	
244541	GPS SCREEN REPAIR	BEC03MRM	16/02/2025	Internal	9267.0	\$0.00	
244522	REPLACE A/C CONDENSOR FANS	XXXX	16/02/2025	Internal	9267.0	\$0.00	
244516	REPLACE LOAD ROLLERS	CAJ10PROJDARW	16/02/2025	Internal	9257.0	\$0.00	
244505	DIAGNOSE A/C FAULT	BEC03MRM	15/02/2025	Internal	9257.0	\$0.00	
244445	REPLACE START ISOLATOR	BEC03MRM	14/02/2025	Internal	9257.0	\$0.00	
244401	#REPAIR BROKEN BOLTS	CAJ10PROJDARW	13/02/2025	External	9256.0	\$0.00	
244392	#BELLY GUARD REPAIRS	DINK02	12/02/2025	External	9256.0	\$1,441.39	
244389	GPS REPAIRS	DINK02	12/02/2025	Internal	9257.0	\$0.00	
244086	250HR SERVICE PM Service	OCP02MRM	9/02/2025	Internal	9257.0	\$0.00	
243739	RETIGHTEN GPS MOUNT	BEC03MRM	3/02/2025	Internal	9181.0	\$0.00	
243623	TIGHTEN LOOSE EQ BAR BOLTS	DYNA04DF	2/02/2025	Internal	9176.0	\$0.00	
252471	REFER JOB # 243433 - ALTERNATOR	XXXX	29/01/2025	Internal	9145.0	\$0.00	
243433	REPLACE ALTERNATOR	DRC01PROJDARW	29/01/2025	Internal	9145.0	\$0.00	
244960	FIRE SUPPRESSION SERVICE	SUB	22/01/2025	Internal	9145.0	\$0.00	
242141	FIT RIGHT HAND SPROKET BOLT	MCL10MRM	9/01/2025	Internal	53641.0	\$0.00	
238629	REPLACE CALL SIGNS	TODD01MRM	2/01/2025	Internal	14523.0	\$0.00	
238639	REBUSH BLADE LIFT CYLINDER YOKE	TODD01MRM	31/12/2024	Internal	9024.0	\$0.00	
238636	REPLACE EQ BAR END PINS ANC BEARINGS	TODD01MRM	31/12/2024	Internal	9024.0	\$0.00	
238635	REPLACE REAR ENGINE MOUNTS	TODD01MRM	31/12/2024	Internal	9024.0	\$0.00	
238554	PUSH ARM CENTRE PIN REPAIR	TODD01MRM	31/12/2024	Internal	9024.0	\$0.00	
239645	REPLACE BUSHES SCRUB CANOPY	TODD01MRM	28/12/2024	Internal	9034.0	\$0.00	
241176	FIT LOAD ROLLERS	OCP02MRM	17/12/2024	Internal	9011.0	\$0.00	

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: EZYQUIP							
Equip. Code: DZ06037		Description: Dozer 21t					
Make: Caterpillar		Model: D6T LGP		Serial No.: CAT00D6TKSGZ00335			
239317	Scheduled Service Job. PM Service OCP02MRM 9,000 HR		17/12/2024	Internal	9011.0	\$0.00	
241346	CTS INSPECTION	XXXX	14/12/2024	Internal	9011.0	\$0.00	
238913	DAILY CHECKS	XXXX	12/11/2024	Internal	8897.0	\$0.00	
238810	GPS BLADE SENSOR FAULT	DINK02	10/11/2024	Internal	8786.0	\$0.00	
237071	Scheduled Service Job. PM Service CHJ07MRM 750 HR		3/11/2024	Internal	8767.0	\$0.00	
237836	MAKE AND REPLACE TRANNY HOSE	CAJ10	28/10/2024	Internal	8640.0	\$0.00	
237824	REPLACE TRANS HOSE	CAJ10	27/10/2024	Internal	8640.0	\$0.00	
237025	REPLACE SEAT BELT	GAC01MRM	19/10/2024	Internal	8628.0	\$0.00	
236493	REPLACE SCRUB CANOPY MOUNTS	GAC01MRM	19/10/2024	Internal	8628.0	\$0.00	
236631	C/O FUEL FILTER HOUSING	DINK02	7/10/2024	Internal	8538.0	\$0.00	
236496	REPLACE HYDRAULIC DRAIN BUNG	DINK02	3/10/2024	Internal	8529.0	\$0.00	
234210	Scheduled Service Job. PM Service MCL10MRM 500 HR		2/10/2024	Internal	8538.0	\$0.00	
236399	FLIP CUTTING EDGES	DINK02	1/10/2024	Internal	8529.0	\$0.00	
236384	REPLACE MISSING DOOR LATCH XXXX KNOB		1/10/2024	Internal	8529.0	\$0.00	
236354	REPLACE TRANSMISSION FILTER HOUSING	DINK02	1/10/2024	Internal	8529.0	\$0.00	
236286	REPLACE IDLERS	DINK02	1/10/2024	Internal	8529.0	\$0.00	
236118	SENSOR REPAIRS	HAYN01NTCAS2AE	28/09/2024	Internal	8511.0	\$0.00	
236048	REPLACE DAMAGED BEVEL GEAR HOUSING DRAIN PLUG	XXXX	24/09/2024	Internal	8462.0	\$0.00	
235937	TEST BLADE SENSORS	HAYN01NTCAS2AE	24/09/2024	Internal	8462.0	\$0.00	
235802	REPLACE BLOWN HYD HOSE	GAC01MRM	22/09/2024	Internal	8454.0	\$0.00	
235536	REPAIR GPS HARNESS/SENSOR	HAYN01NTCAS2AE	18/09/2024	Internal	8408.0	\$0.00	
235331	DPF FAULT	TODD01MRM	13/09/2024	Internal	8389.0	\$0.00	
234114	REPLACE GPS SENSOR & CABLE	HAYN01NTSITE	24/08/2024	External	8293.0	\$3,174.94	
233917	INSPECT FUEL PRESSURE SENSOR FAULT	DINK02	20/08/2024	Internal	8272.0	\$0.00	
233910	REPLACE FAULTY GPS BLADE SNESOR	DINK02	20/08/2024	Internal	8272.0	\$0.00	
233646	REPAIR DOOR LATCH	HAST06MRMSTANDBY	16/08/2024	Internal	8226.0	\$0.00	
228846	RESEAL SUMP	DINK02	10/08/2024	Internal	8222.0	\$0.00	
228850	CANNON SEAL REPAIRS	DINK02	8/08/2024	Internal	8222.0	\$0.00	
232837	CHANGE OUT BATTERIES	TODD01MRM	6/08/2024	Internal	8208.0	\$0.00	
229674	Scheduled Service Job. PM Service DYNA04DF 250 HR		6/08/2024	Internal	8221.0	\$0.00	
232899	SPROCKET BOLT DAMAGED	DYNA04LV	5/08/2024	Internal	8215.0	\$0.00	

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: EYZQUIP							
Equip. Code: DZ06037		Description: Dozer 21t					
Make: Caterpillar		Model: D6T LGP		Serial No.: CAT00D6TKSGZ00335			
232722	STEER FILTER RESTRICTION FAULT	WIM12MRMLHAND	1/08/2024	Internal	8195.0	\$0.00	
232714	START FAULT	DINK02	31/07/2024	Internal	8194.0	\$0.00	
232575	TIGTEN LOOSE GPS RECEIVER CAP	DINK02	30/07/2024	Internal	8194.0	\$0.00	
232236	REPLACE FUEL FILTERS	MADE01RDFFIELD	26/07/2024	Internal	8194.0	\$0.00	
232198	INSPECT FUEL FAULT	DINK02	24/07/2024	Internal	8182.0	\$0.00	
230730	FIT NEW EQ BAR	CHJ07	18/07/2024	Internal	8124.0	\$0.00	
232340	REFER SJ # 230413 - TC CHARGE PUMP	DYNA04DF	14/07/2024	Internal	8124.0	\$0.00	
230852	FIRE SUPPRESSION SERVICE	SUB	14/07/2024	Internal	8124.0	\$0.00	
230459	LH TRUNNION CAP BOLTS MISSING	WIB08MRM	14/07/2024	Internal	8124.0	\$0.00	
230413	TC CHARGE PUMP	WIB08MRM	14/07/2024	Internal	8124.0	\$0.00	
230407	REPLACE TILT HOSES	MADE01RDFFIELD	12/07/2024	Internal	8116.0	\$0.00	
230059	INSPECT FUEL FAULT	WIM12MRMLHAND	7/07/2024	Internal	8106.0	\$0.00	
230003	REPLACE PARK BRAKE SWITCH	DYNA04FIELD	5/07/2024	Internal	8088.0	\$0.00	
229596	TRANSMISSION FILTER LEAK	DYNA04FIELD	29/06/2024	Internal	8042.0	\$0.00	
229170	INVESTIGATE HYDRAULIC LEAK	CHJ07MRM	24/06/2024	Internal	7963.0	\$0.00	
228966	STEERING FAULT	HAST06MRM	20/06/2024	Internal	7959.0	\$0.00	
228851	PUMP LEAK REPAIRS	XXXX	20/06/2024	Internal	7963.0	\$0.00	
228690	REPLACE RH & LH TRACKS	BOUC01MRM	17/06/2024	Internal	7959.0	\$0.00	
226797	Scheduled Service Job. PM Service 8,000 HR	BOUC01MRM	15/06/2024	Internal	7959.0	\$0.00	
228693	REPLACE FAN HOSE	PAN03MRM	14/06/2024	Internal	8116.0	\$0.00	
226586	REPLACE HYDRAULIC HOSES	BOUC01MRM	14/06/2024	Internal	7767.0	\$0.00	
228602	REPLACE RH REAR WORK LIGHT	BOUC01MRM	13/06/2024	Internal	7959.0	\$0.00	
228598	REMOVE BELLY PLATES	BOUC01MRM	13/06/2024	Internal	7958.0	\$0.00	
228179	INSPECT FUEL LEAK	TODD01MRM	12/06/2024	Internal	7958.0	\$0.00	
228419	DAILY CHECKS	XXXX	11/06/2024	Internal	7948.0	\$0.00	
228420	REPLACE FIRE SUPPRESSION BOTTLES	BOUC01MRM	10/06/2024	Internal	7949.0	\$0.00	
227426	REPLACE REAR COVER ASSEMBLY	WIM12MRMLHAND	7/06/2024	Internal	7934.0	\$0.00	
227894	REPAIR SEAT BELT AND SEAT MOUNT	WIM12MRMLHAND	1/06/2024	Internal	7889.0	\$0.00	
227400	REPLACE PARK BRAKE SWITCH	XXXX	23/05/2024	Internal	7810.0	\$0.00	
227313	FIT CANOPY MOUNTS REFER SJ #224511	TODD01MRM	21/05/2024	Internal	7810.0	\$0.00	
224587	REPLACE RIPPER LIFT CYL ROD END PIN	TODD01MRM	21/05/2024	Internal	7810.0	\$0.00	
226890	#REPLACE DAMAGED REAR COVER ASSEMBLY	XXXX	14/05/2024	External	7810.0	\$2,153.48	

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: EYZQUIP							
Equip. Code: DZ06037		Description: Dozer 21t					
Make: Caterpillar		Model: D6T LGP		Serial No.: CAT00D6TKSGZ00335			
226856	REPLACE BROKEN TRACK LINK	CHJ07	14/05/2024	Internal	7810.0	\$0.00	
226787	DAILY CHECKS	WIB08	12/05/2024	Internal	7800.0	\$0.00	
223379	Scheduled Service Job. PM Service	PAN03MRM	7/05/2024	Internal	7767.0	\$0.00	
	750 HR						
224514	ENGINE BELT REPAIRS	OCP02MRM	3/04/2024	Internal	7603.0	\$0.00	
224511	REPLACE SCRUB CANOPY	CHJ07MRM	3/04/2024	Internal	7603.0	\$0.00	
	MOUNTS						
226304	REMAN CORE CREDIT FROM	XXXX	28/03/2024	Internal	7606.0	\$0.00	
	JOB # 222239						
224550	REPLACE 3 UNDERCARRIAGE	TODD01MRM	28/03/2024	Internal	7604.0	\$0.00	
	ROLLERS						
222239	INSPECT & REPLACE LHS FINAL	HAYN01NTSITE	28/03/2024	Internal	7606.0	\$0.00	
	DRIVE						
224513	REPLACE WORK LIGHT GLOBES	TODD01MRM	27/03/2024	Internal	7604.0	\$0.00	
218636	REPLACE HYDRAULIC CAP	TODD01MRM	27/03/2024	Internal	7603.0	\$0.00	
224046	REPLACE WORN PINS &	TODD01MRM	26/03/2024	Internal	7604.0	\$0.00	
	BUSHES - SEE S/J 216134						
216684	NOSE CONE REPAIRS	HAYN01NTSITE	18/03/2024	Internal	7603.0	\$0.00	
222974	DRAIN HYDRAULIC OIL AND	HAYN01QLDSITE	1/03/2024	Internal	7564.0	\$0.00	
	REPLACE HYDRAULIC FILTER						
219989	REPLACE RHS BLADE TILT	WIM12MRMLHAND	27/02/2024	Internal	7511.0	\$0.00	
	CYLINDER HOSES						
249721	REFER SJ # 222614 - REPLACE	XXXX	26/02/2024	Internal	7511.0	\$0.00	
	DEF						
222849	COMPLETE TRACK INSPECTION	PAN03MRM	26/02/2024	Internal	7511.0	\$0.00	
222614	REPLACE DEF MANIFOLD	WIM12MRMLHAND	26/02/2024	Internal	7511.0	\$0.00	
222263	EMISSIONS FAULT	HAST06MRMSTANDBY	14/02/2024	Internal	7508.0	\$0.00	
222245	REPLACE TRANSMISSION HOSE	TODD01MRM	14/02/2024	Internal	7508.0	\$0.00	
222236	REPLACE G.E.T	TODD01MRM	14/02/2024	Internal	7508.0	\$0.00	
220366	Scheduled Service Job. PM Service	TODD01MRM	14/02/2024	Internal	7508.0	\$0.00	
	500 HR						
221995	REPAIR LHS LIGHT	TODD01MRM	10/02/2024	Internal	7480.0	\$0.00	
221441	REMOVE TRACK GROUSERS	WIM12MRMLHAND	2/02/2024	Internal	7408.0	\$0.00	
223133	FIRE SUPPRESSION SERVICE	SUB	31/01/2024	Internal	7408.0	\$0.00	
221455	REPLACE CRACKED TRACK LINK	HAYN01NTSITE	31/01/2024	Internal	7408.0	\$0.00	
221448	REPLACE E STOP	WIM12MRMLHAND	31/01/2024	Internal	7408.0	\$0.00	
221106	A/C REPAIRS	TRJ03MRM	25/01/2024	Internal	7407.0	\$0.00	
221104	REWIRE FIRE SUPPRESSION	TRJ03MRM	25/01/2024	Internal	7407.0	\$0.00	
219759	WEEKLY INSPECTIONS	XXXX	21/01/2024	Internal	7406.0	\$0.00	
220166	REPLACE FLOOD LIGHT -	WIM12MRMLHAND	11/01/2024	Internal	7383.0	\$0.00	
	#LABOUR ONLY REFER						
	SJ#218779						
220022	INSPECT GPS FAULT	DINK02	9/01/2024	Internal	7360.0	\$0.00	

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: EYZQUIP							
Equip. Code: DZ06037		Description: Dozer 21t					
Make: Caterpillar		Model: D6T LGP		Serial No.: CAT00D6TKSGZ00335			
216270	REPLACE WORN BLADE LIFT CYLINDER YOKES & BEARINGS	GAC01MRM	2/01/2024	Internal	7300.0	\$0.00	
219078	GPS FAULT	DINK02	16/12/2023	Internal	7278.0	\$0.00	
219068	FIRE SUPPRESSION FAULT	DINK02	14/12/2023	Internal	7262.0	\$0.00	
218779	REPLACE LHS REAR WORKLIGHT	XXXX	12/12/2023	Internal	7383.0	\$0.00	
217572	Scheduled Service Job. PM Service 250 HR	PAN03MRM	11/12/2023	Internal	7235.0	\$0.00	
218703	WEEKLY INSPECTIONS	XXXX	10/12/2023	Internal	7229.0	\$0.00	
219719	REMAN CORE RETURN REFER JOB # 217932	XXXX	4/12/2023	Internal	7177.0	\$0.00	
217932	REPLACE ARD HEAD	HAST06MRMSTANDBY	4/12/2023	Internal	7177.0	\$0.00	
217638	TIGHTEN LOOSE PANELS	PAN03MRM	21/11/2023	Internal	7130.0	\$0.00	
217027	REPAIR BROKEN FIRE SUPPRESSION BRACKET	GAC01MRM	10/11/2023	Internal	7014.0	\$0.00	
216615	WEEKLY INSPECTIONS	XXXX	1/11/2023	Internal	7060.0	\$0.00	
216309	CHANGE OUT COOLANT HOSES	PAN03MRM	29/10/2023	Internal	6984.0	\$0.00	
215915	REPLACE CONDENSOR	DINK02	26/10/2023	Internal	6667.0	\$0.00	
214845	Scheduled Service Job. PM Service 7,000 HR	DOM05MRM	25/10/2023	Internal	6962.0	\$0.00	
216134	REPLACE WORN PINS & BUSHES - PARTS ONLY - SEE S/J 224046	XXXX	24/10/2023	Internal	6963.0	\$0.00	
216022	RESEAL STARTER MOTOR	DOM05MRM	24/10/2023	Internal	6962.0	\$0.00	
215903	FIT MISSING BOLTS	TODD01MRM	21/10/2023	Internal	6667.0	\$0.00	
213516	REPLACE COOLANT HOSES	HAYN01NTSITE	19/10/2023	Internal	6667.0	\$0.00	
214735	RIPPER PIN REPLACEMENT	HAYN01NTSITE	30/09/2023	Internal	6805.0	\$0.00	
217867	REPLACE DAMAGED GUARD REFER JOB # 214715	XXXX	29/09/2023	External	6753.0	\$1,520.34	
214715	#FIT TILT CYLINDER GUARD	OCP02MRM	29/09/2023	Internal	6753.0	\$0.00	
214589	REPLACE PARK BRAKE FAULT	DINK02	27/09/2023	Internal	6774.0	\$0.00	
214154	REPLACE GPS BLADE SENSOR	DINK02	20/09/2023	Internal	6727.0	\$0.00	
212732	Scheduled Service Job. PM Service 750 HR	DINK02	19/09/2023	Internal	6727.0	\$0.00	
213923	CUT DOWN TRACK PLATES	DINK02	17/09/2023	Internal	6712.0	\$0.00	
213881	TIGHTEN UP DOOR LATCH	DINK02	16/09/2023	Internal	6667.0	\$0.00	
213613	REPLACE DUST EJECTOR HOSE	XXXX	12/09/2023	Internal	6667.0	\$0.00	
210244	FUEL DILUTION FAULT - REPLACE ALL INJECTORS	GAC01MRM	10/09/2023	Internal	6666.0	\$0.00	
211813	EQUALISER BAR REPAIRS	GAC01	9/09/2023	Internal	6666.0	\$0.00	
212671	GPS RECEIVER BASE	DINK02	27/08/2023	Internal	6569.0	\$0.00	
212211	#REPLACE CUTTING EDGES	DINK02	21/08/2023	External	6523.0	\$1,327.52	
211808	WASHER BOTTLE FAULT	WAH02MRM	12/08/2023	Internal	6473.0	\$0.00	
211793	REPLACE LEAKING ROLLERS	WAH02MRM	11/08/2023	Internal	6473.0	\$0.00	

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: EYZQUIP							
Equip. Code: DZ06037		Description: Dozer 21t					
Make: Caterpillar		Model: D6T LGP		Serial No.: CAT00D6TKSGZ00335			
210174	Scheduled Service Job. PM Service WAH02MRM 500 HR		11/08/2023	Internal	6473.0	\$0.00	
214002	FIRE SUPPRESSION SERVICE	SUB	7/08/2023	Internal	6454.0	\$0.00	
210978	FIRE SUPPRESSION FAULT	HAST06MRM	26/07/2023	Internal	6372.0	\$0.00	
210615	REPAIR TRACK	DINK02	24/07/2023	Internal	6353.0	\$0.00	
210577	REPLACE GPS RECIEVER CABLE	DINK02	21/07/2023	Internal	6353.0	\$0.00	
209972	REPAIR WIRING TO PRODUCT LINK	HAST06MRMSTANDBY	13/07/2023	Internal	6299.0	\$0.00	
207509	Scheduled Service Job. PM Service HAYN01MRMDFCAS 250 HR		3/07/2023	Internal	6249.0	\$0.00	
209084	LIGHT FAULT	TRJ03MRM	2/07/2023	Internal	6237.0	\$0.00	
209056	REPAIR BLADE FRAME PIN	HAYN01MRMDFCAS	1/07/2023	Internal	6174.0	\$0.00	
208406	UPDATE ECM SOFTWARE	HAST06MRMSTANDBY	20/06/2023	Internal	6130.0	\$0.00	
207855	REPLACE TRANSMISSION HOSE	MAM08MRM	12/06/2023	Internal	6111.0	\$0.00	
207603	CHANGE OUT LEAKING LOAD ROLLERS	XXXX	7/06/2023	Internal	6061.0	\$0.00	
207609	POWER FAULT /OVERHEATING FAULT	DINK02	6/06/2023	Internal	6061.0	\$0.00	
207388	GPS CALIBRATION	DINK02	2/06/2023	Internal	6027.0	\$0.00	
205979	Scheduled Service Job. PM Service HAYN01MRMDF1 6,000 HR		2/06/2023	Internal	6027.0	\$0.00	
207058	REPLACE FAULTY BEACON	RAA05MRM	28/05/2023	Internal	5985.0	\$0.00	
206987	GPS FAULT	MAM08	26/05/2023	Internal	5971.0	\$0.00	
205372	FIT TURBO TIMER	DINK02	25/04/2023	Internal	5762.0	\$0.00	
205185	REPLACE FAN BELT	HAYN01MRMDF1	21/04/2023	Internal	5761.0	\$0.00	
204560	Scheduled Service Job. PM Service HAYN01MRMDF1 750 HR		21/04/2023	Internal	5761.0	\$0.00	
204050	REPLACE BLADE LIFT CYLINDER HOSES	HAYN01MRMDF1	21/04/2023	Internal	5761.0	\$0.00	
204416	STEERING FILTER RESTRICTION FAULT	WAH02MRM	6/04/2023	Internal	5697.0	\$0.00	
204165	REPAIR HYDRAULIC LEAK	HAYN01MRMDF1	31/03/2023	Internal	5581.0	\$0.00	
204049	STEERING FILTER RESTRICTION FAULT	SAB02MRMLHAND	29/03/2023	Internal	5563.0	\$0.00	
203809	BLADE REPAIRS	ELSM01	25/03/2023	Internal	5563.0	\$0.00	
203807	INSTALL VISION LINK	DINK02	25/03/2023	Internal	5563.0	\$0.00	
203212	FIRE SUPPRESSION REPAIRS	DINK02	13/03/2023	Internal	5551.0	\$0.00	
203138	#REPLACE DAMAGED GUARD & TILT CYLINDER HOSES	HAYN01MRMDF1	12/03/2023	External	5544.0	\$1,590.46	
203121	#REPLACE END BITS & FLIP CUTTING EDGE	HAYN01MRMDF1	11/03/2023	External	5535.0	\$353.48	
200267	Scheduled Service Job. PM Service HAYN01MRMDF1 500 HR		27/02/2023	Internal	5471.0	\$0.00	
200189	RESEAL TILT CYLINDER & FIT MISSING GUARD	ELSM01	11/02/2023	Internal	5415.0	\$0.00	

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: EZYQUIP							
Equip. Code: DZ06037		Description: Dozer 21t					
Make: Caterpillar		Model: D6T LGP		Serial No.: CAT00D6TKSGZ00335			
201229	REPLACE TILT CYLINDER HOSE	MAM08MRM	6/02/2023	Internal	5389.0	\$0.00	
200939	SENSOR FAULT	WAH02MRM	2/02/2023	Internal	5363.0	\$0.00	
199356	REPLACE TILT CLYINDER HOSES	WAH02MRM	17/01/2023	Internal	5274.0	\$0.00	
198616	Scheduled Service Job. PM Service	WAH02MRM	17/01/2023	Internal	5274.0	\$0.00	
	250 HR						
201977	FIRE SUPPRESSION SERVICE	SUB	15/01/2023	Internal	5262.0	\$0.00	
201461	REMAN CORE CREDIT FOR DPF FILTER	XXXX	31/12/2022	Internal	5151.0	\$0.00	
197947	REPLACE DPF FILTER	MAM08	31/12/2022	Internal	5151.0	\$0.00	
198790	#GPS REPAIRS - CORRUPT SOFTWARE/SURVEY FILES	TRJ03	23/12/2022	External	5150.0	\$1,170.00	
198984	HIGH TORQUE CONVERTER OIL TEMPERATURE #02124452	XXXX	19/12/2022	Internal	5114.0	\$0.00	
198272	PARK BRAKE SOLENOID FAULT	TRJ03MRM	9/12/2022	Internal	5008.0	\$0.00	
195057	FIT TRIANGLE CALL SIGN	HAYN01MRMDF1	3/12/2022	Internal	5008.0	\$0.00	
196462	Scheduled Service Job. PM Service	GAC01	29/11/2022	Internal	5008.0	\$0.00	
	5,000 HR						
194760	REPLACE TRACKS	GAC01	29/11/2022	Internal	5008.0	\$0.00	
194672	Scheduled Service Job. PM Service	BAK03	31/10/2022	Internal	4844.0	\$0.00	
	750 HR						
196211	FIRE SUPPRESSION FAULT	TRJ03MRM	25/10/2022	Internal	4772.0	\$0.00	
196082	DEF FAULT	TRJ03MRM	23/10/2022	Internal	4756.0	\$0.00	
194664	TRACK REPAIRS	DINK02	1/10/2022	Internal	4554.0	\$0.00	
197760	PARTS RETURN CREDIT REFER JOB # 190013	XXXX	29/09/2022	Internal	4554.0	\$0.00	
190013	REPLACE HYDRAULIC TANK GUARD	SAB03MRM	29/09/2022	Internal	4554.0	\$0.00	
192658	Scheduled Service Job. PM Service	GAC01MRM	23/09/2022	Internal	4524.0	\$0.00	
	500 HR						
194162	REPLACE BATTERIES	MAM08	14/09/2022	Internal	4444.0	\$0.00	
195609	FIRE SUPPRESSION SERVICE	SUB	1/09/2022	Internal	4380.0	\$0.00	
193214	REPLACE BROKEN TRACK BOLTS	DINK01SAWAY	27/08/2022	Internal	4320.0	\$0.00	
190794	Scheduled Service Job. PM Service	PRL01TRADEAWAY	11/08/2022	Internal	4307.0	\$0.00	
	250 HR						
191892	HYDRAULIC LOCKOUT FAULT	HAYN01MRMDF1	29/07/2022	Internal	4161.0	\$0.00	
188715	REPLACE SHUTDOW SWITCH	XXXX	21/06/2022	Internal	3997.0	\$0.00	
186930	Scheduled Service Job. PM Service	MAM08MRM	20/06/2022	Internal	3997.0	\$0.00	
	4,000 HR						
189470	REPLACE BLOWN TRANNY HOSE	DINK01SAWAY	8/06/2022	Internal	3955.0	\$0.00	
185961	A/C FAULT	DINK01SAWAY	27/03/2022	Internal	3801.0	\$0.00	
185596	REPLACE WIPER MOTOR	MAM01MRMBASE	10/03/2022	Internal	3800.0	\$0.00	
181531	Scheduled Service Job. PM Service	MAM01MRMBASE	10/03/2022	Internal	3800.0	\$0.00	
	750 HR						

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: EYZQUIP							
Equip. Code: DZ06037		Description: Dozer 21t					
Make: Caterpillar		Model: D6T LGP		Serial No.: CAT00D6TKSGZ00335			
183510	FIRE SUPPRESSION SERVICE	SUB	1/01/2022	Internal	3687.0	\$0.00	
180957	#REPLACE CUTTING EDGES	DINK01SAWAY	9/12/2021	External	3507.0	\$1,475.14	
179476	Scheduled Service Job. PM Service	MAM01MRMBASE	5/12/2021	Internal	3518.0	\$0.00	
	500 HR						
179341	LABOUR REPLACED TO PM	DRC01	5/11/2021	Internal	3305.0	\$0.00	
	SERVICE 176538						
176538	Scheduled Service Job. PM Service	NOB01MRM	3/11/2021	Internal	3305.0	\$0.00	
	250 HR						
176636	OFFHIRE / PREP FOR HIRE	DINK01SAWAY	3/10/2021	Internal	3091.0	\$0.00	
175963	GPS FAULT	DINK01SAWAY	21/09/2021	Internal	3001.0	\$0.00	
173823	Scheduled Service Job. PM Service	DINK01SAWAY	16/09/2021	Internal	3000.0	\$0.00	
	1,000 HR						
175013	GPS FAULT	DINK01SAWAY	31/08/2021	Internal	2910.0	\$0.00	
174201	GPS FAULT	DINK01SAWAY	17/08/2021	Internal	2850.0	\$0.00	
174100	PARK BRAKE FAULT	DINK01SAWAY	16/08/2021	Internal	2787.0	\$0.00	
173903	GPS FAULT	DINK01SAWAY	10/08/2021	Internal	2787.0	\$0.00	
173590	REPAIR COOLER PACK	DINK01SAWAY	3/08/2021	Internal	2750.0	\$0.00	
172181	Scheduled Service Job. PM Service	SAB03TRADEAWAY	2/08/2021	Internal	2750.0	\$0.00	
	750 HR						
171896	REPLACE BLADE TILT CYL	DINK01SUPERVISOR	24/06/2021	Internal	2560.0	\$0.00	
	HOSES & REFIT CUTTING EDGE						
171784	NOSE CONE REPAIRS	XXXX	22/06/2021	Internal	2560.0	\$0.00	
170545	Scheduled Service Job. PM Service	PRL01TRADEAWAY	22/06/2021	Internal	2560.0	\$0.00	
	500 HR						
171122	REPLACE BLADE TILT HOSES	ROJ08AWAY	8/06/2021	Internal	2415.0	\$0.00	
169744	Scheduled Service Job. PM Service	SAB03TRADEAWAY	21/05/2021	Internal	2321.0	\$0.00	
	250 HR						
171714	REMOVE LGP TRACKS & FIT	SUB	26/04/2021	Internal	2558.0	\$0.00	
	TRIANGULAR TRACKS						
169458	ASSEMBLE & FIT UP GPS	DINK01SAWAY	26/04/2021	Internal	2126.0	\$0.00	
190780	REMOVE LGP TRACKS, FIT	SUB	30/03/2021	Internal	2126.0	\$0.00	
	TRIANGULAR TRACKS, PREPARE						
	TANK FOR QUICKFILL						
168517	DZ06037 CAPITAL ACQUISITION	XXXX	30/03/2021	Cap Prep	0.0	\$0.00	
Equipment Total:						\$20,568.48	
Customer Total:						\$20,568.48	