

JMH Equipment Repair Ltd.

PO Box 398

Radisson SK S0K 3L0

+13069612482

jmhequipment@yahoo.ca

GST/HST Registration No.: 825962988

PST SK Registration No.: 2744274

INVOICE**BILL TO****INVOICE #** 1559**DATE** 20/08/2025**DUE DATE** 19/09/2025**TERMS** Net 30

ACTIVITY	QTY	RATE	AMOUNT	TAX
Heavy Duty Mechanic Shop Service	76	135.00	10,260.00	GST/PST SK
Grey 1998 Volvo -Jan - Hooked to computer and preformed cut out test, #5 dead, pulled into shop and found exhaust valve on #5 to be broken as well as the slippers on #1. Waited for go ahead on truck. June - Removed bumper and hood, drained coolant, removed dog house, cooling package, valve cover/rocker box/intake, oil pan, jake towers, front eng cover and mount, and finished disassembling engine. Removed piston and liner, cleaned block, removed timing gears , Cleaned parts, assembled engine. Installed new #5 piston and liner, installed new cyl head w head bolts, installed timing gears and timed gear train to spec, replaced front cover as old one was cracked and had been repaired but was still leaking. installed crank seal, harmonic balancer. installed new exhaust rockers on rocker shaft assembly. Adjusted valves, set injectors, installed jake towers and set. assembled the rest of engine , installed new filters and filled with eng oil. filled with coolant, primed fuel system , boosted batterys and started engine. checked for leaks, installed hood and bumper as well as dog house and interior. test drove truck, noticed fan would not shut off, checked valve and it was plumbed wrong and leaking, replaced valve and plumbed correct, fan stayed off and would cycle on with switch. Fan hub - bearings were noisy in fan hub , went to replace fan hub but none were available, rebuilt hub with the only repair kit available , found pilot to be to big on hub so fan would not fit on the hub. disassembled and machined hub down to size, reassembled fan hub and installed in truck				
Heavy Duty Mechanic Field Service	1	11,956.86	11,956.86	GST/PST SK
cyl head, piston assembly, gasket kit, 5x rocker assembly, fan drive, front cover, air valve, antifreeze, oil, coolant, filters.				

Interest will be charged on accounts over 30 days at 2% per month or 24% per annum on the previous month's unpaid balance.

ACTIVITY	QTY	RATE	AMOUNT	TAX
Heavy Duty Mechanic Field Service shop supplies	76	10.00	760.00	GST/PST SK

SUBTOTAL			22,976.86	
GST @ 5%			1,148.84	
PST (SK) @ 6%			1,378.61	
TOTAL			25,504.31	
BALANCE DUE			\$25,504.31	