

**rb RITCHIE BROS. Diagnostic Report**  
Auctioneers®

**2014 Freightliner 106 Medium Duty**

Test Information	
<b>Engine</b>	Cummins ISL (8.9)
<b>Engine Serial</b>	CMMNS*6L u13D089000000*73589154
<b>VIN</b>	<a href="#">1FVACYCY8EHFW6600</a>
<b>Driveline</b>	Class 8 4x2
<b>Body</b>	Truck MDHD: Conventional
<b>Test Time</b>	May 15, 2026, 8:54 a.m.
<b>File Length</b>	34.3 s

Usage			
Label	Value	Units	
Engine Odometer	119,853	mi	
Odometer (Instrument Cluster #1)	119,882	mi	
Engine Total Hours of Operation	12,448.0	h	
Aftertreatment 1 Diesel Particulate Filter Soot Load Percent	6	%	

Engine On/Off
Engine running

Check Engine Light
No check engine lights on

Emissions Deleted/Tampered
No

## Faults

<u>DM</u>	<u>Controller Name</u>	<u>SPN Name</u>	<u>FMI Name</u>	<u>Count</u>
Previous	Body Controller	Unknown	Data Error	1
Previous	Body Controller	Tire Location	Current Below Normal	126
Previous	Body Controller	SCR System Cleaning Inhibited Due to Service Brake Active	Not Responding Properly	14
Previous	Body Controller	SCR System Cleaning Inhibited Due to Inhibit Switch	Not Responding Properly	126
Previous	Body Controller	SCR System Cleaning Inhibited Status	Data Error	1
Previous	Body Controller	SCR System Cleaning Status	Data Error	126
Previous	Body Controller	Source Address 3	Data Error	1
Previous	Body Controller	Source Address 71	Data Error	2
Previous	Body Controller	Estimated Percent Fan 2 Speed	Current Below Normal	2
Previous	Body Controller	Required Tire Pressure	Current Below Normal	2
Previous	Body Controller	Tire Wireless Signal Strength Indicator	Data Error	126
Previous	Body Controller	Tire Location	Data Error	126
Previous	Body Controller	Engine Cylinder 6 Exclude from Combustion Request	Voltage Below Normal	2
Previous	Body Controller	Engine Cylinder 2 Exclude from Combustion Request	Not Responding Properly	2
Previous	Body Controller	Engine Cylinder 1 Exclude from Combustion Request	Data Error	4
Previous	Body Controller	Tire Sensor Information	Not Responding Properly	1
Previous	Body Controller	SCR System Cleaning Inhibited Due to Out of Neutral	Not Responding Properly	1
Previous	Body Controller	Tire Location	Data Error	4
Previous	Body Controller	Over Temperature Setting	Data Error	4
Previous	Body Controller	Over Pressure Percentage Threshold Setting	Data Error	126
Previous	Body Controller	Cold Inflation Pressure Setting	Data Error	126
Previous	Body Controller	Tail Lamp/License Plate Lamp Circuit (Brown)	Current Below Normal	126
Previous	Cab Controller - Primary	Source Address 33	Data Error	15
Previous	Proprietary	Source Address 33	Data Error	126
Emissions Previous	Engine #1	ECU Power Output Supply Voltage #1	Erratic, Intermittent, or Incorrect	3