



**WINDSOR FORD**

10001 139 Avenue • Grande Prairie, AB • T8X 0V3  
 Tel: (780) 532-9555 • 1-800-422-6094  
 service@windsorford.com • www.windsorford.com  
 SERVICE HOURS - Mon - Fri 7:30 A.M. - 6:00 P.M.  
 Saturday - 8:00 A.M. - 5:00 P.M.

**GENUINE PEOPLE  
 TREATING YOU LIKE  
 A PERSON**

**OUR REPUTATION IS  
 YOUR EXPERIENCE**

**SO # 620013**

Status  
 Printed 02/05/2026 2:38:04 PM

**SERVICE ORDER  
 CUSTOMER COPY**



User 788 Page 1

Advisor	Shay G	Location	Promised	01/16/2026 6:30 PM
Shop	WF	PO #	Opened	01/07/2026 3:44 PM
Tag#	3777		Cashiered	

License	Odom In	Odom Out	In Service Date	Stock No
	82038	82051		
Year	Make	Model	Model Number	Colour
2023	FORD	SUPER DUTY F-350 SRW	W3B	1 OXFORD
Vehicle ID No	Selling Dealer	Extended Warranty	Delivery Date	
1FT8W3BA0PEC66401				
Engine	6.8L 2V DEVCT NA PFI V8 GAS			

Request	Description	Job	CSR	Status
160	CHECK AND ADVISE ON NO START - TOWED IN	1	SHAY G	Original
Labour	Description	Type	Amount	
MT	GET TRUCK STARTED AND INTO SHOP	W		
6007A	Engine Assembly - Remove and Install 6.8L DEVCT,10R100	W		
6007A34	Service Engine Assembly - FR (Ford Remanufactured Engine)/OEM Long Block - Replace 6.8L DEVCT	W		
6007E1	Inspect and Determine Engine Condition - Check 6.8L DEVCT	W		
6007E	Engine Exchange - Diagnosis	W		
12650D	EEC System Diagnosis (Quick Test).	W		
12650D45	EEC System Diagnostic Pin Point Test.	W		
MT	MANUAL TIME	W		

Part	Description	Shp	Bin	Type	Price	Amount
FL 820 S	FILTER ASY - OIL	1	K3	WR84		
ENFILT	TXLEV ENVIRO FEE	1	SPORD	WR84		
PC3Z 6006 P	SERVICE ENGINE ASY	1	SPORD	WR84		
CORE CHARGE	CORE CHARGE PC3Z 6006 P	1		WR84		
WR 6170	WIRE ASY - IGNITION	8	C1D	WR84		
AL3Z 6379 BA	BOLT - HEX.HEAD	8	F1D	WR84		
W715068 S437	BOLT	3	M4	WR84		
W715106 S439	BOLT	2	M4	WR84		
FL 820 S	FILTER ASY - OIL	1	K3	WR84		
ENFILT	TXLEV ENVIRO FEE	1	SPORD	WR84		
YF 37200	KIT - AIR CONDITIONI	1	D1D	WR84		
YF 37294	"O" RING	1	D1D	WR84		
W711336 S441	NUT	6	M4	WR84		
W715618 S437	NUT	4	M4	WR84		
W709771 S440	NUT - ADJUSTING SCRE	2	M3	WR84		
W520514 S440	NUT - HEX.	4	M3	WR84		
LC3Z 6020 A	GASKET	2	F1D	WR84		
LC3Z 6020 B	GASKET	1	F1D	WR84		
W717760 S439	BOLT AND WASHER ASY	6	M4	WR84		

**TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE.** "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

**DISCLAIMER OF WARRANTIES:** Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes or authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

**PRIVACY STATEMENT:** Personal information is collected in accordance with applicable privacy legislation and is governed by the Dealer's Privacy Policy. Your privacy is important to us. Ask us if you would like information about our Privacy Policy. We provide this personal information to Ford Motor Company of Canada Limited (together with third parties acting on its behalf "Ford") to enable Ford to administer your transaction, to provide you with services, to improve automotive related products and services by conducting customer surveys, and to provide you with marketing material which may be of interest to you. To obtain the Ford Privacy Policy or if you do not want to receive marketing or survey materials from Ford please call 1-800-565-FORD (3673).

**NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS**

**DISCLAIMER:** Wheel lug nuts must be retorqued 100km after any wheel has been removed. This is the CUSTOMERS responsibility.

Customer Signature: \_\_\_\_\_

GST# 10570 8457 RT0001



**WINDSOR FORD**  
 10001 139 Avenue • Grande Prairie, AB T8X 0V3  
 Tel: (780) 532-9555 • 1-800-422-6094  
 service@windsorford.com • www.windsorford.com  
**SERVICE HOURS - Mon - Fri 7:30 A.M. - 6:00 P.M.**  
**Saturday - 8:00 A.M. - 5:00 P.M.**

**GENUINE PEOPLE  
 TREATING YOU LIKE  
 A PERSON**

**OUR REPUTATION IS  
 YOUR EXPERIENCE**

**SO # 620013**

Status  
 Printed 02/05/2026 2:38:04 PM

**SERVICE ORDER  
 CUSTOMER COPY**



User 788 Page 2

Advisor	Shay G	Location	Promised	01/16/2026 6:30 PM
Shop	WF	PO #	Opened	01/07/2026 3:44 PM
Tag#	3777		Cashiered	

License	Odom In	Odom Out	In Service Date	Stock No
	82038	82051		
Year	Make	Model	Model Number	Colour
2023	FORD	SUPER DUTY F-350 SRW	W3B	1 OXFORD
Vehicle ID No	Selling Dealer	Extended Warranty	Delivery Date	
1FT8W3BA0PEC66401				
Engine	6.8L 2V DEVCT NA PFI V8 GAS			

KH 1340	HOSE - HEATER WATER	1	SPORD	WR84
LC2Z 9448 A	GASKET	2	G2	WR84
W714870 S430	NUT	16	M4	WR84

Technician 1324 -  
 139 -

Cause CHECK AND ADVISE ON NO STAT - TOWED IN

boost to start,found engine run very bad,check engine light flashing,all fault light on dash in on.  
 scan dtc,found P0132,P0300,P0301,P0302,P0303,P0303,P0306,P0313,P0316.  
 perform relative compression using FDRS,found #1-1% , #4 - 5% , #8 - 9% , #2 - 29%  
 checked oasis, found related TSB 25-2572.  
 as per TSB service procedure.  
 step 1-yes,step2-yes,step3-no,step4-yes,step5-(1). Yes - replace engine long block assembly  
 using shop phone take photo of open oil filter for approval.

as per request - remove and install both valve cover for picture reference.  
 as per request continue TSB step 7-remove and install both cylinder head.  
 step 8. Inspect the camshaft lobes and tappets for damage. Is damage present? - yes.  
 step 9. Inspect the engine for any related collateral damage/ - yes, piston liner has excessive wear  
 submitted photo for approval.

**TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE.** "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

**DISCLAIMER OF WARRANTIES:** Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes or authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

**PRIVACY STATEMENT:** Personal information is collected in accordance with applicable privacy legislation and is governed by the Dealer's Privacy Policy. Your privacy is important to us. Ask us if you would like information about our Privacy Policy. We provide this personal information to Ford Motor Company of Canada Limited (together with third parties acting on its behalf "Ford") to enable Ford to administer your transaction, to provide you with services, to improve automotive related products and services by conducting customer surveys, and to provide you with marketing material which may be of interest to you. To obtain the Ford Privacy Policy or if you do not want to receive marketing or survey materials from Ford please call 1-800-565-FORD (3673).

**NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS**

DISCLAIMER: Wheel lug nuts must be retorqued 100km after any wheel has been removed. This is the CUSTOMERS responsibility.

Customer Signature: \_\_\_\_\_

GST# 10570 8457 RT0001



**WINDSOR FORD**  
 10001 139 Avenue • Grande Prairie, AB • T8X 0V3  
 Tel: (780) 532-9555 • 1-800-422-6094  
 service@windsorford.com • www.windsorford.com  
**SERVICE HOURS** - Mon - Fri 7:30 A.M. - 6:00 P.M.  
 Saturday - 8:00 A.M. - 5:00 P.M.

**GENUINE PEOPLE  
 TREATING YOU LIKE  
 A PERSON**

**OUR REPUTATION IS  
 YOUR EXPERIENCE**

**SO # 620013**

Status  
 Printed 02/05/2026 2:38:04 PM

**SERVICE ORDER  
 CUSTOMER COPY**



User 788 Page 3

Advisor	Shay G	Location	Promised	01/16/2026 6:30 PM
Shop	WF	PO #	Opened	01/07/2026 3:44 PM
Tag#	3777		Cashiered	

License	Odom In	Odom Out	In Service Date	Stock No
	82038	82051		
Year	Make	Model	Model Number	Colour
2023	FORD	SUPER DUTY F-350 SRW	W3B	1 OXFORD
Vehicle ID No	Selling Dealer	Extended Warranty	Delivery Date	
1FT8W3BA0PEC66401				
Engine	6.8L 2V DEVCT NA PFI V8 GAS			

Correction Approval code: THGE041102  
 done replaced long block as per WSM 303-01B Engine - 6.8L  
 start vehicle and monitor for possible leak/fault,none found.  
 scan and clear dtc,reset KAM and misfire monitor relearn.  
 test drive vehicle while monitor misfire event,none found,perform visual  
 inspection,no fault found,scan dtc,no dtc found,verified repair.

- remove and install cab.
- additional MT..
- cab broken bolts x3 ( extract and replace )
- cat to exhaust bolts and nuts x4
- exhaust manifold x2
- exhaust Y-pipe-to-resonator pipe clamp x2
- exhaust Y-pipe-to-resonator bolts x2

Request	Description	Job	CSR	Status
99P	Windsor Ford Vehicle Report Card	2	SHAY G	Original
Labour	Description	Type	Amount	
99PA	WINDSOR FORD SAFETY & RELIABILITY INSPECTION \$49.95 VALUE -NO CHARGE	C	0.00	
Cause	Windsor Ford Vehicle Report Card			

**TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE.** "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

**DISCLAIMER OF WARRANTIES:** Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes or authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

**PRIVACY STATEMENT:** Personal information is collected in accordance with applicable privacy legislation and is governed by the Dealer's Privacy Policy. Your privacy is important to us. Ask us if you would like information about our Privacy Policy. We provide this personal information to Ford Motor Company of Canada Limited (together with third parties acting on its behalf "Ford") to enable Ford to administer your transaction, to provide you with services, to improve automotive related products and services by conducting customer surveys, and to provide you with marketing material which may be of interest to you. To obtain the Ford Privacy Policy or if you do not want to receive marketing or survey materials from Ford please call 1-800-565-FORD (3673).

**NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS**

DISCLAIMER: Wheel lug nuts must be retorqued 100km after any wheel has been removed. This is the CUSTOMERS responsibility.

Customer Signature: \_\_\_\_\_

GST# 10570 8457 RT0001



**WINDSOR FORD**  
 10001 139 Avenue • Grande Prairie, AB • T8X 0V3  
 Tel: (780) 532-9555 • 1-800-422-6094  
 service@windsorford.com • www.windsorford.com  
**SERVICE HOURS - Mon - Fri 7:30 A.M. - 6:00 P.M.**  
**Saturday - 8:00 A.M. - 5:00 P.M.**

**GENUINE PEOPLE  
 TREATING YOU LIKE  
 A PERSON**

**OUR REPUTATION IS  
 YOUR EXPERIENCE**

**SO # 620013**

Status  
 Printed 02/05/2026 2:38:04 PM

**SERVICE ORDER  
 CUSTOMER COPY**



User 788 Page 4

Advisor	Shay G	Location	Promised	01/16/2026 6:30 PM
Shop	WF	PO #	Opened	01/07/2026 3:44 PM
Tag#	3777		Cashiered	

License	Odom In	Odom Out	In Service Date	Stock No
	82038	82051		
Year	Make	Model	Model Number	Colour
2023	FORD	SUPER DUTY F-350 SRW	W3B	1 OXFORD
Vehicle ID No	Selling Dealer	Extended Warranty	Delivery Date	
1FT8W3BA0PEC66401				
Engine	6.8L 2V DEVCT NA PFI V8 GAS			

Correction need approval for diagnose..  
 4x4 in op  
 rear camera display-flickering  
 windshield washer in op  
 clunk on rear from stop  
 howling noise underload

need approval for repair..  
 air and cabin filter  
 park brake switch need replace  
 master window switch need replace  
 transmission service + filter  
 vacuum solenoid pigtail need replace  
 both catalytic converter need replace  
 muffler and tail pipe need replace  
 front bumper plastic inserts need replace  
 radiator sight shield need replace  
 block heater cord need replace  
 spare tire missing need replace

Request	Description	Job	CSR	Status
888	CUSTOMER INFORMATION/CONTACT# ___SHANE 512-5311	3	SHAY G	Original

CUSTOMER'S PREFERRED METHOD OF CONTACT:  
 TEXT \_\_\_\_\_ CALL \_\_\_\_\_ EMAIL \_\_\_\_\_

ENGINE HOURS \_\_\_\_\_

Would you like your used parts returned Yes / No (not applicable if warranty)

Labour	Description	Type	Amount
888	CUSTOMER INFORMATION/CONTACT# ___DELBERT 882-5990	CQL	0.00

CUSTOMER'S PREFERRED METHOD OF CONTACT:  
 TEXT \_\_\_\_\_ CALL \_\_\_\_\_ EMAIL \_\_\_\_\_

ENGINE HOURS \_\_\_\_\_

**TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE.** "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

**DISCLAIMER OF WARRANTIES:** Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes or authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

**PRIVACY STATEMENT:** Personal information is collected in accordance with applicable privacy legislation and is governed by the Dealer's Privacy Policy. Your privacy is important to us. Ask us if you would like information about our Privacy Policy. We provide this personal information to Ford Motor Company of Canada Limited (together with third parties acting on its behalf "Ford") to enable Ford to administer your transaction, to provide you with services, to improve automotive related products and services by conducting customer surveys, and to provide you with marketing material which may be of interest to you. To obtain the Ford Privacy Policy or if you do not want to receive marketing or survey materials from Ford please call 1-800-565-FORD (3673).

**NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS**

**DISCLAIMER:** Wheel lug nuts must be retorqued 100km after any wheel has been removed. This is the CUSTOMERS responsibility.

Customer Signature: \_\_\_\_\_

GST# 10570 8457 RT0001



# WINDSOR FORD

10001 139 Avenue • Grande Prairie, AB • T8X 0V3  
 Tel: (780) 532-9555 • 1-800-422-6094  
 service@windsorford.com • www.windsorford.com  
 SERVICE HOURS - Mon - Fri 7:30 A.M. - 6:00 P.M.  
 Saturday - 8:00 A.M. - 5:00 P.M.

**GENUINE PEOPLE  
 TREATING YOU LIKE  
 A PERSON**

**OUR REPUTATION IS  
 YOUR EXPERIENCE**

## SO # 620013

Status  
 Printed 02/05/2026 2:38:04 PM

## SERVICE ORDER CUSTOMER COPY



User 788 Page 5

<b>Advisor</b>	Shay G	<b>Location</b>	<b>Promised</b>	01/16/2026 6:30 PM
<b>Shop</b>	WF	<b>PO #</b>	<b>Opened</b>	01/07/2026 3:44 PM
<b>Tag#</b>	3777		<b>Cashiered</b>	
<b>License</b>		<b>Odom In</b>	<b>Odom Out</b>	<b>In Service Date</b>
		82038	82051	
<b>Year</b>	<b>Make</b>	<b>Model</b>	<b>Model Number</b>	<b>Colour</b>
2023	FORD	SUPER DUTY F-350 SRW	W3B	1 OXFORD
<b>Vehicle ID No</b>		<b>Selling Dealer</b>	<b>Extended Warranty</b>	<b>Delivery Date</b>
1FT8W3BA0PEC66401				
<b>Engine</b>	6.8L 2V DEVCT NA PFI V8 GAS			

Would you like your used parts returned Yes / No (not applicable if warranty)

Technician 999 -

Request	Description	Job	CSR	Status		
140	CHECK AND ADVIS EON TRANY FLUID LEAK	4	SHAY G	Approved		
Labour	Description	Type	Amount			
7000E	Automatic Transmission - External Oil Leaks -Diagnosis 10R100	W				
7095C	Oil Cooler - Automatic Transmission - Replace 10R100	W				
Part	Description	Shp	Bin	Type	Price	Amount
PC3Z 7869 E	OIL COOLER ASY	1	G1	WR84		
CVC 13 G	ANTI-FREEZE	3	WH1	WR84		

Technician 139 -

Cause CHECK AND ADVIS EON TRANY FLUID LEAK

VIN #: 1FT8W3BA0PEC66401  
 SUBMISSION DATE/TIME: FEBRUARY 04, 2026 10:52:23 A.M. (Dearborn, MI Time)  
 PART NUMBER: 7869 (TRANSMISSION (OIL COOLER ASSY))  
 REPAIR DATE 02/04/2026  
 REPAIR DISTANCE 82038 Km  
 IS COVERED UNDER -POWERTRAIN WARRANTY (BEGIN 07)

Correction lift vehicle and perform visual inspection,found transmission fluid cooler leaking. done replaced Transmission Fluid Heat Exchanger as per WSM 307-02A Transmission Cooling. test drive vehicle,perform visual inspection,no leak found,verified repair.

**TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE.** "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

**DISCLAIMER OF WARRANTIES:** Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes or authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

**PRIVACY STATEMENT:** Personal information is collected in accordance with applicable privacy legislation and is governed by the Dealer's Privacy Policy. Your privacy is important to us. Ask us if you would like information about our Privacy Policy. We provide this personal information to Ford Motor Company of Canada Limited (together with third parties acting on its behalf "Ford") to enable Ford to administer your transaction, to provide you with services, to improve automotive related products and services by conducting customer surveys, and to provide you with marketing material which may be of interest to you. To obtain the Ford Privacy Policy or if you do not want to receive marketing or survey materials from Ford please call 1-800-565-FORD (3673).

**NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS**

DISCLAIMER: Wheel lug nuts must be retorqued 100km after any wheel has been removed. This is the CUSTOMERS responsibility.

Customer Signature: \_\_\_\_\_

GST# 10570 8457 RT0001



**WINDSOR FORD**  
 10001 139 Avenue • Grand Prairie, AB • T8X 0V3  
 Tel: (780) 532-9555 • 1-800-422-6094  
 service@windsorford.com • www.windsorford.com  
**SERVICE HOURS - Mon - Fri 7:30 A.M. - 6:00 P.M.**  
**Saturday - 8:00 A.M. - 5:00 P.M.**

**GENUINE PEOPLE  
 TREATING YOU LIKE  
 A PERSON**

**OUR REPUTATION IS  
 YOUR EXPERIENCE**

**SO # 620013**

Status  
 Printed 02/05/2026 2:38:04 PM

**SERVICE ORDER  
 CUSTOMER COPY**



User 788 Page 6

Advisor	Shay G	Location	Promised	01/16/2026 6:30 PM
Shop	WF	PO #	Opened	01/07/2026 3:44 PM
Tag#	3777		Cashiered	

License	Odom In	Odom Out	In Service Date	Stock No
	82038	82051		
Year	Make	Model	Model Number	Colour
2023	FORD	SUPER DUTY F-350 SRW	W3B	1 OXFORD
Vehicle ID No	Selling Dealer	Extended Warranty	Delivery Date	
1FT8W3BA0PEC66401				
Engine	6.8L 2V DEVCT NA PFI V8 GAS			

Labour	0.00
Parts	0.00
Supplies	0.00
<b>Sub-Total</b>	<b>0.00</b>
GST	0.00
<b>Total Invoice</b>	<b>0.00</b>

**TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE.** "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

**DISCLAIMER OF WARRANTIES:** Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes or authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

**PRIVACY STATEMENT:** Personal information is collected in accordance with applicable privacy legislation and is governed by the Dealer's Privacy Policy. Your privacy is important to us. Ask us if you would like information about our Privacy Policy. We provide this personal information to Ford Motor Company of Canada Limited (together with third parties acting on its behalf "Ford") to enable Ford to administer your transaction, to provide you with services, to improve automotive related products and services by conducting customer surveys, and to provide you with marketing material which may be of interest to you. To obtain the Ford Privacy Policy or if you do not want to receive marketing or survey materials from Ford please call 1-800-565-FORD (3673).

**NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS**

**DISCLAIMER:** Wheel lug nuts must be retorqued 100km after any wheel has been removed. This is the CUSTOMERS responsibility.

Customer Signature: \_\_\_\_\_

GST# 10570 8457 RT0001