

0565346 B.C LTD. DBA Stewart

PO Box 2057, Dawson Creek BC V1G 4K8

Ph: (250) 782-7097 Fax: (250) 782-7094 Email: smf167@telus.net

REPAIR

14933

GST#: 870517281rt0001

Recvd By: DG

Date Recvd: 03/23/2017

Date Completed: 04/20/2017

| | | |
|--|--|---|
| Customer KROPP LOGGING PO BOX 74 POUCE COUPE, BC V0C 2C0 Contact MARVIN KROPP | CustID KLOGG Phone (250)784-8296 Ext | Repair Location Contact Phone |
|--|--|---|

| | | | | | |
|-------------|--------|----------------|--------------------|------------|-----------------|
| Warranty No | Vendor | Warranty Ref # | Sales Order # 0 | Contract # | Purchase Order# |
|-------------|--------|----------------|--------------------|------------|-----------------|

| | | | |
|---|--|---|--------------------------------|
| Stock Number M | Description 2000 PETERBELT UNIT #06 | Serial Number 1NPFDB0X9YN518347 PETERBILT | Problem / Complaint Repairs |
| Additional Products / Condition NONE | | | |

| Tech Stock Number | Date | WorkCode | Work Performed Parts Description | Billed Time (Hrs:Mins) Qty / Price | Rate | Total |
|-------------------------|------------|----------|---|---------------------------------------|--------|----------|
| KKK | 04/12/2016 | 03 | engine work. helped install valve covers and rocker box cover, installed peanut cover. bolted down fan hub assedmbly. connected all oil and air lines to head. | 0:0 | 80.00 | 0.00 |
| KKK | 04/13/2017 | 03 | MECHANIC'S HELPER bolted power steering assembly and bracket to head. bolted top rad support on and connected collant lines. installed new airfilters and cleaned air intake before installing. zip tied all lines to swecurements. filled with oil and coolant and power steering fluid. checked all fluids. put front passenger side steer tire on and torqued. start unit. topped up all fluids again. | 3:0 | 80.00 | 240.00 |
| Total For WorkCode : 03 | | | | | | 240.00 |
| KKK | 03/28/2017 | 04 | engine work, dropped coolant, pulled air intake, pulled rad lines, unbolted power steering resevoir, blocked up hood and undid top rad supports, unbolted all lines to head, unbolted covers and rocker box, disconnected injector wiring, pulled rocker box off, pulled peanut cover off, unbolted rocker assemblies, unbolted injectors, pushed cam back and unbolted headbolts, pulled passengers front tire, rigged up hoist to head, lifted off, pulled all fittings, loaded onto truck. | 0:0 | 125.00 | 0.00 |
| RAP | 03/28/2017 | 04 | removed turbo and manifold vave cover and spacer for valve cover thermostat houseing alternator air condidtioning pump removed head | 6:0 | 125.00 | 750.00 |
| TTC | 03/31/2017 | 04 | ENGINE WORK Started removing oil pan, oil pump and crankcase ladder. Removed main crank bearings 2,3,5,6,7. Removed all connecting rod caps and pistons. Removed cylinder liners. Starting to clean up engine bloc. | 8:0 | 125.00 | 1,000.00 |
| TTC | 04/03/2017 | 04 | ENGINE WORK Cleaned up bloc and sanded down all carbon build up on ridge of engine bloc. Cleaned up all engine parts and started to build new pistons and installed rings. Also removed cooling jets from bloc. Removed all crank bearings. | 8:0 | 125.00 | 1,000.00 |
| TTC | 04/04/2017 | 04 | ENGINE WORK. Did one final clean on engine bloc and all main bearing caps and connecting rod caps. Started to roll main bearings in. After 6 main caps were installed we then removed the final 3 main caps. Cleaned and re installed with new bearings. Tightened and torqued all main caps to spec. Installed all pistons and connecting rods. Torqued all to spec. Turned engine over to confirm proper piston placeent-OK- | 8:0 | 125.00 | 1,000.00 |
| TTC | 04/05/2017 | 04 | ENGINE WORK Started to clean up oil pan, oil pump and crankcase ladder. Cleaned all old locitite off bolts and installed oil pump, crankcase ladder and oil pan with new gasket. Torqued all bolts to spec. | 4:0 | 125.00 | 500.00 |
| RAP | 04/03/2017 | 04 | engine work helped cleaning up block sanding down carbon build up on block and cleaning all barts for re assembly | 0:0 | 125.00 | 0.00 |

Payee : Customer

SalesID : DEM Inv # : 6687

Received By

Date

X

Your one stop shop!

Thank-you for your buisiness!

| | |
|--------------|--------------------|
| Labour | \$7,490.00 |
| Parts | \$12,255.07 |
| Travel | \$0.00 |
| Shipping | \$0.00 |
| Taxes | \$2,369.40 |
| TOTAL | \$22,114.47 |

REPAIR

14933

Page 2

| Tech Stock Number | Date | WorkCode | Work Performed Parts Description | Billed Time (Hrs:Mins) Qty / Price | Rate | Total |
|----------------------|------------|----------|--|---------------------------------------|--------|----------|
| RAP | 04/04/2017 | 04 | cleaned up engine block again installed bearings liners and pistons | 0:0 | 125.00 | 0.00 |
| RAP | 04/05/2017 | 04 | cleaned up all parts to finish off bottom end and installed oil pan | 4:0 | 125.00 | 500.00 |
| TTC | 04/07/2017 | 04 | ENGINE WORK Cleaned up engine block and laid installed first cylinder head gasket, then spacer plate, installed all water jacket o rings. Installed final head gasket. Installed bolts and torqued all to spec. Installed camshaft before installation of cylinder head. Starting installing all rocker levers, injectors and valve bridges. Torqued to spec. Paul set backlash on camshaft gear. | 8:0 | 125.00 | 1,000.00 |
| TTC | 04/12/2016 | 04 | ENGINE WORK Performed valve set on engine. Double checked all adjustments and rollen engine over manually to confirm proper adjustment. Torqued everything. Installed bottom valver cover gasket with new gaskets. Torqued to spec. Installed all top valve covers with new gaskets and some new bolts. Installed exhaust manifold with new gaskets and bolts. Installed new turbo, with new gaskets for oil feed and drain. Pre oiled turbo. Installed Air to air tube. | 8:0 | 125.00 | 1,000.00 |
| TTC | 04/13/2017 | 04 | ENGINE WORK Filled engine with 45L of oil, filled up with all new coolant. Installed air intake piping. Replaced fuel filters. Replaced air filters. Primed fuel system and fired up engine. Ran great. Put truck outside on high idle and got to operating temperature. Checked for leaks.-OK- Finsihed tying up few things. | 4:0 | 125.00 | 500.00 |

Total For WorkCode : 04 7,250.00

| | | | | | |
|---------------|-------|--------------------------------------|------|---------|----------|
| SHOPSUPPLES | ZZZZZ | SHOP SUPPLIES | 1.00 | 524.30 | 524.30 |
| 10231 | ZZZZZ | Boxed Radiator Cap | 1.00 | 7.20 | 7.20 |
| FREIGHT | ZZZZZ | FREIGHT | 1.00 | 61.57 | 61.57 |
| 2481394 | ZZZZZ | KIT-GASKET-S | 6.00 | 30.49 | 182.94 |
| F:2818261 | ZZZZZ | sleeve | 1.00 | 74.02 | 74.02 |
| IPD 7352IF/CS | ZZZZZ | IN-Frame Kit | 1.00 | 5566.99 | 5,566.99 |
| 1756000HPX | ZZZZZ | Turbo | 1.00 | 2863.44 | 2,863.44 |
| WF2071 | ZZZZZ | WATER FILTER | 1.00 | 13.97 | 13.97 |
| ECO<8 | ZZZZZ | FILTER ECO | 1.00 | 1.25 | 1.25 |
| FF5319 | ZZZZZ | FILTER | 1.00 | 18.29 | 18.29 |
| ECO>8 | ZZZZZ | Filter | 1.00 | 1.56 | 1.56 |
| FF105 | ZZZZZ | Fuel Filter | 1.00 | 8.68 | 8.68 |
| ECO>8 | ZZZZZ | Filter | 1.00 | 1.56 | 1.56 |
| FREIGHT | ZZZZZ | FREIGHT | 1.00 | 35.42 | 35.42 |
| SUBLET | ZZZZZ | machine hed , new valves and springs | 1.00 | 2893.88 | 2,893.88 |

Total For WorkCode : ZZZZZ 12,255.07