

P10 - 2012 Tigercat 855C

Serial	Tag	Closed Meters
85531010		22,859 hr

Type	Created	Scheduled	Due	Started	Closed
	Jun 18, 2024	Jun 18, 2024		Jun 19, 2024 12:29 PM	Jul 31, 2024 2:43 PM

Line	Task	Parts	Labor	Total
------	------	-------	-------	-------

1	✓ Weld top knife	\$0.00	\$0.00	\$0.00
---	------------------	--------	--------	--------

Notes

Cut broken knife off tack on new kinife and add material to fill
broken base plate weld up cracks on sliding pins

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
Knife section	Kropp Shop		1.0	\$0.00	\$0.00

2	✓ Broken bolts on swing bearing	\$0.00	\$0.00	\$0.00
---	---------------------------------	--------	--------	--------

3	✓ Rubber stop	\$0.00	\$0.00	\$0.00
---	---------------	--------	--------	--------

Notes

Remove mounting plate and rebuild , put on new pad

4	✓ Tap feed roll motors out to 5/8"	\$0.00	\$0.00	\$0.00
---	------------------------------------	--------	--------	--------

5	✓ weld repads on boom	\$0.00	\$0.00	\$0.00
---	-----------------------	--------	--------	--------

6	✓ shim dog bone to head	\$0.00	\$0.00	\$0.00
---	-------------------------	--------	--------	--------

Notes

1/8 shim plate added

7	✓ Reseal cylinders	\$0.00	\$0.00	\$0.00
---	--------------------	--------	--------	--------

Notes

Drive cylinders, grab arm cylinder, tilt cylinder, measuring wheel
cylinder

8	✓ replace bushings on grab arm link	\$0.00	\$0.00	\$0.00
---	-------------------------------------	--------	--------	--------

P10 - 2012 Tigercat 855C

CLOSED

9	✓ replace measuring wheel bearings	\$0.00	\$0.00	\$0.00
10	✓ replace measuring wheel seal and plastic bushing	\$0.00	\$0.00	\$0.00
11	✓ hinges on carrier door broken	\$0.00	\$0.00	\$0.00
12	✓ check fluid levels	\$0.00	\$0.00	\$0.00
13	✓ check webasto	\$0.00	\$0.00	\$0.00
14	✓ check lights	\$0.00	\$0.00	\$0.00
15	✓ Weld cracks on head	\$0.00	\$0.00	\$0.00
16	✓ Add steel washers to bottom of grab arm pins and feed arm pins	\$0.00	\$0.00	\$0.00
17	✓ Wrap hoses on feed arms	\$0.00	\$0.00	\$0.00
18	✓ Fix hood and tap out hold down holes	\$0.00	\$0.00	\$0.00
19	✓ Grease head	\$0.00	\$0.00	\$0.00
20	✓ Inspect main saw for leaks	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

P10 - 2012 Tigercat 855C

Serial	Tag	Closed Meters
85531010		22,859 hr

Type	Created	Scheduled	Due	Started	Closed
	Aug 28, 2024	Aug 22, 2024		Oct 12, 2024 10:35 AM	Oct 12, 2024 10:35 AM

Line	Task	Parts	Labor	Total
1	✓ Measuring not correct	\$0.00	\$0.00	\$0.00
Notes				
Computer measurements all over the place, checked wire to encoder and changed problem still there... changed encoder problem still there.... Found out using diagnostic screen head module to be no good... ordered module				
2	✓ Oiler not working	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

P10 - 2012 Tigercat 855C

CLOSED

Serial	Tag	Closed Meters
85531010		22,859 hr

Type	Scheduled	Due	Started	Closed
	Dec 9, 2024		Dec 9, 2024 4:27 AM	Dec 9, 2024 4:27 AM

Line	Task	Parts	Labor	Total
1	✓ Get webasto to work	\$0.00	\$0.00	\$0.00
2	✓ Fitting broke off on buttsaw	\$0.00	\$0.00	\$0.00
3	✓ Loose hydraulic fittings up by rotary manifold	\$0.00	\$0.00	\$0.00
4	✓ Bumper missing on head	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00