

CD76 - 2019 Cross Country

CLOSED

Serial	Tag	Closed Meters
--------	-----	---------------

2C9SB3WXXM183776

Type	Created	Scheduled	Due	Started	Closed
	Jul 17, 2025	Jul 17, 2025		Jul 18, 2025 1:33 PM	Jul 30, 2025 2:04 PM

Line	Task	Parts	Labor	Total
1	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00
2	✓ CVIP inspection (wheels off)	\$0.00	\$0.00	\$0.00
Notes				
CVIP inspection sheet completed				
3	✓ Air tank drain leaking	\$0.00	\$0.00	\$0.00
Notes				
Replace petcock with 1/4 valve				

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

CD76 - 2019 Cross Country

CLOSED

Serial	Tag	Closed Meters
--------	-----	---------------

2C9SB3WXXM183776

Type	Scheduled	Due	Started	Closed
	Jan 23, 2026		Jan 23, 2026 5:33 PM	Jan 23, 2026 5:33 PM

Line	Task	Parts	Labor	Total
1	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

CD76 - 2019 Cross Country

CLOSED

Serial	Tag	Closed Meters
--------	-----	---------------

2C9SB3WXXM183776

Type	Scheduled	Due	Started	Closed
	Jul 17, 2026		Jul 17, 2026 6:48 PM	Jul 17, 2026 6:48 PM

Line	Task	Parts	Labor	Total
1	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

CD76 - 2019 Cross Country

CLOSED

Serial	Tag	Closed Meters
--------	-----	---------------

2C9SB3WXKM183776

Type	Created	Scheduled	Due	Started	Closed
	Jul 27, 2026	Jul 27, 2026		Jul 27, 2026 10:01 AM	Jul 31, 2026 8:37 AM

Line	Task	Parts	Labor	Total
1	✓ CVIP inspection (wheels off)	\$0.00	\$0.00	\$0.00
2	✓ Rear center markers change out	\$0.00	\$0.00	\$0.00
3	✓ rear Lh marker half burned out	\$0.00	\$0.00	\$0.00
4	✓ Front Lh marker burned out	\$0.00	\$0.00	\$0.00
5	✓ hinge pin keeper bolts all loose	\$0.00	\$0.00	\$0.00
6	✓ rear cylinder pin keeper bolt loose	\$0.00	\$0.00	\$0.00
7	✓ rh fender bolts loose	\$0.00	\$0.00	\$0.00
8	✓ Straighten Lh light bar	\$0.00	\$0.00	\$0.00
9	✓ Left front hub low	\$0.00	\$0.00	\$0.00
Part Cost				\$0.00
Labor				\$0.00
Subtotal				\$0.00
Tax 1 (0.0%)				\$0.00
Tax 2 (0.0%)				\$0.00
Credit				(\$0.00)
Total Cost				\$0.00