

T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z6LM183241	5ZL977	

Type	Scheduled	Due	Started	Closed
	Mar 9, 2024	Mar 9, 2024	Mar 9, 2024 4:07 PM	Mar 9, 2024 4:07 PM

Line	Task	Parts	Labor	Total
1	✓ Tires	\$0.00	\$0.00	\$0.00

Notes

#5LH inside #7LH inside #6 RH both wore out

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z6LM183241	5ZL977	

Type	Created	Scheduled	Due	Started	Closed
	May 13, 2024	May 13, 2024		May 13, 2024 5:45 AM	May 13, 2024 5:45 AM

Line	Task	Parts	Labor	Total		
1	✓ Wheels off CVIP inspection	\$0.00	\$0.00	\$0.00		
2	✓ change bunk #2 wrapper	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	log wrapper	Kropp Shop		1.0	\$0.00	\$0.00
3	✓ limit chains	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	3/8 bitch link	Kropp Shop		6.0	\$0.00	\$0.00
4	✓ scam bushings	\$0.00	\$0.00	\$0.00		

Notes

#3 LH,RH

#2 RH

#1 RH

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
cc s cam bushing	Kropp Shop		4.0	\$0.00	\$0.00

5	✓ Trailer Brakes	\$0.00	\$0.00	\$0.00
---	------------------	--------	--------	--------

Notes

#2 LH

#2 RH

#3 LH

#3 RH

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
Q plus shoe kit	Kropp Shop		4.0	\$0.00	\$0.00

T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Brake Drum	Kropp Shop	4.0	\$0.00	\$0.00
------------	------------	-----	--------	--------

6	✓ slack adjusters not working	\$0.00	\$0.00	\$0.00
---	-------------------------------	--------	--------	--------

Notes

#2LH

#3LH

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
6" slack adjuster CC	Kropp Shop		2.0	\$0.00	\$0.00

7	✓ Wheel seal leaking	\$0.00	\$0.00	\$0.00
---	----------------------	--------	--------	--------

Notes

#3 LH

#2 RH

#3RH

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
2110 wheel seal	Kropp Shop		3.0	\$0.00	\$0.00

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z6LM183241	5ZL977	

Type	Scheduled	Due	Started	Closed
	Nov 1, 2024		Nov 1, 2024 6:30 PM	Nov 1, 2024 6:30 PM

Line	Task	Parts	Labor	Total
1	✓ Brakes	\$0.00	\$0.00	\$0.00
	Notes			
	LH front brake pot nfg			
2	✓ Hub Levels	\$0.00	\$0.00	\$0.00
	Notes			
	LH front LH rear low			
3	✓ Saddle cracks	\$0.00	\$0.00	\$0.00
	Notes			
	lift axle crack			
Part Cost				\$0.00
Labor				\$0.00
Subtotal				\$0.00
Tax 1 (0.0%)				\$0.00
Tax 2 (0.0%)				\$0.00
Credit				(\$0.00)
Total Cost				\$0.00

T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z6LM183241	5ZL977	

Type	Created	Scheduled	Due	Started	Closed
	Nov 8, 2024	Nov 8, 2024		Nov 8, 2024 6:33 PM	Nov 8, 2024 6:33 PM

Line	Task	Parts	Labor	Total
1	✓ lift axle cracks <u>Notes</u> bottom crossmember to beam cracked	\$0.00	\$0.00	\$0.00
2	✓ saddle crack <u>Notes</u> back LH, front RH crack	\$0.00	\$0.00	\$0.00
3	✓ Flat tire <u>Notes</u> Rh lift inside	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z6LM183241	5ZL977	

Type	Scheduled	Due	Started	Closed
	Dec 1, 2024		Dec 1, 2024 6:55 AM	Dec 1, 2024 6:55 AM

Line	Task	Parts	Labor	Total
1	✓ Brakes	\$0.00	\$0.00	\$0.00

Notes

Back rh brakes springs MIA

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
Q plus hardware kit	Kropp Shop		1.0	\$0.00	\$0.00

2	✓ Lights - All	\$0.00	\$0.00	\$0.00
---	----------------	--------	--------	--------

Notes

front markers out

3	✓ Saddle cracks	\$0.00	\$0.00	\$0.00
---	-----------------	--------	--------	--------

Notes

front RH crack

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z6LM183241	5ZL977	

Type	Scheduled	Due	Started	Closed
	Jan 19, 2025		Jan 19, 2025 6:40 PM	Jan 19, 2025 6:40 PM

Line	Task	Parts	Labor	Total
1	✓ Suspension	\$0.00	\$0.00	\$0.00
	Notes			
	rear rh air bag bolt			
2	✓ Tires	\$0.00	\$0.00	\$0.00
	Notes			
	RLHI tire flat			
Part Cost				\$0.00
Labor				\$0.00
Subtotal				\$0.00
Tax 1 (0.0%)				\$0.00
Tax 2 (0.0%)				\$0.00
Credit				(\$0.00)
Total Cost				\$0.00

T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z6LM183241	5ZL977	

Type	Created	Scheduled	Due	Started	Closed
	Jan 31, 2025	Jan 31, 2025		Jan 31, 2025 4:32 PM	Jan 31, 2025 4:33 PM

Line	Task	Parts	Labor	Total		
1	✓ Bunk bolts	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	3,4,6 loose bolts					
2	✓ Lights - All	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	RH signal wont blink, front bunk lights out					
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	2 wire pigtail	Kropp Shop		2.0	\$0.00	\$0.00
	3050A round light	Kropp Shop		1.0	\$0.00	\$0.00
3	✓ Suspension	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	rear axle u bolts loose inside, front rh inside u bolt loose					
4	✓ Tires	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	Middle LH outside NFG					
	middle LH					
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00

Kropp Contracting
Shop

Work Order 1624

Trent Court

T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z6LM183241	5ZL977	

Type	Created	Scheduled	Due	Started	Closed
	Mar 3, 2025	Mar 3, 2025		Mar 3, 2025 11:33 AM	Mar 3, 2025 11:33 AM

Line	Task	Parts	Labor	Total
1	✓ Saddle cracks	\$0.00	\$0.00	\$0.00

Notes

rear rh saddle crack

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z6LM183241	5ZL977	

Type	Created	Scheduled	Due	Started	Closed
	Mar 20, 2025	Mar 20, 2025		Mar 20, 2025 7:49 AM	Mar 20, 2025 7:49 AM

Line	Task			Parts	Labor	Total
1	✓ stake broke off			\$1,100.00	\$0.00	\$1,100.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Cc stake	Kropp Shop		1.0	\$1,100.00	\$1,100.00
				Part Cost		\$1,100.00
				Labor		\$0.00
				Subtotal		\$1,100.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$1,100.00

T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z6LM183241	5ZL977	

Type	Created	Scheduled	Due	Started	Closed
Cvip inspection	May 14, 2025	May 14, 2025		May 28, 2025 4:49 AM	May 28, 2025 4:49 AM

Line	Task	Parts	Labor	Total
1	✓ trailer brakes	\$0.00	\$0.00	\$0.00
2	✓ Welding	\$0.00	\$0.00	\$0.00
3	✓ Installed lift axel	\$0.00	\$0.00	\$0.00
4	✓ Cam rotation	\$0.00	\$0.00	\$0.00
5	✓ Installed new clevis's on all limiting chains	\$0.00	\$0.00	\$0.00
6	✓ Fixed air leak off foot brake valve	\$0.00	\$0.00	\$0.00
7	✓ Installed new brake pot air line	\$0.00	\$0.00	\$0.00
8	✓ CVIP wheels off	\$0.00	\$0.00	\$0.00
9	✓ Repaired lift axel wiring	\$0.00	\$0.00	\$0.00
10	✓ Installed 7 pin plug	\$0.00	\$0.00	\$0.00
11	✓ Straightened bent handles on straps	\$0.00	\$0.00	\$0.00
12	✓ CVIP inspection (wheels off)	\$0.00	\$0.00	\$0.00
13	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00
Part Cost				\$0.00
Labor				\$0.00
Subtotal				\$0.00
Tax 1 (0.0%)				\$0.00
Tax 2 (0.0%)				\$0.00
Credit				(\$0.00)
Total Cost				\$0.00

T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z6LM183241	5ZL977	

Type	Created	Scheduled	Due	Started	Closed
	Jul 15, 2025	Jul 15, 2025		Jul 15, 2025 9:48 AM	Jul 15, 2025 9:50 AM

Line	Task	Parts	Labor	Total
1	✓ saddle crack	\$0.00	\$0.00	\$0.00
	Notes			
	LHS lift axle			
2	✓ Replace tire	\$0.00	\$0.00	\$0.00
	Notes			
	LH front tires			
3	✓ Trailer Brakes	\$0.00	\$0.00	\$0.00
	Notes			
	LH lift axle S-cam loose. Install new bushings and shim S-cam, new shoes			

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
Brake Shoes	Kropp Shop		1.0	\$0.00	\$0.00

4	✓ Bunk crack	\$0.00	\$0.00	\$0.00
	Notes			
	#5 RHS bunk crack			

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z6LM183241	5ZL977	

Type	Created	Scheduled	Due	Started	Closed
	Nov 5, 2025	Nov 5, 2025		Nov 6, 2025 10:22 AM	Nov 7, 2025 1:37 PM

Line	Task	Parts	Labor	Total
1	✓ Fucked lift axel tire	\$0.00	\$0.00	\$0.00
2	✓ Loose mud flap hanger	\$0.00	\$0.00	\$0.00
3	✓ Fucked up light box at the back	\$0.00	\$0.00	\$0.00
4	✓ Adjust all brakes	\$0.00	\$0.00	\$0.00
5	✓ Lift axle missing dust covers	\$0.00	\$0.00	\$0.00
6	✓ Dust cover missing on middle axle	\$0.00	\$0.00	\$0.00
7	✓ Lift axle broken on cross member	\$0.00	\$0.00	\$0.00
8	✓ Saddle crack on axle 2	\$0.00	\$0.00	\$0.00
9	✓ 8th axle right side rim fucked	\$0.00	\$0.00	\$0.00
10	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00
Part Cost				\$0.00
Labor				\$0.00
Subtotal				\$0.00
Tax 1 (0.0%)				\$0.00
Tax 2 (0.0%)				\$0.00
Credit				(\$0.00)
Total Cost				\$0.00

T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z6LM183241	5ZL977	

Type	Scheduled	Due	Started	Closed
	Nov 18, 2025		Nov 18, 2025 12:59 PM	Nov 18, 2025 12:59 PM

Line	Task			Parts	Labor	Total
1	✓ hub cap			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	hub cap	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z6LM183241	5ZL977	

Type	Scheduled	Due	Started	Closed
	Nov 30, 2025		Nov 30, 2025 12:11 PM	Nov 30, 2025 12:11 PM

Line	Task	Parts	Labor	Total
1	✓ Brake Connections <u>Notes</u> tie up chafing air lines	\$0.00	\$0.00	\$0.00
2	✓ Brakes <u>Notes</u> lh left slack fell of s cam	\$0.00	\$0.00	\$0.00
3	✓ Tires <u>Notes</u> fornt lh inside flat	\$0.00	\$0.00	\$0.00
4	✓ other <u>Notes</u> lift axle tie rod end lh	\$0.00	\$0.00	\$0.00
Part Cost				\$0.00
Labor				\$0.00
Subtotal				\$0.00
Tax 1 (0.0%)				\$0.00
Tax 2 (0.0%)				\$0.00
Credit				(\$0.00)
Total Cost				\$0.00

T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z6LM183241	5ZL977	

Type	Created	Scheduled	Due	Started	Closed
	Dec 12, 2025	Dec 12, 2025		Dec 13, 2025 8:20 AM	Dec 13, 2025 8:20 AM

Line	Task	Parts	Labor	Total
------	------	-------	-------	-------

1	✓ Coupling Devices	\$0.00	\$0.00	\$0.00
---	--------------------	--------	--------	--------

Notes

blue glad hand leaking

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
Glad hand blue	Kropp Shop		1.0	\$0.00	\$0.00

2	✓ Lights - All	\$0.00	\$0.00	\$0.00
---	----------------	--------	--------	--------

Notes

bunk #1 yellow 2" light out

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
2 wire pigtail	Kropp Shop		1.0	\$0.00	\$0.00

3	✓ other	\$0.00	\$0.00	\$0.00
---	---------	--------	--------	--------

Notes

#7 air bag line leaking left hand

4	✓ Suspension	\$0.00	\$0.00	\$0.00
---	--------------	--------	--------	--------

Notes

leveling valve bent

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z6LM183241	5ZL977	

Type	Created	Scheduled	Due	Started	Closed
	Jan 16, 2026	Jan 16, 2026		Jan 17, 2026 6:43 AM	Jan 17, 2026 6:43 AM

Line	Task	Parts	Labor	Total
1	✓ Centre 3 lights in the bumper out	\$0.00	\$0.00	\$0.00
	Part Cost			\$0.00
	Labor			\$0.00
	Subtotal			\$0.00
	Tax 1 (0.0%)			\$0.00
	Tax 2 (0.0%)			\$0.00
	Credit			(\$0.00)
	Total Cost			\$0.00

T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z6LM183241	5ZL977	

Type	Created	Scheduled	Due	Started	Closed
	Feb 1, 2026	Feb 1, 2026		Feb 2, 2026 7:58 AM	Feb 2, 2026 7:58 AM

Line	Task	Parts	Labor	Total		
1	✓ Brake Connections	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	Rh front dust cover mia					
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Clamp on dust cover	Kropp Shop		1.0	\$0.00	\$0.00
2	✓ Brakes	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	rh rear clevis nut loose					
3	✓ Lights - All	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	license plate light out					
4	✓ other	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	#4 wrapper handle broken					
		Part Cost		\$0.00		
		Labor		\$0.00		
		Subtotal		\$0.00		
		Tax 1 (0.0%)		\$0.00		
		Tax 2 (0.0%)		\$0.00		
		Credit		(\$0.00)		
		Total Cost		\$0.00		

T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z6LM183241	5ZL977	

Type	Created	Scheduled	Due	Started	Closed
	Feb 15, 2026	Feb 15, 2026		Feb 16, 2026 5:04 PM	Feb 16, 2026 5:04 PM

Line	Task	Parts	Labor	Total
1	✓ Hub Levels <u>Notes</u> lh rear hub low	\$0.00	\$0.00	\$0.00
2	✓ Lights - All <u>Notes</u> no lh signal	\$0.00	\$0.00	\$0.00
3	✓ Tires <u>Notes</u> front rh inside nfg, middle lh inside nfg	\$0.00	\$0.00	\$0.00
Part Cost				\$0.00
Labor				\$0.00
Subtotal				\$0.00
Tax 1 (0.0%)				\$0.00
Tax 2 (0.0%)				\$0.00
Credit				(\$0.00)
Total Cost				\$0.00

T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z6LM183241	5ZL977	

Type	Created	Scheduled	Due	Started	Closed
	Feb 25, 2026	Feb 25, 2026		Feb 25, 2026 4:06 PM	Feb 25, 2026 4:06 PM

Line	Task			Parts	Labor	Total
1	✓ Lost wheels replaced hub drum and brakes			\$486.00	\$0.00	\$486.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	10082225 - Con met trailer hub	Kropp Shop		1.0	\$486.00	\$486.00
	Brake Drum	Kropp Shop		1.0	\$0.00	\$0.00
	Q plus shoe kit	Kropp Shop		1.0	\$0.00	\$0.00
	245 Trailer - Trailer Tire	Kropp Shop		2.0	\$0.00	\$0.00
				Part Cost		\$486.00
				Labor		\$0.00
				Subtotal		\$486.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$486.00

T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z6LM183241	5ZL977	

Type	Created	Scheduled	Due	Started	Closed
	Feb 27, 2026	Feb 27, 2026		Mar 2, 2026 8:35 AM	Mar 2, 2026 8:35 AM

Line	Task	Parts	Labor	Total
1	✓ Loose u bolt on front right	\$0.00	\$0.00	\$0.00
2	✓ 2 loose shocks	\$0.00	\$0.00	\$0.00
3	✓ Missing dust cover	\$0.00	\$0.00	\$0.00
4	✓ Licence plate light	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z6LM183241	5ZL977	

Type	Created	Scheduled	Due	Started	Closed
	Mar 17, 2026	Mar 17, 2026		Mar 17, 2026 4:30 PM	Mar 19, 2026 4:29 PM

Line	Task	Parts	Labor	Total		
1	✓ ABS codes	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	Wire broke right hand					
2	✓ Brake Connections	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	Missing brake spring on middle axle right hand, dust cover ripped off					
3	✓ Saddle cracks	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	Front and back axles right side and u bolts loose					
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	RH beam	Kropp Shop		1.0	\$0.00	\$0.00
	S-24679 - Quick align pivot bolt	Kropp Shop		1.0	\$0.00	\$0.00
	S-21099 - Teflon washer	Kropp Shop		2.0	\$0.00	\$0.00
	U bolts	Kropp Shop		3.0	\$0.00	\$0.00
4	✓ Suspension	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	Leveling valve was frize					
5	✓ Wheels & Rims	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	Middle left outside rim cracked					

T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

6	✓ Left front hub cab changed plug	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z6LM183241	5ZL977	

Type	Scheduled	Due	Started	Closed
	Mar 27, 2026		Mar 27, 2026 4:14 AM	Mar 27, 2026 4:14 AM

Line	Task	Parts	Labor	Total
1	✓ Bunk #5 rh cracked weld a reinforced	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z6LM183241	5ZL977	

Type	Created	Scheduled	Due	Started	Closed
	May 19, 2026	May 19, 2026		May 22, 2026 2:19 PM	Jun 11, 2026 5:43 AM

Line	Task	Parts	Labor	Total
1	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00
2	✓ CVIP inspection (wheels off)	\$0.00	\$0.00	\$0.00
3	✓ change tires	\$0.00	\$0.00	\$0.00
4	✓ #2 rh stake	\$0.00	\$0.00	\$0.00
5	✓ abs wire	\$0.00	\$0.00	\$0.00
Notes				
Changed both sensor				
6	✓ wire lift axle	\$0.00	\$0.00	\$0.00
7	✓ lift axle dust cover lh	\$0.00	\$0.00	\$0.00
8	✓ lift axle brakes	\$0.00	\$0.00	\$0.00
9	✓ lift axle shocks	\$0.00	\$0.00	\$0.00
10	✓ lift axle cracks	\$0.00	\$0.00	\$0.00
11	✓ #5 bunk crack RH	\$0.00	\$0.00	\$0.00
12	✓ licence plate light	\$0.00	\$0.00	\$0.00
13	✓ lh bunk light out	\$0.00	\$0.00	\$0.00
14	✓ center marker 50% out	\$0.00	\$0.00	\$0.00
15	✓ no rh signal	\$0.00	\$0.00	\$0.00
16	✓ weld by midway marker	\$0.00	\$0.00	\$0.00

T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

17	✓ bunk 4 crack rh	\$0.00	\$0.00	\$0.00
18	✓ air leak on trailer	\$0.00	\$0.00	\$0.00
19	✓ middle axle lh slack pins	\$0.00	\$0.00	\$0.00
20	✓ middle rh slack cotter pin	\$0.00	\$0.00	\$0.00
21	✓ leveling rod bracket bent	\$0.00	\$0.00	\$0.00
22	✓ lh rear hub empty	\$0.00	\$0.00	\$0.00
23	✓ front lh hubcap cracked	\$0.00	\$0.00	\$0.00
24	✓ blue glad hand loose	\$0.00	\$0.00	\$0.00
25	✓ Front right airbag	\$0.00	\$0.00	\$0.00
26	✓ Wheel seal on back left axle	\$0.00	\$0.00	\$0.00
27	✓ S cam bushings	\$0.00	\$0.00	\$0.00
28	✓ On lift axel	\$0.00	\$0.00	\$0.00
29	✓ Scam bushing on middle right axle with new intrax tube	\$0.00	\$0.00	\$0.00
30	✓ S cam bushings on front left axel and new intrax tube	\$0.00	\$0.00	\$0.00

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00