

T239 - 2021 Peak hayrack

Parent: N123 - 2025 KENWORTH T880

CLOSED

Serial	Tag	Closed Meters
2A9145138MA003239	6PB993	

Type	Created	Scheduled	Due	Started	Closed
Cvip inspection	Apr 17, 2024	Apr 17, 2024		Apr 17, 2024 4:21 PM	Apr 17, 2024 4:22 PM

Line	Task	Parts	Labor	Total		
1	✓ Wheels off CVIP inspection	\$0.00	\$0.00	\$0.00		
2	✓ Install Lift axle	\$0.00	\$0.00	\$0.00		
3	✓ Wire lift axle switch	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	2 wire cord	Kropp Shop		3.0	\$0.00	\$0.00
	2 pin weather pack and pins	Kropp Shop		1.0	\$0.00	\$0.00
4	✓ install lift axle mud flap	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	2" x 1/4 angle	Kropp Shop		8.0	\$0.00	\$0.00
	belting	Kropp Shop		1.0	\$0.00	\$0.00
5	✓ install front axle mud flap	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	24" mudflap	Kropp Shop		2.0	\$0.00	\$0.00
6	✓ change lift axle plug 7 wire	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	7 wire female plug	Kropp Shop		1.0	\$0.00	\$0.00
7	✓ front RH marker light out on bunk	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	yellow penny light	Kropp Shop		1.0	\$0.00	\$0.00
8	✓ grease trailer	\$0.00	\$0.00	\$0.00		

Kropp Contracting
Shop

T239 - 2021 Peak hayrack

Parent: N123 - 2025 KENWORTH T880

Work Order 1067
Nate Vandenberghe, Trent Court

CLOSED

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T239 - 2021 Peak hayrack

Parent: N123 - 2025 KENWORTH T880

CLOSED

Serial	Tag	Closed Meters
2A9145138MA003239	6PB993	

Type	Created	Scheduled	Due	Started	Closed
	Apr 25, 2024	Apr 25, 2024		Apr 25, 2024 1:51 PM	Apr 26, 2024 9:05 PM

Line	Task	Parts	Labor	Total
1	✓ Diagnose and repair trailer scales	\$0.00	\$0.00	\$0.00

Notes

Changed suspension air gauge, took out vs 227 for a rapid response valve, adjusted ride height

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
4" pressure gauge	Kropp Shop		1.0	\$0.00	\$0.00
Rapid response levelling valve	Kropp Shop		1.0	\$0.00	\$0.00
48100267 - Leveling rod kit	Kropp Shop		1.0	\$0.00	\$0.00
Part Cost					\$0.00
Labor					\$0.00
Subtotal					\$0.00
Tax 1 (0.0%)					\$0.00
Tax 2 (0.0%)					\$0.00
Credit					(\$0.00)
Total Cost					\$0.00

T239 - 2021 Peak hayrack

Parent: N123 - 2025 KENWORTH T880

CLOSED

Serial	Tag	Closed Meters
2A9145138MA003239	6PB993	

Type	Scheduled	Due	Started	Closed
	Jul 9, 2024		Jul 9, 2024 6:16 AM	Jul 9, 2024 6:16 AM

Line	Task	Parts	Labor	Total
1	✓ Tires	\$0.00	\$0.00	\$0.00

Notes

RH #3 outside flat

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
Part Cost					\$0.00
Labor					\$0.00
Subtotal					\$0.00
Tax 1 (0.0%)					\$0.00
Tax 2 (0.0%)					\$0.00
Credit					(\$0.00)
Total Cost					\$0.00

T239 - 2021 Peak hayrack

Parent: N123 - 2025 KENWORTH T880

CLOSED

Serial	Tag	Closed Meters
2A9145138MA003239	6PB993	

Type	Scheduled	Due	Started	Closed
	Nov 2, 2024		Nov 2, 2024 1:42 PM	Nov 2, 2024 1:42 PM

Line	Task	Parts	Labor	Total
1	✓ ABS codes	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	Blink code 4			
2	✓ Suspension	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	Limit chains			
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

T239 - 2021 Peak hayrack

Parent: N123 - 2025 KENWORTH T880

CLOSED

Serial	Tag	Closed Meters
2A9145138MA003239	6PB993	

Type	Created	Scheduled	Due	Started	Closed
	Nov 30, 2024	Nov 30, 2024		Dec 9, 2024 4:10 AM	Dec 9, 2024 4:10 AM

Line	Task	Parts	Labor	Total
1	✓ Lights - All	\$0.00	\$0.00	\$0.00

Notes

LH signal out marker on LH light bar out

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T239 - 2021 Peak hayrack

Parent: N123 - 2025 KENWORTH T880

CLOSED

Serial	Tag	Closed Meters
2A9145138MA003239	6PB993	

Type	Scheduled	Due	Started	Closed
	Dec 14, 2024		Dec 14, 2024 2:23 PM	Dec 14, 2024 2:23 PM

Line	Task	Parts	Labor	Total
1	✓ Bunk cracks	\$0.00	\$0.00	\$0.00
	Notes			
	#5LH cracked			
2	✓ Hub Levels	\$0.00	\$0.00	\$0.00
	Notes			
	all low top up			
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

T239 - 2021 Peak hayrack

Parent: N123 - 2025 KENWORTH T880

CLOSED

Serial	Tag	Closed Meters
2A9145138MA003239	6PB993	

Type	Created	Scheduled	Due	Started	Closed
	Jan 6, 2025	Jan 6, 2025		Jan 6, 2025 5:58 AM	Jan 6, 2025 5:58 AM

Line	Task	Parts	Labor	Total
1	✓ Replace tire	\$0.00	\$0.00	\$0.00

Notes

#6LHS outside, rim bent

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T239 - 2021 Peak hayrack

Parent: N123 - 2025 KENWORTH T880

CLOSED

Serial	Tag	Closed Meters
2A9145138MA003239	6PB993	

Type	Created	Scheduled	Due	Started	Closed
	Jan 18, 2025	Jan 18, 2025		Jan 18, 2025 4:46 PM	Jan 18, 2025 4:46 PM

Line	Task	Parts	Labor	Total
1	✓ ABS codes	\$100.00	\$0.00	\$100.00

Notes

lh WSS

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
K181625 - 6' 90 ABS WSS	Kropp Shop		1.0	\$100.00	\$100.00

2	✓ Hub Levels	\$0.00	\$0.00	\$0.00
---	--------------	--------	--------	--------

Notes

top up LHM LHF

3	✓ Suspension	\$0.00	\$0.00	\$0.00
---	--------------	--------	--------	--------

Notes

LHF RHF shock bolts loose

Part Cost	\$100.00
Labor	\$0.00
Subtotal	\$100.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$100.00

T239 - 2021 Peak hayrack

Parent: N123 - 2025 KENWORTH T880

CLOSED

Serial	Tag	Closed Meters
2A9145138MA003239	6PB993	

Type	Scheduled	Due	Started	Closed
	Feb 2, 2025		Feb 2, 2025 6:55 PM	Feb 2, 2025 6:55 PM

Line	Task	Parts	Labor	Total
1	✓ Lights - All	\$0.00	\$0.00	\$0.00

Notes

bunk markers out penny lights

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
yellow penny light	Kropp Shop		3.0	\$0.00	\$0.00
Part Cost					\$0.00
Labor					\$0.00
Subtotal					\$0.00
Tax 1 (0.0%)					\$0.00
Tax 2 (0.0%)					\$0.00
Credit					(\$0.00)
Total Cost					\$0.00

T239 - 2021 Peak hayrack

Parent: N123 - 2025 KENWORTH T880

CLOSED

Serial	Tag	Closed Meters
2A9145138MA003239	6PB993	

Type	Created	Scheduled	Due	Started	Closed
	Feb 12, 2025	Feb 12, 2025		Feb 12, 2025 9:53 PM	Feb 12, 2025 9:53 PM

Line	Task	Parts	Labor	Total		
1	✓ ABS codes	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	Broken speed sensor					
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Speed sensor	Kropp Shop		1.0	\$0.00	\$0.00
2	✓ Brakes	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	contaminated shoes					
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Brake Shoes	Kropp Shop		1.0	\$0.00	\$0.00
3	✓ Hub Levels	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	LM, LF, RM, RR					
4	✓ other	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	LF wheel seal and speed sensor replace					
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	2110 wheel seal	Kropp Shop		1.0	\$0.00	\$0.00

Kropp Contracting
Shop

T239 - 2021 Peak hayrack

Parent: N123 - 2025 KENWORTH T880

Work Order 1678

Everett Twin

CLOSED

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T239 - 2021 Peak hayrack

Parent: N123 - 2025 KENWORTH T880

CLOSED

Serial	Tag	Closed Meters
2A9145138MA003239	6PB993	

Type	Created	Scheduled	Due	Started	Closed
	Mar 3, 2025	Mar 3, 2025		Mar 3, 2025 11:41 AM	Mar 3, 2025 11:41 AM

Line	Task	Parts	Labor	Total
1	✓ ABS codes	\$0.00	\$0.00	\$0.00

Notes

6 blink code

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
ABS ECU	Kropp Shop		1.0	\$0.00	\$0.00

2	✓ Tires	\$0.00	\$0.00	\$0.00
---	---------	--------	--------	--------

Notes

front LHO flat

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T239 - 2021 Peak hayrack

Parent: N123 - 2025 KENWORTH T880

CLOSED

Serial	Tag	Closed Meters
2A9145138MA003239	6PB993	

Type	Created	Scheduled	Due	Started	Closed
	Apr 3, 2025	Apr 3, 2025		Apr 4, 2025 2:38 PM	Apr 22, 2025 7:06 AM

Line	Task	Parts	Labor	Total		
1	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00		
2	✓ CVIP inspection (wheels off)	\$0.00	\$0.00	\$0.00		
3	✓ haldex adjuster bars missing	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Haldex bar kit	Kropp Shop		1.0	\$0.00	\$0.00
4	✓ haldex adjuster bushings MIA	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Haldex bushing kit	Kropp Shop		1.0	\$0.00	\$0.00
5	✓ limit chains hanging	\$0.00	\$0.00	\$0.00		
6	✓ Install lift axle	\$0.00	\$0.00	\$0.00		
7	✓ ABS codes	\$100.00	\$0.00	\$100.00		

Notes

Rh wheel speed sensor broken in spider mount

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
K181625 - 6' 90 ABS WSS	Kropp Shop		1.0	\$100.00	\$100.00

Part Cost	\$100.00
Labor	\$0.00
Subtotal	\$100.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$100.00

T239 - 2021 Peak hayrack

Parent: N123 - 2025 KENWORTH T880

CLOSED

Serial	Tag	Closed Meters
2A9145138MA003239	6PB993	

Type	Created	Scheduled	Due	Started	Closed
	Jul 25, 2025	Jul 25, 2025		Jul 25, 2025 10:59 AM	Jul 25, 2025 11:00 AM

Line	Task	Parts	Labor	Total
1	✓ Replace tire	\$0.00	\$0.00	\$0.00

Notes

LFI

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00

2	✓ Lights inop	\$0.00	\$0.00	\$0.00
---	---------------	--------	--------	--------

Notes

LHS midship marker light INOP.

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T239 - 2021 Peak hayrack

Parent: N123 - 2025 KENWORTH T880

CLOSED

Serial	Tag	Closed Meters
2A9145138MA003239	6PB993	

Type	Created	Scheduled	Due	Started	Closed
	Aug 11, 2025	Aug 11, 2025		Aug 12, 2025 5:54 AM	Aug 12, 2025 5:54 AM

Line	Task	Parts	Labor	Total
1	✓ Lights inop	\$0.00	\$0.00	\$0.00

Notes

Tail lamps on rear bumper inop. Replaced 7-wire female plug. Found rear lights operational. Found front bunk lights INOP afterwards. Found multiple splices with corrosion. Run new wires to front bunks and found bunk lights operational.

Note front right bunk light has voltage drop somewhere, only red light works and is dim

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
127-66793AB - 3/4" amber marker light	Kropp Shop		2.0	\$0.00	\$0.00
Part Cost					\$0.00
Labor					\$0.00
Subtotal					\$0.00
Tax 1 (0.0%)					\$0.00
Tax 2 (0.0%)					\$0.00
Credit					(\$0.00)
Total Cost					\$0.00

T239 - 2021 Peak hayrack

Parent: N123 - 2025 KENWORTH T880

CLOSED

Serial	Tag	Closed Meters
2A9145138MA003239	6PB993	

Type	Created	Scheduled	Due	Started	Closed
	Sep 16, 2025	Sep 16, 2025		Sep 16, 2025 7:01 PM	Sep 16, 2025 7:01 PM

Line	Task			Parts	Labor	Total
1	✓ Middle LH inside nfg			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

T239 - 2021 Peak hayrack

Parent: N123 - 2025 KENWORTH T880

CLOSED

Serial	Tag	Closed Meters
2A9145138MA003239	6PB993	

Type	Scheduled	Due	Started	Closed
	Nov 14, 2025		Nov 14, 2025 5:06 PM	Nov 14, 2025 5:06 PM

Line	Task	Parts	Labor	Total
1	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

T239 - 2021 Peak hayrack

Parent: N123 - 2025 KENWORTH T880

CLOSED

Serial	Tag	Closed Meters
2A9145138MA003239	6PB993	

Type	Created	Scheduled	Due	Started	Closed
	Dec 13, 2025	Dec 13, 2025		Dec 13, 2025 6:13 PM	Dec 13, 2025 6:13 PM

Line	Task	Parts	Labor	Total
1	✓ Brakes	\$0.00	\$0.00	\$0.00
	Notes			
	middle axle slack bushings mia			
2	✓ other	\$0.00	\$0.00	\$0.00
	Notes			
	limit chains hanging fron rh rear axle			
3	✓ Tires	\$0.00	\$0.00	\$0.00
	Notes			
	lh rear inside flat			
Part Cost				\$0.00
Labor				\$0.00
Subtotal				\$0.00
Tax 1 (0.0%)				\$0.00
Tax 2 (0.0%)				\$0.00
Credit				(\$0.00)
Total Cost				\$0.00

Kropp Contracting
Shop

T239 - 2021 Peak hayrack

Parent: N123 - 2025 KENWORTH T880

Work Order 2385

Sam Hawksley

CLOSED

Serial	Tag	Closed Meters
2A9145138MA003239	6PB993	

Type	Created	Scheduled	Due	Started	Closed
	Dec 16, 2025	Dec 16, 2025		Dec 19, 2025 9:29 AM	Dec 19, 2025 9:29 AM

Line	Task	Parts	Labor	Total
1	✓ Wrapper handle #4,#6	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

T239 - 2021 Peak hayrack

Parent: N123 - 2025 KENWORTH T880

Work Order 2419

Sam Hawksley

CLOSED

Serial	Tag	Closed Meters
2A9145138MA003239	6PB993	

Type	Created	Scheduled	Due	Started	Closed
	Jan 4, 2026	Jan 4, 2026		Jan 8, 2026 5:56 AM	Jan 8, 2026 5:56 AM

Line	Task	Parts	Labor	Total
1	✓ Tightened leveling valve	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

T239 - 2021 Peak hayrack

Parent: N123 - 2025 KENWORTH T880

CLOSED

Serial	Tag	Closed Meters
2A9145138MA003239	6PB993	

Type	Created	Scheduled	Due	Started	Closed
	Jan 14, 2026	Jan 14, 2026		Jan 14, 2026 5:38 PM	Jan 14, 2026 5:38 PM

Line	Task	Parts	Labor	Total
1	✓ Scale issues	\$0.00	\$0.00	\$0.00
	Notes			
	Switch supply air from dump valve back to air bags			
2	✓ Flat tire on #7	\$0.00	\$0.00	\$0.00
	Part Cost			\$0.00
	Labor			\$0.00
	Subtotal			\$0.00
	Tax 1 (0.0%)			\$0.00
	Tax 2 (0.0%)			\$0.00
	Credit			(\$0.00)
	Total Cost			\$0.00

T239 - 2021 Peak hayrack

Parent: N123 - 2025 KENWORTH T880

CLOSED

Serial	Tag	Closed Meters
2A9145138MA003239	6PB993	

Type	Scheduled	Due	Started	Closed
	Jan 31, 2026		Jan 31, 2026 7:01 AM	Jan 31, 2026 7:01 AM

Line	Task	Parts	Labor	Total
1	✓ Brake Connections	\$0.00	\$0.00	\$0.00
	Notes			
	front axle service line leak			
2	✓ Hub Levels	\$0.00	\$0.00	\$0.00
	Notes			
	rh rear front rh hub low			
3	✓ other	\$0.00	\$0.00	\$0.00
	Notes			
	#6 wrapper handle mia			
Part Cost				\$0.00
Labor				\$0.00
Subtotal				\$0.00
Tax 1 (0.0%)				\$0.00
Tax 2 (0.0%)				\$0.00
Credit				(\$0.00)
Total Cost				\$0.00

T239 - 2021 Peak hayrack

Parent: N123 - 2025 KENWORTH T880

Serial	Tag	Closed Meters
2A9145138MA003239	6PB993	

Type	Created	Scheduled	Due	Started	Closed
	Feb 13, 2026	Feb 13, 2026		Feb 15, 2026 10:11 AM	Feb 15, 2026 10:11 AM

Line	Task	Parts	Labor	Total												
1	✓ Brakes	\$0.00	\$0.00	\$0.00												
	<u>Notes</u>															
	Rh axle brakes all wore out															
	<table><tr><th>Part</th><th>Warehouse</th><th>Vendor/Bin</th><th>Qty</th><th>Unit Cost</th><th>Cost</th></tr><tr><td>Q plus shoe kit</td><td>Kropp Shop</td><td></td><td>3.0</td><td>\$0.00</td><td>\$0.00</td></tr></table>	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost	Q plus shoe kit	Kropp Shop		3.0	\$0.00	\$0.00			
Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost											
Q plus shoe kit	Kropp Shop		3.0	\$0.00	\$0.00											
2	✓ Tires	\$0.00	\$0.00	\$0.00												
	<u>Notes</u>															
	LH rear inside flat															
	<table><tr><th>Part</th><th>Warehouse</th><th>Vendor/Bin</th><th>Qty</th><th>Unit Cost</th><th>Cost</th></tr><tr><td>245 Trailer - Trailer Tire</td><td>Kropp Shop</td><td></td><td>1.0</td><td>\$0.00</td><td>\$0.00</td></tr></table>	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost	245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00			
Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost											
245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00											
3	✓ And wheel speed sensor middle lh	\$100.00	\$0.00	\$100.00												
	<table><tr><th>Part</th><th>Warehouse</th><th>Vendor/Bin</th><th>Qty</th><th>Unit Cost</th><th>Cost</th></tr><tr><td>K181625 - 6' 90 ABS WSS</td><td>Kropp Shop</td><td></td><td>1.0</td><td>\$100.00</td><td>\$100.00</td></tr></table>	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost	K181625 - 6' 90 ABS WSS	Kropp Shop		1.0	\$100.00	\$100.00			
Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost											
K181625 - 6' 90 ABS WSS	Kropp Shop		1.0	\$100.00	\$100.00											
4	✓ Rh rear bunk light out	\$0.00	\$0.00	\$0.00												
		Part Cost		\$100.00												
		Labor		\$0.00												
		Subtotal		\$100.00												
		Tax 1 (0.0%)		\$0.00												
		Tax 2 (0.0%)		\$0.00												
		Credit		(\$0.00)												
		Total Cost		\$100.00												

T239 - 2021 Peak hayrack

Parent: N123 - 2025 KENWORTH T880

CLOSED

Serial	Tag	Closed Meters
2A9145138MA003239	6PB993	

Type	Created	Scheduled	Due	Started	Closed
	Feb 26, 2026	Feb 26, 2026		Mar 2, 2026 8:35 AM	Mar 2, 2026 8:35 AM

Line	Task	Parts	Labor	Total
1	✓ Brake Connections	\$0.00	\$0.00	\$0.00
	Notes			
	adjuster bars			
2	✓ Lights - All	\$0.00	\$0.00	\$0.00
	Notes			
	back rh penny light out			
Part Cost				\$0.00
Labor				\$0.00
Subtotal				\$0.00
Tax 1 (0.0%)				\$0.00
Tax 2 (0.0%)				\$0.00
Credit				(\$0.00)
Total Cost				\$0.00

T239 - 2021 Peak hayrack

Parent: N123 - 2025 KENWORTH T880

Work Order 2684

Aiden Kenny

CLOSED

Serial	Tag	Closed Meters
2A9145138MA003239	6PB993	

Type	Scheduled	Due	Started	Closed
	Apr 14, 2026		Apr 14, 2026 6:34 PM	Apr 14, 2026 6:34 PM

Line	Task	Parts	Labor	Total
1	✓ Front LH inside flat	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

T239 - 2021 Peak hayrack

Parent: N123 - 2025 KENWORTH T880

Serial	Tag	Current Meters
2A9145138MA003239	6PB993	

Type	Created	Scheduled	Due	Started	Closed
	Jul 10, 2026	Jul 10, 2026		Jul 14, 2026 10:23 AM	

Line	Task	Parts	Labor	Total
1	✓ CVIP inspection (wheels off)	\$0.00	\$0.00	\$0.00
2	✓ Bunk 2 5 and 6 broke	\$0.00	\$0.00	\$0.00
3	✓ Bunk lights out	\$0.00	\$0.00	\$0.00
4	✓ Brake job back left axle	\$0.00	\$0.00	\$0.00
5	✓ Service valve leaking	\$0.00	\$0.00	\$0.00
6	✓ 2 dust covers	\$0.00	\$0.00	\$0.00
7	✓ Inside front left axle tire is weather cracked badly	\$0.00	\$0.00	\$0.00
8	✓ No license plate light	\$0.00	\$0.00	\$0.00
9	✓ Flat spot on middle right hand axle	\$0.00	\$0.00	\$0.00
10	✓ Middle left hand and back left hand hubs low	\$0.00	\$0.00	\$0.00
11	✓ Bunk 6 cracked	\$0.00	\$0.00	\$0.00
12	✓ Limit chains	\$0.00	\$0.00	\$0.00
13	✓ Suspension airline	\$0.00	\$0.00	\$0.00
14	✓ Marker light right hand midway out	\$0.00	\$0.00	\$0.00
15	✓ Flat tire middle right out sude	\$0.00	\$0.00	\$0.00
16	✓ Abs	\$0.00	\$0.00	\$0.00
17	✓ Tie up wires along frame	\$0.00	\$0.00	\$0.00
18	✓ Supply valve dumping all air	\$0.00	\$0.00	\$0.00

Kropp Contracting
Shop

T239 - 2021 Peak hayrack

Parent: N123 - 2025 KENWORTH T880

Work Order 2760
Sam Hawksley
Status: In Progress

19	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00