

T436 - 2015 Peerless

Serial	Tag	Closed Meters
2PLB04840FBL17436	5WZ971	

Type	Scheduled	Due	Started	Closed
	Mar 9, 2024		Mar 9, 2024 7:22 PM	Mar 9, 2024 7:22 PM

Line	Task	Parts	Labor	Total
1	✓ Tires	\$0.00	\$0.00	\$0.00

Notes

no leak found just low
#6 outside low check for leak

Part Cost	\$0.00
Labor	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T436 - 2015 Peerless

CLOSED

Serial	Tag	Closed Meters
2PLB04840FBL17436	5WZ971	

Type	Created	Scheduled	Due	Started	Closed
	May 6, 2024	May 6, 2024		May 9, 2024 7:17 AM	May 10, 2024 11:04 AM

Line	Task	Parts	Labor	Total		
1	✓ Wheels off CVIP inspection	\$0.00	\$0.00	\$0.00		
2	✓ saddle crack	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	Middle LH and bolts loose					
	Front LH crack					
3	✓ Front LH dust cover cracked	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Clamp on dust cover	Kropp Shop		1.0	\$0.00	\$0.00
4	✓ Junction box middle of trailer broke wires exposed	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Round junction box	Kropp Shop		1.0	\$0.00	\$0.00
5	✓ Leveling valve no goid	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Rapid response levelling valve	Kropp Shop		1.0	\$0.00	\$0.00
6	✓ Replace tire	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	Rear RH inside					
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
7	✓ RH rear marker light out in light bar	\$0.00	\$0.00	\$0.00		
8	✓ Cracked stake pocket #3 RH	\$0.00	\$0.00	\$0.00		

T436 - 2015 Peerless

CLOSED

9	✓ Cracked stake pocket #4 RH	\$0.00	\$0.00	\$0.00
10	✓ Install lift axle	\$0.00	\$0.00	\$0.00
11	✓ Lift air bag LH fitting loose	\$0.00	\$0.00	\$0.00
12	✓ Quick release valve on lift axle no good	\$0.00	\$0.00	\$0.00

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
QR-1 - Quick release valve	Kropp Shop		1.0	\$0.00	\$0.00

Part Cost	\$0.00
Labor	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T436 - 2015 Peerless

Serial	Tag	Closed Meters
2PLB04840FBL17436	5WZ971	

Type	Created	Scheduled	Due	Started	Closed
	May 31, 2024	May 31, 2024		May 31, 2024 6:07 AM	May 31, 2024 6:07 AM

Line	Task	Parts	Labor	Total
1	✓ Tires	\$0.00	\$0.00	\$0.00

Notes

RH lift axle outside tire showing cords

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
22.5 trailer tire	Kropp Shop		1.0	\$0.00	\$0.00
Part Cost					\$0.00
Labor					\$0.00
Tax 1 (0.0%)					\$0.00
Tax 2 (0.0%)					\$0.00
Credit					(\$0.00)
Total Cost					\$0.00

T436 - 2015 Peerless

Serial	Tag	Closed Meters
2PLB04840FBL17436	5WZ971	

Type	Created	Scheduled	Due	Started	Closed
	Jul 10, 2024	Jul 10, 2024		Jul 10, 2024 4:29 AM	Jul 10, 2024 4:29 AM

Line	Task			Parts	Labor	Total
1	✓ Lift axle tire			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	22.5 trailer tire	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

T436 - 2015 Peerless

Serial	Tag	Closed Meters
2PLB04840FBL17436	5WZ971	

Type	Scheduled	Due	Started	Closed
	Jul 12, 2024		Jul 12, 2024 7:25 AM	Jul 12, 2024 7:25 AM

Line	Task			Parts	Labor	Total
1	✓ Rh front outside tire flat			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

T436 - 2015 Peerless

Serial	Tag	Closed Meters
2PLB04840FBL17436	5WZ971	

Type	Created	Scheduled	Due	Started	Closed
	Jul 23, 2024	Jul 23, 2024		Jul 23, 2024 3:07 AM	Jul 23, 2024 3:07 AM

Line	Task	Parts	Labor	Total
1	✓ Replace tire	\$0.00	\$0.00	\$0.00

Notes

RH inside lift axle tire wore out

Part Cost	\$0.00
Labor	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T436 - 2015 Peerless

Serial	Tag	Closed Meters
2PLB04840FBL17436	5WZ971	

Type	Scheduled	Due	Started	Closed
	Sep 4, 2024		Sep 4, 2024 12:04 PM	Sep 4, 2024 12:04 PM

Line	Task	Parts	Labor	Total
------	------	-------	-------	-------

1	✓ Lights - All	\$0.00	\$0.00	\$0.00
---	----------------	--------	--------	--------

Notes

License plate light out

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
licence plate light	Kropp Shop		1.0	\$0.00	\$0.00

2	✓ Saddle cracks	\$0.00	\$0.00	\$0.00
---	-----------------	--------	--------	--------

Notes

Weld crack

Back LH saddle crack

Part Cost	\$0.00
Labor	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T436 - 2015 Peerless

CLOSED

Serial	Tag	Closed Meters
2PLB04840FBL17436	5WZ971	

Type	Scheduled	Due	Started	Closed
	Oct 20, 2024		Oct 20, 2024 3:35 PM	Oct 20, 2024 3:35 PM

Line	Task	Parts	Labor	Total												
1	✓ ABS codes	\$100.00	\$0.00	\$100.00												
	<u>Notes</u>															
	6 blink code															
	<table><tr><th>Part</th><th>Warehouse</th><th>Vendor/Bin</th><th>Qty</th><th>Unit Cost</th><th>Cost</th></tr><tr><td>K181625 - 6' 90 ABS WSS</td><td>Kropp Shop</td><td></td><td>1.0</td><td>\$100.00</td><td>\$100.00</td></tr></table>	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost	K181625 - 6' 90 ABS WSS	Kropp Shop		1.0	\$100.00	\$100.00			
Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost											
K181625 - 6' 90 ABS WSS	Kropp Shop		1.0	\$100.00	\$100.00											
2	✓ Lights - All	\$0.00	\$0.00	\$0.00												
	<u>Notes</u>															
	rear marker lights out															
3	✓ Suspension	\$0.00	\$0.00	\$0.00												
	<u>Notes</u>															
	middle rh shock loose lh back shock loose															
4	✓ Tires	\$0.00	\$0.00	\$0.00												
	<u>Notes</u>															
	rear rh outside nfg															
	<table><tr><th>Part</th><th>Warehouse</th><th>Vendor/Bin</th><th>Qty</th><th>Unit Cost</th><th>Cost</th></tr><tr><td>245 Trailer - Trailer Tire</td><td>Kropp Shop</td><td></td><td>1.0</td><td>\$0.00</td><td>\$0.00</td></tr></table>	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost	245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00			
Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost											
245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00											
				Part Cost	\$100.00											
				Labor	\$0.00											
				Tax 1 (0.0%)	\$0.00											
				Tax 2 (0.0%)	\$0.00											
				Credit	(\$0.00)											
				Total Cost	\$100.00											

T436 - 2015 Peerless

Serial	Tag	Closed Meters
2PLB04840FBL17436	5WZ971	

Type	Created	Scheduled	Due	Started	Closed
	Nov 2, 2024	Nov 2, 2024		Nov 2, 2024 10:39 PM	Nov 2, 2024 10:39 PM

Line	Task	Parts	Labor	Total
1	✓ Suspension	\$0.00	\$0.00	\$0.00

Notes

Rear LH shock no good

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
S-20126 - Trailer shock	Kropp Shop		1.0	\$0.00	\$0.00

2	✓ Tires	\$0.00	\$0.00	\$0.00
---	---------	--------	--------	--------

Notes

Middle LH inside nfg

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00

Part Cost	\$0.00
Labor	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T436 - 2015 Peerless

Serial	Tag	Closed Meters
2PLB04840FBL17436	5WZ971	

Type	Created	Scheduled	Due	Started	Closed
	Nov 16, 2024	Nov 16, 2024		Nov 16, 2024 11:59 AM	Nov 16, 2024 11:59 AM

Line	Task	Parts	Labor	Total
1	✓ rear axle air bag bolt RH	\$0.00	\$0.00	\$0.00
2	✓ rear axle LH saddle cracked	\$0.00	\$0.00	\$0.00
3	✓ rear axle air bag bolt LH loose	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

T436 - 2015 Peerless

CLOSED

Serial	Tag	Closed Meters
2PLB04840FBL17436	5WZ971	

Type	Created	Scheduled	Due	Started	Closed
	Nov 16, 2024	Nov 16, 2024		Nov 16, 2024 3:41 PM	Nov 16, 2024 3:41 PM

Line	Task	Parts	Labor	Total		
1	✓ Rear LH saddle crack	\$0.00	\$0.00	\$0.00		
2	✓ Licence plate light out	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	licence plate light	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

T436 - 2015 Peerless

Serial	Tag	Closed Meters
2PLB04840FBL17436	5WZ971	

Type	Scheduled	Due	Started	Closed
	Jan 17, 2025		Jan 17, 2025 11:24 AM	Jan 17, 2025 11:24 AM

Line	Task	Parts	Labor	Total
1	✓ ABS codes <u>Notes</u> light on	\$0.00	\$0.00	\$0.00
2	✓ Hub Levels <u>Notes</u> rear axle low	\$0.00	\$0.00	\$0.00
3	✓ Saddle cracks <u>Notes</u> middle LH cracked	\$0.00	\$0.00	\$0.00
Part Cost				\$0.00
Labor				\$0.00
Tax 1 (0.0%)				\$0.00
Tax 2 (0.0%)				\$0.00
Credit				(\$0.00)
Total Cost				\$0.00

T436 - 2015 Peerless

Serial	Tag	Closed Meters
2PLB04840FBL17436	5WZ971	

Type	Created	Scheduled	Due	Started	Closed
	Feb 1, 2025	Feb 1, 2025		Feb 1, 2025 5:10 PM	Feb 1, 2025 5:10 PM

Line	Task	Parts	Labor	Total
1	✓ Brakes	\$0.00	\$0.00	\$0.00

Notes

lh rear axle brakes nfg

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
Q plus shoe kit	Kropp Shop		1.0	\$0.00	\$0.00

2	✓ Lights - All	\$0.00	\$0.00	\$0.00
---	----------------	--------	--------	--------

Notes

rh front bunk markers out

3	✓ other	\$0.00	\$0.00	\$0.00
---	---------	--------	--------	--------

Notes

middle lh dust cover MIA

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
Clamp on dust cover	Kropp Shop		1.0	\$0.00	\$0.00

Part Cost	\$0.00
Labor	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T436 - 2015 Peerless

Serial	Tag	Closed Meters
2PLB04840FBL17436	5WZ971	

Type	Scheduled	Due	Started	Closed
	Feb 12, 2025		Feb 12, 2025 9:25 PM	Feb 12, 2025 9:25 PM

Line	Task	Parts	Labor	Total
1	✓ Suspension	\$0.00	\$0.00	\$0.00

Notes

Rear LH u bolt loose rear air bag bolt broke

Part Cost	\$0.00
Labor	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T436 - 2015 Peerless

CLOSED

Serial	Tag	Closed Meters
2PLB04840FBL17436	5WZ971	

Type	Scheduled	Due	Started	Closed
	Feb 17, 2025		Feb 17, 2025 7:26 PM	Feb 17, 2025 7:26 PM

Line	Task	Parts	Labor	Total		
1	✓ Middle LH outside flat	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

T436 - 2015 Peerless

Serial	Tag	Closed Meters
2PLB04840FBL17436	5WZ971	

Type	Created	Scheduled	Due	Started	Closed
	Mar 3, 2025	Mar 3, 2025		Mar 3, 2025 11:27 AM	Mar 3, 2025 11:27 AM

Line	Task	Parts	Labor	Total
1	✓ Hub Levels <u>Notes</u> front and rear axle both sides low	\$0.00	\$0.00	\$0.00
2	✓ Lights - All <u>Notes</u> bunk markers out	\$0.00	\$0.00	\$0.00
3	✓ other <u>Notes</u> rear LH inner bag bolt	\$0.00	\$0.00	\$0.00
4	✓ Saddle cracks <u>Notes</u> front LH crack	\$0.00	\$0.00	\$0.00
Part Cost				\$0.00
Labor				\$0.00
Tax 1 (0.0%)				\$0.00
Tax 2 (0.0%)				\$0.00
Credit				(\$0.00)
Total Cost				\$0.00

T436 - 2015 Peerless

CLOSED

Serial	Tag	Closed Meters
2PLB04840FBL17436	5WZ971	

Type	Created	Scheduled	Due	Started	Closed
	May 6, 2025	May 6, 2025		May 15, 2025 7:02 AM	May 22, 2025 4:49 AM

Line	Task	Parts	Labor	Total		
1	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00		
2	✓ Marker light(s) INOP	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	LR bunk light					
3	✓ ABS codes	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	RM ABS wire chafed					
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	K181265 - Wheel speed sensor	Kropp Shop		1.0	\$0.00	\$0.00
4	✓ Trailer Brakes	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	Middle axle and RR					
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Brake Shoes	Kropp Shop		3.0	\$0.00	\$0.00
	Brake Drum	Kropp Shop		2.0	\$0.00	\$0.00
5	✓ Replace tire	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	RFO					
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
6	✓ Broken Crossmember	\$0.00	\$0.00	\$0.00		

T436 - 2015 Peerless

CLOSED

Notes

Tube #4 cracked and dolly leg cross member cracked

Technician	Hours	Rate	Cost
Everett Twin	0.0	\$0.00	\$0.00
7 ✓ saddle crack	\$0.00	\$0.00	\$0.00

Notes

RF, LM, LR, & RR

8 ✓ Haldex bar bushing missing	\$0.00	\$0.00	\$0.00
--------------------------------	--------	--------	--------

Notes

RF&RR

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
Haldex bar kit	Kropp Shop		2.0	\$0.00	\$0.00
9 ✓ air bag bracket cracked			\$150.00	\$0.00	\$150.00

Notes

LF

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
8050 air bag	Kropp Shop		1.0	\$150.00	\$150.00
10 ✓ Wheel seal leaking			\$0.00	\$0.00	\$0.00

Notes

RR

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
2110 wheel seal	Kropp Shop		1.0	\$0.00	\$0.00
Con met trailer hub	Kropp Shop		1.0	\$0.00	\$0.00
11 ✓ License plate light			\$0.00	\$0.00	\$0.00

Notes

Hanging

12 ✓ Rubber air lines	\$0.00	\$0.00	\$0.00
-----------------------	--------	--------	--------

Notes

T436 - 2015 Peerless

CLOSED

LR service line NFG, chafed into reinforcement layer

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
Hab 8 72 fs - Rubber air brake service 72" long	Kropp Shop		1.0	\$0.00	\$0.00

13 ✓ Trailer Brakes \$0.00 \$0.00 \$0.00

Notes

LH lift axle

14 ✓ Bent S-cam/tube \$0.00 \$0.00 \$0.00

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
X038 RHS S cam - X038 RHS S cam	Kropp Shop		1.0	\$0.00	\$0.00
X039 - CC S cam tube	Kropp Shop		1.0	\$0.00	\$0.00

15 ✓ Air bag bracket \$0.00 \$0.00 \$0.00

Notes

Weld new bracket onto saddle

Part Cost	\$150.00
Labor	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$150.00

T436 - 2015 Peerless

CLOSED

Serial	Tag	Closed Meters
2PLB04840FBL17436	5WZ971	

Type	Scheduled	Due	Started	Closed
Cvip inspection	Jun 2, 2025		Jun 2, 2025 4:10 AM	Jun 2, 2025 4:10 AM

Line	Task	Parts	Labor	Total
1	✓ CVIP inspection (wheels off)	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

T436 - 2015 Peerless

CLOSED

Serial	Tag	Closed Meters
2PLB04840FBL17436	5WZ971	

Type	Created	Scheduled	Due	Started	Closed
	Jun 23, 2025	Jun 23, 2025		Jun 23, 2025 4:50 PM	Jun 23, 2025 5:01 PM

Line	Task	Parts	Labor	Total		
1	✓ Replace shock	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	S-20126 - Trailer shock	Kropp Shop		1.0	\$0.00	\$0.00
2	✓ saddle crack	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	LF&RR trailer					
3	✓ Hub leaking	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	RF hub leaking, tighten bolts and top up bearing oil					
		Part Cost				\$0.00
		Labor				\$0.00
		Tax 1 (0.0%)				\$0.00
		Tax 2 (0.0%)				\$0.00
		Credit				(\$0.00)
		Total Cost				\$0.00

T436 - 2015 Peerless

CLOSED

Serial	Tag	Closed Meters
2PLB04840FBL17436	5WZ971	

Type	Created	Scheduled	Due	Started	Closed
	Jul 15, 2025	Jul 15, 2025		Jul 16, 2025 2:37 PM	Jul 16, 2025 2:37 PM

Line	Task	Parts	Labor	Total
1	✓ saddle crack	\$0.00	\$0.00	\$0.00
2	✓ Brake shoe	\$0.00	\$0.00	\$0.00
3	✓ RH lift axle S cam bushing	\$0.00	\$0.00	\$0.00
4	✓ Check and replace lift axle shocks if needed	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

T436 - 2015 Peerless

CLOSED

Serial	Tag	Closed Meters
2PLB04840FBL17436	5WZ971	

Type	Scheduled	Due	Started	Closed
	Aug 22, 2025		Aug 22, 2025 6:56 PM	Aug 22, 2025 6:56 PM

Line	Task	Parts	Labor	Total
1	✓ Changed left hand lift axel bag	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

T436 - 2015 Peerless

CLOSED

Serial	Tag	Closed Meters
2PLB04840FBL17436	5WZ971	

Type	Created	Scheduled	Due	Started	Closed
	Sep 8, 2025	Sep 8, 2025		Sep 8, 2025 5:37 AM	Sep 8, 2025 5:37 AM

Line	Task	Parts	Labor	Total
1	✓ Replace tire	\$0.00	\$0.00	\$0.00

Notes

L/H rear tires, 2 tires

Part Cost	\$0.00
Labor	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T436 - 2015 Peerless

CLOSED

Serial	Tag	Closed Meters
2PLB04840FBL17436	5WZ971	

Type	Created	Scheduled	Due	Started	Closed
	Sep 30, 2025	Sep 30, 2025		Sep 30, 2025 5:40 PM	Sep 30, 2025 5:40 PM

Line	Task	Parts	Labor	Total
1	✓ RH middle inside tire nfg	\$0.00	\$0.00	\$0.00
2	✓ Check lift axle power	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

T436 - 2015 Peerless

CLOSED

Serial	Tag	Closed Meters
2PLB04840FBL17436	5WZ971	

Type	Created	Scheduled	Due	Started	Closed
	Oct 3, 2025	Oct 3, 2025		Oct 3, 2025 1:42 PM	Oct 3, 2025 1:54 PM

Line	Task	Parts	Labor	Total
1	✓ ABS codes	\$0.00	\$0.00	\$0.00
2	✓ Bunk bolts	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	#2 loose			
3	✓ Hub Levels	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	Low			
4	✓ Hanger cracks	\$0.00	\$0.00	\$0.00
5	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

T436 - 2015 Peerless

Serial	Tag	Closed Meters
2PLB04840FBL17436	5WZ971	

Type	Created	Scheduled	Due	Started	Closed
	Nov 17, 2025	Nov 17, 2025		Nov 17, 2025 6:20 PM	Nov 17, 2025 6:20 PM

Line	Task	Parts	Labor	Total
1	✓ Broken rim	\$0.00	\$0.00	\$0.00

Notes

Front LH outside

Part Cost	\$0.00
Labor	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T436 - 2015 Peerless

CLOSED

Serial	Tag	Closed Meters
2PLB04840FBL17436	5WZ971	

Type	Scheduled	Due	Started	Closed
	Dec 1, 2025		Dec 1, 2025 5:34 PM	Dec 1, 2025 5:34 PM

Line	Task	Parts	Labor	Total
1	✓ Brake Connections	\$0.00	\$0.00	\$0.00

Notes

mid rh brake pot nfg

2	✓ Hub Levels	\$0.00	\$0.00	\$0.00
---	--------------	--------	--------	--------

Notes

middle and rear rh low

Part Cost	\$0.00
Labor	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T436 - 2015 Peerless

CLOSED

Serial	Tag	Closed Meters
2PLB04840FBL17436	5WZ971	

Type	Created	Scheduled	Due	Started	Closed
	Dec 2, 2025	Dec 2, 2025		Dec 5, 2025 6:19 PM	Dec 5, 2025 6:19 PM

Line	Task	Parts	Labor	Total
1	✓ Installed new bolt in front mudflap hanger	\$0.00	\$0.00	\$0.00
	Part Cost			\$0.00
	Labor			\$0.00
	Tax 1 (0.0%)			\$0.00
	Tax 2 (0.0%)			\$0.00
	Credit			(\$0.00)
	Total Cost			\$0.00

T436 - 2015 Peerless

CLOSED

Serial	Tag	Closed Meters
2PLB04840FBL17436	5WZ971	

Type	Created	Scheduled	Due	Started	Closed
	Dec 2, 2025	Dec 2, 2025		Dec 5, 2025 6:20 PM	Dec 5, 2025 6:20 PM

Line	Task	Parts	Labor	Total
1	✓ Replaced mudflap bolt	\$0.00	\$0.00	\$0.00
	Part Cost			\$0.00
	Labor			\$0.00
	Tax 1 (0.0%)			\$0.00
	Tax 2 (0.0%)			\$0.00
	Credit			(\$0.00)
	Total Cost			\$0.00

T436 - 2015 Peerless

CLOSED

Serial	Tag	Closed Meters
2PLB04840FBL17436	5WZ971	

Type	Created	Scheduled	Due	Started	Closed
	Dec 14, 2025	Dec 14, 2025		Dec 14, 2025 5:58 PM	Dec 14, 2025 5:58 PM

Line	Task	Parts	Labor	Total
1	✓ Hub Levels	\$0.00	\$0.00	\$0.00
	Notes			
	#7 and #6 left hand hubs			
2	✓ Suspension	\$0.00	\$0.00	\$0.00
	Notes			
	lift axle air line leaking			
3	✓ Tires	\$0.00	\$0.00	\$0.00
	Notes			
	#7 right hand inside			
Part Cost				\$0.00
Labor				\$0.00
Tax 1 (0.0%)				\$0.00
Tax 2 (0.0%)				\$0.00
Credit				(\$0.00)
Total Cost				\$0.00

T436 - 2015 Peerless

CLOSED

Serial	Tag	Closed Meters
2PLB04840FBL17436	5WZ971	

Type	Created	Scheduled	Due	Started	Closed
	Jan 2, 2026	Jan 2, 2026		Jan 4, 2026 8:16 AM	Jan 4, 2026 8:16 AM

Line	Task	Parts	Labor	Total
1	✓ Weld rh front brake pot bracket back on	\$0.00	\$0.00	\$0.00
	Part Cost			\$0.00
	Labor			\$0.00
	Tax 1 (0.0%)			\$0.00
	Tax 2 (0.0%)			\$0.00
	Credit			(\$0.00)
	Total Cost			\$0.00

T436 - 2015 Peerless

CLOSED

Serial	Tag	Closed Meters
2PLB04840FBL17436	5WZ971	

Type	Created	Scheduled	Due	Started	Closed
	Jan 4, 2026	Jan 4, 2026		Jan 8, 2026 5:56 AM	Jan 8, 2026 5:56 AM

Line	Task	Parts	Labor	Total
1	✓ Weld bunk pocket passenger side last bunk	\$0.00	\$0.00	\$0.00
	Part Cost			\$0.00
	Labor			\$0.00
	Tax 1 (0.0%)			\$0.00
	Tax 2 (0.0%)			\$0.00
	Credit			(\$0.00)
	Total Cost			\$0.00

T436 - 2015 Peerless

CLOSED

Serial	Tag	Closed Meters
2PLB04840FBL17436	5WZ971	

Type	Created	Scheduled	Due	Started	Closed
	Jan 13, 2026	Jan 13, 2026		Jan 13, 2026 5:24 PM	Jan 13, 2026 5:24 PM

Line	Task	Parts	Labor	Total
1	✓ Front LH inside flat	\$0.00	\$0.00	\$0.00
	Part Cost			\$0.00
	Labor			\$0.00
	Tax 1 (0.0%)			\$0.00
	Tax 2 (0.0%)			\$0.00
	Credit			(\$0.00)
	Total Cost			\$0.00

T436 - 2015 Peerless

CLOSED

Serial	Tag	Closed Meters
2PLB04840FBL17436	5WZ971	

Type	Created	Scheduled	Due	Started	Closed
	Feb 12, 2026	Feb 12, 2026		Feb 12, 2026 8:04 PM	Feb 12, 2026 8:04 PM

Line	Task	Parts	Labor	Total
1	✓ ABS codes	\$0.00	\$0.00	\$0.00
2	✓ Scam to weld on front right axle	\$0.00	\$0.00	\$0.00
3	✓ Chaffed air lines middle axle	\$0.00	\$0.00	\$0.00
4	✓ Loose bunk 5 and 3	\$0.00	\$0.00	\$0.00
5	✓ Lose air bag bolt	\$0.00	\$0.00	\$0.00
6	✓ Bad shock on back right	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

T436 - 2015 Peerless

Serial	Tag	Closed Meters
2PLB04840FBL17436	5WZ971	

Type	Created	Scheduled	Due	Started	Closed
	Mar 13, 2026	Mar 13, 2026		Mar 13, 2026 6:51 PM	Mar 13, 2026 8:25 PM

Line	Task	Parts	Labor	Total
1	✓ Brakes <u>Notes</u> Cotter pin missing on lh slack	\$0.00	\$0.00	\$0.00
2	✓ Bunk bolts <u>Notes</u> #5lh inside #6rh all are loose #3rh inside loose	\$0.00	\$0.00	\$0.00
3	✓ Bunk cracks <u>Notes</u> #3 rh broken pocket	\$0.00	\$0.00	\$0.00
4	✓ Hub Levels <u>Notes</u> Middle rh hub cap	\$0.00	\$0.00	\$0.00
5	✓ Lights - All <u>Notes</u> Lh rear marker out	\$0.00	\$0.00	\$0.00
6	✓ other <u>Notes</u> Wrapper handle on #5lh broken off and dust shield on middle lh	\$0.00	\$0.00	\$0.00
7	✓ Tires <u>Notes</u>	\$0.00	\$0.00	\$0.00

T436 - 2015 Peerless

At 90psi

Front rh inside low? Psi

8	✓ LH rear j box loose	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

T436 - 2015 Peerless

CLOSED

Serial	Tag	Closed Meters
2PLB04840FBL17436	5WZ971	

Type	Created	Scheduled	Due	Started	Closed
	May 27, 2026	May 27, 2026		Jun 1, 2026 4:10 PM	Jun 11, 2026 5:43 AM

Line	Task	Parts	Labor	Total		
1	✓ CVIP inspection (wheels off)	\$0.00	\$0.00	\$0.00		
2	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00		
3	✓ Rh front air bag bolt mia	\$0.00	\$0.00	\$0.00		
4	✓ Lh middle air bag bolt	\$0.00	\$0.00	\$0.00		
5	✓ #6 bunk rh loose	\$0.00	\$0.00	\$0.00		
6	✓ Middle Lh hub low	\$0.00	\$0.00	\$0.00		
7	✓ rear Lh hub low	\$0.00	\$0.00	\$0.00		
8	✓ ABS codes	\$0.00	\$0.00	\$0.00		
9	✓ Rear bunk lights out	\$0.00	\$0.00	\$0.00		
10	✓ rear light bar round chenters burned out	\$0.00	\$0.00	\$0.00		
11	✓ Lh rear wheel bearing loose	\$0.00	\$0.00	\$0.00		
12	✓ Lh front brake no good	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Q plus shoe kit	Kropp Shop		1.0	\$0.00	\$0.00
	Brake Drum	Kropp Shop		1.0	\$0.00	\$0.00
13	✓ Lh front outside rim cracked	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	24.5 rim	Kropp Shop		1.0	\$0.00	\$0.00
14	✓ Lift axle wiring	\$0.00	\$0.00	\$0.00		

Kropp Contracting
Shop

T436 - 2015 Peerless

Work Order 2728

Trent Court

CLOSED

Part Cost	\$0.00
Labor	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00