

T367 - 2015 Peerless

CLOSED

Serial	Tag	Closed Meters
2PLB04847FBL17367	6PB991	

Type	Scheduled	Due	Started	Closed
	Mar 12, 2024		Mar 12, 2024 3:53 PM	Mar 12, 2024 3:53 PM

Line	Task	Parts	Labor	Total
1	✓ saddle crack	\$0.00	\$0.00	\$0.00

Notes

front RH axle cracked loose u bolt and tightened. welded crack

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T367 - 2015 Peerless

CLOSED

Serial	Tag	Closed Meters
2PLB04847FBL17367	6PB991	

Type	Created	Scheduled	Due	Started	Closed
	May 31, 2024	May 31, 2024		Jun 5, 2024 6:04 AM	Jun 27, 2024 6:33 AM

Line	Task	Parts	Labor	Total
1	✓ Wheels off CVIP inspection	\$0.00	\$0.00	\$0.00
2	✓ Trailer Brakes	\$0.00	\$0.00	\$0.00

Notes

Lift axle LH shoes wore out, lift axle RH shoes/Drum wore out

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
Q plus shoe kit	Kropp Shop		2.0	\$0.00	\$0.00
Brake Drum	Kropp Shop		1.0	\$0.00	\$0.00

3	✓ Bent S-cam/tube	\$0.00	\$0.00	\$0.00
---	-------------------	--------	--------	--------

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
Peerless S cam tube	Kropp Shop		1.0	\$0.00	\$0.00
Peerless RH s cam	Kropp Shop		1.0	\$0.00	\$0.00

4	✓ saddle crack	\$0.00	\$0.00	\$0.00
---	----------------	--------	--------	--------

Notes

Front LH cacked Front RH cracked Middle LH,RH cracked

5	✓ loose u bolts	\$0.00	\$0.00	\$0.00
---	-----------------	--------	--------	--------

Notes

Front RH axle u bolts loose

6	✓ taillight bar bent	\$0.00	\$0.00	\$0.00
---	----------------------	--------	--------	--------

Notes

Remove and replace (6x4 tube)

T367 - 2015 Peerless

CLOSED

7 ✓ bunks cracked \$0.00 \$0.00 \$0.00

Notes

#6 top cracked, #5 LH mount cracked, #2 cracked

8 ✓ weld S cam tube \$0.00 \$0.00 \$0.00

Notes

Back axle LH side s cam spins

9 ✓ brake pot full of mud/missing plug \$0.00 \$0.00 \$0.00

Notes

Front axle LH/RH missing plugs, Middle LH missing plugs will not push on emergency brake

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
3030 brake pot	Kropp Shop		2.0	\$0.00	\$0.00

10 ✓ loose air bag bolts \$0.00 \$0.00 \$0.00

Notes

Middle RH, Rear RH bolts loose

11 ✓ lift axle air leak \$0.00 \$0.00 \$0.00

Notes

Leaks on control box with Lift raised, broken air line

12 ✓ ABS codes \$100.00 \$0.00 \$100.00

Notes

Middle LH blink code

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
K181625 - 6' 90 ABS WSS	Kropp Shop		1.0	\$100.00	\$100.00

13 ✓ loose fenders \$0.00 \$0.00 \$0.00

Notes

Middle Brackets L/H, R/H both loose

T367 - 2015 Peerless

CLOSED

14 ✓ Leveling valve no good \$0.00 \$0.00 \$0.00

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
Rapid response levelling valve	Kropp Shop		1.0	\$0.00	\$0.00

15 ✓ loose bunk bolt \$0.00 \$0.00 \$0.00

Notes

Front bunk RH side loose

16 ✓ Lift axle Electric lift not working \$0.00 \$0.00 \$0.00

Notes

pin broke on front of trailer

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
7 wire female plug	Kropp Shop		1.0	\$0.00	\$0.00

17 ✓ scale line couplar siezed \$0.00 \$0.00 \$0.00

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
Female air line coupler	Kropp Shop		1.0	\$0.00	\$0.00

18 ✓ hub level low \$0.00 \$0.00 \$0.00

Notes

Rear LH,RH low

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
80 w 90 gear oil	Kropp Shop		1.0	\$0.00	\$0.00

19 ✓ dolly leg cross member cracks \$0.00 \$0.00 \$0.00

20 ✓ low tire \$0.00 \$0.00 \$0.00

Notes

Middle LH outside 60 PSI valve leaking

21 ✓ remove lights and rubber fenders for sandblast and paint \$0.00 \$0.00 \$0.00

Kropp Contracting
Shop

T367 - 2015 Peerless

Work Order 1126
Trent Court, Nate Vandenberghe

CLOSED

Part Cost	\$100.00
Labor	\$0.00
Subtotal	\$100.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$100.00

T367 - 2015 Peerless

Serial	Tag	Closed Meters
2PLB04847FBL17367	6PB991	

Type	Created	Scheduled	Due	Started	Closed
	Aug 12, 2024	Aug 12, 2024		Aug 22, 2024 6:32 AM	Aug 22, 2024 6:32 AM

Line	Task	Parts	Labor	Total
1	✓ Bunk #6 loose LH side	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

T367 - 2015 Peerless

Serial	Tag	Closed Meters
2PLB04847FBL17367	6PB991	

Type	Created	Scheduled	Due	Started	Closed
	Oct 20, 2024	Oct 20, 2024		Oct 20, 2024 9:36 AM	Oct 20, 2024 9:36 AM

Line	Task	Parts	Labor	Total
------	------	-------	-------	-------

1	✓ ABS codes	\$100.00	\$0.00	\$100.00
---	-------------	----------	--------	----------

Notes

6 blink code wire broken

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
K181625 - 6' 90 ABS WSS	Kropp Shop		1.0	\$100.00	\$100.00

2	✓ Brakes	\$0.00	\$0.00	\$0.00
---	----------	--------	--------	--------

Notes

middle LH dust cover MIA

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
Clamp on dust cover	Kropp Shop		1.0	\$0.00	\$0.00

3	✓ Suspension	\$0.00	\$0.00	\$0.00
---	--------------	--------	--------	--------

Notes

middle air bag bolts loose, middle axle shocks loose

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
S-20126 - Trailer shock	Kropp Shop		2.0	\$0.00	\$0.00

Part Cost	\$100.00
Labor	\$0.00
Subtotal	\$100.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$100.00

T367 - 2015 Peerless

Serial	Tag	Closed Meters
2PLB04847FBL17367	6PB991	

Type	Created	Scheduled	Due	Started	Closed
	Nov 16, 2024	Nov 16, 2024		Nov 17, 2024 10:49 AM	Nov 17, 2024 10:49 AM

Line	Task	Parts	Labor	Total
1	✓ LHO lift axle tire flat	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

T367 - 2015 Peerless

CLOSED

Serial	Tag	Closed Meters
2PLB04847FBL17367	6PB991	

Type	Scheduled	Due	Started	Closed
	Dec 4, 2024		Dec 4, 2024 8:01 AM	Dec 4, 2024 8:01 AM

Line	Task	Parts	Labor	Total
------	------	-------	-------	-------

1	✓ Bunk bolts	\$0.00	\$0.00	\$0.00
---	--------------	--------	--------	--------

Notes

loose bunk bolts-tightened

2	✓ Saddle cracks	\$0.00	\$0.00	\$0.00
---	-----------------	--------	--------	--------

Notes

#6 and 7

3	✓ Tires	\$0.00	\$0.00	\$0.00
---	---------	--------	--------	--------

Notes

RFO, LFI

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
245 Trailer - Trailer Tire	Kropp Shop		2.0	\$0.00	\$0.00

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

Serial	Tag	Closed Meters
2PLB04847FBL17367	6PB991	

Type	Created	Scheduled	Due	Started	Closed
	Dec 15, 2024	Dec 15, 2024		Dec 15, 2024 2:35 PM	Dec 15, 2024 2:35 PM

Line	Task	Parts	Labor	Total																		
1	✓ ABS codes	\$0.00	\$0.00	\$0.00																		
	<u>Notes</u>																					
	RH WSS blink code																					
2	✓ Brakes	\$0.00	\$0.00	\$0.00																		
	<u>Notes</u>																					
	Middle RH scam tube broke, Scam wore into bracket																					
	<table><tr><th>Part</th><th>Warehouse</th><th>Vendor/Bin</th><th>Qty</th><th>Unit Cost</th><th>Cost</th></tr><tr><td>124R - peerless Scam right</td><td>Kropp Shop</td><td></td><td>1.0</td><td>\$0.00</td><td>\$0.00</td></tr><tr><td>Peerless S cam tube</td><td>Kropp Shop</td><td></td><td>1.0</td><td>\$0.00</td><td>\$0.00</td></tr></table>	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost	124R - peerless Scam right	Kropp Shop		1.0	\$0.00	\$0.00	Peerless S cam tube	Kropp Shop		1.0	\$0.00	\$0.00			
Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost																	
124R - peerless Scam right	Kropp Shop		1.0	\$0.00	\$0.00																	
Peerless S cam tube	Kropp Shop		1.0	\$0.00	\$0.00																	
3	✓ Hub Levels	\$0.00	\$0.00	\$0.00																		
	<u>Notes</u>																					
	LH rear wheel seal NFG RH middle wheel seal NFG																					
	<table><tr><th>Part</th><th>Warehouse</th><th>Vendor/Bin</th><th>Qty</th><th>Unit Cost</th><th>Cost</th></tr><tr><td>2110 wheel seal</td><td>Kropp Shop</td><td></td><td>2.0</td><td>\$0.00</td><td>\$0.00</td></tr><tr><td>75 W 90 gear oil</td><td>Kropp Shop</td><td></td><td>1.0</td><td>\$0.00</td><td>\$0.00</td></tr></table>	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost	2110 wheel seal	Kropp Shop		2.0	\$0.00	\$0.00	75 W 90 gear oil	Kropp Shop		1.0	\$0.00	\$0.00			
Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost																	
2110 wheel seal	Kropp Shop		2.0	\$0.00	\$0.00																	
75 W 90 gear oil	Kropp Shop		1.0	\$0.00	\$0.00																	
4	✓ Lights - All	\$0.00	\$0.00	\$0.00																		
	<u>Notes</u>																					
	RH mid ship marker out, RH signal Out																					

Kropp Contracting
Shop

T367 - 2015 Peerless

Work Order 1528

Trent Court

CLOSED

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T367 - 2015 Peerless

CLOSED

Serial	Tag	Closed Meters
2PLB04847FBL17367	6PB991	

Type	Scheduled	Due	Started	Closed
	Jan 7, 2025		Jan 7, 2025 5:36 PM	Jan 7, 2025 5:36 PM

Line	Task	Parts	Labor	Total		
1	✓ Loose bunks #6,#5,#3	\$0.00	\$0.00	\$0.00		
2	✓ Male 7 wire plug broke off	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	7 wire male plug	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

T367 - 2015 Peerless

CLOSED

Serial	Tag	Closed Meters
2PLB04847FBL17367	6PB991	

Type	Scheduled	Due	Started	Closed
	Jan 19, 2025		Jan 19, 2025 6:41 PM	Jan 19, 2025 6:41 PM

Line	Task	Parts	Labor	Total
1	✓ Hub Levels	\$0.00	\$0.00	\$0.00
	Notes			
	LH low RH rear low			
2	✓ other	\$0.00	\$0.00	\$0.00
	Notes			
	#3,4 winch handle			
3	✓ Suspension	\$0.00	\$0.00	\$0.00
	Notes			
	FLH bolt loose			
Part Cost				\$0.00
Labor				\$0.00
Subtotal				\$0.00
Tax 1 (0.0%)				\$0.00
Tax 2 (0.0%)				\$0.00
Credit				(\$0.00)
Total Cost				\$0.00

T367 - 2015 Peerless

Serial	Tag	Closed Meters
2PLB04847FBL17367	6PB991	

Type	Scheduled	Due	Started	Closed
	Feb 2, 2025		Feb 2, 2025 6:25 PM	Feb 2, 2025 6:25 PM

Line	Task	Parts	Labor	Total
1	✓ Lights - All	\$0.00	\$0.00	\$0.00

Notes

RH tail light bar marker out

2	✓ Suspension	\$150.00	\$0.00	\$150.00
---	--------------	----------	--------	----------

Notes

front LH air bag base broken

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
8050 air bag	Kropp Shop		1.0	\$150.00	\$150.00

3	✓ Tires	\$0.00	\$0.00	\$0.00
---	---------	--------	--------	--------

Notes

bacl lh inside no good

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00

Part Cost	\$150.00
Labor	\$0.00
Subtotal	\$150.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$150.00

T367 - 2015 Peerless

CLOSED

Serial	Tag	Closed Meters
2PLB04847FBL17367	6PB991	

Type	Created	Scheduled	Due	Started	Closed
	Mar 17, 2025	Mar 17, 2025		Mar 17, 2025 6:42 PM	Mar 17, 2025 6:42 PM

Line	Task	Parts	Labor	Total		
1	✓ rh mud flap tore off	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	24" mudflap	Kropp Shop		1.0	\$0.00	\$0.00
2	✓ RH rear axle tire outside tire flat	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

T367 - 2015 Peerless

CLOSED

Serial	Tag	Closed Meters
2PLB04847FBL17367	6PB991	

Type	Scheduled	Due	Started	Closed
	Mar 19, 2025		Mar 19, 2025 4:13 AM	Mar 19, 2025 4:13 AM

Line	Task	Parts	Labor	Total
1	✓ RH front fender brackets bolts broke	\$0.00	\$0.00	\$0.00
2	✓ Clean out 7 wire plug lights all flickering	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

T367 - 2015 Peerless

CLOSED

Serial	Tag	Closed Meters
2PLB04847FBL17367	6PB991	

Type	Created	Scheduled	Due	Started	Closed
	Jun 6, 2025	Jun 6, 2025		Jun 6, 2025 8:06 AM	Jun 6, 2025 8:12 AM

Line	Task	Parts	Labor	Total
1	✓ Market light out <u>Notes</u> RH middle marker	\$0.00	\$0.00	\$0.00
2	✓ Bunk cracks <u>Notes</u> 2, 3 & 6 RH, 5&6 LH	\$0.00	\$0.00	\$0.00
3	✓ Stake cracks <u>Notes</u> 5&6 RH, install wedge in #5LH	\$0.00	\$0.00	\$0.00
4	✓ Crossmember cracks <u>Notes</u> Dolly crossmember cracks, 2, 3, 4 and rear cross member cracked, gouge, weld and spray paint	\$0.00	\$0.00	\$0.00
5	✓ saddle crack <u>Notes</u> LM, RM & RR, gouge, preheat and weld	\$0.00	\$0.00	\$0.00
6	✓ Haldex bushings MIA <u>Notes</u> All but RF missing bushing	\$0.00	\$0.00	\$0.00

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
------	-----------	------------	-----	-----------	------

T367 - 2015 Peerless

CLOSED

	Haldex bar kit	Kropp Shop	2.0	\$0.00	\$0.00
	Haldex bushing kit	Kropp Shop	5.0	\$0.00	\$0.00
7	✓ Trailer Brakes		\$0.00	\$0.00	\$0.00

Notes

Middle axle and LF new shoes, new drum on RM

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
Brake Drum	Kropp Shop		1.0	\$0.00	\$0.00
Q plus shoe kit	Kropp Shop		3.0	\$0.00	\$0.00
8	✓ CVIP inspection (wheels off)		\$0.00	\$0.00	\$0.00
9	✓ Preform Scheduled Maintenance		\$0.00	\$0.00	\$0.00

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T367 - 2015 Peerless

CLOSED

Serial	Tag	Closed Meters
2PLB04847FBL17367	6PB991	

Type	Scheduled	Due	Started	Closed
	Sep 12, 2025		Sep 12, 2025 7:23 PM	Sep 12, 2025 7:23 PM

Line	Task	Parts	Labor	Total		
1	✓ Rh rear trailer inside tire nfg	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

T367 - 2015 Peerless

Serial	Tag	Closed Meters
2PLB04847FBL17367	6PB991	

Type	Created	Scheduled	Due	Started	Closed
	Nov 12, 2025	Nov 12, 2025		Nov 12, 2025 4:26 PM	Nov 13, 2025 1:17 PM

Line	Task	Parts	Labor	Total		
1	✓ Brakes	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	rear axle s cam tubes need welded					
2	✓ Tires	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	rear rh outside nfg					
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
3	✓ other	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	lift axle tie rod bar bent					
4	✓ Haldex bar bushing	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	LF & LHS lift axle					
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Haldex bushing kit	Kropp Shop		2.0	\$0.00	\$0.00
5	✓ Dust cover MIA	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	LHF					
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost

Kropp Contracting
Shop

T367 - 2015 Peerless

Work Order 2253
Terren Page, Everett Twin
CLOSED

Clamp on dust cover

Kropp Shop

1.0

\$0.00

\$0.00

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T367 - 2015 Peerless

CLOSED

Serial	Tag	Closed Meters
2PLB04847FBL17367	6PB991	

Type	Created	Scheduled	Due	Started	Closed
	Nov 28, 2025	Nov 28, 2025		Nov 29, 2025 5:50 AM	Nov 29, 2025 5:50 AM

Line	Task	Parts	Labor	Total
1	✓ Brake Connections <u>Notes</u> Rh supply line to brake pot chafed and leaking	\$0.00	\$0.00	\$0.00
2	✓ Hub Levels <u>Notes</u> Rear axle low, middle LH low, lift rh low	\$0.00	\$0.00	\$0.00
3	✓ Landing Gear <u>Notes</u> Dolly pin retainers MIA	\$0.00	\$0.00	\$0.00
4	✓ Tires <u>Notes</u> Lift axle inside LH nfg, lift axle rh outside chunk mia out of sidewall, middle rh outside nfg	\$0.00	\$0.00	\$0.00
5	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00
6	✓ rh rear air bag bolt mia	\$0.00	\$0.00	\$0.00
Part Cost				\$0.00
Labor				\$0.00
Subtotal				\$0.00
Tax 1 (0.0%)				\$0.00
Tax 2 (0.0%)				\$0.00
Credit				(\$0.00)
Total Cost				\$0.00

T367 - 2015 Peerless

CLOSED

Serial	Tag	Closed Meters
2PLB04847FBL17367	6PB991	

Type	Created	Scheduled	Due	Started	Closed
	Dec 13, 2025	Dec 13, 2025		Dec 14, 2025 11:08 AM	Dec 14, 2025 11:08 AM

Line	Task	Parts	Labor	Total
1	✓ Brakes	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	5 dust covers MIA			
2	✓ Hub Levels	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	middle axle low, rear lh low			
3	✓ other	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	shim middle rh slack			
Part Cost				\$0.00
Labor				\$0.00
Subtotal				\$0.00
Tax 1 (0.0%)				\$0.00
Tax 2 (0.0%)				\$0.00
Credit				(\$0.00)
Total Cost				\$0.00

T367 - 2015 Peerless

CLOSED

Serial	Tag	Closed Meters
2PLB04847FBL17367	6PB991	

Type	Created	Scheduled	Due	Started	Closed
	Jan 13, 2026	Jan 13, 2026		Jan 13, 2026 5:25 PM	Jan 13, 2026 5:25 PM

Line	Task	Parts	Labor	Total
1	✓ #7 both hubs low	\$0.00	\$0.00	\$0.00
2	✓ #7 rh slack fell off and had to pull s cam back into place	\$0.00	\$0.00	\$0.00
3	✓ Adjusted all brakes	\$0.00	\$0.00	\$0.00
4	✓ Tightened bunk bolts	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

T367 - 2015 Peerless

CLOSED

Serial	Tag	Closed Meters
2PLB04847FBL17367	6PB991	

Type	Created	Scheduled	Due	Started	Closed
	Jan 23, 2026	Jan 23, 2026		Feb 26, 2026 8:08 PM	Feb 26, 2026 8:08 PM

Line	Task	Parts	Labor	Total		
1	✓ accident rolled	\$0.00	\$0.00	\$0.00		
2	✓ 5th wheel bolster plate pulled down	\$907.00	\$0.00	\$907.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	3/8 qt plate	Kropp Shop		1.0	\$907.00	\$907.00
3	✓ king pin bent	\$120.00	\$0.00	\$120.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	KP100 - 2" king pin 3/8 plate	Kropp Shop		1.0	\$120.00	\$120.00
4	✓ LH fender tore off	\$0.00	\$0.00	\$0.00		
5	✓ Wrappers all broken	\$600.00	\$0.00	\$600.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	log wrapper	Kropp Shop		6.0	\$100.00	\$600.00
		Part Cost				\$1,627.00
		Labor				\$0.00
		Subtotal				\$1,627.00
		Tax 1 (0.0%)				\$0.00
		Tax 2 (0.0%)				\$0.00
		Credit				(\$0.00)
		Total Cost				\$1,627.00

T367 - 2015 Peerless

CLOSED

Serial	Tag	Closed Meters
2PLB04847FBL17367	6PB991	

Type	Created	Scheduled	Due	Started	Closed
	Mar 24, 2026	Mar 24, 2026		Mar 24, 2026 8:08 AM	Mar 24, 2026 8:08 AM

Line	Task	Parts	Labor	Total
------	------	-------	-------	-------

1	✓ Flat tire	\$0.00	\$0.00	\$0.00
---	-------------	--------	--------	--------

Notes

MRHO

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T367 - 2015 Peerless

CLOSED

Serial	Tag	Closed Meters
2PLB04847FBL17367	6PB991	

Type	Created	Scheduled	Due	Started	Closed
	Jul 3, 2026	Jul 3, 2026		Jul 6, 2026 10:28 AM	Jul 10, 2026 4:58 AM

Line	Task	Parts	Labor	Total
1	✓ CVIP inspection (wheels off)	\$0.00	\$0.00	\$0.00
2	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00
3	✓ ABS codes	\$0.00	\$0.00	\$0.00
4	✓ Rear 3 marker lights out	\$0.00	\$0.00	\$0.00
5	✓ front axle dust covers mia	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00