

N122 - 2025 KENWORTH T880

Parent: T499 - 2019 Peak hayrack

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX5SJ981437	0-BY693	6.5 hr & 309.5 km

Type	Created	Scheduled	Due	Started	Closed
	Jul 10, 2024	Jul 10, 2024		Jul 18, 2024 10:58 AM	Aug 29, 2024 11:01 AM

Line	Task	Parts	Labor	Total		
1	✓ Install T-Rail	\$0.00	\$0.00	\$0.00		
2	✓ Install 5th wheel	\$0.00	\$0.00	\$0.00		
3	✓ Run wiring for scale pads and headache rack	\$0.00	\$0.00	\$0.00		
4	✓ Remove hand rails on steps	\$0.00	\$0.00	\$0.00		
5	✓ install bandit bar	\$0.00	\$0.00	\$0.00		
6	✓ install LED low beam bulbs	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	H11 led bulb kit	Kropp Shop		1.0	\$0.00	\$0.00
7	✓ install chain hangers	\$0.00	\$0.00	\$0.00		
8	✓ install rear fender brackets	\$0.00	\$0.00	\$0.00		
9	✓ install plastic fenders	\$0.00	\$0.00	\$0.00		
10	✓ runs trailer scale line	\$0.00	\$0.00	\$0.00		
11	✓ install 2 way	\$0.00	\$0.00	\$0.00		
12	✓ install GPS	\$0.00	\$0.00	\$0.00		
13	✓ Build and install mirror extensions	\$0.00	\$0.00	\$0.00		
14	✓ Make umbilical cord	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	7 wire trailer cord	Kropp Shop		1.0	\$0.00	\$0.00

Kropp Contracting
Shop

N122 - 2025 KENWORTH T880

Parent: T499 - 2019 Peak hayrack

Work Order 1178

Trent Court

CLOSED

	3/8 bulk rubber air line	Kropp Shop	1.0	\$0.00	\$0.00
	7 wire female plug	Kropp Shop	3.0	\$0.00	\$0.00
15	✓ Put on decals		\$0.00	\$0.00	\$0.00
16	✓ Install headache rack		\$0.00	\$0.00	\$0.00
17	✓ Mill plate license plate and binder		\$0.00	\$0.00	\$0.00
18	✓ Log lights		\$0.00	\$0.00	\$0.00
19	✓ Steamers		\$0.00	\$0.00	\$0.00
			Part Cost		\$0.00
			Labor		\$0.00
			Subtotal		\$0.00
			Tax 1 (0.0%)		\$0.00
			Tax 2 (0.0%)		\$0.00
			Credit		(\$0.00)
			Total Cost		\$0.00

N122 - 2025 KENWORTH T880

Parent: T499 - 2019 Peak hayrack

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX5SJ981437	0-BY693	338 hr & 16,227 km

Type	Created	Scheduled	Due	Started	Closed
	Sep 26, 2024	Sep 26, 2024		Sep 26, 2024 1:01 PM	Sep 26, 2024 1:01 PM

Line	Task	Parts	Labor	Total		
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00		
2	✓ RH top Mickey Mouse work light missing	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Work light	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

N122 - 2025 KENWORTH T880

Parent: T499 - 2019 Peak hayrack

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX5SJ981437	0-BY693	400 hr & 16,227 km

Type	Scheduled	Due	Started	Closed
	Oct 15, 2024		Oct 15, 2024 6:27 AM	Oct 15, 2024 6:27 AM

Line	Task	Parts	Labor	Total
1	✓ Oil change	\$0.00	\$0.00	\$0.00
2	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

N122 - 2025 KENWORTH T880

Parent: T499 - 2019 Peak hayrack

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX5SJ981437	0-BY693	400 hr & 16,227 km

Type	Created	Scheduled	Due	Started	Closed
	Oct 20, 2024	Oct 20, 2024		Oct 25, 2024 9:15 AM	Oct 25, 2024 9:15 AM

Line	Task	Parts	Labor	Total
1	✓ Exhaust	\$0.00	\$0.00	\$0.00

Notes

loose stack mount RH side

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

N122 - 2025 KENWORTH T880

Parent: T499 - 2019 Peak hayrack

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX5SJ981437	0-BY693	531 hr & 27,450 km

Type	Scheduled	Due	Started	Closed
	Nov 1, 2024		Nov 1, 2024 6:30 PM	Nov 1, 2024 6:30 PM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

N122 - 2025 KENWORTH T880

Parent: T499 - 2019 Peak hayrack

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX5SJ981437	0-BY693	904 hr & 47,308 km

Type	Created	Scheduled	Due	Started	Closed
	Dec 1, 2024	Dec 1, 2024		Dec 9, 2024 4:08 AM	Dec 9, 2024 4:08 AM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
2	✓ Oil change	\$0.00	\$0.00	\$0.00
3	✓ Tires	\$0.00	\$0.00	\$0.00
Notes				
RH front drive inside low				
4	✓ change windshield	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

N122 - 2025 KENWORTH T880

Parent: T499 - 2019 Peak hayrack

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX5SJ981437	0-BY693	1,113 hr & 59,640 km

Type	Created	Scheduled	Due	Started	Closed
	Dec 14, 2024	Dec 14, 2024		Dec 14, 2024 11:39 AM	Dec 14, 2024 11:39 AM

Line	Task	Parts	Labor	Total
1	✓ Defroster	\$0.00	\$0.00	\$0.00
	Notes			
	cab filters plugged			
2	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
3	✓ Mirrors	\$0.00	\$0.00	\$0.00
	Notes			
	no mirror heat			

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

N122 - 2025 KENWORTH T880

Parent: T499 - 2019 Peak hayrack

Serial	Tag	Closed Meters
1NKZX4EX5SJ981437	0-BY693	1,113 hr & 59,640 km

Type	Created	Scheduled	Due	Started	Closed
	Dec 18, 2024	Dec 18, 2024		Dec 21, 2024 4:29 PM	Dec 21, 2024 4:29 PM

Line	Task	Parts	Labor	Total
1	✓ No start,	\$0.00	\$0.00	\$0.00

Notes

Has 12.2 voltage turn key... no crank, jump starter with ignition on and truck will run, once running comes up with light faults, no fuel level, no temperature sensor data, hooked up Daveie and have no communication to CMP... and no communication to MSB1 and MSB2 checked fuses and verified power, suspect bad bad chassis module, KW to come and change for warranty

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

N122 - 2025 KENWORTH T880

Parent: T499 - 2019 Peak hayrack

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX5SJ981437	0-BY693	1,200 hr & 59,640 km

Type	Scheduled	Due	Started	Closed
	Jan 3, 2025		Jan 3, 2025 8:50 AM	Jan 3, 2025 8:50 AM

Line	Task	Parts	Labor	Total
1	✓ Oil change	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

N122 - 2025 KENWORTH T880

Parent: T499 - 2019 Peak hayrack

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX5SJ981437	0-BY693	1,613 hr & 81,941 km

Type	Created	Scheduled	Due	Started	Closed
	Jan 26, 2025	Jan 26, 2025		Jan 28, 2025 2:03 PM	Jan 28, 2025 2:03 PM

Line	Task	Parts	Labor	Total		
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00		
2	✓ Oil change	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LF14000 - Cummins oil filter	Kropp Shop		1.0	\$0.00	\$0.00
3	✓ update ecm calibration	\$0.00	\$0.00	\$0.00		
		Part Cost				\$0.00
		Labor				\$0.00
		Subtotal				\$0.00
		Tax 1 (0.0%)				\$0.00
		Tax 2 (0.0%)				\$0.00
		Credit				(\$0.00)
		Total Cost				\$0.00

N122 - 2025 KENWORTH T880

Parent: T499 - 2019 Peak hayrack

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX5SJ981437	0-BY693	1,899 hr & 95,778 km

Type	Created	Scheduled	Due	Started	Closed
	Feb 15, 2025	Feb 15, 2025		Feb 15, 2025 1:02 PM	Feb 15, 2025 1:02 PM

Line	Task	Parts	Labor	Total
1	✓ Body <u>Notes</u> battery box bolt mia	\$0.00	\$0.00	\$0.00
2	✓ Check all fluid levels <u>Notes</u> oil low 1L tranny 2L low	\$0.00	\$0.00	\$0.00
3	✓ Mirrors <u>Notes</u> RH convex broken	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

N122 - 2025 KENWORTH T880

Parent: T499 - 2019 Peak hayrack

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX5SJ981437	0-BY693	1,899 hr & 95,778 km

Type	Created	Scheduled	Due	Started	Closed
	Feb 25, 2025	Feb 25, 2025		Feb 27, 2025 11:37 AM	Feb 27, 2025 11:37 AM

Line	Task	Parts	Labor	Total		
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00		
2	✓ Oil change	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LF14000 - Cummins oil filter	Kropp Shop		1.0	\$0.00	\$0.00
	oil 15w-40	Kropp Shop		1.0	\$0.00	\$0.00
3	✓ #4 LHI flat	\$0.00	\$0.00	\$0.00		
4	✓ windshield	\$0.00	\$0.00	\$0.00		
		Part Cost				\$0.00
		Labor				\$0.00
		Subtotal				\$0.00
		Tax 1 (0.0%)				\$0.00
		Tax 2 (0.0%)				\$0.00
		Credit				(\$0.00)
		Total Cost				\$0.00

N122 - 2025 KENWORTH T880

Parent: T499 - 2019 Peak hayrack

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX5SJ981437	0-BY693	2,000 hr & 98,428 km

Type	Scheduled	Due	Started	Closed
	Mar 5, 2025		Mar 5, 2025 8:11 PM	Mar 5, 2025 8:11 PM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

N122 - 2025 KENWORTH T880

Parent: T499 - 2019 Peak hayrack

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX5SJ981437	0-BY693	2,417 hr & 119,231 km

Type	Created	Scheduled	Due	Started	Closed
Service	May 3, 2025	May 3, 2025		May 3, 2025 8:06 AM	May 3, 2025 8:06 AM

Line	Task	Parts	Labor	Total
1	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00
2	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
3	✓ Mirror cracked, replace	\$0.00	\$0.00	\$0.00
Notes				
Replace r/h and l/h convex				
Replace L/h mirror				
4	✓ Oil change	\$0.00	\$0.00	\$0.00
5	✓ Air filters	\$0.00	\$0.00	\$0.00
6	✓ change diff filters	\$0.00	\$0.00	\$0.00
7	✓ Replace Belt	\$0.00	\$0.00	\$0.00

Notes

A/c and fan belts

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

N122 - 2025 KENWORTH T880

Parent: T499 - 2019 Peak hayrack

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX5SJ981437	0-BY693	2,578 hr & 127,608 km

Type	Created	Scheduled	Due	Started	Closed
	May 28, 2025	May 28, 2025		May 28, 2025 12:53 PM	May 28, 2025 12:53 PM

Line	Task	Parts	Labor	Total
1	✓ Steer Tires	\$0.00	\$0.00	\$0.00

Notes

Flat steer tire RHS. Install used but similar steer tire, inspect take off tire for leaks

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

N122 - 2025 KENWORTH T880

Parent: T499 - 2019 Peak hayrack

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX5SJ981437	0-BY693	2,757 hr & 137,159 km

Type	Created	Scheduled	Due	Started	Closed
	Jun 25, 2025	Jun 25, 2025		Jun 25, 2025 6:34 AM	Jun 25, 2025 6:34 AM

Line	Task	Parts	Labor	Total
1	✓ AC not working	\$0.00	\$0.00	\$0.00

Notes

hole in AC condenser... Bolt from factory was wedged in between condenser and Air to Air and rubbed hole in both

2	✓ Change AC condenser developed a hole	\$0.00	\$0.00	\$0.00
---	--	--------	--------	--------

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
813.59107 - AC condenser T880	Kropp Shop		1.0	\$0.00	\$0.00
R134a	Kropp Shop		1.0	\$0.00	\$0.00

3	✓ change Air to Air developed a hole	\$0.00	\$0.00	\$0.00
---	--------------------------------------	--------	--------	--------

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

N122 - 2025 KENWORTH T880

Parent: T499 - 2019 Peak hayrack

Serial	Tag	Closed Meters
1NKZX4EX5SJ981437	0-BY693	2,781 hr & 138,423 km

Type	Created	Scheduled	Due	Started	Closed
	Jun 27, 2025	Jun 27, 2025		Jun 27, 2025 10:55 AM	Jul 1, 2025 5:18 AM

Line	Task	Parts	Labor	Total		
1	✓ Body	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	Hood grill bolts MIA					
2	✓ Engine	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	Quick drain cap MIA					
3	✓ Lights - All	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	Rear tail lights not working on skirt					
4	✓ Mirrors	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	Both west cost mirrors cracked					
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	mirror t880	Kropp Shop		2.0	\$0.00	\$0.00
5	✓ Other	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	Front drive axle mudflaps wore and broke					
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	24" plastic mudflap	Kropp Shop		2.0	\$0.00	\$0.00
	anti sail bracket	Kropp Shop		1.0	\$0.00	\$0.00

Kropp Contracting
Shop

N122 - 2025 KENWORTH T880

Parent: T499 - 2019 Peak hayrack

Work Order 1945
Sam Hawksley, Trent Court
CLOSED

6	✓ CVIP inspection (wheels off)	\$0.00	\$0.00	\$0.00
7	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00
8	✓ Oil change	\$0.00	\$0.00	\$0.00
9	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Kropp Contracting
Shop

N122 - 2025 KENWORTH T880

Parent: T499 - 2019 Peak hayrack

Work Order 1968
Sam Hawksley, Everett Twin

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX5SJ981437	0-BY693	2,781 hr & 138,423 km

Type	Scheduled	Due	Started	Closed
	Jul 7, 2025		Jul 7, 2025 2:57 PM	Jul 7, 2025 2:57 PM

Line	Task	Parts	Labor	Total
1	✓ Drive tires (set of 12)	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

N122 - 2025 KENWORTH T880

Parent: T499 - 2019 Peak hayrack

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX5SJ981437	0-BY693	2,953 hr & 149,357 km

Type	Created	Scheduled	Due	Started	Closed
	Aug 21, 2025	Aug 21, 2025		Aug 21, 2025 4:42 PM	Aug 21, 2025 4:42 PM

Line	Task	Parts	Labor	Total
1	✓ Lights inop	\$0.00	\$0.00	\$0.00
	Notes			
	Repair ground circuit on red Mickey Mouse light driver side			
2	✓ Scale pad washer MIA	\$0.00	\$0.00	\$0.00
	Notes			
	Remove 5th wheel plate and remove scale pad bolt, clean and chase threads, install bolt with new washer and copper kote. Change out X2 grease zirks and grease 5th wheel jaws			
3	✓ Adjust 5th wheel	\$0.00	\$0.00	\$0.00
4	✓ Steer Tires	\$0.00	\$0.00	\$0.00

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
steer tires	Kropp Shop		2.0	\$0.00	\$0.00

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

N122 - 2025 KENWORTH T880

Parent: T499 - 2019 Peak hayrack

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX5SJ981437	0-BY693	3,110 hr & 159,386 km

Type	Scheduled	Due	Started	Closed
	Sep 22, 2025		Sep 22, 2025 1:08 PM	Sep 22, 2025 1:08 PM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

N122 - 2025 KENWORTH T880

Parent: T499 - 2019 Peak hayrack

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX5SJ981437	0-BY693	3,200 hr & 164,187 km

Type	Created	Scheduled	Due	Started	Closed
	Oct 6, 2025	Oct 6, 2025		Oct 6, 2025 5:19 AM	Oct 6, 2025 5:19 AM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

N122 - 2025 KENWORTH T880

Parent: T499 - 2019 Peak hayrack

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX5SJ981437	0-BY693	3,259 hr & 167,160 km

Type	Created	Scheduled	Due	Started	Closed
	Oct 14, 2025	Oct 14, 2025		Oct 14, 2025 9:43 AM	Oct 14, 2025 9:43 AM

Line	Task			Parts	Labor	Total
1	✓ Oil change			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LF14000 - Cummins oil filter	Kropp Shop		1.0	\$0.00	\$0.00
	FF5825NN - Cummins fuel filter	Kropp Shop		1.0	\$0.00	\$0.00
	FS20172 - Cummins water separator filter	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

N122 - 2025 KENWORTH T880

Parent: T499 - 2019 Peak hayrack

Serial	Tag	Closed Meters
1NKZX4EX5SJ981437	0-BY693	3,434 hr & 175,059 km

Type	Created	Scheduled	Due	Started	Closed
	Nov 15, 2025	Nov 15, 2025		Nov 21, 2025 8:00 AM	Nov 21, 2025 8:00 AM

Line	Task	Parts	Labor	Total
1	✓ Exhaust <u>Notes</u> RH stack loose	\$0.00	\$0.00	\$0.00
2	✓ Lights - All <u>Notes</u> top work lights need work	\$0.00	\$0.00	\$0.00
3	✓ Mirrors <u>Notes</u> RH convex	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

N122 - 2025 KENWORTH T880

Parent: T499 - 2019 Peak hayrack

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX5SJ981437	0-BY693	3,413 hr & 173,951 km

Type	Created	Scheduled	Due	Started	Closed
	Nov 18, 2025	Nov 18, 2025		Nov 18, 2025 2:48 PM	Nov 18, 2025 2:48 PM

Line	Task	Parts	Labor	Total		
1	✓ mickey mouse light repair	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	6050 - Oval Red light	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

N122 - 2025 KENWORTH T880

Parent: T499 - 2019 Peak hayrack

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX5SJ981437	0-BY693	3,434 hr & 175,059 km

Type	Created	Scheduled	Due	Started	Closed
	Nov 20, 2025	Nov 20, 2025		Nov 20, 2025 2:08 PM	Nov 21, 2025 8:27 PM

Line	Task	Parts	Labor	Total
1	✓ plywood behind hitch missing bunjee	\$0.00	\$0.00	\$0.00
2	✓ exhaust stack loose	\$0.00	\$0.00	\$0.00
3	✓ micky light loose	\$0.00	\$0.00	\$0.00
4	✓ micky light fell out	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

N122 - 2025 KENWORTH T880

Parent: T499 - 2019 Peak hayrack

Serial	Tag	Closed Meters
1NKZX4EX5SJ981437	0-BY693	3,519 hr & 179,238 km

Type	Created	Scheduled	Due	Started	Closed
	Nov 29, 2025	Nov 29, 2025		Nov 30, 2025 5:42 AM	Nov 30, 2025 5:42 AM

Line	Task	Parts	Labor	Total
1	✓ Air Lines <u>Notes</u> Tie up air lines off LH from diff brake pot	\$0.00	\$0.00	\$0.00
2	✓ Battery <u>Notes</u> Battery box bolt loose	\$0.00	\$0.00	\$0.00
3	✓ Defroster <u>Notes</u> Cab filters plugged	\$0.00	\$0.00	\$0.00
4	✓ Exhaust <u>Notes</u> Rh stack bushing nfg	\$0.00	\$0.00	\$0.00
5	✓ Frame & Assembly <u>Notes</u> Check scale pad bolts with wrench	\$0.00	\$0.00	\$0.00
6	✓ Fuel Tanks <u>Notes</u> Rock jammed between frame and tank	\$0.00	\$0.00	\$0.00
7	✓ Lights - All	\$0.00	\$0.00	\$0.00

Kropp Contracting
Shop

N122 - 2025 KENWORTH T880

Parent: T499 - 2019 Peak hayrack

Work Order 2312
Trent Court, Aiden Kenny
CLOSED

Notes

Put In LED low beams, top RH work light out

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

N122 - 2025 KENWORTH T880

Parent: T499 - 2019 Peak hayrack

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX5SJ981437	0-BY693	3,535 hr & 179,748 km

Type	Scheduled	Due	Started	Closed
	Dec 1, 2025		Dec 1, 2025 5:42 PM	Dec 1, 2025 5:42 PM

Line	Task	Parts	Labor	Total		
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00		
2	✓ Oil change	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LF14000 - Cummins oil filter	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

N122 - 2025 KENWORTH T880

Parent: T499 - 2019 Peak hayrack

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX5SJ981437	0-BY693	3,661 hr & 185,007 km

Type	Created	Scheduled	Due	Started	Closed
	Dec 14, 2025	Dec 14, 2025		Dec 14, 2025 6:39 PM	Dec 14, 2025 7:31 PM

Line	Task	Parts	Labor	Total
------	------	-------	-------	-------

1	✓ Mirrors	\$0.00	\$0.00	\$0.00
---	-----------	--------	--------	--------

Notes

right hand mirror

2	✓ Other	\$0.00	\$0.00	\$0.00
---	---------	--------	--------	--------

Notes

Tested the blower motor on all setting and different levels of airflow and found no issue or wierd noises....-Aiden

blower motor

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

N122 - 2025 KENWORTH T880

Parent: T499 - 2019 Peak hayrack

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX5SJ981437	0-BY693	3,661 hr & 185,007 km

Type	Created	Scheduled	Due	Started	Closed
	Jan 2, 2026	Jan 2, 2026		Jan 4, 2026 8:16 AM	Jan 4, 2026 8:16 AM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
2	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

N122 - 2025 KENWORTH T880

Parent: T499 - 2019 Peak hayrack

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX5SJ981437	0-BY693	3,886 hr & 194,297 km

Type	Created	Scheduled	Due	Started	Closed
	Jan 14, 2026	Jan 14, 2026		Jan 14, 2026 4:57 AM	Jan 14, 2026 5:38 PM

Line	Task	Parts	Labor	Total
1	✓ Chaffed hoses	\$0.00	\$0.00	\$0.00
2	✓ Light out on left due of headache rack	\$0.00	\$0.00	\$0.00
3	✓ Left micky out	\$0.00	\$0.00	\$0.00
4	✓ Drivers side mirror	\$0.00	\$0.00	\$0.00
5	✓ Loose mudflap hanger bolt	\$0.00	\$0.00	\$0.00
6	✓ Set up scale	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

N122 - 2025 KENWORTH T880

Parent: T499 - 2019 Peak hayrack

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX5SJ981437	0-BY693	3,929 hr & 194,297 km

Type	Scheduled	Due	Started	Closed
	Jan 20, 2026		Jan 20, 2026 5:29 AM	Jan 20, 2026 5:29 AM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
2	✓ Oil change	\$0.00	\$0.00	\$0.00
3	✓ change windshield	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

N122 - 2025 KENWORTH T880

Parent: T499 - 2019 Peak hayrack

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX5SJ981437	0-BY693	4,055 hr & 202,633 km

Type	Created	Scheduled	Due	Started	Closed
	Jan 30, 2026	Jan 30, 2026		Jan 30, 2026 6:42 PM	Jan 30, 2026 6:42 PM

Line	Task	Parts	Labor	Total												
1	✓ Lights - All	\$0.00	\$0.00	\$0.00												
	<u>Notes</u>															
	Top LH work light															
2	✓ Mirrors	\$0.00	\$0.00	\$0.00												
	<u>Notes</u>															
	Convex mirror LH cracked															
	<table><tr><th>Part</th><th>Warehouse</th><th>Vendor/Bin</th><th>Qty</th><th>Unit Cost</th><th>Cost</th></tr><tr><td>convex mirror t880</td><td>Kropp Shop</td><td></td><td>1.0</td><td>\$0.00</td><td>\$0.00</td></tr></table>	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost	convex mirror t880	Kropp Shop		1.0	\$0.00	\$0.00			
Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost											
convex mirror t880	Kropp Shop		1.0	\$0.00	\$0.00											
3	✓ LH MM light bracket loose	\$0.00	\$0.00	\$0.00												
		Part Cost		\$0.00												
		Labor		\$0.00												
		Subtotal		\$0.00												
		Tax 1 (0.0%)		\$0.00												
		Tax 2 (0.0%)		\$0.00												
		Credit		(\$0.00)												
		Total Cost		\$0.00												

N122 - 2025 KENWORTH T880

Parent: T499 - 2019 Peak hayrack

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX5SJ981437	0-BY693	4,055 hr & 202,633 km

Type	Scheduled	Due	Started	Closed
	Feb 6, 2026		Feb 6, 2026 3:51 AM	Feb 6, 2026 3:51 AM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

N122 - 2025 KENWORTH T880

Parent: T499 - 2019 Peak hayrack

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX5SJ981437	0-BY693	4,158 hr & 208,535 km

Type	Created	Scheduled	Due	Started	Closed
	Feb 16, 2026	Feb 16, 2026		Feb 16, 2026 5:03 PM	Feb 16, 2026 5:03 PM

Line	Task	Parts	Labor	Total
1	✓ Lights - All	\$0.00	\$0.00	\$0.00

Notes

top LH MM out

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

N122 - 2025 KENWORTH T880

Parent: T499 - 2019 Peak hayrack

Work Order 2573

Unassigned

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX5SJ981437	0-BY693	4,267 hr & 211,974 km

Type	Created	Scheduled	Due	Started	Closed
	Feb 24, 2026	Feb 24, 2026		Feb 24, 2026 9:26 PM	Feb 24, 2026 9:26 PM

Line	Task	Parts	Labor	Total
1	✓ Windshield Wipers	\$0.00	\$0.00	\$0.00

Notes

wiper squirter not working

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

N122 - 2025 KENWORTH T880

Parent: T499 - 2019 Peak hayrack

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX5SJ981437	0-BY693	4,267 hr & 211,974 km

Type	Created	Scheduled	Due	Started	Closed
	Mar 1, 2026	Mar 1, 2026		Mar 2, 2026 8:32 AM	Mar 2, 2026 8:32 AM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

N122 - 2025 KENWORTH T880

Parent: T499 - 2019 Peak hayrack

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX5SJ981437	0-BY693	4,267 hr & 211,974 km

Type	Created	Scheduled	Due	Started	Closed
	Mar 9, 2026	Mar 9, 2026		Mar 9, 2026 3:55 PM	Mar 9, 2026 3:55 PM

Line	Task			Parts	Labor	Total
1	✓ Rh rear outside drive flat			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Truck - Drive tire	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

N122 - 2025 KENWORTH T880

Parent: T499 - 2019 Peak hayrack

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX5SJ981437	0-BY693	4,443 hr & 218,663 km

Type	Created	Scheduled	Due	Started	Closed
	Mar 11, 2026	Mar 11, 2026		Mar 13, 2026 6:14 PM	Mar 13, 2026 6:14 PM

Line	Task			Parts	Labor	Total
1	✓ Oil change			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LF14000 - Cummins oil filter	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

N122 - 2025 KENWORTH T880

Parent: T499 - 2019 Peak hayrack

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX5SJ981437	0-BY693	4,748 hr & 232,619 km

Type	Created	Scheduled	Due	Started	Closed
	May 21, 2026	May 21, 2026		May 21, 2026 5:02 PM	May 21, 2026 5:03 PM

Line	Task			Parts	Labor	Total
1	✓ Ac not working			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	813.59107 - AC condenser T880	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

N122 - 2025 KENWORTH T880

Parent: T499 - 2019 Peak hayrack

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX5SJ981437	0-BY693	4,859 hr & 237,982 km

Type	Created	Scheduled	Due	Started	Closed
	Jun 16, 2026	Jun 16, 2026		Jun 17, 2026 7:18 AM	Jun 17, 2026 7:18 AM

Line	Task			Parts	Labor	Total
1	✓ Changed leaking radiator			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	T880 Radiator	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

N122 - 2025 KENWORTH T880

Parent: T499 - 2019 Peak hayrack

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX5SJ981437	0-BY693	4,917 hr & 240,749 km

Type	Created	Scheduled	Due	Started	Closed
	Jul 2, 2026	Jul 2, 2026		Jul 3, 2026 7:56 AM	Jul 10, 2026 4:58 AM

Line	Task	Parts	Labor	Total		
1	✓ CVIP inspection (wheels off)	\$0.00	\$0.00	\$0.00		
2	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00		
3	✓ Oil change	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LF14000 - Cummins oil filter	Kropp Shop		1.0	\$0.00	\$0.00
	FS20172 - Cummins water separator filter	Kropp Shop		1.0	\$0.00	\$0.00
	FF5825NN - Cummins fuel filter	Kropp Shop		1.0	\$0.00	\$0.00
4	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00		
5	✓ Lh Mickey Mouse lights falling out	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	6050A oval light	Kropp Shop		2.0	\$0.00	\$0.00
	6050 - Oval Red light	Kropp Shop		1.0	\$0.00	\$0.00
6	✓ Drive tires (set of 12)	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Truck - Drive tire	Kropp Shop		12.0	\$0.00	\$0.00
7	✓ Lh mirror	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	mirror t880	Kropp Shop		1.0	\$0.00	\$0.00
8	✓ rh mirror cracked	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	mirror t880	Kropp Shop		1.0	\$0.00	\$0.00

N122 - 2025 KENWORTH T880

Parent: T499 - 2019 Peak hayrack

CLOSED

9	✓ change diff filters			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LF3311 - Rockwell diff filter	Kropp Shop		2.0	\$0.00	\$0.00
10	✓ Change air filter			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	air filter T880	Kropp Shop		1.0	\$0.00	\$0.00
11	✓ change belts			\$0.00	\$0.00	\$0.00
12	✓ Pilot line broke off at relay valve rear drives			\$0.00	\$0.00	\$0.00
13	✓ supply line broke rh middle			\$0.00	\$0.00	\$0.00
14	✓ middle Lh brake pot broke			\$0.00	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00