

W5 - 2015 Kenworth t800

CLOSED

Serial	Tag	Closed Meters
1NKDXPEX3FR977194	k93133	19,224 hr & 823,172 km

Type	Created	Scheduled	Due	Started	Closed
	Apr 30, 2024	Apr 30, 2024		May 13, 2024 10:47 AM	May 27, 2024 5:54 AM

Line	Task	Parts	Labor	Total		
1	✓ Check engine light	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	Unit pump #2 data low					
	Injector 5 solenoid					
2	✓ Change #5 injector	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Mx13 injector	Kropp Shop		1.0	\$0.00	\$0.00
3	✓ Replace low pressure fuel lines	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Low pressure line set mx13	Kropp Shop		1.0	\$0.00	\$0.00
4	✓ Replace #2 unit pump	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Unit pump mx13	Kropp Shop		1.0	\$0.00	\$0.00
5	✓ Wheels off CVIP inspection	\$0.00	\$0.00	\$0.00		
6	✓ REPLACE PLASTIC FENDERS	\$0.00	\$0.00	\$0.00		
7	✓ WELD 5TH WHEEL STOPPERS	\$0.00	\$0.00	\$0.00		
8	✓ spring pins	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	spring pins	Kropp Shop		4.0	\$0.00	\$0.00
	spring pin bushings	Kropp Shop		1.0	\$0.00	\$0.00

W5 - 2015 Kenworth t800

CLOSED

9	✓ change diff filters			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LF3311 - Rockwell diff filter	Kropp Shop		2.0	\$0.00	\$0.00
10	✓ Air filters			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	air filters	Kropp Shop		2.0	\$0.00	\$0.00
11	✓ middle wishbone bushings loose			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	v-rod bushing kit	Kropp Shop		1.0	\$0.00	\$0.00
12	✓ o-ring on pressure line into control valve leaking			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	-16 ORing	Kropp Shop		1.0	\$0.00	\$0.00
13	✓ RH outrigger drops			\$0.00	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

W5 - 2015 Kenworth t800

CLOSED

Serial	Tag	Closed Meters
1NKDXPEX3FR977194	k93133	19,700 hr & 833,644 km

Type	Created	Scheduled	Due	Started	Closed
	Feb 14, 2025	Feb 14, 2025		Feb 25, 2025 1:49 PM	Feb 25, 2025 1:49 PM

Line	Task	Parts	Labor	Total		
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00		
2	✓ Oil change	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	0w-30 oil	Kropp Shop		43.0	\$0.00	\$0.00
	1948921 - MX13 oil filter	Kropp Shop		1.0	\$0.00	\$0.00
	1922496 - MX13 Oil spinner	Kropp Shop		1.0	\$0.00	\$0.00
	1852006PE - MX13 fuel filter	Kropp Shop		1.0	\$0.00	\$0.00
	K37-1029 - Water separator filter	Kropp Shop		1.0	\$0.00	\$0.00
3	✓ Middle drive wishbone bushings no good	\$0.00	\$0.00	\$0.00		
4	✓ front Drive wishbone top diff bolt loose	\$0.00	\$0.00	\$0.00		
5	✓ LH high beam bulb broke	\$0.00	\$0.00	\$0.00		
6	✓ Injector 5 engine code (wiring issue)	\$0.00	\$0.00	\$0.00		
7	✓ Middle diff input leaking oil	\$0.00	\$0.00	\$0.00		
		Part Cost		\$0.00		
		Labor		\$0.00		
		Subtotal		\$0.00		
		Tax 1 (0.0%)		\$0.00		
		Tax 2 (0.0%)		\$0.00		
		Credit		(\$0.00)		
		Total Cost		\$0.00		

W5 - 2015 Kenworth t800

CLOSED

Serial	Tag	Closed Meters
1NKDXPEX3FR977194	k93133	19,890 hr & 836,393 km

Type	Created	Scheduled	Due	Started	Closed
	Jun 11, 2025	Jun 11, 2025		Jun 17, 2025 1:48 PM	Jun 19, 2025 12:17 PM

Line	Task	Parts	Labor	Total		
1	✓ Hood light INOP	\$0.00	\$0.00	\$0.00		
2	✓ Tail lamp INOP	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	3 wire pigtail	Kropp Shop		1.0	\$0.00	\$0.00
3	✓ Loose shock	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	RF					
4	✓ Hood bushings NFG	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	Replaced hood bushings					
5	✓ loose yoke on diff	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	SPL170-4x - SPL170 U joint	Kropp Shop		1.0	\$0.00	\$0.00
	R945007 - Input diff seal rockwell	Kropp Shop		1.0	\$0.00	\$0.00
6	✓ change diff filters	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LF3311 - Rockwell diff filter	Kropp Shop		2.0	\$0.00	\$0.00
7	✓ replace air filters	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	AF4195 - air filters T800	Kropp Shop		2.0	\$0.00	\$0.00

W5 - 2015 Kenworth t800

CLOSED

8	✓ Brake job			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Brake Drum	Kropp Shop		6.0	\$0.00	\$0.00
	Es2 shoe kit	Kropp Shop		5.0	\$0.00	\$0.00
9	✓ Winch hydraulic hoses			\$0.00	\$0.00	\$0.00
	Notes					
	New hoses for winch supply and return lines					
10	✓ Air line			\$0.00	\$0.00	\$0.00
	Notes					
	Air line from compressor to dryer. Remove old hoses and route new hose in OEM factory routing against frame rail.					
11	✓ Loose Scam bolts			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	MC-250 - 2.5" exhaust clamp	Kropp Shop		2.0	\$0.00	\$0.00
12	✓ Grease truck and trailer			\$0.00	\$0.00	\$0.00
13	✓ CVIP inspection (wheels off)			\$0.00	\$0.00	\$0.00
14	✓ Exhaust			\$0.00	\$0.00	\$0.00
	Notes					
	Straighten out Ben exhaust bracket from SER outlet					
15	✓ Backup lights			\$0.00	\$0.00	\$0.00
	Notes					
	Replaced broken back up lights					
16	✓ Preform Scheduled Maintenance			\$0.00	\$0.00	\$0.00

Kropp Contracting
Shop

W5 - 2015 Kenworth t800

Work Order 1912

Everett Twin

CLOSED

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

W5 - 2015 Kenworth t800

CLOSED

Serial	Tag	Closed Meters
1NKDXPEX3FR977194	k93133	19,890 hr & 836,393 km

Type	Created	Scheduled	Due	Started	Closed
	Jul 21, 2025	Jul 21, 2025		Jul 21, 2025 7:08 AM	Aug 8, 2025 3:23 PM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
2	✓ Bent ride height rod	\$0.00	\$0.00	\$0.00
Notes				
Bend ride height rods back to normal				
3	✓ Bleed air from hydraulic system	\$0.00	\$0.00	\$0.00
4	✓ Grease picker	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Notes

Notes	User	Time
Fifth wheel cracked	Trent Court	Aug 8, 2025 3:23 PM

W5 - 2015 Kenworth t800

CLOSED

Serial	Tag	Closed Meters
1NKDXPEX3FR977194	k93133	19,890 hr & 836,393 km

Type	Scheduled	Due	Started	Closed
	Jan 3, 2026		Jan 3, 2026 4:21 PM	Jan 3, 2026 4:21 PM

Line	Task	Parts	Labor	Total
1	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

W5 - 2015 Kenworth t800

Serial	Tag	Closed Meters
1NKDXPEX3FR977194	k93133	19,890 hr & 836,393 km

Type	Created	Scheduled	Due	Started	Closed
	Mar 24, 2026	Mar 24, 2026		Jun 19, 2026 7:27 PM	Jun 19, 2026 7:27 PM

Line	Task	Parts	Labor	Total		
1	✓ Ecm communication issues	\$0.00	\$0.00	\$0.00		
2	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00		
3	✓ change diff filters	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LF3311 - Rockwell diff filter	Kropp Shop		2.0	\$0.00	\$0.00
4	✓ Change air filters	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	AF4195 - air filters T800	Kropp Shop		2.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

W5 - 2015 Kenworth t800

CLOSED

Serial	Tag	Closed Meters
1NKDXPEX3FR977194	k93133	19,890 hr & 836,393 km

Type	Created	Scheduled	Due	Started	Closed
Cvip inspection	Jun 15, 2026	Jun 15, 2026		Jun 15, 2026 10:48 AM	Jul 10, 2026 4:59 AM

Line	Task	Parts	Labor	Total
1	✓ CVIP inspection (wheels off)	\$0.00	\$0.00	\$0.00
2	✓ Air filters	\$0.00	\$0.00	\$0.00
3	✓ change diff filters	\$0.00	\$0.00	\$0.00
4	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
5	✓ Fix lights	\$0.00	\$0.00	\$0.00
Notes R/H rear skirt light, L/h and r/h mirror lights, top roof marker, r/h front fender light				
6	✓ change windshield	\$0.00	\$0.00	\$0.00
Notes Right hand				
7	✓ replace wishbone bushings	\$0.00	\$0.00	\$0.00
8	✓ Dust cover	\$0.00	\$0.00	\$0.00
9	✓ Fuse panel cover	\$0.00	\$0.00	\$0.00
10	✓ Fix hood	\$0.00	\$0.00	\$0.00
Notes Repair L/h side				
11	✓ oil leak (compressor o ring)	\$0.00	\$0.00	\$0.00

W5 - 2015 Kenworth t800

CLOSED

12	✓ seat shock	\$0.00	\$0.00	\$0.00
13	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

W5 - 2015 Kenworth t800

CLOSED

Serial	Tag	Closed Meters
1NKDXPEX3FR977194	k93133	19,892 hr & 857,597 km

Type	Created	Scheduled	Due	Started	Closed
Service	Jul 13, 2026	Jul 13, 2026		Jul 13, 2026 10:31 AM	Jul 13, 2026 10:32 AM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
2	✓ Diff output seal	\$0.00	\$0.00	\$0.00
	Notes			
	Front diff seal and middle diff seal			
3	✓ Dust cover	\$0.00	\$0.00	\$0.00
	Notes			
	#2LHS and #3LHS			

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

W5 - 2015 Kenworth t800

CLOSED

Serial	Tag	Closed Meters
1NKDXPEX3FR977194	k93133	19,892 hr & 857,597 km

Type	Created	Scheduled	Due	Started	Closed
	Jul 23, 2026	Jul 23, 2026		Jul 25, 2026 1:47 PM	Jul 31, 2026 8:37 AM

Line	Task	Parts	Labor	Total		
1	✓ Mid Lh drive brake pot	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	3030 brake pot	Kropp Shop		1.0	\$0.00	\$0.00
2	✓ middle diff input yoke loose	\$0.00	\$0.00	\$0.00		
3	✓ Middle diff u joint	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	Cap loose					
4	✓ mainshaft u joint	\$0.00	\$0.00	\$0.00		
5	✓ s cam u bokts	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	s cam u bolt	Kropp Shop		4.0	\$0.00	\$0.00
6	✓ pto cover leak	\$0.00	\$0.00	\$0.00		
		Part Cost				\$0.00
		Labor				\$0.00
		Subtotal				\$0.00
		Tax 1 (0.0%)				\$0.00
		Tax 2 (0.0%)				\$0.00
		Credit				(\$0.00)
		Total Cost				\$0.00

W5 - 2015 Kenworth t800

CLOSED

Serial	Tag	Closed Meters
1NKDXPEX3FR977194	k93133	19,957 hr & 861,476 km

Type	Created	Scheduled	Due	Started	Closed
	Aug 7, 2026	Aug 7, 2026		Aug 7, 2026 8:10 AM	Aug 7, 2026 8:10 AM

Line	Task	Parts	Labor	Total
1	✓ Oil change	\$0.00	\$0.00	\$0.00
	Notes			
	15/40 and changed both filters			
2	✓ Fuel filters	\$0.00	\$0.00	\$0.00
3	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
	Part Cost			\$0.00
	Labor			\$0.00
	Subtotal			\$0.00
	Tax 1 (0.0%)			\$0.00
	Tax 2 (0.0%)			\$0.00
	Credit			(\$0.00)
	Total Cost			\$0.00