

Engine History

H06-2

VIN: 471684 / ESN: 80353760

06/11/2024

Km / 8,514 hrs / 288,912 L

Complaint: Chuffing noise from intake

Cause: Intake valve chipped #5, coolant thermostat sticking, belt tensioner notchy

Correction: Replace the below components:

- Cylinder head
- Injector
- Coolant thermostat
- 1x Connecting Rod
- Turbocharger
- Upper engine gasket set
- Belt tensioner

27/01/2026

946,620km / 1,234 hr / 402,958 L

Complaint: Oil temp gets hot on big pulls

Cause: Oil thermostat stuck closed

Correction: Replace oil thermostat