

Number	Type	Date Open	Date Closed	Kilometres	Clos	HoursClosed	Fuel Usage	Clos	Fault	Repairer / Notes	Cost / Invoice		
R-8310	Seat	02/01/2025	11/20/2025	0		2,500		0		9765 Porter Equipment	REPALCED TOP AND BOTTOM RAILS WITH AFTER MARKET ONES.	\$0.00	
S-7354	B - 500	10/10/2025	11/20/2025	0	2,501	501		0		internal workshop	ACTUALLY DONE AT 2592 HRS.	\$0.00	
R-8570	Batter bucket	05/20/2025	05/22/2025			2,031		0		10359	FLIPPED CUTTING EDGE WITH NEW BOLTS AND NUTS. Internal Workshop - Field Service	LOOSE ENGINE MOUNTS/ RETENSND. FLIPPED MUD BUCKET CUTTING EDGE.	\$0.00
S-6998	C - 1000	06/03/2025	05/20/2025	0	2,000	1,00		0			ACTUALLY DONE AT 2026.	\$0.00	
R-8457	Grease nipple	04/02/2025	05/01/2025			1,942		0		10076	REPLACED GREASE NIPPLES OM SLEW.	\$0.00	
R-8228	Cracks	12/18/2024	05/01/2025			1,942		0		9619	Base Metal Fabrication	CRACKS HAVE BEEN REPAIRED	\$0.00
R-7924	Grouser	09/12/2024	05/01/2025	0		1,942		0	9089, 9438	Internal Workshop - Field Service	TENSIONED ALL GROUSERS.	\$0.00	
R-8102	reverse camera	10/28/2024	02/25/2025			1,682		0		9384	work. Internal Workshop - Field Service	Removed cutting edge cleaned and replaced edge	\$0.00
R-8106	Cutting Edge	10/30/2024	01/24/2025			1,569		0		9403	with new bolts	Supplied by WPA	\$0.00
S-6736	B - 500	01/07/2025	01/06/2025	0	1,500	500		0		Internal Workshop - Field Service	ACTULLAY DONE AT 1541HRS	\$0.00	
R-7380	thumb ram	04/11/2024	10/15/2024			1,220		0	8011, 8137, 904	Internal Workshop - Field Service	Removed cylinder and had it re rodde, fitted back to machine.	\$0.00	
S-6391	C - 1000	07/12/2024	08/05/2024	0	1,000	1,00		0		Internal Workshop - Field Service	grab cylinder leaking from dust seal. ACTUALLY SERVICED AT 1014HRS.	\$0.00	
R-7623	HYD Hose	06/24/2024	07/08/2024			881		0		8460	less then factory ones to minimise this again.	\$0.00	
R-7359	Grab	04/09/2024	04/09/2024			483		0		Internal Workshop - Field Service	Replace plate	\$0.00	
R-7309	Beacon	03/18/2024	04/08/2024			483		0		7902	Internal Workshop - Field Service	Beacon faulty	\$0.00
S-6156	B - 500	03/28/2024	03/28/2024	0	461	461		0				\$0.00	
R-6409	Cracks	06/28/2023	06/28/2023	0		283		0		Internal Workshop - Fabrication	Repairs by Danny as per attached job card.	\$0.00	
R-6296	Quick Hitch	05/31/2023	05/31/2023					0		Nix Line Boring & Welding	Repairs to Quick hitch bored to suit bushes Line bore quick hitch clamp bores Done by Nix Line Boring and Welding Invoice attached.	\$0.00	