

TAX INVOICE *OVERDUE

Redland Premium Fruit Pty Ltd

85108.S - Removed wheels from left hand rear, replaced

Invoice Date 11 Mar 2024

Invoice Number INV-0453

Reference PO-1225

ABN 55 659 650 718

D.C. Truck Maintenance

Pty Ltd 20 Vickers St KIALLA VIC 3631 AUSTRALIA

dctruckmaintenance@gma

il.com

0417 154 545

Description	Quantity	Unit Price	GST	Amount AUD
Contracted Work Monday 4th March: Y29061 YV98CL Carried out trailer services	3.50	100.00	10%	350.00
Consumables	5.00	20.00	10%	100.00
Grease	1.00	11.00	10%	11.00
Contracted Work Tuesday 5th March: YSQ254 Fit gate and uprgiht rollers to hand side of body. Flat batteries, load test batteries to find failed batteries, removed and replaced batteries	6.50	100.00	10%	650.00
YSQ262 - Removed engine and transmission From K200. Toyota Forklift 7070: Coolant light on in dash, checked coolant level, very low, topped up coolant.				
NI50EN - Neuton Power	2.00	370.50	10%	741.00
Contracted Work Wednesday 6th March: YSQ262 - Traveled to eastfields to get failed engine for parts. Yale Forklift - Forklift overheating, found radiator very low on coolant, topped up coolant level, found radiator blocked, cleaned out radiator and all of engine bay.	9.00	100.00	10%	900.00
WFS700 - Driver reported engine brakes not working, inspected for clutch switch not working.				
85108.S - Inspected wheel stud reported by tyre fitter.				
Contracted Work Thursday 7th March: 85108.S - Traveled to Pogues Rd Bunbartha to orchard. Left hand middle hub cap smashed off. Removed and replaced hub cap, top up oil level. WFS700 - removed and replaced failed switch for engine brakes, adjusted switch	6.50	100.00	10%	650.00



GRAHAM THOMSON MOTORS





SHEPPARTON TRUCK CENTRE PTY. LTD. A.C.N. 147 859 210 A.B.N. 92 147 859 210 CNR. DOYLES & NEW DOOKIE ROADS PO BOX 6116 SHEPPARTON VIC 3632 PHONE: (03) 5821 3977 FAX: (03) 5821 9547

BANK DETAILS: NAB 083-764 189430118

Service TAX Invoice	CUSTOMER COPY	Date: (02/10/23	Document Number:	527448
Customer Details		Reg No. 85108S	Stock No. T38932	Advisor COREY SEIGEL	Terms 3 0
REDLAND PREMIUM FRUIT PTY LTD P.O. BOX 369 MOOROOPNA VIC 3629		Current Klms	Body No.	Wty Start Date 30/01/12	Wty Expiry Date
		Vehicle Identification Number 6F80000000B082056		Build Date 01/12	Compliance Date
Contact No. Today 0358 299 446	Contact Today JEFTOMSON TRANS	Engine Number		Selling Dealer	Delivery Date
Driver Name	Driver Phone	PP# PPP DCODE/12		Fleet No.	Order No. ENG67131
Ccard No. 12013	Home No.	Vehicle Description FREIGHTER			Body Type
Mobile No.	Work No. 03 5823 8244	Model MAXI	Cotour BL	Sale Kims	Ext Wty Type
Email Address accountspayable.ra@redl		Booked 25/09/23 08:00AM	Required 25/09/23 04:30PM	Ext Wty Exp Date	Ext Wty Exp KM

Work Description

RH REAR SIDE LIGHT BROKEN 1 R

P: RH REAR SIDE LIGHT TO BE REPLACED

C: BROKEN

R: REMOVED AND REPLACED LIGHT, WIRED IN TEST OK.

Labour RH REAR SIDE LIGHT BROKEN Parts (F1) Lamp-Led Red/Amber (F1) Terminal Adhesive Single

Amount Operation 53.98 Unit Price Amount Qty Num/Ref 17.64 17.64 1 K*91602BL 2.78 1.39 2 K*56350-1 74.40 Total Item 1

REPLACE ALL 6 AIRBAGS AS PERISHED 2 R

P: ALL 6 AIRBAGS TO BE REPLACED

C: PERISHED/RWC ITEM

R: SUPPORTED CHASSIS, REMOVED AIRLINES, REMOVED ALL AIRBAGS, FIT NEW AIRBAGS, REFIT LINES, REMOVED CHASSIS

SUPPORTS.

Labour REPLACE ALL 6 AIRBAGS AS PERISHED Parts (F1) Airbag-Hend Ht230 (F1) Fitting Push To Connect

Amount Operation 674.78 Amount Unit Price Qty Num/Ref 309.37 1856.22 6 K*S-21208 6.93 1 K*VS68PTC-6-4 6.93 Total Item 2 2537.93

Sublet

(R2) CONSUMABLES/ENVIRO LEVY

15.29 15.29 Total Sublet

Total Costs

Total Invoice (excluding GST) Total Goods & Services Tax Total Invoice (including GST)

262.76 2890.38

Amount Due

2890.38

Amount

2627.62

Payment Details

SubAcct 53072

Ref No. 527448

Date 02/10/23 Detail

Next Service Details

Continued Over

Our services comes with gauarantess that cannot be excluded umder the Australian Consumer Law. For major failures with service, you are entitled; .to a refund for the unused portion, or to componsation for its reduced value.