



Vehicle History Summary

5

Fleet #	
Registration	
Make	Kenworth
Model	T409
VIN / Chassis #	6F5000000DA448836
Build Date	2013

Date	Reading / Units	Type / Repairer Notes	Repairer
21/08/2026	818,046 kms	Fault R-4176 Booked in for replacement	Internal Workshop
20/08/2026	817,421 kms	Fault R-4170 Booked in for replacement	Internal Workshop
19/08/2026	229,580 kms	Fault R-4164 Book in for replacement windscreen	Internal Workshop
18/08/2026	816,253 kms	Fault R-4154 Minor damage all secure	Internal Workshop
17/08/2026	815,986 kms	Fault R-4147 Minor damage all secure	Internal Workshop
14/08/2026		Fault R-4145 Minor damage all secure	Internal Workshop
05/08/2026	811,938 kms	Fault R-4138 Booked in for replacement	Internal Workshop
29/07/2026	809,024 kms	Fault R-4130 Minor damage all secure	Internal Workshop
21/07/2026	805,136 kms	Fault R-4102 Minor damage all secure	Internal Workshop
20/07/2026	804,659 kms	Fault R-4095 Minor chip and crack all ok	Internal Workshop
17/07/2026		Fault R-4087	
11/07/2026	801,251 kms	brake adjustment, wheel alignment R-4240 performed trailer wheel alignment and brake adjustment	Internal Workshop
10/07/2026	800,834 kms	leaks, maxi brake, tail lights, tyres R-4237 repaired hose removed + replaced 4x drive tyres , 2x steer tyres repair broken taillight bracket	Internal Workshop
09/07/2026	800,389 kms	clearance lights, maxi brake, tyres R-4236 removed + replaced 4x tyres 3rd, 4th axle D/S remove + replaced maxi park brake valve repaired clearance lamp on P/S bin - truck	Internal Workshop
07/07/2026	799,532 kms	gearbox, tarp pulley R-4231	Internal Workshop

Date	Reading / Units	Type / Repairer Notes	Repairer
		diagnosed faulty gearbox clutch on tarp diagnosed seized pulleys manually wound up tarp to cover so truck could deliver load	
02/07/2026	798,771 kms	maxi brake R-4229 replaced maxi brake valve roll pin repaired cigarette lighter	Internal Workshop
30/06/2026	793,633 kms	air leak, clearance lights, tyres R-4222 removed + replaced x2 tyre 3rd axle P/S dog removed +replaced front position clearance light removed + replaced side position clearance light P/S removed + replaced top steer shock rubber fixed airleak @ bulkhead	Internal Workshop
22/06/2026		Fault R-3963 Check lights	
15/06/2026	793,633 kms	puncture, tyres R-4215 Removed + replaced punctured tyre 2nd axle dolly D/S outer	Internal Workshop
13/06/2026	790,687 kms	Maxi alarm, tyres R-4213 replaced x 4 drive tyres 2nd drive organised maxi door brake alarm installation	Internal Workshop
26/05/2026		Alternator, batteries R-4204 load tested batteries and cabling between alternator and batteries - low voltage found removed and replaced faulty alternator re-tested all circuits - successful readings	Internal Workshop
11/05/2026		puncture R-4195 Puncture repair on 4th axle D/S +P/S outer tyres	Internal Workshop
07/05/2026		tyres R-4189 Fitted new tyre and rim to 4th axle dog P/S Outer per puncture	Internal Workshop
05/05/2026	776,363 kms	abs R-4182 ABS Modular valve fitting	Internal Workshop
09/04/2026	770,979 kms	HORTON FAN R-3692 replaced Horton	Internal Workshop
24/03/2026	765,657 kms	Tarp R-3701 repaired broken tarp wiring at rear of truck	Internal Workshop
21/03/2026	764,777 kms	Airbag R-3591 Replaced leaking airbag on trailer fourth axle passenger side Replaced passenger side steer mud flap	Internal Workshop
12/03/2026	760,384 kms	Mudflaps R-3590 Adjusted all brakes Fitted mud flap to dolly	Internal Workshop
11/03/2026	760,334 kms	Breakdown, Tarp R-3589 Breakdown call out tarp not working Found cable off roller Refitted cable to roller Tightened cable	Internal Workshop
08/01/2025	707,010 kms	windscreen R-1476	
06/01/2025	706,735 kms	mudflap R-1463	
22/11/2024	701,154 kms	C - 100k S-1278 -C service Completed	Internal Workshop
11/11/2024	701,154 kms	Air Conditioner, air leak, CLUTCH, EXHAUST LEAK, Lights, OIL LEAKS, seat belt, TYRE R-1394 repaired the following: -Steer tyres -L/H cab shock leaking -Air leaks -Exhaust leaks -AC inop -seat belt fraued -Clutch Rose joints & crank -Mirror light broken R/H Hard starting	Internal Workshop
31/10/2024	700,492 kms	TYRE R-1029 replaced 2 front steer tyres	
31/10/2024	700,492 kms	mudguard R-1030	

Date	Reading / Units	Type / Repairer Notes	Repairer
		replaced new front dolly mud guard and pole	
14/10/2024	698,852 kms	A - 10k S-763 A Service Carried out A Service Checked all Levels. All ok	
08/10/2024	697,942 kms	TYRE R-861	Internal Workshop
02/10/2024	697,275 kms	General R-863 replaced gearstick as had snapped	Internal Workshop
04/09/2024	688,850 kms	B - 50k S-639 B Service Carried out B Service Changed Oil Filter Oil Coolant All Ok	Internal Workshop
22/07/2024	678,349 kms	TYRE R-743	
04/06/2024	675,864 kms	A - 10k S-762 A Service Carried out A Service Checked all Levels. All ok	Internal Workshop

Signed: _____

Name: _____

Date: _____