

SERVICE TAX INVOICE

Invoice To: 2965
WAGNER INVESTMENTS PTY LTD
PO BOX 151
DRAYTON QLD 4350

Deliver To:
Wagners Holding Company Limited
ABN 49 622 632 848
11 Ballera Court
WELLCAMP QLD 4350

Document No.: 3569803
Document Date: 20/06/2025
Repair Order No.: 930671
RO Creation Date: 27/05/2025
Rego No.: XQ89HS
Make/Model: 2020 KENWORTH T659
Vehicle ID No.: 6F500000LA467289
Fleet No: TKP00769
Odometer:
Engine Hours:
Delivery Date: 07/03/2020
Invoice To: 2965
Customer ABN: 66011055271
P/Order No.: AU00019792
Page: 1 of 1

ESTDIFREB

Strip down, clean and inspect Front DANA 251626.

Strip down diff. Clean and inspect. Found crown wheel and pinion damaged, also the power divider had been damaged as well. Diff not viable to rebuild. Remove from roll over frame, put into spare parts crate.

Ordered a new diff centre. Send to Mt Isa.

**** New diff Serial Number: 341391 ****

<u>Part Number</u>	<u>Part Description</u>	<u>Quantity</u>
515909	Misc	1.00

Advisor: Ian Wayman

Workshop Trading Hours: Mon-Fri 7am to 6pm, Sat 8am to 12pm

*** Refrigerant trading authority number: AU13435 ***

Bank Account Details for Direct Payments:

Bank: CBA Branch: Kyogle

BSB: 062563 Account No.: 10059314 Account Name: The Brown and Hurley Group Pty Ltd

Customer's Signature

SERVICE TAX INVOICE

Invoice To: 2965
WAGNER INVESTMENTS PTY LTD
PO BOX 151
DRAYTON QLD 4350

Deliver To:
Wagners Holding Company Limited
ABN 49 622 632 848
11 Ballera Court
WELLCAMP QLD 4350

Document No.: 3448150
Document Date: 31/01/2025
Repair Order No.: 915542
RO Creation Date: 9/01/2025
Rego No.: XQ89HS
Make/Model: 2020 KENWORTH T659
Vehicle ID No.: 6F500000LA467289
Fleet No: TKP00769
Odometer:
Engine Hours:
Delivery Date: 07/03/2020
Invoice To: 2965
Customer ABN: 66011055271
P/Order No.: AU00019816
Page: 1 of 1

ESTDIFREB Strip down, clean and inspect parts, rebuild Rear SISU 291995

Cross lock not working.

Cause. Engaging cross lock with high wheel spin

Remove carrier cap clean and check bearings and remove crown wheel. Unbolt hemishpere and remove cross lock sliding gear and side gear, clean up hemisphere. make sure sliding gear slides. used secondhand sliding gear and side gear, replace membrane check operation of crosslock.

Wrap in plastic, send to Mt Isa

<u>Part Number</u>	<u>Part Description</u>	<u>Quantity</u>
172-351-1202	MEMBRANE	1.00

Advisor: Ian Wayman

Workshop Trading Hours: Mon-Fri 7am to 6pm, Sat 8am to 12pm

*** Refrigerant trading authority number: AU13435 ***

Bank Account Details for Direct Payments:

Bank: CBA Branch: Kyogle

BSB: 062563 Account No.: 10059314 Account Name: The Brown and Hurley Group Pty Ltd

Customer's Signature

SERVICE TAX INVOICE

Invoice To: 2965
WAGNER INVESTMENTS PTY LTD
PO BOX 151
DRAYTON QLD 4350

Deliver To:
Wagners Holding Company Limited
ABN 49 622 632 848
11 Ballera Court
WELLCAMP QLD 4350

Document No.:	3160813
Document Date:	25/03/2024
Repair Order No.:	880632
RO Creation Date:	19/03/2024
Rego No.:	XQ89HS
Make/Model:	2020 KENWORTH T659
Vehicle ID No.:	6F5000000LA467289
Fleet No:	TKP00769
Odometer:	
Engine Hours:	
Delivery Date:	07/03/2020
Invoice To:	2965
Customer ABN:	66011055271
P/Order No.:	5059384
Page:	1 of 1

*SCSFE2 Overhaul ISRI drivers seat.(Replace with new)

Seat covers, S&F both (Eldorado, KAB, Isri)
Overhaul ISRI Drivers Seat (Replace with new)
Strip down and inspect ISRI seat. Found seat to badly worn and unviable to repair. Seat replaced with a new assembly.
Seat assembly 6860/870 Big Foam with isolator, Black/Burgundy Trim.
Serial Number: 20240308

*CABMISC Overhaul ISRI Drivers seat.(TKP769)

Cab & Bonnet Misc
Overhaul ISRI Drivers Seat (TKP769)
Refurbish 6860/870 Seat.
Replace ISRI damper, Valve level kit, airline kit, dump valve, recline knob, seat foam cushion.
Strip seat, hot wash, repair and replace bent broken parts. Fit new seat belt.

Advisor: Ian Wayman

Workshop Trading Hours: Mon-Fri 7am to 6pm, Sat 8am to 12pm
*** Refrigerant trading authority number: AU13435 ***

Bank Account Details for Direct Payments: Customer's Signature
Bank: CBA Branch: Kyogle
BSB: 062563 Account No.: 10059314 Account Name: The Brown and Hurley Group Pty Ltd

SERVICE TAX INVOICE

Invoice To: 2965
 WAGNER INVESTMENTS PTY LTD
 PO BOX 151
 DRAYTON QLD 4350

Deliver To:
 Wagners Holding Company Limited
 ABN 49 622 632 848
 11 Ballera Court
 WELLCAMP QLD 4350

Document No.: 2347614
Document Date: 30/11/2021
Repair Order No.: 697911
RO Creation Date: 7/07/2021
Rego No.: XQ89HS
Make/Model: 2020 KENWORTH T659
Vehicle ID No.: 6F5000000LA467289
Fleet No: TKP00769
Odometer:
Engine Hours:
Delivery Date: 07/03/2020
Invoice To: 2965
Customer ABN: 66011055271
P/Order No.: 5023110
Page: 1 of 2

ESTDIFREB

Estimate to complete Differential Rebuild DANA FRONT

Serial Number: 203548 (211312 New Fitted)

Set diff up in the roll over frame. Strip down the diff assembly. Inspect for damage, found intermediate diff seized due to broken gear teeth. Clean up parts, order parts. Assemble diff, fit updated power divider kit. Set pre load and back lash. Put diff back in transport crate, send back to Mt Isa.

Serail Number: 203548

Repair pinion as required GM

<u>Part Number</u>	<u>Part Description</u>	<u>Quantity</u>
513878-A	KIT-MANIFOLD PARTS	1.00
504364-1	LUBE PUMP KIT	1.00
512892-A	KIT - AIR LOCKOUT REPAIR D170/	1.00
139974	BEARING CUP	1.00
140012	BEARING CUP-HALF FLANGE	1.00
<i>Comments: NIL PDC</i>		
140014	BEARING CUP-FLANGE HALF	1.00
<i>Comments: 1 x arrived 23/07/21 IC</i>		
300HS100-1	THRUST WASHER	4.00
139968	PINION BEARING INNER	1.00
<i>Comments: PDC ARRIVED 15/07/21 JB</i>		
139969	PINION CUP	1.00
<i>Comments: PDC</i>		
<i>ARRIVED 15/07/21 JB</i>		
131343	GEAR	1.00
<i>Comments: MELB</i>		
139971	PINION BEARING CONE	1.00
<i>Comments: PDC ARRIVED 15/07/21 JB</i>		
139972	PINION BRG CUP	1.00
<i>Comments: PDC</i>		
<i>ARRIVED 15/07/21 JB</i>		
131095K	NUT-INPUT	1.00

SERVICE TAX INVOICE

Invoice To: 2965
WAGNER INVESTMENTS PTY LTD
PO BOX 151
DRAYTON QLD 4350

Deliver To:
Wagners Holding Company Limited
ABN 49 622 632 848
11 Ballera Court
WELLCAMP QLD 4350

Document No.: 2347614
Document Date: 30/11/2021
Repair Order No.: 697911
RO Creation Date: 7/07/2021
Rego No.: XQ89HS
Make/Model: 2020 KENWORTH T659
Vehicle ID No.: 6F500000LA467289
Fleet No: TKP00769
Odometer:
Engine Hours:
Delivery Date: 07/03/2020
Invoice To: 2965
Customer ABN: 66011055271
P/Order No.: 5023110
Page: 2 of 2

FREIGHT	FREIGHT	1.00
<i>Comments: VOR X DANA MELBOURNE</i>		
HS108-1	THRUST WASHER - SIDE GEAR	2.00
131008K	KIT-PINION OIL SEAL & NUT	1.00
129947	Misc	1.00
140019	BEARING CONE	2.00
<i>Comments: arrived 27/08/21</i>		
140020	BEARING CUP	2.00
<i>Comments: ARRIVED 06/09/21 IC</i>		
L0C44279	LOCTITE 263 STUD LOCK	1.00

Advisor: Ian Wayman

Workshop Trading Hours: Mon-Fri 7am to 6pm, Sat 8am to 12pm
*** Refrigerant trading authority number: AU13435 ***

Bank Account Details for Direct Payments:

Bank: CBA Branch: Kyogle
BSB: 062563 Account No.: 10059314 Account Name: The Brown and Hurley Group Pty Ltd

Customer's Signature

SERVICE TAX INVOICE

Invoice To: 11065
KENWORTH WARRANTY NEW - TWBA (07)
28-30 CARRINGTON ROAD
TORRINGTON
QUEENSLAND 4350

Deliver To:
Wagners Holding Company Limited
ABN 49 622 632 848
11 Ballera Court
WELLCAMP QLD 4350

Document No.: 2344613
Document Date: 26/11/2021
Repair Order No.: 711690
RO Creation Date: 19/11/2021
Rego No.: XQ89HS
Make/Model: 2020 KENWORTH T659
Vehicle ID No.: 6F5000000LA467289
Fleet No.: TKP00769
Odometer: 570008
Engine Hours:
Delivery Date: 07/03/2020
Invoice To: 11065
Customer ABN:
P/Order No.:
Page: 1 of 1

*FSC RH Steer spring broken the 4th leaf from the top on the rear side.

Front Springs - 50/50 between B&H and Paccar

**

Claim number 424803

Sundry side of claim

Part Number

Part Description

Quantity

B81-1039

SPRING-FRONT MULTI LEAF

1.00

Comments: dispatch direct from townsville to Mt isa

Advisor: Michelle Read

Workshop Trading Hours: Mon-Fri 7am to 6pm, Sat 8am to 12pm

*** Refrigerant trading authority number: AU13435 ***

Bank Account Details for Direct Payments:

Bank: CBA Branch: Kyogle

BSB: 062563 Account No.: 10059314 Account Name: The Brown and Hurley Group Pty Ltd

Customer's Signature

SERVICE TAX INVOICE

Invoice To: 11065
KENWORTH WARRANTY NEW - TWBA (07)
28-30 CARRINGTON ROAD
TORRINGTON
QUEENSLAND 4350

Deliver To:
Wagners Holding Company Limited
ABN 49 622 632 848
11 Ballera Court
WELLCAMP QLD 4350

Document No.: 2322871
Document Date: 29/10/2021
Repair Order No.: 708093
RO Creation Date: 15/10/2021
Rego No.: XQ89HS
Make/Model: 2020 KENWORTH T659
Vehicle ID No.: 6F5000000LA467289
Fleet No.: TKP00769
Odometer: 524424
Engine Hours:
Delivery Date: 07/03/2020
Invoice To: 11065
Customer ABN:
P/Order No.:
Page: 1 of 1

K024-1 RH Rear spring broken.

50/50 Split, Paccar and B& H. As Agreed by Mark Proctor

Supplied part to customer.
Customer fit to vehicle.
Claim 50/20 as per agreement between B&H and Paccar.
**
Claim number 423602

<u>Part Number</u>	<u>Part Description</u>	<u>Quantity</u>
K223-1229	SPRING ASSY	1.00

Advisor: Michelle Read

Workshop Trading Hours: Mon-Fri 7am to 6pm, Sat 8am to 12pm
*** Refrigerant trading authority number: AU13435 ***

Bank Account Details for Direct Payments: Customer's Signature
Bank: CBA Branch: Kyogle
BSB: 062563 Account No.: 10059314 Account Name: The Brown and Hurley Group Pty Ltd

SERVICE TAX INVOICE

Invoice To: 11065
KENWORTH WARRANTY NEW - TWBA (07)
28-30 CARRINGTON ROAD
TORRINGTON
QUEENSLAND 4350

Deliver To:
Wagners Holding Company Limited
ABN 49 622 632 848
11 Ballera Court
WELLCAMP QLD 4350

Document No.:	2306920
Document Date:	12/10/2021
Repair Order No.:	706415
RO Creation Date:	29/09/2021
Rego No.:	XQ89HS
Make/Model:	2020 KENWORTH T659
Vehicle ID No.:	6F5000000LA467289
Fleet No:	TKP00769
Odometer:	524424
Engine Hours:	
Delivery Date:	07/03/2020
Invoice To:	11065
Customer ABN:	
P/Order No.:	
Page:	1 of 1

K024-1 Paccar policy contribution as per agreement

Supplied part to customer.
Customer fitting to vehicle.
**

Claim number 422635
**

Part number K223-1229
50/50 contribution

Advisor: Michelle Read

Workshop Trading Hours: Mon-Fri 7am to 6pm, Sat 8am to 12pm
*** Refrigerant trading authority number: AU13435 ***

Bank Account Details for Direct Payments:

Bank: CBA Branch: Kyogle
BSB: 062563 Account No.: 10059314 Account Name: The Brown and Hurley Group Pty Ltd

Customer's Signature