

L20-6



Mécanique générale
St-Thomas

88, Route 158, St-Thomas
(Québec) J0K 3L0
TEL: (450) 759-0004
Courriel : mgsttho@gmail.com

Facture

25697

Date: 16 jun, 2026

Page: 1

N° commande

#141

Vendu à:

Expédié à:

Article	Quantité	Description	Prix unitaire	Montant
108825-25	1.00	clutch	1,357.41	1,357.41
	1.00	fly wheel usiné	118.50	118.50
	1.00	transport	30.00	30.00
	1.00	shaft de clutch	202.75	202.75
	1.00	brake clutch	55.53	55.53
	1.00	shaft de clutch	75.35	75.35
	1.00	bearing	28.03	28.03
	1.00	bearing input	130.65	130.65
	1.00	input shaft	135.60	135.60
	1.00	retainer	47.50	47.50
	1.00	snap ring	3.10	3.10
	1.00	snap ring	4.35	4.35
	1.00	plaque de transfert	40.56	40.56
	8.25	heures ouvrage	105.00	866.25
	1.00	frais atelier	92.90	92.90
		freightliner changer clutch		
		Sous-total:		3,188.48

GQ - TPS 5%, TVQ 9.975%
TPS
TVQ

PAR E-MAIL LE 23 JUIN 2026



Montant dû

3,665.99