



EQUIPMENT SALES & SERVICE LIMITED

1030 (part) Toronto, ON M9W 4W3
Tel: 416-249-8141 Fax: 416-249-8912
Toll Free: 800-268-0679 www.essltd.com
BEST MANAGED COMPANIES
Platinum member

WORK SAFE

Ship to:

Drainville Ltd

Invoice to:

Drainville Ltd
1 Hickory Tree Road
Suite #1510
York ON M9N 3W4

Branch		
Toronto	Time	Page
Date	12:15:35 (O)	02
04/05/21	Phone No.	Work Order No.
Account No.	4169386824	W36847
DRAIN010	Purchase Order	
Ship Via	DENIS	
PICK UP	Hours to Complete	
Date	Salesperson	
	APA	

SERVICE WORK ORDER

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
007537	EXCAVATOR	1	80040066	
	TXC225LC-2	2		

out of the frames.
 Installed 2 x idlers and recoil springs in place. Installed both tracks and secured the master pins securely with lock pins.
 Installed and torqued the master pad and bolts. Adjusted the track tension, tested machine. The track tension should be set to suit site conditions upon return to site.
 Job complete.

*** During repair there was fuel leaking from the reservoir sight glass. Resealed the lower end of the sight glass***

ADDITIONAL DESCRIPTION:

Re & re 2 x track groups and deliver to the track shop to transfer the current shoes to new chains. Re & re 2x drive sprockets, 18x bottom rollers and 4x top rollers. The customer will be dropping the 4x top rollers off with the machine.
 Inspect the 2x front idlers and 2x track adjusters once the tracks are removed and advise. If idlers, track adjuster seals, etc. are required, service and parts will be charged extra as per quote.

K1000682	SPROCKET	2	N	350.00	700.00
K1000976A	ROLLER	18	N	235.00	4230.00
M16X1.5X90	FINE THREAD	72	N	3.95	284.40
270-00063J	IDLER DX225	2		875.00	1750.00
	PARTS				6964.40
	LABOR				4184.75
	SEGMENT TOTAL==>				11149.15

11040001
 SEGMENT# 3 5 JC04 . 01/05/21 03/10/21 02/28/21
 Front right carrier roller pedestal damaged 5.00

CONTINUED ON PAGE 03

CONFIRMATION OF WORK PERFORMED

Correction: _____

Customer Signature: _____

Details describing the cause and correction as well as all other related charges for labour, mileage, sundries and taxes will be included on the Service Invoice. If nobody is available for signature, this report will be emailed or faxed to the customer. E & O.E