

Job No.	Finish Date	Instructions	Km	Eng. Hrs	Labour \$	Supply \$	Total \$	Status
WK1-29213	04/02/22 13:30	STRIP OUT + FIT NUMBER PLATE LIGHT + WASH DOWN	519,069	0	447.50	29.98	477.48	Finalised
WK2-54046	27/01/22 16:10	A-SERVICE	515,395	0	45.00	20.00	65.00	Finalised
WK2-53752	19/01/22 10:28	CHECK FOR AIR LEAKS REPLACE LUMBAR SUPPORT SWITCH WITH GOOD SECOND HAND ONE + REPLACE WIPER BLADES	509,505	0	75.00	40.78	115.78	Finalised
WK2-53461	10/01/22 10:28	A+B SERVICE(CHASIS FUEL FILTER ONLY) (PYRO GAUGE NOT WORKING)	503,230	0	150.00	290.63	440.63	Finalised
WK2-53232	31/12/21 13:52	TRUCK FRIDGE NOT COOLING	502,730	0	90.00	20.00	110.00	Finalised
WK1-28403	11/12/21 00:00	RUNOUT POS1 A864027 INV161246	495,220	0	19.09	0.00	19.09	Finalised
WK2-51922	18/11/21 00:00	BALANCE & ROTATE STEER A13452 INV160558	491,154	0	45.45	0.00	45.45	Finalised
WK2-51651	16/11/21 16:00	A-SERVICE+HOTSET+FAULT FIND ELECTRICAL FAULT WITH INSTRUMET CLUSTER-NO GAUGES.	491,136	0	345.00	771.37	1,116.37	Finalised
WK2-51449	11/11/21 10:51	REPLACE TAILER PARK BRAKE HOBBS SWITCH	491,136	0	60.00	74.55	134.55	Finalised
WK2-51217	03/11/21 00:00	PUNCTURE REPAIR POS10 A921377 INV160133	487,863	0	156.35	0.00	156.35	Finalised
WK2-50574	20/10/21 08:45	REKIT HORTON FAN	484,598	0	210.00	625.60	835.60	Finalised
WK2-50427	15/10/21 07:09	A SERVICE	482,070	0	60.00	20.00	80.00	Finalised
WK2-49867	05/10/21 11:18	A+B-SERVICE	472,066	0	112.50	251.84	364.34	Finalised
WK2-49611	27/09/21 10:43	REPAIR WINDSCREEN DRIP TRAY+INSPECT TURBO FOR NOISE+PULL INTAKE TRUNK OFF TURBO+INSPECT TURBO FINS+END FLOAT IN TURBO SHAFT ALL INSPECTED FINE+TEST DRIVE TRUCK COULD NOT FAULT TURBO AT TIME OF TEST DRIVE. (MONITOR)	468,800	0	60.00	10.00	70.00	Finalised
WK2-49291	16/09/21 14:45	A+C-SERVICE+REPLACE BRACKET FOR CABING AIR FILTER+REPLACE ALL 4 DRAIN COCKS ON AIR TANKS	462,155	0	135.00	348.69	483.69	Finalised
WK2-48554	30/08/21 07:51	ROO STRIKE DAMAGE STEER HUB CAP. DRIVER DID TEMP REPAIR TO GET TO MELB SO CAN REPAIR.	0	0	92.45	0.00	92.45	Finalised
WK2-48440	26/08/21 08:06	A+B+D+SD+SE+ST.. ALL FILTERS ON THE OIL CHANGE	447,337	0	292.50	640.74	933.24	Finalised
WK2-48887	09/09/21 11:07	REPLACE TURBO DUMP PIPE CLAMP NUT, TAKEN PART FROM ANOTHER CLAMP.	444,130	0	60.00	10.00	70.00	Finalised
WK2-47690	05/08/21 12:22	A-SERVICE.	431,351	0	62.50	13.96	76.46	Finalised
WK1-27153	10/08/21 00:00	NEW STEER TYRES POS1+2 A13403 INV157462	0	0	1,083.64	0.00	1,083.64	Finalised
WK2-47176	20/07/21 16:31	A SERVICE + REPLACE R/H/F ENGINE MOUNT BRACKET	421,480	0	240.00	72.82	312.82	Finalised
WK2-46637	07/07/21 15:35	REPLACE BOTTOM RADIATOR MOUNTS + REPLACE REAR ENGINE MOUNTS + RESECURE R/H MIRROR BRACE + REPLACE EXHAUST GASKET AT FLEX	414,769	0	930.00	791.50	1,721.50	Finalised
WK2-46367	24/06/21 12:30	A & B SERVICE + INSPECT RHS STEER FOR LEAK, NOT LEAKING (GREASE GOT HOT AND RAN ONTO SHOES) CLEAN BRAKES AND HUB	409,220	0	112.50	251.84	364.34	Finalised
WK2-46132	18/06/21 10:00	REPLACE MAXI LINE FOR RL BOOSTER (RUBBED THROUGH ON ICEPACK HOSES)	403,420	0	15.00	4.43	19.43	Finalised
WK1-26020	18/06/21 00:00	RUNOUT POS1 INV156063 A920367	403,421	0	10.00	0.00	10.00	Finalised
WK2-45833	09/06/21 14:20	A SERVICE + REPAIR AUTO GREASER LINE ON R/H TIE ROD END + REPLACE RADIATOR SIGHT GLASS, REPLACE RH FRONT DRIVE BRAKE DRUM, SHOES AND WHEEL BEARINGS + REPLACE PARK BRAKE STICKER NO. 27812	397,545	0	277.50	242.15	519.65	Finalised
WK1-26137	09/06/21 00:00	TYRE ROTATION & PRESSURE MAINT POS1&2 INV155937 A920162	397,545	0	8.00	0.00	8.00	Finalised
WK2-45543	29/05/21 11:30	A SERVICE + REPLACE LHR BRAKE BOOSTER AIRLINE AND OLIVE IN RHR RIDE HEIGHT VALVE + REPLACE STARTER MOTOR	389,930	0	270.00	418.44	688.44	Finalised
WK2-45256	20/05/21 15:00	A + B + SE SERVICE (OIL FILTER ONLY) +TIGHTEN UP AIR FITTING ON RIDE HEIGHT VALVE+REPLACE WIPER BLADES+GREASE STEERING COLUM.	382,606	0	165.00	305.35	470.35	Finalised
WK1-25577	20/05/21 00:00	NEW DRIVE TYRES x8 (A920082)	382,606	0	3,854.54	0.00	3,854.54	Finalised
WK2-44883	07/05/21 17:00	A-SERVICE, REPLACE LF STEER SEAL DRUM AND BRAKE SHOES	373,339	0	247.50	436.40	683.90	Finalised

WK2-44448	23/04/21 14:00	A SERVICE + TOP UP ENGINE OIL 4L	366,850	0	0.00	27.73	27.73	Finalised
WK2-44173	15/04/21 16:59	DRIVER DROPPING SUZI TO TRUCK	0	0	0.00	130.11	130.11	Finalised
WK2-43910	08/04/21 11:00	A+B-SERVICE+(ALL FILTERS) + REPLACE EXHAUST BUSH TURBO DUMP	355,954	0	105.00	635.33	740.33	Finalised
WK1-24750	31/03/21 11:00	NOX SENSOR REPLACEMENT - WHILE AT CUMMINS FOR WARRNTY - OIL LEAK	0	0	939.00	0.00	939.00	Finalised
WK1-24751	29/09/21 13:52	WARRANTY REPAIR -CUMMINS-ENGINE DROPPED OIL AT COLUSSEM - TIMING COVER PLATE & BOLTS LOOSE	0	0	0.00	0.00	0.00	Finalised
WK2-43244	18/03/21 09:00	A+D-SERVICE+ST+SD,REPAIR WIRING TO R/H/S-BONNST INDICATOR,CLEAN OUT FRONT DIFF BREATHER, CHECK OVER + ZIPTIE ENGINE HARNESS, SINCE TRUCK JUST CAME OUT OF CUMMINS FOR REPAIRS.	343,615	0	157.50	265.80	423.30	Finalised
WK1-24377	30/09/21 07:21	ENGINE HYDRAULICING & LOOSING COOLANT	0	0	0.00	0.00	0.00	Finalised
WK2-42547	25/02/21 13:00	A-SERVICE + HOT SET + REPLACE LHR SERVICE LINE ON BRAKE BOOSTER	332,320	0	202.50	332.26	534.76	Finalised
WK1-24203	25/02/21 00:00	FIT R/OUT POS 3&4 (A920843)	332,320	0	20.00	0.00	20.00	Finalised
WK2-42206	15/02/21 11:00	A, B & SE SERVICE, REPAIR WINDSCREEN DRIP TRAY, PRESSURE TEST, CHECK + INSPECT INTERCOOLER (TESTED OK) & REPLACE INTERCOOLER HOSE ON TURBO. FILL AUTO GREASER.	326,273	0	187.50	352.05	539.55	Finalised
WK2-41961	06/02/21 13:37	SUPPLY ADBLUE CAP	0	0	0.00	54.00	54.00	Finalised
WK1-23919	03/02/21 13:11	WARRANTY - HILL START ASSIST BRAKE PIPING SAFTEY RECALL 20-01	0	0	0.00	0.00	0.00	Finalised
WK1-24439	01/02/21 14:00	BATTERY'S FAULTY STEALTH INV 63603	0	0	1,080.00	0.00	1,080.00	Finalised
WK2-41347	19/01/21 16:15	WARRANTY CLAIM - REPLACE BOTH HEADLIGHTS SUPPLIED BY B/H	316,163	0	45.00	10.00	55.00	Finalised
WK1-23523	19/01/21 00:00	NEW STEER TYRES (A920958)	316,163	0	1,083.64	0.00	1,083.64	Finalised
WK2-41154	13/01/21 10:00	A-SERVICE, PULL FUEL TANK OF TO BE WELDED UP, DUE TO PIN HOLE IN TANK, GREASE CLUTCH & CLEAR G.I CODE.	309,975	0	217.50	20.45	237.95	Finalised
WK1-23077	30/12/20 00:00	ROTATE STEER TYRES (A921017)	299,705	0	5.00	0.00	5.00	Finalised
WK2-40567	23/12/20 08:00	A-SERVICE, REPLACE AFTERTREAT HOSE TO DOSAGE INJECTOR.	296,120	0	105.00	71.95	176.95	Finalised
WK2-40399	16/12/20 13:00	A,B SERVICE (OIL FILTER ONLY), CHECKED BATTERY'S TESTED FINE TOPPED UP WATER.	289,385	0	187.50	240.14	427.64	Finalised
WK2-39908	02/12/20 10:00	A SERVICE, REPLACE FRONT CAB MOUNTS	279,405	0	187.50	449.94	637.44	Finalised
WK2-39183	10/11/20 13:31	A,B,SE SERVICE (FUEL AND OIL FILTER), WATER FILTER.... ADBLU SERVICE...REPLACE AD BLU INJECTOR HOSE AND NUT (ALL MISSING)	264,775	0	210.00	571.33	781.33	Finalised
WK2-38790	29/10/20 16:00	A-SERVICE..REPLACE LHFF & LHFR AIRBAGS..REPLACE FRONT DIFF BREATHER HOSE, REPLACE LH FRONT DRIVE DRUM SHOES AND BEARINGS	256,255	0	240.00	819.61	1,059.61	Finalised
WK2-38541	21/10/20 12:28	A SERVICE + REPLACE POWER STEERING SUCTION HOSE	249,105	0	195.00	165.67	360.67	Finalised
WK1-21673	19/10/20 08:26	FIT NEW TYRES POS 1&2 (A876977)	243,965	0	1,083.64	0.00	1,083.64	Finalised
WK2-38292	16/10/20 10:50	A-SERVICE, D-SERVICE, SAMPLE DIFFS, SAMPLE TRANSMISSION, REPLACE LH REAR DRIVE AIR BAG.REPLACE COOLANT HOSE.	243,965	0	285.00	544.80	829.80	Finalised
WK2-37978	30/09/20 14:06	A,B SERVICE (OIL FILTER ONLY), REPLACED RHF STEER BRAKE LININGS AND DRUM, REPLACED RHR DRIVE BRAKE LININGS DRUM AND WHEEL SEAL, TESTED BATTERY'S, FOUND LOOSE EARTH WIRE,	235,385	0	480.00	900.57	1,380.57	Finalised
WK1-21369	26/09/20 17:00	REPLACE ALTERNATOR PACCAR INV 965129	0	0	1,367.92	0.00	1,367.92	Finalised
WK2-37881	26/09/20 15:40	HAD ALTERNATOR LIGHT ON DASH AND NOT CHARGING IN MELBOURNE DEPOT, GOT PACCAR OUT.	0	0	60.00	0.00	60.00	Finalised
WK2-37549	16/09/20 17:00	MAKE BRACKETS, MISSING BOLTS AND SECURE REAR DECK PLATE.	226,685	0	75.00	11.65	86.65	Finalised
WK2-37426	12/09/20 12:10	A + C SERVICE	223,660	0	180.00	259.15	439.15	Finalised
WK1-20944	01/09/20 14:00	BALANCE + ROTATE STEER TYRES (A876908)	216,620	0	50.45	0.00	50.45	Finalised
WK2-37012	01/09/20 09:00	REPLACE NOX SENSOR	216,567	0	47.50	780.86	828.36	Finalised

WK2-37008	01/09/20 11:00	A & G SERVICE REPLACE ENGINE MOUNTS	216,567	0	166.25	407.49	573.74	Finalised
WK1-20840	27/08/20 14:00	SUPPLIED SPOTTER MIRROR TO OPERATIONS FOR DRIVER TO COLLECT / REPLACE	0	0	0.00	25.76	25.76	Finalised
WK2-36718	22/08/20 12:03	REPLACED AD BLU PUMP - AFTER TREATMENT LIGHT ON	208,390	0	80.00	1,950.71	2,030.71	Finalised
WK2-36705	22/08/20 12:02	A + B (OIL ONLY) + SE SERVICES	208,390	0	67.50	267.14	334.64	Finalised
WK1-20759	21/08/20 00:00	FIT STEER R/OUT POS 2 (A876753)	208,390	0	10.00	0.00	10.00	Finalised
WK2-36419	13/08/20 11:53	BUNK FRIDGE NOT COOLING	0	0	30.00	0.00	30.00	Finalised
WK2-36210	06/08/20 10:58	A SERVICE + TIGHTEN RR FUEL TAP FITTINGS	195,115	0	37.50	12.10	49.60	Finalised
WK2-35560	16/07/20 14:00	A,B (FUEL AND OIL FILTER), AD BLU SERVICE, HOTSET, REPLACED AIR DRYER ASSEMBLY DUE TO EXHAUSTING CONSTANTLY, REPAIRED BROKEN WIRE FOR RH HEAD LIGHT, REPLACED HEATER TAP NEAR OIL FILTER, TOPPED UP COOLANT AND WASHED DOWN, REPLACED FAN BELT AND AC BELT.	182,250	0	285.00	716.71	1,001.71	Finalised
WK2-34897	25/06/20 14:28	A SERVICE + REPLACE L/H OUTER HEADLIGHT SURROUND + REPLACE R/H STEER HUB SEAL	167,450	0	172.50	107.34	279.84	Finalised
WK2-34659	18/06/20 13:00	CHECK FOR AIR LEAK FOUND GOVERNOR LINES LEAKING REPLACE GOVERNOR LINES	160,770	0	0.00	27.38	27.38	Finalised
WK1-19402	11/06/20 10:00	REPLACE BROKEN GREASE LINE IN THE GEARBOX + REPLACE EXHAUST GASKETS + REPLACE REAR CAB BUMP STOP RUBBER AND RH BONNET STRAP	157,525	0	840.00	230.06	1,070.06	Finalised
WK2-34306	09/06/20 11:00	DIGNOSE GEARBOX FAULTS FOUND BROKEN PIN IN ECA , REPLACE ECA ADJUST CLUTCH AND TEST DRIVE CLEAR INACTIVE FAULTS	157,486	0	180.00	0.00	180.00	Finalised
WK2-34186	04/06/20 16:00	A SERVICE + REPLACE L/H BRAKE LIGHT	157,486	0	60.00	96.12	156.12	Finalised
WK2-33905	28/05/20 11:32	CHECK FAULTS FOR GEAR BOX..AND CLEAR ..GREASE INPUT SHAFT AND AXUATOR...CLEAN POWER PLUGS	154,228	0	61.25	10.00	71.25	Finalised
WK2-33684	21/05/20 12:28	A + B (OIL FILTER ONLY) + D + ST + SD + SE SERVICES + TOP UP COOLANT + REPLACE SPARE COOLANT BOTTLE + TOP UP SPARE OIL BOTTLE	148,910	0	213.75	580.81	794.56	Finalised
WK2-33682	21/05/20 11:00	FIT POWER LEAD FOR PIE WARMER.	0	0	0.00	21.49	21.49	Finalised
WK1-19090	21/05/20 00:00	BALANCE STEER TYRES (A843912)	148,910	0	45.45	0.00	45.45	Finalised
WK2-33338	17/02/21 11:36	UNDER BUNK FRIDGE NOT COOLING.	0	0	32.50	0.00	32.50	Finalised
WK2-32936	29/04/20 12:00	REPLACE L/H SPOTTER MIRROR, REPLACE FUEL ACTUATOR	134,300	0	0.00	452.34	452.34	Finalised
WK2-32688	22/04/20 13:39	A SERVICE + REPLACE FRONT MIDDLE TOP CAB MARKER + REPLACE LEAKING EFC	127,716	0	90.00	64.55	154.55	Finalised
WK2-32653	21/04/20 14:48	REPAIR BRACKETS FOR AIR TANK COVERS LH SIDE	127,716	0	60.00	0.00	60.00	Finalised
WK1-18547	15/04/20 00:00	NEW STEER TYRES (A843715)	124,242	0	1,083.64	0.00	1,083.64	Finalised
WK2-32361	20/04/20 16:46	NO A/C.	124,239	0	272.50	54.43	326.93	Finalised
WK2-31869	28/03/20 09:00	A,B SERVICE (OIL FILTER ONLY) REPLACE FRONT DOG BONE BUSHES	117,923	0	360.00	953.42	1,313.42	Finalised
WK2-31139	05/03/20 10:30	A SERVICE + REPLACE ALL DRIVE SHOCKIES	100,411	0	150.00	885.84	1,035.84	Finalised
WK2-30770	20/04/20 16:55	A/C NOT COOLING.	0	0	345.00	81.10	426.10	Finalised
WK2-30647	20/02/20 11:00	A SERVICE	90,290	0	60.00	10.00	70.00	Finalised
WK2-30098	06/02/20 10:50	A,B SERVICE (ALL FILTERS) , SAMPLE ENGINE , CLEAN OUT DIFF BREATHERS, REPLACE AIR DRAIN CORD	80,166	0	135.00	357.28	492.28	Finalised
WK1-17103	29/01/20 00:00	FIT R/OUT POS 2 (A811867)	74,888	0	10.00	0.00	10.00	Finalised
WK2-29616	23/01/20 12:00	A SERVICE + RESEAL LEFT HAND REAR HUB SEAL	69,150	0	245.00	225.35	470.35	Finalised
WK1-16819	15/01/20 00:00	NEW DRIVE TYRES x8 (A811746)	65,773	0	3,854.55	0.00	3,854.55	Finalised
WK2-29102	09/01/20 12:45	A SERVICE	60,452	0	60.00	10.80	70.80	Finalised
WK1-16133	23/12/19 17:00	REPLACED CLUTCH	0	0	870.00	5,892.92	6,762.92	Finalised
WK2-28394	19/12/19 12:00	A,B,D SERVICE (OIL FILTER) ,ST,SD , REPLACE SUZI COILS WITH SECOND HAND ONES	50,425	0	148.20	510.37	658.57	Finalised

WK2-27883	04/12/19 15:00	INSPECT FOR AIR LEAKS REPACE GOVERNOR VALVE AND CAB RIDE HEIGHT VALVE, GREASE CLUTCH AND CLEAR GI CODE	0	0	120.00	180.19	300.19	Finalised
WK1-15863	04/12/19 00:00	NEW STEER TYRES (A811757)	42,588	0	1,083.64	0.00	1,083.64	Finalised
WK2-27662	28/11/19 15:01	A SERVICE , REPLACE COOLANT BYPASS PIPE	37,835	0	270.00	1,092.11	1,362.11	Finalised
WK1-15691	20/11/19 00:00	REPAIR POS 10 (A811246)	33,481	0	29.09	0.00	29.09	Finalised
WK2-27355	19/11/19 15:00	REPAIR DAMAGE FROM HITTING KANGAROO'S , MOVE BUMPER BAR FROM RUBBING L/H STEER TYRE , REPLACE DAMAGED R/H DRIVING LIGHT , STRAIGHTEN L/H LIGHT BAR	33,481	0	90.00	293.00	383.00	Finalised
WK2-27789	13/11/19 17:00	PARTS NOT PICKED TO JOB (REFER WK2-27135)	28,553	0	0.00	24.99	24.99	Finalised
WK2-27135	13/11/19 16:00	A SERVICE + REPLACE EXHAUST DUMP PIPE ELBOW	28,553	0	75.00	199.43	274.43	Finalised
WK2-26661	31/10/19 13:30	A SERVICE + B SERVICE (OIL FILTER ONLY) + SAMPLE ENGINE + HOTSET + REFIT EXHAUST PIPE (PARTS ON ORDER)	19,400	0	285.00	573.82	858.82	Finalised
WK2-26160	17/10/19 13:00	A SERVICE + REPLACE SPEED SENSOR + REPLACE WIPER BLEADES	9,980	0	105.00	177.18	282.18	Finalised
WK2-25861	09/10/19 11:02	REPLACE DASH LIGHT BULB	5,220	0	0.00	0.45	0.45	Finalised
WK2-25679	03/10/19 11:08	A SERVICE + SPEEDO NEEDLE JUMP AROUND ALL THE TIME AND ODOMETER NOT COUNTING REPLACE SPEEDO HEAD KM'S BACK TO 0 BECAUSE OF NEW SPEEDO HEAD + REPLACE EXHAUST CLAMP	0	0	60.00	423.98	483.98	Finalised
WK2-25403	18/09/19 16:35	PARTS NOT BOOKED, REFER TO WK2-25139	0	0	0.00	27.73	27.73	Finalised
WK2-25181	18/09/19 15:30	BRAKE TEST	736,205	0	15.00	0.00	15.00	Finalised
WK2-25139	18/09/19 13:58	A + B SERVICE ALL FILTERS REPLACED + C SERVICE + REPLACE LEAKING HEATER CONTROL VALVE +REPLACE R/H HUB CAP+ CAB POWER DASH GAUGES RADIOS ALL LOOSING POWER WHEN HITTING BUMPS IN THE ROAD CHECK OVER WIRING HARNESS AND EARTH FOUND BATTERY HOLD DOWN CLAMP SHORTING OUT ON TERMINALS REPAIR HOLD DOWN BRACKET AND BROKEN BOLT REPLACE ALL BATTERIES DUE TO SHORTING OUT (REPLACED USING PREVIOUSLY WARRANTY SUPPLIED PACCAR BATTERIES) + REPLACE NUMBER PLATE LIGHT + TEST DRIVE NO FURTHER FAULTS FOUND	736,205	0	630.00	1,430.06	2,060.06	Finalised
WK2-24716	04/09/19 17:00	REPAIR BATTERY BOX + REPAIR WIRING HARNESS GOING TO CAB AND CHECK ALL EARTHS (TRUCK SHUTTING DOWN ON BIG BUMPS)	729,900	0	90.00	1.75	91.75	Finalised
WK2-24439	28/08/19 11:26	A SERVICE	725,515	0	0.00	10.00	10.00	Finalised
WK1-14093	23/08/19 00:00	NEW STEER TYRES (A770184)	720,249	0	1,083.64	0.00	1,083.64	Finalised
WK2-24014	15/08/19 12:00	A SERVICE + RE-RIVET CHROME COVER BRACKETS BACK ON UNDER BATERIES	714,740	0	0.00	10.00	10.00	Finalised
WK2-23587	02/08/19 13:33	A + B SERVICE (OIL FILTER ONLY) + SAMPLE ENGINE + REBOLT RHF DRIVE MUDGUARD BRACKET	705,005	0	117.50	263.06	380.56	Finalised
WK2-23403	30/07/19 14:00	A SERVICE + REMOVE RADIATOR AND REPAIR BROKEN MOUNT + REMOVE STEER HUBCAP AND REPLACE ABS PULSE RING FIT HUB TEST DRIVE TRUCK AND RECHECK WHEEL BEARING + BLOW OUT AIR CLEANNERS	701,750	0	792.50	129.84	922.34	Finalised
WK2-23345	26/07/19 16:30	INSPECT TRUCK A/C FOR LEAKS	0	0	46.25	0.00	46.25	Finalised
WK2-22903	12/07/19 15:00	WARRANTY DECLINED - REPLACE EXHAUST FLEX NOT AUTHORIZED BEFORE DOING	693,075	0	0.00	270.75	270.75	Finalised
WK2-22786	10/07/19 12:00	DIFF SERVICE + SAMPLE DIFFS + SAMPLE TRANS + TOP UP ENGINE OIL SAMPLE POTS SUPPLIED BY BROWN HURLY.	691,131	0	75.00	200.90	275.90	Finalised
WK2-22584	04/07/19 09:00	1621 RANG TO SAY HE LOST OIL OUT OF LEFT HUB ABOUT 30 KM OUT OF GOODIWINDI HE SNOKE IT TO BP I RANG PACCAR THEY RANG TOOWOOMBA TOOWOOMBA TRIED KEENWAY AND CLARK NO ANSWER SO TOOWOOMBA ATEND REFNO 11962	637,965	0	4,679.70	0.00	4,679.70	Finalised
WK2-22571	03/07/19 16:22	A SERVICE + CENTRE STEERING WHEEL + REPLACE LHS STEER WHEEL SEAL AND BEARINGS IP HOURS 1909	687,703	0	82.50	377.18	459.68	Finalised
WK2-21986	18/06/19 16:02	A SERVICE + B SERVICE (OIL FILTER ONLY) + REPLACE CLOCK SPRING + REPLACE ELECTRICAL LEAD + REPLACE BULB IN ENGINE RETARDER	677,071	0	275.00	1,048.29	1,323.29	Finalised

WK2-21960	17/06/19 15:53	REPLACE SPEED SENSOR	677,051	0	0.00	116.00	116.00	Finalised
WK2-21951	19/08/19 14:07	A/C NOT COOLING	677,051	0	90.00	20.34	110.34	Finalised
WK2-21845	13/06/19 15:59	REFIT MIRROR TO CAB LEFT HAND SIDE. AJUST HOOD MOUNTS.	673,620	0	65.00	25.31	90.31	Finalised
WK2-21575	05/06/19 14:08	EXHAUST FLEX UNDER GEARBOX BROKEN REPLACE EXHAUST FLEX WARRANTY DECLINED NOT AUTHORIZED BEFORE DOING JOB	669,555	8,358	30.00	178.19	208.19	Finalised
WK2-21574	05/06/19 17:00	A SERVICE + REMOVE RADIATOR TO REPAIR BROKEN MOUNT AND REFIT RADIATOR	669,555	0	435.00	42.20	477.20	Finalised
WK2-21510	30/05/19 09:00	REPLACE DUCT AIR CONDITIONING PIPE FOR FEET HEATING	669,555	0	30.00	0.00	30.00	Finalised
WK2-21211	25/05/19 08:29	A SERVICE	662,770	0	50.00	10.66	60.66	Finalised
WK2-20700	09/05/19 11:00	A + B SERVICE (ALL FILTERS) SAMPLE ENGINE OIL + REPLACE LEAKING HEATER TAP + REPLACE STEER HUBCAPS	650,695	0	150.00	428.33	578.33	Finalised
WK2-20226	26/04/19 09:00	A SERVICE , REPLACE AIR FILTERS , REPLACE EXHAUST FLEX	640,535	0	150.00	443.49	593.49	Finalised
WK2-19829	11/04/19 14:45	A SERVICE + REPLACE WATER SEPERATOR FUEL FILTER	630,327	0	75.00	37.73	112.73	Finalised
WK1-11515	03/04/19 00:00	NEW DRIVE TYRE + CALL OUT - LISMORE	624,504	0	910.91	0.00	910.91	Finalised
WK2-19346	28/03/19 17:00	A + B (OIL FILTER ONLY) SERVICE	619,507	0	225.00	235.99	460.99	Finalised
WK2-19066	21/03/19 10:12	A SERVICE , HOTSET JOB MADE (HOTSET DONE BY CUMMINS), REPLACE LEAKING DIFF BREATHER HOSE ON FRONT DIFF	614,235	0	165.00	220.40	385.40	Finalised
WK2-18462	05/03/19 14:22	A SERVICE + REPLACE TOP RADIATOR HOSE. A/C NOT COLD ON HOT DAYS.	602,220	0	142.50	47.04	189.54	Finalised
WK1-10979	05/03/19 00:00	NEW STEER TYRES (A791031)	602,220	0	1,083.64	0.00	1,083.64	Finalised
WK2-18188	26/02/19 11:29	REPLACE LHS TANK SIDE CLEARANCE LIGHT FUSE AND CAB BUMP STOP. STRAIGHTER SUZI LEAD MOUNT.	595,564	0	90.00	56.81	146.81	Finalised
WK2-18034	20/02/19 17:00	A,B,D,ST,SD SERVICE (OIL FILTER ONLY) B SERVICE DONE EARLY DUE TO HAVING HEAD DONE, REPLACED EBS BASE, REMOVED TAPET COVER TO CHECKED EXHUAUST BRAKE SOLOIDES COULD NOT FAULT	591,437	0	187.50	543.01	730.51	Finalised
WK2-17892	16/02/19 09:00	FIIL COOLANT BOTTLE	0	0	15.00	26.62	41.62	Finalised
WK1-10428	13/02/19 08:00	PRESSOR IN COOLING SYTEM DUBBO	0	0	0.00	0.00	0.00	Finalised
WK2-17685	11/02/19 16:56	CHECK ENGINE LIGHT , REPLACE LEAKING RADIATOR CAP	587,070	0	45.00	12.85	57.85	Finalised
WK2-17537	07/02/19 10:01	A SERVICE L/H ROOF LIGHT NOT WORKING	583,161	0	105.00	52.44	157.44	Finalised
WK2-17202	29/01/19 09:00	REPLACE EBS LEAD AND GLUE EBS BASE BACK TOGETHER.	578,902	0	60.00	176.58	236.58	Finalised
WK1-10221	27/01/19 00:00	REPAIR POS 9 + CALL OUT - EASTERN CREEK	577,918	0	449.09	0.00	449.09	Finalised
WK2-17097	25/01/19 10:15	A + B (OIL AND FUEL) + SE + REPLACE 12V OULET FUSE.	575,066	0	315.00	439.62	754.62	Finalised
WK1-9990	19/01/19 00:00	NEW DRIVE TYRES (A657420)	571,151	0	3,854.55	0.00	3,854.55	Finalised
WK2-16530	11/01/19 09:44	A SERVICE + MID LIFE, NEW TURBO S/N P1704057084, REPLACE O RINGS IN EGR COOLER BYPASS PIPE. ... REPLACED TRAILER BRAKE HOB SWITCH. REPLACED ENGINE BRAKE AND TRAILER AIR INDICATION LIGHTS. CLEANED SENSOR WIRING FOR FRONT DIFF TEMP SENSOR.	567,087	0	845.00	5,856.27	6,701.27	Finalised
WK2-15663	13/12/18 10:16	A + B SERVICE (OIL FILTER ONLY) + FIT NEW E TAG	549,000	0	152.50	233.81	386.31	Finalised
WK2-15178	28/11/18 15:18	A SERVICE + SAMPLE FRONT DIFF	538,446	0	62.50	37.00	99.50	Finalised
WK2-15050	23/11/18 13:00	REPLACE STARTER AT EPPIN. BP SERVO VIC PACCAR SORTED CALL	0	0	1,490.00	0.00	1,490.00	Finalised
WK1-9068	22/11/18 00:00	REPAIR POS 9 (WESTERN HUB)	529,663	0	55.00	0.00	55.00	Finalised
WK2-14758	15/11/18 10:17	REPLACE ADBLUE CAP	527,964	0	16.25	50.62	66.87	Finalised
WK1-8516	17/10/18 00:00	1373437 TEMP REPAIR RADIATOR TO GET HOME WESTRAC	0	0	435.50	0.00	435.50	Finalised

WK2-13751	16/10/18 02:10	1621 WAS AT COBAR CALLED SAYING HE HAS A LEAK IN THE RADIATOR GOT HIM TO LOOK AND FOUND A RUBB AT THE BOTTOM WAITED TILL MORING TO ORGANISE SOMEONE TO GO OUT	0	0	50.00	0.00	50.00	Finalised
WK2-13659	13/10/18 11:27	A,B SERVICE.	523,915	0	150.00	230.31	380.31	Finalised
WK1-8512	29/09/18 00:00	COOLANT LEAK NEAR HEADER TANK, REPLACE RUBBED HOSES -COBAR- KENWORTH	516,600	0	1,112.12	0.00	1,112.12	Finalised
WK2-13169	29/09/18 07:46	C SERVICE	514,667	0	120.00	254.23	374.23	Finalised
WK1-7844	27/09/18 10:47	BRAKE TEST	514,667	0	15.00	0.00	15.00	Finalised
WK2-13048	22/09/18 08:30	A SERVICE, REPAIRED LH OUTTA HEADLIGHT SURROUND	510,865	0	75.00	10.20	85.20	Finalised
WK2-12221	29/08/18 12:30	A,B,G,D,ST,SD, (OIL+FUEL) ADD BLU SERVICE	496,010	0	137.50	888.78	1,026.28	Finalised
WK2-11473	08/08/18 15:36	A SERVICE TOP UP ENGINE 4.5 LTRS CHANGE NUMBER PL,ATES	482,660	0	105.00	18.50	123.50	Finalised
WK2-10892	23/07/18 12:15	TOP ENGINE OIL UP 3 LITRES	470,390	0	15.00	12.06	27.06	Finalised
WK2-10597	14/07/18 14:30	TEMP REPAIR HEATER TAPE DONE BY DRIVER, REPLACED ELECTRICAL HEATER CONTROL VALVE	466,836	0	125.00	289.61	414.61	Finalised
WK1-6370	10/07/18 16:48	FIT NEW TYRES POS 1&2 (A550840)	460,015	0	1,083.64	0.00	1,083.64	Finalised
WK2-10438	10/07/18 16:00	A,B SERVICE (OIL FILTER ONLY), HOTSET	460,015	0	195.00	419.18	614.18	Finalised
WK2-10431	10/07/18 13:59	REFIT MIRROR MOUNT	460,015	0	60.00	11.32	71.32	Finalised
WK2-9605	18/06/18 12:30	A SERVICE	443,332	0	67.50	10.00	77.50	Finalised
WK2-8994	31/05/18 11:54	A,B SERVICE SAMPLE ENGINE(OIL FILTER ONLY)	430,810	0	112.50	311.90	424.40	Finalised
WK2-8864	27/05/18 15:00	REPLACE BATTERIES	427,550	0	97.50	520.00	617.50	Finalised
WK2-8422	12/05/18 15:38	REPLACE COMPRESSOR (REFER WK2-8370)	416,355	5,287	0.00	2,134.80	2,134.80	Finalised
WK2-8370	12/05/18 11:30	NOT BUILDING UP AIR - R&R COMPRESSOR & GOVERNER VALVE	416,355	5,287	292.50	196.31	488.81	Finalised
WK1-5236	10/05/18 00:00	NEW TYRE POS 8 + CALL OUT - WESTERN HUB (A538043)	414,760	0	910.91	0.00	910.91	Finalised
WK2-8079	04/05/18 13:08	A SERVICE	411,135	0	50.00	10.00	60.00	Finalised
WK2-7600	19/04/18 17:00	REPAIR AROUND LH H LIGHT AND RE AIM	339,649	0	120.00	20.00	140.00	Finalised
WK2-7574	19/04/18 12:00	A SERVICE, B SERVICE - (OIL FILTER, FUEL FILTER & PARTICULATE FUEL FILTER), SAMPLE GEARBOX, SAMPLE DIFFS, CLEANED DIFF BREATHERS, TOPPED UP COOLANT - CHECKED FOR LEAKS (NO LEAK), WASHED OUT RADIATOR AND INTERCOOLER, REPAIRED GREASE ;LINE ON LH SIDE OF FRONT DIFF, WELDED LHR EXHAUST MOUNT	399,650	0	225.00	605.79	830.79	Finalised
WK2-6673	24/03/18 11:00	A SERVICE, TOPPED UP ENGINE OIL AND GREASED THROWOUT BEARING AND CLEARED GI CODE OFF DASH	381,228	0	75.00	44.17	119.17	Finalised
WK2-6277	12/03/18 17:00	A + REPLACED RH STEER WHEEL SEAL	372,237	0	277.50	52.90	330.40	Finalised
WK2-5839	27/02/18 11:00	A + B + SE (OIL FILTER ONLY) SERVICE	360,850	0	165.00	280.81	445.81	Finalised
WK2-5388	12/02/18 12:30	A SERVICE AND CLEAN OUT REAR DIFF BREATHER LINE	350,209	0	100.00	10.00	110.00	Finalised
WK2-5313	09/02/18 09:30	REPLACE LH WIPER ARM AND ADJUST SQUIRTERS	346,977	0	25.00	154.54	179.54	Finalised
WK1-3139	31/01/18 12:00	REPLACE BOTH LH & RH WINDSCREENS	0	0	0.00	472.72	472.72	Finalised
WK2-4982	31/01/18 12:15	A SERVICE,REPLACED LHS WIPER ARM WITH ONE OF 516	341,430	0	62.50	20.00	82.50	Finalised
WK2-4576	18/01/18 11:03	REHUCK LHS MIRROR	330,371	0	60.00	10.68	70.68	Finalised
WK2-4568	18/01/18 11:30	A SERVICE, B SERVICE (OIL AND FUEL FILTER), SERVICE ADBLU SYSTEM	330,370	0	100.00	403.26	503.26	Finalised
WK1-2968	16/01/18 00:00	NEW STEER TYRES BALANCE STEER - WESTERN HUB	328,777	0	1,129.10	0.00	1,129.10	Finalised
WK1-2709	09/01/18 00:00	NEW DRIVE TYRES POS 3-10 (A629377)	323,035	0	3,854.56	0.00	3,854.56	Finalised
WK2-4145	05/01/18 10:30	A SERVICE AND RESEAL RHR AXLE SEAL AND WASH DOWN, REPAIR R/H MIRROR MOUNT, AND BONNET	323,032	0	262.50	100.13	362.63	Finalised
WK2-3685	20/12/17 17:00	A, FIT LONG VEHICLE SIGNS, R&R FEMALE AIR FITTING, GREASE THROWOUT BEARING & CLEAR GI CODE	310,290	0	149.50	130.01	279.51	Finalised

WK2-3307	08/12/17 09:00	A,B (OIL FILTER ONLY), HOTSET, SE	301,722	0	237.25	680.53	917.78	Finalised
WK2-3031	30/11/17 15:00	A, ST, SD SERVICE	296,520	0	91.75	114.44	206.19	Finalised
WK2-2512	14/11/17 16:00	A SERVICE, TYRE PRESSURES CHECK, R&R RHR DRIVE HUBCAP	285,883	0	137.50	54.12	191.62	Finalised
WK1-1625	13/11/17 00:00	FIT R/OUT POS 9&10 (A616643)	285,883	0	20.00	0.00	20.00	Finalised
WK2-2187	03/11/17 17:00	CALL FROM DRIVER - TRAILERS DROPPED ON RHR OF TRUCK	285,883	0	695.00	2,628.50	3,323.50	Finalised
WK1-1817	03/11/17 00:00	ACCIDENT DAMAGE - TEMP REPAIR OF REAR TAIL LIGHT MOUNT, REMOVE TURNABLE AND FIT NEW - TORQUE N DIESEL (4083 & 4090)	283,303	0	470.00	0.00	470.00	Finalised
WK2-1607	19/10/17 09:00	A SERVICE, B SERVICE (OIL FILTER ONLY)	271,964	0	107.50	243.81	351.31	Finalised
WK2-1146	04/10/17 10:30	A SERVICE, C SERVICE	259,580	0	182.50	287.69	470.19	Finalised
WK1-797	04/10/17 00:00	FIT R/OUT POS 4&5 (A616284)	259,577	0	20.00	0.00	20.00	Finalised
WK2-681	16/09/17 10:30	A + B SERVICE (FUEL FILTER)	246,885	0	135.50	382.80	518.30	Finalised
WK1-394	08/09/17 00:01	NEW TYRE POS 1 - WESTERN HUB (A520810)	0	0	550.91	0.00	550.91	Finalised
WK2-365	06/09/17 14:50	A SERVICE	239,831	0	76.25	10.00	86.25	Finalised
WK1-116	28/08/17 00:00	FIT R/OUT POS 3 (A587976)	0	0	10.00	0.00	10.00	Finalised
				Overall Total:	\$64,453.51	\$54,336.02	\$118,789.53	