



Cummins South Pacific Pty. Ltd.

ABN NO. 42006332949

WORKSHOP TAX INVOICE

Emerald
PO Box 668
Emerald QLD 4720
Tel : 07 49838 600
Fax: 07 4982 4159

COPY

INVOICE NUMBER

5532055

INVOICE DATE

20/12/23

PAGE

1

Invoice To

Customer

Engine Model:	SIGNATURE/ISX/QSX	Eng No:	80567764	Equip Make:	KENWORTH
FleetNo:	118 IAP	Reg No:	983TXX	Cust Ord NO:	PO-PAR-010-780
Date in Service:		KLMS:	106279	HRS:	20624
Repair Date:	16/11/23	Chassis NO:	453446	Currency:	AUD
C.O.No.	6691920	Work ordNo.	2853663	Facility	134

Complaint:

T909 Capped price engine change out

Cause:

Broken crankshaft cylinder #3

Correction:

Guidanz SO Number:00732103

ECM KLM: 106,279 klm

ECM HRS: 20,624 hrs

ECM Fuel Burn: 617469 L

OLD ESN: 79764713

NEW ESN: 80567764

Below costs include:

- Engine \$69,589.50
- Capped price R&R \$6,280.00
- Labour for OEM parts \$1,640

Subcontract additional

- OEM parts: hood bushes, front cab support \$289.05
- Clutch kit \$4750.58

TOTAL: \$82,549.13

RH589 - 01/12/2023

Assist with towing truck into workshop, remove bonnet,
drain coolant, remove oem wiring from engine and starter
motor. Remove radiator, shroud and fan hub.

Remove intake. Remove exhaust down pipe.

Disconnect fuel lines remove engine and gear box as complete
unit. Place on engine stand and remove gear box.

Install new spiggot bearing

Install new clutch refit gearbox

Install new engine mounts

Install engine into truck


Install exhaust with new mounts and clamp

Install oem wiring to engine gearbox and starter motor

All goods and services provided in line with Cummins Terms and Conditions of Sale

Payment Terms 30 Days from End of Month

Cummins South Pacific Pty. Ltd. WORKSHOP TAX INVOICE



INVOICE NUMBER 5532055
INVOICE DATE 20/12/23
PAGE 2

Invoice To



Customer



Description	Operation	Unit price	Qty	Extension
-------------	-----------	------------	-----	-----------

Fit air lines and gear stick to gearbox
Replace power steering filter
Install battery box and battery's and place on charge
Fit tail shaft
Fit fan hub, fan and shroud and belts
Fit radiator with new mounts
Fit gear box and fuel coolers
Re run gearbox hoses and fuel lines that pirtek replaced
Fill coolant and engine oil
Run engine - all ok
Fit new bonnet mounts fit bonnet
Wash truck clean work area

Banking Details

Cummins South Pacific Pty Ltd
Australia and New Zealand Banking Group Limited (ANZ)
Level 4, 100 Queen Street, Melbourne VIC 3000
Account No: 836551902 BSB:013 479
Swift Code: ANZBAU3M

Include Account and Invoice Numbers in Payment Reference

Description	Operation	Unit price	Qty	Extension
-------------	-----------	------------	-----	-----------

Labour

3

205.00

8.00

1640.00

LABOUR TOTAL

1640.00

Material

52370.02
DISCOUNT

ENGINE, ISXE5 500 / 1850
MATERIALS DISCOUNT (SERVI

69589.50
6280.00

1
1

69589.50
6280.00

MATERIAL TOTAL

75869.50

Subcontract

5476820


Clutch kit

4750.58

1

4750.58

Cummins South Pacific Pty. Ltd. WORKSHOP TAX INVOICE



INVOICE NUMBER 5532055
INVOICE DATE 20/12/23
PAGE 3

Customer 

Description	Operation	Unit price	Qty	Extension
5478367	Parts	289.05	1	289.05
SUBCONTRACT TOTAL				5039.63
SUB-TOTAL				82549.13
G.S.T				8254.91
INVOICE TOTAL				90804.04