



Work Order: 10143

EB10-48

Description:	Inspection, 250 Hour Service Repair Winch and	7429 Hours	Date Started:	2018-07-11
Equipment:	E530 Caterpillar D7R LGP DS A/W Dozer	RD-2018-235 Insheet RD-2018-246 Outsheet		
Serial#:	CAT00D7RTABJ01568			

Segment: 1 Parts and Service

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
30	08/07/18	EMParts	2307770W 24volt coil, value		EA	1.000	120.38	120.38
31	08/07/18	EMParts	5W40 Spectra 5W40		I	32.000	5.15	164.94
235	07/12/18	EMParts	1R0749 Filter-Fuel Advanced Efficiency		EA	1.000	19.54	19.54
236	07/12/18	EMParts	1R1808 Filter-Oil Advanced Efficiency		EA	1.000	35.76	35.76
237	07/12/18	EMParts	3261642 Filter-Fuel/Water Separator		EA	1.000	27.13	27.13
245	07/12/18	EMParts	RD705120 Valve Core-13mm Hi-Flow Hi sid		EA	1.000	3.44	3.44
246	07/12/18	EMParts	RD705125 Valve Core-16mm Hi-Flow Lo Sid		EA	1.000	3.93	3.93
247	07/12/18	EMParts	RD740470 A/C Drier-Cat In-line W/Connec		EA	1.000	95.54	95.54
Labour Total						0.00		
Parts Total						470.66		
Miscellaneous Total						0.00		

Segment: 2 250 Hour Service

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
36	08/07/18	EMTime	Employee: 1575 Paul Nixon		HRS	2.000		
Labour Total						2.00		
Parts Total						0.00		
Miscellaneous Total						0.00		

Segment: 3 Inspection

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
37	08/07/18	EMTime	Employee: 1575 Paul Nixon		HRS	1.500		
Labour Total						1.50		
Parts Total						0.00		
Miscellaneous Total						0.00		

Segment: 4 Trouble Shoot A/C and Repair

Found Hi & Low Port Valves Leaking, Evacuate System.
Refrigerant contaminated with moisture and 1.5 lb low.
Replaced Valves, Pulled Vacuum filled system with 3.5lb 134A.
Test system (9°C)



Work Order: 10143

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
38	08/07/18	EMTime	Employee: 1575 Paul Nixon		HRS	4.000		

Labour Total	4.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 5 Trouble Shoot Winch

*Traded Wires determined controller is getting signal from Joystick, But not going from there.
Can hear engine loading up slightly when test functions. Will need to be further Diagnosed.*

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
39	08/07/18	EMTime	Employee: 1575 Paul Nixon		HRS	3.500		

Labour Total	3.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 6 Replace Coil on Winch

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
40	08/07/18	EMTime	Employee: 2205 Alexander Zavadii		HRS	0.500		

Labour Total	0.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 7 Outsheet Inspection

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
41	08/07/18	EMTime	Employee: 2205 Alexander Zavadii		HRS	1.500		

Labour Total	1.50
Parts Total	0.00
Miscellaneous Total	0.00

Labour Total	13.00
Parts Total	470.66
Miscellaneous Total	0.00



Work Order: 14228

Description: Camera and Radar Installed by Emsco
Equipment: E530 Caterpillar D7R LGP DS A/W Dozer
Serial#: CAT00D7RTABJ01568

Date Started: 2023-07-24

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
479	07/24/23	EMParts	BS8000 Radar		EA	1.000	2,262.33	2,262.33
480	07/24/23	EMParts	Bracket Radar mounting Bracket W/Camea		EA	1.000	48.90	48.90
481	07/24/23	EMParts	VBV770M Monitor-Single Input		EA	1.000	537.58	537.58
482	07/24/23	EMParts	VBV791C Camera		EA	1.000	215.71	215.71
483	07/24/23	EMParts	VBVL405 Camera Cable 5m		EA	1.000	18.37	18.37

Labour Total	0.00
Parts Total	3,082.89
Miscellaneous Total	0.00

Segment: 2 Install Camera and Radar for Emsco to install

Labour Total	0.00
Parts Total	3,082.89
Miscellaneous Total	0.00

Description: Inspections, Replace Track Shoe's and Repair: 8313 Hours
Equipment: E530 Caterpillar D7R LGP DS A/W Dozer
Serial#: CAT00D7RTABJ01568

Date Started: 2023-11-06

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
811	11/05/24	AP	Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S7611088.001 Line: 1		LS	0.000	0.00	123.34
839	10/27/24	AP	Vendor: 10407 Onsite Machining Solutions Ltd. 5646 Line: 1		LS	0.000	0.00	900.00
946	12/11/23	AP	Vendor: 10321 Union Tractor Ltd. 040-230794 Line: 2		EA	84.000	97.00	8,148.00
947	12/11/23	AP	Vendor: 10321 Union Tractor Ltd. 040-230794 Line: 3		EA	336.000	3.01	1,009.68
948	12/11/23	AP	Vendor: 10321 Union Tractor Ltd. 040-230794 Line: 4		EA	336.000	1.41	472.75
954	12/18/23	AP	Vendor: 10321 Union Tractor Ltd. 240-102281 Line: 1		LS	0.000	0.00	2,364.70
1136	08/28/24	AP	Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S7533113.001 Line: 1		EA	2.000	31.77	63.53
1372	10/27/24	AP	Vendor: 10401 RBC Avion Visa Oct2724 LD Line: 30		LS	0.000	0.00	38.75
1410	08/26/24	AP	Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S7529954.001 Line: 1		EA	1.000	35.02	35.02
1411	08/27/24	AP	Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S7531380.001 Line: 1		LS	0.000	0.00	8.40
1412	08/27/24	AP	Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S7531380.001 Line: 2		LS	0.000	0.00	4.14
1477	09/27/24	AP	Vendor: 10401 RBC Avion Visa Sep2024 LD Line: 28		LS	0.000	0.00	647.39



Work Order: 14482

1634	08/26/24	AP	Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S7529954.001	EA	-1.000	35.02	-35.02
			Line: 2				
1635	08/26/24	AP	Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S7529954.001	EA	1.000	35.02	35.02
			Line: 3				
1636	08/27/24	AP	Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S7531380.001	LS	0.000	0.00	-8.40
			Line: 3				
1637	08/27/24	AP	Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S7531380.001	LS	0.000	0.00	-4.14
			Line: 4				
1638	08/27/24	AP	Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S7531380.001	LS	0.000	0.00	8.40
			Line: 5				
1639	08/27/24	AP	Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S7531380.001	LS	0.000	0.00	4.14
			Line: 6				
1	11/01/24	EMP	3124247 Seal-Wiper	EA	1.000	72.82	72.82
2	01/02/24	EMP	6V1723 Bolt-Track-7/8-14x3.42"	EA	4.000	2.03	8.12
3	01/02/24	EMP	9W9058 Bolt-Master Link-7/8-14x4.57"	EA	4.000	6.40	25.60
4	11/01/24	EMP	4214025 Seal-U-Cup	EA	1.000	58.82	58.82
5	11/01/24	EMP	5J4991 Seal Assembly	EA	1.000	133.08	133.08
6	11/01/24	EMP	7J8955 Ring-Backup	EA	1.000	16.03	16.03
7	11/01/24	EMP	7J8956 Seal-O-Ring	EA	1.000	16.67	16.67
8	11/01/24	EMP	8T8379 Seal-Head	EA	1.000	21.30	21.30
9	11/01/24	EMP	9T0094 Ring-Wear	EA	1.000	25.81	25.81
50	12/04/24	EMP	9Y6089 Gasket-Starter	EA	1.000	10.95	10.95
97	10/11/24	EMP	2661470 Sensor GP-Brake	EA	1.000	700.68	700.68
98	09/10/24	EMP	1578851 Sender-Fuel	EA	1.000	323.00	323.00
99	09/10/24	EMP	6C3060 Gasket	EA	1.000	9.78	9.78
108	12/16/24	EMP	2428403 Panel-L/H Rear Cab	EA	1.000	345.14	345.14
109	10/15/24	EMP	4J6374 Bushing-Tilt Cylinder	EA	4.000	34.69	138.76
110	10/15/24	EMP	1U0873 Pin-Tilt Cylinder to Push Arm	EA	2.000	113.46	226.92
146	09/11/24	EMP	2292626 Seal Kit-Lift Cylinder	EA	1.000	263.79	263.79
174	09/12/24	EMP	2987340 Lever-Steering	EA	1.000	223.46	223.46
175	09/12/24	EMP	3139374 Link-Steering	EA	1.000	127.78	127.78
205	11/14/23	EMP	1657211 Wear Strip - Front	EA	4.000	31.64	126.56
206	11/14/23	EMP	2038040 Wear Strip - Rear	EA	4.000	64.67	258.67
207	11/14/23	EMP	8T4122 Washer	EA	24.000	1.28	30.72
378	10/18/24	EMP	3T3434 Plug-Rubber Ball	EA	6.000	4.84	29.04
379	10/18/24	EMP	4H7869 Gasket	EA	1.000	4.82	4.82
467	11/25/24	EMP	8C3089 Seal-O-Ring	EA	1.000	36.50	36.50
495	10/29/24	EMP	6N2985 Cap-Oil Fill	EA	1.000	21.56	21.56
530	08/22/24	EMP	1654854 Seal-O-Ring	EA	2.000	15.04	30.08
531	08/22/24	EMP	1S9799 Seal-O-Ring	EA	1.000	7.33	7.33
1505	11/30/23	EMP	6V5851 Wiper Blade-16"(400mm)	EA	1.000	60.91	60.91
1506	11/30/23	EMP	7X0343 Bolt-5/8"x1 1/4" Gr8 NC	EA	24.000	1.48	35.45
1543	11/30/23	EMP	2D1690 Seal-O-Ring	EA	1.000	10.10	10.10
1544	11/30/23	EMP	4K1388 Seal-O-Ring	EA	1.000	2.51	2.51
1545	11/30/23	EMP	6S3002 Seal-O-Ring	EA	1.000	7.83	7.83
1546	11/30/23	EMP	8J1665 Seal-O-Ring	EA	1.000	12.90	12.90
			PO - Open - #1026534 - 10321 complete pad swap on customer supplied rails	LS	0.00	0.00	2,364.70
			PO - Open - #1026534 - 10321 6I9912- track shoe	EA	84.00	97.00	8,148.00
			PO - Open - #1026534 - 10321 7H3599- bolt, track	EA	336.00	3.01	1,009.68
			PO - Open - #1026534 - 10321 2S2140- nut	EA	336.00	1.41	472.75
			PO - Open - #1028146 - 10416 Hose Assembly Inv#S7529954.001	EA	1.00	35.02	35.02
			PO - Open - #1028158 - 10416 black push on hose	LS	0.00	0.00	8.40
			PO - Open - #1028158 - 10416 mini t bolt aba clamp	LS	0.00	0.00	4.14
			PO - Open - #1028485 - 10407 weld+machine the hyd cyl mounting bores on :	LS	0.00	0.00	900.00
			PO - Open - #1028497 - 10401 switch terminal, broken bolt on solenoid	LS	0.00	0.00	40.68
Labour Total					0.00		
Parts Total					30,613.52		
Miscellaneous Total					0.00		



Work Order: 14482

Segment: 2 Inspections

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
501	12/12/24	PR	Employee: 3103 Dallas Wood		HRS	3.000		
502	12/13/24	PR	Employee: 3103 Dallas Wood		HRS	4.000		
Labour Total						7.00		
Parts Total						0.00		
Miscellaneous Total						0.00		

Segment: 3 Wash

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
635	10/21/24	PR	Employee: 2623 Brenton Woolman		HRS	3.000		
636	10/22/24	PR	Employee: 2623 Brenton Woolman		HRS	8.500		
Labour Total						11.50		
Parts Total						0.00		
Miscellaneous Total						0.00		

Segment: 4 Repair Leaks and install belly pans

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
270	10/08/24	PR	Employee: 3108 Zachary Dean		HRS	4.000		
384	09/12/24	PR	Employee: 3108 Zachary Dean		HRS	9.500		
637	10/23/24	PR	Employee: 3108 Zachary Dean		HRS	2.500		
1297	08/21/24	PR	Employee: 2623 Brenton Woolman		HRS	4.500		
1299	08/26/24	PR	Employee: 2623 Brenton Woolman		HRS	1.000		
1301	08/27/24	PR	Employee: 2623 Brenton Woolman		HRS	3.000		
1324	10/31/24	PR	Employee: 3108 Zachary Dean		HRS	9.500		
Labour Total						34.00		
Parts Total						0.00		
Miscellaneous Total						0.00		

Segment: 5 Repair Panels, latches, radio, F/E mount. P.A.S.S., radar

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
383	09/11/24	PR	Employee: 3108 Zachary Dean		HRS	9.500		
503	12/16/24	PR	Employee: 2623 Brenton Woolman		HRS	4.000		
504	12/17/24	PR	Employee: 2623 Brenton Woolman		HRS	1.500		
505	12/17/24	PR	Employee: 3103 Dallas Wood		HRS	1.000		
1298	08/21/24	PR	Employee: 2623 Brenton Woolman		HRS	2.500		



Work Order: 14482

1300	08/26/24	PR	Employee: 2623 Brenton Woolman	HRS	3.500
1302	08/27/24	PR	Employee: 2623 Brenton Woolman	HRS	4.500
1304	08/28/24	PR	Employee: 2623 Brenton Woolman	HRS	6.500

Labour Total	33.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 6 Tighten belts and top up fluids

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1305	08/28/24	PR	Employee: 2623 Brenton Woolman		HRS	1.500		
1306	08/29/24	PR	Employee: 2623 Brenton Woolman		HRS	1.000		

Labour Total	2.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 7 Replace track shoes and guards

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1303	08/27/24	PR	Employee: 2623 Brenton Woolman		HRS	1.500		
1414	12/21/23	PR	Employee: 3109 Cameron Ellsworth		HRS	5.500		

Labour Total	7.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 8 Repair Blade

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
241	11/05/24	PR	Employee: 3108 Zachary Dean		HRS	9.500		
242	11/07/24	PR	Employee: 3108 Zachary Dean		HRS	1.000		
271	10/09/24	PR	Employee: 3108 Zachary Dean		HRS	9.500		
273	10/11/24	PR	Employee: 3108 Zachary Dean		HRS	9.000		
385	09/13/24	PR	Employee: 3108 Zachary Dean		HRS	3.500		

Labour Total	32.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 9 T/S and Repair Transmission/check pressures



Work Order: 14482

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
272	10/10/24	PR	Employee: 3108 Zachary Dean		HRS	9.500		
634	10/17/24	PR	Employee: 3108 Zachary Dean		HRS	9.500		
807	09/24/24	PR	Employee: 3108 Zachary Dean		HRS	1.500		
Labour Total						20.50		
Parts Total						0.00		
Miscellaneous Total						0.00		

Segment: 10 Repair Fuel Gauge

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
381	09/05/24	PR	Employee: 3108 Zachary Dean		HRS	4.500		
382	09/10/24	PR	Employee: 3108 Zachary Dean		HRS	9.500		
Labour Total						14.00		
Parts Total						0.00		
Miscellaneous Total						0.00		
Labour Total						162.00		
Parts Total						30,613.52		
Miscellaneous Total						0.00		

Description: Rental Return Legacy
Equipment: E530 Caterpillar D7R LGP DS A/W Dozer
Serial#: CAT00D7RTABJ01568
8313 Hours
Date Started: 2023-11-06
 RD-2023-384 Insheet
 RD-2024-236 Outsheet

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
103	11/06/23	EMParts	2S2140 Nut-Track		EA	8.000	2.01	16.08
104	11/06/23	EMParts	3261134 Shoe-Track(D7R)		EA	2.000	143.65	287.30
105	11/06/23	EMParts	7H3599 Bolt-Track		EA	8.000	4.24	33.92
193	11/09/23	EMParts	6T0988 Filter-Cab Air Standard Effici		EA	1.000	49.88	49.88
194	11/09/23	EMParts	6T5068 Filter-Cab Air		EA	1.000	28.41	28.41
210	11/14/23	EMParts	2431171 Panel-R/H Acoustical		EA	1.000	600.42	600.42
231	11/14/23	EMParts	4F1252 Pin-Blade Push Arm (3F6157)		EA	1.000	45.30	45.30
232	11/14/23	EMParts	6Y6752 Pin-Blade Pivot		EA	1.000	183.79	183.79
233	11/14/23	EMParts	6Y7474 Pin-Pivot Blade		EA	1.000	1,034.65	1,034.65
936	12/20/23	EMParts	Dyed Diesel Dyed Diesel		EA	105.992	1.54	163.34
1550	11/30/23	EMParts	9P7121 Fuel Tank Screen		EA	1.000	78.26	78.26



Work Order: 14483

Labour Total	0.00
Parts Total	2,521.35
Miscellaneous Total	0.00

Segment: 2 Wash and Clean Cab

Segment: 3 Top up Fluids

Segment: 4 Repair Pivot, Panels and Track pad

Blade Pivot pin broken off-unable to mount blade to test.
Unit has camera and radar, cables poorly routed, no power to monitors.
R/H Panel below armrest missing vinyl cover.
Badly bent track pads.
Rear work lights not working.
L/H Lollipop bent and no retainer.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
633	10/15/24	PR	Employee: 3108 Zachary Dean		HRS	0.500		
1295	08/27/24	PR	Employee: 2623 Brenton Woolman		HRS	0.500		
1296	08/28/24	PR	Employee: 2623 Brenton Woolman		HRS	1.500		

Labour Total	2.50
Parts Total	0.00
Miscellaneous Total	0.00

Labour Total	2.50
Parts Total	15,504.72
Miscellaneous Total	0.00

Description: T/S and Repair Leaks Date Started: 2025-07-03
Equipment: E530 Caterpillar D7R LGP DS A/W Dozer
Serial #: CAT00D7RTABJ01568

Segment: 1 Parts

PO - Open - #1029346 - 10416 Hose Assemblies LS 0.00 0.00 250.34

Segment: 2 T/S and Repair Leaks

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
994	06/23/25	PR	Employee: 3108 Zachary Dean		HRS	2.500		
995	06/24/25	PR	Employee: 3108 Zachary Dean		HRS	7.000		



Work Order: 15412

Labour Total	9.50
Parts Total	0.00
Miscellaneous Total	0.00
Labour Total	9.50
Parts Total	13,233.71
Miscellaneous Total	0.00

Description: 1000 Hour Service, Replace Idlers, Rollers and 7418 Hours **Date Started:** 2018-03-01
Equipment: E530 Caterpillar D7R LGP DS A/W Dozer RD-2017-345 Insheet
Serial#: CAT00D7RTABJ01568

Segment: 1 Parts and Service

2-1R0777 Hydraulic Filter (31.39ea)
 2-6V9633 Seal-O-Ring (13.25ea)
 1-3283655 P/T Filter (71.91ea)
 1-6V5188 Seal-O-Ring (16.87ea)
 1-4M0189 Seal-O-Ring (7.76ea)
 2-7L6580 Seal-O-Ring (4.18ea)

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
4	03/01/18	EMParts	1653663 Tube-Guard		EA	4.000	113.59	454.36
5	03/01/18	EMParts	1787195 Spacer-Track Guard		EA	8.000	36.33	290.64
6	03/01/18	EMParts	6V1723 Bolt-Track-7/8"-14x3.42"		EA	4.000	1.64	6.56
7	03/01/18	EMParts	9W3301 Snap Ring		EA	1.000	83.28	83.28
8	03/01/18	EMParts	9W9058 Bolt-Master Link-7/8"-14x4.5"		EA	4.000	7.10	28.40
9	03/01/18	EMParts	9X4584 Seal Assembly-Cannon		EA	1.000	551.39	551.39
122	03/07/18	EMParts	01643-32260 Washer		EA	72.000	2.31	166.32
123	03/07/18	EMParts	1657211 Wear Strip - Front		EA	4.000	67.23	268.92
124	03/07/18	EMParts	2038040 Wear Strip - Rear		EA	4.000	79.29	317.16
125	03/07/18	EMParts	CR2615 DF Roller		EA	6.000	351.83	2,110.98
126	03/07/18	EMParts	CR2617 SF Roller		EA	8.000	325.69	2,605.52
127	03/07/18	EMParts	CR4593 Idler-D7		EA	4.000	1,066.64	4,266.56
128	03/07/18	EMParts	CS8SC-088-350 7/8x3 1/2" GR8 NC Bolt		EA	56.000	4.46	249.76
129	03/07/18	EMParts	CS8SC-088-600 7/8X6 GR8 PL NC Bolts		EA	16.000	7.25	116.00
220	03/13/18	EMParts	1757904 Seal-O-Ring		EA	1.000	10.45	10.45
342	03/20/18	EMParts	1466315 Pin-Pivot Float Control		EA	1.000	21.22	21.22
343	03/20/18	EMParts	1466317 Retainer-Float Control		EA	1.000	25.75	25.75
344	03/20/18	EMParts	5C2890 Nut		EA	1.000	0.22	0.22
345	03/20/18	EMParts	7N0296 Cyinder Either Bottle 18oz		EA	1.000	77.22	77.22
386	03/22/18	EMParts	7X0383 Bolt-Track		EA	8.000	5.30	42.40

Labour Total	0.00
Parts Total	11,693.11
Miscellaneous Total	0.00

Segment: 2 Insheet Inspection



Work Order: Z10056

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
376	07/17/18	EMTime	Employee: 1575 Paul Nixon		HRS	1.500		

Labour Total	1.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 Wash and Clean Cab

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
377	07/17/18	EMTime	Employee: 1074 Jack Lougheed		HRS	12.000		

Labour Total	12.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 4 R&R Tracks, Rollers, Rock Gaurds, Wear Plates and Idlers

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
378	07/17/18	EMTime	Employee: 2205 Alexander Zavadil		HRS	38.000		

Labour Total	38.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 5 R&R Reseal Cannon

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
379	07/17/18	EMTime	Employee: 2205 Alexander Zavadil		HRS	9.500		

Labour Total	9.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 6 replace Seals on Flywheel Housing

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
380	07/17/18	EMTime	Employee: 2205 Alexander Zavadil		HRS	6.000		



Work Order: Z10056

Labour Total	6.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 7 1000 Hour Service (No Engine Service)

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
381	07/17/18	EMTime	Employee: 2205 Alexander Zavadil		HRS	7.000		

Labour Total	7.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 8 Change Hydraulic Accuator Hose

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
382	07/17/18	EMTime	Employee: 2205 Alexander Zavadil		HRS	4.000		

Labour Total	4.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 9 Repair Float Control

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
383	07/17/18	EMTime	Employee: 2205 Alexander Zavadil		HRS	5.000		

Labour Total	5.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 10 Reassemble Cab pannels and Belly Pans

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
384	07/17/18	EMTime	Employee: 2205 Alexander Zavadil		HRS	9.000		

Labour Total	9.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 11 Outsheet Inspection



Work Order: Z10056

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
385	07/17/18	EMTime	Employee: 1577 Dylan Grant		HRS	2.000		

Labour Total	2.00
--------------	------

Parts Total	0.00
-------------	------

Miscellaneous Total	0.00
---------------------	------

Labour Total	94.00
--------------	-------

Parts Total	24,926.82
-------------	-----------

Miscellaneous Total	0.00
---------------------	------