



Work Order: 11327

EB10-58

Description: Inspections and Repairs	8671 Hours	Date Started: 2020-07-21
Equipment: E416 Caterpillar D6T LGP A/W Dozer	RD-2020-247 Insheet	
	GRO-9116/9117/9197/9208/9304/930	
	3	
Serial#: CAT00D6THKJL00698		

Segment: 1 Parts and Service

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
124	08/04/20	AP	Vendor: 10111 Finning (Canada) a division of Finning International 946941990 Line: 1		EA	1.000	27.28	27.28
125	08/04/20	AP	Vendor: 10111 Finning (Canada) a division of Finning International 946942975 Line: 1		EA	1.000	12.17	12.17
126	08/05/20	AP	Vendor: 10111 Finning (Canada) a division of Finning International 946944448 Line: 2		EA	1.000	11.56	11.56
127	08/04/20	AP	Vendor: 10321 Union Tractor Ltd. 040-217907 Line: 1		EA	2.000	223.52	447.04
128	08/04/20	AP	Vendor: 10321 Union Tractor Ltd. 040-217907 Line: 2		EA	2.000	50.14	100.28
655	08/04/20	AP	Vendor: 10321 Union Tractor Ltd. 040-217924 Line: 1		EA	2.000	-50.14	-100.28
3403	07/31/20	AP	Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S5882716.001 Line: 1		LS	0.000	0.00	133.07
3404	07/30/20	AP	Vendor: 10111 Finning (Canada) a division of Finning International 946936979 Line: 1		EA	1.000	84.31	84.31
3405	07/31/20	AP	Vendor: 10111 Finning (Canada) a division of Finning International 946939002 Line: 1		EA	1.000	344.94	344.94
3406	07/31/20	AP	Vendor: 10111 Finning (Canada) a division of Finning International 946939002 Line: 2		EA	1.000	176.57	176.57
3407	07/31/20	AP	Vendor: 10111 Finning (Canada) a division of Finning International 946939002 Line: 3		EA	1.000	11.72	11.72
1	08/04/20	EMP	1R1808 Filter-Oil Advanced Efficiency		EA	1.000	32.78	32.78
2	08/04/20	EMP	6T0988 Filter-Cab Air Standard Efficiency		EA	1.000	20.32	20.32
760	08/17/20	EMP	7N0296 Cylinder Either Bottle 18oz		EA	1.000	78.70	78.70
1265	08/20/20	EMP	5W40 Spectra 5W40		I	59.560	5.22	310.64
1266	08/20/20	EMP	60/40 Rad-Cool Antifreeze		EA	66.000	5.67	373.97
1267	08/20/20	EMP	6V8397 Seal-O-Ring Face -6		EA	1.000	2.01	2.01
1268	08/20/20	EMP	75W90 Certop SN 75W90 Gear Lube		EA	3.200	9.78	31.29
1269	08/20/20	EMP	Dyed Diesel Dyed Diesel		EA	73.440	0.70	51.40
1270	08/20/20	EMP	TO4 Spectra Xtreme TO-4 All season		EA	3.000	5.59	16.77
1773	07/27/20	EMP	1597949 Floor Mat		EA	1.000	339.97	339.97
1774	07/27/20	EMP	2943342 Cap As-Rad		EA	1.000	27.95	27.95

Labour Total	0.00
Parts Total	2,534.46
Miscellaneous Total	0.00

Segment: 2 Insheet Inspection

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1440	07/20/20	PR	Employee: 2338 Nolan MacGregor		HRS	3.500		
2111	07/20/20	PR	Employee: 2338 Nolan MacGregor		HRS	-3.500		
2112	07/20/20	PR	Employee: 2338 Nolan MacGregor		HRS	3.500		



Work Order: 11327

Labour Total	3.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 Wash and Clean Cab

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
98	08/04/20	PR	Employee: 2528 Raymond Carlile		HRS	3.000		
433	08/04/20	PR	Employee: 2528 Raymond Carlile		HRS	-3.000		
434	08/04/20	PR	Employee: 2528 Raymond Carlile		HRS	3.000		
2693	07/28/20	PR	Employee: 2528 Raymond Carlile		HRS	1.000		
3642	07/28/20	PR	Employee: 2528 Raymond Carlile		HRS	-1.000		
3643	07/28/20	PR	Employee: 2528 Raymond Carlile		HRS	1.000		

Labour Total	4.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 4 Repair PAS

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
99	08/04/20	PR	Employee: 2395 Nickolas Schou		HRS	1.000		
435	08/04/20	PR	Employee: 2395 Nickolas Schou		HRS	-1.000		
436	08/04/20	PR	Employee: 2395 Nickolas Schou		HRS	1.000		
2113	07/24/20	PR	Employee: 2338 Nolan MacGregor		HRS	0.500		

Labour Total	1.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 5 Inspect/repair A/C

Segment: 6 Re-index hyd lines on blade lift circuit/repair

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
2463	07/29/20	PR	Employee: 2338 Nolan MacGregor		HRS	1.000		
2470	07/31/20	PR	Employee: 2338 Nolan MacGregor		HRS	1.500		
2700	07/29/20	PR	Employee: 2338 Nolan MacGregor		HRS	-1.000		
2701	07/29/20	PR	Employee: 2338 Nolan MacGregor		HRS	1.000		
2714	07/31/20	PR	Employee: 2338 Nolan MacGregor		HRS	-1.500		
2715	07/31/20	PR	Employee: 2338 Nolan MacGregor		HRS	1.500		
3650	07/29/20	PR	Employee: 2338 Nolan MacGregor		HRS	-1.000		
3651	07/29/20	PR	Employee: 2338 Nolan MacGregor		HRS	1.000		



Work Order: 11327

3664	07/31/20	PR	Employee: 2338 Nolan MacGregor	HRS	-1.500
3665	07/31/20	PR	Employee: 2338 Nolan MacGregor	HRS	1.500

Labour Total	2.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 7 Check/adjust fluids, clean breathers, adjust belts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
100	08/04/20	PR	Employee: 2338 Nolan MacGregor		HRS	0.500		
101	08/04/20	PR	Employee: 2395 Nickolas Schou		HRS	4.000		
437	08/04/20	PR	Employee: 2338 Nolan MacGregor		HRS	-0.500		
438	08/04/20	PR	Employee: 2338 Nolan MacGregor		HRS	0.500		
439	08/04/20	PR	Employee: 2395 Nickolas Schou		HRS	-4.000		
440	08/04/20	PR	Employee: 2395 Nickolas Schou		HRS	4.000		
2457	07/27/20	PR	Employee: 2338 Nolan MacGregor		HRS	1.000		
2460	07/28/20	PR	Employee: 2338 Nolan MacGregor		HRS	2.000		
2687	07/27/20	PR	Employee: 2338 Nolan MacGregor		HRS	-1.000		
2688	07/27/20	PR	Employee: 2338 Nolan MacGregor		HRS	1.000		
2694	07/28/20	PR	Employee: 2338 Nolan MacGregor		HRS	-2.000		
2695	07/28/20	PR	Employee: 2338 Nolan MacGregor		HRS	2.000		
3636	07/27/20	PR	Employee: 2338 Nolan MacGregor		HRS	-1.000		
3637	07/27/20	PR	Employee: 2338 Nolan MacGregor		HRS	1.000		
3644	07/28/20	PR	Employee: 2338 Nolan MacGregor		HRS	-2.000		
3645	07/28/20	PR	Employee: 2338 Nolan MacGregor		HRS	2.000		

Labour Total	7.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 8 Remove/add decals, change rad cap, fix seat adjustment

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
2464	07/29/20	PR	Employee: 2338 Nolan MacGregor		HRS	2.500		
2468	07/30/20	PR	Employee: 2338 Nolan MacGregor		HRS	4.500		
2702	07/29/20	PR	Employee: 2338 Nolan MacGregor		HRS	-2.500		
2703	07/29/20	PR	Employee: 2338 Nolan MacGregor		HRS	2.500		
2710	07/30/20	PR	Employee: 2338 Nolan MacGregor		HRS	-4.500		
2711	07/30/20	PR	Employee: 2338 Nolan MacGregor		HRS	4.500		
3652	07/29/20	PR	Employee: 2338 Nolan MacGregor		HRS	-2.500		
3653	07/29/20	PR	Employee: 2338 Nolan MacGregor		HRS	2.500		
3660	07/30/20	PR	Employee: 2338 Nolan MacGregor		HRS	-4.500		
3661	07/30/20	PR	Employee: 2338 Nolan MacGregor		HRS	4.500		



Work Order: 11327

Labour Total	7.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 9 Repair radio/speakers

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
102	08/04/20	PR	Employee: 2338 Nolan MacGregor		HRS	1.500		
441	08/04/20	PR	Employee: 2338 Nolan MacGregor		HRS	-1.500		
442	08/04/20	PR	Employee: 2338 Nolan MacGregor		HRS	1.500		

Labour Total	1.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 10 Clean battery posts/test batteries

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
94	08/04/20	PR	Employee: 2338 Nolan MacGregor		HRS	1.000		
425	08/04/20	PR	Employee: 2338 Nolan MacGregor		HRS	-1.000		
426	08/04/20	PR	Employee: 2338 Nolan MacGregor		HRS	1.000		
2458	07/28/20	PR	Employee: 2338 Nolan MacGregor		HRS	2.500		
2689	07/28/20	PR	Employee: 2338 Nolan MacGregor		HRS	-2.500		
2690	07/28/20	PR	Employee: 2338 Nolan MacGregor		HRS	2.500		
3638	07/28/20	PR	Employee: 2338 Nolan MacGregor		HRS	-2.500		
3639	07/28/20	PR	Employee: 2338 Nolan MacGregor		HRS	2.500		

Labour Total	3.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 11 Tidy up fuse panel area/mouse debris

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
2455	07/27/20	PR	Employee: 2338 Nolan MacGregor		HRS	1.500		
2683	07/27/20	PR	Employee: 2338 Nolan MacGregor		HRS	-1.500		
2684	07/27/20	PR	Employee: 2338 Nolan MacGregor		HRS	1.500		
3632	07/27/20	PR	Employee: 2338 Nolan MacGregor		HRS	-1.500		
3633	07/27/20	PR	Employee: 2338 Nolan MacGregor		HRS	1.500		

Labour Total	1.50
Parts Total	0.00
Miscellaneous Total	0.00



Work Order: 11327

Segment: 12 Repair oil pan leak

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
95	08/04/20	PR	Employee: 2338 Nolan MacGregor		HRS	2.000		
427	08/04/20	PR	Employee: 2338 Nolan MacGregor		HRS	-2.000		
428	08/04/20	PR	Employee: 2338 Nolan MacGregor		HRS	2.000		
2459	07/28/20	PR	Employee: 2338 Nolan MacGregor		HRS	3.500		
2465	07/30/20	PR	Employee: 2338 Nolan MacGregor		HRS	3.500		
2469	07/31/20	PR	Employee: 2338 Nolan MacGregor		HRS	8.000		
2691	07/28/20	PR	Employee: 2338 Nolan MacGregor		HRS	-3.500		
2692	07/28/20	PR	Employee: 2338 Nolan MacGregor		HRS	3.500		
2704	07/30/20	PR	Employee: 2338 Nolan MacGregor		HRS	-3.500		
2705	07/30/20	PR	Employee: 2338 Nolan MacGregor		HRS	3.500		
2712	07/31/20	PR	Employee: 2338 Nolan MacGregor		HRS	-8.000		
2713	07/31/20	PR	Employee: 2338 Nolan MacGregor		HRS	8.000		
3640	07/28/20	PR	Employee: 2338 Nolan MacGregor		HRS	-3.500		
3641	07/28/20	PR	Employee: 2338 Nolan MacGregor		HRS	3.500		
3654	07/30/20	PR	Employee: 2338 Nolan MacGregor		HRS	-3.500		
3655	07/30/20	PR	Employee: 2338 Nolan MacGregor		HRS	3.500		
3662	07/31/20	PR	Employee: 2338 Nolan MacGregor		HRS	-8.000		
3663	07/31/20	PR	Employee: 2338 Nolan MacGregor		HRS	8.000		
Labour Total						17.00		
Parts Total						0.00		
Miscellaneous Total						0.00		

Segment: 13 Repair lift cylinder leaks

Segment: 14 Repair blade hoses/hardware

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
2461	07/29/20	PR	Employee: 2338 Nolan MacGregor		HRS	1.000		
2466	07/30/20	PR	Employee: 2338 Nolan MacGregor		HRS	0.500		
2696	07/29/20	PR	Employee: 2338 Nolan MacGregor		HRS	-1.000		
2697	07/29/20	PR	Employee: 2338 Nolan MacGregor		HRS	1.000		
2706	07/30/20	PR	Employee: 2338 Nolan MacGregor		HRS	-0.500		
2707	07/30/20	PR	Employee: 2338 Nolan MacGregor		HRS	0.500		
3646	07/29/20	PR	Employee: 2338 Nolan MacGregor		HRS	-1.000		
3647	07/29/20	PR	Employee: 2338 Nolan MacGregor		HRS	1.000		
3656	07/30/20	PR	Employee: 2338 Nolan MacGregor		HRS	-0.500		
3657	07/30/20	PR	Employee: 2338 Nolan MacGregor		HRS	0.500		



Work Order: 11327

Labour Total	1.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 15 Run/test winch, re/spool cable

Segment: 16 Replace floor mat, repair fire ext. bracket

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
96	08/04/20	PR	Employee: 2338 Nolan MacGregor		HRS	0.500		
429	08/04/20	PR	Employee: 2338 Nolan MacGregor		HRS	-0.500		
430	08/04/20	PR	Employee: 2338 Nolan MacGregor		HRS	0.500		
2456	07/27/20	PR	Employee: 2338 Nolan MacGregor		HRS	0.500		
2462	07/29/20	PR	Employee: 2338 Nolan MacGregor		HRS	1.000		
2467	07/30/20	PR	Employee: 2338 Nolan MacGregor		HRS	0.500		
2685	07/27/20	PR	Employee: 2338 Nolan MacGregor		HRS	-0.500		
2686	07/27/20	PR	Employee: 2338 Nolan MacGregor		HRS	0.500		
2698	07/29/20	PR	Employee: 2338 Nolan MacGregor		HRS	-1.000		
2699	07/29/20	PR	Employee: 2338 Nolan MacGregor		HRS	1.000		
2708	07/30/20	PR	Employee: 2338 Nolan MacGregor		HRS	-0.500		
2709	07/30/20	PR	Employee: 2338 Nolan MacGregor		HRS	0.500		
3634	07/27/20	PR	Employee: 2338 Nolan MacGregor		HRS	-0.500		
3635	07/27/20	PR	Employee: 2338 Nolan MacGregor		HRS	0.500		
3648	07/29/20	PR	Employee: 2338 Nolan MacGregor		HRS	-1.000		
3649	07/29/20	PR	Employee: 2338 Nolan MacGregor		HRS	1.000		
3658	07/30/20	PR	Employee: 2338 Nolan MacGregor		HRS	-0.500		
3659	07/30/20	PR	Employee: 2338 Nolan MacGregor		HRS	0.500		

Labour Total	2.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 17 Replace operators manual, repair wiper sprayer

Segment: 18 Outsheet

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
97	08/04/20	PR	Employee: 2471 Greg Royer		HRS	1.000		
103	08/05/20	PR	Employee: 2471 Greg Royer		HRS	1.500		
431	08/04/20	PR	Employee: 2471 Greg Royer		HRS	-1.000		
432	08/04/20	PR	Employee: 2471 Greg Royer		HRS	1.000		
443	08/05/20	PR	Employee: 2471 Greg Royer		HRS	-1.500		
444	08/05/20	PR	Employee: 2471 Greg Royer		HRS	1.500		



Work Order: 11327

Labour Total	2.50
Parts Total	0.00
Miscellaneous Total	0.00
Labour Total	56.00
Parts Total	2,534.46
Miscellaneous Total	0.00

Description: Inspections and Repairs	GRO-8326/8327	Date Started: 2021-06-28
Equipment: E416 Caterpillar D6T LGP A/W Dozer	8674 Hours	
	RD-2021-249 Insheet	
	RD-2021-221 Outsheet	
Serial#: CAT00D6THKJL00698		

Segment: 1 Parts

6Y7474 is incorrect pivot pin use 2519832

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
824	07/08/21	AP	Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S6234523.001 Line: 1	LS		0.000	0.00	29.16
1037	06/29/21	AP	Vendor: 10111 Finning (Canada) a division of Finning International 947562429 Line: 1	EA		53.000	0.09	4.77
1039	06/29/21	AP	Vendor: 10111 Finning (Canada) a division of Finning International 947562429 Line: 3	EA		1.000	357.70	357.70
2226	07/27/21	AP	Vendor: 10401 RBC Avion Visa Jul 21_Lance Line: 7	LS		0.000	0.00	256.29
802	07/28/21	EMParts	2519832 Pin-Pivot Blade	EA		1.000	1,298.98	1,298.98
803	07/28/21	EMParts	6Y7474 Pin-Pivot Blade	EA		-1.000	1,034.65	-1,034.65
1077	06/29/21	EMParts	1R0762 Filter-Fuel Advanced Efficiency	EA		1.000	29.71	29.71
1078	06/29/21	EMParts	3261644 Filter-Fuel / Water Separator	EA		1.000	35.50	35.50
1079	06/29/21	EMParts	3383540 Filter-Hydraulic Ultra High Ef	EA		1.000	60.70	60.70
1080	06/29/21	EMParts	3F6157 Pin & Chain-Blade(4F1252)	EA		1.000	27.36	27.36
1081	06/29/21	EMParts	4656504 Filter-Hydraulic	EA		1.000	54.99	54.99
1082	06/29/21	EMParts	6Y7474 Pin-Pivot Blade	EA		1.000	1,034.65	1,034.65
1083	06/29/21	EMParts	8E5486 Bushing-Pivot Pin	EA		2.000	86.84	173.68
1124	06/29/21	EMParts	6V5849 Wiper Blade-14"	EA		2.000	10.16	20.32
		PO - Open - #1019176 - 10401	Repair Alternator	LS		0.00	0.00	269.11

Labour Total	0.00
Parts Total	2,618.27
Miscellaneous Total	0.00

Segment: 2 Insheet and Outsheet Inspections

Outsheet unit, pictures. Top up fuel.
-Paul

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
54	07/07/21	PR	Employee: 1575 Paul Nixon		HRS	1.000		
156	07/07/21	PR	Employee: 1575 Paul Nixon		HRS	-1.000		
157	07/07/21	PR	Employee: 1575 Paul Nixon		HRS	1.000		
158	07/08/21	PR	Employee: 1575 Paul Nixon		HRS	4.000		
159	07/09/21	PR	Employee: 1575 Paul Nixon		HRS	3.000		



Work Order: 12241

2092	06/28/21	PR	Employee: 2611 Matthew Walter	HRS	3.500		
1038	06/29/21	AP	Vendor: 10111 Finning (Canada) a division of Finning International 947562429 Line: 2	EA	1.000	53.09	53.09

Labour Total	11.50
Parts Total	53.09
Miscellaneous Total	0.00

Segment: 3 Wash and Clean Cab

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
648	07/21/21	PR	Employee: 2623 Brenton Woolman		HRS	4.000		
649	07/22/21	PR	Employee: 2623 Brenton Woolman		HRS	1.500		

Labour Total	5.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 4 Replace C-Frame Bushings and Pins

Install new blade pivot pin. Had to helicoil threads for pin retaining bolt.
-Paul

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
2093	06/28/21	PR	Employee: 2611 Matthew Walter		HRS	3.000		
2096	06/29/21	PR	Employee: 2611 Matthew Walter		HRS	5.000		

Labour Total	8.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 5 Check, adjust, change Fluid levels and filters

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
2097	06/29/21	PR	Employee: 2611 Matthew Walter		HRS	1.500		

Labour Total	1.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 6 Check and Adjust Tracks

Segment: 7 T/S and Repair Leaks



GCS Energy Services Ltd.

Work Order: 12241

Replace quick couplers on machine and blade for aux hydraulics.

-Paul

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
2094	06/28/21	PR	Employee: 2611 Matthew Walter		HRS	1.500		

Labour Total	1.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 8 Repair doors, panels, windows and wipers

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
2095	06/28/21	PR	Employee: 2611 Matthew Walter		HRS	1.000		
2098	06/29/21	PR	Employee: 2611 Matthew Walter		HRS	1.500		
2099	06/30/21	PR	Employee: 2611 Matthew Walter		HRS	1.500		

Labour Total	4.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 9 T/S and repair electrical issues

Repair for unit shutting down intermittently.

Remove floor boards, panels, check for loose connections, none found.

Remove fuse panel cover, found all fuses full of dirt and corrosion. Removed all fuses, cleaned connections and put dielectric grease on everything and reassemble.

Run/test unit, could not get it to fail anymore.

Alternator belt squealing on start up. Try tightening belt, still active. Remove alternator, found it had some play in bearings.

Send out for repair. Reinstall alternator and run/test, no more noise. Get trans warm and perform trans calibration.

-Paul

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
160	07/09/21	PR	Employee: 1575 Paul Nixon		HRS	2.000		
472	07/13/21	PR	Employee: 1575 Paul Nixon		HRS	2.000		
473	07/14/21	PR	Employee: 1575 Paul Nixon		HRS	2.000		
650	07/22/21	PR	Employee: 1575 Paul Nixon		HRS	1.500		
651	07/23/21	PR	Employee: 1575 Paul Nixon		HRS	2.000		

Labour Total	9.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 10 Repair blade float not working



GCS Energy Services Ltd.

Work Order: 12241

Blade float working, but not holding.
Remove panels in cab, clean float hold magnet, adjust linkage and test, working now.
Reinstall panels.
-Paul

Labour Total	41.50
Parts Total	2,671.36
Miscellaneous Total	0.00

Description: regular maintenance	8680 HRS, GRO 8577	Date Started: 2021-11-01
Equipment: E416 Caterpillar D6T LGP A/W Dozer		
Serial#: CAT00D6THKJL00698		

Segment: 1 parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
658	11/01/21	EMParts	TO4 Spectra Xtreme TO-4 All season		EA	4.000	6.23	24.93

Labour Total	0.00
Parts Total	24.93
Miscellaneous Total	0.00

Segment: 2 wash

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
408	11/01/21	PR	Employee: 2024 Travis Schmidt		HRS	2.000		
409	11/01/21	PR	Employee: 2392 Carmen Beck		HRS	1.000		

Labour Total	3.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 Checkover - top up fluids

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
410	11/01/21	PR	Employee: 2024 Travis Schmidt		HRS	1.000		

Labour Total	1.00
Parts Total	0.00
Miscellaneous Total	0.00



Work Order: 12550

Labour Total	4.00
Parts Total	294.04
Miscellaneous Total	0.00

Description: Repair broken track No hours reported. **Date Started:** 2021-12-06
Equipment: E416 Caterpillar D6T LGP A/W Dozer
Serial#: CAT00D6THKJL00698

Segment: 1 Parts

Segment: 2 Repair broken track enough to get off site

Track pin broke on unit. Used blocking and hydraulic jack to lift unit. Rotated track so the break was between final drive and rear idler. Loosened track adjustment fitting and pulled canon in. Cut out broken pin and welded in a temporary piece of round stock in its place. Tightened track enough so it would not fall off unit. Followed unit and operator from work site to equipment. Lay down where it could get trucked out.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
2105	11/29/21	PR	Employee: 2395 Nickolas Schou		HRS	5.500		

Labour Total	5.50
Parts Total	0.00
Miscellaneous Total	0.00
Labour Total	5.50
Parts Total	269.11
Miscellaneous Total	0.00

Description: Inspections, U/C, 4000 Hour Service and Repai 8888 Hours **Date Started:** 2022-04-08
Equipment: E416 Caterpillar D6T LGP A/W Dozer RD-2023- Insheet
Unit was moved to See's for repairs.
U/C Done at 8888 Hours July 10
2023
Serial#: CAT00D6THKJL00698 GRO# 10742

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1048	06/21/23	AP	Vendor: 10321 Union Tractor Ltd. 040-228970 Line: 1	LS		0.000	0.00	10,920.53
1662	06/29/23	AP	Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S7040247.001 Line: 1	EA		2.000	54.42	108.84
1663	06/29/23	AP	Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S7040247.001 Line: 2	EA		2.000	35.88	71.76
1664	06/30/23	AP	Vendor: 10132 Gregg Distributors LP 059-559357 Line: 1	EA		2.000	8.82	17.64
1678	06/21/23	AP	Vendor: 10111 Finning (Canada) a division of Finning International 949238777 Line: 1	EA		2.000	10,366.01	20,732.02
1679	06/21/23	AP	Vendor: 10111 Finning (Canada) a division of Finning International 949238777 Line: 2	EA		10.000	100.37	1,003.70



Work Order: 12991

2092	06/21/23	AP	Vendor: 10111 Finning (Canada) a division of Finning International 949238777 Line: 3	EA	-2.000	10,366.01	-20,732.02
2093	06/21/23	AP	Vendor: 10111 Finning (Canada) a division of Finning International 949238777 Line: 4	EA	-10.000	100.37	-1,003.70
2094	06/21/23	AP	Vendor: 10111 Finning (Canada) a division of Finning International 949238777 Line: 5	EA	2.000	10,366.01	20,732.02
2095	06/21/23	AP	Vendor: 10111 Finning (Canada) a division of Finning International 949238777 Line: 6	EA	10.000	100.37	1,003.70
2130	06/30/23	AP	Vendor: 10132 Gregg Distributors LP 059-559357 Line: 2	EA	-2.000	8.82	-17.64
2131	06/30/23	AP	Vendor: 10132 Gregg Distributors LP 059-559357 Line: 3	EA	2.000	8.82	17.64
2222	06/29/23	AP	Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S7040247.001 Line: 3	EA	-2.000	54.42	-108.84
2223	06/29/23	AP	Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S7040247.001 Line: 4	EA	-2.000	35.88	-71.76
2224	06/29/23	AP	Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S7040247.001 Line: 5	EA	2.000	54.42	108.84
2225	06/29/23	AP	Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S7040247.001 Line: 6	EA	2.000	35.88	71.76
31	07/04/23	EMParts	2S5658 Washer	EA	50.000	1.39	69.50
32	07/04/23	EMParts	6V0937 "Bolt-Segment-5/8-18x2.1""	EA	50.000	1.25	62.50
33	07/04/23	EMParts	7H3607 Nut	EA	50.000	2.71	135.50
34	07/04/23	EMParts	1251302 Switch As	EA	1.000	217.69	217.69
35	07/04/23	EMParts	2370050 Strap	EA	1.000	207.80	207.80
36	07/04/23	EMParts	2370051 Strap	EA	1.000	188.19	188.19
37	07/04/23	EMParts	2382014 Wire As	EA	1.000	22.56	22.56
38	07/04/23	EMParts	2418368 Switch As-Ma	EA	1.000	630.24	630.24
39	07/04/23	EMParts	5C2890 Nut	EA	1.000	0.40	0.40
40	07/04/23	EMParts	6T3643 Breaker-Circuit 15 amp	EA	1.000	76.25	76.25
41	07/04/23	EMParts	5C2890 Nut	EA	3.000	0.42	1.26
45	08/09/23	EMParts	4W1203 Cup-Bearing	EA	2.000	24.27	48.54
46	08/09/23	EMParts	4W1204 Cone-Bearing	EA	2.000	34.75	69.50
47	08/09/23	EMParts	4W2042 Spacer-Fan Hub	EA	1.000	80.05	80.05
48	08/09/23	EMParts	5K1770 Seal-O-Ring	EA	1.000	15.25	15.25
49	08/09/23	EMParts	5S9062 Spacer-Fan Hub	EA	1.000	17.64	17.64
50	08/09/23	EMParts	6L5359 Seal-O-Ring	EA	1.000	25.41	25.41
51	08/09/23	EMParts	6V9748 Seal-Fan Drive	EA	1.000	15.44	15.44
52	08/09/23	EMParts	9T8578 Filter-Hydraulic	EA	1.000	57.90	57.90
78	07/11/23	EMParts	BS8000 Radar	EA	1.000	2,262.33	2,262.33
79	07/11/23	EMParts	VBV770M Monitor-Single Input	EA	1.000	537.58	537.58
80	07/11/23	EMParts	VBV791C Camera	EA	1.000	215.71	215.71
81	07/11/23	EMParts	VBVL405 Camera Cable 5m	EA	1.000	18.37	18.37
82	07/11/23	EMParts	VBVL410 Camera Cable 10m	EA	1.000	25.00	25.00
490	08/17/23	EMParts	Dyed Diesel Dyed Diesel	EA	344.470	1.22	419.60
952	06/29/23	EMParts	1R0762 Filter-Fuel Advanced Efficiency	EA	1.000	45.95	45.95
953	06/29/23	EMParts	1R0777 Filter-Hydraulic Advanced Efficiency	EA	1.000	44.46	44.46
954	06/29/23	EMParts	1R1808 Filter-Oil Advanced Efficiency	EA	1.000	40.05	40.05
955	06/29/23	EMParts	3261644 Filter-Fuel / Water Separator	EA	1.000	40.72	40.72
956	06/29/23	EMParts	3283655 Filter-P/T Advanced Efficiency	EA	1.000	97.37	97.37
957	06/29/23	EMParts	4656504 Filter-Hydraulic	EA	1.000	164.37	164.37
958	06/29/23	EMParts	6I2501 Filter-Air Primary	EA	1.000	63.07	63.07
959	06/29/23	EMParts	6I2502 Filter-Air Secondary	EA	1.000	86.85	86.85
960	06/29/23	EMParts	6T0988 Filter-Cab Air Standard Efficiency	EA	1.000	34.36	34.36
961	06/29/23	EMParts	6T5068 Filter-Cab Air	EA	1.000	29.07	29.07
962	06/29/23	EMParts	6V5188 Seal-O-Ring-Power Train Screen	EA	1.000	26.08	26.08
963	06/29/23	EMParts	6V9633 Seal-Square-Ring	EA	1.000	27.46	27.46
964	06/29/23	EMParts	9G5127 Breather-Power Train	EA	1.000	29.01	29.01
			PO - Open - #1024910 - 10111 3913924-Track GP 45L CAT 36"MS GDMTO	EA	2.00	10,366.01	20,732.02
			PO - Open - #1024910 - 10111 3980972- Segment-sprocket CAT GD	EA	10.00	100.37	1,003.70



Work Order: 12991

Labour Total	0.00
Parts Total	60,739.24
Miscellaneous Total	0.00

Segment: 2 Inspections

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1840	06/27/23	PR	Employee: 3103 Dallas Wood		HRS	3.000		

Labour Total	3.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 Wash and Clean Cab

Segment: 4 U/C

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
217	07/04/23	PR	Employee: 3103 Dallas Wood		HRS	9.000		
218	07/04/23	PR	Employee: 3109 Cameron Ellsworth		HRS	2.000		
219	07/05/23	PR	Employee: 3103 Dallas Wood		HRS	8.000		
220	07/05/23	PR	Employee: 3109 Cameron Ellsworth		HRS	9.500		
221	07/06/23	PR	Employee: 3103 Dallas Wood		HRS	9.500		
222	07/06/23	PR	Employee: 3109 Cameron Ellsworth		HRS	9.000		
223	07/07/23	PR	Employee: 3103 Dallas Wood		HRS	9.500		
224	07/07/23	PR	Employee: 3109 Cameron Ellsworth		HRS	9.500		
801	07/10/23	PR	Employee: 3103 Dallas Wood		HRS	5.000		
802	07/10/23	PR	Employee: 3109 Cameron Ellsworth		HRS	3.000		
1841	06/29/23	PR	Employee: 1575 Paul Nixon		HRS	1.000		
1842	06/29/23	PR	Employee: 3103 Dallas Wood		HRS	9.500		

Labour Total	84.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 5 Repair Heater, wipers, Windows and Decals

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
724	06/19/23	PR	Employee: 1575 Paul Nixon		HRS	5.000		
725	06/20/23	PR	Employee: 1575 Paul Nixon		HRS	3.500		
726	06/21/23	PR	Employee: 1575 Paul Nixon		HRS	1.000		
727	06/22/23	PR	Employee: 1575 Paul Nixon		HRS	2.000		



Work Order: 12991

Labour Total	11.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 6 4000 Hour Service

Segment: 7 T/S and Repair Leaks

Segment: 8 Install Camera and Radar

Labour Total	99.00
Parts Total	61,008.35
Miscellaneous Total	0.00

Description: Inspections and Repairs	9012 Hours	Date Started: 2023-11-08
Equipment: E416 Caterpillar D6T LGP A/W Dozer	RD-2023-303 Insheet RD-2025-112 Outsheet	
Serial#: CAT00D6THKJL00698		

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
640	04/16/24	AP	Vendor: 10321 Union Tractor Ltd. 040-232037 Line: 3	EA		5.000	1,239.65	6,198.25
858	03/25/24	AP	Vendor: 10132 Gregg Distributors LP 059-630657 Line: 2	EA		1.000	51.71	51.71
859	03/25/24	AP	Vendor: 10132 Gregg Distributors LP 059-630657 Line: 3	EA		1.000	8.82	8.82
860	03/22/24	AP	Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S7333599.001 Line: 1	LS		0.000	0.00	190.66
926	04/25/24	AP	Vendor: 10111 Finning (Canada) a division of Finning International 949907239 Line: 1	EA		1.000	77.68	77.68
1349	04/30/24	AP	Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S7382509.001 Line: 1	LS		0.000	0.00	48.22
1942	04/29/24	AP	Vendor: 10401 RBC Avion Visa Apr 24_P Nixon Line: 7	LS		0.000	0.00	305.75
1953	04/29/24	AP	Vendor: 10401 RBC Avion Visa Apr 24_L Dahl Line: 2	LS		0.000	0.00	288.26
1	04/01/24	EMParts	1149125 Cup Holder	EA		1.000	6.36	6.36
2	04/01/24	EMParts	1282573 Hose Assembly	EA		1.000	303.18	303.18
6	04/01/24	EMParts	612431 Seal-Radiator Core	EA		5.000	92.88	464.40
9	06/03/24	EMParts	1466315 Pin-Pivot Float Control	EA		1.000	23.07	23.07
10	06/03/24	EMParts	1466317 Retainer-Float Control	EA		1.000	27.65	27.65
12	04/01/24	EMParts	612431 Seal-Radiator Core	EA		1.000	92.88	92.88
227	02/21/25	EMParts	7N0296 Ether Cyinder-18oz	EA		1.000	123.84	123.84
330	11/15/23	EMParts	3658408 Seal-D-Ring	EA		1.000	16.76	16.76
729	04/23/24	EMParts	2507533 Hose	EA		1.000	219.36	219.36
819	03/25/24	EMParts	1108827 Coupler-Oil	EA		1.000	468.00	468.00
820	03/25/24	EMParts	8N6854 Gasket-Oil Drain	EA		1.000	8.21	8.21
839	03/26/24	EMParts	2870415 Hose Assembly	EA		1.000	286.48	286.48
840	03/26/24	EMParts	2943345 Hose Assembly	EA		1.000	325.09	325.09
841	03/26/24	EMParts	3T6471 Screen	EA		1.000	15.63	15.63
842	03/26/24	EMParts	8H9818 Gasket	EA		1.000	3.72	3.72
843	03/26/24	EMParts	8M4986 Seal-O-Ring	EA		2.000	10.56	21.12



Work Order: 14507

844	03/26/24	EMParts	8M4987 Seal-O-Ring	EA	2.000	7.75	15.50
856	03/27/24	EMParts	2506052 Hose Assembly(415mm Long)	EA	1.000	259.25	259.25
940	11/22/23	EMParts	1U1176 Pin-Tilt Cylinder	EA	2.000	97.98	195.96
941	11/22/23	EMParts	2J8489 Bearing	EA	2.000	20.24	40.48
			PO - Open - #1027383 - 10401 repair core damage	LS	0.00	0.00	305.75
			PO - Open - #1027464 - 10416 Hose assembly	LS	0.00	0.00	48.22
					Labour Total	0.00	
					Parts Total	10,533.98	
					Miscellaneous Total	0.00	

Segment: 2 Inspections

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1015	02/21/25	PR	Employee: 3103 Dallas Wood		HRS	4.000		
						Labour Total	4.00	
						Parts Total	0.00	
						Miscellaneous Total	0.00	

Segment: 3 Wash

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
212	06/06/24	PR	Employee: 2623 Brenton Woolman		HRS	6.000		
						Labour Total	6.00	
						Parts Total	0.00	
						Miscellaneous Total	0.00	

Segment: 4 Repair lights, panels, seats and doors

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1213	03/19/24	PR	Employee: 3110 Callum Deditch		HRS	1.000		
1217	03/21/24	PR	Employee: 3110 Callum Deditch		HRS	1.000		
1220	03/22/24	PR	Employee: 3110 Callum Deditch		HRS	4.500		
1222	03/26/24	PR	Employee: 3110 Callum Deditch		HRS	3.000		
1224	03/27/24	PR	Employee: 3109 Cameron Ellsworth		HRS	1.000		
1225	03/27/24	PR	Employee: 3110 Callum Deditch		HRS	8.500		
						Labour Total	19.00	
						Parts Total	0.00	
						Miscellaneous Total	0.00	

Segment: 5 Repair Leaks



Work Order: 14507

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1212	03/18/24	PR	Employee: 3110 Callum Deditch		HRS	5.000		
1214	03/19/24	PR	Employee: 3110 Callum Deditch		HRS	2.000		
1216	03/20/24	PR	Employee: 3110 Callum Deditch		HRS	4.000		
1218	03/21/24	PR	Employee: 3110 Callum Deditch		HRS	2.000		
1221	03/25/24	PR	Employee: 3110 Callum Deditch		HRS	5.000		
1343	05/29/24	PR	Employee: 3131 Shawn Rowe		HRS	4.000		
						Labour Total	22.00	
						Parts Total	0.00	
						Miscellaneous Total	0.00	

Segment: 6 Repair Pins and Bushings

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
210	06/04/24	PR	Employee: 3109 Cameron Ellsworth		HRS	3.500		
1215	03/19/24	PR	Employee: 3110 Callum Deditch		HRS	1.500		
1223	03/26/24	PR	Employee: 3110 Callum Deditch		HRS	3.500		
						Labour Total	8.50	
						Parts Total	0.00	
						Miscellaneous Total	0.00	

Segment: 7 Repair Float

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
209	06/03/24	PR	Employee: 3109 Cameron Ellsworth		HRS	4.000		
211	06/04/24	PR	Employee: 3109 Cameron Ellsworth		HRS	2.000		
						Labour Total	6.00	
						Parts Total	0.00	
						Miscellaneous Total	0.00	

Segment: 8 Check Belts, batteries

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1219	03/21/24	PR	Employee: 3110 Callum Deditch		HRS	3.000		
						Labour Total	3.00	
						Parts Total	0.00	
						Miscellaneous Total	0.00	



Work Order: 14507

Segment: 9 Remove radiators for cleaning

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
432	04/02/24	PR	Employee: 3110 Callum Deditch		HRS	4.500		
621	05/16/24	PR	Employee: 3103 Dallas Wood		HRS	3.000		
1161	04/19/24	PR	Employee: 3108 Zachary Dean		HRS	2.000		
1162	04/19/24	PR	Employee: 3110 Callum Deditch		HRS	2.000		
1163	04/24/24	PR	Employee: 3110 Callum Deditch		HRS	4.000		
1164	04/26/24	PR	Employee: 3103 Dallas Wood		HRS	2.000		
1165	04/26/24	PR	Employee: 3110 Callum Deditch		HRS	5.000		
1226	03/28/24	PR	Employee: 3109 Cameron Ellsworth		HRS	0.500		
1227	03/28/24	PR	Employee: 3110 Callum Deditch		HRS	3.500		
1492	04/30/24	PR	Employee: 3110 Callum Deditch		HRS	3.500		

Labour Total 30.00

Parts Total 0.00

Miscellaneous Total 0.00

Labour Total 98.50

Parts Total 32,538.81

Miscellaneous Total 0.00

Description: Rental Return Legacy	9006 Hours	Date Started: 2023-11-08
Equipment: E416 Caterpillar D6T LGP A/W Dozer	RD-2023-303 Insheet	
Serial#: CAT00D6THKJL00698		

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
293	11/15/23	EMParts	1R0762 Filter-Fuel Advanced Efficiency		EA	1.000	34.60	34.60
294	11/15/23	EMParts	1R1808 Filter-Oil Advanced Efficiency		EA	1.000	40.40	40.40
295	11/15/23	EMParts	3261644 Filter-Fuel / Water Separator		EA	1.000	55.22	55.22
296	11/15/23	EMParts	6I2501 Filter-Air Primary		EA	1.000	63.07	63.07
297	11/15/23	EMParts	6T0988 Filter-Cab Air Standard Efficiency		EA	1.000	49.78	49.78
298	11/15/23	EMParts	6T5068 Filter-Cab Air		EA	1.000	29.01	29.01
299	11/15/23	EMParts	9P7121 Fuel Tank Screen		EA	1.000	55.66	55.66
403	03/20/25	EMParts	5W40 Spectra Xtreme 5W40 (CK-4)		I	30.000	7.81	234.35
404	03/20/25	EMParts	60/40 Rad-Cool Antifreeze		EA	3.000	4.82	14.46
405	03/20/25	EMParts	TO4 Spectra Xtreme TO-4 MG All Sea		EA	13.000	7.38	95.95

Labour Total 0.00

Parts Total 672.50

Miscellaneous Total 0.00

Segment: 2 Wash and Clean Cab



Work Order: 14508

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
208	06/05/24	PR	Employee: 2623 Brenton Woolman		HRS	9.500		

Labour Total	9.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 250 Hour Service

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1210	03/25/24	PR	Employee: 3110 Callum Deditch		HRS	3.000		

Labour Total	3.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 4 Remove Renters decals and repair radar

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1208	03/18/24	PR	Employee: 3110 Callum Deditch		HRS	2.500		
1209	03/21/24	PR	Employee: 3110 Callum Deditch		HRS	2.500		
1211	03/25/24	PR	Employee: 3110 Callum Deditch		HRS	0.500		

Labour Total	5.50
Parts Total	0.00
Miscellaneous Total	0.00

Labour Total	18.00
Parts Total	23,031.30
Miscellaneous Total	0.00

Description: Repair Final Drive and Leaks	7678 Hours	Date Started: 2018-01-05
Equipment: E416 Caterpillar D6T LGP A/W Dozer		
Serial#: CAT00D6THKJL00698		

Segment: 1 Parts - Repair Final Drive and Leaks



GCS Energy Services Ltd.

Work Order: Z10005

30L - 704 oil
 34L 5W40
 1 - 1R1808 Filter
 2 - 3/4" quick coupler set
 1 - used aster track pad
 1 - 9H3360 Seal (24.27)
 1 - 2430388 - Kit Seal H.C (231.67)
 1 - 2292626 - Kit Seal HC (180.99)
 1 - 8H0901 - Bearing-Cup (183.04)
 1 - 8H0902 - Cone (387.06)
 1 - 6V0330 - Cup (87.13)
 1 - 2K5066 - Cone (187.98)
 1 - 4194175 - Seal Lip (20.91)
 1 - 6Y0859 - Seal (298.07)
 1 - 1P9005 - Seal (9.88)
 8 - 2540224 Bolt (8.13/EA)
 1 - 3510956 - Link AS-Box (922.52)
 1 - 3510955 - Link AS-Box
 4 - 2349699 - Link Trak (114.45/EA)
 28 - 6Y9024 - Track bolt (3/EA)
 28 - HT530 - Nut Track (1.6/EA)
 1 - 9T6093 - Rod (525.00/EA)
 4 - M20-100 - Bolt (291.2/Per 100 - Total 11.65)
 1 - 1U1176 - Pin (84.72/EA)
 1 - 2J8489 - Bering (16.39/EA)
 2 - Hose Assembly (47.86/EA)

Segment: 2 RR, Reseal Blade Lift Cyl.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
83	01/05/18	EMTime	Employee: 1577 Dylan Grant		HRS	11.000		
						Labour Total	11.00	
						Parts Total	0.00	
						Miscellaneous Total	0.00	

Segment: 3 Disassemble RH Final Drive and Re-Seal

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
85	01/05/18	EMTime	Employee: 1577 Dylan Grant		HRS	21.000		
						Labour Total	21.00	
						Parts Total	0.00	
						Miscellaneous Total	0.00	

Segment: 4 Split LH Track and Cut out Leaking Track

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
86	01/05/18	EMTime	Employee: 1577 Dylan Grant		HRS	8.000		



Work Order: Z10005

Labour Total	8.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 5 Removed/Reseal LH Tilt Cyl.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
87	01/05/18	EMTime	Employee: 1577 Dylan Grant		HRS	10.500		

Labour Total	10.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 6 Test Engine Oil/Reseal LH Tilt Cyl. Shimmer Blade

Segment: 7 Test Engine Oil Pressure, Check for wear on injection pump

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
88	01/05/18	EMTime	Employee: 1577 Dylan Grant		HRS	9.000		

Labour Total	9.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 8 Change Blade Loser, coupler off hard nose

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
89	01/05/18	EMTime	Employee: 1577 Dylan Grant		HRS	1.500		

Labour Total	1.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 9 250/Hr Service

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
84	01/05/18	EMTime	Employee: 1577 Dylan Grant		HRS	6.000		



Work Order: Z10005

Labour Total	6.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 10 Resealed Winch Cover

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
90	01/05/18	EMTime	Employee: 1577 Dylan Grant		HRS	1.000		

Labour Total	1.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 11 Outsheet / Inspection

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
91	01/05/18	EMTime	Employee: 1575 Paul Nixon		HRS	1.000		

Labour Total	1.00
Parts Total	0.00
Miscellaneous Total	0.00

Labour Total	69.00
Parts Total	22,358.80
Miscellaneous Total	0.00