



Work Order: 10574

EB10-72

|                                                   |                             |                          |
|---------------------------------------------------|-----------------------------|--------------------------|
| Description: Flat Tire                            | 13373 Hours                 | Date Started: 2019-10-25 |
| Equipment: E359 Caterpillar 730 6 x 6 Water Wagon | GRO#9910                    |                          |
| Serial#: AGF00509                                 | *Unit over due for service* |                          |

Segment: 1 Parts and Service

Segment: 2 T/S and attempt to fill Flat tire

| Trans | Actual Date | Source | Details                    | STATUS | UM  | Units               | Price | Total Cost |
|-------|-------------|--------|----------------------------|--------|-----|---------------------|-------|------------|
| 630   | 10/29/19    | EMTime | Employee: 1577 Dylan Grant |        | HRS | 1.000               |       |            |
|       |             |        |                            |        |     | Labour Total        | 1.00  |            |
|       |             |        |                            |        |     | Parts Total         | 0.00  |            |
|       |             |        |                            |        |     | Miscellaneous Total | 0.00  |            |

Segment: 3 Assist Kal Tire with flat repair

Repair was expensed to unit.

| Trans | Actual Date | Source | Details                    | STATUS | UM  | Units               | Price | Total Cost |
|-------|-------------|--------|----------------------------|--------|-----|---------------------|-------|------------|
| 631   | 10/29/19    | EMTime | Employee: 1577 Dylan Grant |        | HRS | 2.000               |       |            |
|       |             |        |                            |        |     | Labour Total        | 2.00  |            |
|       |             |        |                            |        |     | Parts Total         | 0.00  |            |
|       |             |        |                            |        |     | Miscellaneous Total | 0.00  |            |
|       |             |        |                            |        |     | Labour Total        | 3.00  |            |
|       |             |        |                            |        |     | Parts Total         | 0.00  |            |
|       |             |        |                            |        |     | Miscellaneous Total | 0.00  |            |

|                                                    |                         |                          |
|----------------------------------------------------|-------------------------|--------------------------|
| Description: Inspections, 4000 Service and Repairs | 13376 Hours             | Date Started: 2020-01-31 |
| Equipment: E359 Caterpillar 730 6 x 6 Water Wagon  | RD-2020-111 Insheet     |                          |
| Serial#: AGF00509                                  | RD-2020-161 Outsheat    |                          |
|                                                    | GRO-9631/9585/9658/9717 |                          |

Segment: 1 Parts and Service

| Trans | Actual Date | Source | Details                                                      | STATUS | UM | Units | Price | Total Cost |
|-------|-------------|--------|--------------------------------------------------------------|--------|----|-------|-------|------------|
| 255   | 06/01/20    | AP     | Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S5818409.001 | LS     |    | 0.000 | 0.00  | 21.54      |
|       |             |        | Line: 1                                                      |        |    |       |       |            |
| 312   | 04/06/20    | AP     | Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S5762583.001 | LS     |    | 0.000 | 0.00  | 24.27      |
|       |             |        | Line: 1                                                      |        |    |       |       |            |
| 467   | 04/14/20    | AP     | Vendor: 10132 Gregg Distributors LP 059-288683 Line: 2       | EA     |    | 4.000 | 2.38  | 9.52       |
| 468   | 04/14/20    | AP     | Vendor: 10132 Gregg Distributors LP 059-288683 Line: 3       | EA     |    | 2.000 | 1.97  | 3.94       |



## Work Order: 10715

|      |          |         |                                                              |    |        |        |        |
|------|----------|---------|--------------------------------------------------------------|----|--------|--------|--------|
| 642  | 03/12/20 | AP      | Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S5744027.001 | LS | 0.000  | 0.00   | 181.02 |
|      |          |         | Line: 1                                                      |    |        |        |        |
| 643  | 03/10/20 | AP      | Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S5741264.001 | LS | 0.000  | 0.00   | 37.14  |
|      |          |         | Line: 1                                                      |    |        |        |        |
| 720  | 04/13/20 | AP      | Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S5766787.001 | LS | 0.000  | 0.00   | 44.18  |
|      |          |         | Line: 1                                                      |    |        |        |        |
| 789  | 04/29/20 | AP      | Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S5784096.001 | LS | 0.000  | 0.00   | 467.52 |
|      |          |         | Line: 2                                                      |    |        |        |        |
| 825  | 03/13/20 | AP      | Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S5744765.001 | LS | 0.000  | 0.00   | 83.04  |
|      |          |         | Line: 1                                                      |    |        |        |        |
| 1187 | 03/11/20 | AP      | Vendor: 10202 McLevin Industries Inc. 192826 Line: 1         | EA | 8.000  | 19.32  | 154.56 |
| 1188 | 03/17/20 | AP      | Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S5746968.001 | LS | 0.000  | 0.00   | 10.29  |
|      |          |         | Line: 1                                                      |    |        |        |        |
| 1189 | 03/13/20 | AP      | Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S5745207.001 | LS | 0.000  | 0.00   | 7.00   |
|      |          |         | Line: 1                                                      |    |        |        |        |
| 1190 | 03/18/20 | AP      | Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S5748934.001 | LS | 0.000  | 0.00   | 29.90  |
|      |          |         | Line: 1                                                      |    |        |        |        |
| 1201 | 03/19/20 | AP      | Vendor: 10034 Brandt Tractor Ltd. 05 4582910 Line: 1         | EA | 1.000  | 134.66 | 134.66 |
| 1323 | 03/25/20 | AP      | Vendor: 32797 P.S.I. Fluid Power Ltd 3126856 Line: 1         | EA | 1.000  | 321.15 | 321.15 |
| 1430 | 03/23/20 | AP      | Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S5751891.001 | LS | 0.000  | 0.00   | 12.66  |
|      |          |         | Line: 1                                                      |    |        |        |        |
| 1431 | 03/23/20 | AP      | Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S5752115.001 | LS | 0.000  | 0.00   | 17.64  |
|      |          |         | Line: 1                                                      |    |        |        |        |
| 1432 | 03/19/20 | AP      | Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S5750329.001 | LS | 0.000  | 0.00   | -0.32  |
|      |          |         | Line: 1                                                      |    |        |        |        |
| 1433 | 03/24/20 | AP      | Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S5752867.001 | LS | 0.000  | 0.00   | 339.38 |
|      |          |         | Line: 1                                                      |    |        |        |        |
| 2285 | 03/27/20 | AP      | Vendor: 10401 RBC Avion Visa MAR/20 Lance Line: 29           | LS | 0.000  | 0.00   | 84.67  |
| 2286 | 03/27/20 | AP      | Vendor: 10401 RBC Avion Visa MAR/20 Lance Line: 32           | EA | 8.000  | 9.60   | 76.80  |
| 2287 | 03/27/20 | AP      | Vendor: 10401 RBC Avion Visa MAR/20 Lance Line: 33           | EA | 5.000  | 2.24   | 11.20  |
| 2288 | 03/27/20 | AP      | Vendor: 10401 RBC Avion Visa MAR/20 Lance Line: 34           | EA | 5.000  | 0.10   | 0.50   |
| 2289 | 03/27/20 | AP      | Vendor: 10401 RBC Avion Visa MAR/20 Lance Line: 35           | EA | 10.000 | 0.05   | 0.50   |
| 2290 | 03/27/20 | AP      | Vendor: 10401 RBC Avion Visa MAR/20 Lance Line: 36           | LS | 0.000  | 0.00   | 30.00  |
| 2996 | 04/27/20 | AP      | Vendor: 10401 RBC Avion Visa APR 20/Lance Line: 3            | EA | 2.000  | 9.60   | 19.20  |
| 2997 | 04/27/20 | AP      | Vendor: 10401 RBC Avion Visa APR 20/Lance Line: 4            | EA | 2.000  | 3.80   | 7.60   |
| 2998 | 04/27/20 | AP      | Vendor: 10401 RBC Avion Visa APR 20/Lance Line: 5            | LS | 0.000  | 0.00   | 30.00  |
| 49   | 06/02/20 | EMParts | 1008525 Gasket                                               | EA | 1.000  | 2.28   | 2.28   |
| 50   | 06/02/20 | EMParts | 1011635 Gasket                                               | EA | 1.000  | 1.38   | 1.38   |
| 51   | 06/02/20 | EMParts | 5P8068 Seal-O-Ring                                           | EA | 2.000  | 19.61  | 39.21  |
| 52   | 06/02/20 | EMParts | 618561 Seal                                                  | EA | 1.000  | 14.03  | 14.03  |
| 53   | 06/02/20 | EMParts | OS-6V5134 Seal-O-Ring                                        | EA | 3.000  | 18.24  | 54.72  |
| 54   | 06/02/20 | EMParts | 9H8872 Gasket                                                | EA | 1.000  | 2.67   | 2.67   |
| 79   | 06/03/20 | EMParts | 2165584 Bushing Sleeve-Cam                                   | EA | 1.000  | 69.90  | 69.90  |
| 80   | 06/03/20 | EMParts | 4K9841 Washer                                                | EA | 1.000  | 3.15   | 3.15   |
| 81   | 06/03/20 | EMParts | 5P5678 Seal-Bulk By the Meter                                | EA | 3.000  | 28.14  | 84.42  |
| 82   | 06/03/20 | EMParts | 6D1004 Gasket-Fuel Transfer Pump                             | EA | 1.000  | 3.23   | 3.23   |
| 83   | 06/03/20 | EMParts | 8J4351 Seal O Ring                                           | EA | 2.000  | 18.79  | 37.58  |
| 84   | 06/03/20 | EMParts | 6V0405 Washer-Sealing                                        | EA | 2.000  | 6.52   | 13.04  |
| 250  | 06/08/20 | EMParts | 9P7121 Fuel Tank Screen                                      | EA | 1.000  | 46.70  | 46.70  |
| 288  | 08/12/20 | EMParts | 4662407 Kit Gasket                                           | EA | 1.000  | 484.12 | 484.12 |
| 388  | 03/11/20 | EMParts | 1231PMF Battery-12v Group 31                                 | EA | 2.000  | 134.95 | 269.90 |
| 410  | 02/12/20 | EMParts | 1421339 Filter-Air Primary                                   | EA | 1.000  | 76.32  | 76.32  |
| 411  | 02/12/20 | EMParts | 1R0762 Filter-Fuel Advanced Efficiency                       | EA | 1.000  | 29.71  | 29.71  |
| 412  | 02/12/20 | EMParts | 1R1808 Filter-Oil Advanced Efficiency                        | EA | 1.000  | 33.18  | 33.18  |
| 413  | 02/12/20 | EMParts | 5134490 Filter-Fuel / Water Separator                        | EA | 1.000  | 43.72  | 43.72  |
| 414  | 02/12/20 | EMParts | 1193355 Filter-Cab Air Standard Efficiency                   | EA | 1.000  | 31.36  | 31.36  |
| 415  | 02/12/20 | EMParts | 1748145 Filter-Cab Air                                       | EA | 1.000  | 24.35  | 24.35  |
| 416  | 02/12/20 | EMParts | 1328876 Filter-Power Train                                   | EA | 2.000  | 44.24  | 88.48  |
| 417  | 02/12/20 | EMParts | 1391537 Filter-Hydraulic Ultra High Ef                       | EA | 1.000  | 43.03  | 43.03  |
| 418  | 02/12/20 | EMParts | 1446691 Filter-Hydraulic/Transmission                        | EA | 1.000  | 51.75  | 51.75  |
| 419  | 02/12/20 | EMParts | 2D8009 Seal O Ring                                           | EA | 1.000  | 9.01   | 9.01   |
| 420  | 02/12/20 | EMParts | 3567423 Breather-Hydraulic Tank                              | EA | 1.000  | 182.02 | 182.02 |
| 421  | 02/12/20 | EMParts | 4H6112 Breather-Tandem                                       | EA | 2.000  | 21.35  | 42.70  |



## Work Order: 10715

|      |          |         |                                       |    |        |        |        |
|------|----------|---------|---------------------------------------|----|--------|--------|--------|
| 422  | 02/12/20 | EMParts | 6U1989 Breather                       | EA | 3.000  | 2.91   | 8.73   |
| 423  | 02/12/20 | EMParts | 8J1665 Seal-O-Ring                    | EA | 1.000  | 6.46   | 6.46   |
| 427  | 03/11/20 | EMParts | 1058901 Gasket-Transmission Cooler    | EA | 2.000  | 9.61   | 19.22  |
| 428  | 03/11/20 | EMParts | 1095308 Gasket-Oil Pan                | EA | 1.000  | 308.21 | 308.21 |
| 429  | 03/11/20 | EMParts | 5P8211 Seal-O-Ring                    | EA | 1.000  | 22.03  | 22.03  |
| 430  | 03/11/20 | EMParts | 7C8296 Isolator-Oil Pan               | EA | 14.000 | 9.70   | 135.80 |
| 639  | 03/13/20 | EMParts | 8M7160 Magnet                         | EA | 1.000  | 10.65  | 10.65  |
| 690  | 08/16/20 | EMParts | 5W40 Spectra 5W40                     | I  | 67.000 | 5.21   | 349.30 |
| 691  | 08/16/20 | EMParts | 60/40 Rad-Cool Antifreeze             | EA | 3.000  | 5.90   | 17.70  |
| 692  | 08/16/20 | EMParts | 75W90 Certop SN 75W90 Gear Lube       | EA | 5.500  | 9.71   | 53.39  |
| 693  | 08/16/20 | EMParts | TO4 Spectra Xtreme TO-4 All season    | EA | 1.000  | 5.59   | 5.59   |
| 1076 | 04/24/20 | EMParts | 3E8772 Switch Assembly-Head Light&Tai | EA | 1.000  | 150.92 | 150.92 |
| 1077 | 04/24/20 | EMParts | 3E9326 Actuator-Switch                | EA | 1.000  | 28.58  | 28.58  |
| 1078 | 04/24/20 | EMParts | 9S4693 Breaker(80amp)                 | EA | 1.000  | 89.42  | 89.42  |
| 1229 | 04/29/20 | EMParts | 9H8872 Gasket                         | EA | 1.000  | 2.67   | 2.67   |
| 1599 | 06/17/20 | EMParts | Dyed Diesel Dyed Diesel               | EA | 45.420 | 0.60   | 27.38  |
| 3656 | 09/16/20 | EMParts | 1234003 Seal-Lip                      | EA | 1.000  | 52.54  | 52.54  |
| 3657 | 09/16/20 | EMParts | 1757904 Seal-O-Ring                   | EA | 1.000  | 11.39  | 11.39  |
| 3658 | 09/16/20 | EMParts | 4F7391 Seal-O-Ring                    | EA | 1.000  | 3.62   | 3.62   |
| 3659 | 09/16/20 | EMParts | 9F1399 Ring                           | EA | 1.000  | 10.44  | 10.44  |

|                     |          |
|---------------------|----------|
| Labour Total        | 0.00     |
| Parts Total         | 5,255.56 |
| Miscellaneous Total | 0.00     |

### Segment: 2 Insheet Inspection

| Trans | Actual Date | Source | Details                    | STATUS | UM  | Units | Price | Total Cost |
|-------|-------------|--------|----------------------------|--------|-----|-------|-------|------------|
| 930   | 01/31/20    | EMTime | Employee: 1577 Dylan Grant |        | HRS | 2.000 |       |            |

|                     |      |
|---------------------|------|
| Labour Total        | 2.00 |
| Parts Total         | 0.00 |
| Miscellaneous Total | 0.00 |

### Segment: 3 Wash and Clean Cab

| Trans | Actual Date | Source | Details                       | STATUS | UM  | Units  | Price | Total Cost |
|-------|-------------|--------|-------------------------------|--------|-----|--------|-------|------------|
| 1443  | 04/28/20    | PR     | Employee: 1074 Jack Lougheed  |        | HRS | 3.000  |       |            |
| 2600  | 04/28/20    | PR     | Employee: 1074 Jack Lougheed  |        | HRS | -3.000 |       |            |
| 2601  | 04/28/20    | PR     | Employee: 1074 Jack Lougheed  |        | HRS | 3.000  |       |            |
| 1272  | 02/19/20    | EMTime | Employee: 1074 Jack Lougheed  |        | HRS | 5.500  |       |            |
| 1287  | 02/19/20    | EMTime | Employee: 2395 Nickolas Schou |        | HRS | 1.000  |       |            |
| 1417  | 02/20/20    | EMTime | Employee: 1074 Jack Lougheed  |        | HRS | 1.500  |       |            |
| 1420  | 02/21/20    | EMTime | Employee: 1074 Jack Lougheed  |        | HRS | 2.000  |       |            |



**Work Order: 10715**

|                     |       |
|---------------------|-------|
| Labour Total        | 13.00 |
| Parts Total         | 0.00  |
| Miscellaneous Total | 0.00  |

**Segment: 4 4000 Hour Service, Check and Adjust Fluid Levels**

| Trans | Actual Date | Source | Details                       | STATUS | UM  | Units  | Price | Total Cost |
|-------|-------------|--------|-------------------------------|--------|-----|--------|-------|------------|
| 1547  | 04/28/20    | PR     | Employee: 1577 Dylan Grant    |        | HRS | 4.500  |       |            |
| 2602  | 04/28/20    | PR     | Employee: 1577 Dylan Grant    |        | HRS | -4.500 |       |            |
| 2603  | 04/28/20    | PR     | Employee: 1577 Dylan Grant    |        | HRS | 4.500  |       |            |
| 761   | 03/13/20    | EMTime | Employee: 2395 Nickolas Schou |        | HRS | 4.000  |       |            |
| 762   | 03/16/20    | EMTime | Employee: 2395 Nickolas Schou |        | HRS | 1.500  |       |            |
| 1281  | 02/18/20    | EMTime | Employee: 2395 Nickolas Schou |        | HRS | 0.500  |       |            |

|                     |       |
|---------------------|-------|
| Labour Total        | 10.50 |
| Parts Total         | 0.00  |
| Miscellaneous Total | 0.00  |

**Segment: 5 T/S and repair park brake**

| Trans | Actual Date | Source | Details                       | STATUS | UM  | Units | Price | Total Cost |
|-------|-------------|--------|-------------------------------|--------|-----|-------|-------|------------|
| 1280  | 02/18/20    | EMTime | Employee: 2395 Nickolas Schou |        | HRS | 3.500 |       |            |
| 1293  | 02/14/20    | EMTime | Employee: 2395 Nickolas Schou |        | HRS | 3.000 |       |            |

|                     |      |
|---------------------|------|
| Labour Total        | 6.50 |
| Parts Total         | 0.00 |
| Miscellaneous Total | 0.00 |

**Segment: 6 T/S and repair exhaust leak**

**Segment: 7 T/S and repair Oil leak on front cover**

| Trans | Actual Date | Source | Details                   | STATUS | UM  | Units  | Price | Total Cost |
|-------|-------------|--------|---------------------------|--------|-----|--------|-------|------------|
| 207   | 06/01/20    | PR     | Employee: 1575 Paul Nixon |        | HRS | 5.500  |       |            |
| 208   | 06/02/20    | PR     | Employee: 1575 Paul Nixon |        | HRS | 9.000  |       |            |
| 209   | 06/03/20    | PR     | Employee: 1575 Paul Nixon |        | HRS | 9.000  |       |            |
| 210   | 06/04/20    | PR     | Employee: 1575 Paul Nixon |        | HRS | 7.000  |       |            |
| 455   | 06/01/20    | PR     | Employee: 1575 Paul Nixon |        | HRS | -5.500 |       |            |
| 456   | 06/01/20    | PR     | Employee: 1575 Paul Nixon |        | HRS | 5.500  |       |            |
| 457   | 06/02/20    | PR     | Employee: 1575 Paul Nixon |        | HRS | -9.000 |       |            |
| 458   | 06/02/20    | PR     | Employee: 1575 Paul Nixon |        | HRS | 9.000  |       |            |
| 459   | 06/03/20    | PR     | Employee: 1575 Paul Nixon |        | HRS | -9.000 |       |            |
| 460   | 06/03/20    | PR     | Employee: 1575 Paul Nixon |        | HRS | 9.000  |       |            |
| 461   | 06/04/20    | PR     | Employee: 1575 Paul Nixon |        | HRS | -7.000 |       |            |



**Work Order: 10715**

|      |          |        |                               |     |        |
|------|----------|--------|-------------------------------|-----|--------|
| 462  | 06/04/20 | PR     | Employee: 1575 Paul Nixon     | HRS | 7.000  |
| 463  | 06/05/20 | PR     | Employee: 1575 Paul Nixon     | HRS | 6.000  |
| 465  | 06/08/20 | PR     | Employee: 1575 Paul Nixon     | HRS | 7.000  |
| 740  | 06/01/20 | PR     | Employee: 1575 Paul Nixon     | HRS | -5.500 |
| 741  | 06/01/20 | PR     | Employee: 1575 Paul Nixon     | HRS | 5.500  |
| 742  | 06/02/20 | PR     | Employee: 1575 Paul Nixon     | HRS | -9.000 |
| 743  | 06/02/20 | PR     | Employee: 1575 Paul Nixon     | HRS | 9.000  |
| 744  | 06/03/20 | PR     | Employee: 1575 Paul Nixon     | HRS | -9.000 |
| 745  | 06/03/20 | PR     | Employee: 1575 Paul Nixon     | HRS | 9.000  |
| 746  | 06/04/20 | PR     | Employee: 1575 Paul Nixon     | HRS | -7.000 |
| 747  | 06/04/20 | PR     | Employee: 1575 Paul Nixon     | HRS | 7.000  |
| 748  | 06/05/20 | PR     | Employee: 1575 Paul Nixon     | HRS | -6.000 |
| 749  | 06/05/20 | PR     | Employee: 1575 Paul Nixon     | HRS | 6.000  |
| 752  | 06/08/20 | PR     | Employee: 1575 Paul Nixon     | HRS | -7.000 |
| 753  | 06/08/20 | PR     | Employee: 1575 Paul Nixon     | HRS | 7.000  |
| 1290 | 06/01/20 | PR     | Employee: 1575 Paul Nixon     | HRS | -5.500 |
| 1291 | 06/01/20 | PR     | Employee: 1575 Paul Nixon     | HRS | 5.500  |
| 1292 | 06/02/20 | PR     | Employee: 1575 Paul Nixon     | HRS | -9.000 |
| 1293 | 06/02/20 | PR     | Employee: 1575 Paul Nixon     | HRS | 9.000  |
| 1294 | 06/03/20 | PR     | Employee: 1575 Paul Nixon     | HRS | -9.000 |
| 1295 | 06/03/20 | PR     | Employee: 1575 Paul Nixon     | HRS | 9.000  |
| 1296 | 06/04/20 | PR     | Employee: 1575 Paul Nixon     | HRS | -7.000 |
| 1297 | 06/04/20 | PR     | Employee: 1575 Paul Nixon     | HRS | 7.000  |
| 1298 | 06/05/20 | PR     | Employee: 1575 Paul Nixon     | HRS | -6.000 |
| 1299 | 06/05/20 | PR     | Employee: 1575 Paul Nixon     | HRS | 6.000  |
| 1302 | 06/08/20 | PR     | Employee: 1575 Paul Nixon     | HRS | -7.000 |
| 1303 | 06/08/20 | PR     | Employee: 1575 Paul Nixon     | HRS | 7.000  |
| 2612 | 05/29/20 | PR     | Employee: 1575 Paul Nixon     | HRS | 3.000  |
| 477  | 03/11/20 | EMTime | Employee: 2395 Nickolas Schou | HRS | 4.500  |
| 479  | 03/10/20 | EMTime | Employee: 2395 Nickolas Schou | HRS | 1.000  |
| 760  | 03/13/20 | EMTime | Employee: 2395 Nickolas Schou | HRS | 3.500  |
| 763  | 03/16/20 | EMTime | Employee: 2395 Nickolas Schou | HRS | 2.000  |
| 801  | 03/12/20 | EMTime | Employee: 2395 Nickolas Schou | HRS | 6.500  |

|                     |       |
|---------------------|-------|
| Labour Total        | 64.00 |
| Parts Total         | 0.00  |
| Miscellaneous Total | 0.00  |

**Segment: 8 T/S and repair A/C**

| Trans | Actual Date | Source | Details                       | STATUS | UM  | Units | Price | Total Cost |
|-------|-------------|--------|-------------------------------|--------|-----|-------|-------|------------|
| 765   | 03/16/20    | EMTime | Employee: 2395 Nickolas Schou |        | HRS | 3.000 |       |            |

  

|                     |      |
|---------------------|------|
| Labour Total        | 3.00 |
| Parts Total         | 0.00 |
| Miscellaneous Total | 0.00 |



**Work Order: 10715**

**Segment: 9 Test and Repair Water System**

| Trans | Actual Date | Source | Details                       | STATUS | UM  | Units               | Price | Total Cost |
|-------|-------------|--------|-------------------------------|--------|-----|---------------------|-------|------------|
| 895   | 03/18/20    | EMTime | Employee: 2395 Nickolas Schou |        | HRS | 2.500               |       |            |
|       |             |        |                               |        |     | Labour Total        | 2.50  |            |
|       |             |        |                               |        |     | Parts Total         | 0.00  |            |
|       |             |        |                               |        |     | Miscellaneous Total | 0.00  |            |

**Segment: 10 Free up P.A.S.S.**

| Trans | Actual Date | Source | Details                       | STATUS | UM  | Units               | Price | Total Cost |
|-------|-------------|--------|-------------------------------|--------|-----|---------------------|-------|------------|
| 890   | 03/17/20    | EMTime | Employee: 2395 Nickolas Schou |        | HRS | 1.000               |       |            |
| 1258  | 03/23/20    | EMTime | Employee: 2395 Nickolas Schou |        | HRS | 0.500               |       |            |
|       |             |        |                               |        |     | Labour Total        | 1.50  |            |
|       |             |        |                               |        |     | Parts Total         | 0.00  |            |
|       |             |        |                               |        |     | Miscellaneous Total | 0.00  |            |

**Segment: 11 Inspect and adjust Coolant**

| Trans | Actual Date | Source | Details                       | STATUS | UM  | Units               | Price | Total Cost |
|-------|-------------|--------|-------------------------------|--------|-----|---------------------|-------|------------|
| 802   | 03/12/20    | EMTime | Employee: 2395 Nickolas Schou |        | HRS | 0.500               |       |            |
|       |             |        |                               |        |     | Labour Total        | 0.50  |            |
|       |             |        |                               |        |     | Parts Total         | 0.00  |            |
|       |             |        |                               |        |     | Miscellaneous Total | 0.00  |            |

**Segment: 12 Check and adjust tire pressures**

| Trans | Actual Date | Source | Details                       | STATUS | UM  | Units               | Price | Total Cost |
|-------|-------------|--------|-------------------------------|--------|-----|---------------------|-------|------------|
| 891   | 03/17/20    | EMTime | Employee: 2395 Nickolas Schou |        | HRS | 1.000               |       |            |
|       |             |        |                               |        |     | Labour Total        | 1.00  |            |
|       |             |        |                               |        |     | Parts Total         | 0.00  |            |
|       |             |        |                               |        |     | Miscellaneous Total | 0.00  |            |

**Segment: 13 Tilt and inspect under cab**

| Trans | Actual Date | Source | Details                       | STATUS | UM  | Units | Price | Total Cost |
|-------|-------------|--------|-------------------------------|--------|-----|-------|-------|------------|
| 1282  | 02/18/20    | EMTime | Employee: 2395 Nickolas Schou |        | HRS | 1.000 |       |            |



Work Order: 10715

|                     |      |
|---------------------|------|
| Labour Total        | 1.00 |
| Parts Total         | 0.00 |
| Miscellaneous Total | 0.00 |

Segment: 14 T/S Radio

Segment: 15 Test and Replace Batteries

| Trans | Actual Date | Source | Details                       | STATUS | UM  | Units | Price | Total Cost |
|-------|-------------|--------|-------------------------------|--------|-----|-------|-------|------------|
| 475   | 03/10/20    | EMTime | Employee: 2395 Nickolas Schou |        | HRS | 1.000 |       |            |
| 476   | 03/11/20    | EMTime | Employee: 2395 Nickolas Schou |        | HRS | 3.000 |       |            |
| 764   | 03/16/20    | EMTime | Employee: 2395 Nickolas Schou |        | HRS | 1.000 |       |            |

|                     |      |
|---------------------|------|
| Labour Total        | 5.00 |
| Parts Total         | 0.00 |
| Miscellaneous Total | 0.00 |

Segment: 16 Work on Water Tank

*Remove old brackets, build 4" Fill line.  
Test water pump and motor*

| Trans | Actual Date | Source | Details                       | STATUS | UM  | Units | Price | Total Cost |
|-------|-------------|--------|-------------------------------|--------|-----|-------|-------|------------|
| 81    | 04/03/20    | EMTime | Employee: 2395 Nickolas Schou |        | HRS | 2.500 |       |            |
| 474   | 03/10/20    | EMTime | Employee: 2395 Nickolas Schou |        | HRS | 2.500 |       |            |
| 607   | 04/06/20    | EMTime | Employee: 2395 Nickolas Schou |        | HRS | 6.500 |       |            |
| 892   | 03/17/20    | EMTime | Employee: 2395 Nickolas Schou |        | HRS | 5.500 |       |            |
| 894   | 03/18/20    | EMTime | Employee: 2395 Nickolas Schou |        | HRS | 5.000 |       |            |
| 897   | 03/19/20    | EMTime | Employee: 2395 Nickolas Schou |        | HRS | 5.500 |       |            |
| 900   | 03/20/20    | EMTime | Employee: 2395 Nickolas Schou |        | HRS | 4.000 |       |            |
| 908   | 03/19/20    | EMTime | Employee: 1074 Jack Loughheed |        | HRS | 1.500 |       |            |
| 1049  | 04/13/20    | EMTime | Employee: 2395 Nickolas Schou |        | HRS | 7.500 |       |            |
| 1259  | 03/23/20    | EMTime | Employee: 2395 Nickolas Schou |        | HRS | 7.000 |       |            |
| 1261  | 03/24/20    | EMTime | Employee: 2395 Nickolas Schou |        | HRS | 7.500 |       |            |
| 1269  | 03/26/20    | EMTime | Employee: 2395 Nickolas Schou |        | HRS | 5.000 |       |            |
| 1273  | 03/27/20    | EMTime | Employee: 2395 Nickolas Schou |        | HRS | 7.500 |       |            |

|                     |       |
|---------------------|-------|
| Labour Total        | 67.50 |
| Parts Total         | 0.00  |
| Miscellaneous Total | 0.00  |

Segment: 17 T/S Hydraulic leak

| Trans | Actual Date | Source | Details                        | STATUS | UM  | Units | Price | Total Cost |
|-------|-------------|--------|--------------------------------|--------|-----|-------|-------|------------|
| 153   | 05/01/20    | PR     | Employee: 2338 Nolan MacGregor |        | HRS | 2.500 |       |            |



## Work Order: 10715

|      |          |    |                                |     |        |
|------|----------|----|--------------------------------|-----|--------|
| 467  | 05/03/20 | PR | Employee: 1577 Dylan Grant     | HRS | 2.000  |
| 1133 | 05/03/20 | PR | Employee: 1577 Dylan Grant     | HRS | -2.000 |
| 1134 | 05/03/20 | PR | Employee: 1577 Dylan Grant     | HRS | 2.000  |
| 1546 | 04/28/20 | PR | Employee: 2338 Nolan MacGregor | HRS | 3.000  |
| 1548 | 04/29/20 | PR | Employee: 2338 Nolan MacGregor | HRS | 3.000  |
| 2604 | 04/29/20 | PR | Employee: 2338 Nolan MacGregor | HRS | -3.000 |
| 2605 | 04/29/20 | PR | Employee: 2338 Nolan MacGregor | HRS | 3.000  |
| 2608 | 04/30/20 | PR | Employee: 2338 Nolan MacGregor | HRS | 5.500  |

|                     |       |
|---------------------|-------|
| Labour Total        | 16.00 |
| Parts Total         | 0.00  |
| Miscellaneous Total | 0.00  |

### Segment: 18 T/S no power to cab, no taillights

| Trans | Actual Date | Source | Details                    | STATUS | UM  | Units  | Price | Total Cost |
|-------|-------------|--------|----------------------------|--------|-----|--------|-------|------------|
| 1540  | 04/22/20    | PR     | Employee: 1577 Dylan Grant |        | HRS | 4.000  |       |            |
| 1541  | 04/23/20    | PR     | Employee: 1577 Dylan Grant |        | HRS | 3.000  |       |            |
| 1542  | 04/24/20    | PR     | Employee: 1577 Dylan Grant |        | HRS | 2.000  |       |            |
| 2588  | 04/22/20    | PR     | Employee: 1577 Dylan Grant |        | HRS | -4.000 |       |            |
| 2589  | 04/22/20    | PR     | Employee: 1577 Dylan Grant |        | HRS | 4.000  |       |            |
| 2590  | 04/23/20    | PR     | Employee: 1577 Dylan Grant |        | HRS | -3.000 |       |            |
| 2591  | 04/23/20    | PR     | Employee: 1577 Dylan Grant |        | HRS | 3.000  |       |            |
| 2592  | 04/24/20    | PR     | Employee: 1577 Dylan Grant |        | HRS | -2.000 |       |            |
| 2593  | 04/24/20    | PR     | Employee: 1577 Dylan Grant |        | HRS | 2.000  |       |            |

|                     |      |
|---------------------|------|
| Labour Total        | 9.00 |
| Parts Total         | 0.00 |
| Miscellaneous Total | 0.00 |

### Segment: 19 Run and test

| Trans | Actual Date | Source | Details                    | STATUS | UM  | Units  | Price | Total Cost |
|-------|-------------|--------|----------------------------|--------|-----|--------|-------|------------|
| 1543  | 04/24/20    | PR     | Employee: 1577 Dylan Grant |        | HRS | 1.000  |       |            |
| 2594  | 04/24/20    | PR     | Employee: 1577 Dylan Grant |        | HRS | -1.000 |       |            |
| 2595  | 04/24/20    | PR     | Employee: 1577 Dylan Grant |        | HRS | 1.000  |       |            |

|                     |      |
|---------------------|------|
| Labour Total        | 1.00 |
| Parts Total         | 0.00 |
| Miscellaneous Total | 0.00 |

### Segment: 20 T/S low pump RPM

| Trans | Actual Date | Source | Details | STATUS | UM | Units | Price | Total Cost |
|-------|-------------|--------|---------|--------|----|-------|-------|------------|
|-------|-------------|--------|---------|--------|----|-------|-------|------------|





## Work Order: 10715

|      |          |    |                            |     |        |
|------|----------|----|----------------------------|-----|--------|
| 1544 | 04/24/20 | PR | Employee: 1577 Dylan Grant | HRS | 1.500  |
| 1545 | 04/27/20 | PR | Employee: 1577 Dylan Grant | HRS | 5.000  |
| 1549 | 04/29/20 | PR | Employee: 1577 Dylan Grant | HRS | 2.500  |
| 2596 | 04/24/20 | PR | Employee: 1577 Dylan Grant | HRS | -1.500 |
| 2597 | 04/24/20 | PR | Employee: 1577 Dylan Grant | HRS | 1.500  |
| 2598 | 04/27/20 | PR | Employee: 1577 Dylan Grant | HRS | -5.000 |
| 2599 | 04/27/20 | PR | Employee: 1577 Dylan Grant | HRS | 5.000  |
| 2606 | 04/29/20 | PR | Employee: 1577 Dylan Grant | HRS | -2.500 |
| 2607 | 04/29/20 | PR | Employee: 1577 Dylan Grant | HRS | 2.500  |

|                     |      |
|---------------------|------|
| Labour Total        | 9.00 |
| Parts Total         | 0.00 |
| Miscellaneous Total | 0.00 |

### Segment: 21 Outsheet

| Trans | Actual Date | Source | Details                   | STATUS | UM  | Units  | Price | Total Cost |
|-------|-------------|--------|---------------------------|--------|-----|--------|-------|------------|
| 464   | 06/08/20    | PR     | Employee: 1575 Paul Nixon |        | HRS | 2.000  |       |            |
| 750   | 06/08/20    | PR     | Employee: 1575 Paul Nixon |        | HRS | -2.000 |       |            |
| 751   | 06/08/20    | PR     | Employee: 1575 Paul Nixon |        | HRS | 2.000  |       |            |
| 1300  | 06/08/20    | PR     | Employee: 1575 Paul Nixon |        | HRS | -2.000 |       |            |
| 1301  | 06/08/20    | PR     | Employee: 1575 Paul Nixon |        | HRS | 2.000  |       |            |

|                     |      |
|---------------------|------|
| Labour Total        | 2.00 |
| Parts Total         | 0.00 |
| Miscellaneous Total | 0.00 |

|                     |          |
|---------------------|----------|
| Labour Total        | 215.00   |
| Parts Total         | 5,255.56 |
| Miscellaneous Total | 0.00     |

**Description:** Repair Leaking water valves, T/S and Repair P; GRO-9385  
**Equipment:** E359 Caterpillar 730 6 x 6 Water Wagon 13,551 Hours  
**Date Started:** 2020-07-24  
**Serial#:** AGF00509

### Segment: 1 Parts and Service

| Trans | Actual Date | Source  | Details                           | STATUS | UM | Units | Price  | Total Cost |
|-------|-------------|---------|-----------------------------------|--------|----|-------|--------|------------|
| 793   | 08/17/20    | EMParts | 2060408 Park Brake Actuator Assy. |        | EA | 1.000 | 687.42 | 687.42     |
| 794   | 08/17/20    | EMParts | 3B4611 Cotter Pin                 |        | EA | 1.000 | 0.08   | 0.08       |
| 795   | 08/18/20    | EMParts | 1723931 Pin                       |        | EA | 1.000 | 11.19  | 11.19      |
| 796   | 08/18/20    | EMParts | 3460331 Yoke-Actuator             |        | EA | 1.000 | 192.46 | 192.46     |



## Work Order: 11357

|                     |        |
|---------------------|--------|
| Labour Total        | 0.00   |
| Parts Total         | 891.15 |
| Miscellaneous Total | 0.00   |

### Segment: 2 Repair leaking water valves

| Trans | Actual Date | Source | Details                    | STATUS | UM  | Units | Price | Total Cost |
|-------|-------------|--------|----------------------------|--------|-----|-------|-------|------------|
| 1396  | 08/12/20    | PR     | Employee: 1577 Dylan Grant |        | HRS | 2.000 |       |            |
| 2073  | 07/23/20    | PR     | Employee: 1577 Dylan Grant |        | HRS | 1.000 |       |            |
| 3444  | 07/27/20    | PR     | Employee: 1577 Dylan Grant |        | HRS | 1.000 |       |            |

|                     |      |
|---------------------|------|
| Labour Total        | 4.00 |
| Parts Total         | 0.00 |
| Miscellaneous Total | 0.00 |

### Segment: 3 Repair Park Brake

| Trans | Actual Date | Source | Details                    | STATUS | UM  | Units | Price | Total Cost |
|-------|-------------|--------|----------------------------|--------|-----|-------|-------|------------|
| 1397  | 08/19/20    | PR     | Employee: 1577 Dylan Grant |        | HRS | 4.000 |       |            |

|                     |      |
|---------------------|------|
| Labour Total        | 4.00 |
| Parts Total         | 0.00 |
| Miscellaneous Total | 0.00 |

|                     |        |
|---------------------|--------|
| Labour Total        | 8.00   |
| Parts Total         | 891.15 |
| Miscellaneous Total | 0.00   |

|                                                              |                    |                                 |
|--------------------------------------------------------------|--------------------|---------------------------------|
| <b>Description:</b> 250 Hour Service and T/S T/C Temp Sensor | 13669 Hours        | <b>Date Started:</b> 2020-09-14 |
| <b>Equipment:</b> E359 Caterpillar 730 6 x 6 Water Wagon     | GRO#8066/8088      |                                 |
| <b>Serial#:</b> AGF00509                                     | BRADEN<br>GRO 6774 |                                 |

### Segment: 1 Parts and Service

2566453 wrong sensor new one ordered

| Trans | Actual Date | Source  | Details                                                                                 | STATUS | UM | Units  | Price | Total Cost |
|-------|-------------|---------|-----------------------------------------------------------------------------------------|--------|----|--------|-------|------------|
| 2469  | 10/03/20    | AP      | Vendor: 10111 Finning (Canada) a division of Finning International<br>984937364 Line: 1 | EA     |    | -1.000 | 75.47 | -75.47     |
| 1104  | 09/23/20    | EMParts | 1193355 Filter-Cab Air Standard Efficiency                                              | EA     |    | 1.000  | 24.91 | 24.91      |
| 1105  | 09/23/20    | EMParts | 1421339 Filter-Air Primary                                                              | EA     |    | 1.000  | 76.32 | 76.32      |
| 1106  | 09/23/20    | EMParts | 1748145 Filter-Cab Air                                                                  | EA     |    | 1.000  | 16.14 | 16.14      |
| 1107  | 09/23/20    | EMParts | 1R0762 Filter-Fuel Advanced Efficiency                                                  | EA     |    | 1.000  | 29.71 | 29.71      |
| 1108  | 09/23/20    | EMParts | 1R1808 Filter-Oil Advanced Efficiency                                                   | EA     |    | 1.000  | 32.53 | 32.53      |
| 1109  | 09/23/20    | EMParts | 2566453 Sensor Gp-Temp                                                                  | EA     |    | 1.000  | 75.47 | 75.47      |



**GCS Energy Services Ltd.**

## Work Order: 11520

|      |          |         |                                       |    |        |        |        |
|------|----------|---------|---------------------------------------|----|--------|--------|--------|
| 1110 | 09/23/20 | EMParts | 5134490 Filter-Fuel / Water Seperator | EA | 1.000  | 42.06  | 42.06  |
| 1121 | 09/23/20 | EMParts | 5W40 Spectra 5W40                     | I  | 20.000 | 5.22   | 104.31 |
| 1131 | 09/23/20 | EMParts | 1187226 Sensor Gp-Temp                | EA | 1.000  | 269.89 | 269.89 |
| 1809 | 09/21/20 | EMParts | TO4 Spectra Xtreme TO-4 All season    | EA | 10.000 | 7.00   | 70.00  |

|                     |        |
|---------------------|--------|
| Labour Total        | 0.00   |
| Parts Total         | 665.87 |
| Miscellaneous Total | 0.00   |

### Segment: 2 250 Hour Service and T/S Code#826-3

826-3 Torque Converter oil temp voltage above normal.  
Replace fuse for Hazard light and look into brake lights not working.  
Could not determine failure.

| Trans | Actual Date | Source | Details                   | STATUS | UM  | Units | Price | Total Cost |
|-------|-------------|--------|---------------------------|--------|-----|-------|-------|------------|
| 854   | 09/18/20    | PR     | Employee: 2471 Greg Royer |        | HRS | 3.500 |       |            |

|                     |      |
|---------------------|------|
| Labour Total        | 3.50 |
| Parts Total         | 0.00 |
| Miscellaneous Total | 0.00 |

### Segment: 3 Replace Torque Converter Temp Sensor

### Segment: 4 Diagnose hyd pump and valve falts - top up oil - repaired

| Trans | Actual Date | Source | Details                      | STATUS | UM  | Units | Price | Total Cost |
|-------|-------------|--------|------------------------------|--------|-----|-------|-------|------------|
| 1645  | 09/21/20    | PR     | Employee: 1266 Braden Bitzer |        | HRS | 1.000 |       |            |

|                     |      |
|---------------------|------|
| Labour Total        | 1.00 |
| Parts Total         | 0.00 |
| Miscellaneous Total | 0.00 |

### Segment: 5 Repair Hydraulic leak

| Trans | Actual Date | Source | Details                   | STATUS | UM  | Units | Price | Total Cost |
|-------|-------------|--------|---------------------------|--------|-----|-------|-------|------------|
| 747   | 10/13/20    | PR     | Employee: 2471 Greg Royer |        | HRS | 1.500 |       |            |

|                     |      |
|---------------------|------|
| Labour Total        | 1.50 |
| Parts Total         | 0.00 |
| Miscellaneous Total | 0.00 |



# Work Order: 11520

|                     |        |
|---------------------|--------|
| Labour Total        | 6.00   |
| Parts Total         | 665.87 |
| Miscellaneous Total | 0.00   |

|                                                               |                         |                                 |
|---------------------------------------------------------------|-------------------------|---------------------------------|
| <b>Description:</b> Inspections, 250 Hour Service and Repairs | GRO-8954/8504/8505/8506 | <b>Date Started:</b> 2020-12-17 |
| <b>Equipment:</b> E359 Caterpillar 730 6 x 6 Water Wagon      | GRO-8507/8508/8509/8512 |                                 |
|                                                               | GRO-8513/8514/8276/8277 |                                 |
|                                                               | GRO-8374/8395           |                                 |
| <b>Serial#:</b> AGF00509                                      | 13834 Hours             |                                 |
|                                                               | RD-2021-139 Insheet     |                                 |
|                                                               | RD-2021-237 Outsheet    |                                 |
|                                                               | 13828 HRS, GRO 5817     |                                 |

## Segment: 1 Parts

4L X WIPER FLUID  
 1-Hydraulic Cylinder SureLift 1506 146.99ea  
 16 feet - Orange 16g wire  
 16 feet - Red 16g wire  
 16 feet - Black 16g wire

| Trans | Actual Date | Source  | Details                                                                              | STATUS | UM | Units  | Price  | Total Cost |
|-------|-------------|---------|--------------------------------------------------------------------------------------|--------|----|--------|--------|------------|
| 466   | 08/06/21    | AP      | Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S6268116.001 Line: 1                 |        | EA | 1.000  | 12.24  | 12.24      |
| 823   | 07/07/21    | AP      | Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S6233765.001 Line: 1                 |        | LS | 0.000  | 0.00   | 36.30      |
| 1036  | 06/10/21    | AP      | Vendor: 10111 Finning (Canada) a division of Finning International 947523671 Line: 1 |        | EA | 1.000  | 3.65   | 3.65       |
| 1234  | 03/18/21    | AP      | Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S6102792.001 Line: 1                 |        | EA | 5.000  | 72.48  | 362.40     |
| 1235  | 03/22/21    | AP      | Vendor: 11081 Polar Mobility Research Ltd 0000357575 Line: 1                         |        | LS | 0.000  | 0.00   | 136.35     |
| 1236  | 03/24/21    | AP      | Vendor: 32797 P.S.I. Fluid Power Ltd 3147858 Line: 1                                 |        | LS | 0.000  | 0.00   | 249.81     |
| 1316  | 03/22/21    | AP      | Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S6105697.001 Line: 1                 |        | LS | 0.000  | 0.00   | 12.72      |
| 1317  | 03/25/21    | AP      | Vendor: 10132 Gregg Distributors LP 059-354768 Line: 2                               |        | EA | 2.000  | 19.99  | 39.98      |
| 1318  | 03/25/21    | AP      | Vendor: 10132 Gregg Distributors LP 059-354768 Line: 3                               |        | EA | 2.000  | 1.77   | 3.54       |
| 2033  | 06/09/21    | AP      | Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S6201707.001 Line: 1                 |        | LS | 0.000  | 0.00   | 10.20      |
| 2198  | 04/27/21    | AP      | Vendor: 10401 RBC Avion Visa Apr 21_Lance Line: 2                                    |        | LS | 0.000  | 0.00   | 29.39      |
| 2199  | 04/27/21    | AP      | Vendor: 10401 RBC Avion Visa Apr 21_Lance Line: 12                                   |        | LS | 0.000  | 0.00   | 139.99     |
| 2280  | 03/25/21    | AP      | Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S6110727.001 Line: 1                 |        | LS | 0.000  | 0.00   | 29.16      |
| 2516  | 03/31/21    | AP      | Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S6117441.001 Line: 1                 |        | LS | 0.000  | 0.00   | 31.98      |
| 2603  | 03/31/21    | AP      | Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S6117441.001 Line: 2                 |        | LS | 0.000  | 0.00   | -31.98     |
| 2604  | 03/31/21    | AP      | Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S6117441.001 Line: 3                 |        | LS | 0.000  | 0.00   | 31.98      |
| 1     | 07/02/21    | EMParts | 2284947 Seal-O-Ring                                                                  |        | EA | 1.000  | 8.50   | 8.50       |
| 87    | 04/08/21    | EMParts | 1893744 Seal-Antenna                                                                 |        | EA | 1.000  | 2.60   | 2.60       |
| 88    | 04/08/21    | EMParts | 8E1118 Antenna                                                                       |        | EA | 1.000  | 36.98  | 36.98      |
| 95    | 06/09/21    | EMParts | 8C3089 Seal-Face                                                                     |        | EA | 1.000  | 21.93  | 21.93      |
| 116   | 08/06/21    | EMParts | 1187226 Sensor Gp-Temp                                                               |        | EA | 1.000  | 269.89 | 269.89     |
| 364   | 07/19/21    | EMParts | 1482751 Tube Assembly                                                                |        | EA | 1.000  | 161.55 | 161.55     |
| 365   | 07/19/21    | EMParts | 1482752 Tube Assembly                                                                |        | EA | 1.000  | 146.40 | 146.40     |
| 410   | 08/12/21    | EMParts | 1P3703 Seal-Square-Ring-38.66mm OD                                                   |        | EA | 1.000  | 3.90   | 3.90       |
| 411   | 08/12/21    | EMParts | 1P3708 Seal-O-Ring-64.2mm OD                                                         |        | EA | 2.000  | 6.67   | 13.34      |
| 412   | 08/12/21    | EMParts | 4J0520 Seal-O-Ring Flange -16                                                        |        | EA | 2.000  | 4.05   | 8.10       |
| 413   | 08/12/21    | EMParts | 4J0527 Seal-O-Ring                                                                   |        | EA | 2.000  | 2.25   | 4.50       |
| 414   | 08/12/21    | EMParts | 4J5477 Seal-O-Ring                                                                   |        | EA | 4.000  | 1.52   | 6.08       |
| 415   | 08/12/21    | EMParts | 5W40 Spectra 5W40                                                                    |        | I  | 37.000 | 5.22   | 193.10     |



## Work Order: 11775

|      |          |         |                                          |    |        |        |        |
|------|----------|---------|------------------------------------------|----|--------|--------|--------|
| 416  | 08/12/21 | EMParts | 60/40 Rad-Cool Antifreeze                | EA | 27.000 | 5.74   | 155.09 |
| 417  | 08/12/21 | EMParts | 6V8397 Seal-O-Ring Face -6               | EA | 3.000  | 1.62   | 4.86   |
| 418  | 08/12/21 | EMParts | 6V8398 Seal-O-Ring Face -8               | EA | 6.000  | 1.69   | 10.14  |
| 419  | 08/12/21 | EMParts | 6V9746 Seal-O-Ring Face -12              | EA | 7.000  | 1.89   | 13.23  |
| 420  | 08/12/21 | EMParts | 75W90 Certop SN 75W90 Gear Lube          | EA | 48.000 | 9.48   | 454.99 |
| 421  | 08/12/21 | EMParts | Dyed Diesel Dyed Diesel                  | EA | 87.065 | 0.98   | 85.75  |
| 422  | 08/12/21 | EMParts | TO4 Spectra Xtreme TO-4 All season       | EA | 12.500 | 5.48   | 68.49  |
| 423  | 08/12/21 | EMParts | Zink Free Multoil 5w20 Zink-Free Hydraul | EA | 9.000  | 5.87   | 52.82  |
| 424  | 08/12/21 | EMParts | 7M8485 Seal-O-Ring                       | EA | 4.000  | 2.80   | 11.20  |
| 637  | 03/15/21 | EMParts | 1193355 Filter-Cab Air Standard Effici   | EA | 1.000  | 18.45  | 18.45  |
| 638  | 03/15/21 | EMParts | 1421339 Filter-Air Primary               | EA | 1.000  | 72.23  | 72.23  |
| 639  | 03/15/21 | EMParts | 1748145 Filter-Cab Air                   | EA | 1.000  | 16.14  | 16.14  |
| 640  | 03/15/21 | EMParts | 1R0762 Filter-Fuel Advanced Efficiency   | EA | 1.000  | 29.71  | 29.71  |
| 641  | 03/15/21 | EMParts | 1R1808 Filter-Oil Advanced Efficiency    | EA | 1.000  | 32.29  | 32.29  |
| 642  | 03/15/21 | EMParts | 5134490 Filter-Fuel / Water Separator    | EA | 1.000  | 42.06  | 42.06  |
| 686  | 05/19/21 | EMParts | 3T3434 Plug-Rubber Ball                  | EA | 6.000  | 3.32   | 19.92  |
| 687  | 05/19/21 | EMParts | 9Y6089 Gasket-Starter                    | EA | 1.000  | 8.29   | 8.29   |
| 688  | 05/19/21 | EMParts | 9Y6089 Gasket-Starter                    | EA | 1.000  | 8.29   | 8.29   |
| 879  | 05/26/21 | EMParts | 1013125 Gasket-Intake                    | EA | 1.000  | 11.06  | 11.06  |
| 880  | 05/26/21 | EMParts | 1352654 Seal-O-Ring                      | EA | 1.000  | 20.83  | 20.83  |
| 881  | 05/26/21 | EMParts | 1H6227 Seal-O-Ring                       | EA | 1.000  | 8.62   | 8.62   |
| 882  | 05/26/21 | EMParts | 2190606 Seal-Lip                         | EA | 1.000  | 189.52 | 189.52 |
| 883  | 05/26/21 | EMParts | 5332152 Seal-GP-CSHA                     | EA | 1.000  | 121.09 | 121.09 |
| 884  | 05/26/21 | EMParts | 5D9344 Seal                              | EA | 1.000  | 26.94  | 26.94  |
| 885  | 05/26/21 | EMParts | 7C1583 Gasket                            | EA | 1.000  | 12.87  | 12.87  |
| 886  | 05/26/21 | EMParts | 9X7518 Seal-Coupling                     | EA | 4.000  | 15.65  | 62.60  |
| 967  | 03/23/21 | EMParts | 1038133 Receptacle Kit-Injector Harnes   | EA | 1.000  | 68.30  | 68.30  |
| 968  | 03/23/21 | EMParts | 1095308 Gasket-Oil Pan                   | EA | 1.000  | 315.39 | 315.39 |
| 969  | 03/23/21 | EMParts | 2203373 Sleeve-Crank Seal                | EA | 1.000  | 49.39  | 49.39  |
| 970  | 03/23/21 | EMParts | 2264755 Seal-Front Crankshaft            | EA | 1.000  | 121.32 | 121.32 |
| 971  | 03/23/21 | EMParts | 3E6770 Seal-O-Ring                       | EA | 1.000  | 40.15  | 40.15  |
| 972  | 03/23/21 | EMParts | 5746249 Gasket-Crankcase Breather        | EA | 1.000  | 8.91   | 8.91   |
| 973  | 03/23/21 | EMParts | 5K9090 Seal-O-Ring                       | EA | 2.000  | 2.09   | 4.18   |
| 974  | 03/23/21 | EMParts | 6U9992 Seal                              | EA | 1.000  | 29.59  | 29.59  |
| 975  | 03/23/21 | EMParts | 6U9994 Seal                              | EA | 1.000  | 34.16  | 34.16  |
| 976  | 03/23/21 | EMParts | 6V3908 Seal-O-Ring                       | EA | 2.000  | 41.68  | 83.36  |
| 977  | 03/23/21 | EMParts | 7C8296 Isolator-Oil Pan                  | EA | 14.000 | 10.21  | 142.94 |
| 978  | 03/23/21 | EMParts | 7M8485 Seal-O-Ring                       | EA | 1.000  | 2.97   | 2.97   |
| 979  | 03/23/21 | EMParts | 9Y4357 Breather-Crankcase                | EA | 1.000  | 70.21  | 70.21  |
| 980  | 03/23/21 | EMParts | 1234003 Seal-Lip                         | EA | 1.000  | 52.54  | 52.54  |
| 981  | 03/23/21 | EMParts | 1757904 Seal-O-Ring                      | EA | 1.000  | 11.39  | 11.39  |
| 1014 | 03/24/21 | EMParts | 2033940 Seal-O-Ring                      | EA | 1.000  | 2.40   | 2.40   |
| 1015 | 03/24/21 | EMParts | 8L2786 Seal-O-Ring                       | EA | 1.000  | 8.41   | 8.41   |
| 1135 | 12/16/20 | EMParts | 5W40 Spectra 5W40                        | I  | 8.000  | 5.34   | 42.72  |
| 1214 | 03/25/21 | EMParts | 2304171 Pulley-Idler(8-Groove)           | EA | 1.000  | 275.10 | 275.10 |
| 1215 | 03/25/21 | EMParts | 2A1162 Gasket                            | EA | 1.000  | 1.46   | 1.46   |
| 1216 | 03/25/21 | EMParts | 5P5678 Seal-Bulk By the Meter            | EA | 3.000  | 27.53  | 82.59  |
| 1223 | 03/25/21 | EMParts | 2021839 Clamp-V Band                     | EA | 1.000  | 104.30 | 104.30 |
| 1224 | 03/25/21 | EMParts | 7X2497 Handle-Door                       | EA | 1.000  | 10.69  | 10.69  |
| 1364 | 03/30/21 | EMParts | 2287088 Seal-O-Ring                      | EA | 3.000  | 6.86   | 20.58  |
| 1365 | 03/30/21 | EMParts | 8U6013 Seal-O-Ring                       | EA | 4.000  | 6.18   | 24.72  |
| 1502 | 03/31/21 | EMParts | 6E4004 Seal-Shaft                        | EA | 1.000  | 46.61  | 46.61  |
| 1503 | 03/31/21 | EMParts | 1757904 Seal-O-Ring                      | EA | 1.000  | 11.87  | 11.87  |



## Work Order: 11775

|                     |          |
|---------------------|----------|
| Labour Total        | 0.00     |
| Parts Total         | 5,198.31 |
| Miscellaneous Total | 0.00     |

### Segment: 2 Inspections

| Trans | Actual Date | Source | Details                       | STATUS | UM  | Units | Price | Total Cost |
|-------|-------------|--------|-------------------------------|--------|-----|-------|-------|------------|
| 52    | 07/06/21    | PR     | Employee: 2395 Nickolas Schou |        | HRS | 1.500 |       |            |
| 112   | 03/04/21    | PR     | Employee: 2471 Greg Royer     |        | HRS | 3.500 |       |            |
| 179   | 08/04/21    | PR     | Employee: 2471 Greg Royer     |        | HRS | 2.000 |       |            |

|                     |      |
|---------------------|------|
| Labour Total        | 7.00 |
| Parts Total         | 0.00 |
| Miscellaneous Total | 0.00 |

### Segment: 3 Wash and Clean Cab

| Trans | Actual Date | Source | Details                        | STATUS | UM  | Units | Price | Total Cost |
|-------|-------------|--------|--------------------------------|--------|-----|-------|-------|------------|
| 57    | 08/03/21    | PR     | Employee: 2623 Brenton Woolman |        | HRS | 6.000 |       |            |
| 180   | 08/04/21    | PR     | Employee: 2623 Brenton Woolman |        | HRS | 2.000 |       |            |
| 799   | 04/19/21    | PR     | Employee: 2623 Brenton Woolman |        | HRS | 4.500 |       |            |
| 800   | 04/20/21    | PR     | Employee: 2623 Brenton Woolman |        | HRS | 7.500 |       |            |
| 802   | 04/21/21    | PR     | Employee: 2623 Brenton Woolman |        | HRS | 0.500 |       |            |

|                     |       |
|---------------------|-------|
| Labour Total        | 20.50 |
| Parts Total         | 0.00  |
| Miscellaneous Total | 0.00  |

### Segment: 4 checkover and top up fluids before hauling to RD

| Trans | Actual Date | Source | Details                      | STATUS | UM  | Units | Price | Total Cost |
|-------|-------------|--------|------------------------------|--------|-----|-------|-------|------------|
| 1444  | 12/16/20    | PR     | Employee: 1266 Braden Bitzer |        | HRS | 1.000 |       |            |

|                     |      |
|---------------------|------|
| Labour Total        | 1.00 |
| Parts Total         | 0.00 |
| Miscellaneous Total | 0.00 |

### Segment: 5 250 Hour Service

| Trans | Actual Date | Source | Details                       | STATUS | UM  | Units | Price | Total Cost |
|-------|-------------|--------|-------------------------------|--------|-----|-------|-------|------------|
| 263   | 04/05/21    | PR     | Employee: 2611 Matthew Walter |        | HRS | 1.000 |       |            |
| 265   | 04/07/21    | PR     | Employee: 2611 Matthew Walter |        | HRS | 1.000 |       |            |



**GCS Energy Services Ltd.**

**Work Order: 11775**

|      |          |    |                               |     |       |
|------|----------|----|-------------------------------|-----|-------|
| 825  | 05/17/21 | PR | Employee: 2611 Matthew Walter | HRS | 7.500 |
| 826  | 05/18/21 | PR | Employee: 2611 Matthew Walter | HRS | 7.500 |
| 827  | 05/19/21 | PR | Employee: 2611 Matthew Walter | HRS | 7.500 |
| 828  | 05/20/21 | PR | Employee: 2611 Matthew Walter | HRS | 7.500 |
| 1122 | 05/25/21 | PR | Employee: 2611 Matthew Walter | HRS | 2.000 |
| 1439 | 03/22/21 | PR | Employee: 2611 Matthew Walter | HRS | 1.000 |
| 1448 | 03/26/21 | PR | Employee: 2611 Matthew Walter | HRS | 1.000 |

|                     |       |
|---------------------|-------|
| Labour Total        | 36.00 |
| Parts Total         | 0.00  |
| Miscellaneous Total | 0.00  |

**Segment: 6 T/S and Repair Leaks**

*L/F Tire Low check for leak.  
 Upper water pump hose clamp leaking.  
 Orbital steering valve hoses all seeping.  
 Oil Leaking down belly pan, remove and inspect.  
 Mid engine valve cover leaking through electrical connector.  
 A/C line is seeping/leaking wet?  
 Oil Line to oil filter is leaking off fitting closest to engine.  
 Oil Pan wet on R/S? Sorce?  
 Engine bay and everything black. Exhaust leak?  
 Cab tilt cylinder seeping.  
 Cracked and weathered hoses wrapped up at articulation.  
 Hydraulic valve above R/H steering Cylinder leaking.  
 Hoses to water tank control weathered and cracked.  
 Water pump hydraulic motor is wet/leaking clean and verify.  
 Water valve on top of tank is leaking(Covered in oil)*

| Trans | Actual Date | Source | Details                       | STATUS | UM  | Units | Price | Total Cost |
|-------|-------------|--------|-------------------------------|--------|-----|-------|-------|------------|
| 56    | 04/01/21    | PR     | Employee: 2611 Matthew Walter |        | HRS | 3.000 |       |            |
| 214   | 06/07/21    | PR     | Employee: 2611 Matthew Walter |        | HRS | 4.000 |       |            |
| 215   | 06/08/21    | PR     | Employee: 2611 Matthew Walter |        | HRS | 9.500 |       |            |
| 216   | 06/09/21    | PR     | Employee: 2611 Matthew Walter |        | HRS | 7.000 |       |            |
| 257   | 06/10/21    | PR     | Employee: 2611 Matthew Walter |        | HRS | 9.500 |       |            |
| 264   | 04/05/21    | PR     | Employee: 2611 Matthew Walter |        | HRS | 6.000 |       |            |
| 266   | 04/07/21    | PR     | Employee: 2611 Matthew Walter |        | HRS | 3.500 |       |            |
| 269   | 04/08/21    | PR     | Employee: 2611 Matthew Walter |        | HRS | 1.000 |       |            |
| 614   | 05/13/21    | PR     | Employee: 2611 Matthew Walter |        | HRS | 3.500 |       |            |
| 615   | 05/14/21    | PR     | Employee: 2611 Matthew Walter |        | HRS | 2.500 |       |            |
| 803   | 04/22/21    | PR     | Employee: 2611 Matthew Walter |        | HRS | 7.000 |       |            |
| 937   | 06/14/21    | PR     | Employee: 2611 Matthew Walter |        | HRS | 2.500 |       |            |
| 1061  | 06/24/21    | PR     | Employee: 2611 Matthew Walter |        | HRS | 7.500 |       |            |
| 1094  | 03/17/21    | PR     | Employee: 2611 Matthew Walter |        | HRS | 1.500 |       |            |
| 1095  | 03/18/21    | PR     | Employee: 2611 Matthew Walter |        | HRS | 9.500 |       |            |
| 1096  | 03/19/21    | PR     | Employee: 2611 Matthew Walter |        | HRS | 5.500 |       |            |
| 1440  | 03/22/21    | PR     | Employee: 2611 Matthew Walter |        | HRS | 6.000 |       |            |
| 1442  | 03/23/21    | PR     | Employee: 2611 Matthew Walter |        | HRS | 5.000 |       |            |
| 1444  | 03/24/21    | PR     | Employee: 2611 Matthew Walter |        | HRS | 1.000 |       |            |
| 1447  | 03/25/21    | PR     | Employee: 2611 Matthew Walter |        | HRS | 6.500 |       |            |



**GCS Energy Services Ltd.**

**Work Order: 11775**

|      |          |    |                               |     |       |
|------|----------|----|-------------------------------|-----|-------|
| 1449 | 03/26/21 | PR | Employee: 2611 Matthew Walter | HRS | 6.000 |
| 1826 | 04/23/21 | PR | Employee: 2611 Matthew Walter | HRS | 1.500 |
| 2397 | 03/29/21 | PR | Employee: 2611 Matthew Walter | HRS | 4.000 |
| 2398 | 03/30/21 | PR | Employee: 2611 Matthew Walter | HRS | 3.500 |
| 2399 | 03/31/21 | PR | Employee: 2611 Matthew Walter | HRS | 7.000 |

|                     |        |
|---------------------|--------|
| Labour Total        | 123.50 |
| Parts Total         | 0.00   |
| Miscellaneous Total | 0.00   |

**Segment: 7 Repair Panels, doors, steps, Struts and Radios**

*Inner door handle inside of door.*  
*Radio missing knobs and work intermittently.*  
*2Way mike bracket bent up.*  
*Cab door tough to open.*  
*Cab access step panel in rough shape.*  
*body panels and bumpers in rough shape.*  
*Check cab over in shop.*  
*L/F Strut bottom mount has a circle bushing sticking out.*

| Trans | Actual Date | Source | Details                       | STATUS | UM  | Units | Price | Total Cost |
|-------|-------------|--------|-------------------------------|--------|-----|-------|-------|------------|
| 57    | 04/01/21    | PR     | Employee: 2611 Matthew Walter |        | HRS | 4.000 |       |            |
| 267   | 04/07/21    | PR     | Employee: 2611 Matthew Walter |        | HRS | 1.500 |       |            |
| 270   | 04/08/21    | PR     | Employee: 2611 Matthew Walter |        | HRS | 2.000 |       |            |
| 418   | 04/14/21    | PR     | Employee: 2611 Matthew Walter |        | HRS | 4.000 |       |            |

|                     |       |
|---------------------|-------|
| Labour Total        | 11.50 |
| Parts Total         | 0.00  |
| Miscellaneous Total | 0.00  |

**Segment: 8 T/S and Repair Electrical and lights**

*R/R Flasher and light out and beacon doesn't work*  
*Front pod light won't turn on.*

| Trans | Actual Date | Source | Details                       | STATUS | UM  | Units | Price | Total Cost |
|-------|-------------|--------|-------------------------------|--------|-----|-------|-------|------------|
| 181   | 08/04/21    | PR     | Employee: 2611 Matthew Walter |        | HRS | 2.500 |       |            |
| 182   | 08/05/21    | PR     | Employee: 2611 Matthew Walter |        | HRS | 5.000 |       |            |
| 183   | 08/06/21    | PR     | Employee: 2611 Matthew Walter |        | HRS | 3.000 |       |            |
| 1097  | 03/19/21    | PR     | Employee: 2611 Matthew Walter |        | HRS | 3.000 |       |            |
| 1445  | 03/24/21    | PR     | Employee: 2611 Matthew Walter |        | HRS | 2.500 |       |            |

|                     |       |
|---------------------|-------|
| Labour Total        | 16.00 |
| Parts Total         | 0.00  |
| Miscellaneous Total | 0.00  |

**Segment: 9 T/S and Repair Transmission hard shifting**





**Work Order: 11775**

| Trans | Actual Date | Source | Details                       | STATUS | UM  | Units | Price | Total Cost |
|-------|-------------|--------|-------------------------------|--------|-----|-------|-------|------------|
| 268   | 04/07/21    | PR     | Employee: 2611 Matthew Walter |        | HRS | 2.500 |       |            |
| 271   | 04/08/21    | PR     | Employee: 2611 Matthew Walter |        | HRS | 3.500 |       |            |
| 1441  | 03/22/21    | PR     | Employee: 2611 Matthew Walter |        | HRS | 2.500 |       |            |
| 1443  | 03/23/21    | PR     | Employee: 2611 Matthew Walter |        | HRS | 4.500 |       |            |
| 1446  | 03/24/21    | PR     | Employee: 2611 Matthew Walter |        | HRS | 6.000 |       |            |

|                     |       |
|---------------------|-------|
| Labour Total        | 19.00 |
| Parts Total         | 0.00  |
| Miscellaneous Total | 0.00  |

**Segment: 10 Fill and Test water system**

| Trans | Actual Date | Source | Details                       | STATUS | UM  | Units | Price | Total Cost |
|-------|-------------|--------|-------------------------------|--------|-----|-------|-------|------------|
| 801   | 04/21/21    | PR     | Employee: 2611 Matthew Walter |        | HRS | 2.500 |       |            |
| 936   | 06/14/21    | PR     | Employee: 2611 Matthew Walter |        | HRS | 6.000 |       |            |
| 2089  | 06/30/21    | PR     | Employee: 2611 Matthew Walter |        | HRS | 1.000 |       |            |

|                     |      |
|---------------------|------|
| Labour Total        | 9.50 |
| Parts Total         | 0.00 |
| Miscellaneous Total | 0.00 |

**Segment: 11 Remove coolant line off reservoir**

| Trans | Actual Date | Source | Details                       | STATUS | UM  | Units | Price | Total Cost |
|-------|-------------|--------|-------------------------------|--------|-----|-------|-------|------------|
| 53    | 07/07/21    | PR     | Employee: 2395 Nickolas Schou |        | HRS | 4.000 |       |            |
| 155   | 07/08/21    | PR     | Employee: 2395 Nickolas Schou |        | HRS | 3.500 |       |            |

|                     |      |
|---------------------|------|
| Labour Total        | 7.50 |
| Parts Total         | 0.00 |
| Miscellaneous Total | 0.00 |

|                     |          |
|---------------------|----------|
| Labour Total        | 251.50   |
| Parts Total         | 5,198.31 |
| Miscellaneous Total | 0.00     |

|                                                          |          |                                 |
|----------------------------------------------------------|----------|---------------------------------|
| <b>Description:</b> WASH & REPAIR FLAT TIRE              | GRO 9955 | <b>Date Started:</b> 2022-04-26 |
| <b>Equipment:</b> E359 Caterpillar 730 6 x 6 Water Wagon |          |                                 |
| <b>Serial#:</b> AGF00509                                 |          |                                 |

**Segment: 1 parts & service**



## Work Order: 13039

| Trans | Actual Date | Source | Details                                                       | STATUS | UM | Units | Price | Total Cost |
|-------|-------------|--------|---------------------------------------------------------------|--------|----|-------|-------|------------|
| 2050  | 04/28/22    | AP     | Vendor: 32459 Fountain Tire (004C00013647) 080I073537 Line: 1 |        | LS | 0.000 | 0.00  | 670.62     |

|                     |        |
|---------------------|--------|
| Labour Total        | 0.00   |
| Parts Total         | 670.62 |
| Miscellaneous Total | 0.00   |

### Segment: 2 Fountain Tire - Repair flat tire (LF)

| Trans | Actual Date | Source | Details                       | STATUS | UM  | Units | Price | Total Cost |
|-------|-------------|--------|-------------------------------|--------|-----|-------|-------|------------|
| 1749  | 04/26/22    | PR     | Employee: 2024 Travis Schmidt |        | HRS | 0.500 |       |            |

|                     |      |
|---------------------|------|
| Labour Total        | 0.50 |
| Parts Total         | 0.00 |
| Miscellaneous Total | 0.00 |

### Segment: 3 WASH

| Trans | Actual Date | Source | Details                    | STATUS | UM  | Units | Price | Total Cost |
|-------|-------------|--------|----------------------------|--------|-----|-------|-------|------------|
| 1750  | 04/26/22    | PR     | Employee: 2392 Carmen Beck |        | HRS | 2.000 |       |            |

|                     |      |
|---------------------|------|
| Labour Total        | 2.00 |
| Parts Total         | 0.00 |
| Miscellaneous Total | 0.00 |

|                     |        |
|---------------------|--------|
| Labour Total        | 2.50   |
| Parts Total         | 670.62 |
| Miscellaneous Total | 0.00   |

|                                                                                                                          |                                     |                                 |
|--------------------------------------------------------------------------------------------------------------------------|-------------------------------------|---------------------------------|
| <b>Description:</b> Inspect unit<br><b>Equipment:</b> E359 Caterpillar 730 6 x 6 Water Wagon<br><b>Serial#:</b> AGF00509 | Unit at Mildred lake with customer. | <b>Date Started:</b> 2022-08-31 |
|--------------------------------------------------------------------------------------------------------------------------|-------------------------------------|---------------------------------|

### Segment: 1 Parts

### Segment: 2 Inspect unit

| Trans | Actual Date | Source | Details                       | STATUS | UM  | Units | Price | Total Cost |
|-------|-------------|--------|-------------------------------|--------|-----|-------|-------|------------|
| 2222  | 08/24/22    | PR     | Employee: 2395 Nickolas Schou |        | HRS | 1.500 |       |            |



Work Order: 13394

|                            |             |
|----------------------------|-------------|
| Labour Total               | 1.50        |
| Parts Total                | 0.00        |
| Miscellaneous Total        | 0.00        |
| <b>Labour Total</b>        | <b>1.50</b> |
| <b>Parts Total</b>         | <b>0.00</b> |
| <b>Miscellaneous Total</b> | <b>0.00</b> |

**Description:** Inspections and Repairs  
**Equipment:** E359 Caterpillar 730 6 x 6 Water Wagon  
**Serial#:** AGF00509  
**14773 Hours**  
**RD-2022-261 Insheet**  
**Date Started:** 2022-10-13

**Segment: 1 Parts**

(5) Nozzle Cylinder seal kits  
 Contains per kit  
 (1) HU05000750125 Homo U Cup 1/2x3/4 @4.95EA  
 (2) HU087511250125 Homo U Cup 7/8x1 1/8x1/8 @9.60ea  
 (2) ORN702022 O-Ring 2-022 Nitrile 70 @0.80 ea  
 (2) ORT8206SPLIT Backup Ring 8-206 Teflon Split @3.80ea  
 Water Cannon Seals  
 (4) ORN704.0X68.0 O-Ring Metric 4.0x68.0 ID Nitrile 70 @2.40ea  
 (148) SB1/4 Steel Ball @0.28ea

| Trans | Actual Date | Source  | Details                                                                 | STATUS | UM | Units   | Price  | Total Cost |
|-------|-------------|---------|-------------------------------------------------------------------------|--------|----|---------|--------|------------|
| 200   | 06/09/25    | AP      | Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S7862948.001<br>Line: 1 |        | EA | 1.000   | 13.80  | 13.80      |
| 201   | 06/09/25    | AP      | Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S7862948.001<br>Line: 2 |        | EA | 1.000   | 42.84  | 42.84      |
| 202   | 06/09/25    | AP      | Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S7862948.001<br>Line: 3 |        | EA | 1.000   | 5.13   | 5.13       |
| 305   | 05/12/25    | AP      | Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S7824129.001<br>Line: 1 |        | EA | 1.000   | 15.36  | 15.36      |
| 1051  | 06/27/25    | AP      | Vendor: 10401 RBC Avion Visa Jun 25/Lance Line: 26                      |        | EA | 148.000 | 0.28   | 41.44      |
| 1052  | 06/27/25    | AP      | Vendor: 10401 RBC Avion Visa Jun 25/Lance Line: 20                      |        | LS | 0.000   | 0.00   | 85.80      |
| 1053  | 06/27/25    | AP      | Vendor: 10401 RBC Avion Visa Jun 25/Lance Line: 22                      |        | LS | 0.000   | 0.00   | 56.22      |
| 17    | 05/01/25    | EMParts | 1J2176 Seal-O-Ring                                                      |        | EA | 1.000   | 24.36  | 24.36      |
| 18    | 05/01/25    | EMParts | 5H2767 Seal-O-Ring                                                      |        | EA | 1.000   | 4.58   | 4.58       |
| 19    | 05/01/25    | EMParts | 5H3252 Seal-O-Ring                                                      |        | EA | 1.000   | 13.97  | 13.97      |
| 20    | 05/01/25    | EMParts | 6S3018 Seal-O-Ring                                                      |        | EA | 1.000   | 10.40  | 10.40      |
| 24    | 05/02/25    | EMParts | 1890599 Plate-Hinge(3mm Thk)                                            |        | EA | 2.000   | 20.45  | 40.90      |
| 25    | 05/02/25    | EMParts | 1890602 Hinge Assembly                                                  |        | EA | 2.000   | 145.58 | 291.16     |
| 26    | 05/02/25    | EMParts | 2032354 Plate-Hinge(1mm Thk)                                            |        | EA | 2.000   | 16.81  | 33.62      |
| 27    | 05/02/25    | EMParts | 6U5960 Grommet                                                          |        | EA | 3.000   | 5.08   | 15.24      |
| 49    | 05/02/25    | EMParts | 3T6541 Duo-Cone Seal                                                    |        | EA | 1.000   | 216.21 | 216.21     |
| 50    | 05/02/25    | EMParts | 9X3975 Seal-Square-Ring                                                 |        | EA | 1.000   | 8.88   | 8.88       |
| 202   | 05/14/25    | EMParts | 7K6058 Bolt-12 point(1/2"-13x5")                                        |        | EA | 8.000   | 27.71  | 221.68     |
| 219   | 06/13/25    | EMParts | 1492612 Relay-Hood                                                      |        | EA | 1.000   | 309.98 | 309.98     |
| 220   | 06/13/25    | EMParts | 6T3644 Circuit Breaker-20Amp                                            |        | EA | 1.000   | 113.27 | 113.27     |
| 230   | 05/15/25    | EMParts | GA31A Battery-12 Volt Group 31 Top P                                    |        | EA | 2.000   | 129.00 | 258.00     |
| 231   | 05/16/25    | EMParts | 3445588 Seal Kit-Brake Caliper                                          |        | EA | 2.000   | 245.57 | 491.15     |
| 232   | 05/16/25    | EMParts | 8F0212 Seal-O-Ring                                                      |        | EA | 1.000   | 2.18   | 2.18       |
| 233   | 05/16/25    | EMParts | 9C0566 Brake Lining-Outboard                                            |        | EA | 2.000   | 220.68 | 441.35     |
| 234   | 05/16/25    | EMParts | 9C0567 Brake Lining-Inboard                                             |        | EA | 2.000   | 220.68 | 441.35     |
| 237   | 06/17/25    | EMParts | 30080B Switch-Toggle (SPST On-Off 20A                                   |        | EA | 2.000   | 4.40   | 8.80       |



## Work Order: 13536

|                     |          |
|---------------------|----------|
| Labour Total        | 0.00     |
| Parts Total         | 3,207.67 |
| Miscellaneous Total | 0.00     |

### Segment: 2 Inspections

| Trans | Actual Date | Source | Details                        | STATUS | UM  | Units | Price | Total Cost |
|-------|-------------|--------|--------------------------------|--------|-----|-------|-------|------------|
| 535   | 10/14/22    | PR     | Employee: 2915 Scott Scrivener |        | HRS | 3.000 |       |            |

|                     |      |
|---------------------|------|
| Labour Total        | 3.00 |
| Parts Total         | 0.00 |
| Miscellaneous Total | 0.00 |

### Segment: 3 Wash and Clean Cab

| Trans | Actual Date | Source | Details                                 | STATUS | UM  | Units | Price | Total Cost |
|-------|-------------|--------|-----------------------------------------|--------|-----|-------|-------|------------|
| 394   | 06/12/25    | PR     | Employee: 3087 Bogdan (Dan) Korchinskii |        | HRS | 6.500 |       |            |
| 396   | 06/13/25    | PR     | Employee: 3087 Bogdan (Dan) Korchinskii |        | HRS | 6.000 |       |            |

|                     |       |
|---------------------|-------|
| Labour Total        | 12.50 |
| Parts Total         | 0.00  |
| Miscellaneous Total | 0.00  |

### Segment: 4 Repair Lights, fender,

*L/R Tail Light out.  
Both Fenders rusting above step.  
R/H Fender Loose.*

| Trans | Actual Date | Source | Details                     | STATUS | UM  | Units | Price | Total Cost |
|-------|-------------|--------|-----------------------------|--------|-----|-------|-------|------------|
| 164   | 05/08/25    | PR     | Employee: 3108 Zachary Dean |        | HRS | 3.000 |       |            |
| 165   | 05/09/25    | PR     | Employee: 3108 Zachary Dean |        | HRS | 9.500 |       |            |
| 395   | 06/12/25    | PR     | Employee: 3108 Zachary Dean |        | HRS | 0.500 |       |            |
| 398   | 06/17/25    | PR     | Employee: 3108 Zachary Dean |        | HRS | 2.500 |       |            |
| 405   | 05/12/25    | PR     | Employee: 3108 Zachary Dean |        | HRS | 9.500 |       |            |
| 1120  | 04/28/25    | PR     | Employee: 3108 Zachary Dean |        | HRS | 1.000 |       |            |

|                     |       |
|---------------------|-------|
| Labour Total        | 26.00 |
| Parts Total         | 0.00  |
| Miscellaneous Total | 0.00  |

### Segment: 5 Repair Leaks



**Work Order: 13536**

Water Valve on top of tank leaking.  
 Crack in water tank L/H between rear tires.  
 Coolant line bottom of tank leaking.  
 Hydraulic lines cracking at articulation pivot.  
 A/C Hose/fitting coming loose.  
 Engine oil filter hose rubbing on turbo hose.  
 Coolant line over engine fitting leaking.  
 Output on center Differential wet/sweating.  
 Oil Leak L/H under engine(Hydraulic Fluid).

| Trans | Actual Date | Source | Details                     | STATUS | UM  | Units | Price | Total Cost |
|-------|-------------|--------|-----------------------------|--------|-----|-------|-------|------------|
| 141   | 06/06/25    | PR     | Employee: 3108 Zachary Dean |        | HRS | 7.500 |       |            |
| 392   | 06/09/25    | PR     | Employee: 3108 Zachary Dean |        | HRS | 9.500 |       |            |
| 393   | 06/11/25    | PR     | Employee: 3108 Zachary Dean |        | HRS | 1.500 |       |            |
| 397   | 06/16/25    | PR     | Employee: 3108 Zachary Dean |        | HRS | 7.000 |       |            |
| 406   | 05/13/25    | PR     | Employee: 3108 Zachary Dean |        | HRS | 9.500 |       |            |
| 407   | 05/14/25    | PR     | Employee: 3108 Zachary Dean |        | HRS | 9.500 |       |            |
| 408   | 05/15/25    | PR     | Employee: 3108 Zachary Dean |        | HRS | 9.500 |       |            |
| 1121  | 04/29/25    | PR     | Employee: 3108 Zachary Dean |        | HRS | 8.500 |       |            |

|                     |       |
|---------------------|-------|
| Labour Total        | 62.50 |
| Parts Total         | 0.00  |
| Miscellaneous Total | 0.00  |

**Segment: 6 Check out Brakes**

Drive Line Brake heat marks.

| Trans | Actual Date | Source | Details                     | STATUS | UM  | Units | Price | Total Cost |
|-------|-------------|--------|-----------------------------|--------|-----|-------|-------|------------|
| 409   | 05/20/25    | PR     | Employee: 3108 Zachary Dean |        | HRS | 4.500 |       |            |

|                     |      |
|---------------------|------|
| Labour Total        | 4.50 |
| Parts Total         | 0.00 |
| Miscellaneous Total | 0.00 |

|                     |          |
|---------------------|----------|
| Labour Total        | 108.50   |
| Parts Total         | 3,207.67 |
| Miscellaneous Total | 0.00     |

|                                                          |                     |                                 |
|----------------------------------------------------------|---------------------|---------------------------------|
| <b>Description:</b> Rental Return-Emsco                  | 14773 Hours         | <b>Date Started:</b> 2022-10-17 |
| <b>Equipment:</b> E359 Caterpillar 730 6 x 6 Water Wagon | RD-2022-261 Insheet |                                 |
| <b>Serial#:</b> AGF00509                                 |                     |                                 |

**Segment: 1 Parts**

| Trans | Actual Date | Source | Details | STATUS | UM | Units | Price | Total Cost |
|-------|-------------|--------|---------|--------|----|-------|-------|------------|
|-------|-------------|--------|---------|--------|----|-------|-------|------------|



## Work Order: 13540

|     |          |         |                             |    |         |        |        |
|-----|----------|---------|-----------------------------|----|---------|--------|--------|
| 102 | 04/10/23 | EMParts | 9P7121 Fuel Tank Screen     | EA | 1.000   | 53.01  | 53.01  |
| 103 | 04/10/23 | EMParts | OMT Operators Manual        | EA | 1.000   | 150.00 | 150.00 |
| 278 | 10/18/22 | EMParts | 1890599 Plate-Hinge         | EA | 2.000   | 16.99  | 33.98  |
| 279 | 10/18/22 | EMParts | 1890602 Hinge Assembly      | EA | 1.000   | 145.58 | 145.58 |
| 280 | 10/18/22 | EMParts | 1891516 Plate-Hinge         | EA | 1.000   | 156.38 | 156.38 |
| 281 | 10/18/22 | EMParts | 1892910 Gasket-Rubber       | EA | 1.000   | 35.86  | 35.86  |
| 282 | 10/18/22 | EMParts | 2032354 Plate-Hinge         | EA | 1.000   | 12.58  | 12.58  |
| 283 | 10/18/22 | EMParts | 2055149 Screw-Flat Head     | EA | 2.000   | 8.05   | 16.10  |
| 284 | 10/18/22 | EMParts | 2606695 Screw-Flat Head     | EA | 2.000   | 8.46   | 16.92  |
| 285 | 10/18/22 | EMParts | 5C2890 Nut                  | EA | 4.000   | 0.28   | 1.13   |
| 286 | 10/18/22 | EMParts | 9X8256 Washer-6.6x12x2mmThk | EA | 8.000   | 0.28   | 2.24   |
| 287 | 10/18/22 | EMParts | Dyed Diesel Dyed Diesel     | EA | 124.920 | 1.54   | 192.36 |

|                     |        |
|---------------------|--------|
| Labour Total        | 0.00   |
| Parts Total         | 816.14 |
| Miscellaneous Total | 0.00   |

### Segment: 2 Wash and Clean Cab

| Trans | Actual Date | Source | Details                        | STATUS | UM  | Units | Price | Total Cost |
|-------|-------------|--------|--------------------------------|--------|-----|-------|-------|------------|
| 1888  | 10/25/22    | PR     | Employee: 2623 Brenton Woolman |        | HRS | 5.000 |       |            |
| 1889  | 10/26/22    | PR     | Employee: 2623 Brenton Woolman |        | HRS | 9.500 |       |            |
| 1890  | 10/27/22    | PR     | Employee: 2623 Brenton Woolman |        | HRS | 9.000 |       |            |

|                     |       |
|---------------------|-------|
| Labour Total        | 23.50 |
| Parts Total         | 0.00  |
| Miscellaneous Total | 0.00  |

### Segment: 3 Replace Lockout cover, Fuel Screen and Operators Manual

|                     |        |
|---------------------|--------|
| Labour Total        | 23.50  |
| Parts Total         | 816.14 |
| Miscellaneous Total | 0.00   |

|                                                          |                   |                                 |
|----------------------------------------------------------|-------------------|---------------------------------|
| <b>Description:</b> Repairs                              | No hours recorded | <b>Date Started:</b> 2019-08-29 |
| <b>Equipment:</b> E359 Caterpillar 730 6 x 6 Water Wagon | GRO - 6665        |                                 |
| <b>Serial#:</b> AGF00509                                 |                   |                                 |

### Segment: 1 Parts and Service

1 - Hydraulic Pump (no part number given)

### Segment: 2 Service

Diagnose two pump failures, Emsco installed a hydraulic pump instead of a motor.  
The system needed a case drain as it had prior to Emsco working on it and it caused two pumps to blow out seals.  
Installed new pump as a motor and plumbed in a new case drain.



**Work Order: Z10145**

| Trans | Actual Date | Source | Details                      | STATUS | UM  | Units | Price | Total Cost |
|-------|-------------|--------|------------------------------|--------|-----|-------|-------|------------|
| 891   | 01/30/20    | EMTime | Employee: 1266 Braden Bitzer |        | HRS | 7.500 |       |            |

|              |      |
|--------------|------|
| Labour Total | 7.50 |
|--------------|------|

|             |      |
|-------------|------|
| Parts Total | 0.00 |
|-------------|------|

|                     |      |
|---------------------|------|
| Miscellaneous Total | 0.00 |
|---------------------|------|

|                     |             |
|---------------------|-------------|
| <b>Labour Total</b> | <b>7.50</b> |
|---------------------|-------------|

|                    |             |
|--------------------|-------------|
| <b>Parts Total</b> | <b>0.00</b> |
|--------------------|-------------|

|                            |             |
|----------------------------|-------------|
| <b>Miscellaneous Total</b> | <b>0.00</b> |
|----------------------------|-------------|