



Work Order: 12137

EB10-214

Description: Inspections and Repairs	GRO-8304/11766/11763/ 11764/11765/11767/11810	Date Started: 2021-05-13
Equipment: E453 Bomag BW213PDH 84" Pad Foot Packer	2779 Hours RD-2021-207 Insheet RD-2021-268 Outsheet	
Serial#: 901582571153		

Segment: 1 Parts

2 - relays

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
254	09/10/21	AP	Vendor: 10132 Gregg Distributors LP 059-392990 Line: 1	EA		1.000	9.85	9.85
474	09/14/21	AP	Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S6308643.001 Line: 2	LS		0.000	0.00	42.80
475	09/15/21	AP	Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S6309103.001 Line: 2	LS		0.000	0.00	78.22
476	09/13/21	AP	Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S6306737.001 Line: 1	LS		0.000	0.00	14.82
479	09/16/21	AP	Vendor: 10132 Gregg Distributors LP 059-394304 Line: 1	LS		0.000	0.00	5.07
655	09/20/21	AP	Vendor: 21172 SMS Equipment Inc. PSI/71153399 Line: 1	EA		8.000	70.71	565.68
940	09/22/21	AP	Vendor: 21172 SMS Equipment Inc. PSI/71154331 Line: 5	EA		1.000	80.00	80.00
941	09/14/21	AP	Vendor: 10132 Gregg Distributors LP 059-393641 Line: 1	EA		2.000	0.50	1.00
1976	10/04/21	AP	Vendor: 21172 SMS Equipment Inc. PSI/71157997 Line: 1	EA		-1.000	245.32	-245.32
1977	10/04/21	AP	Vendor: 21172 SMS Equipment Inc. PSI/71157997 Line: 2	EA		-1.000	41.11	-41.11
2237	09/30/21	AP	Vendor: 21172 SMS Equipment Inc. PSI/71156953 Line: 1	EA		1.000	131.32	131.32
25	10/06/21	EMParts	05818299 Seal Retainer	EA		-1.000	187.77	-187.77
183	09/09/21	EMParts	83211512 Fuel/ Water Separator	EA		1.000	119.90	119.90
184	09/09/21	EMParts	83211513 Filter-Fuel	EA		1.000	51.70	51.70
185	09/09/21	EMParts	938187 Filter-Oil	EA		1.000	37.37	37.37
186	09/09/21	EMParts	AT300487 Filter-Air Primary	EA		1.000	29.06	29.06
197	09/09/21	EMParts	0148890 V-Belt(A/C)	EA		1.000	22.12	22.12
198	09/09/21	EMParts	05011420 Belt-Serpentine	EA		1.000	228.69	228.69
199	09/09/21	EMParts	05571242 Mirror-Outter	EA		1.000	149.82	149.82
200	09/09/21	EMParts	05571509 Blade-Wiper	EA		1.000	96.46	96.46
201	09/09/21	EMParts	05581171 Strut-Hood	EA		1.000	87.41	87.41
202	09/09/21	EMParts	6754614111 Tensioner-Belt(Cummins)	EA		1.000	191.68	191.68
267	09/13/21	EMParts	05551609 Hose Assembly(114-10 FDIxNFDIN	EA		1.000	113.00	113.00
275	09/14/21	EMParts	05766886 Relay-12v (871-1C-C-R1-U01)	EA		2.000	6.50	13.00
285	11/17/21	EMParts	4J0520 Seal-O-Ring Flange -16	EA		2.000	4.05	8.10
286	11/17/21	EMParts	5W40 Spectra 5W40	I		12.000	6.47	77.63
287	11/17/21	EMParts	60/40 Rad-Cool Antifreeze	EA		20.000	5.60	112.00
288	11/17/21	EMParts	75W90 Certop SN 75W90 Gear Lube	EA		19.500	9.48	184.84
289	11/17/21	EMParts	Oil All Plus Hydraulic Oil 10W30	EA		6.000	17.84	107.06
571	11/18/21	EMParts	Dyed Diesel Dyed Diesel	EA		18.927	1.02	19.40
833	06/23/21	EMParts	Dyed Diesel Dyed Diesel	EA		77.600	0.87	67.89
858	09/23/21	EMParts	05579290 Solenoid Valve (Coolant)	EA		1.000	385.74	385.74
859	09/23/21	EMParts	05817921 Sealing Ring	EA		1.000	245.32	245.32
860	09/23/21	EMParts	05817922 Seal-O-Ring	EA		1.000	41.11	41.11
861	09/23/21	EMParts	05818299 Seal Retainer	EA		1.000	187.77	187.77
1171	09/30/21	EMParts	05762302 Switch-Normally Open (Green)(Z	EA		2.000	17.30	34.60

Labour Total	0.00
Parts Total	3,066.23
Miscellaneous Total	0.00

Segment: 2 Inspections



Work Order: 12137

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
939	06/23/21	PR	Employee: 2471 Greg Royer		HRS	2.000		
1396	09/29/21	PR	Employee: 2395 Nickolas Schou		HRS	1.000		
1397	09/30/21	PR	Employee: 2395 Nickolas Schou		HRS	6.500		
						Labour Total		9.50
						Parts Total		0.00
						Miscellaneous Total		0.00

Segment: 3 Wash and Clean Cab

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1393	09/27/21	PR	Employee: 2623 Brenton Woolman		HRS	4.500		
						Labour Total		4.50
						Parts Total		0.00
						Miscellaneous Total		0.00

Segment: 4 350 Hour Service

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
325	09/13/21	PR	Employee: 2611 Matthew Walter		HRS	1.500		
499	09/15/21	PR	Employee: 2611 Matthew Walter		HRS	2.000		
738	09/16/21	PR	Employee: 2611 Matthew Walter		HRS	3.000		
1394	09/27/21	PR	Employee: 2611 Matthew Walter		HRS	1.000		
						Labour Total		7.50
						Parts Total		0.00
						Miscellaneous Total		0.00

Segment: 5 T/S, Repair A/C and Heater

A/C control dial set screw tightened.
 Heat Dial just spins and no heat coming from vents.
 When A/c is on Hear whistle noise from behind seat.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
496	09/14/21	PR	Employee: 2611 Matthew Walter		HRS	2.500		
500	09/15/21	PR	Employee: 2611 Matthew Walter		HRS	1.500		



Work Order: 12137

Labour Total	4.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 6 T/S and Repair Belts

*A/C Belt old and weather cracking.
Belt Squeals when shut off, appears to be walking off tensioner.*

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
326	09/13/21	PR	Employee: 2611 Matthew Walter		HRS	2.000		

Labour Total	2.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 7 Repair Panels, doors, wipers and seats

*Front wiper and rear wiper need replacing.
Seat Slides and adjuster stiff (Lube)
Hood Latch stiff to open and hood shock weak.
Unit # on L/S Missing.
Hood lock pin broken??
A Lot of corrosion on R/S Rim at tire bead.
Exhaust tip smashed at tip.
R/S Mirror Cracked.
Cup Holder Broken.
R/H arm Rest missing stop screw.
Light switch don't work.*

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
324	09/10/21	PR	Employee: 2611 Matthew Walter		HRS	1.500		
327	09/13/21	PR	Employee: 2611 Matthew Walter		HRS	2.500		
497	09/14/21	PR	Employee: 2611 Matthew Walter		HRS	5.000		
501	09/15/21	PR	Employee: 2611 Matthew Walter		HRS	0.500		

Labour Total	9.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 8 T/S and Repair Leaks

*Weathered hose's on both sides of drum.
Block Heater fitting leaking.
Coolant slightly Low.
Fuel lines on tank weathered and Cracking.
Drum Seal leaking at large flange both sides.
Drum motor leaking R/S
Leaking hose on drive motor.
Leaking hose on valve above drive motor.*



Work Order: 12137

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
328	09/13/21	PR	Employee: 2611 Matthew Walter		HRS	3.000		
498	09/14/21	PR	Employee: 2611 Matthew Walter		HRS	2.000		
502	09/15/21	PR	Employee: 2611 Matthew Walter		HRS	4.500		
739	09/16/21	PR	Employee: 2611 Matthew Walter		HRS	0.500		
1391	09/21/21	PR	Employee: 2611 Matthew Walter		HRS	3.000		
1392	09/22/21	PR	Employee: 2611 Matthew Walter		HRS	1.000		
1395	09/27/21	PR	Employee: 2611 Matthew Walter		HRS	2.000		

Segment: 9 Repair/replace scraper teeth

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
740	09/16/21	PR	Employee: 2611 Matthew Walter		HRS	5.000		
						Labour Total	5.00	
						Parts Total	0.00	
						Miscellaneous Total	0.00	
						Labour Total	58.00	
						Parts Total	3,066.23	
						Miscellaneous Total	0.00	

Description: checkover - R&R batteries 27 HRS, GRO 9371/9373/9503/9504 Date Started: 2022-06-09
Equipment: E453 Bomag BW213PDH 84" Pad Foot
Packer
Serial#: 901582571153

Segment: 1 parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
2145	06/09/22	AP	Vendor: 10064 Comrades Parts & Accessories Ltd. 000-371867 Line: 1 EA			2.000	139.70	279.40
2146	06/09/22	AP	Vendor: 10064 Comrades Parts & Accessories Ltd. 000-371867 Line: 2 EA			2.000	27.00	54.00
2147	06/14/22	AP	Vendor: 10064 Comrades Parts & Accessories Ltd. 000-372027 Line: 1 EA			-2.000	27.00	-54.00
2148	06/21/22	AP	Vendor: 10064 Comrades Parts & Accessories Ltd. 000-372295 Line: 1 EA			1.000	11.26	11.26
476	07/26/22	EMParts	06550011 Cap-Fuel Tank		EA	1.000	57.20	57.20
667	06/16/22	EMParts	WWFluid Window Washer Fluid -35/-40C (208L drums added to tote)		EA	2.000	1.23	2.47
766	06/21/22	EMParts	60/40 Rad-Cool Antifreeze		EA	2.000	6.45	12.89
767	06/21/22	EMParts	5W40 Spectra 5W40		I	1.000	5.34	5.34



Work Order: 13179

Labour Total	0.00
Parts Total	368.56
Miscellaneous Total	0.00

Segment: 2 outsheet checkover

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
437	06/09/22	PR	Employee: 1266 Braden Bitzer		HRS	1.000		
1307	06/16/22	PR	Employee: 1266 Braden Bitzer		HRS	1.000		
1308	06/21/22	PR	Employee: 1266 Braden Bitzer		HRS	1.000		

Labour Total	3.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 R&R batteries

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
438	06/09/22	PR	Employee: 1266 Braden Bitzer		HRS	1.000		
1306	06/14/22	PR	Employee: 1266 Braden Bitzer		HRS	1.000		
1309	06/21/22	PR	Employee: 1266 Braden Bitzer		HRS	1.000		

Labour Total	3.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 4 R&R muffler end pipe - replace with angled tip

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1310	06/21/22	PR	Employee: 1266 Braden Bitzer		HRS	2.000		

Labour Total	2.00
Parts Total	0.00
Miscellaneous Total	0.00

Labour Total	8.00
Parts Total	368.56
Miscellaneous Total	0.00



Work Order: 13411

Description: Repair Leaks	Date Started: 2022-09-06
Equipment: E453 Bomag BW213PDH 84" Pad Foot Packer	
Serial#: 901582571153	

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1109	09/08/22	AP	Vendor: 10416 Hose Headquarters (Red Deer) Ltd. Line: 1	S6702571.001	EA	1.000	130.02	130.02

Labour Total	0.00
Parts Total	130.02
Miscellaneous Total	0.00

Segment: 2 Repair leaks

Replace hyd hose.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
108	09/03/22	PR	Employee: 2915 Scott Scrivener		HRS	1.000		
604	09/09/22	PR	Employee: 2915 Scott Scrivener		HRS	1.500		

Labour Total	2.50
Parts Total	0.00
Miscellaneous Total	0.00
Labour Total	2.50
Parts Total	130.02
Miscellaneous Total	0.00

Description: Diagnose No Heat	Unit at Emerson Site.	Date Started: 2022-10-26
Equipment: E453 Bomag BW213PDH 84" Pad Foot Packer		
Serial#: 901582571153		

Segment: 1 Parts

Segment: 2 Diagnose No Heat. Heat Control Knob Not Working.

Diag no heat. Heat control knob not working. Try to repair. Issue is internal.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1898	10/18/22	PR	Employee: 2915 Scott Scrivener		HRS	1.000		



Work Order: 13588

Labour Total	1.00
Parts Total	0.00
Miscellaneous Total	0.00
Labour Total	1.00
Parts Total	0.00
Miscellaneous Total	0.00

Description: Inspections, 3000 Hour Service and Repairs Equipment: E453 Bomag BW213PDH 84" Pad Foot Packer Serial#: 901582571153	2961 Hours RD-2023-240 Insheet Unit went to Hardisty for Wash and Outsheet.	Date Started: 2023-09-15
---	---	---------------------------------

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1061	11/14/23	AP	Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S7194246.001 Line: 1		EA	10.000	1.83	18.30
1062	11/14/23	AP	Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S7194246.001 Line: 2		EA	4.000	5.22	20.88
1374	10/12/23	AP	Vendor: 32484 Nortrux Inc. 425383 Line: 1		EA	1.000	159.21	159.21
1375	10/12/23	AP	Vendor: 32484 Nortrux Inc. 425383 Line: 2		EA	1.000	11.64	11.64
1376	10/12/23	AP	Vendor: 32484 Nortrux Inc. 425383 Line: 3		LS	0.000	0.00	20.00
2499	11/27/23	AP	Vendor: 10401 RBC Avion Visa Nov 23_L Dahl Line: 12		LS	0.000	0.00	5,244.90
2654	10/12/23	AP	Vendor: 32484 Nortrux Inc. 425383 Line: 4		EA	-1.000	159.21	-159.21
2655	10/12/23	AP	Vendor: 32484 Nortrux Inc. 425383 Line: 5		EA	-1.000	11.64	-11.64
2656	10/12/23	AP	Vendor: 32484 Nortrux Inc. 425383 Line: 6		EA	1.000	159.21	159.21
2657	10/12/23	AP	Vendor: 32484 Nortrux Inc. 425383 Line: 7		EA	1.000	11.64	11.64
72	10/04/23	EMParts	83211512 Fuel/ Water Seperator		EA	1.000	263.78	263.78
73	10/04/23	EMParts	83211513 Filter-Fuel		EA	1.000	120.63	120.63
74	10/04/23	EMParts	938187 Filter-Oil		EA	1.000	99.65	99.65
75	10/04/23	EMParts	AT300487 Filter-Air Primary		EA	1.000	105.51	105.51
76	10/04/23	EMParts	AT314583 Filter-Air Secondary		EA	1.000	48.99	48.99
77	10/04/23	EMParts	OMT Operators Manual		EA	1.000	150.00	150.00
112	10/10/23	EMParts	06220882 Seal-O-Ring		EA	1.000	5.41	5.41
113	10/10/23	EMParts	07993014 Filter-Hydraulic		EA	1.000	195.95	195.95
339	11/15/23	EMParts	05011275 Hose-Radiator		EA	1.000	284.45	284.45
683	12/14/23	EMParts	05756360 Plug Housing		EA	1.000	12.22	12.22
712	12/14/23	EMParts	5W40 Spectra 5W40		I	0.000	7.70	0.00
713	12/14/23	EMParts	75W90 Certop SN 75W90 Gear Lube		EA	8.000	10.27	82.14
714	12/14/23	EMParts	Zinc Free Multoil 5w20 Zink-Free Hydraul		EA	130.000	7.20	935.92
898	10/23/23	EMParts	8355307 Cup Holder		EA	1.000	7.99	7.99

Labour Total	0.00
Parts Total	7,787.57
Miscellaneous Total	0.00

Segment: 2 Inspections

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
-------	-------------	--------	---------	--------	----	-------	-------	------------



GCS Energy Services Ltd.

Work Order: 14334

594	09/15/23	PR	Employee: 3110 Callum Deditch	HRS	1.500
1461	09/21/23	PR	Employee: 3110 Callum Deditch	HRS	2.500
1462	09/22/23	PR	Employee: 3110 Callum Deditch	HRS	3.000

Labour Total	7.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 Wash and Clean Cab

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1386	12/18/23	PR	Employee: 22 Garrett Nelson		HRS	3.500		

Labour Total	3.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 4 Repair A/C

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
525	12/07/23	PR	Employee: 3110 Callum Deditch		HRS	4.500		
535	10/11/23	PR	Employee: 3110 Callum Deditch		HRS	9.500		

Labour Total	14.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 5 Repair beacon, cup holder, door and OMT

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
531	10/06/23	PR	Employee: 3110 Callum Deditch		HRS	1.500		
533	10/10/23	PR	Employee: 3110 Callum Deditch		HRS	1.000		

Labour Total	2.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 6 Repair Leaks

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
523	12/04/23	PR	Employee: 3110 Callum Deditch		HRS	7.500		
524	12/06/23	PR	Employee: 3110 Callum Deditch		HRS	7.500		



Work Order: 14334

534	10/10/23	PR	Employee: 3110 Callum Deditch	HRS	8.500
536	10/12/23	PR	Employee: 3110 Callum Deditch	HRS	2.000
1323	11/14/23	PR	Employee: 3110 Callum Deditch	HRS	8.000
1324	11/15/23	PR	Employee: 3110 Callum Deditch	HRS	5.000
1546	10/16/23	PR	Employee: 3110 Callum Deditch	HRS	0.500

Labour Total	39.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 7 3000 Hour Service

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
532	10/06/23	PR	Employee: 3110 Callum Deditch		HRS	6.500		

Labour Total	6.50
Parts Total	0.00
Miscellaneous Total	0.00
Labour Total	72.50
Parts Total	7,787.57
Miscellaneous Total	0.00

Description:	Reg Maintenance	GRO11787	Date Started:	2024-07-10
Equipment:	E453 Bomag BW213PDH 84" Pad Foot Packer	2964:hours		
Serial#:	901582571153			

Segment: 1 parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
169	07/11/24	EMParts	58070901 Plate		EA	4.000	6.72	26.88
170	07/11/24	EMParts	58070902 Slipper		EA	2.000	9.74	19.48
171	07/11/24	EMParts	58070919 Bolt-Shoulder		EA	4.000	22.05	88.20
307	07/22/24	EMParts	06281206 Bushing		EA	1.000	7.13	7.13

Labour Total	0.00
Parts Total	141.69
Miscellaneous Total	0.00

Segment: 2 Complete In/Out Inspection

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
607	07/10/24	PR	Employee: 3119 Shawn Dittmer		HRS	2.000		



Work Order: 14950

Labour Total	2.00
Parts Total	0.00
Miscellaneous Total	0.00

Labour Total	2.00
Parts Total	141.69
Miscellaneous Total	0.00

Description: Repair for drivetrain failure	Hours:2974	Date Started: 2024-08-13
Equipment: E453 Bomag BW213PDH 84" Pad Foot Packer	Next Service 3310 GRO#10286	
Serial#: 901582571153		

Segment: 1 Parts

Segment: 2 T/S drivetrain failure

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
413	08/07/24	PR	Employee: 3103 Dallas Wood		HRS	2.000		

Labour Total	2.00
Parts Total	0.00
Miscellaneous Total	0.00

Labour Total	2.00
Parts Total	0.00
Miscellaneous Total	0.00

Description: Inspections, Differential locked up and Repairs	2975 Hours	Date Started: 2025-01-21
Equipment: E453 Bomag BW213PDH 84" Pad Foot Packer	RD-2025-137 Insheet RD-2025-138 Outsheet	
Serial#: 901582571153		

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
156	03/17/25	EMParts	1920700802 Plate-Brake Disc Intermediate		EA	1.000	338.57	338.57
182	04/15/25	EMParts	75W90 Certop SN 75W90 Gear Lube		EA	17.000	10.27	174.55
183	04/15/25	EMParts	Dyed Diesel Dyed Diesel		EA	70.030	1.42	99.36
184	04/15/25	EMParts	Zinc Free Spectra MV 5W20 Zinc-Free Hydr		EA	7.000	26.05	182.35
196	02/19/25	EMParts	05585770 Breather		EA	1.000	10.92	10.92
204	02/20/25	EMParts	001051487 Seal-O-Ring		EA	1.000	2.23	2.23
205	02/20/25	EMParts	005101457 Bearing-Tapered Roller		EA	1.000	234.88	234.88
206	02/20/25	EMParts	011131227 Washer-Lock		EA	4.000	5.31	21.24



Work Order: 15211

207	02/20/25	EMParts	1760702901 Seal-O-Ring	EA	4.000	6.41	25.64
208	02/20/25	EMParts	7020100307 Breather	EA	1.000	11.49	11.49
441	02/27/25	EMParts	001030621 Seal-Lip Type	EA	1.000	50.84	50.84
482	03/26/25	EMParts	AT226281 Horn	EA	1.000	128.90	128.90
511	03/28/25	EMParts	05571242 Mirror-Outter	EA	1.000	256.79	256.79

Labour Total	0.00
Parts Total	1,537.76
Miscellaneous Total	0.00

Segment: 2 Inspections

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
583	04/14/25	PR	Employee: 3108 Zachary Dean		HRS	2.500		

Labour Total	2.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 Wash and Clean Cab

Segment: 4 T/S, Repair Differential Issue, Mirror and Horn

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
333	03/03/25	PR	Employee: 3108 Zachary Dean		HRS	8.000		
349	02/12/25	PR	Employee: 3108 Zachary Dean		HRS	8.000		
350	02/13/25	PR	Employee: 3103 Dallas Wood		HRS	3.000		
351	02/13/25	PR	Employee: 3108 Zachary Dean		HRS	7.500		
352	02/14/25	PR	Employee: 3108 Zachary Dean		HRS	4.500		
663	03/25/25	PR	Employee: 3108 Zachary Dean		HRS	9.500		
664	03/26/25	PR	Employee: 3108 Zachary Dean		HRS	4.500		
1021	02/27/25	PR	Employee: 3108 Zachary Dean		HRS	8.000		
1022	02/28/25	PR	Employee: 3108 Zachary Dean		HRS	9.500		

Labour Total	62.50
Parts Total	0.00
Miscellaneous Total	0.00

Labour Total	65.00
Parts Total	1,537.76
Miscellaneous Total	0.00

