



# Work Order: 13417

|                                                           |                                 |
|-----------------------------------------------------------|---------------------------------|
| <b>Description:</b> outsheet checkover                    | <b>Date Started:</b> 2022-09-07 |
| <b>Equipment:</b> E696 2021 Case TR310B Tracked Skidsteer |                                 |
| <b>Serial#:</b> JAFTR310LLM486685                         |                                 |

## Segment: 1 parts

- 4 x 3/8 x 1 bolt
- 4 x 3/8 flat washer
- 4 x 3/8 fender washer
- 4 x 3/8 lock nut

| Trans | Actual Date | Source  | Details                                                         | STATUS | UM | Units | Price | Total Cost |
|-------|-------------|---------|-----------------------------------------------------------------|--------|----|-------|-------|------------|
| 269   | 09/07/22    | EMParts | VB7 F/E Vehicle Bracket                                         |        | EA | 1.000 | 61.25 | 61.25      |
| 270   | 09/07/22    | EMParts | WWFluid Window Washer Fluid -35/-40C (208L drums added to tote) |        | EA | 2.000 | 1.26  | 2.52       |

|                     |       |
|---------------------|-------|
| Labour Total        | 0.00  |
| Parts Total         | 63.77 |
| Miscellaneous Total | 0.00  |

## Segment: 2 outsheet checkover

| Trans | Actual Date | Source | Details                      | STATUS | UM  | Units | Price | Total Cost |
|-------|-------------|--------|------------------------------|--------|-----|-------|-------|------------|
| 739   | 09/07/22    | PR     | Employee: 1266 Braden Bitzer |        | HRS | 1.000 |       |            |

|                     |      |
|---------------------|------|
| Labour Total        | 1.00 |
| Parts Total         | 0.00 |
| Miscellaneous Total | 0.00 |

## Segment: 3 Measure and PAS (install at a later date)

| Trans | Actual Date | Source | Details                      | STATUS | UM  | Units | Price | Total Cost |
|-------|-------------|--------|------------------------------|--------|-----|-------|-------|------------|
| 740   | 09/07/22    | PR     | Employee: 1266 Braden Bitzer |        | HRS | 0.500 |       |            |

|                     |      |
|---------------------|------|
| Labour Total        | 0.50 |
| Parts Total         | 0.00 |
| Miscellaneous Total | 0.00 |

## Segment: 7 wash & bleach

| Trans | Actual Date | Source | Details                     | STATUS | UM  | Units | Price | Total Cost |
|-------|-------------|--------|-----------------------------|--------|-----|-------|-------|------------|
| 741   | 09/07/22    | PR     | Employee: 22 Garrett Nelson |        | HRS | 1.000 |       |            |



## Work Order: 13417

|                            |              |
|----------------------------|--------------|
| Labour Total               | 1.00         |
| Parts Total                | 0.00         |
| Miscellaneous Total        | 0.00         |
| <b>Labour Total</b>        | <b>2.50</b>  |
| <b>Parts Total</b>         | <b>63.77</b> |
| <b>Miscellaneous Total</b> | <b>0.00</b>  |

**Description:** 350 Hour Service and Repair Door latch  
**Equipment:** E696 2021 Case TR310B Tracked Skidsteer  
**Serial#:** JAFTR310LLM486685

**Unit at Emerson Site.**  
**GRO #10755**

**Date Started:** 2022-12-12

### Segment: 1 Parts

| Trans | Actual Date | Source  | Details                                                   | STATUS | UM | Units  | Price | Total Cost |
|-------|-------------|---------|-----------------------------------------------------------|--------|----|--------|-------|------------|
| 364   | 05/04/23    | AP      | Vendor: 33178 Rocky Mountain Equipment LP P90830 Line: 1  |        | EA | 1.000  | 1.71  | 1.71       |
| 365   | 05/04/23    | AP      | Vendor: 33178 Rocky Mountain Equipment LP P90830 Line: 2  |        | EA | 1.000  | 2.25  | 2.25       |
| 366   | 05/04/23    | AP      | Vendor: 33178 Rocky Mountain Equipment LP P90830 Line: 3  |        | EA | 1.000  | 21.24 | 21.24      |
| 367   | 05/04/23    | AP      | Vendor: 33178 Rocky Mountain Equipment LP P90830 Line: 4  |        | EA | 1.000  | 11.68 | 11.68      |
| 368   | 05/04/23    | AP      | Vendor: 33178 Rocky Mountain Equipment LP P90830 Line: 5  |        | EA | 1.000  | 64.88 | 64.88      |
| 369   | 05/04/23    | AP      | Vendor: 33178 Rocky Mountain Equipment LP P90830 Line: 6  |        | EA | 1.000  | 48.88 | 48.88      |
| 2226  | 05/04/23    | AP      | Vendor: 33178 Rocky Mountain Equipment LP P90830 Line: 11 |        | EA | -1.000 | 1.71  | -1.71      |
| 2227  | 05/04/23    | AP      | Vendor: 33178 Rocky Mountain Equipment LP P90830 Line: 12 |        | EA | -1.000 | 2.25  | -2.25      |
| 2228  | 05/04/23    | AP      | Vendor: 33178 Rocky Mountain Equipment LP P90830 Line: 13 |        | EA | -1.000 | 21.24 | -21.24     |
| 2229  | 05/04/23    | AP      | Vendor: 33178 Rocky Mountain Equipment LP P90830 Line: 14 |        | EA | -1.000 | 11.68 | -11.68     |
| 2230  | 05/04/23    | AP      | Vendor: 33178 Rocky Mountain Equipment LP P90830 Line: 15 |        | EA | -1.000 | 64.88 | -64.88     |
| 2231  | 05/04/23    | AP      | Vendor: 33178 Rocky Mountain Equipment LP P90830 Line: 16 |        | EA | -1.000 | 48.88 | -48.88     |
| 2232  | 05/04/23    | AP      | Vendor: 33178 Rocky Mountain Equipment LP P90830 Line: 21 |        | EA | 1.000  | 1.71  | 1.71       |
| 2233  | 05/04/23    | AP      | Vendor: 33178 Rocky Mountain Equipment LP P90830 Line: 22 |        | EA | 1.000  | 2.25  | 2.25       |
| 2234  | 05/04/23    | AP      | Vendor: 33178 Rocky Mountain Equipment LP P90830 Line: 23 |        | EA | 1.000  | 21.24 | 21.24      |
| 2235  | 05/04/23    | AP      | Vendor: 33178 Rocky Mountain Equipment LP P90830 Line: 24 |        | EA | 1.000  | 11.68 | 11.68      |
| 2236  | 05/04/23    | AP      | Vendor: 33178 Rocky Mountain Equipment LP P90830 Line: 25 |        | EA | 1.000  | 64.88 | 64.88      |
| 2237  | 05/04/23    | AP      | Vendor: 33178 Rocky Mountain Equipment LP P90830 Line: 26 |        | EA | 1.000  | 48.88 | 48.88      |
| 120   | 12/12/22    | EMParts | 48138563 Filter-Oil                                       |        | EA | 1.000  | 37.00 | 37.00      |
| 121   | 12/12/22    | EMParts | 84376814 Filter-Cab                                       |        | EA | 1.000  | 16.39 | 16.39      |
| 122   | 12/12/22    | EMParts | 84565926 Filter-Fuel                                      |        | EA | 1.000  | 58.70 | 58.70      |
| 123   | 12/12/22    | EMParts | AF25557 Air-Filter-Element                                |        | EA | 1.000  | 23.25 | 23.25      |
| 124   | 12/12/22    | EMParts | FF5421 Filter-Fuel                                        |        | EA | 1.000  | 42.32 | 42.32      |

|                     |        |
|---------------------|--------|
| Labour Total        | 0.00   |
| Parts Total         | 328.30 |
| Miscellaneous Total | 0.00   |

### Segment: 2 350 Hour Service

| Trans | Actual Date | Source | Details                       | STATUS | UM  | Units | Price | Total Cost |
|-------|-------------|--------|-------------------------------|--------|-----|-------|-------|------------|
| 904   | 12/15/22    | PR     | Employee: 2395 Nickolas Schou |        | HRS | 1.000 |       |            |



## Work Order: 13731

|                     |      |
|---------------------|------|
| Labour Total        | 1.00 |
| Parts Total         | 0.00 |
| Miscellaneous Total | 0.00 |

### Segment: 3 Repair Door Latch,wiper and light

| Trans | Actual Date | Source | Details                        | STATUS | UM  | Units | Price | Total Cost |
|-------|-------------|--------|--------------------------------|--------|-----|-------|-------|------------|
| 905   | 12/17/22    | PR     | Employee: 2915 Scott Scrivener |        | HRS | 1.500 |       |            |

|                     |      |
|---------------------|------|
| Labour Total        | 1.50 |
| Parts Total         | 0.00 |
| Miscellaneous Total | 0.00 |

|                            |               |
|----------------------------|---------------|
| <b>Labour Total</b>        | <b>2.50</b>   |
| <b>Parts Total</b>         | <b>328.30</b> |
| <b>Miscellaneous Total</b> | <b>0.00</b>   |

**Description:** 350 Hour Service Unit at Emerson Site. **Date Started:** 2023-07-05  
**Equipment:** E696 2021 Case TR310B Tracked Skidsteer  
**Serial#:** JAFTR310LLM486685

### Segment: 1 Parts

| Trans | Actual Date | Source  | Details                                                  | STATUS | UM | Units  | Price | Total Cost |
|-------|-------------|---------|----------------------------------------------------------|--------|----|--------|-------|------------|
| 653   | 08/16/23    | AP      | Vendor: 33178 Rocky Mountain Equipment LP P94027 Line: 1 |        | EA | 2.000  | 14.54 | 29.08      |
| 1229  | 08/28/23    | AP      | Vendor: 33178 Rocky Mountain Equipment LP P94526 Line: 2 |        | EA | 2.000  | 14.54 | 29.08      |
| 2549  | 08/28/23    | AP      | Vendor: 33178 Rocky Mountain Equipment LP P94526 Line: 3 |        | EA | -2.000 | 14.54 | -29.08     |
| 2550  | 08/28/23    | AP      | Vendor: 33178 Rocky Mountain Equipment LP P94526 Line: 4 |        | EA | 2.000  | 14.54 | 29.08      |
| 31    | 09/06/23    | EMParts | 44995162 Bulb                                            |        | EA | 1.000  | 14.54 | 14.54      |
| 32    | 09/06/23    | EMParts | 44995162 Bulb                                            |        | EA | 3.000  | 14.54 | 43.62      |
| 49    | 07/06/23    | EMParts | 48138563 Filter-Oil                                      |        | EA | 1.000  | 40.44 | 40.44      |
| 50    | 07/06/23    | EMParts | 84376814 Filter-Cab                                      |        | EA | 1.000  | 99.40 | 99.40      |
| 51    | 07/06/23    | EMParts | 84565926 Filter-Fuel                                     |        | EA | 1.000  | 61.95 | 61.95      |
| 52    | 07/06/23    | EMParts | AF25557 Air-Filter-Element                               |        | EA | 1.000  | 54.30 | 54.30      |
| 53    | 07/06/23    | EMParts | FF5421 Filter-Fuel                                       |        | EA | 1.000  | 44.76 | 44.76      |
| 1113  | 08/31/23    | EMParts | R50468 Plug                                              |        | EA | 1.000  | 26.52 | 26.52      |

|                     |        |
|---------------------|--------|
| Labour Total        | 0.00   |
| Parts Total         | 443.69 |
| Miscellaneous Total | 0.00   |

### Segment: 2 350 Hour Service

| Trans | Actual Date | Source | Details                       | STATUS | UM  | Units | Price | Total Cost |
|-------|-------------|--------|-------------------------------|--------|-----|-------|-------|------------|
| 1508  | 07/24/23    | PR     | Employee: 3110 Callum Deditch |        | HRS | 3.000 |       |            |



## Work Order: 14191

|                     |      |
|---------------------|------|
| Labour Total        | 3.00 |
| Parts Total         | 0.00 |
| Miscellaneous Total | 0.00 |

### Segment: 3 Repair Front lights

| Trans | Actual Date | Source | Details                       | STATUS | UM  | Units | Price | Total Cost |
|-------|-------------|--------|-------------------------------|--------|-----|-------|-------|------------|
| 1545  | 08/21/23    | PR     | Employee: 3110 Callum Deditch |        | HRS | 1.000 |       |            |
| 1546  | 08/28/23    | PR     | Employee: 3110 Callum Deditch |        | HRS | 0.500 |       |            |

|                     |      |
|---------------------|------|
| Labour Total        | 1.50 |
| Parts Total         | 0.00 |
| Miscellaneous Total | 0.00 |

### Segment: 4 Repair bucket tilt pin

| Trans | Actual Date | Source | Details                       | STATUS | UM  | Units | Price | Total Cost |
|-------|-------------|--------|-------------------------------|--------|-----|-------|-------|------------|
| 1547  | 08/29/23    | PR     | Employee: 3110 Callum Deditch |        | HRS | 1.500 |       |            |

|                     |      |
|---------------------|------|
| Labour Total        | 1.50 |
| Parts Total         | 0.00 |
| Miscellaneous Total | 0.00 |

|                            |               |
|----------------------------|---------------|
| <b>Labour Total</b>        | <b>6.00</b>   |
| <b>Parts Total</b>         | <b>443.69</b> |
| <b>Miscellaneous Total</b> | <b>0.00</b>   |

|                                                           |                          |                                 |
|-----------------------------------------------------------|--------------------------|---------------------------------|
| <b>Description:</b> 350 Hour Service                      | Unit at Emerson Site.    | <b>Date Started:</b> 2023-11-02 |
| <b>Equipment:</b> E696 2021 Case TR310B Tracked Skidsteer | Hours: 1245              |                                 |
|                                                           | Next service hours: 1545 |                                 |
| <b>Serial#:</b> JAFTR310LLM486685                         | GRO#10874                |                                 |

### Segment: 1 Parts

| Trans | Actual Date | Source  | Details                    | STATUS | UM | Units | Price  | Total Cost |
|-------|-------------|---------|----------------------------|--------|----|-------|--------|------------|
| 32    | 11/02/23    | EMParts | 48138563 Filter-Oil        |        | EA | 1.000 | 39.26  | 39.26      |
| 33    | 11/02/23    | EMParts | 84376814 Filter-Cab        |        | EA | 1.000 | 111.90 | 111.90     |
| 34    | 11/02/23    | EMParts | 84565926 Filter-Fuel       |        | EA | 1.000 | 60.51  | 60.51      |
| 35    | 11/02/23    | EMParts | AF25557 Filter-Air Primary |        | EA | 1.000 | 39.07  | 39.07      |
| 36    | 11/02/23    | EMParts | FF5421 Filter-Fuel         |        | EA | 1.000 | 44.76  | 44.76      |
| 678   | 11/16/23    | EMParts | 5W40 Spectra 5W40          |        | I  | 8.000 | 7.70   | 61.61      |



## Work Order: 14454

|                     |        |
|---------------------|--------|
| Labour Total        | 0.00   |
| Parts Total         | 357.11 |
| Miscellaneous Total | 0.00   |

### Segment: 2 350 Hour Service

| Trans | Actual Date | Source | Details                     | STATUS | UM  | Units | Price | Total Cost |
|-------|-------------|--------|-----------------------------|--------|-----|-------|-------|------------|
| 523   | 11/07/23    | PR     | Employee: 3108 Zachary Dean |        | HRS | 3.000 |       |            |
| 524   | 11/08/23    | PR     | Employee: 3108 Zachary Dean |        | HRS | 0.500 |       |            |

|                     |      |
|---------------------|------|
| Labour Total        | 3.50 |
| Parts Total         | 0.00 |
| Miscellaneous Total | 0.00 |

|                            |               |
|----------------------------|---------------|
| <b>Labour Total</b>        | <b>3.50</b>   |
| <b>Parts Total</b>         | <b>357.11</b> |
| <b>Miscellaneous Total</b> | <b>0.00</b>   |

**Description:** Unit takes a long time cranking  
**Equipment:** E696 2021 Case TR310B Tracked Skidsteer  
**Serial#:** JAFTR310LLM486685

Unit at Emerson Site.  
GRO#3927

**Date Started:** 2023-11-20

### Segment: 1 Parts

*Bled fuel system, cleaned air filters- Zac*

| Trans | Actual Date | Source  | Details              | STATUS | UM | Units  | Price | Total Cost |
|-------|-------------|---------|----------------------|--------|----|--------|-------|------------|
| 755   | 11/20/23    | EMParts | 84565926 Filter-Fuel |        | EA | 1.000  | 60.51 | 60.51      |
| 756   | 11/20/23    | EMParts | FF5421 Filter-Fuel   |        | EA | 1.000  | 44.76 | 44.76      |
| 901   | 12/20/23    | EMParts | 84565926 Filter-Fuel |        | EA | -1.000 | 60.51 | -60.51     |
| 902   | 12/20/23    | EMParts | FF5421 Filter-Fuel   |        | EA | -1.000 | 44.76 | -44.76     |

|                     |      |
|---------------------|------|
| Labour Total        | 0.00 |
| Parts Total         | 0.00 |
| Miscellaneous Total | 0.00 |

### Segment: 2 Unit takes a long time cranking before it starts

| Trans | Actual Date | Source | Details                     | STATUS | UM  | Units | Price | Total Cost |
|-------|-------------|--------|-----------------------------|--------|-----|-------|-------|------------|
| 1392  | 11/21/23    | PR     | Employee: 3108 Zachary Dean |        | HRS | 1.000 |       |            |



## Work Order: 14522

|                            |             |
|----------------------------|-------------|
| Labour Total               | 1.00        |
| Parts Total                | 0.00        |
| Miscellaneous Total        | 0.00        |
| <b>Labour Total</b>        | <b>1.00</b> |
| <b>Parts Total</b>         | <b>0.00</b> |
| <b>Miscellaneous Total</b> | <b>0.00</b> |

|                                                           |                   |                                 |
|-----------------------------------------------------------|-------------------|---------------------------------|
| <b>Description:</b> Repair Lights, Panels                 | hours:1429        | <b>Date Started:</b> 2024-07-05 |
| <b>Equipment:</b> E696 2021 Case TR310B Tracked Skidsteer | Next service:1545 |                                 |
|                                                           | GRO#10213         |                                 |
| <b>Serial#:</b> JAFTR310LLM486685                         |                   |                                 |

### Segment: 1 Parts

| Trans | Actual Date | Source | Details                                                  | STATUS | UM | Units               | Price  | Total Cost |
|-------|-------------|--------|----------------------------------------------------------|--------|----|---------------------|--------|------------|
| 219   | 07/05/24    | AP     | Vendor: 33178 Rocky Mountain Equipment LP P01537 Line: 1 |        | EA | 1.000               | 109.67 | 109.67     |
| 220   | 07/05/24    | AP     | Vendor: 33178 Rocky Mountain Equipment LP P01537 Line: 2 |        | EA | 1.000               | 14.63  | 14.63      |
| 1704  | 07/05/24    | AP     | Vendor: 33178 Rocky Mountain Equipment LP P01537 Line: 3 |        | EA | -1.000              | 109.67 | -109.67    |
| 1705  | 07/05/24    | AP     | Vendor: 33178 Rocky Mountain Equipment LP P01537 Line: 4 |        | EA | -1.000              | 14.63  | -14.63     |
| 1706  | 07/05/24    | AP     | Vendor: 33178 Rocky Mountain Equipment LP P01537 Line: 5 |        | EA | 1.000               | 109.67 | 109.67     |
| 1707  | 07/05/24    | AP     | Vendor: 33178 Rocky Mountain Equipment LP P01537 Line: 6 |        | EA | 1.000               | 14.63  | 14.63      |
|       |             |        | PO - Open - #1027786 - 33178 400472A1-spring             |        | EA | 1.00                | 109.67 | 109.67     |
|       |             |        | PO - Open - #1027786 - 33178 84155097-bulb               |        | EA | 1.00                | 14.63  | 14.63      |
|       |             |        |                                                          |        |    | Labour Total        | 0.00   |            |
|       |             |        |                                                          |        |    | Parts Total         | 248.60 |            |
|       |             |        |                                                          |        |    | Miscellaneous Total | 0.00   |            |

### Segment: 2 Repair Lights

### Segment: 3 Repair Hood

| Trans | Actual Date | Source | Details                     | STATUS | UM  | Units                      | Price         | Total Cost |
|-------|-------------|--------|-----------------------------|--------|-----|----------------------------|---------------|------------|
| 684   | 07/09/24    | PR     | Employee: 3108 Zachary Dean |        | HRS | 0.500                      |               |            |
|       |             |        |                             |        |     | Labour Total               | 0.50          |            |
|       |             |        |                             |        |     | Parts Total                | 0.00          |            |
|       |             |        |                             |        |     | Miscellaneous Total        | 0.00          |            |
|       |             |        |                             |        |     | <b>Labour Total</b>        | <b>0.50</b>   |            |
|       |             |        |                             |        |     | <b>Parts Total</b>         | <b>248.60</b> |            |
|       |             |        |                             |        |     | <b>Miscellaneous Total</b> | <b>0.00</b>   |            |



## Work Order: 14992

|                                                           |                                 |                                 |
|-----------------------------------------------------------|---------------------------------|---------------------------------|
| <b>Description:</b> Reg Maintenance                       | GRO11912/11907/11910/11911/1189 | <b>Date Started:</b> 2024-08-01 |
| <b>Equipment:</b> E696 2021 Case TR310B Tracked Skidsteer | 3/11957/13685                   |                                 |
| <b>Serial#:</b> JAFTR310LLM486685                         | 1467 hours Dec 19 2024 hours    |                                 |

### Segment: 1 parts

1 x 44995162 bulb

Headwind Solutions

1 x X-200012VARINL - air shutoff system

1 x WH-0001-R5 Wire harness

1 x R5-2018-CANUP250 - Controller, CANbus

| Trans               | Actual Date | Source | Details                                                            | STATUS | UM | Units  | Price | Total Cost |
|---------------------|-------------|--------|--------------------------------------------------------------------|--------|----|--------|-------|------------|
| 276                 | 08/09/24    | AP     | Vendor: 33178 Rocky Mountain Equipment LP P02759 Line: 1           |        | EA | 1.000  | 57.18 | 57.18      |
| 277                 | 08/09/24    | AP     | Vendor: 33178 Rocky Mountain Equipment LP P02759 Line: 2           |        | EA | 1.000  | 8.89  | 8.89       |
| 551                 | 08/07/24    | AP     | Vendor: 10064 Comrades Parts & Accessories Ltd. 000-402380 Line: 2 |        | LS | 0.000  | 0.00  | 14.68      |
| 1670                | 08/09/24    | AP     | Vendor: 33178 Rocky Mountain Equipment LP P02759 Line: 3           |        | EA | -1.000 | 57.18 | -57.18     |
| 1671                | 08/09/24    | AP     | Vendor: 33178 Rocky Mountain Equipment LP P02759 Line: 4           |        | EA | -1.000 | 8.89  | -8.89      |
| 1672                | 08/09/24    | AP     | Vendor: 33178 Rocky Mountain Equipment LP P02759 Line: 5           |        | EA | 1.000  | 57.18 | 57.18      |
| 1673                | 08/09/24    | AP     | Vendor: 33178 Rocky Mountain Equipment LP P02759 Line: 6           |        | EA | 1.000  | 8.89  | 8.89       |
|                     |             |        | PO - Open - #1028030 - 33178 47600574- rod                         |        | EA | 1.00   | 57.18 | 57.18      |
|                     |             |        | PO - Open - #1028030 - 33178 84158586- pin, coil                   |        | EA | 1.00   | 8.89  | 8.89       |
| Labour Total        |             |        |                                                                    |        |    | 0.00   |       |            |
| Parts Total         |             |        |                                                                    |        |    | 146.82 |       |            |
| Miscellaneous Total |             |        |                                                                    |        |    | 0.00   |       |            |

### Segment: 2 wash

| Trans               | Actual Date | Source | Details                      | STATUS | UM  | Units | Price | Total Cost |
|---------------------|-------------|--------|------------------------------|--------|-----|-------|-------|------------|
| 474                 | 08/06/24    | PR     | Employee: 3142 Trina Schmidt |        | HRS | 2.000 |       |            |
| 478                 | 08/09/24    | PR     | Employee: 3119 Shawn Dittmer |        | HRS | 1.000 |       |            |
| 1151                | 07/31/24    | PR     | Employee: 3142 Trina Schmidt |        | HRS | 1.000 |       |            |
| Labour Total        |             |        |                              |        |     | 4.00  |       |            |
| Parts Total         |             |        |                              |        |     | 0.00  |       |            |
| Miscellaneous Total |             |        |                              |        |     | 0.00  |       |            |

### Segment: 3 Install belly plates & cab mounts

| Trans | Actual Date | Source | Details                      | STATUS | UM  | Units | Price | Total Cost |
|-------|-------------|--------|------------------------------|--------|-----|-------|-------|------------|
| 479   | 08/09/24    | PR     | Employee: 3119 Shawn Dittmer |        | HRS | 2.000 |       |            |



## Work Order: 14992

|                     |      |
|---------------------|------|
| Labour Total        | 2.00 |
| Parts Total         | 0.00 |
| Miscellaneous Total | 0.00 |

### Segment: 4 Complete In/sheet/change light bulb

| Trans | Actual Date | Source | Details                      | STATUS | UM  | Units | Price | Total Cost |
|-------|-------------|--------|------------------------------|--------|-----|-------|-------|------------|
| 475   | 08/06/24    | PR     | Employee: 3119 Shawn Dittmer |        | HRS | 1.500 |       |            |

|                     |      |
|---------------------|------|
| Labour Total        | 1.50 |
| Parts Total         | 0.00 |
| Miscellaneous Total | 0.00 |

### Segment: 5 Install positive air system

| Trans | Actual Date | Source | Details                      | STATUS | UM  | Units | Price | Total Cost |
|-------|-------------|--------|------------------------------|--------|-----|-------|-------|------------|
| 476   | 08/07/24    | PR     | Employee: 3119 Shawn Dittmer |        | HRS | 7.500 |       |            |
| 477   | 08/08/24    | PR     | Employee: 3119 Shawn Dittmer |        | HRS | 6.000 |       |            |

|                     |       |
|---------------------|-------|
| Labour Total        | 13.50 |
| Parts Total         | 0.00  |
| Miscellaneous Total | 0.00  |

### Segment: 6 help Shawn with repairs

| Trans | Actual Date | Source | Details                       | STATUS | UM  | Units | Price | Total Cost |
|-------|-------------|--------|-------------------------------|--------|-----|-------|-------|------------|
| 480   | 08/09/24    | PR     | Employee: 2024 Travis Schmidt |        | HRS | 0.500 |       |            |

|                     |      |
|---------------------|------|
| Labour Total        | 0.50 |
| Parts Total         | 0.00 |
| Miscellaneous Total | 0.00 |

### Segment: 7 Install lock indicator rod

| Trans | Actual Date | Source | Details                      | STATUS | UM  | Units | Price | Total Cost |
|-------|-------------|--------|------------------------------|--------|-----|-------|-------|------------|
| 1357  | 08/21/24    | PR     | Employee: 3119 Shawn Dittmer |        | HRS | 2.000 |       |            |

|                     |      |
|---------------------|------|
| Labour Total        | 2.00 |
| Parts Total         | 0.00 |
| Miscellaneous Total | 0.00 |



## Work Order: 14992

Segment: 8 trace block heater cord/cold start machine/bring to shop

| Trans | Actual Date | Source | Details                      | STATUS | UM  | Units                      | Price         | Total Cost |
|-------|-------------|--------|------------------------------|--------|-----|----------------------------|---------------|------------|
| 541   | 12/19/24    | PR     | Employee: 3119 Shawn Dittmer |        | HRS | 5.000                      |               |            |
|       |             |        |                              |        |     | Labour Total               | 5.00          |            |
|       |             |        |                              |        |     | Parts Total                | 0.00          |            |
|       |             |        |                              |        |     | Miscellaneous Total        | 0.00          |            |
|       |             |        |                              |        |     | <b>Labour Total</b>        | <b>28.50</b>  |            |
|       |             |        |                              |        |     | <b>Parts Total</b>         | <b>271.12</b> |            |
|       |             |        |                              |        |     | <b>Miscellaneous Total</b> | <b>0.00</b>   |            |

**Description:** Reg Maintenance **Date Started:** 2025-07-18  
**Equipment:** E696 2021 Case TR310B Tracked Skidsteer  
**Serial#:** JAFTR310LLM486685

Segment: 1 parts

| Trans | Actual Date | Source  | Details                             | STATUS | UM | Units               | Price  | Total Cost |
|-------|-------------|---------|-------------------------------------|--------|----|---------------------|--------|------------|
| 138   | 07/17/25    | EMParts | GX31S 12v Battery Top Stud Group 31 |        | EA | 1.000               | 188.56 | 188.56     |
|       |             |         |                                     |        |    | Labour Total        | 0.00   |            |
|       |             |         |                                     |        |    | Parts Total         | 188.56 |            |
|       |             |         |                                     |        |    | Miscellaneous Total | 0.00   |            |

Segment: 2 R&R battery

| Trans | Actual Date | Source | Details                       | STATUS | UM  | Units               | Price | Total Cost |
|-------|-------------|--------|-------------------------------|--------|-----|---------------------|-------|------------|
| 297   | 07/17/25    | PR     | Employee: 2024 Travis Schmidt |        | HRS | 1.500               |       |            |
|       |             |        |                               |        |     | Labour Total        | 1.50  |            |
|       |             |        |                               |        |     | Parts Total         | 0.00  |            |
|       |             |        |                               |        |     | Miscellaneous Total | 0.00  |            |

Segment: 3 insheet inspection

| Trans | Actual Date | Source | Details                      | STATUS | UM  | Units | Price | Total Cost |
|-------|-------------|--------|------------------------------|--------|-----|-------|-------|------------|
| 1106  | 07/30/25    | PR     | Employee: 3119 Shawn Dittmer |        | HRS | 2.000 |       |            |



**Work Order: 15430**

|                            |               |
|----------------------------|---------------|
| Labour Total               | 2.00          |
| Parts Total                | 0.00          |
| Miscellaneous Total        | 0.00          |
| <hr/>                      |               |
| <b>Labour Total</b>        | <b>3.50</b>   |
| <b>Parts Total</b>         | <b>378.93</b> |
| <b>Miscellaneous Total</b> | <b>0.00</b>   |