



H.F. NODES CONSTRUCTION

P25 – Caterpillar 815 Packer

5:06 PM 7/18/2014

hours 20405 NEXT SERVICE DUE AT 20655

SERVICE TECH GORDON

SERVICED THE ENGINE 15/40

REPLACED THE OIL AIR AND FUEL FILTERS

4:50 PM 7/24/2014

HOURS 20417 NEXT SERVICE DUE AT 20607

SERVICE TECH RYAN

SERVICED THE ENGINE 15/40

REPLACED THE OIL AIR AND FUEL FILTERS

CENTRE PIN AND BUSHINGS ARE STARTING TO GET BAD

2:20 PM 8/19/2014

HOURS 20529 NEXT SERVICE DUE AT 20667

SERVICE TECH ANDREW

CHECKED MACHINE OVER

FIRE EXT AUG 2014


2:15 PM 8/20/2014

HOURS 20529 NEXT SERVICE DUE AT 20667

SERVICE TECH GORDON

CHECK OUT AIR COMPRESSOR

7:12 AM 10/16/2014



H.F. NODES CONSTRUCTION

HOURS 20686 NEXT SERVICE DUE AT 20936

SERVICE TECH BRAXTON

SERVICED THE ENGINE 10/30

REPLACED THE OIL AIR AND FUEL FILTER

FIRE EXT MAY 2014

11:50 AM 26/01/2015

HOURS 20826 NEXT SERVICE 20436

SERVICE TECH BRAXTON

CHECKED OUT THE AIR COMPRESSOR

REPLACED WITH AN EXCHANGE FROM FINNING TRACTOR

FIRE EXT MAY 2014

1:20 PM 17/03/2015

HOURS 20985 NEXT SERVICE DUE AT 21235

SERVICE TECH GORDON

CHECKED MACHINE OVER

REMOVED THE LEFT REAR WHEEL

REPLACED THE DUO CONE SEAL

FIRE EXT MARCH 2015

9:34 AM 23/07/2015

HOURS 21252 NEXT SERVICE DUE AT 21502

SERVICE TECH BRAXTON

SERVICED THE ENGINE 15/40

REPLACED THE OIL AIR AND FUEL FILTERS

BLOW OUT THE RAD

FIRE EXT MAY 2015



H.F. NODES CONSTRUCTION

4:48 PM 19/08/2015

HOURS 21282 NEXT SERVICE DUE AT 21502

SERVICE TECH GORDON

CHECKED MACHINE OVER

FIRE EXT APRIL 2015

11:31 AM 22/10/2015

HOURS 21408 NEXT SERVICE DUE AT 21502

SERVICE TECH RANDY

CHECKED MACHINE OVER

CLEANED THE CAB OUT

REPLACED THE WATER TEMP SENDER

FIRE EXT MAR 2015

5:48 AM 05/08/2016

HOURS 21468 NEXT SERVICE 21502

SERVICE TECH RANDY

REPLACED THE BATTERY CABLE

12:21 PM 14/08/2016

HOURS


JOB FORMAN CALLED IN AND SAID THE MACHINE WAS HEATING UP

RYAN WENT OUT AND BLEW THE RAD OUT

REMOVED THE SIDE CURTAINS

10:18 AM 11/09/2016

HOURS 21547 NEXT SERVICE DUE AT 21800



H.F. NODES CONSTRUCTION

SERVICE TECH RYAN

SERVICED THE ENGINE 15/40

REPLACED THE OIL AIR AND FUEL FILTERS

INSTALLED A NEW RAD CAP

7:21 AM 29/11/2016

HOURS 21799 NEXT SERVICE DUE AT 22050

SERVICE TECH BRAXTON

OPERATO COMPLAINED THE ENGINE HAD A HOLE IN THE BLOCK

HAULED MACHINE HOME

START TO REMOVE THE ENGINE

INSTALLED OUR NEW ENGINE OUT OF STOCK

INSTALLED 10/30 INTO THE ENGINE

SENT RAD TO COOL CORE

REPLACED THE FAN BELTS

INSTALLED NEW BATTERY

FIRE EXT NOV 2016

CHANGED TRANSMISSION OIL AND FILTER

2:06 PM 12/04/2017

HOURS 21840 NEXT SERVICE DUE AT 22050

SERVICE TECH BRAXTON

CHECKED MACHINE OVER

REPLACED THE BOLTS IN THE SCRAPER BAR

REPLACED THE GASKET ON THE TURBO RETURN OIL LINE

CHECEKD ALL THE OIL LEVELS

12:44 PM 23/06/2017



H.F. NODES CONSTRUCTION

HOURS

SERVICE TECH RANDY

CHECKED OUT LOW POWER COMPLAINTS

CHECKED THE BOOST STALL RPM AND WOT THROTTLE RPM

CHECKED FUEL PRESSURE AT IDLE AND FULL THROTTLE

EVERTHING IS IN SPEC

11:55 AM 01/08/2017

HOURS 22123 NEXT SERVICE DUE AT 22373

SERVICE TECH SLADE

SERVICED THE ENGINE 15/40

REPLACED THE OIL AIR AND FUEL FILTERS

FIRE EXT APRIL 2017

9:33 AM 29/08/2017

HOURS 22413 NEXT SERVICE DUE AT 22663

SERVICE TECH SLADE

SERVICED THE ENGINE 15/40

REPLACED THE OIL AIR AND FUEL FILTERS

FIRE EXT MARCH 2017

11:27 AM 28/11/2017

HOURS 22516 NEXT SERVICE DUE AT 22663

SERVICE TECH BRAXTON

CHECKED MACHINE OVER

FIRE EXT APRIL 2017

REPAIRED THE LIGHTS

INSTALLED NEW FAN BELTS



H.F. NODES CONSTRUCTION

2:49 PM 09/08/2018

HOURS 22607 NEXT SERVICE DUE AT 22857

SERVICE TECH COLE AND AYDEN

SERVICED THE ENGINE 15/40

REPLACED THE OIL AIR AND FUEL FILTERS

FIRE EXT OCT 2018

4:26 PM 17/09/2018

HOURS 22712 NEXT SERVICE DUE AT 22913

SERVICE TECH NEIL;

OPERATORS WHERE COMPLAINING THAT THE TRANSMISSON WAS RUNNING HOT

PUT PRSSURE GAUGE ON THE MAIN PRESSURE SHECK

ONLY HAD 100 PSI

REMOVED THE TRANSMISSON CHARGING PUMP

FOUND THE BEARING HAD FAILED THE GEARS WERE.

INSTALLED A NEW CAT EXCHANGE PUMP

TEST RUN 320 PSI AT IDLE AND 390 AT HIGH IDLE

TORQUE OUT PSI AT HIGH IDLE IN FOURTH 60 PSI

CHANGED OIL AND FILTERS

AFTER TESTING

FIRE EXT OCT 2018

2:43 PM 24/04/2019

HOURS 22818 NEXT SERVICE DUE AT 22913

SERVICE TECH SLADE

REMOVED THE FAILED TRANSMISSON

REBUILT AS REQUIRED



H.F. NODES CONSTRUCTION

INSTALLED THE TRANSMISSION

REPLACED THE CENTRE JOINT BEARINGS

SEE WORK ORDER

9:22 AM 03/06/2019

HOURS 22910 NEXT SERVICE DUE AT 23160

SERVICE TECH NEIL

SERIVED THE ENGINE 15/40

REPLACED THE AIR OIL AND FUEL FILTERS

FIRE EXT OCT 2018

8:35 AM 13/12/2019

HOURS 23136 NEXT SERVICE DUE AT 23389

SERVICE TECH MURRAY

SERVICED THE ENGINE 10/30

REPLACED THE OIL AIR AND FUEL FILTERS

FIRE EXT AUG 2019

2:19 PM 22/01/2020

HOURS

SERVICE TECH MURRAY

CHECKED OUT TRANSMISSION OIL LEAK

REPLACED THE OIL FILLER CAP THAT WAS GONE

WASHED THE TRANSMISSION DOWN

RUN MACHINE AROUND DID NOT FIND ANY LEAKS

ENGINE IS ALL COVERED IN OIL

RAD IS VERY DIRTY



H.F. NODES CONSTRUCTION

8:56 AM 19/08/2020

HOURS 23240 NEXT SERVICE DUE AT 23386

SERVICE TECH AYDEN

CHECKED THE MACHINE OVER

REMOVED THE RAD AND WASHED

REPLACED THE TOP AND BOTTOM SEALS

REPLACED THE TOP RAD HOSE

REPLACED THE BACKUP ALARM SWITCH

INSTALLED A NEW NUETRAL SAFTEY SWITCH

REPLACED THE FAN BELTS

GREASED THE MACHINE

CHANGED OIL IN THE FINAL DRIVES

FIRE EXTJULY 2020

1:22 PM 16/06/2020

HOURS 23284 NEXT SERVICE DUE AT 23386

SERVICE TECH MURRAY

CHECKED THE MACHINE OVER

FIRE EXT JULY 2020

1:45 PM 20/11/2020

HOURS 23391 NNEXT SERVICE DUE AT 23436

SERVICE TECH COLE


CHECKED THE MACHINE OVER

INSTALLED A DRAIN ON THE AIR TANK

REPLACED THE SEAL RINGS BETWEEN THE TURBO AND THE MUFFLER

CLEANED OUT THE CAB

TIGHTEN UP COOLANT HOSES



H.F. NODES CONSTRUCTION

GREASE THE MACHINE

SHAWN REPLACED THE BROKEN FEET

FIRE EXT JUNE 2020

2:54 PM 12/05/2021

HOURS 23491 NEXT SERVICE DUE AT 23790

SERVICE TECH AYDEN

SERVICED THE ENGINE 15/40

REPLACED THE OIL AIR AND FUEL FILTERS

REPLACED THE LIGHTS AT THE REAR OF THE MACHINE

REPLACED THE POPPET VALVE ON TH AIR COMPRESSER

RESEALED THE LEFT REAR WHEEL BRAKE

CLEANED THE STUMP PANS

ADJUSTED THE WIPER BARS ON THE DRUMS WHEELS

FRONT DIFF YOKE STARTING TO LEAK SLIGHTLY

FIRE EXT JULY 2020

7:58 AM 27/04/2022

HOURS 23731 NEXT SERVICE DUE AT 24031

SERVICE TECH SLADE

INSTALLED A/C ON THE MACHINE

REPAIRED AND ADJUSTED THE SCARPER BARS

WELD NEW FEET ONTO THE WHEELS

SERVICED THE ENGINE 15/40

REPLACED THE OIL AIR AND FUEL FILTERS

FIRE EXT SEPT 2021

7:29 AM 14/06/2022



H.F. NODES CONSTRUCTION

HOURS 23746 NEXT SERVICE DUE AT 24031

SERVICE TECH SLADE

CHECKED OUT THE ANTI FREEZE LEAK

FOUND NO 1 PRECUP SEAL TO BE LEAKIG=NG

REMOVED THE PRECUP AND RESEAL

INSTALLED

TOPPED UP WITH ANTI FREEZE

REPLACED THE NO 1 GLOW PLUG TIP WAS BROKE OFF

5:59 AM 30/07/2022

HOURS 23788 NEXT SERVICE DUE AT 24031

SERVICE TECH SLADE

OPERATOR COMPLAINED OF LOW POWER

CHECKED THE FUEL PUMP AND FOUND IT HAD FAILED

REMOVED THE PUMP AND SENT TO NDS TO HAVE IT

REPAIRED

7:51 AM 08/10/2022

HOURS

SERVICE TECH MURRAY AND WES

INSTALLED SOME NEW SCRAPER BAR

REPLACED THE BATTERYYS

10:37 AM 21/10/2022

HOURS 23801

SERVICE TECH MURRAY

CHECKED OUT THE OIL LEAK ON THE ENGINE

REMOVED THE OIL PAN



H.F. NODES CONSTRUCTION

INSTALLED A NEW OIL PAN GASKET

REPAIRED THE STEP ON THE OPERATORS SIDE

FIRE EXT SEPT 2022

7:47 AM 10/06/2023

HOURS 23935 NEXT SERVICE DUE AT 24031

SERVICE TECH WESTLY

FIRE EXT SEPT 2023

9:25 AM 26/06/2023

HOURS 23936 NEXT SERVICE DUE AT 24236

SERVICE TECH WES

CHANGED ENGINE OIL 15/40

CHANGED OUTER AIR FILTER

CHANGED CAB AIR FILTER

NO VISIBLE LEAKS

FRONT WINDOW IS CRACKED

FIRE EXT SEPT 2023

REMOVED RAD COVERS, SENT TO COOL CORE. REPLACED THERMOSTAT, INSTALLED COOLANT CHECK VALVE IN HEAD.
REPLACED TURBO DRAIN LINE GASKET

8:20 AM 25/11/2023

HOURS 24175 NEXT SERVICE DUE AT 24236

SERVICE TECH SLADE

REMOVED THE FAILED TURBO

INSTALLED A EXCHANGE FROM FINNING

2:05 PM 15/05/2024



H.F. NODES CONSTRUCTION

HOURS 24277 NEXT SERVICE DUE AT 24577

SERVICE TECH SLADE

SERVICED THE ENGINE 15/40

REPLACED THE OIL AIR AND FUEL FILTERS

FIRE XET EXPIRED

1:24 PM 15/10/2024

HOURS 24305 NEXT SERVICE DUE AT 24577

6:19 AM 21/10/2024

HOURS 24314 NEXT SERVICE DUE AT 24577

SERVICE TECH WESTLY

CHECKED THE MACHINE OVER

REPLACED THE HEAD LINER

REPLACED THE FRONT WINDSHIELD

CHECKED THE BLOCK HEATER

FIRE EXT MARCH 2025