

## Work Order Details

This report was run on: Nov 24, 2024 02:53:42 PM  
 with the following parameters  
 Opened After: Nov 24, 2022 02:38:00 PM  
 Opened Before: Nov 24, 2024 02:38:00 PM  
 Parent Asset: "Articulated Rock Truck (19-45-044)"  
 Asset Category: "All"  
 Assigned User: "All"  
 Maintenance Type: "All"  
 Priority: "All"  
 Status: "All"

Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late
62524	Engine rebuild - Parts on site incomplete orders	Closed, Completed	Corrective	Dec 01, 2022 01:16:27 PM		Dec 18, 2022 07:56:23 PM	
Task Description	Asset	Assigned To	Completed By	Date Completed		Est Hours	Spent Hours
CHRIS WISEMAN DEC 09/2022 -PULLED FILTER HOUSINGS OFF HEAD -PULLED WIRING -PULLED COOLING AND HEATER HOSES CHRIS WISEMAN DEC 10/2022 -REMOVED CYLINDER HEAD -SWAP OVER PARTS TO NEW HEAD -START CLEANING UP SPACER PLATE CHRIS WISEMAN DEC 11/2022 -CLEAN UP SPACER PLATE AND BLOCK -INSTALLED NEW GASKETS AND CYLINDER HEAD -TORQUE DOWN HEAD -INSTALL BACKING PLATE AND CAM GEAR -INSTALL INJECTORS -INSTALL ROCKER ARMS -CLEAN UP INTERMEDIATE HOUSING AND ROCKER COVERS INSTALL NEW WIRING HARNESS AND GASKETS CHRIS WISEMAN DEC 12/2022 -INSTALLED INTERMEDIATE COVER AND HOOKED UP INJECTORS -INSTALLED EXHAUST BRAKES -REMOVED STARTER -SET INJECTORS,VALVES AND EXHAUST BRAKES 13 DEC 2022 Austin H -Look through work orders to see what was done/needs to be done. No crossover was written -Organize parts and clean work area -Continue with cylinder head install -Installed fuel filter housings and fuel filters -Installed all L/H brackets and electrical -Installed air intake 14 DEC 2022 Austin H -Continued cylinder head install -Disassembled thermostat housing and replaced lip seals and thermostats -Installed thermostat housing -Installed all remaining lines/brackets/exhaust pieces on R/H side -Replaced damaged coolant line on DEF pump	Articulated Rock Truck Articulated Rock Truck	Chris Wiseman Chris Wiseman Chris Wiseman Chris Wiseman Chris Wiseman Chris Wiseman Chris Wiseman Chris Wiseman Chris Wiseman Chris Wiseman Austin Heino Austin Heino	Austin Heino Austin Heino Austin Heino Austin Heino Austin Heino Austin Heino Austin Heino Austin Heino Austin Heino Austin Heino	Dec 01, 2022 01:16:27 PM		5.50 11.50 11.50 11.50 7.00 11.50	
15 DEC 2022 Austin H -Disassembled L/H starter and resealed it -Installed L/H starter with new gasket	Articulated Rock Truck	Austin Heino	Austin Heino	Dec 18, 2022 07:56:23 PM		11.50	70.00

Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late
------	------------------------	--------	------	--------------	----------	----------------	-----------

65391 Post transmission install inspection,  
Needs CEN Harness and Chassis to CEM harness  
Brakes and final drives all worn-out, front right is the only good one  
\*\*Done \*\*  
Needs alternator \*Done\*

Task Description	Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours
29 January 2023 - Gabe Elnamer -Inspect unit thoroughly -Check box hinge pins and bushings, lift cylinders and both A-frames -Grease unit 30 January 2023 - Gabe Elnamer -Look up/order parts for unit -Handed in inspection sheet and parts req. to Tim March 01, 2023- MARVIN C- BOOSTED THE BATTERIES AND HAD TO KEEP IT RUNNING WITH THE BOOSTING MACHINE FOR A LITTLE WHILE AS IT WAS ROZEN DEAD. MOVED THE MACHINE IN THE SHOP, DRIANED COOLANT, REMOVED LINES AND NRS COOLER AND INSTALLED NEW ONE. REINSTALLED ALL LINES, FILLED UP NEW COOLANT, BLED AIR IN THE SYSTEM, RAN THE ENGINE AND BLED THE SYSTEM AGAIN UNTIL AIR IS GONE AND READJUSTED THE COOLANT LEVEL. REMOVED REAR DUMP BOX PINS, LIFTED IT AND BLOCKED, MOVED AWAY LIGHT GROUP AND REMOVED THE BUSHINGS. POLISHED BORES, INSTALLED NEW BUSHINGS. March 2 2023 Ken C /DS Finished Hinge pins & Greased Got both hoist bushings pins to take grease Installed lateral brace bolts Installed Alternator pulley Resealed Aux Pump Found 5 out 6 brakes are worn out ,show from indicators	Articulated Rock Truck Articulated Rock Truck	Gabe Elnamer Gabe Elnamer Marvin Corpuz Ken Connion Ken Connion	Gabe Elnamer Gabe Elnamer Marvin Corpuz Ken Connion Ken Connion	Jan 26, 2023 10:35:18 AM Jan 29, 2023 05:05:00 PM Jan 30, 2023 08:55:00 AM Mar 01, 2023 05:20:00 AM Mar 02, 2023 05:26:00 PM Mar 03, 2023 05:18:00 PM Mar 03, 2023 05:18:00 PM Mar 04, 2023 05:01:00 PM Mar 04, 2023 05:02:00 AM Mar 05, 2023 05:01:00 PM	Apr 16, 2023 11:29:50 AM	3.00 0.50 11.50 11.50
CHRIS WISEMAN MARCH 03/2023 -SHOP CLEANUP -UNBOXED BRAKE HUB PARTS AND CLEANED -MADE LIST OF PARTS REQUIRED TO MAKE SPARE BRAKE ASSY March 3 2023 Ken C /DS Went to move unit to make more room for hub removal tried closing the hood which didnt work so i borrowed a switch out of a diffrent unit but it didnt work either then the batteries died. went to charge batteries , charger started charging then quit. i tried a few times with no luck, charger dosent seem to work.	Articulated Rock Truck	Ken Connion	Ken Connion	Mar 03, 2023 05:18:00 PM	3.50 9.50	
drained brake oil and rear diff. drained hub and removed. MARCH 02, 2023- MARVIN C- CLEANED PARTS, POLISHED ALL MATING SURFACES. REMOVED ALL OLD BEARINGS AND SEALS AND INSTALLED NEW ONE. INSTALLED NEW SETS OF FRICTION DISC AND PLATES. COMPLETED AS COMPLETE REBUILT. MARCH 03, 2023-MARVIN C- DISASSEMBLED RIGHT REAR BRAKE AND FINAL DRIVE GROUP, REMOVED ALL BEARINGS AND SEALS AND WASHED AND POLISHED PARTS. RESEALED AND INSTALLED NEW BEARINGS, EW FRICTION DISCS AD PLATES. March 4 2023 Ken C /DS installed hub , torqued flange to 400 ft lbs	Articulated Rock Truck	Marvin Corpuz	Marvin Corpuz	Mar 02, 2023 06:25:00 PM Mar 03, 2023 05:17:00 AM Mar 04, 2023 05:01:00 PM	11.50 10.50 11.50	
hub is missing bleeder screw but it will be here tomorrow MARCH 04, 2023-MARVIN C- CONTINUE AND COMPLETED FULL REBUILT OF BRAKE AND FINAL DRIVE GROUP INTENDED TO BE INSTALLED TO RIGHT CENTER POSITION. INSTALLED NEW BLEEDER SCREW AND THE WHEELS ON REAR RIGHT AND TORQUED TO 350 FT.LBS. REMOVED STAND AND POSITIONED TO THE REAR CENTER AND REMOVED WHEEL AND BRAKE AND FINAL DRIVE GROUP FOR REBUILD. March 5 2023 Ken C /DS	Articulated Rock Truck	Marvin Corpuz	Marvin Corpuz	Mar 04, 2023 05:02:00 AM Mar 05, 2023 05:01:00 PM	9.50 9.50	

Placed old hub n rebuild bench					
installed new hub					
torqued wheel to 350 ft-lbs 08 March 2023 - Gabe Einamer -Remove alternator -Install pully onto new alternator -Clean all connections -Install new alternator -Check charging system voltage -Check wiring harnesses for hood switch/motor (found broken wire) -Re-spliced wire and tape up/secure harnesses -Raised/lowered hood to verify repair is completed	Articulated Rock Truck	Gabe Einamer	Gabe Einamer	Mar 08, 2023 05:28:00 PM	5.00
Daniel Reid March 09/23 took dirty complete final drive assemble into wsah bay and washed, stripped down complete final drive and brake assembly. Washed parts and removed all old bearings and races. Rebearing final drive gears with new thrust washers. Resealed piston and installed. Ready to install brake discs and plates.	Articulated Rock Truck				11.50
Daniel Reid March 10/23 Finished assembling brake section and completed final drive.	Articulated Rock Truck				7.50
MARCH 31, 2023-MARVIN C- GATHERED ALL PARTS AND CHECKED WHAT IS MISSING AND GET THEM ALL OUT OF THE WAREHOUSE. NEW SPINDLE, ANCHOR, SERVICE BRAKE HOUSING, AND THE REST ARE NEW PARTS. WAHED AND CLEANED, AND POLISHED PARTS AND ASSEMBLED.	Articulated Rock Truck	Marvin Corpuz			11.50
Mar 31/23 Kristian Z /DS  -Removed the rear left final drive that needs a rebuild -Installed a rebuilt final drive on the rear left, with new seals. Torqued final to 400 ft-lbs -Bolted on tire and torqued to 350 ft-lbs	Articulated Rock Truck	Kristian Zimmer	Kristian Zimmer		11.50
<b>Note:</b> -Before machine can be moved out, the rear diff and the rear left final needs to be filled with oil. -Left centre and Left Front finals need to be swapped out. 31 April 2023-Diego Z -removed left center tire and final	Articulated Rock Truck	Diego Zamora	Diego Zamora	Apr 01, 2023 05:26:00 AM	3.00
1 April 2023-Diego Z -installed planetary onto brake assembly -installed final drive onto axle -installed axle -filled final -bled brake (on center axle left) -reinstalled tire and torqued wheel nuts to spec -all hardware torqued to spec -started lifting machine to remove front left final	Articulated Rock Truck	Diego Zamora	Diego Zamora	Apr 02, 2023 04:44:00 AM	12.00
2 April 2023-Diego Z -removed left front final -started disassembly	Articulated Rock Truck	Diego Zamora	Diego Zamora	Apr 03, 2023 05:15:00 AM	12.00
APRIL 03, 2023-MARVIN C- CONTINUE N/S WORK. REMOVED OLD BEARINGS AND SEALS. WASHED AND POLISHED BEARING SEATS, MATING SURFACES AND ASSEMBLED THE BRAKE GROUP WITH NEW SEALS AND BEARINGS, FICKION DISCS/PLATES. N/S TO CONTINUE DO THE BEARING PRE-LOADING AND INSTALL CORRECT AMOUNT OF SHIMS, RECON THE PLANETARY AND INSTALL AND COMPLETE THE REBUILD.	Articulated Rock Truck	Marvin Corpuz			6.50
3 April 2023-Diego Z -finished preload procedure and finished rebuild -installed final and wheel, all hardware torqued to spec -filled front left and rear left final with oil -unit needs to be checked over, fluids filled, greased	Articulated Rock Truck	Diego Zamora	Diego Zamora	Apr 04, 2023 04:57:00 AM	12.00
04-04-23 - REY CONTRERAS  FILLED ALL FLUIDS/ CHECK OVER THE UNIT FOR LEAKS. APPLY GREASING TO THE UNIT.	Articulated Rock Truck	Rey Contreras	Rey Contreras	Apr 04, 2023 04:32:00 PM	11.50
HOOK -UP COMPUTER THEN OPEN THE E.T. TO RESET THE CODE. I CAN RESET THE CODE MYBE I HAVE BROKEN WIRE.					
INSTALLED NEW COIL AS #2 DPF					
PARKING THE MACHINE TO DOWNLINE FOR MORE TROUBLE SHOOTING.					

15 April 2023 - Blair T - "Complaint DISPATCHED BY NICK EMISSIONS CODE Correction/Repair Process Comments LOCATE UNIT CONNECT ET (ACTIVE CODE FOR # 1 FUEL CONTROL CURRENT HIGH) ACTIVE EVENT HIGH FUEL PRESSURE AND HIGH SOOT LOAD CHECK CONNECTOR AT ACTUATOR (OK) DISCONNECT ACTUATOR (CODE REMAINS -6) CHECK BOTH WIRES FOR SHORT TO GROUND (OK) DISCONNECT 40 PIN AND CONFIRM CONTINUITY TO ACTUATOR CONNECTOR ON BOTH WIRES AND NOT SHORDED TO ANOTHER CIRCUIT START INSPECTING HARNESS BACK TO CAB FIND HARNESS TAPED UP REMOVE TAPE FIND BARE/BROKEN WIRES CLEAN UP SVC RPT FURTHER TROUBLESHOOTING REQUIRED AND HARNESS REPAIR ASSIST TREVOR WITH A/C ISSUE ON 19-45-031 (GO OVER SCHEMATIC)"	Articulated Rock Truck	Blair Townley - Finning	Blair Townley - Finning	Apr 05, 2023 10:33:00 AM	2.50
07 April 2023 - Blair T - "Complaint DISPATCHED BY NICK EMISSIONS CODE Correction/Repair Process Comments FINISH HARNESS REPAIR INSTALL HARNESS AND SECURE CONNECT ET CLEAR ARD FUEL#1 ACTUATOR CODE FIRE UP UNIT (CODE RETURNS) CHECK WIRING OK DISCONNECT ACTUATOR COIL (CODE REMAINS -6) REMOVE WIRING FROM ECM (CODE REMAINS -6 SHOULD BE -5) SUSPECT ECM LOOK UP ECM PART NUMBER (NONE ONSITE NONE AVAILABLE FROM CAT) REMOVE AFTERTREATMENT ECM FROM 19-45-026 CONNECT TO 19-45-044 CONNECT ET CLEAR CODE/FIRE UP (CODE REMAINS INACTIVE) REMOVE AFTERTREATMENT ECM FROM UNIT AND INSTALL BORROWED ECM FIRE UP AND INITIATE REGEN (REGEN STARTED AND HIT 11% COMPLETE, WARNING FOR ARD FAN SPEED LOW) CANCEL REGEN CHECK CONNECTORS (TIGHT AND CONNECTED) BACK PROBE INTO ARD FAN WIRING CONNECT ET AND LOOK FOR FAN OVERRIDE OPTION (NOT AVAILABLE) CLEAN UP SVC RPT FURTHER TROUBLESHOOTING REQUIRED HARNESS REPAIRED ON DRIVERS SIDE WIRING WILL HAVE TO BE CHECKED AND POWER CONFIRMED TO FAN WHEN DOING A REGEN/FUNCTION TEST"	Articulated Rock Truck	Blair Townley - Finning	Blair Townley - Finning	Apr 07, 2023 08:48:00 AM	7.00
08 April 2023 - Blair T - "Complaint DISPATCHED BY NICK EMISSIONS CODE Correction/Repair Process Comments SAFETY MEETING CONTINUE WITH REPAIRS FOUND AFTER INITIAL COMPLAINT OF HIGH FUEL PRESSURE AND FUEL PRESSURE ACTUATOR CODE REPAIRED ARD FAN SPEED LOW NOW ACTIVE EVENT CODE INSTALL MISSING EXHAUST STACK BACK PROBE INTO ARD FAN SUPPLY AND GROUND FIRE UP UNIT (WAIT FOR FAN SELF TEST, POWER AND GROUND PRESENT FAN NOT TURNING) LOAD TEST CIRCUIT WHEN FAN CIRCUIT ENERGIZED (CIRCUIT LOAD TEST PASSES) LOOK UP PARTS HEAD TO WAREHOUSE AND PICK UP PARTS RETURN AND INSTALL NEW FAN FIRE/WARM UP UNIT INITIATE REGEN (REGEN GETS TO 10% AND ARD FAN SPEED LOW WARNING	Articulated Rock Truck	Blair Townley - Finning	Blair Townley - Finning	Apr 08, 2023 05:48:00 AM	9.00

ILLUMINATES)  
 RE-CONFIRM POWER AND GROUND AT FAN AND ON BOTH SIDES OF VOLTAGE  
 LIMITING PROTECTION MODULE (POWER AND GROUND PRESENT AT ALL TEST POINTS)  
 BENCH TEST OLD FAN (SUPPLY POWER AND GROUND TO FAN, FAN DOES NOT TURN  
 STUDY SCHEMATIC FIND HY746 YL IS PWM SIGNAL FROM ECM  
 CHECK CONTINUITY FROM FAN WIRING BACK TO LEFT HAND SIDE OF ENGINE  
 CONNECTOR (OPEN)  
 REMOVE TAPE ON WHAT APPEARS TO BE PREVIOUS REPAIR  
 FIND REPAIR BROKEN  
 CUT OUT REPAIR AND MAKE NEW WIRE FROM 12 PIN CONNECTOR ON L/H SIDE OF  
 ENGINE AND JOIN INTO HARNESS CLOSE TO HOOD WHERE THE HARNESS IS NO  
 LONGER VISIBLE  
 TAPE/PROTECT/SECURE HARNESS  
 START ENGINE AND MONITOR FAN FOR SELF TEST (FAN NOW WORKING)  
 REMOVE NEW FAN AND INSTALL ORIGINAL FAN  
 FIRE UP AND MONITOR FAN DURING SELF TEST (FAN SPINS)  
 WARM UP  
 PERFORM REGEN (SUCCESS, HIGH FUEL PRESSURE CODE DID OCCUR WHEN REGEN  
 STOPPED)  
 CLEAR FUEL PRESSURE CODE  
 PERFORM ASH SERVICE REGEN (SUCCESS, FUEL PRESSURE CODE DID NOT RETURN)  
 DURING REGEN THERE WAS A ENGINE OIL LEAK SPOTTED  
 FOUND BOLTS MISSING IN FUEL FILTER BRACKET TO FRONT COVER  
 INSTALL BOLTS  
 CLEAN OFF AREA (LEAK APPEARS TO HAVE STOPPED)  
 ALSO FOUND P CLAMP BOLTS LOOSE AND OTHER HARNESSSES NOT SECURES  
 (TIGHTEN BOLTS AND SECURE HARNESSSES)  
 CLEAN UP  
 RETURN NEW FAN TO WAREHOUSE  
 SVC RPT

-CHRIS W NEEDED ASSISTANCE ON 18-14-003 ASSIST CHRIS AS PER NICK"  
 CHRIS WISEMAN APRIL 10/2023  
 -CHECK OVER TRUCK MOVE TO ANOTHER BAY SO HOOD COULD BE OPENED  
 -REMOVED L/S STARTER LEAKING AND REMOVED SLING JAMMED BEHIND IT  
 REINSTALLED  
 -RECONNECTED EXHAUST TO TURBO PROPERLY LEAKING  
 -REPAIRED BRAKE LINE LEAK R/S CAB NO O-RING  
 -CODE 1449 CHARGED L/S REAR ACCUMULATOR  
 -INSTALL SKID PLATES  
 -REPLACED MISSING EXHAUST PIPE BEHIND CAB  
 -REMOVED FIRE EXTINGUISHER FROM R/S TO BE MOUNTED ON L/S  
 -NOT SURE WHERE PANEL ON L/S BEHIND CAB IS LOCATED  
 April 10/23 Gerald Granger  
 repairs horn, radio antenna , fire extinguisher

Articulated Rock Truck

11.50

Articulated Rock Truck

Gerald Granger

Apr 10, 2023 05:19:00 AM

6.50

April 10/23 Gerald Granger

repairs ,horn , fire extinguisher bracket,side panel, etc

Apr 11/23 Kristian Z /NS

Articulated Rock Truck

Kristian Zimmer

Kristian Zimmer

Apr 11, 2023 11:00:00 PM

6.00

-Placed on drivers side radiator panel. Welded a nut on one of the brackets, so be  
 easy to bolt on panel  
 -Checked all oils, lights, windshield wipers, heat and A/C  
 -Rear work light has a burnt bulb. Replaced it with a new one

-Topped up a bit of coolant

Note: 2 way radio needs to be replaced. Makes a loud noise when somebody is talking on the radio. Did a radio check and made the same loud noise, speaker must be broken

Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late
		Closed, Completed	Preventive - Planned	Mar 12, 2023 03:46:17 PM	Mar 12, 2023 03:46:00 PM	Mar 12, 2023 03:47:47 PM	0
	Task Description	Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours
	Brake Accumulator (Service) - Check	Articulated Rock Truck	PMtech	PMtech	Mar 12, 2023 03:47:00 PM	1.00	
	Brake Pads - Check	Articulated Rock Truck	PMtech	PMtech	Mar 12, 2023 03:47:00 PM	1.00	
	Braking System - Test	Articulated Rock Truck	PMtech	PMtech	Mar 12, 2023 03:47:00 PM	1.00	
	Diff & Final Drive Oil Level - Check (note particulates on mag plug and indicate findings)	Articulated Rock Truck	PMtech	PMtech	Mar 12, 2023 03:47:00 PM	1.00	
	Differential and Final Drive Oil Sample - Obtain	Articulated Rock Truck	PMtech	PMtech	Mar 12, 2023 03:47:00 PM	1.00	
	Engine Air Filter Secondary Element (Outer) - Replace	Articulated Rock Truck	PMtech	PMtech	Mar 12, 2023 03:47:00 PM	1.00	
	Engine Oil and Filter - Change	Articulated Rock Truck	PMtech	PMtech	Mar 12, 2023 03:47:00 PM	1.00	
	Engine Oil Filter Inspect (Cut Filter and Record Findings)	Articulated Rock Truck	PMtech	PMtech	Mar 12, 2023 03:47:00 PM	1.00	
	Fuel System Primary Filter - Replace	Articulated Rock Truck	PMtech	PMtech	Mar 12, 2023 03:47:00 PM	1.00	
	Fuel System Secondary Filter - Replace	Articulated Rock Truck	PMtech	PMtech	Mar 12, 2023 03:47:00 PM	1.00	
	Hoist System and Brake System Oil Sample - Obtain	Articulated Rock Truck	PMtech	PMtech	Mar 12, 2023 03:47:00 PM	1.00	
	Secondary Steering - Test	Articulated Rock Truck	PMtech	PMtech	Mar 12, 2023 03:47:00 PM	1.00	
	Steering System Oil Sample - Obtain	Articulated Rock Truck	PMtech	PMtech	Mar 12, 2023 03:47:00 PM	1.00	
	Torque Converter and Transmission Oil Sample - Obtain	Articulated Rock Truck	PMtech	PMtech	Mar 12, 2023 03:47:00 PM	1.00	
	Transfer Gear Oil Sample - Obtain	Articulated Rock Truck	PMtech	PMtech	Mar 12, 2023 03:47:00 PM	1.00	
	Transmission Oil Filter Replace	Articulated Rock Truck	PMtech	PMtech	Mar 12, 2023 03:47:00 PM	1.00	
	Transmission Oil Filter - Inspect (Cut Filter and Record Findings.)	Articulated Rock Truck	PMtech	PMtech	Mar 12, 2023 03:47:00 PM	1.00	

12.00

Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late
		Closed, Completed	Preventive - Planned	Mar 12, 2023 03:48:05 PM	Mar 12, 2023 03:48:00 PM	Mar 12, 2023 03:49:28 PM	0
	Task Description	Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours
	Battery or Battery Cable - Inspect/Replace	Articulated Rock Truck	PMtech	PMtech	Mar 12, 2023 03:48:00 PM	1.00	
	Brake Oil Filter - Replace	Articulated Rock Truck	PMtech	PMtech	Mar 12, 2023 03:48:00 PM	1.00	
	Brake Tank Strainer - Clean/Inspect/Replace	Articulated Rock Truck	PMtech	PMtech	Mar 12, 2023 03:48:00 PM	1.00	
	Cab Recirc Air Filter Element (Inner) - Replace	Articulated Rock Truck	PMtech	PMtech	Mar 12, 2023 03:48:00 PM	1.00	
	Fuel Tank Cap Filter - Replace	Articulated Rock Truck	PMtech	PMtech	Mar 12, 2023 03:48:00 PM	1.00	
	Hydraulic System Oil Filter and Screen - Clean/Inspect/Replace	Articulated Rock Truck	PMtech	PMtech	Mar 12, 2023 03:48:00 PM	1.00	
	Hydraulic System Oil Filter Inspect (Cut Filter and Record Findings)	Articulated Rock Truck	PMtech	PMtech	Mar 12, 2023 03:48:00 PM	1.00	
	Hydraulic Tank Strainer - Clean/Inspect/Replace	Articulated Rock Truck	PMtech	PMtech	Mar 12, 2023 03:48:00 PM	1.00	
	Oscillating Hitch - Adjust	Articulated Rock Truck	PMtech	PMtech	Mar 12, 2023 03:48:00 PM	1.00	
	Rollover Protective Structure (ROPS) - Inspect	Articulated Rock Truck	PMtech	PMtech	Mar 12, 2023 03:48:00 PM	1.00	
	Torque Converter, Transmission, and Transfer Gear Oil - Change	Articulated Rock Truck	PMtech	PMtech	Mar 12, 2023 03:48:00 PM	1.00	
	Transmission Clutch Calibrations - Complete	Articulated Rock Truck	PMtech	PMtech	Mar 12, 2023 03:48:00 PM	1.00	
	Transmission and Transfer Gear Breather - Replace	Articulated Rock Truck	PMtech	PMtech	Mar 12, 2023 03:48:00 PM	1.00	
08/04/23	claude white	Articulated Rock Truck	PMtech	Claude White	Apr 08, 2023 04:25:00 AM	4.00	
	installed 2-way radio						
	installed bolts in dash						
	checked lights (signal lights not working)						
	found flasher 8D-6946 missing						

9.00

4.00

Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late
		Closed, Completed	Corrective	Apr 16, 2023 11:28:06 AM	Apr 16, 2023 11:28:06 AM	Apr 16, 2023 11:28:06 AM	0
	Task Description	Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours
69638	Weld on wheel chalk holder	Articulated Rock Truck	Ray Ferron	Nick Vanderkooi			

April 16 2023	Articulated Rock Truck	Ray Ferron	Ray Ferron	Apr 16, 2023 05:08:00 PM	1.00
Ray Ferron					
Weld on wheel chock holders					
					1.00
<b>Work</b>	<b>Work Order Description</b>	<b>Status</b>	<b>Type</b>	<b>Date Created</b>	<b>Due Date</b>
69997	Replace AM/FM radio	Closed, Completed	Corrective	Apr 21, 2023 04:14:03 PM	Apr 21, 2023 04:50:00 PM
	<b>Task Description</b>	<b>Asset</b>	<b>Assigned To</b>	<b>Completed By</b>	<b>Date Completed</b>
	april 21 2023 tyler penkoff	Articulated Rock Truck	Tyler Penkoff	Daniel Reid	Apr 21, 2023 04:50:00 PM
	installed radio.				
					1.50
					1.50
<b>Work</b>	<b>Work Order Description</b>	<b>Status</b>	<b>Type</b>	<b>Date Created</b>	<b>Due Date</b>
70512	Needs a 2 way	Closed, Completed	Corrective	Apr 30, 2023 07:26:03 AM	Apr 30, 2023 03:52:33 PM
	<b>Task Description</b>	<b>Asset</b>	<b>Assigned To</b>	<b>Completed By</b>	<b>Date Completed</b>
	April 30 2023 tyler penkoff	Articulated Rock Truck	Tyler Penkoff	Menno Buhler	Apr 30, 2023 03:52:33 PM
	Old radio was missing mic, new mike installed but radio non functional. Co-axial cable coming out of back. chqnged cable end. Took apart rear dash and cut zipties to allow cable to reach radio properly. Tested radio wnd radio now functional.				
					5.00
<b>Work</b>	<b>Work Order Description</b>	<b>Status</b>	<b>Type</b>	<b>Date Created</b>	<b>Due Date</b>
70691	Bolt fell out of window latch	Closed, Completed	Corrective	May 02, 2023 03:01:19 PM	May 02, 2023 03:37:17 PM
	<b>Task Description</b>	<b>Asset</b>	<b>Assigned To</b>	<b>Completed By</b>	<b>Date Completed</b>
		Articulated Rock Truck	Christopher Paul	Ian Knott	May 02, 2023 03:37:17 PM
<b>Work</b>	<b>Work Order Description</b>	<b>Status</b>	<b>Type</b>	<b>Date Created</b>	<b>Due Date</b>
70726	Wiggle 44...	Closed, Completed	Corrective	May 03, 2023 04:52:21 AM	May 03, 2023 02:21:02 PM
	Retarder does not work.				
	<b>Hi beams do not work</b>				
	<b>Task Description</b>	<b>Asset</b>	<b>Assigned To</b>	<b>Completed By</b>	<b>Date Completed</b>
	go to unit, complaint of retarder not working and head lights not working. Go through who headlight circuit checking all connections found bad connection at relay under dash, tighten up. For the retarder not working while monitoring engine / machine response i could not get unit to mess up, under all parameters set out by sis the control handle and engine responded correctly.	Articulated Rock Truck	Jon Strasdin - Wajax	Jon Strasdin - Wajax	May 03, 2023 02:21:02 PM
					3.00
<b>Work</b>	<b>Work Order Description</b>	<b>Status</b>	<b>Type</b>	<b>Date Created</b>	<b>Due Date</b>
71050	No headlights	Closed, Completed		May 07, 2023 01:30:15 PM	May 07, 2023 04:02:44 PM
	<b>Task Description</b>	<b>Asset</b>	<b>Assigned To</b>	<b>Completed By</b>	<b>Date Completed</b>
	Troubleshoot wiring issue Wiring inside right light bucket short to ground	Articulated Rock Truck	Nick Misener	Nick Misener	May 07, 2023 04:02:39 PM
					2.83
					2.83
<b>Work</b>	<b>Work Order Description</b>	<b>Status</b>	<b>Type</b>	<b>Date Created</b>	<b>Due Date</b>
71160	Hydraulic tank empty & Brake tank overflowing	Closed, Completed	Warranty	May 09, 2023 10:07:30 AM	May 10, 2023 08:03:16 AM
	<b>Task Description</b>	<b>Asset</b>	<b>Assigned To</b>	<b>Completed By</b>	<b>Date Completed</b>
	09 MAY 2023 Austin H -Washed mud from all wheels/brake hubs -Drained brake cooling reservoir down to appropriate level -Removed all brake guards and pressure tested each brake hub individually -All brake hubs held pressure at 800 psi indicating that the piston seals are all good	Articulated Rock Truck	Austin Heino	Austin Heino	
					9.00

- Suspected inner duo cone seal is faulty on 1 or more brake hubs, unsure of how to test for that & there is no troubleshooting for it on SIS
- Installed all brake guards
- Drained black brake oil and replaced
- Topped up hydraulic oil

09 May 2023 - Sebastian C - "DROVE TO TRUCK AND INSPECTED LEAK CLEANED AROUND TANK AND DIAGNOSED SOURCE OF LEAK FOUND BRAKE RESERVOIR WAS OVERFULL HYDRAULIC OIL ENTERING BRAKE RESERVOIR BRAKES WILL HAVE TO BE ISOLATED AND PRESSURE TESTED TO IDENTIFY WHICH ONE/ONES ARE LEAKING "	Articulated Rock Truck	Sebastian Cepeda - Brandt	Sebastian Cepeda - Brandt	May 09, 2023 12:24:00 PM	1.50
<b>10.50</b>					
<b>Work</b>	<b>Work Order Description</b>	<b>Status</b>	<b>Type</b>	<b>Date Created</b>	<b>Due Date</b>
71179	Drain down Brake oil and top up HYD oil Ricky/John	Closed, Completed	Corrective	May 09, 2023 03:35:29 PM	May 09, 2023 03:36:00 PM
<b>Task Description</b>	<b>Asset</b>	<b>Assigned To</b>	<b>Completed By</b>	<b>Date Completed</b>	<b>Est Hours</b>
Drained down Brake oil and top up HYD oil 110L SW30	Articulated Rock Truck	PMtech	May 09, 2023 03:38:00 PM	1.00	<b>1.00</b>
<b>Work</b>	<b>Work Order Description</b>	<b>Status</b>	<b>Type</b>	<b>Date Created</b>	<b>Due Date</b>
72099	Hydraulic leak. Right front brake leaking	Closed, Completed	Corrective	May 25, 2023 03:35:13 PM	May 25, 2023 08:06:16 PM
<b>Task Description</b>	<b>Asset</b>	<b>Assigned To</b>	<b>Completed By</b>	<b>Date Completed</b>	<b>Est Hours</b>
Travel/locate Got to unit appeared to be leaking from on top of hydraulic tank Further inspection showed brake tank empty and hydraulic tank over filling So must have a brake seals gone Got Kristian to bring up lube truck topped up brakes returned lube truck Brought him to drive unit to shop On way we boosted water buffalo 36 in lay down May 25/23 Kristian Z /NS	Articulated Rock Truck	Kristian Zimmer	Kristian Zimmer	May 25, 2023 08:05:40 PM	2.83
-Assisted Hermen with hydraulic leak -Drove lube truck to the unit to fill up the brake fluid tank -Drove unit to the shop in the downline 05-29-23- REY CONTRERAS	Articulated Rock Truck	Kristian Zimmer	Kristian Zimmer	May 26, 2023 05:00:00 AM	3.00
TORQUED ALL MOUNTING BOLT OF FINAL DRIVE.					
INSTALLED OTHER BOLT AND COVER					
INSTALLED WHEEL					
RE-FILL GEAR OIL TO FINAL DRIVE May 29/23 Kristian Z /NS	Articulated Rock Truck	Kristian Zimmer	Kristian Zimmer	May 30, 2023 05:26:00 AM	3.50
-Torqued right wheel to 400 ft-lbs -Filled final with 60W oil -Drained hydraulic oil. Was to full from leakage -High beam wasn't working due to a pulled wire. Rewired the high beam -Brake fault code, due to low brake accumulator pressure. Charged the right accumulator to 1200 psi. Was down at 400 psi -Checked the rest of the lights, wipers and A/C. All working good May 28/23 -Blair T- Finning	Articulated Rock Truck	Blair Townley - Finning	Blair Townley - Finning	May 28, 2023 06:33:00 AM	8.00
"Complaint DISPATCHED BY NICK BRAKE COOLING TANK OVERFULL (OIL TRANSFER) Cause BYPASSING FRONT R/H BRAKE Correction/Repair Process Comments SAFETY MEETING PAPERWORK LOCATE UNIT VERIFY COMPLAINT OF OIL TRANSFER (HYD TANK LOW, BRAKE COOLING TANK OVERFULL) DRAIN DOWN BRAKE COOLING TANK USE SERVICE TRUCK TO EVAC OIL FROM CONTAINER PUMP OFF OIL INTO WASTE OIL TANK HEAD TO LUBE ISLAND AND RETRIEVE PAILS OF HYD OIL RETURN TO UNIT AND TOP UP HYD OIL SO UNIT CAN BE RUN SET UP TEST TOOLING TO UTILIZE TRUCK BRAKING SYSTEM TO TEST INDIVIDUAL					

AXLES  
 ISOLATE FRONT AXLE AND APPLY FULL BRAKE PRESSURE TO FRONT AXLE (WILL NOT HOLD PRESSURE)  
 ISOLATE CENTER AXLE AND APPLY FULL BRAKE PRESSURE AND CLOSE OFF TEST RIGGING AND MONITOR PRESSURE (1100PSI FOR 20 MINS, AXLE OK)  
 ISOLATE REA AXLE AND APPLY FULL BRAKE PRESSURE AND CLOSE OFF TEST RIGGING AND MONITOR PRESSURE (1100 PSI FOR 20 MINS AXLE OK)  
 CHANGE ORINGS AND RECONNECT REAR BRAKING SYSTEM  
 ISOLATE FRONT LEFT HAND BRAKE AND APPLY FULL BRAKE PRESSURE (1100PSI FOR 20 MINS, FRONT L/H BRAKE OK)  
 ISOLATE FRONT RIGHT HAND BRAKE AND APPLY FULL BRAKE PRESSURE (BRAKE WILL NOT BUILD TO FULL PRESSURE AND DROPS WHEN USING TOOLING TO HOLD PRESSURE IN BRAKE, FRONT R/H BRAKE IS BYPASSING)  
 RESEAL FITTINGS AND RECONNECT LINES  
 REMOVE TEST TOOLING  
 CLEAN UP  
 SVC RPT  
 Complication  
 TIME TAKEN TO SET UP FITTINGS/HOSES TO USE TRUCK BRAKING SYSTEM FOR TESTING (TRUCK SYSTEM USED TO ENSURE FULL PUMP FLOW AND CORRECT PRESSURE USED WHEN PERFORMING TESTING)"

								2.83	25.33
Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late		
72677	Truck won't start	Closed, Completed	Corrective	Jun 04, 2023 07:17:51 AM	Jun 04, 2023 07:29:16 AM				
Task Description	Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours			
	Articulated Rock Truck	Tyler Penkoff	Menno Buhler	Jun 04, 2023 07:29:16 AM					
Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late		
74032	Hydraulic hose/fitting spraying all over back right side of cab.  **PARKED SOUTH OF YELLOW FLOATS**	Closed, Completed	Corrective	Jun 27, 2023 03:10:41 PM	Jun 27, 2023 07:22:10 PM				
Task Description	Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours			
27-06-23 Andy Boettger located truck and inspected for leak, started truck and operated functions, found one line leaking on right side near cooling pack, found line is loose, tightened line and cleaned up, started and monitored, no leaks now, checked other lines for tightness, checked fluid,	Articulated Rock Truck	Andy Boettger	Menno Buhler	Jun 27, 2023 07:22:10 PM	1.50				
Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late		
74156	Pop window piece fell off. Window rattles around freely going to break if not secured.	Closed, Completed	Corrective	Jun 29, 2023 02:50:33 PM	Jun 29, 2023 05:14:45 PM				
Task Description	Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours			
WINDOW LATCH FELL APART. WENT TO UNIT TO INSPECT AND SEE WHAT PARTS ARE NEEDED. GET PARTS . INSTALL WINDOW SCREW.	Articulated Rock Truck	Trevor Irwin - Brandt	Trevor Irwin - Brandt	Jun 29, 2023 05:14:45 PM	2.00				
Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late		
75002	PM 2 and machine inspection	Closed, Completed	Preventive - Planned	Jul 16, 2023 07:15:39 AM	Jul 16, 2023 11:54:28 AM				
Task Description	Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours			
Brake Accumulator (Service) - Check	Articulated Rock Truck				0.00				
Brake Pads - Check	Articulated Rock Truck				0.00				
Braking System - Test	Articulated Rock Truck				0.00				
Diff & Final Drive Oil Level - Check (note particulates on mag plug and indicate findings)	Articulated Rock Truck				0.00				
Differential and Final Drive Oil Sample - Obtain	Articulated Rock Truck				0.00				
Engine Air Filter Secondary Element (Outer) - Replace	Articulated Rock Truck				0.00				

Engine Oil and Filter - Change	Articulated Rock Truck				0.00
Engine Oil Filter Inspect (Cut Filter and Record Findings)	Articulated Rock Truck				0.00
Fuel System Primary Filter - Replace	Articulated Rock Truck				0.00
Fuel System Secondary Filter - Replace	Articulated Rock Truck				0.00
Hoist System and Brake System Oil Sample - Obtain	Articulated Rock Truck				0.00
Secondary Steering - Test	Articulated Rock Truck				0.00
Steering System Oil Sample - Obtain	Articulated Rock Truck				0.00
Torque Converter and Transmission Oil Sample - Obtain	Articulated Rock Truck				0.00
Transfer Gear Oil Sample - Obtain	Articulated Rock Truck				0.00
Transmission Oil Filter Replace	Articulated Rock Truck				0.00
Transmission Oil Filter - Inspect (Cut Filter and Record Findings.)	Articulated Rock Truck				0.00
Aftercooler Core - Inspect/Clean	Articulated Rock Truck				0.00
Automatic Lubrication Grease Tank - Fill	Articulated Rock Truck				0.00
Cab Fresh Air Filter (Outer)- Replace	Articulated Rock Truck				0.00
Cab Recirc Air Filter (Inner)- Inspect and Replace if Needed	Articulated Rock Truck				0.00
DEF Filler Screen - Clean	Articulated Rock Truck				0.00
Diesel Exhaust Fluid - Fill	Articulated Rock Truck				0.00
Engine Air Filter Primary Element (Outer) - Replace	Articulated Rock Truck				0.00
Engine Air Filter Secondary Element (Inner) - Inspect and Replace if Needed	Articulated Rock Truck				0.00
Ether Starting Aid Cylinder - Inspect/Replace	Articulated Rock Truck				0.00
Radiator Core - Clean	Articulated Rock Truck				0.00
Tire Inflation - Check	Articulated Rock Truck				0.00
Window Washer Reservoir - Fill	Articulated Rock Truck				0.00
Belt - Inspect/Replace	Articulated Rock Truck				0.00
Backup Alarm - Test	Articulated Rock Truck				0.00
Brakes, Indicators and Gauges - Test	Articulated Rock Truck				0.00
Engine Oil Level - Check	Articulated Rock Truck				0.00
Seat Belt - Inspect	Articulated Rock Truck				0.00
Wheel Nut Torque - Check (350 /-45 Ft.Lbs)	Articulated Rock Truck				0.00
Suspension and Suspension Cylinder Bearings - Lubricate	Articulated Rock Truck				0.00
Body Pivot Bearings - Lubricate	Articulated Rock Truck				0.00
Brake Oil Level - Check	Articulated Rock Truck				0.00
Cooling System Coolant Level - Check	Articulated Rock Truck				0.00
Fuel System Water Separator - Drain	Articulated Rock Truck				0.00
Fuel Tank Water and Sediment - Drain	Articulated Rock Truck				0.00
Fluids - Check for Leaks	Articulated Rock Truck				0.00
Hoist Cylinder Bearings - Lubricate	Articulated Rock Truck				0.00
Hydraulic System Oil Level - Check	Articulated Rock Truck				0.00
Oscillating Hitch - Lubricate	Articulated Rock Truck				0.00
Steering Cylinder Bearings - Lubricate	Articulated Rock Truck				0.00
Torque Converter, Transmission, and Transfer Gear Oil Level - Check	Articulated Rock Truck				0.00
Coolant Sample (Level 2) - Obtain(Test coolant and record freeze point)	Articulated Rock Truck				0.00
Engine Oil Sample - Obtain	Articulated Rock Truck				0.00
16 July 2023 - Gabe Elnamer		Gabe Elnamer		Jul 16, 2023 05:11:00 PM	
-PM 2 service and inspect machine					4.00
-Clean and wash lube bay afterwards					

Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late
75072	Missing hardware on right back window	Closed, Completed		Jul 17, 2023 07:41:04 PM	Jul 18, 2023 03:25:52 AM	Jul 18, 2023 03:25:52 AM	1.50
Task Description	Asset	Assigned To	Completed By	Date Completed		Est Hours	Spent Hours
17 July 2023-Diego Z -stole right rear window latch assembly off 745-26 and installed on 745-44 -adjusted mirrors for operator	Articulated Rock Truck	Diego Zamora	Diego Zamora	Jul 18, 2023 03:25:00 AM			1.50
Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late
75141	Retarder is working intermittently. Tried all 3 settings & won't work at times.	Closed, Completed	Corrective	Jul 18, 2023 10:18:50 PM	Jul 19, 2023 09:22:23 AM	Jul 19, 2023 09:22:23 AM	1.50
Task Description	Asset	Assigned To	Completed By	Date Completed		Est Hours	Spent Hours

19 July 2023 - Sebastian C -  
 "DROVE TO UNIT AND DIAGNOSED INTERMITTANT RETARDER PROBLEMS  
 CHECKED OUT ALL WIRING  
 TEST DROVE UNIT AND FOUND NO ISSUES  
 CONNECTED LAPTOP AND RECORDED RETARDER STATUS  
 ALL SETTINGS ON HANDLE ARE WORKING PROPERLY  
 "

Articulated Rock Truck Sebastian Cepeda - Brandt Sebastian Cepeda - Brandt Jul 19, 2023 09:22:23 AM

3.00

Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late	3.00
75175	No fuel gauge	Closed, Completed		Jul 19, 2023 04:01:47 PM		Jul 19, 2023 10:11:28 PM		
Task Description	Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours		
	Articulated Rock Truck	Ken Cannon	Nick Vanderkooi	Jul 19, 2023 10:11:28 PM				
Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late	
75184	Small engine oil leak *Done*, A-frame clunking	Closed, Completed		Jul 19, 2023 07:16:34 PM		Jul 20, 2023 01:42:08 PM		
Task Description	Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours		
Changed out front a-frame bearing with new pin adaptor and grease seal. Unplugged main grease line to bearing before new bearing install and changed grease zerk for lower pin to a 90 degree one so it also can get grease. put 2.5 tubes of grease into all three zerk.	Articulated Rock Truck	Daniel Reid		Jul 20, 2023 01:41:00 PM				8.00
Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late	
75267	Overgreased Equipment	Closed, Completed	Corrective	Jul 21, 2023 01:06:56 PM		Jul 21, 2023 04:36:17 PM		
Task Description	Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours		
Overgreased Equipment	Articulated Rock Truck	Grease Task Force	Grease Task Force	Jul 21, 2023 04:38:08 PM				
Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late	
75321	Hydraulic hose started sweating on dayshift. Was dry last night.	Closed, Completed		Jul 22, 2023 07:41:36 PM		Jul 26, 2023 03:39:35 AM		
Task Description	Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours		
Inspected unit and looked up hose to order	Articulated Rock Truck	Ken Cannon	Nick Vanderkooi	Jul 26, 2023 03:39:35 AM				2.00
								2.00
Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late	
75438	Code ARD fuel pressure	Closed, Completed		Jul 25, 2023 11:45:13 AM		Jul 25, 2023 04:32:05 PM		
Task Description	Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours		
Replace priming pump Manual regen	Articulated Rock Truck	Nick Misener	Nick Misener	Jul 25, 2023 04:31:28 PM				3.00
								3.00
Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late	
75439	Seat damper is not working	Closed, Completed		Jul 25, 2023 11:55:30 AM		Jul 25, 2023 03:16:17 PM		
Task Description	Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours		
Seat damper does work as it should	Articulated Rock Truck	Nick Misener	Nick Misener	Jul 25, 2023 03:15:32 PM				1.00
								1.00
								0.00
Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late	
75440	Seat damper is not working	Closed, Completed		Jul 25, 2023 11:55:37 AM		Jul 25, 2023 03:16:18 PM		
Task Description	Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours		
	Articulated Rock Truck	Nick Misener	Nick Misener	Jul 25, 2023 03:16:18 PM				
Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late	
75465	745C PM2 500 Service Hours	Closed, Completed	Preventive -	Jul 25, 2023		Jul 26, 2023 05: Jul 25, 2023 05:03: 0		

Task Description	Asset	Assigned To	Planned	05:02:00 PM	02:00 PM	29 PM	Est Hours	Spent Hours	
				Completed By	Date Completed				
Brake Accumulator (Service) - Check	Articulated Rock Truck	PMtech							
Brake Pads - Check	Articulated Rock Truck	PMtech							
Braking System - Test	Articulated Rock Truck	PMtech							
Diff & Final Drive Oil Level - Check (note particulates on mag plug and indicate findings)	Articulated Rock Truck	PMtech	PMtech	Jul 16, 2023 05:02:00 PM			2.00		
Differential and Final Drive Oil Sample - Obtain	Articulated Rock Truck	PMtech	PMtech	Jul 16, 2023 05:02:00 PM			2.00		
Engine Air Filter Secondary Element (Outer) - Replace	Articulated Rock Truck	PMtech	PMtech	Jul 16, 2023 05:02:00 PM			2.00		
Engine Oil and Filter - Change	Articulated Rock Truck	PMtech	PMtech	Jul 16, 2023 05:02:00 PM			2.00		
Engine Oil Filter Inspect (Cut Filter and Record Findings)	Articulated Rock Truck	PMtech	PMtech	Jul 16, 2023 05:02:00 PM			2.00		
Fuel System Primary Filter - Replace	Articulated Rock Truck	PMtech	PMtech	Jul 16, 2023 05:02:00 PM			2.00		
Fuel System Secondary Filter - Replace	Articulated Rock Truck	PMtech	PMtech	Jul 16, 2023 05:02:00 PM			2.00		
Hoist System and Brake System Oil Sample - Obtain	Articulated Rock Truck	PMtech	PMtech	Jul 16, 2023 05:02:00 PM			2.00		
Secondary Steering - Test	Articulated Rock Truck	PMtech	PMtech	Jul 16, 2023 05:02:00 PM			2.00		
Steering System Oil Sample - Obtain	Articulated Rock Truck	PMtech	PMtech	Jul 16, 2023 05:02:00 PM			2.00		
Torque Converter and Transmission Oil Sample - Obtain	Articulated Rock Truck	PMtech	PMtech	Jul 16, 2023 05:02:00 PM			2.00		
Transfer Gear Oil Sample - Obtain	Articulated Rock Truck	PMtech	PMtech	Jul 16, 2023 05:02:00 PM			2.00		
Transmission Oil Filter Replace	Articulated Rock Truck	PMtech	PMtech	Jul 16, 2023 05:02:00 PM			2.00		
Transmission Oil Filter - Inspect (Cut Filter and Record Findings.)	Articulated Rock Truck	PMtech	PMtech	Jul 16, 2023 05:02:00 PM			2.00		
22.00									
Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late	Est Hours	Spent Hours
75680	Ard fuel pressure low	Closed, Completed		Jul 29, 2023 09:53:34 PM		Jul 30, 2023 11:37:01 PM			
Task Description		Asset	Assigned To	Completed By	Date Completed			Est Hours	Spent Hours
Fixed fuel issue and did a regen		Articulated Rock Truck	Ken Cannon	Ken Cannon	Jul 30, 2023 11:37:01 PM			3.00	
3.00									
Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late	Est Hours	Spent Hours
76104	Wheel chock bent	Closed, Completed	Welding	Aug 06, 2023 07:59:25 AM		Aug 06, 2023 11:37:08 AM			
Task Description		Asset	Assigned To	Completed By	Date Completed			Est Hours	Spent Hours
		Articulated Rock Truck	Donald Kearley	Ian Knott	Aug 06, 2023 11:37:08 AM				
Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late	Est Hours	Spent Hours
76361	ARD Fuel level low	Closed, Completed	Corrective	Aug 12, 2023 01:03:35 AM		Aug 12, 2023 09:37:16 AM			
Task Description		Asset	Assigned To	Completed By	Date Completed			Est Hours	Spent Hours
trivde to machine hook up laptop check codes has low ard fuel pressure, diagnose to fuel solenoid on ard manitould, drive to ware hose get part install, test and regen machine.		Articulated Rock Truck	Matt Derfler - Wajax	Matt Derfler - Wajax	Aug 12, 2023 04:44:00 AM			4.00	
4.00									
Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late	Est Hours	Spent Hours
76397	Driver says when brakes are applied there is a lag in actual brake engagement before truck slows down/stops.	Closed, Completed		Aug 12, 2023 03:08:01 PM		Aug 14, 2023 06:25:43 AM			
Task Description		Asset	Assigned To	Completed By	Date Completed			Est Hours	Spent Hours
CHRIS WISEMAN AUG 15/2023		Articulated Rock Truck						11.50	
-REBUILD BRAKE HUB REMOVED FROM 044									
Found bad brake hub/ brought into shop and washed		Articulated Rock Truck	Ken Cannon	Ken Cannon	Aug 14, 2023 06:25:43 AM			2.00	
2.00									11.50
Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late	Est Hours	Spent Hours
76644	Front struts need inspection	Closed, Completed		Aug 17, 2023 10:08:55 PM		Aug 18, 2023 09:21:42 AM			
Task Description		Asset	Assigned To	Completed By	Date Completed			Est Hours	Spent Hours
Strut was filled with only oil, drained oil to where is supposed to be and filled with gas then tested		Articulated Rock Truck	Ken Cannon	Ken Cannon	Aug 18, 2023 09:21:42 AM			2.00	

								2.00
Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late	
76792	Wheel retorque	Closed, Completed	Corrective	Aug 20, 2023 04:49:42 PM		Aug 15, 2023 04:50:00 PM		
Task Description	Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours		
Retorque rears	Articulated Rock Truck	Kal Tire	Kal Tire	Aug 15, 2023 04:50:00 PM				
Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late	
77024	Inside fuel gauge reading basically empty all the time	Closed, Completed	Corrective	Aug 25, 2023 10:25:56 PM		Aug 27, 2023 04:58:28 AM		
Task Description	Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours		
Aug 26/23 Kristian Z /NS	Articulated Rock Truck Articulated Rock Truck	Marvin Corpuz Kristian Zimmer	Menno Buhler Kristian Zimmer	Aug 27, 2023 04:58:28 AM		8.50		
-Found that the radio antenna plug in has a temporary plug and wasn't taken out when assembling. Removed the plug and plugged in the radio plug. All working well -Removed the pass side hoist cylinder to drive out the busted bearings. Placed in new bearing and the bottom side mounting pin								
Note: Needs the top mounting pin AUGUST 26, 2023-MARVIN C- WASHED RIGHT FENDER AREA. REMOVED AND INSTALLED NEW FUEL TANK LEVEL SENDER. CHECKED OVER NIT. FOUND HOIST CYLINDERS BEARINGS CRACKED. REPLACED UPPER PIN AND BAERING ON LEFT. REMOVED RIGHT CYLINDER AND REPLACED BEARINGS.	Articulated Rock Truck	Marvin Corpuz			9.00	8.50		
Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late	
77109	Inside fuel gauge still inaccurate. Outside fuel gauge is now removed but was reading accurate. Only way to check proper fuel level now is to open cap & physically look in.	Closed, Completed		Aug 28, 2023 01:49:38 AM		Aug 29, 2023 05:11:14 AM		
Task Description	Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours		
Checked wiring all seems good, updated sender has no external guage. seems to be reading accurate	Articulated Rock Truck	Ken Cannon	Nick Vanderkooi	Aug 29, 2023 05:11:14 AM				
Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late	
77430	Truck has two.way radio issues. Sometimes.operator can not hear people talking to him.	Closed, Completed	Corrective	Sep 04, 2023 12:41:27 PM		Sep 04, 2023 09:20:36 PM		
Task Description	Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours		
	Articulated Rock Truck	Sebastian Cepeda - Brandt	Nick Vanderkooi	Sep 04, 2023 09:20:36 PM				
Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late	
77587	745C PM2 500 Service Hours	Closed, Completed	Preventive - Planned	Sep 07, 2023 02:57:17 PM	Sep 08, 2023 02:57:17 PM	Sep 07, 2023 03:01:01 PM	0	
Task Description	Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours		
Transmission Oil Filter - Inspect (Cut Filter and Record Findings.) Transmission Oil Filter Replace Transfer Gear Oil Sample - Obtain Torque Converter and Transmission Oil Sample - Obtain Steering System Oil Sample - Obtain Secondary Steering - Test Hoist System and Brake System Oil Sample - Obtain Fuel System Secondary Filter - Replace Engine Oil Filter Inspect (Cut Filter and Record Findings) Engine Oil and Filter - Change Engine Air Filter Secondary Element (Outer) - Replace Differential and Final Drive Oil Sample - Obtain Diff & Final Drive Oil Level - Check (note particulates on mag plug and indicate findings) Braking System - Test	Articulated Rock Truck	PMtech	PMtech	Sep 07, 2023 03:00:00 PM	2.00			
	Articulated Rock Truck	PMtech	PMtech	Sep 07, 2023 03:00:00 PM	2.00			
	Articulated Rock Truck	PMtech	PMtech	Sep 07, 2023 03:00:00 PM	2.00			
	Articulated Rock Truck	PMtech	PMtech	Sep 07, 2023 03:00:00 PM	2.00			
	Articulated Rock Truck	PMtech	PMtech	Sep 07, 2023 03:00:00 PM	2.00			
	Articulated Rock Truck	PMtech	PMtech	Sep 07, 2023 03:00:00 PM	2.00			
	Articulated Rock Truck	PMtech	PMtech	Sep 07, 2023 03:00:00 PM	2.00			
	Articulated Rock Truck	PMtech	PMtech	Sep 07, 2023 03:00:00 PM	2.00			
	Articulated Rock Truck	PMtech	PMtech	Sep 07, 2023 03:00:00 PM	2.00			
	Articulated Rock Truck	PMtech	PMtech	Sep 07, 2023 03:00:00 PM	2.00			
	Articulated Rock Truck	PMtech	PMtech	Sep 07, 2023 03:00:00 PM	2.00			
	Articulated Rock Truck	PMtech	PMtech	Sep 07, 2023 03:00:00 PM	2.00			
	Articulated Rock Truck	PMtech	PMtech	Sep 07, 2023 03:00:00 PM	2.00			
	Articulated Rock Truck	PMtech	PMtech	Sep 07, 2023 03:00:00 PM	2.00			

Brake Pads - Check	Articulated Rock Truck	PMtech					
Brake Accumulator (Service) - Check	Articulated Rock Truck	PMtech					
Fuel System Primary Filter - Replace	Articulated Rock Truck	PMtech					
				PMtech	Sep 07, 2023 03:00:00 PM		2.00
							22.00
<b>Work</b>	<b>Work Order Description</b>	<b>Status</b>	<b>Type</b>	<b>Date Created</b>	<b>Due Date</b>	<b>Date Completed</b>	<b>Days Late</b>
77589	745C PM3 1000 Service Hours	Closed, Completed	Preventive - Planned	Sep 07, 2023 02:57:17 PM	Sep 08, 2023 02:57:17 PM	Sep 07, 2023 02:59:52 PM	0
<b>Task Description</b>							
Brake Tank Strainer - Clean/Inspect/Replace	Articulated Rock Truck	PMtech	PMtech	Sep 07, 2023 02:59:00 PM			1.00
Transmission and Transfer Gear Breather - Replace	Articulated Rock Truck	PMtech	PMtech	Sep 07, 2023 02:59:00 PM			1.00
Transmission Clutch Calibrations - Complete	Articulated Rock Truck	PMtech					
Torque Converter, Transmission, and Transfer Gear Oil - Change	Articulated Rock Truck	PMtech	PMtech	Sep 07, 2023 02:59:00 PM			1.00
Rollover Protective Structure (ROPS) - Inspect	Articulated Rock Truck	PMtech					
Oscillating Hitch - Adjust	Articulated Rock Truck	PMtech					
Hydraulic Tank Strainer - Clean/Inspect/Replace	Articulated Rock Truck	PMtech	PMtech	Sep 07, 2023 02:59:00 PM			1.00
Hydraulic System Oil Filter Inspect (Cut Filter and Record Findings)	Articulated Rock Truck	PMtech					
Hydraulic System Oil Filter and Screen - Clean/Inspect/Replace	Articulated Rock Truck	PMtech	PMtech	Sep 07, 2023 02:59:00 PM			1.00
Fuel Tank Cap Filter - Replace	Articulated Rock Truck	PMtech	PMtech	Sep 07, 2023 02:59:00 PM			1.00
Cab Recirc Air Filter Element (Inner) - Replace	Articulated Rock Truck	PMtech	PMtech	Sep 07, 2023 02:59:00 PM			1.00
Brake Oil Filter - Replace	Articulated Rock Truck	PMtech	PMtech	Sep 07, 2023 02:59:00 PM			1.00
Battery or Battery Cable - Inspect/Replace	Articulated Rock Truck	PMtech					
							7.00
<b>Work</b>	<b>Work Order Description</b>	<b>Status</b>	<b>Type</b>	<b>Date Created</b>	<b>Due Date</b>	<b>Date Completed</b>	<b>Days Late</b>
78015	brake complaint.	Closed, Completed		Sep 15, 2023 06:45:53 AM		Sep 15, 2023 06:50:01 AM	
<b>Task Description</b>							
visual inspection. adjusted brake pressure. repaired back up camera. (found broken wire)	Articulated Rock Truck	Silas Angell - Wajax	Silas Angell - Wajax	Sep 14, 2023 06:54:00 AM			7.50
							7.50
<b>Work</b>	<b>Work Order Description</b>	<b>Status</b>	<b>Type</b>	<b>Date Created</b>	<b>Due Date</b>	<b>Date Completed</b>	<b>Days Late</b>
78106	Brake Service Fault Shows At Startup Of Rock Truck	Closed, Completed		Sep 16, 2023 07:19:04 PM		Sep 22, 2023 08:44:31 AM	
<b>Task Description</b>							
replaced front accumulator and check rears	Articulated Rock Truck	Dane Middlemiss - Wajax	Dane Middlemiss - Wajax				5.00
							5.00
<b>Work</b>	<b>Work Order Description</b>	<b>Status</b>	<b>Type</b>	<b>Date Created</b>	<b>Due Date</b>	<b>Date Completed</b>	<b>Days Late</b>
78309	Windshield washer fluid reservoir leaking * washer pumps ordered Sept 22/23	Closed, Completed		Sep 22, 2023 08:22:10 AM		Oct 01, 2023 11:24:00 AM	
<b>Task Description</b>							
Look into leaking windshield washer bottle, order parts.	Articulated Rock Truck	Trevor Bullock	Trevor Bullock	Sep 22, 2023 11:31:00 AM			2.00
-replaced pumps and seals in tank							
							2.00
<b>Work</b>	<b>Work Order Description</b>	<b>Status</b>	<b>Type</b>	<b>Date Created</b>	<b>Due Date</b>	<b>Date Completed</b>	<b>Days Late</b>
78445	Brakes on full when applied.	Closed, Completed		Sep 25, 2023 04:53:03 PM		Oct 02, 2023 01:06:00 PM	
<b>Task Description</b>							
received brake valve that was ordered by someone else--was unsure if front valve was bad or back valve--tried in front and made no difference--tried in back and still made no difference-brakes still grabbing..checked all accumulator pressures-all good -test drive truck and pedal seems a little weird and seems to be hard to push for first inch or so then it goes good and locks up the brakes on truck--possibly brake control valve issue--will check to see if we have one in stock -brake cooling oil is heavily contaminated -tested pressures threw brake control valve-pressure to front and back seem good but back seems to jump a bit off the start--drained contaminated fluid from brake tank and refilled with new fluid--bleed brakes--got operator to try truck--he says it was better then it was--gonna run truck for a bit to see if fresh fluid get threw system and flushes contaminated oil from lines etc back to tank and will flush tank again--if	Articulated Rock Truck	Trevor Bullock	Trevor Bullock				10.00

problem gets bad again will replace brake control valve

								10.00
Work	Work Order Description		Status	Type	Date Created	Due Date	Date Completed	Days Late
78466	DUPLICATE Brake issues		Closed, Incomplete		Sep 26, 2023 06:33:23 AM		Sep 26, 2023 07:30:01 AM	
	Task Description	Asset	Assigned To	Completed By	Date Completed		Est Hours	Spent Hours
		Articulated Rock Truck		Justin Kung	Sep 26, 2023 07:30:01 AM			
Work	Work Order Description		Status	Type	Date Created	Due Date	Date Completed	Days Late
78880	Small hydraulic leak, possibly a fitting		Closed, Completed		Oct 05, 2023 04:28:57 PM		Oct 06, 2023 08:55:00 AM	
	Task Description	Asset	Assigned To	Completed By	Date Completed		Est Hours	Spent Hours
	fitting loose on rear brake valve-tighten fitting	Articulated Rock Truck	Trevor Bullock	Trevor Bullock				2.00
Work	Work Order Description		Status	Type	Date Created	Due Date	Date Completed	Days Late
78960	Coolant Leak		Closed, Completed		Oct 07, 2023 11:34:36 AM		Oct 11, 2023 08:02:00 AM	
	Task Description	Asset	Assigned To	Completed By	Date Completed		Est Hours	Spent Hours
	replaced blown hose for transmission cooler undercab	Articulated Rock Truck		Dane Middlemiss - Wajax -				7.00
Work	Work Order Description		Status	Type	Date Created	Due Date	Date Completed	Days Late
79127	brake application lock-up issues		Closed, Completed	Corrective	Oct 12, 2023 06:14:29 AM		Nov 05, 2023 04:46:03 PM	
	Task Description	Asset	Assigned To	Completed By	Date Completed		Est Hours	Spent Hours
	brake valve was ordered by another mechanic...replaced brake valve Nov 10/23- Kory K- wajax	Articulated Rock Truck Articulated Rock Truck	Trevor Bullock Kory Kaesmodel - Wajax	Trevor Bullock Kory Kaesmodel - Wajax	Nov 10, 2023 09:11:00 AM			3.00 6.50
	brake issues. Parts arrived for unit that was diagnosed by another mechanic. Started removing brake valve had to clear for a blast. Finished removing brake valve and got pulled off to look at another unit quickly. Cleaned up for end of day. Train was blocking tracks had to wait for train to move before we could leave site.							
								9.50
Work	Work Order Description		Status	Type	Date Created	Due Date	Date Completed	Days Late
80547	No Berm Lights		Closed, Completed	Corrective	Nov 18, 2023 05:07:05 AM		Nov 28, 2023 07:11:00 AM	
	Task Description	Asset	Assigned To	Completed By	Date Completed		Est Hours	Spent Hours
	t/s lights not working--found wires not plugged in	Articulated Rock Truck	Trevor Bullock	Trevor Bullock				1.00
Work	Work Order Description		Status	Type	Date Created	Due Date	Date Completed	Days Late
80677	Fuel Gauge Broken		Closed, Completed	Corrective	Nov 22, 2023 05:01:53 AM		Dec 04, 2023 01:40:00 PM	
	Task Description	Asset	Assigned To	Completed By	Date Completed		Est Hours	Spent Hours
	t/s fuel gauge not working--check wiring--ground seems to be a little high resistance at Articulated Rock Truck times--install new ground wire	Articulated Rock Truck	Trevor Bullock	Trevor Bullock				2.00
Work	Work Order Description		Status	Type	Date Created	Due Date	Date Completed	Days Late
80736	Radio Mic sticks and hot mics occasionally. Priority level 3		Closed, Completed		Nov 24, 2023 04:58:38 AM		Nov 28, 2023 07:13:00 AM	
	Task Description	Asset	Assigned To	Completed By	Date Completed		Est Hours	Spent Hours
		Articulated Rock Truck	Trevor Bullock	Trevor Bullock				1.00
Work	Work Order Description		Status	Type	Date Created	Due Date	Date Completed	Days Late
								1.00

81111	Radio mic needs to be replaced	Closed, Completed	Dec 06, 2023 09:07:06 AM	Dec 06, 2023 02:44:51 PM	Est Hours	Spent Hours	
	<b>Task Description</b>	<b>Asset</b>	<b>Assigned To</b>	<b>Completed By</b>	<b>Date Completed</b>		
	fixed	Articulated Rock Truck	Trevor Bullock	Trevor Bullock		1.00	
						1.00	
Work	<b>Work Order Description</b>	<b>Status</b>	<b>Type</b>	<b>Date Created</b>	<b>Due Date</b>	<b>Date Completed</b>	<b>Days Late</b>
81317	Missing lens on rear blinker light	Closed, Completed		Dec 16, 2023 07:42:49 AM		Dec 16, 2023 02:36:37 PM	
	<b>Task Description</b>	<b>Asset</b>	<b>Assigned To</b>	<b>Completed By</b>	<b>Date Completed</b>	Est Hours	Spent Hours
		Articulated Rock Truck	Shopquest		Dec 16, 2023 02:36:37 PM		
Work	<b>Work Order Description</b>	<b>Status</b>	<b>Type</b>	<b>Date Created</b>	<b>Due Date</b>	<b>Date Completed</b>	<b>Days Late</b>
81547	leak	Closed, Completed		Jan 09, 2024 06:12:09 AM		Jan 14, 2024 06:05:00 AM	
	<b>Task Description</b>	<b>Asset</b>	<b>Assigned To</b>	<b>Completed By</b>	<b>Date Completed</b>	Est Hours	Spent Hours
	brake line hose loose on rear diff--tighted hose and fill hydraulic tank	Articulated Rock Truck	Trevor Bullock	Trevor Bullock			3.00
							3.00
Work	<b>Work Order Description</b>	<b>Status</b>	<b>Type</b>	<b>Date Created</b>	<b>Due Date</b>	<b>Date Completed</b>	<b>Days Late</b>
81617	break alarm	Closed, Completed		Jan 13, 2024 03:35:34 PM		Jan 16, 2024 06:02:00 AM	
	<b>Task Description</b>	<b>Asset</b>	<b>Assigned To</b>	<b>Completed By</b>	<b>Date Completed</b>	Est Hours	Spent Hours
	charge all accumulators	Articulated Rock Truck	Trevor Bullock	Trevor Bullock			3.00
							3.00
Work	<b>Work Order Description</b>	<b>Status</b>	<b>Type</b>	<b>Date Created</b>	<b>Due Date</b>	<b>Date Completed</b>	<b>Days Late</b>
81749	Brake alarm comes on when you press the peddle	Closed, Completed		Jan 25, 2024 09:11:10 AM		Jan 25, 2024 06:44:00 AM	
	<b>Task Description</b>	<b>Asset</b>	<b>Assigned To</b>	<b>Completed By</b>	<b>Date Completed</b>	Est Hours	Spent Hours
	checked accumulators--charged accumulators -lift cab check solenoids for damage etc	Articulated Rock Truck	Trevor Bullock	Trevor Bullock			9.00
							9.00
all brake test on pumps etc,case drain,standby pressure,margin pressure.,done for low brake pressure alarm--adjusted margin pressure/standby pressure on brake system a little higher then specs to stop to get proper operation							
put all hoses etc back on machine-and put cab back in place--							
-install and fix bent hood hinges--install hood actuator -hood broken several places--will try to patch hood the best i can --will continue hood work today							
--machine needs fuel cooler replaced							
Work	<b>Work Order Description</b>	<b>Status</b>	<b>Type</b>	<b>Date Created</b>	<b>Due Date</b>	<b>Date Completed</b>	<b>Days Late</b>
81797	Hood damage due to Wind	Closed, Completed		Jan 30, 2024 12:17:56 PM		Mar 10, 2024 11:00:35 AM	
	<b>Task Description</b>	<b>Asset</b>	<b>Assigned To</b>	<b>Completed By</b>	<b>Date Completed</b>	Est Hours	Spent Hours
	Ordered new hood actuator.	Articulated Rock Truck					
	Removed old fuel cooler and installed new. Cleaned up around unit to begin hood	Articulated Rock Truck		Hayden Balsiger	Mar 06, 2024 06:44:00 AM		2.00
	repairs, parts showed up for another job so packed up and switched jobs.						
	Replaced fuel line, replaced broken plug on hood actuator as wiring was left loose and Articulated Rock Truck			Hayden Balsiger	Mar 07, 2024 06:39:00 AM		2.50
	damaged connector, continued on hood repairs.						
							4.50
Work	<b>Work Order Description</b>	<b>Status</b>	<b>Type</b>	<b>Date Created</b>	<b>Due Date</b>	<b>Date Completed</b>	<b>Days Late</b>
82328	hub leak	Closed, Completed	Corrective	Mar 23, 2024 05:19:55 AM		Mar 24, 2024 05:49:00 AM	
	<b>Task Description</b>	<b>Asset</b>	<b>Assigned To</b>	<b>Completed By</b>	<b>Date Completed</b>	Est Hours	Spent Hours
	leak at inside of front left rim -diff vent line plugged with dirt and grease--cleaned vent and leak is good	Articulated Rock Truck	Trevor Bullock	Trevor Bullock			2.00
							2.00

Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late
82398	Operator complaining of a burning smell inside the cab once the machine gets hot. Possibly Exhaust leak or possibly residuals dripping on the turbo/Exhaust system.	Closed, Completed		Mar 31, 2024 07:02:25 AM		Mar 31, 2024 06:22:00 AM	
	<b>Task Description</b>	<b>Asset</b>	<b>Assigned To</b>	<b>Completed By</b>	<b>Date Completed</b>		<b>Est Hours</b>
	checked over, topped up fluids. Cleaned mud off exhaust that looked to have oil residue. Ran regen to get hot to see if smell was present, seems ok. Grabbed operator to confirm.	Articulated Rock Truck		Hayden Balsiger			2.00
							2.00
Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late
82434	Left front wheel seal leaking.	Closed, Incomplete		Apr 04, 2024 06:48:23 AM		Apr 13, 2024 12:36:13 PM	
	<b>Task Description</b>	<b>Asset</b>	<b>Assigned To</b>	<b>Completed By</b>	<b>Date Completed</b>		<b>Est Hours</b>
	final drive gone--another work order opened	Articulated Rock Truck		Trevor Bullock	Apr 13, 2024 12:36:13 PM		
Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late
82528	Brake/hydraulic issue	Closed, Completed	Corrective	Apr 12, 2024 08:44:18 AM		May 09, 2024 12:51:00 PM	
	<b>Task Description</b>	<b>Asset</b>	<b>Assigned To</b>	<b>Completed By</b>	<b>Date Completed</b>		<b>Est Hours</b>
	brake tank over filling with oil...transferring oil from hydraulic tank to brake cooling tank--one of the final drive brake assembly bypassing --cap off each brake assembly one at a time until find final drive that is bypassing was found -left front final drive needs rebuilding --will need to be removed and rebuilt  ---removed tire and removed final drive--will bring final drive to mainsite tomorrow to get rebuilt  --install rebuilt hub assembly on truck--install tire--fill diff and final drive -drain brake cooling tank-refill with new oil--take truck for test drive--truck has retorque tag put in truck for retorque on left front tire after 10 hours CHRIS WISEMAN APRIL 18/2024 -DISSEMBLE BRAKE ASSY . ORDER PARTS START CLEANING PARTS	Articulated Rock Truck	Trevor Bullock	Trevor Bullock			18.00
							5.00
							23.00
Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late
82794	retorque required	Closed, Completed	Corrective	May 12, 2024 04:28:33 PM		May 12, 2024 04:37:00 PM	
	<b>Task Description</b>	<b>Asset</b>	<b>Assigned To</b>	<b>Completed By</b>	<b>Date Completed</b>		<b>Est Hours</b>
	retorque left front tire	Articulated Rock Truck	Trevor Bullock	Trevor Bullock			2.00
							2.00
Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late
82904	Coolant leak	Closed, Completed		May 23, 2024 10:02:24 AM		May 25, 2024 06:15:03 AM	
	<b>Task Description</b>	<b>Asset</b>	<b>Assigned To</b>	<b>Completed By</b>	<b>Date Completed</b>		<b>Est Hours</b>
	Went to unit, found blown heater hose. Spliced repair, filled with coolant. Difficulties purging air from system before startup. Got air out, ran to temp, no leaks.  Unit blew another hose at end of day. Will address tomorrow. Went to machine, removed blown hose and replaced. Found another hose chaffed and Articulated Rock Truck old, replaced. Filled coolant, burped system, ran to temp.	Articulated Rock Truck		Hayden Balsiger	May 24, 2024 06:16:00 AM		4.00
							4.00
Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late
82923	AC not working	Closed, Completed		May 25, 2024 01:58:07 PM		May 27, 2024 06:22:00 AM	
	<b>Task Description</b>	<b>Asset</b>	<b>Assigned To</b>	<b>Completed By</b>	<b>Date Completed</b>		<b>Est Hours</b>
	Recover, vacuum test, charge 4 lbs, open taps to confirm water valve is ok, blows coldArticulated Rock Truck			Hayden Balsiger			2.00
							2.00
Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late
82990	No bracket for fire extinguisher	Closed, Completed	Corrective	Jun 02, 2024		Jun 16, 2024 11:	

		Status		Type		Date Created	Due Date
Task Description	Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours	
installed by donny	Articulated Rock Truck	Trevor Bullock	Trevor Bullock	Jun 16, 2024 11:25:51 AM			
<b>Work Order Description</b>							
83013 hood stuck open and loose		Closed, Completed	Corrective	Jun 04, 2024 10:28:27 AM			
<b>Task Description</b>							
hood came off hinges-fixed hood and put back on truck-made a make shift front grill to protect coolers	Articulated Rock Truck	Trevor Bullock	Trevor Bullock				5.00
							5.00
<b>Work Order Description</b>							
83021 Berm lights not working		Closed, Completed		Jun 05, 2024 04:41:29 PM			
<b>Task Description</b>							
light unplugged	Articulated Rock Truck	Trevor Bullock	Trevor Bullock				1.00
							1.00
<b>Work Order Description</b>							
83079 needs right side berm light		Closed, Completed	Corrective	Jun 11, 2024 03:50:25 PM			
<b>Task Description</b>							
installed berm light	Articulated Rock Truck	Trevor Bullock	Trevor Bullock				1.00
							1.00
<b>Work Order Description</b>							
83081 19-45-044 Truck is Having Brake Problems Again And Retarter Problems		Closed, Completed	Corrective	Jun 11, 2024 10:05:07 PM			
<b>Task Description</b>							
all brake valves-all pump adjustments-all brake hubs have been rebuilt	Articulated Rock Truck	Trevor Bullock	Trevor Bullock				3.00
- operator is finding problems with every machine that he has been put on since rehired last week when other operator are not finding same issues							
- another mechanic can look at truck to see if they can find any issues that i can not find							
dont brake tank flush--oil turned black again --test drove truck							
-A frame bearing getting bad -will order parts							
							3.00
<b>Work Order Description</b>							
83157 front A frame bearing needs be changed--parts in seacan		Closed, Completed	Corrective	Jun 17, 2024 06:12:43 AM			
<b>Task Description</b>							
Disassembled, removed bearing and inspected bore. Slightly worn, should be ok without machining. Cleaned grease etc.	Articulated Rock Truck		Hayden Balsiger	Jun 20, 2024 05:53:00 AM			2.50
Replaced bearing, used sleeve retainer in bore. Measured cap and shoulder distance, made up shim to take up wear. Reassembled and let retainer cure. Torqued retaining bolts to spec.							
Next day after machine ran, rechecked-still tight. Retorqued retainer bolts.							
							2.50
<b>Work Order Description</b>							
83259 Coolant leak		Closed, Completed		Jun 27, 2024 07:22:08 AM			
<b>Task Description</b>							
Replaced hump hoses, clamps not oriented correctly making very difficult to access. Filled with coolant, burped and ran to temp.	Articulated Rock Truck		Hayden Balsiger				
<b>Work Order Description</b>							

83267	19-45-044 Down With Blown Tire	Closed, Completed	Jun 27, 2024 07:46:23 PM	Jun 30, 2024 06:37:55 AM	Est Hours	Spent Hours
	<b>Task Description</b>	<b>Asset</b>	<b>Assigned To</b>	<b>Completed By</b>	<b>Date Completed</b>	
		Articulated Rock Truck		Hayden Balsiger	Jun 30, 2024 06:37:55 AM	
Work	<b>Work Order Description</b>	<b>Status</b>	<b>Type</b>	<b>Date Created</b>	<b>Due Date</b>	<b>Date Completed</b>
83362	Brakes do not respond right away	Closed, Incomplete		Jul 05, 2024 06:15:03 AM		Jul 09, 2024 03:34:13 PM
	<b>Task Description</b>	<b>Asset</b>	<b>Assigned To</b>	<b>Completed By</b>	<b>Date Completed</b>	
		Articulated Rock Truck		Trevor Bullock	Jul 09, 2024 03:34:13 PM	
Work	<b>Work Order Description</b>	<b>Status</b>	<b>Type</b>	<b>Date Created</b>	<b>Due Date</b>	<b>Date Completed</b>
83395	Brake issue.	Closed, Completed	Corrective	Jul 08, 2024 09:30:32 AM		Jul 10, 2024 12:53:00 PM
	<b>Task Description</b>	<b>Asset</b>	<b>Assigned To</b>	<b>Completed By</b>	<b>Date Completed</b>	
		Articulated Rock Truck	Trevor Bullock	Trevor Bullock		4.00
	-truck has brake cooling oil turned black again--ongoing issue and brakes touchy drain brake cooling tank again and refill with new fluid					
	-will run truck for couple hours then check temperatures of each brake /final drive assembly to see if one is hotter then the rest--possible brake drag					
	-checked brake hubs-temps good					
	-gonna try new from accumulator as having trouble knowing if it sealed properly because of bad threads					
	-truck is currently working at operators discretion					
						4.00
Work	<b>Work Order Description</b>	<b>Status</b>	<b>Type</b>	<b>Date Created</b>	<b>Due Date</b>	<b>Date Completed</b>
83453	Headlights not working	Closed, Completed	Corrective	Jul 13, 2024 11:04:25 AM		Jul 14, 2024 08:32:00 AM
	<b>Task Description</b>	<b>Asset</b>	<b>Assigned To</b>	<b>Completed By</b>	<b>Date Completed</b>	
	fix head lights	Articulated Rock Truck	Trevor Bullock	Trevor Bullock		1.00
						1.00
Work	<b>Work Order Description</b>	<b>Status</b>	<b>Type</b>	<b>Date Created</b>	<b>Due Date</b>	<b>Date Completed</b>
83502	High hydraulic temperature	Closed, Completed		Jul 17, 2024 04:48:11 PM		Jul 18, 2024 06:42:23 AM
	<b>Task Description</b>	<b>Asset</b>	<b>Assigned To</b>	<b>Completed By</b>	<b>Date Completed</b>	
	Very hot out. Blew out coolers	Articulated Rock Truck		Hayden Balsiger	Jul 18, 2024 06:42:23 AM	
Work	<b>Work Order Description</b>	<b>Status</b>	<b>Type</b>	<b>Date Created</b>	<b>Due Date</b>	<b>Date Completed</b>
83625	Radio not working very well	Closed, Completed	Corrective	Jul 30, 2024 04:19:08 PM		Aug 01, 2024 08:03:00 AM
	<b>Task Description</b>	<b>Asset</b>	<b>Assigned To</b>	<b>Completed By</b>	<b>Date Completed</b>	
	Install new antenna end	Articulated Rock Truck	Trevor Bullock	Trevor Bullock		1.00
						1.00

125.16 506.66