

FH34-2.



Unit number: 22-248 Work order Number: 25060522248

Start DATE	June.5th/2025	Finish DATE	June.5th/2025	Journman required YES or NO if so who	No	Y M D and unit number	Engineer approval required YES or NO and who is it	No	Lead Tech assigned	Ryan M
------------	---------------	-------------	---------------	---------------------------------------	----	-----------------------	--	----	--------------------	--------

Detailed discription of work completed: Grease Trailer.

Parts required			Sub Total of Parts and Labour			Total of Parts and labour			
Discription of Part	Part purchased (P) Instock (IN) Used (U)	Approx cost of part	Hours	Total labour costs based on 225.00/hr This should be the number of hours x 225.00/hr	Total Labour for job				
Shop Supplies	IN	\$11.25	0.50		\$112.50				
		\$11.25	0.5		\$112.50	\$123.75			
						Taxes N/A Inhouse use only			
Authorized by						Ross McLeod			



278 Sherwood Road
R.M. of Sherwood, SK
S4K 0A8
Tel: 306-522-2211
Fax: 306-522-9860

TRUCK & TRAILER SERVICE REPORT

Date: June 5/2025

Driver: Ryan M

Trailer: 22-248

Truck: _____

NOTE: DO YOU FEEL THIS IS AN OUT OF SERVICE CONCERN. IF SO PLEASE DISCUSS WITH BOYD OR RUSS SAP. THIS UNIT MAY NEED TO BE PLACED OUT OF SERVICE UNTIL REPAIRS CAN BE COMPLETED.

IF NOT AN OUT OF SERVICE ISSUE, PLEASE HAND THIS TO LANDON IN THE SHOP. IF AFTER HOURS, LEAVE IT IN THE BILL BASKET IN DRIVERS ROOM.

Repairs or service required:

greased trailer

- 1 Tube of grease

- .50 hours.

ATTACH COPY TO WORK ORDER AND PLACE IN UNIT OR TRAILER FILE WHEN COMPLETE.

Richards Transport Work Order #_24030722248_

Y M D unit number

Start DATE	March 7/24	Finish DATE	March 7/24	Unit #	22-248	Journman required YES or NO if so who	NO	Engineer approval required YES or NO and who is it	NO	Lead Tech assigned	Alex
------------	------------	-------------	------------	--------	--------	---------------------------------------	----	--	----	--------------------	------

Detailed discription of work completed: Grease, Check lights. Replace Registration Holder. Replace 10' 1/2" hydraulic hose, rear bed. Replace 8' 3/8" hydraulic hose, front neck. Topped up hydraulic fluid.

Parts required			Sub Total of Parts and Labour			Total of Parts and labour			
Discription of Part	Part purchased (PI) Instock (IN) Used (U)	Approx cost of part	Hours	Total labour costs based on 125.00/hr	Total labour for job				
Shop Supplies	IN	\$200.00	5.00	This should be the number of hours x 125.00/hr	\$625.00				
		\$200.00	5.00	@125.00 hr		825.00			
		PARTS TOTAL	TOTAL HOURS	Rate per hour 125.00	Tost cost hours	Total of Parts and labour			

Taxes N/A inhouse
use only

Authorized by

Boyd Richards

Date: March 7/24

Unit#: 22-248

Engine Hours: N/A

Safety Due: Feb/24

Mileage: N/A

Date Completed: March 7/24



QMF 124

Version 2

4-Oct-23

Quantity		Parts Used	Repairs to be Completed	Time	Initial
1	1	Tube Grease	- Service / Grease / check Lights	1	W/NG
2	1	97960	- Replace Registration Holder	.5	W
3	1	KP81356 / KP81307	- Replace 10' 1/2" Hydraulic Hose / Rear Bed	2	W/NG
4	2	KP81354	- Replace 8' 3/8" Hydraulic Hose / Front Neck	1.5	W
5	1	SL Hydraulic Fluid	- Topped Up Hydraulic Fluid	.25	W
6					
7					
8					

Technician Notes: