

FOUNTAIN TIRE (WHITECOURT) CO. LTD.

5707 50 AVE, PO BOX 1537 WHITECOURT AB T7S 1P4

Invoice

Order Number: Service Contact:

086SWO00169337

SHAWN V JAMES

Phone: 780.778.4401 Fax 780.778.2514 F086@fountaintire.com

889335089RT0001

BOX 97 5807 51 AVE WHITECOURT AB T7S 1N3

Date: Invoice:

16/06/2025 0861146385

PO#:

AirMiles #:

Terms of payment Net_30

Bill to Customer

086C00013128

NEWGEN ENERGY SERVICES CORP

BOX 97 5807 51 AVE WHITECOURT AB T7S 1N3

Ship to Customer: 086C00013128

Year:

2020 **GMC TRUCK**

Make: Model:

SIERRA 2500HD PICKUP

Design:

Engine: V8-403 6.6L Dsl

License: CNN1441, AB Colour: WHITE

Vin:

1GT49REY6LF129386 Mileage: 396885

Hours: 0

į	·	.			
tem number	Item description	Qty	Unit price	Total	
hassis and S	Steering Parts and Service				
1:303-NSA	R REFLEX	2.00	\$216.14	\$432.29	
M1447-NSA	F REFLEX SHOCK	2.00	\$271.80	\$543.60	
66-F-R-2874	AIR RIDE KIT	1.00	\$1,740,00	\$1.740.00	
≱ H <u>L</u>	Remove & Replace Rear Shock Absorber - Rear, Both	1.00	\$145.00	\$145.00	
≱⊣∟	Remove & Install or Remove & Replace Front Shock &/Or Strut Assembly - Both	1.60	\$145.00	\$232.00	
lision and Mi	scellaneous Parts and Service		********	V202.00	
E_	Miscellaneous - INSTALL WIRELESS AIR BAG KIT	6.00	\$145.00	\$870.00	
Mher Miscella	ineous Items	0.00	Q140 .00	4070.00	
p -OP	Shop Supplies	1.00	\$62.35	\$62.35	

NEWGEN ENERGY SERVICES CORP

bese parts and services were recommended for replacement or repair

pr. Description	Qty	Unit price	Net amount
rake Pads	1 00	\$268.92	\$268.92
lerrove & Replace Brake Shoes	1.00	\$145.00	\$145.00
		Sub Total:	5413.92

⁻⁻ s estimate is valid for 30 days and excludes sales taxes

& Miles:

0

Invoice comment

PASTALLED AIR BAGS AND COMPRESSOR, REPLACED THE FRONT AND REAR SHOCKS

1 accrowledge: (1) receipt of goods and senicos; and (2) Fountain Tire may conduct a registry search to verify the VIN on my vehicle if required for screens on unpaid invoices related to my vehicle.

The customer is to ensure all wheel lugs are re-torqued by a qualified technician before the vehicle has travelled 100 kilometers

Parts:	\$2,715.89
Services:	\$1,309.35
Sub Total:	\$4,025.24
GST:	\$201.26
Total: (CAD)	\$4 226 50

Pay type: AR \$4,226.50

Eartia - Tire is committed to protecting your personal information. Please refer to our Privacy Commitment at www.fountaintire.com. The personal information Bedes by Fountain Tird will be stored in Canada or in the United States for the purposes set out in our Privacy Code, and will be subject to the laws of the Eact on -in which it is stored.

Page

1 of 1



FAX: 780-778-3398

WWW.SMYLCHEV.COM

INVOICE ORIGINAL

Work Order #242852

Newgen Energy Services Corp.

March 04, 2025 Svc.Adv Hoff, Blaine

(780) 778-1055 Cust.Ph.

Tag#

Page 1 of 2

03/04/2025 17:02:52

					03/04/2	2025 17:02:52	
To: Newgen F	nergy Services Corp	,	Year:	2020 Veh ld: 50148	Unit #: T20	032	
_			Make:	GMC		License #:	
Box 97			Model	: Sierra Denali 4WD	Crew CA	Odo. In: 378	5,132
			Colou	r: ONYX BLACK		Odo. Out:	
Whitecou	ırt A	В	- 11	#: 1GT49REY6LF129		t Service:	
T7S 1N3			11	n: 03/04/2025	In Se	rvice Date: 11/	08/2019
			Out:			Cases: 3	
				/ar Total"Plus" - 48/160			
			Promi	sed Time: 00/00/0000 (00:00:00 AM	Call When F	Ready: No
ase: 1 LUBE (OIL FILTERIncludes Multi	Point He	ealth Chec	k (LUBE OIL FILTER)			
Quanti	ty Description/Correction				Retail	Price	Total
	00 12737081 - FILTER ASM	Л-OIL (E	Extra		\$12.27	\$12.27	\$12.27
	Item)	`			•	•	•
9.9	50 88865794 - Oil (Extra Ite	m)			\$6.30	\$6.30	\$59.85
						\$30.00	\$30.00
• Te Misc \$0.00	ch Comments: Perform lube		filter serv \$72.12	Prepaid Parts Amt:	\$0.00	Case Total:	\$102.12
			*. = =				***************************************
ase: 2 Replace	e fuel filter						
Quanti	ty Description/Correction				Retail	Price	Total
	00 13539108 - Filter ki				\$75.94		\$75.94
					Ψ10.01	\$87.50	\$87.50
	place fuel filter ch Comments: Replaced fue	el filter				ψον.σσ	ψ07.00
						\$9.63	\$9.63
• Mis	scellaneous						
• Mis Misc \$9.63	scellaneous Labour \$87.50	Parts	\$75.94	Prepaid Parts Amt:	\$0.00	Case Total:	\$173.07

Price Total \$50.00 \$50.00

Added Operation: Rotate Tires

Tech Comments: Performed tire rotation



FAX: 780-778-3398 WWW.SMYLCHEV.COM **INVOICE ORIGINAL Work Order** #242852 Newgen Energy Services Corp.

March 04, 2025 Svc.Adv Hoff, Blaine (780) 778-1055

Tag#

Cust.Ph.

Page 2 of 2 03/04/2025 17:02:53

\$5.50 \$5.50

 Miscellaneous Misc \$5.50 Labour \$50.00 Parts \$0.00 Prepaid Parts Amt: \$0.00 **Case Total:** \$55.50 \$0.00

	03/04/2025 Date Signature		Payment Type	Total:	\$347.22
Т				Tax Adjustment:	\$0.00
υ	Shop supplies are based on 11% of the labour total to a max	imum of \$25.00.	G/HST Reg # 104897806	PST:	\$0.00
0		·	Expiry Date: P/O#:	Sub Total: G/HST:	\$330.69 \$16.53
	Indebtedness is hereby acknowledged for the "Total Charge owing to repairs, parts & accessories described Warranty on parts and labour is 3 years or 60,000km's whi parts. Some OEM powertrain components may have a	in this work order. chever occur first on OEM 5 year or 160,000km's	Currency: Payment Ref:	Labour: Parts: Misc:	\$167.50 \$148.06 \$15.13



SMYL CHEVROLET BUICK GMC LTD. 3520 KEPLER ST. WHITECOURT, AB T7S 0B5 PHONE: 780-778-2202 FAX: 780-778-3398

WWW.SMYLCHEV.COM

Work Order
Technician Copy
#242852
Newgen Energy Services Corp.
March 04, 2025
Svc. Adv. Hoff, Blaine

Page 1 of 2 03/04/2025 14:38:27

TAG#

< '	()	=
2)

Newgen Energy S	ervices Corp.	(M) 780-778-1055		Veh ID: 50148 VII	N: 1GT49REY6LF129386	
Box 97		(W)		Year/Make/Model: 2020	GMC Sierra Denali 4WD Crew CA	
Whitecourt	AB	(C) 780-778-1720	1.00	Ext Colour: Black	Engine: 6.6L V8	
T7S 1N3	\$10 ft 200000.	P. Carlotte		License Plate:	Unit #: T20032	
Email:sloil@telus	planet.net			Odometer In: 375132	In Service Date: 11/08/2019	
ID: 35917				Service Contract: Total"	Plus"	
Date In: 03/04/2025 14:37:42 Promised:			Contract #:			
SC: NT Appointm	nent: Yes	No		Exp Date: 11/08/2023	Exp Mileage: 160000 K	

Service Hist	ory							
Date	Repair	Order	Mileage	Advisor	Technician	Туре	LOP Code	Description
2025-02-05	242194		368693	McCaffrey, Christo	4543	1		Diagnose and report for service emission MSG is on the DIC
2025-02-03	242108		367059	Hoff, Blaine	16186	С		Diagnose and report for service emissions msg on the DIC -
I hereby authorize the repair work herein set forth to be done along with the necessary material and agree that to the extent permitted by law, you are not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. Until payment in full of the within account, thereby acknowledge the existence of a repair lie in in favour of the within dealer on the vehicle described herein in respect of the material supplied and services rendered under this work order for the full amount charged therefor. I further acknowledge that the said lien shall continue in force at all times, whether the vehicle is in my possession of the dealer, until the within account is paid in full. While the vehicle is in my possession it shall at all times be subject to repossession on demand by the dealer until the within account is paid in full. **COMPUTER PROGRAMS** I understand that repair work may require the installation of computer programs on the vehicle's computer systems or the installation of updates or upgrades to previously installed computer programs. I authorize you to make such installations as part of the repair work. I understand that, in some instances, the computer programs or updates or upgrades to be installed may lip collect personal information (as described in the applicable privacy statement or as separately disclosed), or (iii) cause a vehicle computer system to communicate with GMCL servers automatically to collect information about vehicle system status, identify if updates or upgrades are available or to deliver updates or upgrades. I further understand that I may withdraw my consent to Software updates. For more information, or for								
assistance in disa	bling or ren			nge in certain circumstan				
Estimate Requi	_	」Yes □ Cash	☐ No ☐ Credit (3				
Parts Returned	_	Yes	☐ No	Jaro		х		Application of the state of the
1 414 114	[
Case #1	Sub	. Туре	: Custom	er Pay LOP C	ode:		Labou	r Rate:175.00
15/32	FILTER	Inclu C B	ides Mult	i Point Health C	heck (LUBI	E OIL	FILTER)	Est Hrs:0.50 Rec Hrs:
Added Ope	eration:		No E	ate/Time Added	l:		Mana	agement Approval:



WHITECOURT, AB T7S 0B5 PHONE: 780-778-2202

FAX: 780-778-3398

WWW.SMYLCHEV.COM

Work Order
Technician Copy
#242852
Newgen Energy Services Corp.
March 04, 2025
Svc. Adv. Hoff, Blaine
TAG #

Page 2 of 2 03/04/2025 14:38:27

Case #2 Sub	. Type: Customer Pay	LOP Code:	Labo	our Rate:175.00				
Case Description Replace fuel filter					Est Hrs:0.50 Rec Hrs:			
Added Operation:	No Date/Tim	e Added:	Ma	anagement Approv	al <u>:</u>			
	INSTALL COMPUTER PROGRAMS AND ALL AVAILABLE UPDATES OR UPGRADES TO VEHICLE COMPUTER PROGRAMS (IN ACCORDANCE WITH GENERAL MOTORS OF CANADA LIMITED ISSUED BULLETINS)							
±13	ROTATO	LC THE	IRES 8 +0 0 to ved	real of 140lbs	BREC			

Box 1772 Whitecourt, Alberta T7S 1P5 Phone: 780-778-0942 Division of JVC Services Ltd.

24895

Sold To: NEW GEN

Address: _				
h	KE	AB		11777.22
QUANTITY		DESCRIPTION	PRICE PER UNIT	AMOUNT
1	DI	1 2500 6TY WINDSHIRLD		575
				4
		TT and and		
	UN	TO BOK DENTIFE		
	362			
-		49-00		
	-,	SUBTOTAL		575 3
		842485120 G.S.T.		287
	2% Interes	est on Balance over 30 days		6037



FAX: 780-778-3398

WWW.SMYLCHEV.COM

INVOICE ORIGINAL **Work Order**

#239328

Newgen Energy Services Corp.

October 09, 2024

Svc.Adv McCaffrey, Christopl Cust.Ph. (780) 778-1055

Tag#

Page 1 of 2 11/07/2024 16:23:11

To: Newgen Energy Se	rvices Corp.	Year:	2022 Veh Id: 52977 Unit #: T22014		
_	-	Make:	GMC	License #:	
Box 97		Model:	Sierra 3500 4WD Crew	Cab Odo. In: 276,811	
		Colour:	SUMMIT WHITE	Odo. Out:	
Whitecourt	AB	V.I.N.#:	1GT49TEY4NF140726	Next Service:	
T7S 1N3		Date In:	10/09/2024	In Service Date: 10/12/2021	
		Out:	11/07/2024 16:19	Cases: 3	
		Ext. Wa	r (mo/) - D: \$0.00	R/Lab. Rate 165.00	
		Promise	d Time: 00/00/0000 00:00):00 AM Call When Ready: No	

Case: 1 Repair for the Passenger rear hubcap is missing

Quantity Description/Correction

Price Total

Repair for the Passenger rear hubcap is missing.

Tech Comments: Parts ordered

Misc \$0.00

Labour \$0.00

Parts \$0.00

Prepaid Parts Amt:

\$0.00

Case Total:

\$0.00

Case: 2 Diagnose and report for SES light is on-See History

Quantity Description/Correction

1.00 12686811 - Fuel Valve

Retail \$317.48 Price Total

\$317.48 \$317.48

\$1,435.50 \$1,435.50

Diagnose and report for SES light is on--See History

• Tech Comments: Checked for DTC's, P1089/ Found faulty fuel pressure regulator 2. Replaced the fuel pressure regulator and cleared DTC's

Miscellaneous

\$25.00

\$25.00

Misc \$25.00

Labour \$1,435.50

Parts \$317.48 Prepaid Parts Amt: \$0.00

Case Total: \$1,777.98

Case: 3 Added Operation: LUBE OIL FILTER-Includes Multi Point Health Check (LUBE OIL FILTER)

- Tech Comments: Perfromed a lube oil and filter serivce

--Replaced the engine air filter

Quantity Description/Correction

1.00 19385578 - Filter (Extra Item)

9.50 88865794 - Oil (Extra Item)

Retail \$21.83

Price \$21.83

\$6.30

\$21.83 \$59.85

Total

\$6.30



WHITECOURT, AB T7S 0B5

PHONE: 780-778-2202 FAX: 780-778-3398

WWW.SMYLCHEV.COM

1.00 85614334 - ELEMENT-A/CL (Extra Item)

INVOICE ORIGINAL **Work Order** #239328

Newgen Energy Services Corp. October 09, 2024

Svc.Adv McCaffrey, Christopl (780) 778-1055 Cust.Ph.

Tag#

Page 2 of 2

11/07/2024 16:23:11

\$80.11 \$80.11 \$80.11

> \$30.00 \$30.00

• Added Operation: LUBE OIL FILTER--Includes Multi Point Health Check (LUBE OIL FILTER)

Tech Comments: Perfromed a lube oil and filter serivce

--Replaced the engine air filter

Misc \$0.00

Labour \$30.00

Parts \$161.79 Prepaid Parts Amt: \$0.00

Case Total:

\$191.79

\$0.00

Notes

- The following extended warranty plan(s) are attached to this vehicle: Total"Plus", Exp. Date: 11/08/2023, Exp. Milage: 160000, Deduct. Amt: \$200.00.

O U T	owing to repairs, pa Warranty on parts and la parts. Some OEM powe whichever occur first. Use warranty.	cknowledged for the "Total Charges" being all or the balance this & accessories described in this work order. bour is 3 years or 60,000km's whichever occur first on OEM artrain components may have a 5 year or 160,000km's diparts and aftermarket components do not have any labour on 11% of the labour total to a maximum of \$25.00.	Currency: Payment Ref: Expiry Date: P/O#: G/HST Reg # 104897806	Labour: Parts: Misc: Sub Total: G/HST: PST: Tax Adjustment:	\$1,465.50 \$479.27 \$25.00 \$1,969.77 \$98.49 \$0.00 \$0.00
	Date	Signature	Payment Type	Total:	\$2,068.26

HS-02



SMYL CHEVROLET BUICK GMC LTD. 3520 KEPLER ST.

WHITECOURT, AB T7S 0B5

PHONE: 780-778-2202 FAX: 780-778-3398

WWW.SMYLCHEV.COM

INVOICE ORIGINAL Work Order #229804

Newgen Energy Services Corp.

\$0.00

September 06, 2023 Svc.Adv Stieb, Chad Cust.Ph. (780) 778-1055

Tag#

Page 1 of 2

09/06/2023 09:51:13

				00/00/2020 00:01:10
To: Newgen Energy Services Corp.		Year:	2020 Veh ld: 50148	Jnit #: T20032
	•	Make:	GMC	License #:
Box 97		Model:	Sierra Denali 4WD Cre	ew CA Odo. In: 261,062
1		Colour:	ONYX BLACK	Odo. Out:
Whitecourt	AB	V.I.N.#:	1GT49REY6LF129386	6 Next Service:
T7S 1N3		Date In:	09/06/2023	In Service Date: 11/08/2019
		Out:	09/06/2023 09:43	Cases: 1
		Ext. Wa	r Total"Plus" - 48/160 - ((48 m
				00:00 PM Call When Ready: No
		il i		•

Case: 1	LUBE OIL FILTER	
---------	-----------------	--

Quantity	Description/Correction	Retail	Price	Total
1.00	19419485 - FILTER ASM,OIL (Extra	\$16.20	\$16.20	\$16.20
9.50	88865794 - Oil (Extra Item)	\$6.30	\$6.30	\$59.85
1.00	85614334 - ELEMENT-A/CL (Extra Item)	\$77.22	\$77.22	\$77.22
1.00	13508023 - FILTER-PASS COMPT AIR (Extra Item)	\$45.62	\$45.62	\$45.62
1.00	13500812 - Bulb (Extra Item)	\$6.44	\$6.44	\$6.44
			\$20.00	\$20.00

LUBE OIL FILTER•

[•] Tech Comments: Performed LOF. Replaced air and cabin filters. Replaced driver side license plate light bulb

Misc	\$0.00	Labour \$20.00	Parts	\$205.33	Prepaid Parts Amt:	\$0.00	Case Total:	\$225.33

Notes

⁻ The following extended warranty plan(s) are attached to this vehicle: Total"Plus", Exp. Date: 11/08/2023, Exp. Milage: 160000, Deduct. Amt: \$200.00.



SMYL CHEVROLET BUICK GMC LTD. 3520 KEPLER ST. SMY WHITECOURT, AB T7S 0B5 PHONE: 780-778-2202 FAX: 780-778-3398 **WWW.SMYLCHEV.COM**

INVOICE ORIGINAL Work Order #229804 **Newgen Energy Services Corp. September 06, 2023** Svc.Adv Stieb, Chad Cust.Ph. (780) 778-1055 Tag# Page 2 of 2

09/06/2023 09:51:14

	09/06/2023 Date Signature	Payment Type	Total:	\$236.59
			Tax Adjustment:	\$0.00
lu		G/HST Reg # 104897806	PST:	\$0.00
ľ		P/O#:	G/HST:	\$11.26
lc		Expiry Date:	Sub Total:	\$225.33
ı		Payment Ref:	Misc:	\$0.00
ı	owing to repairs, parts & accessories described in this work order.		Parts:	\$205.33
Г	Indebtedness is hereby acknowledged for the "Total Charges" being all or the balance	Currency:	Labour:	\$20.00



WHITECOURT, AB T7S 0B5

PHONE: 780-778-2202 FAX: 780-778-3398

AB

WWW.SMYLCHEV.COM

INVOICE ORIGINAL Work Order #214578

Roshan Property Managemen October 20, 2021

Svc.Adv Stieb, Chad Cust.Ph. (780) 778-1055

Tag#

Page 1 of 2 11/02/2021 12:10:05

To: Roshan Property Management Ltd.

Box 988

Whitecourt

T7S 1N9

Newgen Energy Services Cc Bill-To:

Year: 2020 Veh Id: 50148 Unit #: T20032

Make: **GMC**

Model: Sierra Denali 4WD Crew CA

Colour: ONYX BLACK Odo. Out:

V.I.N.#: 1GT49REY6LF129386

Next Service: Date In: 10/20/2021

In Service Date: 11/08/2019 Cases: 1

Odo. In: 136.754

Out: 10/20/2021 11:00

Ext. War Total"Plus" - 48/160 - (48 m

Promised Time: 10/20/2021 05:00:00 PM Call When Ready:

License #:

Case: 1 Mount, balance and install 4 tires--Remove the driver front tire and put in the box. Save one of the other 3 tires for a spare

Quantity Description/Correction

4.00 P2723900 - P2756520

Retail Price Total \$586.00 \$400.00 \$1.600.00

> \$150.00 \$150.00

• Mount, balance and install 4 tires--Remove the driver front tire and put in the box. Save one of the other 3 tires for a spare.

• Tech Comments: Installed 4 tires. Torqued wheels to 140ft/lbs. Retorque is required within 100km's. TPM calibrated

Tire Recycling Fee

Miscellaneous

\$16.00 \$16.00

\$16.50 \$16.50

Misc \$32.50

Labour \$150.00

Parts \$1,600.00 Prepaid Parts Amt: \$0.00

Case Total: \$1,782.50

\$0.00



FAX: 780-778-3398 WWW.SMYLCHEV.COM

INVOICE ORIGINAL Work Order #214578 **Roshan Property Managemen** October 20, 2021 Svc.Adv Stieb, Chad (780) 778-1055 Cust.Ph. Tag#

Page 2 of 2 11/02/2021 12:10:05

	Indebtedness is hereby acknowledged for the "Total Charges" being all or the baland owing to repairs, parts & accessories described in this work order.	ce Currency:	Labour: Parts:	\$150.00 \$1,616.00
		Payment Ref:	Misc:	\$16.50
۵		Expiry Date:	Sub Total:	\$1,782.50
ľ		P/O#:	G/HST:	\$89.13
h		G/HST Reg # 104897806	PST:	\$0.00
ľ		_	Tax Adjustment:	\$0.00
Т				
	10/20/2021 Date Signature	Payment Type Charge	Total:	\$1,871.63

Payee		Payment Type	Reference	Date	
Newgen Energy	Services Corp.	Charge		10/20/2021	\$1,871.63
				Balance Owing:	\$1,871.63