NC EQUIPMENT LTD.

NRS - INSPECT AND REPAIR

24-Mar-22

Line v	Item Sold	Item Sold Description	Comment	Quantity
1			HOURS: 11,275.6	(
2			COMPLAINT: INSPECTION AND REPAIRS	(
3			CAUSE:	
4			REPAIR: MAR. 8: GET TJW TO HELP DIAG CODES	(
5			DID CALIBRATIONS AS NEEDED - CLEARED	(
3			INSTALL CONNECTOR FOR LM WORK LIGHT	(
7			R+R IMPLEMENT QUICK CONNECT HOSES AT FRONT	(
3			R+R LIGHT BULB IN LR WORK LIGHT, TEST - GOOD	(
9			ADD 10L RED MIXED COOLANT	(
10			CLEAN UP POSSIBLE LEAKS AT COOLER, HYDR FAN	(
11			PUMP, STARTER, REAR JOINT OF OIL PAN	(
12			RUN FOR 15 MINUTES, LOOKS GOOD EXCEPT OIL PAN	(
13			MAR. 9: INSTALL LM WORK LIGHT	(
14			INSTALL MISSING R/H VENT	(
15			ADD 10L HYDR OIL	(
16			CHECK POTENTIAL LEAKS OVERNIGHT - OIL PAN GASKET	(
17			STARTER O-RING, STEERING PUMP RELIEF O-RING ALL	(
18			LEAKING	(
19			REMOVE STARTER, REMOVE + REINSTALL PLATE FOR ACCESS	(
20			TO REPLACE O-RING TORQUE TO 18FTLBS	C
21			MAR. 10: REMOVE STEERING PUMP RELIEF VALVE	(
22			REPLACE O-RING AND REINSTALL	(
23			MAR. 11: DROP OIL AND COVER FOR POTENTIAL REUSE	(
24			REMOVE BOLTS AND DROP PANS. CLEAN MATING	(
25			SURFACES OF SEALANT AND REINSTALL PANS WITH NEW	(
26			GASKETS. 1-2 JOINT GASKET GOT MESSED UP	(
27			TORQUE BOLTS TO SPEC	(
28			MAR. 14: REPLACE JOINT GASKET	(
29			FILL WITH REUSED OIL, PURGE PUMP W/HYDR OIL - 10L	(
ac Eoni	PMENT LTD.		MAR. 15: BOLITILIZET/SZTDARWEZRI.AHOOK UP STARTER	

Line v	Item Sold	Item Sold Description	Comment	Quantity
31			RUN FOR 15 MINUTES - GOOD. TJW DOUBLECHECKED.	0
32			MAR. 16, 17: INSTALL STUMP PANS AND L/H ENGINE PANEL	0
33			ADD 8L ENGINE OIL	0
34	LAB-SHOP	LABOUR-SHOP	NRS, TJW, JAO, CMK	62.5
35	5W40	FULLY SYNTHETIC 5W40 BULK		8
36	5W30	HDTO TO-4 5W30 BULK		20
37	LIG13336	HALOGEN H3 70W 24V BULB		1
38	8C3089	O-RING		1
39	4S12FLB12	#12 FLANGE 90 FITTING		2
40	4SA12MP12	3/4" NPT MALE HOSE FITTING		2
41	GH493-12	3/4" 4-BRAID HOSE		4
42	4222152	LOUVER ASSY		1
43	1042091	SCREW		2
44	2275978	FLOOD LIGHT		1
45	4N7266	GASKET		2
46	7W0845	GASKET		2
47	1880210	GASKET - RAIL		2
48	9Y6089	GASKET		1
49	3T3434	PLUG		6
50	GH493-10	5/8 ID 4 SPIRAL WIRE HOSE		. 3