



H14-4
GR-FEB
Work Order #: 341

Precision Contractors
Box 10578
Lloydminster, Alberta T9V 3A7
Canada

CREATED BY	Nick Kempton	DATE	15 Jul 2022
MAKE	D6 LGP DOZER	MANUF. S/N	RDC00635
MODEL / DESCRIPTION		UNIT #	6163
SERVICE METER	2,547.00	KM	

Description of Work
Replaced track assemblies. ST2092



Precision Contractors

Box 10578
Lloydminster, Alberta T9V 3A7
Canada

CREATED BY Nick Kempton	DATE 6 Jan 2023
MAKE D6 LGP DOZER	MANUF. S/N RDC00635
MODEL / DESCRIPTION	UNIT # 6163
SERVICE METER 4,278.00	KM

Description of Work
R/I edges.

Summary of Labour				
Date	Employee	Work Type	Description	Hours
6 Jan 2023	Nick Kempton	Field Mechanic	R/I edges	1.00



Precision Contractors
Box 10578
Lloydminster, Alberta T9V 3A7
Canada

CREATED BY Nathan Bower	DATE 8 Jan 2023
MAKE D6 LGP DOZER	MANUF. S/N RDC00635
MODEL / DESCRIPTION	UNIT # 6163
SERVICE METER 4,289.00	KM

Description of Work

-repair Blade tilt pin retainer and pin on barrel end of cylinder- Snap ring retainer for barrel end pin on blade tilt cylinder broke and pin fell out-reinstall pin with spacers and weld retainer to pin-a new 454-8458 snap ring and a 473-3136 spacer were used-Travel to 5-8-62-4-W4 East of Fort Kent and Return to shop.

Summary of Labour

Date	Employee	Work Type	Description	Hours
7 Jan 2023	Nathan Bower	Field Mechanic	repair #6163 blade tilt cyl pin	5.00



Precision Contractors

Box 10578
Lloydminster, Alberta T9V 3A7
Canada

CREATED BY Nathan Bower	DATE 23 Feb 2023
MAKE D6 LGP DOZER	MANUF. S/N RDC00635
MODEL / DESCRIPTION	UNIT # 6163
SERVICE METER 4,379.00	KM

Description of Work

Boost machine-Replace batteries--Travel to location to boost machine for truck driver; follow machine to next location (15-32-55-3-W4) to replace batteries. Batteries were frozen in machine, temperature was -28 degrees Celsius. Machine was not going to work until next week. Returned to machine on Feb 25 with heater and temperature was 10 Degrees warmer. Thaw battery box and R&I batteries.

922255 FINNING D6 6163 46518040 BATTERIES--2 OF 1535710 \$1,063.78

Summary of Labour

Date	Employee	Work Type	Description	Hours
23 Feb 2023	Connor Tiller	Field Mechanic	Boost Machine	5.50
25 Feb 2023	Connor Tiller	Field Mechanic	R&I Batteries	5.00



Precision Contractors

Box 10578
Lloydminster, Alberta T9V 3A7
Canada

CREATED BY Nathan Bower	DATE 7 Mar 2023
MAKE D6 LGP DOZER	MANUF. S/N RDC00635
MODEL / DESCRIPTION	UNIT # 6163
SERVICE METER 4,452.00	KM

Description of Work

-DEF Tank cap broken- Travel to 9-28-55-3-W4 with DEF tank cap from #6157 in shop; replace broken DEF tank cap so operator could fill DEF tank. Blew out can and window tracks so that windows could close--Operator cab very dirty and unkempt.

Summary of Labour

Date	Employee	Work Type	Description	Hours
7 Mar 2023	Connor Tiller	Field Mechanic	replace def cap	4.00



Precision Contractors

Box 10578
Lloydminster, Alberta T9V 3A7
Canada

CREATED BY Nathan Bower	DATE 13 Apr 2023
MAKE D6 LGP DOZER	MANUF. S/N RDC00635
MODEL / DESCRIPTION	UNIT # 6163
SERVICE METER 4,457.00	KM

Description of Work

PM-2 (500 Hour) Service and Spring Checkover
 -Change engine oil/engine oil filter/fuel filters/trans filter/hydraulic filter/outer engine air and cab air filters. Take all oil samples. Grease machine. Adjust tracks.
 -Checkover machine and repairs-Replaced 20LB fire extinguisher and bracket; Replaced 460-4592 powertrain oil line (Trans oil was 72L Low); straightened track guides; dropped and cleaned stump pans; cut off ice lugs; replaced ripper line clamp; replaced "D6" and "LGP" decals; Replaced ether valve; Cleaned cab-very dirty.

Summary of Labour

Date	Employee	Work Type	Description	Hours
11 Apr 2023	Connor Tiller	Shop Mechanic	PM-2 service	10.00
19 Apr 2023	Connor Tiller	Shop Mechanic	install stump pans and detail cab	5.00
5 Apr 2023	Connor Tiller	Shop Mechanic	Checkover	10.00
13 Apr 2023	Connor Tiller	Shop Mechanic	checkover repairs	8.50
12 Apr 2023	Connor Tiller	Shop Mechanic	Checkover; drop and clean stump pans	10.00



Precision Contractors
Box 10578
Lloydminster, Alberta T9V 3A7
Canada

CREATED BY Nick Kempton	DATE 27 Sep 2023
MAKE D6 LGP DOZER	MANUF. S/N RDC00635
MODEL / DESCRIPTION	UNIT # 6163
SERVICE METER 5,120.00	KM

Description of Work
R/I left front idler. Split track. replace idler and connect track. adjust track to spec.

Summary of Labour				
Date	Employee	Work Type	Description	Hours
27 Sep 2023	Nathan Bower	Field Mechanic	R/I idler	3.00



Precision Contractors

Box 10578
Lloydminster, Alberta T9V 3A7
Canada

CREATED BY Nick Kempton	DATE 15 Apr 2024
MAKE D6 LGP DOZER	MANUF. S/N RDC00635
MODEL / DESCRIPTION	UNIT # 6163
SERVICE METER 5,567.00	KM

Description of Work

Pm-1 (250hr) Service / T/R Hyd. System - Completed pm-1 and service check over. Complaint of hyd. system getting hot. Hooked up pressure gauge to pump pressure and had found the pump was not returning to stand by pressure after no load was applied. Pump compensator was adjusted but nothing changed with the pressure. Replaced pump compensator and pressure was now returning to stand by pressure and not overheating.

Summary of Labour

Date	Employee	Work Type	Description	Hours
15 Apr 2024	Nathan Bower	Field Mechanic	Repairs	3.00
16 Apr 2024	Nathan Bower	Field Mechanic	Repairs	4.00



Precision Contractors
Box 10578
Lloydminster, Alberta T9V 3A7
Canada

CREATED BY Nick Kempton	DATE 4 May 2024
MAKE D6 LGP DOZER	MANUF. S/N RDC00635
MODEL / DESCRIPTION	UNIT # 6163
SERVICE METER 5,607.00	KM

Description of Work

Repair Segments - Travel to Location to tightened segment that was loose. Removed segment and cleaned mounting surface. Installed segment with new bolts and tightened to spec. Checked the other segments and needed to tightened 2 more segments.

Summary of Labour

Date	Employee	Work Type	Description	Hours
4 May 2024	Kyler Carlson	Field Mechanic	Repairs	2.00



Precision Contractors

Box 10578
Lloydminster, Alberta T9V 3A7
Canada

CREATED BY Nick Kempton	DATE 6 Jun 2024
MAKE D6 LGP DOZER	MANUF. S/N RDC00635
MODEL / DESCRIPTION	UNIT # 6163
SERVICE METER 5,770.00	KM

Description of Work

Track Guide / Pm-1 service (250hr) - Completed pm-1 oil change and service check over. Replaced rh track guide. Needed to trim the new track guide on the inside.

Summary of Labour

Date	Employee	Work Type	Description	Hours
6 Jun 2024	Kyler Carlson	Field Mechanic	Repairs	2.50



Precision Contractors
Box 10578
Lloydminster, Alberta T9V 3A7
Canada

CREATED BY Nick Kempton	DATE 20 Jun 2024
MAKE D6 LGP DOZER	MANUF. S/N RDC00635
MODEL / DESCRIPTION	UNIT # 6163
SERVICE METER 5,818.00	KM

Description of Work
Repair Segments - Final drive segments where starting to loose bolts. Replaced the missing bolts and re-torqued all the bolts. Replaced any bolts that broke or stretched.

Summary of Labour				
Date	Employee	Work Type	Description	Hours
20 Jun 2024	Nathan Bower	Field Mechanic	Repairs	5.00



Precision Contractors
Box 10578
Lloydminster, Alberta T9V 3A7
Canada

CREATED BY Nick Kempton	DATE 19 Jul 2024
MAKE D6 LGP DOZER	MANUF. S/N RDC00635
MODEL / DESCRIPTION	UNIT # 6163
SERVICE METER 5,961.00	KM 0.00

Description of Work
PM-4 Service (2000hrs) - Completed a pm-4 service, changed all the oils and filters including the air filters. Greased machine.

Summary of Labour				
Date	Employee	Work Type	Description	Hours
19 Jul 2024	Kohl Kromrey	Field Mechanic	Service	0.00



Precision Contractors
Box 10578
Lloydminster, Alberta T9V 3A7
Canada

CREATED BY Nick Kempton	DATE 31 Aug 2024
MAKE D6 LGP DOZER	MANUF. S/N RDC00635
MODEL / DESCRIPTION	UNIT # 6163
SERVICE METER 6,180.00	KM 0.00

Description of Work
PM-1 Service (250hr) - Complete pm-1 check over service. Greased machine.

Summary of Labour				
Date	Employee	Work Type	Description	Hours
31 Aug 2024	Kohl Kromrey	Field Mechanic	Service	0.00



Work Order #: 1014

Precision Contractors

Box 10578
Lloydminster, Alberta T9V 3A7
Canada

CREATED BY Nick Kempton	DATE 28 Oct 2024
MAKE D6 LGP DOZER	MANUF. S/N RDC00635
MODEL / DESCRIPTION	UNIT # 6163
SERVICE METER 6,387.00	KM

Description of Work
PM-2 Service (500hr) - Completed a 500hr service. Change engine oil and all the filters.

Summary of Labour				
Date	Employee	Work Type	Description	Hours
28 Oct 2024	Kohl Kromrey	Field Mechanic	Service	3.00



Work Order #: 1205

Precision Contractors

Box 10578
Lloydminster, Alberta T9V 3A7
Canada

CREATED BY Nick Kempton	DATE 26 Feb 2025
MAKE D6 LGP DOZER	MANUF. S/N RDC00635
MODEL / DESCRIPTION	UNIT # 6163
SERVICE METER 6,505.00	KM

Description of Work
Undercarriage / Check Over Repairs / PM-4 Service (2000hrs) - 223 Total Hrs. - Completed PM-4 and service check over; replace engine crank seal; replace power train lines; cracked hyd lines; remove yoke - remove and replace seal; replace broken ang cyl grease line;

Summary of Labour

Date	Employee	Work Type	Description	Hours
26 Feb 2025	Cody Davidson	Shop Mechanic	Repairs	24.00



recision Contractors
Box 10578
Lloydminster, Alberta T9V 3A7
Canada

CREATED BY Nick Kempton	DATE 27 May 2025
MAKE D6 LGP DOZER	MANUF. S/N RDC00635
MODEL / DESCRIPTION	UNIT # 6163
SERVICE METER 6,728.00	KM

Description of Work
PM-1 Service (250hr) / Replace edges - complete PM-1 Service - check all fluids/change air filters. Remove cutting edges, corner bits and hardware

Summary of Labour				
Date	Employee	Work Type	Description	Hours
27 May 2025	Dexter Reese	Field Mechanic	Service / Repairs	2.00



Precision Contractors
Box 10578
Lloydminster, Alberta T9V 3A7
Canada

CREATED BY Nick Kempton	DATE 2 Jun 2025
MAKE D6 LGP DOZER	MANUF. S/N RDC00635
MODEL / DESCRIPTION	UNIT # 6163
SERVICE METER 6,756.00	KM

Description of Work

T/R Regen Code - Repair DPF System - machine had active 2458-13 code for DPF Diff pressure sensor out of calibration. Removed sensors and cleared/blew out sensor tubes. Code still active. Replaced sensor with a new one - code cleared

Summary of Labour

Date	Employee	Work Type	Description	Hours
2 Jun 2025	Nathan Bower	Field Mechanic	Repairs	4.00



Precision Contractors
Box 10578
Lloydminster, Alberta T9V 3A7
Canada

CREATED BY	Nick Kempton	DATE	20 Jun 2025
MAKE	D6 LGP DOZER	MANUF. S/N	RDC00635
MODEL / DESCRIPTION		UNIT #	6163
SERVICE METER	6,874.00	KM	0.00

Description of Work
Repair Door Handles / Grease / Repair Sliding Window - repair door handle, repair window seal, grease machine

Summary of Labour				
Date	Employee	Work Type	Description	Hours
20 Jun 2025	Kohl Kromrey	Field Mechanic	Repairs	2.00



Precision Contractors
Box 10578
Lloydminster, Alberta T9V 3A7
Canada

CREATED BY Nick Kempton	DATE 11 Jul 2025
MAKE D6 LGP DOZER	MANUF. S/N RDC00635
MODEL / DESCRIPTION	UNIT # 6163
SERVICE METER 6,979.00	KM 0.00

Description of Work
Pm-3 Service (1000hrs) - Completed 1000hr service and check over. Changed trans., engine and final drive oils. Changed all the filters.

Summary of Labour				
Date	Employee	Work Type	Description	Hours
11 Jul 2025	Josh Jeffery	Field Mechanic	Repairs	5.00



recision Contractors
Box 10578
Lloydminster, Alberta T9V 3A7
Canada

CREATED BY Nick Kempton	DATE 1 Aug 2025
MAKE D6 LGP DOZER	MANUF. S/N RDC00635
MODEL / DESCRIPTION	UNIT # 6163
SERVICE METER 7,062.00	KM 0.00

Description of Work
 Replace broken grease nipple / Blow out Rads - Blew out rad, coolers and a/c condenser. Replaced broken pitch link grease nipple.

Summary of Labour				
Date	Employee	Work Type	Description	Hours
1 Aug 2025	Kyler Carlson	Field Mechanic	Service / Repairs	1.00



Work Order #: 1574

Precision Contractors

Box 10578
Lloydminster, Alberta T9V 3A7
Canada

CREATED BY Nick Kempton	DATE 30 Aug 2025
MAKE D6 LGP DOZER	MANUF. S/N RDC00635
MODEL / DESCRIPTION	UNIT # 6163
SERVICE METER 7,194.00	KM 0.00

Description of Work

PM-1 Service (250hr) - complete PM-1 Service - check fluids. Change cab filters. Grease machine. Check over machine

Summary of Labour

Date	Employee	Work Type	Description	Hours
30 Aug 2025	Kohl Kromrey	Field Mechanic	Service	1.00



Precision Contractors

Box 10578
Lloydminster, Alberta T9V 3A7
Canada

CREATED BY Nick Kempton	DATE 22 Sep 2025
MAKE D6 LGP DOZER	MANUF. S/N RDC00635
MODEL / DESCRIPTION	UNIT # 6163
SERVICE METER 7,431.00	KM 0.00

Description of Work

PM-2 Service (500hrs) / Flip edges / Track Pad bolts - Complete PM-2 Service. Drain engine oil. Change all filters then refill engine oil and run machine. Flip cutting edges, replace corner bits. Installed new track pad bolts on loose pad on RHS. Blow out cab

Summary of Labour

Date	Employee	Work Type	Description	Hours
22 Sep 2025	Kohl Kromrey	Field Mechanic	Service	3.50



Precision Contractors

Box 10578
Lloydminster, Alberta T9V 3A7
Canada

CREATED BY Nick Kempton	DATE 8 Oct 2025
MAKE D6 LGP DOZER	MANUF. S/N RDC00635
MODEL / DESCRIPTION	UNIT # 6163
SERVICE METER 7,434.00	KM 0.00

Description of Work

Troubleshoot Regen - fail to ignite. R&I ARD head - test - fuel line to ARD head broken/leaking - removed. Replace with new parts, test. ARD ign and manuel Regen - good

Summary of Labour

Date	Employee	Work Type	Description	Hours
7 Oct 2025	Nathan Bower	Field Mechanic	Troubleshoot / Repair	12.00



CREATED BY Nick Kempton	DATE 6 Nov 2025
MAKE D6 LGP DOZER	MANUF. S/N RDC00635
MODEL / DESCRIPTION	UNIT # 6163
SERVICE METER 7,565.00	KM 0.00

Precision Contractors
 Box 10578
 Lloydminster, Alberta T9V 3A7
 Canada

Description of Work
 PM-1 Service (250hr) / Check Over / Clean pans out - Completed pm-1 service, changed engine oil and filter plus fuel filters. Check over machine and dropped stump pans for cleaning.

Summary of Labour

Date	Employee	Work Type	Description	Hours
6 Nov 2025	Kyler Carlson	Shop Mechanic	Service / Repairs	10.00



CREATED BY Nick Kempton	DATE 13 Jan 2026
MAKE D6 LGP DOZER	MANUF. S/N RDC00635
MODEL / DESCRIPTION	UNIT # 6163
SERVICE METER 7,686.00	KM 0.00

Precision Contractors
 Box 10578
 Lloydminster, Alberta T9V 3A7
 Canada

Description of Work
 Auction check over and detail - Check over machine. Replaced cab filters, removed unit numbers and fire ext brackets. Greased machine, adjust tracks and detailed the cab. Replaced cat decals that needed done. Replaced leaking transmission filter hose. Replaced cracked panel inside the cab behind the seat. Repaired washer fluid sprayers and installed a splice on the lh sprayer hose.

Summary of Labour				
Date	Employee	Work Type	Description	Hours
13 Jan 2026	Cody Davidson	Shop Mechanic	Repairs	10.00