



330942 AB LTD.  
 Box 778 (4504 47 Ave.)  
 Rocky Mtn. House, AB, T4T 1A6  
 Phone: 403-845-7445  
 Email: info@peakglassab.com  
 GST: 106150501RT

*710-8  
MAY*

**Invoice: 762**

**Date: 3/24/22**

**Schedule Date: 3/24/2022 12:00 P**

**Customer:**

PIDHERNEY'S INC  
 BOX 940  
 ROCKY MOUNTAIN HOUSE AB T4T 1A7

(403)845-3072  
 AP@PIDHERNEYS.COM

| PO   | Terms  | Job # |
|------|--------|-------|
| 9167 | NET 30 |       |

| Year | Make     | Model | Style            | VIN               |
|------|----------|-------|------------------|-------------------|
| 2020 | KENWORTH | T880  | CONVENTIONAL CAB | 1XKZD40XXLJ969615 |

| Mileage | Lic. Plate | Unit |
|---------|------------|------|
| 172150  | E-94206    | 9167 |

| Qty  | Part Number/Desc.   | List Price | Material | Labor  | Total    |
|------|---|------------|----------|--------|----------|
| 1.00 | DW02038GBY<br>Windshield Green Tint/Blue Shade Windshield (w/Attch)(ENCAPSULATION)(Encap) | \$500.00   | \$400.00 | \$0.00 | \$400.00 |

| Taxes  |         |
|--------|---------|
| G.S.T. | \$20.00 |

**Job Location:**  
 PIDHERNEY'S INC  
 BOX 940  
 ROCKY MOUNTAIN HOUSE AB T4T 1A7

Signature \_\_\_\_\_

| Material | Labor  | Taxes   | Total    | Payments | Balance  |
|----------|--------|---------|----------|----------|----------|
| \$400.00 | \$0.00 | \$20.00 | \$420.00 | \$0.00   | \$420.00 |

PEAK GLASS  
 BOX 778 (4504 47 AVE.)  
 ROCKY MOUNTAIN HOUSE T4T 1A6  
 (403)845-7445  
 Fax#: (403)845-5379

Invoice: 110  
 Date: 1/14/22  
 Schedule Date: 1/13/2022 1:00 PM

Bill To:  
 PIDHERNEY'S INC  
 BOX 940  
 ROCKY MOUNTAIN HOUSE AB T4T 1A7  
 (403)845-3072  
 AP@PIDHERNEYS.COM

Customer:  
 PIDHERNEY'S

| CSR     | Tech  | PO         | Terms            | Job #             | Bill To Terms |
|---------|---|------------|------------------|-------------------|---------------|
| 18      |   | 9167       | NET 30           |                   | NET 30        |
| Year    | Make  | Model      | Style            | VIN               |               |
| 2020    | KENWORTH  | T880       | CONVENTIONAL CAB | 1XKZD40XXLJ969615 |               |
| Mileage | Li. Plate   | Unit       |                  |                   |               |
| 148202  | E94206  | 9167       |                  |                   |               |
| Qty     | Part Number/Desc.   | List Price | Material         | Labor             | Total         |
| 1.00    | DW02038GBY  | \$500.00   | \$400.00         | \$0.00            | \$400.00      |
|         | Windshield Green Tint/Blue Shade Windshield (w/Attch)(ENCAPSULATION)(Encap)<br>DISCOUNT GIVEN |            |                  |                   |               |

| Taxes  |              |         |
|--------|--------------|---------|
| g.s.t. | #106150501RT | \$20.00 |

Job Location:  
 PIDHERNEY'S  
 BOX  
 ROCKY MOUNTAIN HOUSE

Signature \_\_\_\_\_

| Material | Labor  | Taxes   | Total    | Payments | Balance  |
|----------|--------|---------|----------|----------|----------|
| \$400.00 | \$0.00 | \$20.00 | \$420.00 | \$0.00   | \$420.00 |



1-888-SPEEDY8  
www.speedyglass.ca

wo 21748

**Invoice**



330942 ALBERTA LTD  
4504 - 47TH AVENUE, BOX 778  
ROCKY-MTN-HOUSE AB AB T4T 1A6  
(403)845-7445 Fax:(403)845-5379

**8728-601801**

Date: 2021/07/02 C0  
Page: 1 -MOBILE-  
GST/H... 106150501RT

Bill-To:  
PIDHERNEY'S INC  
BOX 940  
ROCKY MOUNTAIN HOUSE AB  
T4T 1A7

Mobile:  
PIDHERNEY'S INC  
BOX 940  
ROCKY MOUNTAIN HOUSE AB  
T4T 1A7

(403)845-3072 fax:(403)845-7184  
(The "Customer")

PH(403)845-3072 FAX(403)845-7184

Account: +28000120000

Truck:

JOB ID: 87280000060180

Policy: Vehicle: 2021 KENWORTH T880...  
Claim: Loss Date:

CSR: 024 License Plate: E-94206 Authorized: BLAIR  
Installer: 018 Unit: 9167 Work Order #: 87280000060180  
V.I.N.: 1XKZD40XXLJ969615 PO/RO: 9167 Scheduled Date: 2021/07/02

| Products & Services                 |                     | Qty  | Labour | Material |
|-------------------------------------|---------------------|------|--------|----------|
| DW02038GBY                          | DOMESTIC WINDSHIELD | 1.00 | 0.00   | 400.00   |
| - DISCOUNT APPLIED (RETAIL \$500 +) |                     |      |        |          |

I have read the details of this invoice, the sale conditions and warranties on the back of the present invoice. I accept them and recognize being bounded by them.

Customer Signature: \_\_\_\_\_ Date: \_\_\_\_\_

|           | NON INSURED | INSURED | TOTAL |
|-----------|-------------|---------|-------|
| Material: | 400.00      | 0.00    |       |
| Labour:   | 0.00        | 0.00    |       |
| GST/HST:  | 20.00       | 0.00    |       |
| PST:      | 0.00        | 0.00    |       |
| Total:    | 420.00      | 0.00    |       |

420.00

TOTAL PAYABLE BY CUSTOMER: 420.00

Payments: 0.00  
Balance: 420.00

The adhesive that we use to attach the windshield to the body takes time to set. In order to allow the adhesive to set sufficiently before driving your vehicle, please follow the instructions below:  
1. Minimum drive-away time; vehicle should not be driven for at least 1hr after installation completed unless technician has stated, in the space below, that a different minimum drive-away time applies.

**YOUR VEHICLE SHOULD NOT BE DRIVEN BEFORE:**  :  AM  PM

2. After the installation, you should not do anything that could interfere with the adhesive setting process such as pushing against, touching or otherwise testing the glass or adhesive.  
3. You should not take the vehicle through a car wash for first 24hours after installation. If these instructions are not followed, adhesive might not set or retain glass sufficiently, which could cause accident or damage to vehicle, or increase the risk of injury if vehicle is involved in a collision.

WINDSHIELD INSTALLATION: The warranty is not transferable or redeemable for cash, the installation is warranted against leaks and windshield manufacturing defects. (See reverse.)

## Invoice

8728-578001

Date: 2020/10/21

C0

Page: 1

GST/H... 106150501RT

330942 ALBERTA LTD  
4504 - 47TH AVENUE, BOX 778  
ROCKY-MTN-HOUSE AB AB T4T 1A6  
(403)845-7445 Fax:(403)845-5379

Bill-To:  
PIDHERNEY'S INC  
BOX 940  
ROCKY MOUNTAIN HOUSE AB  
T4T 1A7

(403)845-3072 fax:(403)845-7184  
(The "Customer")

Account:

*PO# 6907*

|                         |                    |                    |                |
|-------------------------|--------------------|--------------------|----------------|
| Policy:                 | Vehicle:           | 2020 KENWORTH T880 |                |
| Claim:                  | Loss Date:         |                    |                |
| SR: 024                 | Mileage: 43391     | Work Order #:      | 87280000057800 |
| Staller: 018            | Unit: 9167         | Scheduled Date:    | 2020/10/21     |
| I.N.: 1XKZD40XXLJ969615 | PO/RO: 9167        |                    |                |
| License Plate: E-94206  | Authorized: COLTON |                    |                |

| Products & Services           | Qty  | Labour | Material |
|-------------------------------|------|--------|----------|
| W02038GBY DOMESTIC WINDSHIELD | 1.00 | 0.00   | 400.00   |

Notes: DISCOUNT APPLIED (RETAIL \$500+ TAX)  
ADDITIONAL DISCOUNT GIVEN FOR SCRATCH ON DRIVERS SIDE APPROVED AS PER COLTON

I have read the details of this invoice, the sale conditions and warranties on the back of the present invoice. I accept them and recognize being bounded by them.

Customer Signature: \_\_\_\_\_ Date: \_\_\_\_\_

|           | NON INSURED | INSURED | TOTAL |
|-----------|-------------|---------|-------|
| Material: | 400.00      | 0.00    |       |
| Labour:   | 0.00        | 0.00    |       |
| GST/HST:  | 20.00       | 0.00    |       |
| PST:      | 0.00        | 0.00    |       |
| Total:    | 420.00      | 0.00    |       |

|                            |        |        |
|----------------------------|--------|--------|
| TOTAL PAYABLE BY CUSTOMER: | 420.00 | 420.00 |
| Payments:                  | 0.00   |        |
| Balance:                   | 420.00 |        |

The adhesive that we use to attach the windshield to the body takes time to set. In order to allow the adhesive to set sufficiently before driving your vehicle, please follow the instructions below:  
Minimum drive-away time; vehicle should not be driven for at least 1hr after installation completed unless technician has stated, in the space below, that a different minimum drive-away time applies.

### OUR VEHICLE SHOULD NOT BE DRIVEN BEFORE:

\_\_\_\_\_ :

After the installation, you should not do anything that could interfere with the adhesive setting process such as pushing against, touching or otherwise testing the glass or adhesive. You should not take the vehicle through a car wash for first 24hours after installation. If these instructions are not followed, adhesive might not set or retain glass sufficiently, which could cause accident or damage to vehicle, or increase the risk of injury if vehicle is involved in a collision.

WINDSHIELD INSTALLATION: The warranty is not transferable or redeemable for cash, the installation is warranted against leaks and windshield manufacturing defects. (See reverse.)

P.O. BOX 1348  
 4120 - 45A STREET  
 ROCKY MTN. HOUSE, Alberta T4T 1A9  
 CANADA



**INVOICE**  
**161228**

(403) 845-4410  
 e-mail: orascomm@telus.net

Date: Jan 23, 2020  
 Page: 1

Quote/Order

**Sold to:**

PIDHERNEY'S INC.

BOX 940  
 ROCKY MTN. HOUSE, ALBERTA T4T 1A7

**Ship to:**

PIDHERNEY'S INC.

BOX 940  
 ROCKY MTN. HOUSE, ALBERTA T4T 1A7

Business No.: 86126 9652

| Item No.  | Qty | Unit | Description                                       | Tax | Unit Price          | Amount        |
|---|-----|------|---|-----|---------------------|---------------|
| 1159  | 1   | Each | UNIT # 9167 TEST AND INSTALL SUPPLIED 2-WAY RADIO | G   |                     |               |
| NMO-K-UD  | 1   | Each | ANT/MOB 132-174 MHZ NGP                           | G   | 29.00               | 29.00         |
| AT3-3/4   | 1   | Each | CO-AX KIT RG58/U 12" SOLID CORE                   | G   | 19.00               | 19.00         |
| RFU-505   | 1   | Each | ANTENNA BRKT MIRROR MOUNT 3/4" HOLE               | G   | 7.00                | 7.00          |
| E30-3339-15   | 1   | Each | CONNECTOR, UHF (M), RG58, CRIMP                   | G   | 7.00                | 7.00          |
| J29-0726-03   | 1   | Each | POWER CORD, TK-x60/x160 SERIES                    | G   | 29.00               | 29.00         |
| RT3-4112  | 1   | Each | MOUNTING BRACKET, TK-6110                         | G   | 21.00               | 21.00         |
| SP  | 1   | Each | HEAVY DUTY MIC KEEPER                             | G   | 26.00               | 26.00         |
| LAB1  | 3   | Hour | SHOP PARTS  | G   | 8.00                | 8.00          |
|   |     |      | LABOUR  | G   | 94.00               | 282.00        |
|   |     |      | Subtotal:   |     |                     | 428.00        |
|   |     |      | G - GST 5.00%                                     |     |                     |               |
|   |     |      | GST   |     |                     | 21.40         |
| 1. As Oras Communications Ltd. is an independant dealer, company policies and procedures may not reflect those indicated by Telus Mobility.<br>2. Oras Communications Ltd is not liable for any Bluetooth incompatibility issues experienced.<br>3. Cellular phone sales are final. Please retain this invoice for warranty claims. |     |      |   |     | <b>Total Amount</b> | <b>449.40</b> |

**Comments**

Terms: Net 30. Due Feb 22, 2020.

Signature \_\_\_\_\_ Name \_\_\_\_\_ Phone # \_\_\_\_\_

**Work Order:** 8985  
**Equipment:** TRACTOR TANDEM KW T880 [9167]  
**Work Location:**  
**Created by:** Josh LeBlanc  
**Kms:** 9140  
**Hr:** 9366

**Status:** Transferred  
**Serial Number:** 1XKZD40XXLJ969615  
**Business Unit:** Trucks Heavy  
**Start Date:**  
**Stop Date:**

**Work Order Cost Summary**

| Description                                  | Quantity | Labor Type | Rate               | Total    |
|--|----------|------------|--------------------|----------|
|  |          |            | <b>Total Labor</b> | \$0.00   |
| BELT- POLY 12 RIBS X 2180 [D84-1000-6122180] | 1.00     | Each       | \$95.76            | \$95.76  |
| BELT- POLY 6 RIBS X 1620 [D84-1000-6061620]  | 1.00     | Each       | \$43.72            | \$43.72  |
| GUN - GREASE PISTOL W/ WHIP [1133]           | 1.00     | Each       | \$48.95            | \$48.95  |
|  |          |            | <b>Total Parts</b> | \$188.43 |
|  |          |            | <b>Total Equip</b> | \$0.00   |
|  |          |            | <b>Total Cost</b>  | \$188.43 |

| Item ID | Description            | Completed By | Reported Hours |
|---------|------------------------|--------------|----------------|
| 15208   | driver requested parts |              | 0.00           |

**Work Order:** 9438  
**Equipment:** TRACTOR TANDEM KW T880 [9167]  
**Work Location:** Shop Operations - Blackfalds  
**Created by:** Darcy Hallock  
**Kms:** 9140  
**Hr:** 9366

**Status:** Transferred  
**Serial Number:** 1XKZD40XXLJ969615  
**Business Unit:** Trucks Heavy  
**Start Date:** 3-21-2020  
**Stop Date:** 3-21-2020

**Work Order Cost Summary**

| Description   | Quantity | Labor Type        | Rate               | Total   |
|---------------|----------|-------------------|--------------------|---------|
| DARCY HALLOCK | 0.75     | RT Shop Tire Tech | \$35.00            | \$26.25 |
|               |          |                   | <b>Total Labor</b> | \$26.25 |
|               |          |                   | <b>Total Parts</b> | \$0.00  |
|               |          |                   | <b>Total Equip</b> | \$0.00  |
|               |          |                   | <b>Total Cost</b>  | \$26.25 |

| Item ID | Description            | Completed By | Reported Hours |
|---------|------------------------|--------------|----------------|
| 16178   | 9167- PRESSURES/DEPTHS |              | 0.75           |

**Work Order:** 11508  
**Equipment:** TRACTOR TANDEM KW T880 [9167]  
**Work Location:** Parts - INV RM  
**Created by:** Colton Parker  
**Kms:** 9140  
**Hr:** 9366

**Status:** Transferred  
**Serial Number:** 1XKZD40XXLJ969615  
**Business Unit:** Trucks Heavy  
**Start Date:** 6-11-2020  
**Stop Date:** 6-11-2020

**Work Order Cost Summary**

| Description                                 | Quantity | Labor Type       | Rate               | Total             |
|---|----------|------------------|--------------------|-------------------|
| CLAYTON OLSON                               | 6.00     | RT Shop Mech Rky | \$50.00            | \$300.00          |
|   |          |                  | <b>Total Labor</b> | <b>\$300.00</b>   |
| BATTERY GROUP 31 12V 730CCA [7T31]          | 4.00     | Each             | \$136.02           | \$544.08          |
| BATTERY GROUP 31 12V 730CCA CORE [7T31CORE] | 4.00     | Each             | (\$22.50)          | (\$90.00)         |
| BATTERY GROUP 31 12V 730CCA CORE [7T31CORE] | 4.00     | Each             | \$25.33            | \$101.32          |
| BRAKE MATE- STROKE INDICATOR [S-100]        | 6.00     | Each             | \$0.78             | \$4.68            |
| GLAD HAND SEAL CLOSE [H41736]               | 2.00     | Each             | \$0.77             | \$1.54            |
| Hydraulic, Spin-On {HF6720} [P550387]       | 2.00     | Each             | \$13.61            | \$27.21           |
| MARKER LIGHT SWITCH [P27-1241-002-01]       | 1.00     | Each             | \$133.00           | \$133.00          |
|   |          |                  | <b>Total Parts</b> | <b>\$721.83</b>   |
|   |          |                  | <b>Total Equip</b> | <b>\$0.00</b>     |
|   |          |                  | <b>Total Cost</b>  | <b>\$1,021.83</b> |

| Item ID | Description   | Completed By | Reported Hours |
|---------|---|--------------|----------------|
| 19839   | POSITIVE AIR SHUTOFF NOT WORKING  |              | 0.25           |
| 19802   | NEED TO CLEAN, CHARGE, AND LOAD TEST ALL OF THE BATTERIES   |              | 1.00           |
| 19822   | CVIP -- Annual<br>Perform annual CVIP. Change hydraulic filter if applicable.   |              | 3.00           |
| 19823   | REPLACE HYDRAULIC FILTER  |              | 0.50           |
| 14138   | Cummins Idle Shutdown Update<br>Parameters to enable idle shutdown so it cannot be by passed with trailer brakes being left on. Please see attached printable parameters. |              | 0.00           |
| 14088   | PROGRAM ALL MODULES WITH DAVIES - MAKE SURE 12V CHARGER IS ON THE BATTERIES TO BE BOME NEXT SERVICE   |              | 0.00           |
| 19837   | CHECK LIGHTS  |              | 1.00           |
| 19838   | CHECK OVER AND GREASE FIFTH WHEEL   |              | 0.25           |

**Work Order:** 11627  
**Equipment:** TRACTOR TANDEM KW T880 [9167]  
**Work Location:**  
**Created by:** Josh LeBlanc  
**Kms:** 9140  
**Hr:** 9366

**Status:** Transferred  
**Serial Number:** 1XKZD40XXLJ969615  
**Business Unit:** Trucks Heavy  
**Start Date:**  
**Stop Date:**

**Work Order Cost Summary**

| Description                           | Quantity | Labor Type | Rate               | Total          |
|---------------------------------------|----------|------------|--------------------|----------------|
|                                       |          |            | <b>Total Labor</b> | <b>\$0.00</b>  |
| 3L ASSY-L/D 4WAY STRT 12' 4 [19-4012] | 1.00     | Each       | \$36.14            | \$36.14        |
| FIFTH WHEEL SLIDER KIT [FWSK-1]       | 1.00     | Each       | \$16.52            | \$16.52        |
|                                       |          |            | <b>Total Parts</b> | <b>\$52.65</b> |
|                                       |          |            | <b>Total Equip</b> | <b>\$0.00</b>  |
|                                       |          |            | <b>Total Cost</b>  | <b>\$52.65</b> |

| Item ID | Description     | Completed By | Reported Hours |
|---------|-----------------|--------------|----------------|
| 20038   | REQUESTED PARTS |              | 0.00           |

|                       |                               |                       |                   |
|-----------------------|-------------------------------|-----------------------|-------------------|
| <b>Work Order:</b>    | 12059                         | <b>Status:</b>        | Transferred       |
| <b>Equipment:</b>     | TRACTOR TANDEM KW T880 [9167] | <b>Serial Number:</b> | 1XKZD40XXLJ969615 |
| <b>Work Location:</b> |                               | <b>Business Unit:</b> | Trucks Heavy      |
| <b>Created by:</b>    | Maintain Administrator        | <b>Start Date:</b>    |                   |
| <b>Kms:</b>           | 9140                          | <b>Stop Date:</b>     |                   |
| <b>Hr:</b>            | 9366                          |                       |                   |

**Work Order Cost Summary**

| Description   | Quantity | Labor Type | Rate               | Total         |
|---|----------|------------|--------------------|---------------|
|   |          |            | <b>Total Labor</b> | <b>\$0.00</b> |
| 1" MALE WING COUPLER NIPPLE HP CONNECT [6105-16]                      | 1.00     | Each       | \$103.64           | \$103.64      |
| 1" WING NUT COUPLER [6125-16]   | 1.00     | Each       | \$113.02           | \$113.02      |
| 4/W TRAILER CORD 12' - FOR TANDEM TRACTORS [19-4012]                  | 1.00     | Each       | \$36.84            | \$36.84       |
| 4/W TRAILER CORD 12' - FOR TANDEM TRACTORS [19-4012]                  | 1.00     | Each       | \$36.83            | \$36.83       |
| 6 x 20 TOW SLING [TS2620]   | 1.00     | Each       | \$100.34           | \$100.34      |
| EMMISSIONS LABEL[Custom]  | 1.00     | Each       | \$244.85           | \$244.85      |
| FLOOR MAT KW LOGO @ T880[Custom]                                      | 1.00     | Pair       | \$124.31           | \$124.31      |
| GLAD HAND SEAL CLOSE {XREF 101113} [FS-312A]                          | 10.00    | Each       | \$0.47             | \$4.66        |
| GUN - GREASE PISTOL W/ WHIP [1133]                                    | 1.00     | Each       | \$50.82            | \$50.82       |
| HEADLAMP 23762 [H11-55/BP]  | 2.00     | Each       | \$9.81             | \$19.62       |
| HUB CAP VENT PLUG [3595990]   | 1.00     | Each       | \$4.29             | \$4.29        |
| KENWORTH PLUG ADAPTER [KW123]   | 1.00     | Each       | \$26.01            | \$26.01       |
| LED H11 SET OF 2 [LEDH11]   | 1.00     | Each       | \$47.84            | \$47.84       |
| LIGHT GROTE - OVAL RED LED STOP, TURN & SIGNAL [G6002 {xr 127-63002}] | 1.00     | Each       | \$19.07            | \$19.07       |
| MNPT- CRIMP [10143-16-16]   | 2.00     | Each       | \$29.30            | \$58.60       |
| MOTHERS -X REF 35316 [MOT35316]                                       | 1.00     | Each       | \$10.45            | \$10.45       |
| MOTHERS -X REF 35316 [MOT35316]                                       | 1.00     | Each       | \$9.42             | \$9.42        |
| PIDHERNEY MUD FLAP - 24 X 24 [PB2424]                                 | 2.00     | Each       | \$29.55            | \$59.11       |

|   |           |                    |                   |
|---|-----------|--------------------|-------------------|
| TRAILER LIGHT CORD TARP 15' 2 POLE VERTICAL [212272]          | 2.00 Each | \$229.63           | \$459.26          |
| USE OLD ONES FIRST, RATCHET TIEDOWN- MINI (1 X 16) [43887-10] | 1.00 Each | \$9.57             | \$9.57            |
| USED OLD ONES FIRST, 2" RATCHET STRAP W/WIRE HOOK [45982-43]  | 1.00 Each | \$17.94            | \$17.94           |
| WIPER BLADE 20" WINTER *NOTES [WW2010]                        | 1.00 Each | \$14.78            | \$14.78           |
|   |           | <b>Total Parts</b> | <b>\$1,571.27</b> |
|   |           | <b>Total Equip</b> | <b>\$0.00</b>     |
|   |           | <b>Total Cost</b>  | <b>\$1,571.27</b> |

| Item ID | Description            | Completed By | Reported Hours |
|---------|------------------------|--------------|----------------|
| 20610   | 9167- DIRECT BILL      |              | 0.00           |
| 23375   | DANE TOOK PARTS        | Josh LeBlanc | 0.00           |
| 27679   | KAT REQUESTED SUPPLIES | Josh LeBlanc | 0.00           |

|                       |                               |                       |                   |
|-----------------------|-------------------------------|-----------------------|-------------------|
| <b>Work Order:</b>    | 12825                         | <b>Status:</b>        | Transferred       |
| <b>Equipment:</b>     | TRACTOR TANDEM KW T880 [9167] | <b>Serial Number:</b> | 1XKZD40XXLJ969615 |
| <b>Work Location:</b> | Blackfalds Shop               | <b>Business Unit:</b> | Trucks Heavy      |
| <b>Created by:</b>    | Oom Jarussirirat              | <b>Start Date:</b>    | 7-1-2020          |
| <b>Kms:</b>           | 9140                          | <b>Stop Date:</b>     | 7-2-2020          |
| <b>Hr:</b>            | 9366                          |                       |                   |

**Work Order Cost Summary**

| Description                            | Quantity | Labor Type         | Rate               | Total           |
|--|----------|--------------------|--------------------|-----------------|
| SCOTT MCLEAN                           | 5.00     | RT Shop Mech Blfds | \$49.00            | \$245.00        |
|  |          |                    | <b>Total Labor</b> | <b>\$245.00</b> |
| FEMCO ISX/QSK M27X2.0M [10-27200-02]   | 1.00     | Each               | \$40.57            | \$40.57         |
| FILTER - AIR CAB EXTERIOR [CF19013]    | 1.00     | Each               | \$29.73            | \$29.73         |
| FILTER - AIR CAB INTERIOR [CF19012]    | 1.00     | Each               | \$25.69            | \$25.69         |
| FILTER-AIR CLEANER {P621725} [P637453] | 1.00     | Each               | \$151.20           | \$151.20        |
| FUEL FILTER [FF5825]                   | 1.00     | Each               | \$37.34            | \$37.34         |
| FUEL FILTER [FS19764]                  | 1.00     | Each               | \$15.45            | \$15.45         |
| Lube {P559000} [LF14000NN]             | 1.00     | Each               | \$30.21            | \$30.21         |
| PARTICULATE FILTER [F37-1018]          | 1.00     | Each               | \$42.49            | \$42.49         |
|  |          |                    | <b>Total Parts</b> | <b>\$372.67</b> |
|  |          |                    | <b>Total Equip</b> | <b>\$0.00</b>   |
|  |          |                    | <b>Total Cost</b>  | <b>\$617.67</b> |

| Item ID | Description  | Completed By | Reported Hours |
|---------|--|--------------|----------------|
| 21429   | 30k/400hr Service - All Filters Replaced<br>Perform regular check list with the below fluids & filters will be replaced every A service. | Scott Mclean | 3.50           |
| 20267   | SOB - LIGHT TOGGLE SWITCH FOR MARKER LIGHTS  | Scott Mclean | 0.50           |

21560 NEED TO SET ALL BRAKES Scott Mclean 0.50

561 NEED TO ADJUST ALL TIRES PRESSURE; STEER 110 PSI AND ALL DRIVE 90 PSI Scott Mclean 0.50

**Work Order:** 13026 **Status:** Transferred  
**Equipment:** TRACTOR TANDEM KW T880 [9167] **Serial Number:** 1XKZD40XXLJ969615  
**Work Location:** **Business Unit:** Trucks Heavy  
**Created by:** Oom Jarussirrat **Start Date:**  
**Kms:** 9140 **Stop Date:**  
**Hr:** 9366

**Work Order Cost Summary**

| Description      | Quantity | Labor Type      | Rate               | Total          |
|------------------|----------|-----------------|--------------------|----------------|
| OOM JARUSSIRIRAT | 0.75     | RT Shop Foreman | \$48.00            | \$36.00        |
|                  |          |                 | <b>Total Labor</b> | <b>\$36.00</b> |
|                  |          |                 | <b>Total Parts</b> | <b>\$0.00</b>  |
|                  |          |                 | <b>Total Equip</b> | <b>\$0.00</b>  |
|                  |          |                 | <b>Total Cost</b>  | <b>\$36.00</b> |

| Item ID | Description                    | Completed By    | Reported Hours |
|---------|--------------------------------|-----------------|----------------|
| 21836   | TARP SYSTEM ISSUE; NOT WORKING | Oom Jarussirrat | 0.75           |

**Work Order:** 13664 **Status:** Transferred  
**Equipment:** TRACTOR TANDEM KW T880 [9167] **Serial Number:** 1XKZD40XXLJ969615  
**Work Location:** Blackfalds Shop **Business Unit:** Trucks Heavy  
**Created by:** Oom Jarussirrat **Start Date:** 7-16-2020  
**Kms:** 9140 **Stop Date:** 7-17-2020  
**Hr:** 9366

**Work Order Cost Summary**

| Description                   | Quantity | Labor Type         | Rate               | Total           |
|-------------------------------|----------|--------------------|--------------------|-----------------|
| OOM JARUSSIRIRAT              | 0.25     | RT Shop Foreman    | \$48.00            | \$12.00         |
| STEPHEN DEWOLFE               | 2.00     | RT Shop Mech Bifds | \$49.00            | \$98.00         |
|                               |          |                    | <b>Total Labor</b> | <b>\$110.00</b> |
| TEMPERATURE SENDER [Q21-1002] | 1.00     | Each               | \$86.54            | \$86.54         |
|                               |          |                    | <b>Total Parts</b> | <b>\$86.54</b>  |
|                               |          |                    | <b>Total Equip</b> | <b>\$0.00</b>   |
|                               |          |                    | <b>Total Cost</b>  | <b>\$196.54</b> |

| Item ID | Description                         | Completed By    | Reported Hours |
|---------|-------------------------------------|-----------------|----------------|
| 22722   | REPLACE DIFF LOCK/TEMP AS NECESSARY | Stephen DeWolfe | 0.50           |

22723 CHECK FOR AIR LEAKS; AROUND BRAKE POTS Stephen DeWolfe 0.50

22724 CHECK SUSPENSIONS Stephen DeWolfe 0.50

22725 CHECK ALL TIRES PRESSURE Stephen DeWolfe 0.50

22738 NEED A NEW WINDSHIELD Oom Jarussirat 0.25

**Work Order:** 14863 **Status:** Transferred  
**Equipment:** TRACTOR TANDEM KW T880 [9167] **Serial Number:** 1XKZD40XXLJ969615  
**Work Location:** **Business Unit:** Trucks Heavy  
**Created by:** Nick Depratto **Start Date:**  
**Kms:** 9140 **Stop Date:**  
**Hr:** 9366

**Work Order Cost Summary**

| Description                         | Quantity | Labor Type | Rate               | Total    |
|-------------------------------------|----------|------------|--------------------|----------|
|                                     |          |            | <b>Total Labor</b> | \$0.00   |
| GW KW INV SR2002972[Custom]         | 1.00     | Each       | \$0.01             | \$0.01   |
| TRUCK WINDSHEILD - PB 567 [DW02038] | 1.00     | Each       | \$400.00           | \$400.00 |
|                                     |          |            | <b>Total Parts</b> | \$400.01 |
|                                     |          |            | <b>Total Equip</b> | \$0.00   |
|                                     |          |            | <b>Total Cost</b>  | \$400.01 |

| Item ID | Description                        | Completed By  | Reported Hours |
|---------|------------------------------------|---------------|----------------|
| 24894   | 9167 - VENDOR REPAIR INVOICES      | Nick Depratto | 0.00           |
| 24895   | 9167 - VENDOR WINDSHIELD INVOICES  | Nick Depratto | 0.00           |
| 24896   | 9167 - VENDOR TIRE REPAIR INVOICES | Nick Depratto | 0.00           |

**Work Order:** 15896 **Status:** Transferred  
**Equipment:** TRACTOR TANDEM KW T880 [9167] **Serial Number:** 1XKZD40XXLJ969615  
**Work Location:** Rocky Mountain House Shop **Business Unit:** Trucks Heavy  
**Created by:** Colton Parker **Start Date:** 10-6-2020  
**Kms:** 9140 **Stop Date:** 10-6-2020  
**Hr:** 9366

**Work Order Cost Summary**

| Description    | Quantity | Labor Type       | Rate               | Total    |
|----------------|----------|------------------|--------------------|----------|
| BRETT LANGFORD | 11.00    | RT Shop Mech Rky | \$50.00            | \$550.00 |
|                |          |                  | <b>Total Labor</b> | \$550.00 |

|   |           |                    |            |
|---|-----------|--------------------|------------|
| AD-IS AIR DRYER DESSICANT FILTER CARTRIDGE [5008414PG {xr FLT109994, AC1001}] | 1.00 Each | \$34.27            | \$34.27    |
| CAB & BUNK FILTER - W/COVER PB 567 & KW T880 [CF19012 {xr X1987001}]          | 1.00 Each | \$20.54            | \$20.54    |
| CAB & BUNK FILTER - W/O COVER PB 567 & KW T880 [CFR19012]                     | 1.00 Each | \$12.90            | \$12.90    |
| CAB FILTER - PB 567 & KW T880 [F37-1018 {xr PA30269JAB}]                      | 1.00 Each | \$40.57            | \$40.57    |
| CAB FILTER - W/O COVER PB 567 & KW T880 [CFR19013]                            | 1.00 Each | \$11.42            | \$11.42    |
| ENGINE AIR FILTER [P637453 {xr P621725}]                                      | 1.00 Each | \$132.64           | \$132.64   |
| ENGINE LUBE FILTER [DBL7900 {xr P559000, LF14000NN}]                          | 1.00 Each | \$41.67            | \$41.67    |
| ENGINE SECONDARY FUEL FILTER [DBF6776 {xr FF5825NN}]                          | 1.00 Each | \$42.88            | \$42.88    |
| MARKER LIGHT SWITCH [P27-1241-002-01]   | 1.00 Each | \$129.71           | \$129.71   |
| PARTS FREIGHT [7540]  | 1.00 Each | \$115.00           | \$115.00   |
| PRIMARY ENGINE FUEL FILTER [P550849 {xr FS19764, FS19763}]                    | 1.00 Each | \$15.87            | \$15.87    |
| SCREW - WING M10X1.5X40MM [HWC09341]  | 1.00 Each | \$11.96            | \$11.96    |
|   |           | <b>Total Parts</b> | \$609.44   |
|   |           | <b>Total Equip</b> | \$0.00     |
|   |           | <b>Total Cost</b>  | \$1,159.44 |

| Item ID | Description  | Completed By   | Reported Hours |
|---------|--|----------------|----------------|
| 27157   | 30k/400hr Service - All Filters Replaced<br>Perform regular check list with the below fluids & filters will be replaced every A service. | Brett Langford | 6.00           |
| 27108   | CAB LIGHTS WORK WITH LAMP TEST BUT NOT WITH SWITCHES PT-53537  | Brett Langford | 4.00           |
| 26997   | REPLACE AIR DRYER  | Brett Langford | 1.00           |
| 24558   | CHECK GPS SERIAL# AND IGNITION STATE   | Brett Langford | 0.00           |

|                       |                               |                       |                   |
|-----------------------|-------------------------------|-----------------------|-------------------|
| <b>Work Order:</b>    | 16233                         | <b>Status:</b>        | Transferred       |
| <b>Equipment:</b>     | TRACTOR TANDEM KW T880 [9167] | <b>Serial Number:</b> | 1XKZD40XXLJ969615 |
| <b>Work Location:</b> | Blackfalds Shop               | <b>Business Unit:</b> | Trucks Heavy      |
| <b>Created by:</b>    | Oom Jarussirirat              | <b>Start Date:</b>    | 10-19-2020        |
| <b>Kms:</b>           | 9140                          | <b>Stop Date:</b>     | 10-20-2020        |
| <b>Hr:</b>            | 9366                          |                       |                   |

**Work Order Cost Summary**

| Description      | Quantity | Labor Type         | Rate               | Total    |
|------------------|----------|--------------------|--------------------|----------|
| OOM JARUSSIRIRAT | 0.50     | RT Shop Foreman    | \$48.00            | \$24.00  |
| SCOTT MCLEAN     | 2.50     | RT Shop Mech Blfds | \$49.00            | \$122.50 |
|                  |          |                    | <b>Total Labor</b> | \$146.50 |
|                  |          |                    | <b>Total Parts</b> | \$0.00   |
|                  |          |                    | <b>Total Equip</b> | \$0.00   |
|                  |          |                    | <b>Total Cost</b>  | \$146.50 |

| Item ID | Description       | Completed By | Reported Hours |
|---------|-------------------|--------------|----------------|
| 27768   | TRUCK WON'T START | Scott Mclean | 3.00           |

**Work Order:** 16699      **Status:** Transferred  
**Equipment:** TRACTOR TANDEM KW T880 [9167]      **Serial Number:** 1XKZD40XXLJ969615  
**Work Location:** Blackfalds Shop      **Business Unit:** Trucks Heavy  
**Created by:** Oom Jarussirrat      **Start Date:** 11-6-2020  
**Kms:** 9140      **Stop Date:** 11-7-2020  
**Hr:** 9366

**Work Order Cost Summary**

| Description   | Quantity | Labor Type         | Rate               | Total           |
|---|----------|--------------------|--------------------|-----------------|
| MITCHELL WILLERT  | 4.50     | RT Shop Mech Blfds | \$49.00            | \$220.50        |
| OOM JARUSSIRIRAT  | 0.25     | RT Shop Foreman    | \$48.00            | \$12.00         |
|   |          |                    | <b>Total Labor</b> | <b>\$232.50</b> |
| O-RING FOR WATER SEPP HOUSING - PACCAR ENGINE [910005DVC] | 1.00     | Each               | \$9.71             | \$9.71          |
| PARTS FREIGHT [7540]                                      | 1.00     | Each               | \$115.00           | \$115.00        |
|   |          |                    | <b>Total Parts</b> | <b>\$124.71</b> |
|   |          |                    | <b>Total Equip</b> | <b>\$0.00</b>   |
|   |          |                    | <b>Total Cost</b>  | <b>\$357.21</b> |

| Item ID | Description                   | Completed By     | Reported Hours |
|---------|-------------------------------|------------------|----------------|
| 27876   | WINDSHIELD CRACKED - PT 55649 | Mitchell Willert | 0.25           |
| 28588   | TRUCK WON'T START             | Mitchell Willert | 4.50           |

**Work Order:** 16728      **Status:** Transferred  
**Equipment:** TRACTOR TANDEM KW T880 [9167]      **Serial Number:** 1XKZD40XXLJ969615  
**Work Location:** Blackfalds Shop      **Business Unit:** Trucks Heavy  
**Created by:** Oom Jarussirrat      **Start Date:** 11-5-2020  
**Kms:** 9140      **Stop Date:** 11-6-2020  
**Hr:** 9366

**Work Order Cost Summary**

| Description     | Quantity | Labor Type         | Rate               | Total          |
|-----------------|----------|--------------------|--------------------|----------------|
| STEPHEN DEWOLFE | 1.25     | RT Shop Mech Blfds | \$49.00            | \$61.25        |
|                 |          |                    | <b>Total Labor</b> | <b>\$61.25</b> |
|                 |          |                    | <b>Total Parts</b> | <b>\$0.00</b>  |
|                 |          |                    | <b>Total Equip</b> | <b>\$0.00</b>  |
|                 |          |                    | <b>Total Cost</b>  | <b>\$61.25</b> |

| Item ID | Description   | Completed By    | Reported Hours |
|---------|---|-----------------|----------------|
| 529     | REPLACE BUMPER WITH SUPPLIED NO COST FROM GWK - GIVE NICK D THE | Stephen DeWolfe | 1.00           |
| 28602   | INSTALL MISSING ASGA# 6101 ON BUMPER                            | Stephen DeWolfe | 0.25           |

**Work Order:** 16885      **Status:** Transferred  
**Equipment:** TRACTOR TANDEM KW T880 [9167]      **Serial Number:** 1XKZD40XXLJ969615  
**Work Location:** Current Equipment Location      **Business Unit:** Trucks Heavy  
**Created by:** Rob Hilton      **Start Date:** 11-11-2020  
**Kms:** 9140      **Stop Date:** 11-11-2020  
**Hr:** 9366

**Work Order Cost Summary**

| Description   | Quantity | Labor Type        | Rate               | Total   |
|---------------|----------|-------------------|--------------------|---------|
| ROBERT HILTON | 1.50     | RT Shop Tire Tech | \$35.00            | \$52.50 |
|               |          |                   | <b>Total Labor</b> | \$52.50 |
|               |          |                   | <b>Total Parts</b> | \$0.00  |
|               |          |                   | <b>Total Equip</b> | \$0.00  |
|               |          |                   | <b>Total Cost</b>  | \$52.50 |

| Item ID | Description       | Completed By | Reported Hours |
|---------|-------------------|--------------|----------------|
| 29001   | 9167 - 11/11/2020 |              | 1.50           |

**Work Order:** 16972      **Status:** Transferred  
**Equipment:** TRACTOR TANDEM KW T880 [9167]      **Serial Number:** 1XKZD40XXLJ969615  
**Work Location:** Stewart Pit      **Business Unit:** Trucks Heavy  
**Created by:** Darcy Hallock      **Start Date:** 11-16-2020  
**Kms:** 9140      **Stop Date:** 11-16-2020  
**Hr:** 9366

**Work Order Cost Summary**

| Description   | Quantity | Labor Type        | Rate               | Total   |
|---------------|----------|-------------------|--------------------|---------|
| DARCY HALLOCK | 1.00     | RT Shop Tire Tech | \$35.00            | \$35.00 |
|               |          |                   | <b>Total Labor</b> | \$35.00 |
|               |          |                   | <b>Total Parts</b> | \$0.00  |
|               |          |                   | <b>Total Equip</b> | \$0.00  |
|               |          |                   | <b>Total Cost</b>  | \$35.00 |

| Item ID | Description      | Completed By  | Reported Hours |
|---------|------------------|---------------|----------------|
| 29144   | 9167- 11/16/2020 | Darcy Hallock | 1.00           |

**Work Order:** 18391  
**Equipment:** TRACTOR TANDEM KW T880 [9167]  
**Work Location:** Blackfalds Shop  
**Created by:** Oom Jarussirrat  
**Kms:** 9140  
**Hr:** 9366

**Status:** Transferred  
**Serial Number:** 1XKZD40XXLJ969615  
**Business Unit:** Trucks Heavy  
**Start Date:** 2-4-2021  
**Stop Date:** 2-5-2021

**Work Order Cost Summary**

| Description                                 | Quantity  | Labor Type   | Rate               | Total     |
|---|-----------|--------------|--------------------|-----------|
| OOM JARUSSIRIRAT                            | 0.50 RT   | Shop Foreman | \$48.00            | \$24.00   |
|   |           |              | <b>Total Labor</b> | \$24.00   |
| BATTERY GROUP 31 12V 730CCA [7T31]          | 4.00 Each |              | \$139.58           | \$558.34  |
| BATTERY GROUP 31 12V 730CCA CORE [7T31CORE] | 4.00 Each |              | (\$2.94)           | (\$11.75) |
|   |           |              | <b>Total Parts</b> | \$546.59  |
|   |           |              | <b>Total Equip</b> | \$0.00    |
|   |           |              | <b>Total Cost</b>  | \$570.59  |

| Item ID | Description                     | Completed By    | Reported Hours |
|---------|---------------------------------|-----------------|----------------|
| 32274   | NEED NEW BATTERIES              | Oom Jarussirrat | 0.25           |
| 30334   | INSTALL NEXT YEARS ASGA STICKER | Oom Jarussirrat | 0.25           |

**Work Order:** 19373  
**Equipment:** TRACTOR TANDEM KW T880 [9167]  
**Work Location:** Shop Operations - RMH  
**Created by:** Darcy Hallock  
**Kms:** 9140  
**Hr:** 9366

**Status:** Transferred  
**Serial Number:** 1XKZD40XXLJ969615  
**Business Unit:** Trucks Heavy  
**Start Date:** 3-22-2021  
**Stop Date:** 3-22-2021

**Work Order Cost Summary**

| Description   | Quantity | Labor Type     | Rate               | Total    |
|---------------|----------|----------------|--------------------|----------|
| DARCY HALLOCK | 3.00 RT  | Shop Tire Tech | \$35.00            | \$105.00 |
|               |          |                | <b>Total Labor</b> | \$105.00 |
|               |          |                | <b>Total Parts</b> | \$0.00   |
|               |          |                | <b>Total Equip</b> | \$0.00   |
|               |          |                | <b>Total Cost</b>  | \$105.00 |

| Item ID | Description      | Completed By  | Reported Hours |
|---------|------------------|---------------|----------------|
| 34429   | 9167- 03/20/2021 | Darcy Hallock | 3.00           |

**Work Order:** 19464  
**Equipment:** TRACTOR TANDEM KW T880 [9167]  
**Work Location:** Rocky Mountain House Shop  
**Created by:** Nick Depratto  
**Kms:** 9140  
**Hr:** 9366

**Status:** Transferred  
**Serial Number:** 1XKZD40XXLJ969615  
**Business Unit:** Trucks Heavy  
**Start Date:** 3-25-2021  
**Stop Date:** 3-26-2021

**Work Order Cost Summary**

| Description  | Quantity | Labor Type       | Rate               | Total           |
|--|----------|------------------|--------------------|-----------------|
| BRENT EVANS  | 3.50     | RT Shop Mech Rky | \$50.00            | \$175.00        |
| BRETT LANGFORD   | 2.00     | RT Shop Mech Rky | \$50.00            | \$100.00        |
|  |          |                  | <b>Total Labor</b> | <b>\$275.00</b> |
| 2 POLE SOCKET [11041-06]                                   | 1.00     | Each             | \$35.11            | \$35.11         |
| CAB & BUNK FILTER - W/O COVER PB 567 & KW T880 [CFR19012]  | 1.00     | Each             | \$10.03            | \$10.03         |
| CAB FILTER - PB 567 & KW T880 [F37-1018 {xr PA30269JAB}]   | 1.00     | Each             | \$41.23            | \$41.23         |
| ENGINE AIR FILTER [P637453 {xr P621725}]                   | 1.00     | Each             | \$130.16           | \$130.16        |
| ENGINE LUBE FILTER [DBL7900 {xr P559000, LF14000NN}]       | 1.00     | Each             | \$38.21            | \$38.21         |
| ENGINE SECONDARY FUEL FILTER [DBF6776 {xr FF5825NN}]       | 1.00     | Each             | \$38.36            | \$38.36         |
| PRIMARY ENGINE FUEL FILTER [P550849 {xr FS19764, FS19763}] | 1.00     | Each             | \$22.79            | \$22.79         |
|  |          |                  | <b>Total Parts</b> | <b>\$315.89</b> |
|  |          |                  | <b>Total Equip</b> | <b>\$0.00</b>   |
|  |          |                  | <b>Total Cost</b>  | <b>\$590.89</b> |

| Item ID | Description  | Completed By  | Reported Hours |
|---------|--|---------------|----------------|
| 34621   | 30k/400hr Service - All Filters Replaced<br>Perform regular check list with the below fluids & filters will be replaced every A service. | Nick Depratto | 5.50           |

**Work Order:** 20574  
**Equipment:** TRACTOR TANDEM KW T880 [9167]  
**Work Location:**  
**Created by:** Nick Depratto  
**Kms:** 9140  
**Hr:** 9366

**Status:** Transferred  
**Serial Number:** 1XKZD40XXLJ969615  
**Business Unit:** Trucks Heavy  
**Start Date:**  
**Stop Date:**

**Work Order Cost Summary**

| Description               | Quantity | Labor Type | Rate               | Total         |
|---------------------------|----------|------------|--------------------|---------------|
|                           |          |            | <b>Total Labor</b> | <b>\$0.00</b> |
| GWK INV SR2003488[Custom] | 0.00     | Each       | \$0.01             | \$0.00        |
|                           |          |            | <b>Total Parts</b> | <b>\$0.00</b> |
|                           |          |            | <b>Total Equip</b> | <b>\$0.00</b> |
|                           |          |            | <b>Total Cost</b>  | <b>\$0.00</b> |

| Item ID | Description           | Completed By  | Reported Hours |
|---------|-----------------------|---------------|----------------|
| 29552   | KW RECALL VECU UPDATE | Nick Depratto | 0.00           |

|                       |                               |                       |                   |
|-----------------------|-------------------------------|-----------------------|-------------------|
| <b>Work Order:</b>    | 21378                         | <b>Status:</b>        | Transferred       |
| <b>Equipment:</b>     | TRACTOR TANDEM KW T880 [9167] | <b>Serial Number:</b> | 1XKZD40XXLJ969615 |
| <b>Work Location:</b> | Rocky Mountain House Shop     | <b>Business Unit:</b> | Trucks Heavy      |
| <b>Created by:</b>    | Blair MacAulay                | <b>Start Date:</b>    | 6-16-2021         |
| <b>Kms:</b>           | 9140                          | <b>Stop Date:</b>     | 6-17-2021         |
| <b>Hr:</b>            | 9366                          |                       |                   |

**Work Order Cost Summary**

| Description                           | Quantity | Labor Type       | Rate               | Total           |
|---------------------------------------|----------|------------------|--------------------|-----------------|
| CLAYTON OLSON                         | 1.50     | RT Shop Mech Rky | \$50.00            | \$75.00         |
|                                       |          |                  | <b>Total Labor</b> | <b>\$75.00</b>  |
| 1/4 MALE/FEMALE BV [MV608-4]          | 1.00     | Each             | \$19.31            | \$19.31         |
| 3/4 TUBE - 1/2 NPT 90 [VS269NTA-12-8] | 1.00     | Each             | \$11.62            | \$11.62         |
|                                       |          |                  | <b>Total Parts</b> | <b>\$30.93</b>  |
|                                       |          |                  | <b>Total Equip</b> | <b>\$0.00</b>   |
|                                       |          |                  | <b>Total Cost</b>  | <b>\$105.93</b> |

| Item ID | Description                                   | Completed By  | Reported Hours |
|---------|---|---------------|----------------|
| 38690   | TRAVEL TO LOCATION AND REPAIR FAILED AIR LINE | Clayton Olson | 1.50           |

|                       |                               |                       |                   |
|-----------------------|-------------------------------|-----------------------|-------------------|
| <b>Work Order:</b>    | 21391                         | <b>Status:</b>        | Transferred       |
| <b>Equipment:</b>     | TRACTOR TANDEM KW T880 [9167] | <b>Serial Number:</b> | 1XKZD40XXLJ969615 |
| <b>Work Location:</b> | Rocky Mountain House Shop     | <b>Business Unit:</b> | Trucks Heavy      |
| <b>Created by:</b>    | Blair MacAulay                | <b>Start Date:</b>    | 6-16-2021         |
| <b>Kms:</b>           | 9140                          | <b>Stop Date:</b>     | 6-16-2021         |
| <b>Hr:</b>            | 9366                          |                       |                   |

**Work Order Cost Summary**

| Description | Quantity | Labor Type | Rate               | Total         |
|-------------|----------|------------|--------------------|---------------|
|             |          |            | <b>Total Labor</b> | <b>\$0.00</b> |
|             |          |            | <b>Total Parts</b> | <b>\$0.00</b> |
|             |          |            | <b>Total Equip</b> | <b>\$0.00</b> |
|             |          |            | <b>Total Cost</b>  | <b>\$0.00</b> |

| Item ID | Description | Completed By   | Reported Hours |
|---------|-------------|----------------|----------------|
| 38726   | REPAIR CEL  | Blair MacAulay | 0.00           |

|                       |                               |                       |                   |
|-----------------------|-------------------------------|-----------------------|-------------------|
| <b>Work Order:</b>    | 21427                         | <b>Status:</b>        | Transferred       |
| <b>Equipment:</b>     | TRACTOR TANDEM KW T880 [9167] | <b>Serial Number:</b> | 1XKZD40XXLJ969615 |
| <b>Work Location:</b> | Rocky Mountain House Shop     | <b>Business Unit:</b> | Trucks Heavy      |

Created by: Blair MacAulay  
 Kms: 9140  
 Hr: 9366

Start Date: 6-18-2021  
 Stop Date: 6-21-2021

**Work Order Cost Summary**

| Description | Quantity | Labor Type       | Rate               | Total          |
|-------------|----------|------------------|--------------------|----------------|
| BRENT EVANS | 1.50     | RT Shop Mech Rky | \$50.00            | \$75.00        |
|             |          |                  | <b>Total Labor</b> | <b>\$75.00</b> |
|             |          |                  | <b>Total Parts</b> | <b>\$0.00</b>  |
|             |          |                  | <b>Total Equip</b> | <b>\$0.00</b>  |
|             |          |                  | <b>Total Cost</b>  | <b>\$75.00</b> |

| Item ID | Description         | Completed By | Reported Hours |
|---------|---------------------|--------------|----------------|
| 38804   | REPAIR FOR DPF CODE | Brent Evans  | 1.50           |

Work Order: 21748  
 Equipment: TRACTOR TANDEM KW T880 [9167]  
 Work Location: Rocky Mountain House Shop, Shop Operations - RMH  
 Created by: Blair MacAulay  
 Kms: 9140  
 Hr: 9366

Status: Transferred  
 Serial Number: 1XKZD40XXLJ969615  
 Business Unit: Trucks Heavy  
 Start Date: 7-1-2021  
 Stop Date: 7-5-2021

**Work Order Cost Summary**

| Description  | Quantity | Labor Type        | Rate               | Total           |
|--|----------|-------------------|--------------------|-----------------|
| BRENT EVANS  | 7.00     | RT Shop Mech Rky  | \$50.00            | \$350.00        |
| CLAYTON OLSON  | 6.75     | RT Shop Mech Rky  | \$50.00            | \$337.50        |
| DARCY HALLOCK  | 3.25     | RT Shop Tire Tech | \$35.00            | \$113.75        |
| H. KANIELA JOHNSON   | 1.50     | RT Shop Weld Rky  | \$49.00            | \$73.50         |
|  |          |                   | <b>Total Labor</b> | <b>\$874.75</b> |
| ALARM - BACK UP (12V) [73040]                              | 1.00     | Each              | \$19.69            | \$19.69         |
| BUSHING-MOUNTING EXHAUST [M13-1009]                        | 2.00     | Each              | \$25.08            | \$50.17         |
| BUSHING-PIN ISOLATOR [M13-6001]                            | 1.00     | Each              | \$7.84             | \$7.84          |
| CAB & BUNK FILTER - W/O COVER PB 567 & KW T880 [CFR19012]  | 2.00     | Each              | \$11.25            | \$22.51         |
| CAB FILTER - PB 567 & KW T880 {PA30269JAB} [F37-1018]      | 1.00     | Each              | \$39.18            | \$39.18         |
| CAB FILTER - W/O COVER PB 567 & KW T880 [CFR19013]         | 1.00     | Each              | \$9.83             | \$9.83          |
| DRIVE TIRE - BRIDGESTONE [11R245M775]                      | 8.00     | Each              | \$543.46           | \$4,347.68      |
| ENGINE AIR FILTER {P621725} [P637453]                      | 1.00     | Each              | \$130.47           | \$130.47        |
| ENGINE LUBE FILTER {P559000, LF14000NN} [DBL7900]          | 1.00     | Each              | \$38.49            | \$38.49         |
| ENGINE LUBE FILTER {P559000, LF14000NN} [DBL7900]          | 1.00     | Each              | \$38.54            | \$38.54         |
| ENGINE SECONDARY FUEL FILTER {FF5825NN} [DBF6776]          | 1.00     | Each              | \$38.56            | \$38.56         |
| hydraulic, Spin-On [P550387 {HF6720}]                      | 2.00     | Each              | \$13.93            | \$27.87         |
| PIGTAIL - TEMPERATURE CONTROL [3823256]                    | 1.00     | Each              | \$16.67            | \$16.67         |
| PRIMARY ENGINE FUEL FILTER [P550849 {xr FS19764, FS19763}] | 1.00     | Each              | \$16.08            | \$16.08         |

|   |           |                    |            |
|---|-----------|--------------------|------------|
| SHAFT - EXHAUST [M05-1007]              | 1.00 Each | \$53.95            | \$53.95    |
| SPEEDY INV 8728-601801[Custom]          | 1.00 Each | \$400.00           | \$400.00   |
| STEER TIRE - FIRESTONE [31580R225FS819] | 2.00 Each | \$665.03           | \$1,330.06 |
| WHEEL SPACER BETWEEN RIMS [A5903]       | 2.00 Each | \$4.92             | \$9.84     |
| WHEEL SPACER BETWEEN RIMS [A5903]       | 1.00 Each | \$4.92             | \$4.92     |
|   |           | <b>Total Parts</b> | \$6,602.34 |
|   |           | <b>Total Equip</b> | \$0.00     |
|   |           | <b>Total Cost</b>  | \$7,477.09 |

| Item ID | Description  | Completed By  | Reported Hours |
|---------|--|---------------|----------------|
| 37907   | REPLACE HYDRAULIC FILTER   | Clayton Olson | 0.25           |
| 37028   | ADJUST CLUTCH AS REQUIRED - 1/2" BETWEEN CLUTCH BRAKE AND RELEASE  | Clayton Olson | 0.25           |
| 39377   | SOB - SWITCH   | Brent Evans   | 0.50           |
| 39610   | REPAIR CEL   | Clayton Olson | 0.25           |
| 39680   | REPAIR FENDERS   | Kani Johnson  | 1.50           |
| 38886   | 30k/400hr Service - All Filters Replaced<br>Perform regular check list with the below fluids & filters will be replaced every A service. | Brent Evans   | 5.00           |
| 37903   | CVIP -- Annual<br>Perform annual CVIP. Change hydraulic filter if applicable.  | Brent Evans   | 7.50           |
| 39645   | 9167- 07/01/2021 "REPLACE ALL TIRES"   | Darcy Hallock | 3.25           |

|                       |                               |                       |                   |
|-----------------------|-------------------------------|-----------------------|-------------------|
| <b>Work Order:</b>    | 22532                         | <b>Status:</b>        | Transferred       |
| <b>Equipment:</b>     | TRACTOR TANDEM KW T880 [9167] | <b>Serial Number:</b> | 1XKZD40XXLJ969615 |
| <b>Work Location:</b> | Rocky Mountain House Shop     | <b>Business Unit:</b> | Trucks Heavy      |
| <b>Created by:</b>    | Blair MacAulay                | <b>Start Date:</b>    | 7-26-2021         |
| <b>Kms:</b>           | 9140                          | <b>Stop Date:</b>     | 7-28-2021         |
| <b>Hr:</b>            | 9366                          |                       |                   |

**Work Order Cost Summary**

| Description | Quantity | Labor Type | Rate               | Total  |
|-------------|----------|------------|--------------------|--------|
|             |          |            | <b>Total Labor</b> | \$0.00 |
|             |          |            | <b>Total Parts</b> | \$0.00 |
|             |          |            | <b>Total Equip</b> | \$0.00 |
|             |          |            | <b>Total Cost</b>  | \$0.00 |

| Item ID | Description              | Completed By   | Reported Hours |
|---------|--------------------------|----------------|----------------|
| 41014   | REPAIR CAB MARKER LIGHTS | Blair MacAulay | 0.00           |

|                       |                               |                       |                   |
|-----------------------|-------------------------------|-----------------------|-------------------|
| <b>Work Order:</b>    | 24513                         | <b>Status:</b>        | Transferred       |
| <b>Equipment:</b>     | TRACTOR TANDEM KW T880 [9167] | <b>Serial Number:</b> | 1XKZD40XXLJ969615 |
| <b>Work Location:</b> | Rocky Mountain House Shop     | <b>Business Unit:</b> | Trucks Heavy      |
| <b>Created by:</b>    | Blair MacAulay                | <b>Start Date:</b>    | 10-1-2021         |
| <b>Kms:</b>           | 9140                          | <b>Stop Date:</b>     | 10-4-2021         |
| <b>Hr:</b>            | 9366                          |                       |                   |

**Work Order Cost Summary**

| Description   | Quantity | Labor Type         | Rate     | Total           |
|---|----------|--------------------|----------|-----------------|
| CLAYTON OLSON   | 2.00     | RT Shop Mech Rky   | \$50.00  | \$100.00        |
| GARRY MELVIN  | 4.50     | RT Shop Mech Rky   | \$50.00  | \$225.00        |
|   |          | <b>Total Labor</b> |          | <b>\$325.00</b> |
| CAB & BUNK FILTER - W/COVER PB 567 & KW T880 {X1987001} [CF19012] | 1.00     | Each               | \$23.16  | \$23.16         |
| CAB FILTER - PB 567 & KW T880 {PA30269JAB} [F37-1018]             | 1.00     | Each               | \$41.08  | \$41.08         |
| CAB FILTER - W/COVER PB 567 & KW T880 [CF19013]                   | 1.00     | Each               | \$25.89  | \$25.89         |
| ENGINE AIR FILTER {P621725} [P637453]                             | 1.00     | Each               | \$118.49 | \$118.49        |
| FILTER AIR {AF55836} [W2084001]                                   | 1.00     | Each               | \$10.82  | \$10.82         |
| FILTER FUEL SEPARATOR {P550849} [FS19763]                         | 1.00     | Each               | \$16.48  | \$16.48         |
| FILTER FUEL SPIN-ON {DBF6776} [FF5825NN]                          | 1.00     | Each               | \$40.74  | \$40.74         |
| FILTER LUBE SPIN-ON {DBL7900} [LF14000NN]                         | 1.00     | Each               | \$35.34  | \$35.34         |
| ADDED WASHER [HWC05782]   | 1.00     | Each               | \$6.42   | \$6.42          |
| TRIANGLE FLARE KIT [71422]  | 1.00     | Each               | \$21.08  | \$21.08         |
|   |          | <b>Total Parts</b> |          | <b>\$339.50</b> |
|   |          | <b>Total Equip</b> |          | <b>\$0.00</b>   |
|   |          | <b>Total Cost</b>  |          | <b>\$664.50</b> |

| Item ID | Description  | Completed By | Reported Hours |
|---------|--|--------------|----------------|
| 43988   | REPLACE TRANSMISSION OIL AND FILTER (IF APPLICABLE) - USE TRANS 75-90  | Garry Melvin | 1.00           |
| 42784   | 30k/400hr Service - All Filters Replaced<br>Perform regular check list with the below fluids & filters will be replaced every A service. | Garry Melvin | 5.50           |
| 41055   | ADJUST CLUTCH AS REQUIRED - 1/2" BETWEEN CLUTCH BRAKE AND RELEASE  | Garry Melvin | 0.00           |

|                       |                               |                       |                   |
|-----------------------|-------------------------------|-----------------------|-------------------|
| <b>Work Order:</b>    | 24603                         | <b>Status:</b>        | Transferred       |
| <b>Equipment:</b>     | TRACTOR TANDEM KW T880 [9167] | <b>Serial Number:</b> | 1XKZD40XXLJ969615 |
| <b>Work Location:</b> | Rocky Mountain House Shop     | <b>Business Unit:</b> | Trucks Heavy      |
| <b>Created by:</b>    | Nick Depratto                 | <b>Start Date:</b>    | 10-4-2021         |
| <b>Kms:</b>           | 9140                          | <b>Stop Date:</b>     | 10-12-2021        |
| <b>Hr:</b>            | 9366                          |                       |                   |

**Work Order Cost Summary**

| Description                                | Quantity | Labor Type       | Rate               | Total           |
|--|----------|------------------|--------------------|-----------------|
| BRETT LANGFORD                             | 3.00     | RT Shop Mech Rky | \$50.00            | \$150.00        |
|  |          |                  | <b>Total Labor</b> | <b>\$150.00</b> |
| ADIS, ADIP AIR DRYER PURGE VALVE [K022105] | 1.00     | Each             | \$114.16           | \$114.16        |
|  |          |                  | <b>Total Parts</b> | <b>\$114.16</b> |
|  |          |                  | <b>Total Equip</b> | <b>\$0.00</b>   |
|  |          |                  | <b>Total Cost</b>  | <b>\$264.16</b> |

| Item ID | Description              | Completed By  | Reported Hours |
|---------|--------------------------|---------------|----------------|
| 44958   | REPAIR CAUSE OF AIR LEAK | Nick Depratto | 3.00           |

**Work Order:** 26806      **Status:** Transferred  
**Equipment:** TRACTOR TANDEM KW T880 [9167]      **Serial Number:** 1XKZD40XXLJ969615  
**Work Location:** MAIN YARD      **Business Unit:** Trucks Heavy  
**Created by:** Darcy Hallock      **Start Date:** 1-5-2022  
**Kms:** 9140      **Stop Date:** 1-5-2022  
**Hr:** 9366

**Work Order Cost Summary**

| Description   | Quantity | Labor Type        | Rate               | Total          |
|---------------|----------|-------------------|--------------------|----------------|
| DARCY HALLOCK | 0.75     | RT Shop Tire Tech | \$35.00            | \$26.25        |
|               |          |                   | <b>Total Labor</b> | <b>\$26.25</b> |
|               |          |                   | <b>Total Parts</b> | <b>\$0.00</b>  |
|               |          |                   | <b>Total Equip</b> | <b>\$0.00</b>  |
|               |          |                   | <b>Total Cost</b>  | <b>\$26.25</b> |

| Item ID | Description                    | Completed By  | Reported Hours |
|---------|--------------------------------|---------------|----------------|
| 49463   | 9167- 01/05/2021 "FLAT REPAIR" | Darcy Hallock | 0.75           |

**Work Order:** 26975      **Status:** Transferred  
**Equipment:** TRACTOR TANDEM KW T880 [9167]      **Serial Number:** 1XKZD40XXLJ969615  
**Work Location:** Rocky Mountain House Shop      **Business Unit:** Trucks Heavy  
**Created by:** Blair MacAulay      **Start Date:** 1-13-2022  
**Kms:** 9140      **Stop Date:** 1-14-2022  
**Hr:** 9366

**Work Order Cost Summary**

| Description                         | Quantity | Labor Type       | Rate               | Total           |
|-------------------------------------|----------|------------------|--------------------|-----------------|
| BRETT LANGFORD                      | 5.50     | RT Shop Mech Rky | \$50.00            | \$275.00        |
| MITCHELL WILLERT                    | 0.50     | RT Shop Mech Rky | \$50.00            | \$25.00         |
|                                     |          |                  | <b>Total Labor</b> | <b>\$300.00</b> |
| BUSHING-MOUNTING EXHAUST [M13-1009] | 1.00     | Each             | \$25.72            | \$25.72         |

|  |           |                    |                   |
|--|-----------|--------------------|-------------------|
| BUSHING-PIN ISOLATOR [M13-6001]                            | 2.00 Each | \$8.81             | \$17.61           |
| FILTER AIR {AF55836} [W2084001]                            | 1.00 Each | \$10.90            | \$10.90           |
| FILTER AIR {P621725} [P637453]                             | 1.00 Each | \$129.15           | \$129.15          |
| FILTER AIR DRYER ADIS [5008414PG]                          | 1.00 Each | \$134.21           | \$134.21          |
| FILTER CAB - W/COVER PB 567 & KW T880 {X1987001} [CF19012] | 1.00 Each | \$13.89            | \$13.89           |
| FILTER CAB AIR W/O COVER PB 567 & KW T880 [CFR19013]       | 2.00 Each | \$10.44            | \$20.89           |
| FILTER FUEL SEPARATOR {P550849} [FS19763]                  | 1.00 Each | \$16.88            | \$16.88           |
| FILTER FUEL SPIN-ON {DBF6776} [FF5825NN]                   | 1.00 Each | \$39.56            | \$39.56           |
| FILTER LUBE SPIN-ON {DBL7900, LF1400NN} [LF14001NN]        | 1.00 Each | \$33.23            | \$33.23           |
| PEAK GLASS INV 110[Custom]                                 | 1.00 Each | \$400.00           | \$400.00          |
| RING - RADIAL RETAINING [E50STZD]                          | 1.00 Each | \$0.10             | \$0.10            |
|  |           | <b>Total Parts</b> | <b>\$842.14</b>   |
|  |           | <b>Total Equip</b> | <b>\$0.00</b>     |
|  |           | <b>Total Cost</b>  | <b>\$1,142.14</b> |

| Item ID | Description  | Completed By   | Reported Hours |
|---------|--|----------------|----------------|
| 45028   | REPLACE AIR DRYER CARTRIDGE FILTER   | Brett Langford | 0.00           |
| 47177   | 30k/400hr Service - All Filters Replaced<br>Perform regular check list with the below fluids & filters will be replaced every A service. | Brett Langford | 4.50           |
| 49843   | REPAIR LH STACK BRACKET  | Brett Langford | 0.50           |
| 45438   | ADJUST CLUTCH AS REQUIRED - 1/2" BETWEEN CLUTCH BRAKE AND RELEASE  | Brett Langford | 1.00           |
| 49610   | CHECK WINDSHIELD PT - 90012  | Brett Langford | 0.00           |

|                       |                               |                       |                   |
|-----------------------|-------------------------------|-----------------------|-------------------|
| <b>Work Order:</b>    | 27532                         | <b>Status:</b>        | Transferred       |
| <b>Equipment:</b>     | TRACTOR TANDEM KW T880 [9167] | <b>Serial Number:</b> | 1XKZD40XXLJ969615 |
| <b>Work Location:</b> | Rocky Mountain House Shop     | <b>Business Unit:</b> | Trucks Heavy      |
| <b>Created by:</b>    | Blair MacAulay                | <b>Start Date:</b>    | 2-1-2022          |
| <b>Kms:</b>           | 9140                          | <b>Stop Date:</b>     | 2-1-2022          |
| <b>Hr:</b>            | 9366                          |                       |                   |

**Work Order Cost Summary**

| Description                | Quantity | Labor Type       | Rate               | Total           |
|----------------------------|----------|------------------|--------------------|-----------------|
| BRETT LANGFORD             | 2.00     | RT Shop Mech Rky | \$50.00            | \$100.00        |
|                            |          |                  | <b>Total Labor</b> | <b>\$100.00</b> |
| HEADLAMP 23762 [H11-55/BP] | 1.00     | Each             | \$10.03            | \$10.03         |
| HEADLAMP 23762 [H11-55/BP] | 2.00     | Each             | \$9.81             | \$19.61         |
|                            |          |                  | <b>Total Parts</b> | <b>\$29.64</b>  |
|                            |          |                  | <b>Total Equip</b> | <b>\$0.00</b>   |
|                            |          |                  | <b>Total Cost</b>  | <b>\$129.64</b> |

| Item ID | Description          | Completed By   | Reported Hours |
|---------|----------------------|----------------|----------------|
| 50931   | REPLACE LH HEADLIGHT | Blair MacAulay | 2.00           |

**Work Order:** 35852 **Status:** Transferred  
**Equipment:** TRACTOR TANDEM KW T880 [9167] **Serial Number:** 1XKZD40XXLJ969615  
**Work Location:** **Business Unit:** Trucks Heavy  
**Created by:** Nick Depratto **Start Date:**  
**Kms:** 9140 **Stop Date:**  
**Hr:** 9366

**Work Order Cost Summary**

| Description                              | Quantity | Labor Type | Rate               | Total    |
|--|----------|------------|--------------------|----------|
|  |          |            | <b>Total Labor</b> | \$0.00   |
| PEAK AUTO GLASS WINDSHIELD [WINDSHEILD1] | 1.00     | Each       | \$420.00           | \$420.00 |
|  |          |            | <b>Total Parts</b> | \$420.00 |
|  |          |            | <b>Total Equip</b> | \$0.00   |
|  |          |            | <b>Total Cost</b>  | \$420.00 |

| Item ID | Description                                  | Completed By  | Reported Hours |
|---------|--|---------------|----------------|
| 66083   | WINDSHIELD - 3/24/2022 - PEAK GLASS INV# 762 | Nick Depratto | 0.00           |

**Work Order:** 30481 **Status:** Transferred  
**Equipment:** TRACTOR TANDEM KW T880 [9167] **Serial Number:** 1XKZD40XXLJ969615  
**Work Location:** Rocky Mountain House Shop **Business Unit:** Trucks Heavy  
**Created by:** Blair MacAulay **Start Date:** 4-12-2022  
**Kms:** 9140 **Stop Date:** 4-14-2022  
**Hr:** 9366

**Work Order Cost Summary**

| Description  | Quantity | Labor Type       | Rate               | Total    |
|--|----------|------------------|--------------------|----------|
| BRENT EVANS  | 2.50     | RT Shop Mech Rky | \$50.00            | \$125.00 |
| JEREMY KEDDY   | 2.50     | RT Shop Mech Rky | \$50.00            | \$125.00 |
| KIRBY BERGEN   | 1.00     | RT Shop Mech Rky | \$50.00            | \$50.00  |
|  |          |                  | <b>Total Labor</b> | \$300.00 |
| FILTER AIR {P621725} [P637453]   | 1.00     | Each             | \$145.68           | \$145.68 |
| FILTER CAB AIR W/O COVER PB 567 & KW T880 {X1987001, CFR19012} [AF55839] | 1.00     | Each             | \$18.34            | \$18.34  |
| FILTER FUEL SEPARATOR {P550849} [FS19763]                                | 1.00     | Each             | \$16.68            | \$16.68  |
| FILTER FUEL SPIN-ON {DBF6776} [FF5825NN]                                 | 1.00     | Each             | \$42.10            | \$42.10  |
| FILTER LUBE SPIN-ON {DBL7900, LF1400NN} [LF14001NN]                      | 1.00     | Each             | \$37.91            | \$37.91  |
| GLADHAND SEAL CLOSE [FS312A]   | 1.00     | Each             | \$0.58             | \$0.58   |
|  |          |                  | <b>Total Parts</b> | \$261.30 |
|  |          |                  | <b>Total Equip</b> | \$0.00   |
|  |          |                  | <b>Total Cost</b>  | \$561.30 |

| Item ID | Description  | Completed By   | Reported Hours |
|---------|--|----------------|----------------|
| 52574   | CHECK WINDSHIELD - 94394   | Blair MacAulay | 0.00           |
| 51420   | 30k/400hr Service - All Filters Replaced<br>Perform regular check list with the below fluids & filters will be replaced every A service. | Blair MacAulay | 5.25           |
| 49925   | ADJUST CLUTCH AS REQUIRED - 1/2" BETWEEN CLUTCH BRAKE AND RELEASE  | Blair MacAulay | 0.50           |
| 48477   | INSTALL NEXT YEARS ASGA STICKER  | Blair MacAulay | 0.25           |

|                       |                               |                       |                   |
|-----------------------|-------------------------------|-----------------------|-------------------|
| <b>Work Order:</b>    | 30589                         | <b>Status:</b>        | Transferred       |
| <b>Equipment:</b>     | TRACTOR TANDEM KW T880 [9167] | <b>Serial Number:</b> | 1XKZD40XXLJ969615 |
| <b>Work Location:</b> | Rocky Mountain House Shop     | <b>Business Unit:</b> | Trucks Heavy      |
| <b>Created by:</b>    | Blair MacAulay                | <b>Start Date:</b>    | 4-19-2022         |
| <b>Kms:</b>           | 9140                          | <b>Stop Date:</b>     | 4-20-2022         |
| <b>Hr:</b>            | 9366                          |                       |                   |

**Work Order Cost Summary**

| Description | Quantity | Labor Type       | Rate               | Total   |
|-------------|----------|------------------|--------------------|---------|
| BRENT EVANS | 1.00     | RT Shop Mech Rky | \$50.00            | \$50.00 |
|             |          |                  | <b>Total Labor</b> | \$50.00 |
|             |          |                  | <b>Total Parts</b> | \$0.00  |
|             |          |                  | <b>Total Equip</b> | \$0.00  |
|             |          |                  | <b>Total Cost</b>  | \$50.00 |

| Item ID | Description     | Completed By | Reported Hours |
|---------|-----------------|--------------|----------------|
| 56007   | REPAIR AIR LEAK | Brent Evans  | 1.00           |

|                       |                               |                       |                   |
|-----------------------|-------------------------------|-----------------------|-------------------|
| <b>Work Order:</b>    | 31680                         | <b>Status:</b>        | Transferred       |
| <b>Equipment:</b>     | TRACTOR TANDEM KW T880 [9167] | <b>Serial Number:</b> | 1XKZD40XXLJ969615 |
| <b>Work Location:</b> | Rocky Mountain House Shop     | <b>Business Unit:</b> | Trucks Heavy      |
| <b>Created by:</b>    | Blair MacAulay                | <b>Start Date:</b>    | 5-31-2022         |
| <b>Kms:</b>           | 9140                          | <b>Stop Date:</b>     | 6-1-2022          |
| <b>Hr:</b>            | 9366                          |                       |                   |

**Work Order Cost Summary**

| Description   | Quantity | Labor Type       | Rate               | Total   |
|---|----------|------------------|--------------------|---------|
| MITCHELL WILLERT  | 0.50     | RT Shop Mech Rky | \$50.00            | \$25.00 |
|   |          |                  | <b>Total Labor</b> | \$25.00 |
| 10 TOOTH 3/4 BORE SPROCKET [40BS1034]   | 1.00     | Each             | \$16.38            | \$16.38 |
| WASHER PUMP W/GROMMET-WASHER BOTTLE {T4695001, WB603-5402PUMP}<br>[WB6035402PUMP] | 1.00     | Each             | \$15.16            | \$15.16 |
|   |          |                  | <b>Total Parts</b> | \$31.54 |
|   |          |                  | <b>Total Equip</b> | \$0.00  |

|                   |                |
|-------------------|----------------|
| <b>Total Cost</b> | <b>\$56.54</b> |
|-------------------|----------------|

| Item ID | Description              | Completed By     | Reported Hours |
|---------|--------------------------|------------------|----------------|
| 58155   | REPAIR WINDSHIELD WASHER | Mitchell Willert | 0.50           |

|                       |                               |                       |                   |
|-----------------------|-------------------------------|-----------------------|-------------------|
| <b>Work Order:</b>    | 31823                         | <b>Status:</b>        | Transferred       |
| <b>Equipment:</b>     | TRACTOR TANDEM KW T880 [9167] | <b>Serial Number:</b> | 1XKZD40XXLJ969615 |
| <b>Work Location:</b> | MAIN YARD                     | <b>Business Unit:</b> | Trucks Heavy      |
| <b>Created by:</b>    | Darcy Hallock                 | <b>Start Date:</b>    | 6-4-2022          |
| <b>Kms:</b>           | 9140                          | <b>Stop Date:</b>     | 6-4-2022          |
| <b>Hr:</b>            | 9366                          |                       |                   |

**Work Order Cost Summary**

| Description                                   | Quantity | Labor Type        | Rate               | Total             |
|---|----------|-------------------|--------------------|-------------------|
| DARCY HALLOCK                                 | 2.00     | RT Shop Tire Tech | \$36.33            | \$72.66           |
|   |          |                   | <b>Total Labor</b> | <b>\$72.66</b>    |
| MATRESS - 31"W x 85"L [U12-6002-015]          | 1.00     | Each              | \$335.26           | \$335.26          |
| TIRE STEER - M320/FS818/XZY3 [38565R225STEER] | 2.00     | Each              | \$718.82           | \$1,437.63        |
|   |          |                   | <b>Total Parts</b> | <b>\$1,772.89</b> |
|   |          |                   | <b>Total Equip</b> | <b>\$0.00</b>     |
|   |          |                   | <b>Total Cost</b>  | <b>\$1,845.55</b> |

| Item ID | Description                       | Completed By  | Reported Hours |
|---------|-----------------------------------|---------------|----------------|
| 58530   | 9167- 06/04/2022 "REPLACE STEERS" | Darcy Hallock | 2.00           |

|                       |                               |                       |                   |
|-----------------------|-------------------------------|-----------------------|-------------------|
| <b>Work Order:</b>    | 32259                         | <b>Status:</b>        | Transferred       |
| <b>Equipment:</b>     | TRACTOR TANDEM KW T880 [9167] | <b>Serial Number:</b> | 1XKZD40XXLJ969615 |
| <b>Work Location:</b> | Rocky Mountain House Shop     | <b>Business Unit:</b> | Trucks Heavy      |
| <b>Created by:</b>    | Blair MacAulay                | <b>Start Date:</b>    | 6-23-2022         |
| <b>Kms:</b>           | 9140                          | <b>Stop Date:</b>     | 6-24-2022         |
| <b>Hr:</b>            | 9366                          |                       |                   |

**Work Order Cost Summary**

| Description                            | Quantity | Labor Type       | Rate               | Total           |
|--|----------|------------------|--------------------|-----------------|
| KIRBY BERGEN                           | 1.00     | RT Shop Mech Rky | \$49.05            | \$49.05         |
|  |          |                  | <b>Total Labor</b> | <b>\$49.05</b>  |
| 19DX COBRA MOBILE CB RADIO[Custom]     | 1.00     | Each             | (\$0.01)           | (\$0.01)        |
| CB RADIO [COBRA 19 DX IV ]             | 1.00     | Each             | \$85.00            | \$85.00         |
| COBRA 29 LID CB RADIO CLASSIC [29-LTD] | 1.00     | Each             | \$196.00           | \$196.00        |
|  |          |                  | <b>Total Parts</b> | <b>\$280.99</b> |
|  |          |                  | <b>Total Equip</b> | <b>\$0.00</b>   |

**Total Cost**     \$330.04

| Item ID | Description               | Completed By | Reported Hours |
|---------|---------------------------|--------------|----------------|
| 59386   | REPLACE CB RADIO          | Kirby Bergen | 0.50           |
| 59654   | REPLACE PTO MASTER SWITCH | Kirby Bergen | 0.25           |
| 59655   | REPLACE SIGNAL STAT       | Kirby Bergen | 0.25           |

|                       |                               |                       |                   |
|-----------------------|-------------------------------|-----------------------|-------------------|
| <b>Work Order:</b>    | 32267                         | <b>Status:</b>        | Transferred       |
| <b>Equipment:</b>     | TRACTOR TANDEM KW T880 [9167] | <b>Serial Number:</b> | 1XKZD40XXLJ969615 |
| <b>Work Location:</b> | Rocky Mountain House Shop     | <b>Business Unit:</b> | Trucks Heavy      |
| <b>Created by:</b>    | Blair MacAulay                | <b>Start Date:</b>    | 6-20-2022         |
| <b>Kms:</b>           | 9140                          | <b>Stop Date:</b>     | 6-21-2022         |
| <b>Hr:</b>            | 9366                          |                       |                   |

**Work Order Cost Summary**

| Description  | Quantity | Labor Type         | Rate       | Total           |
|--|----------|--------------------|------------|-----------------|
| BRETT LANGFORD   | 3.00     | RT Shop Mech Rky   | \$49.05    | \$147.15        |
| OLIVER TRAUTMANN   | 3.00     | RT Shop Mech Rky   | \$49.05    | \$147.15        |
|  |          | <b>Total Labor</b> |            | <b>\$294.30</b> |
| AIR DRYER COMPLETE ASSEMBLY ADIS REMAN {K049086} [5010696]       | 1.00     | Each               | \$435.69   | \$435.69        |
| AIR DRYER COMPLETE ASSEMBLY ADIS REMAN CORE {K049086} [5010696C] | 1.00     | Each               | \$219.83   | \$219.83        |
| CORE RETURN[Custom]  | 1.00     | Each               | (\$238.36) | (\$238.36)      |
| LIGHT CORD TRAILER 4 WAY 15' [194015]                            | 1.00     | Each               | \$45.26    | \$45.26         |
| LIGHT PIGTAIL SEALED MARKER [67050]                              | 1.00     | Each               | \$1.31     | \$1.31          |
| LIGHT RED CLEARANCE MARKER 2" LED [G3002]                        | 1.00     | Each               | \$6.62     | \$6.62          |
| SPST ROCKER SWITCH KIT[Custom]                                   | 1.00     | Each               | \$19.18    | \$19.18         |
|  |          | <b>Total Parts</b> |            | <b>\$489.53</b> |
|  |          | <b>Total Equip</b> |            | <b>\$0.00</b>   |
|  |          | <b>Total Cost</b>  |            | <b>\$783.83</b> |

| Item ID | Description                           | Completed By   | Reported Hours |
|---------|---------------------------------------|----------------|----------------|
| 59423   | REPLACE MATTRESS                      | Blair MacAulay | 0.00           |
| 59407   | REPLACE 4 WIRE CORD AND FUNCTION TEST | Blair MacAulay | 1.00           |
| 59406   | REPLACE PTO MASTER SWITCH             | Blair MacAulay | 0.00           |
| 59393   | TROUBLESHOOT SUSPENSION DROPPING      | Blair MacAulay | 5.00           |
| 59392   | REPAIR AIR LEAKS                      | Blair MacAulay | 0.00           |

|                       |                               |                       |                   |
|-----------------------|-------------------------------|-----------------------|-------------------|
| <b>Work Order:</b>    | 32625                         | <b>Status:</b>        | Transferred       |
| <b>Equipment:</b>     | TRACTOR TANDEM KW T880 [9167] | <b>Serial Number:</b> | 1XKZD40XXLJ969615 |
| <b>Work Location:</b> | Rocky Mountain House Shop     | <b>Business Unit:</b> | Trucks Heavy      |
| <b>Created by:</b>    | Blair MacAulay                | <b>Start Date:</b>    | 7-4-2022          |
| <b>Kms:</b>           | 9140                          | <b>Stop Date:</b>     | 7-5-2022          |
| <b>Hr:</b>            | 9366                          |                       |                   |

**Work Order Cost Summary**

| Description  | Quantity | Labor Type         | Rate    | Total           |
|--|----------|--------------------|---------|-----------------|
| BRETT LANGFORD   | 6.00     | RT Shop Mech Rky   | \$49.05 | \$294.30        |
| OLIVER TRAUTMANN   | 4.00     | RT Shop Mech Rky   | \$49.05 | \$196.20        |
|  |          | <b>Total Labor</b> |         | <b>\$490.50</b> |
| ALCOHOL INJECTOR [A72420]  | 1.00     | Each               | \$39.41 | \$39.41         |
| FILTER CAB AIR W/O COVER PB 567 & KW T880 {X1987001, CFR19012} [AF55839] | 1.00     | Each               | \$2.09  | \$2.09          |
| FILTER FUEL SEPARATOR {P550849}{FS19764} [FS19763]                       | 1.00     | Each               | \$17.33 | \$17.33         |
| FILTER FUEL SPIN-ON {DBF6776} [FF5825NN]                                 | 1.00     | Each               | \$47.35 | \$47.35         |
| FILTER HYDRAULIC SPIN-ON {P550387} [HF6720]                              | 2.00     | Each               | \$17.23 | \$34.46         |
| FILTER LUBE SPIN-ON {DBL7900, LF14000NN} [LF14001NN]                     | 1.00     | Each               | \$36.11 | \$36.11         |
|  |          | <b>Total Parts</b> |         | <b>\$176.75</b> |
|  |          | <b>Total Equip</b> |         | <b>\$0.00</b>   |
|  |          | <b>Total Cost</b>  |         | <b>\$667.25</b> |

| Item ID | Description                              | Completed By   | Reported Hours |
|---------|--|----------------|----------------|
| 57862   | 30k/400hr Service - All Filters Replaced | Blair MacAulay | 9.50           |

Perform regular check list with the below fluids & filters will be replaced every A service.

|       |   |                |      |
|-------|---|----------------|------|
| 59996 | ADJUST CLUTCH AS REQUIRED - 1/2" BETWEEN CLUTCH BRAKE AND RELEASE | Blair MacAulay | 0.50 |
|-------|---|----------------|------|

|                       |                               |                       |                   |
|-----------------------|-------------------------------|-----------------------|-------------------|
| <b>Work Order:</b>    | 32889                         | <b>Status:</b>        | Transferred       |
| <b>Equipment:</b>     | TRACTOR TANDEM KW T880 [9167] | <b>Serial Number:</b> | 1XKZD40XXLJ969615 |
| <b>Work Location:</b> | Rocky Mountain House Shop     | <b>Business Unit:</b> | Trucks Heavy      |
| <b>Created by:</b>    | Blair MacAulay                | <b>Start Date:</b>    | 7-11-2022         |
| <b>Kms:</b>           | 9140                          | <b>Stop Date:</b>     | 7-11-2022         |
| <b>Hr:</b>            | 9366                          |                       |                   |

**Work Order Cost Summary**

| Description                          | Quantity | Labor Type         | Rate    | Total           |
|--------------------------------------|----------|--------------------|---------|-----------------|
| CLAYTON OLSON                        | 1.25     | RT Shop Mech Rky   | \$49.05 | \$61.31         |
|                                      |          | <b>Total Labor</b> |         | <b>\$61.31</b>  |
| 60A CIRCUIT BREAKER [CB-060F]        | 2.00     | Each               | \$56.29 | \$112.58        |
| SCREW - WING M10X1.5X40MM [HWC09341] | 2.00     | Each               | \$10.91 | \$21.83         |
|                                      |          | <b>Total Parts</b> |         | <b>\$134.41</b> |
|                                      |          | <b>Total Equip</b> |         | <b>\$0.00</b>   |
|                                      |          | <b>Total Cost</b>  |         | <b>\$195.72</b> |

| Item ID | Description                     | Completed By  | Reported Hours |
|---------|---------------------------------|---------------|----------------|
| 537     | UPGRADE BREAKERS IN BATTREY BOX | Clayton Olson | 0.75           |
| 60535   | REPAIR BATTERY BOX BOLTS        | Clayton Olson | 0.50           |

|                       |                               |                       |                   |
|-----------------------|-------------------------------|-----------------------|-------------------|
| <b>Work Order:</b>    | 33243                         | <b>Status:</b>        | Transferred       |
| <b>Equipment:</b>     | TRACTOR TANDEM KW T880 [9167] | <b>Serial Number:</b> | 1XKZD40XXLJ969615 |
| <b>Work Location:</b> | Rocky Mountain House Shop     | <b>Business Unit:</b> | Trucks Heavy      |
| <b>Created by:</b>    | Blair MacAulay                | <b>Start Date:</b>    | 7-21-2022         |
| <b>Kms:</b>           | 9140                          | <b>Stop Date:</b>     | 7-25-2022         |
| <b>Hr:</b>            | 9366                          |                       |                   |

#### Work Order Cost Summary

| Description                                     | Quantity | Labor Type       | Rate               | Total           |
|---|----------|------------------|--------------------|-----------------|
| H. KANIELA JOHNSON                              | 2.00     | RT Shop Weld Rky | \$47.83            | \$95.66         |
| JEREMY KEDDY                                    | 5.00     | RT Shop Mech Rky | \$49.05            | \$245.25        |
| MICHAEL GATES                                   | 10.75    | RT Shop Mech Rky | \$49.05            | \$527.29        |
|   |          |                  | <b>Total Labor</b> | <b>\$868.20</b> |
| FILTER HYDRAULIC SPIN-ON {P550387} [HF6720]     | 2.00     | Each             | \$17.23            | \$34.46         |
| HANGER- MUDFLAP 32 1/2" [A253275RL]             | 1.00     | Each             | \$23.81            | \$23.81         |
| HYDRAULIC FILTER [BT287-10]                     | 1.00     | Each             | \$19.45            | \$19.45         |
| SPACER [E80-1027]                               | 2.00     | Each             | \$4.62             | \$9.24          |
| SUMMER TRUCK WIPER BLADE 22" - J-HOOK [WP22031] | 1.00     | Each             | \$4.72             | \$4.72          |
|   |          |                  | <b>Total Parts</b> | <b>\$91.68</b>  |
|   |          |                  | <b>Total Equip</b> | <b>\$0.00</b>   |
|   |          |                  | <b>Total Cost</b>  | <b>\$959.87</b> |

| Item ID | Description   | Completed By | Reported Hours |
|---------|---|--------------|----------------|
| 56190   | ADJUST CLUTCH AS REQUIRED - 1/2" BETWEEN CLUTCH BRAKE AND RELEASE | Mike Gates   | 0.50           |
| 61192   | REPAIR AIR LEAKS  | Mike Gates   | 2.50           |
| 61213   | TIGHTEN BATTERIES   | Mike Gates   | 1.00           |
| 61196   | REPAIR MUD FLAPS  | Mike Gates   | 0.50           |
| 61194   | REPAIR BAR HOLDER ON HEADACHE RACK                                | Kani Johnson | 1.00           |
| 60048   | CVIP -- Annual  | Mike Gates   | 10.00          |
| 61195   | REPAIR REAR FENDERS   | Kani Johnson | 1.00           |
| 3385    | REPLACE HYDRAULIC FILTER  | Mike Gates   | 0.25           |
| 61193   | REPLACE REAR TRANSMISSION MOUNT SPACERS                           | Mike Gates   | 1.00           |

**Work Order:** 33336  
**Equipment:** TRACTOR TANDEM KW T880 [9167]  
**Work Location:** Shop Operations - RMH  
**Created by:** Darcy Hallock  
**Kms:** 9140  
**Hr:** 9366

**Status:** Transferred  
**Serial Number:** 1XKZD40XXLJ969615  
**Business Unit:** Trucks Heavy  
**Start Date:** 7-22-2022  
**Stop Date:** 7-22-2022

**Work Order Cost Summary**

| Description   | Quantity | Labor Type        | Rate               | Total   |
|---------------|----------|-------------------|--------------------|---------|
| DARCY HALLOCK | 0.75     | RT Shop Tire Tech | \$36.33            | \$27.25 |
|               |          |                   | <b>Total Labor</b> | \$27.25 |
|               |          |                   | <b>Total Parts</b> | \$0.00  |
|               |          |                   | <b>Total Equip</b> | \$0.00  |
|               |          |                   | <b>Total Cost</b>  | \$27.25 |

| Item ID | Description                             | Completed By  | Reported Hours |
|---------|---|---------------|----------------|
| 61283   | 9167- 07/22/2022 "INSTALL RUNOUTS (X2)" | Darcy Hallock | 0.75           |

**Work Order:** 33817  
**Equipment:** TRACTOR TANDEM KW T880 [9167]  
**Work Location:** Rocky Mountain House Shop  
**Created by:** Blair MacAulay  
**Kms:** 9140  
**Hr:** 9366

**Status:** Transferred  
**Serial Number:** 1XKZD40XXLJ969615  
**Business Unit:** Trucks Heavy  
**Start Date:** 8-8-2022  
**Stop Date:** 8-9-2022

**Work Order Cost Summary**

| Description                     | Quantity | Labor Type       | Rate               | Total    |
|---------------------------------|----------|------------------|--------------------|----------|
| BRETT LANGFORD                  | 3.00     | RT Shop Mech Rky | \$49.05            | \$147.15 |
|                                 |          |                  | <b>Total Labor</b> | \$147.15 |
| MOTHERS -X REF 35316 [MOT35316] | 1.00     | Each             | \$9.42             | \$9.42   |
|                                 |          |                  | <b>Total Parts</b> | \$9.42   |
|                                 |          |                  | <b>Total Equip</b> | \$0.00   |
|                                 |          |                  | <b>Total Cost</b>  | \$156.57 |

| Item ID | Description                   | Completed By   | Reported Hours |
|---------|-------------------------------|----------------|----------------|
| 62095   | REPAIR LEAK AT HYDRAULIC TANK | Brett Langford | 3.00           |

**Work Order:** 34418  
**Equipment:** TRACTOR TANDEM KW T880 [9167]  
**Work Location:** Rocky Mountain House Shop  
**Created by:** Blair MacAulay

**Status:** Transferred  
**Serial Number:** 1XKZD40XXLJ969615  
**Business Unit:** Trucks Heavy  
**Start Date:** 8-26-2022

Kms: 9140  
 Hr: 9366

Stop Date: 8-29-2022

**Work Order Cost Summary**

| description   | Quantity | Labor Type       | Rate     | Total             |
|---|----------|------------------|----------|-------------------|
| BRENT EVANS   | 7.00     | RT Shop Mech Rky | \$49.05  | \$343.35          |
| H. KANIELA JOHNSON  | 2.00     | RT Shop Weld Rky | \$47.83  | \$95.66           |
| KIRBY BERGEN  | 6.00     | RT Shop Mech Rky | \$49.05  | \$294.30          |
| <b>Total Labor</b>  |          |                  |          | <b>\$733.31</b>   |
| BLOWER MOTOR ASSY [CR705001]  | 1.00     | Each             | \$493.79 | \$493.79          |
| CLUTCH BRAKE [C127200]  | 1.00     | Each             | \$45.61  | \$45.61           |
| CLUTCH BRAKE 2"[Custom]   | 1.00     | Each             | \$55.04  | \$55.04           |
| DEF TANK CAP- NON VENTED DEF TANK [908-0223-01]                                     | 1.00     | Each             | \$32.60  | \$32.60           |
| FILTER AIR {AF55836, SR2000091} [W2084001]  | 1.00     | Each             | \$10.98  | \$10.98           |
| FILTER AIR {P621725} [P637453]  | 1.00     | Each             | \$150.11 | \$150.11          |
| FILTER CAB AIR W/O COVER PB 567 & KW T880 {X1987001, CFR19012, SR2000092} [AF55839] | 2.00     | Each             | \$19.85  | \$39.70           |
| FILTER FUEL SEPARATOR {P550849, FS19764} [FS19763]                                  | 1.00     | Each             | \$18.28  | \$18.28           |
| FILTER FUEL SPIN-ON {DBF6776, FF5971NN} [FF5825NN]                                  | 1.00     | Each             | \$51.54  | \$51.54           |
| FILTER LUBE SPIN-ON {DBL7900, LF14000NN} [LF14001NN]                                | 1.00     | Each             | \$45.08  | \$45.08           |
| GLADHAND SEAL CLOSE [FS312A]  | 1.00     | Each             | \$0.65   | \$0.65            |
| ILS PINS AND BUSHINGS [RK10605]   | 1.00     | Each             | \$66.98  | \$66.98           |
| <b>Total Parts</b>  |          |                  |          | <b>\$1,010.36</b> |
| <b>Total Equip</b>  |          |                  |          | <b>\$0.00</b>     |
| <b>Total Cost</b>   |          |                  |          | <b>\$1,743.67</b> |

| Item ID  | Description   | Completed By   | Reported Hours |
|--|---|----------------|----------------|
| 61169  | 30k/400hr Service - All Filters Replaced                          | Brent Evans    | 8.50           |
| Perform regular check list with the below fluids & filters will be replaced every A service. |   |                |                |
| 63297  | CHECK A/C   | Blair MacAulay | 0.00           |
| 63208  | REPAIR CLUTCH BRAKE   | Brent Evans    | 3.50           |
| 62903  | ADJUST CLUTCH AS REQUIRED - 1/2" BETWEEN CLUTCH BRAKE AND RELEASE | Blair MacAulay | 0.00           |
| 61794  | 9167 - SOB - TRANSMISSION SUPPORT SPACERS                         | Brent Evans    | 1.00           |
| 63209  | REPAIR FENDERS  | Brent Evans    | 1.00           |
| 63306  | REPLACE 5TH WHEEL SADDLE PINS AND BUSHINGS                        | Brent Evans    | 1.00           |

Work Order: 34490  
 Equipment: TRACTOR TANDEM KW T880 [9167]  
 Work Location: Shop Operations - RMH

Status: Transferred  
 Serial Number: 1XKZD40XXLJ969615  
 Business Unit: Trucks Heavy

Created by: Darcy Hallock  
Kms: 9140  
Hr: 9366

Start Date: 8-27-2022  
Stop Date: 8-27-2022

**Work Order Cost Summary**

| Description                           | Quantity | Labor Type        | Rate               | Total      |
|---------------------------------------|----------|-------------------|--------------------|------------|
| DARCY HALLOCK                         | 4.00     | RT Shop Tire Tech | \$36.33            | \$145.32   |
|                                       |          |                   | <b>Total Labor</b> | \$145.32   |
| BLOWER MOTOR ASSY [CR705001]          | 1.00     | Each              | \$493.79           | \$493.79   |
| TIRE DRIVE - M775/BDY2 [11R245DRIVE6] | 8.00     | Each              | \$485.65           | \$3,885.23 |
|                                       |          |                   | <b>Total Parts</b> | \$4,379.02 |
|                                       |          |                   | <b>Total Equip</b> | \$0.00     |
|                                       |          |                   | <b>Total Cost</b>  | \$4,524.34 |

| Item ID | Description                            | Completed By  | Reported Hours |
|---------|--|---------------|----------------|
| 63364   | 9167- 08/27/2022 "REPLACE DRIVES (X8)" | Darcy Hallock | 4.00           |

Work Order: 35465      Status: Transferred  
Equipment: TRACTOR TANDEM KW T880 [9167]      Serial Number: 1XKZD40XXLJ969615  
Work Location: Rocky Mountain House Shop      Business Unit: Trucks Heavy  
Created by: Blair MacAulay      Start Date: 9-29-2022  
Kms: 9140      Stop Date: 10-3-2022  
Hr: 9366

**Work Order Cost Summary**

| Description                               | Quantity | Labor Type       | Rate               | Total      |
|---|----------|------------------|--------------------|------------|
| BRENT EVANS                               | 4.50     | RT Shop Mech Rky | \$49.05            | \$220.73   |
| JEREMY KEDDY                              | 1.00     | RT Shop Mech Rky | \$49.05            | \$49.05    |
|   |          |                  | <b>Total Labor</b> | \$269.78   |
| BLOWER MOTOR ASSY {CR705001} [CR705002]   | 1.00     | Each             | \$493.79           | \$493.79   |
| FLEX PIPE [M74-1020-001]                  | 1.00     | Each             | \$886.96           | \$886.96   |
| LIGHT PIGTAIL SEALED MARKER [67050]       | 4.00     | Each             | \$1.30             | \$5.22     |
| LIGHT RED CLEARANCE MARKER 2" LED [G3002] | 2.00     | Each             | \$7.24             | \$14.49    |
| SCREW - WING M10X1.5X40MM [HWC09341]      | 1.00     | Each             | \$11.56            | \$11.56    |
| SOLENOID [8345G1DC]                       | 1.00     | Each             | \$462.50           | \$462.50   |
|   |          |                  | <b>Total Parts</b> | \$1,874.51 |
|   |          |                  | <b>Total Equip</b> | \$0.00     |
|   |          |                  | <b>Total Cost</b>  | \$2,144.29 |

| Item ID | Description              | Completed By | Reported Hours |
|---------|--------------------------|--------------|----------------|
| 65373   | REPLACE AIR DRYER        | Brent Evans  | 2.00           |
| 65374   | REPAIR LH REAR FENDER    | Brent Evans  | 0.00           |
| 63448   | 9167 - SOB - BLOWER ASSY | Brent Evans  | 1.50           |

|       |                      |             |      |
|-------|----------------------|-------------|------|
| 63952 | 9167 - SOB - cab fan | Brent Evans | 0.00 |
| 65347 | REPAIR AIR LEAKS     | Brent Evans | 2.00 |

|                       |                               |                       |                   |
|-----------------------|-------------------------------|-----------------------|-------------------|
| <b>Work Order:</b>    | 36116                         | <b>Status:</b>        | Transferred       |
| <b>Equipment:</b>     | TRACTOR TANDEM KW T880 [9167] | <b>Serial Number:</b> | 1XKZD40XXLJ969615 |
| <b>Work Location:</b> | Rocky Mountain House Shop     | <b>Business Unit:</b> | Trucks Heavy      |
| <b>Created by:</b>    | Blair MacAulay                | <b>Start Date:</b>    | 10-19-2022        |
| <b>Kms:</b>           | 9140                          | <b>Stop Date:</b>     | 10-21-2022        |
| <b>Hr:</b>            | 9366                          |                       |                   |

**Work Order Cost Summary**

| Description   | Quantity | Labor Type         | Rate     | Total           |
|---|----------|--------------------|----------|-----------------|
| JEREMY KEDDY  | 5.25     | RT Shop Mech Rky   | \$49.05  | \$257.51        |
| MICHAEL GATES   | 3.75     | RT Shop Mech Rky   | \$49.05  | \$183.94        |
|   |          | <b>Total Labor</b> |          | <b>\$441.45</b> |
| FILTER AIR {P621725} [P637453]  | 1.00     | Each               | \$151.44 | \$151.44        |
| FILTER CAB AIR W/O COVER PB 567 & KW T880 {X1987001, CFR19012, SR2000092} [AF55839] | 1.00     | Each               | \$20.70  | \$20.70         |
| FILTER FUEL SEPARATOR {P550849, FS19764} [FS19763]                                  | 1.00     | Each               | \$19.93  | \$19.93         |
| FILTER FUEL SPIN-ON {DBF6776, FF5971NN} [FF5825NN]                                  | 1.00     | Each               | \$49.79  | \$49.79         |
| FILTER LUBE SPIN-ON {DBL7900, LF14000NN} [LF14001NN]                                | 1.00     | Each               | \$41.62  | \$41.62         |
| FILTER LUBE SPIN-ON {P550335} [LF3335]  | 1.00     | Each               | \$8.11   | \$8.11          |
|   |          | <b>Total Parts</b> |          | <b>\$291.59</b> |
|   |          | <b>Total Equip</b> |          | <b>\$0.00</b>   |
|   |          | <b>Total Cost</b>  |          | <b>\$733.04</b> |

| Item ID | Description  | Completed By | Reported Hours |
|---------|--|--------------|----------------|
| 64809   | REPLACE TRANSMISSION OIL AND FILTER (IF APPLICABLE) - USE TRANS 75-90  | Mike Gates   | 0.25           |
| 65774   | REPLACE AIR DRYER CARTRIDGE FILTER   | Mike Gates   | 0.25           |
| 66254   | SOB - FLEX PIPE<br>1 - M74-1020-001 - FLEX PIPE  | Mike Gates   | 2.50           |
| 64788   | 30k/400hr Service - All Filters Replaced<br>Perform regular check list with the below fluids & filters will be replaced every A service. | Mike Gates   | 6.00           |

|                       |                               |                       |                   |
|-----------------------|-------------------------------|-----------------------|-------------------|
| <b>Work Order:</b>    | 36217                         | <b>Status:</b>        | Transferred       |
| <b>Equipment:</b>     | TRACTOR TANDEM KW T880 [9167] | <b>Serial Number:</b> | 1XKZD40XXLJ969615 |
| <b>Work Location:</b> | MAIN YARD                     | <b>Business Unit:</b> | Trucks Heavy      |
| <b>Created by:</b>    | Darcy Hallock                 | <b>Start Date:</b>    | 10-21-2022        |
| <b>Kms:</b>           | 9140                          | <b>Stop Date:</b>     | 10-21-2022        |
| <b>Hr:</b>            | 9366                          |                       |                   |



Kms: 9140  
Hr: 9366

Stop Date: 11-7-2022

**Work Order Cost Summary**

| Description   | Quantity | Labor Type       | Rate               | Total   |
|---------------|----------|------------------|--------------------|---------|
| MICHAEL GATES | 1.00     | RT Shop Mech Rky | \$49.05            | \$49.05 |
|               |          |                  | <b>Total Labor</b> | \$49.05 |
|               |          |                  | <b>Total Parts</b> | \$0.00  |
|               |          |                  | <b>Total Equip</b> | \$0.00  |
|               |          |                  | <b>Total Cost</b>  | \$49.05 |

| Item ID | Description       | Completed By | Reported Hours |
|---------|-------------------|--------------|----------------|
| 67680   | TIGHTEN RR FENDER | Mike Gates   | 1.00           |

**Work Order:** 36857      **Status:** Transferred  
**Equipment:** TRACTOR TANDEM KW T880 [9167]      **Serial Number:** 1XKZD40XXLJ969615  
**Work Location:** Rocky Mountain House Shop      **Business Unit:** Trucks Heavy  
**Created by:** Blair MacAulay      **Start Date:** 11-9-2022  
**Kms:** 9140      **Stop Date:** 11-10-2022  
**Hr:** 9366

**Work Order Cost Summary**

| Description | Quantity | Labor Type       | Rate               | Total   |
|-------------|----------|------------------|--------------------|---------|
| BRENT EVANS | 2.00     | RT Shop Mech Rky | \$49.05            | \$98.10 |
|             |          |                  | <b>Total Labor</b> | \$98.10 |
|             |          |                  | <b>Total Parts</b> | \$0.00  |
|             |          |                  | <b>Total Equip</b> | \$0.00  |
|             |          |                  | <b>Total Cost</b>  | \$98.10 |

| Item ID | Description         | Completed By   | Reported Hours |
|---------|---------------------|----------------|----------------|
| 68025   | REPAIR DUMP CONTROL | Blair MacAulay | 2.00           |

**Work Order:** 37009      **Status:** Transferred  
**Equipment:** TRACTOR TANDEM KW T880 [9167]      **Serial Number:** 1XKZD40XXLJ969615  
**Work Location:** Rocky Mountain House Shop      **Business Unit:** Trucks Heavy  
**Created by:** Blair MacAulay      **Start Date:** 11-18-2022  
**Kms:** 9140      **Stop Date:** 11-21-2022  
**Hr:** 9366

**Work Order Cost Summary**

| Description        | Quantity | Labor Type       | Rate    | Total    |
|--------------------|----------|------------------|---------|----------|
| BRENT EVANS        | 2.00     | RT Shop Mech Rky | \$49.05 | \$98.10  |
| H. KANIELA JOHNSON | 3.00     | RT Shop Weld Rky | \$47.83 | \$143.49 |
| MAXWELL KRABBEN    | 4.00     | RT Shop Mech Rky | \$49.05 | \$196.20 |

|  |           |  | Total Labor        | \$437.79          |
|--|-----------|--|--------------------|-------------------|
| CLUTCH BRAKE {C127200} [SB200]   | 1.00 Each |  | \$42.63            | \$42.63           |
| HYDRAULIC PUMP - GRAVEL TRUCK APPLICATION {DMD25ZLAS250}<br>[HC102LAS25] | 1.00 Each |  | \$676.46           | \$676.46          |
| INDICATOR SWITCH [380515]  | 1.00 Each |  | \$18.15            | \$18.15           |
| LIGHT RED ROUND 4" STOP TAIL TURN LED W/SEALED CONNECTOR [54362]         | 1.00 Each |  | \$17.13            | \$17.13           |
| PTO LIGHT SWITCH[Custom]   | 1.00 Each |  | \$40.63            | \$40.63           |
|  |           |  | <b>Total Parts</b> | <b>\$795.00</b>   |
|  |           |  | <b>Total Equip</b> | <b>\$0.00</b>     |
|  |           |  | <b>Total Cost</b>  | <b>\$1,232.79</b> |

| Item ID | Description   | Completed By   | Reported Hours |
|---------|---|----------------|----------------|
| 65514   | ADJUST CLUTCH AS REQUIRED - 1/2" BETWEEN CLUTCH BRAKE AND RELEASE | Blair MacAulay | 4.00           |
| 68313   | REPAIR TAIL LIGHT   | Blair MacAulay | 2.00           |
| 67222   | SOB - FENDERS<br>2 - FENDERS - F301-55-SS                         | Blair MacAulay | 3.00           |
| 67856   | INSTALL QR WHEEL RETORQ STICKER ON THE INSIDE DRIVER SIDE WINDOW  | Blair MacAulay | 0.00           |

|                       |                               |                       |                   |
|-----------------------|-------------------------------|-----------------------|-------------------|
| <b>Work Order:</b>    | 38105                         | <b>Status:</b>        | Transferred       |
| <b>Equipment:</b>     | TRACTOR TANDEM KW T880 [9167] | <b>Serial Number:</b> | 1XKZD40XXLJ969615 |
| <b>Work Location:</b> | Rocky Mountain House Shop     | <b>Business Unit:</b> | Trucks Heavy      |
| <b>Created by:</b>    | Blair MacAulay                | <b>Start Date:</b>    | 12-20-2022        |
| <b>Kms:</b>           | 9140                          | <b>Stop Date:</b>     | 1-3-2023          |
| <b>Hr:</b>            | 9366                          |                       |                   |

#### Work Order Cost Summary

| Description   | Quantity | Labor Type       | Rate               | Total             |
|---|----------|------------------|--------------------|-------------------|
| BRENT EVANS   | 10.00    | RT Shop Mech Rky | \$49.05            | \$490.50          |
| MICHAEL GATES   | 9.50     | RT Shop Mech Rky | \$49.05            | \$465.98          |
|   |          |                  | <b>Total Labor</b> | <b>\$956.48</b>   |
| FILTER AIR {P621725} [P637453]  | 1.00     | Each             | \$151.54           | \$151.54          |
| FILTER CAB AIR W/O COVER PB 567 & KW T880 {X1987001, CFR19012, SR2000092} [AF55839] | 1.00     | Each             | \$39.60            | \$39.60           |
| FILTER FUEL SEPARATOR {P550849, FS19764} [FS19763]                                  | 1.00     | Each             | \$22.30            | \$22.30           |
| FILTER FUEL SPIN-ON {DBF6776,FF5971NN} [FF5825NN]                                   | 1.00     | Each             | \$50.54            | \$50.54           |
| FILTER LUBE SPIN-ON {DBL7900, LF14000NN} [LF14001NN]                                | 1.00     | Each             | \$43.48            | \$43.48           |
| LIGHT GROMMET CLOSED BACK 4" ROUND [91950]  | 1.00     | Each             | \$3.40             | \$3.40            |
| LIGHT PIGTAIL 2PIN 3PORT 90DEG [67016]  | 1.00     | Each             | \$5.23             | \$5.23            |
| LIGHT PIGTAIL STOP,TAIL,TURN THREE WIRE [67002]                                     | 2.00     | Each             | \$3.69             | \$7.39            |
| LIGHT WHITE ROUND 4" LED BACK UP [62121]  | 2.00     | Each             | \$11.31            | \$22.63           |
|   |          |                  | <b>Total Parts</b> | <b>\$346.10</b>   |
|   |          |                  | <b>Total Equip</b> | <b>\$0.00</b>     |
|   |          |                  | <b>Total Cost</b>  | <b>\$1,302.58</b> |

| Item ID | Description                       | Completed By   | Reported Hours |
|---------|-----------------------------------|----------------|----------------|
| 70454   | REPAIR PTO                        | Blair MacAulay | 5.50           |
| 70455   | INSTALL NEXT YEARS ASGA STICKER   | Blair MacAulay | 0.00           |
| 70455   | REPAIR ENGINE HEATER              | Blair MacAulay | 0.00           |
| 70530   | REPLACE CLUTCH BRAKE              | Blair MacAulay | 4.50           |
| 70453   | 30K SERVICE - REPLACE ALL FILTERS | Blair MacAulay | 9.50           |

**Work Order:** 38471 **Status:** Transferred  
**Equipment:** TRACTOR TANDEM KW T880 [9167] **Serial Number:** 1XKZD40XXLJ969615  
**Work Location:** Shop Operations - RMH **Business Unit:** Trucks Heavy  
**Created by:** Jeremy Keddy **Start Date:** 1-9-2023  
**Kms:** 9140 **Stop Date:** 1-9-2023  
**Hr:** 9366

**Work Order Cost Summary**

| Description  | Quantity | Labor Type       | Rate               | Total          |
|--|----------|------------------|--------------------|----------------|
| JEREMY KEDDY   | 1.00     | RT Shop Mech Rky | \$49.05            | \$49.05        |
|  |          |                  | <b>Total Labor</b> | <b>\$49.05</b> |
| WINTER TRUCK WIPER BLADE 22" J-HOOK {XR WW22-10} [WW22012] | 2.00     | Each             | \$17.02            | \$34.05        |
|  |          |                  | <b>Total Parts</b> | <b>\$34.05</b> |
|  |          |                  | <b>Total Equip</b> | <b>\$0.00</b>  |
|  |          |                  | <b>Total Cost</b>  | <b>\$83.10</b> |

| Item ID | Description           | Completed By | Reported Hours |
|---------|-----------------------|--------------|----------------|
| 71063   | Repair hydraulic line | Jeremy Keddy | 1.00           |
| 262085  | km                    |              |                |

**Work Order:** 39586 **Status:** Transferred  
**Equipment:** TRACTOR TANDEM KW T880 [9167] **Serial Number:** 1XKZD40XXLJ969615  
**Work Location:** Rocky Mountain House Shop **Business Unit:** Trucks Heavy  
**Created by:** Blair MacAulay **Start Date:** 2-10-2023  
**Kms:** 9140 **Stop Date:** 2-14-2023  
**Hr:** 9366

**Work Order Cost Summary**

| Description                                    | Quantity | Labor Type       | Rate               | Total           |
|--|----------|------------------|--------------------|-----------------|
| JEREMY KEDDY                                   | 0.50     | RT Shop Mech Rky | \$49.05            | \$24.53         |
| MICHAEL GATES                                  | 2.50     | RT Shop Mech Rky | \$49.05            | \$122.63        |
|  |          |                  | <b>Total Labor</b> | <b>\$147.15</b> |
| HOSE HYDRAULIC 1" 4 WIRE 4000PSI [722TC-16-RL] | 13.00    | Foot             | \$1.83             | \$23.79         |
| MNPT- CRIMP [10143-16-16]                      | 2.00     | Each             | \$29.31            | \$58.62         |

Total Parts \$82.41

Total Equip \$0.00

Total Cost \$229.56

| Item ID | Description                     | Completed By   | Reported Hours |
|---------|---------------------------------|----------------|----------------|
| 72944   | REPAIR HYDRAULIC CONTROL        | Blair MacAulay | 3.00           |
| 72948   | REPLACE PRESSURE SWITCH         | Blair MacAulay | 0.00           |
| 72949   | REPLACE HYDRAULIC RETURN HOSE   | Blair MacAulay | 0.00           |
| 69532   | 9167 - SOB PTO PRESSURE SWQITCH | Blair MacAulay | 0.00           |

**Work Order:** 39803      **Status:** Transferred  
**Equipment:** TRACTOR TANDEM KW T880 [9167]      **Serial Number:** 1XKZD40XXLJ969615  
**Work Location:**      **Business Unit:** Trucks Heavy  
**Created by:** Blair MacAulay      **Start Date:**  
**Kms:** 9140      **Stop Date:**  
**Hr:** 9366

**Work Order Cost Summary**

| Description | Quantity | Labor Type | Rate               | Total  |
|-------------|----------|------------|--------------------|--------|
|             |          |            | <b>Total Labor</b> | \$0.00 |
|             |          |            | <b>Total Parts</b> | \$0.00 |
|             |          |            | <b>Total Equip</b> | \$0.00 |
|             |          |            | <b>Total Cost</b>  | \$0.00 |

| Item ID | Description      | Completed By   | Reported Hours |
|---------|------------------|----------------|----------------|
| 73305   | REPAIR RR FENDER | Blair MacAulay | 0.00           |

**Work Order:** 40356      **Status:** Transferred  
**Equipment:** TRACTOR TANDEM KW T880 [9167]      **Serial Number:** 1XKZD40XXLJ969615  
**Work Location:** Rocky Mountain House Shop      **Business Unit:** Trucks Heavy  
**Created by:** Blair MacAulay      **Start Date:** 3-9-2023  
**Kms:** 9140      **Stop Date:** 3-10-2023  
**Hr:** 9366

**Work Order Cost Summary**

| Description   | Quantity | Labor Type       | Rate               | Total   |
|---------------|----------|------------------|--------------------|---------|
| CLAYTON OLSON | 1.00     | RT Shop Mech Rky | \$49.05            | \$49.05 |
|               |          |                  | <b>Total Labor</b> | \$49.05 |
|               |          |                  | <b>Total Parts</b> | \$0.00  |
|               |          |                  | <b>Total Equip</b> | \$0.00  |
|               |          |                  | <b>Total Cost</b>  | \$49.05 |

| Item ID | Description      | Completed By  | Reported Hours |
|---------|------------------|---------------|----------------|
| 74482   | REPAIR AIR LINES | Clayton Olson | 1.00           |

|                       |                               |                       |                   |
|-----------------------|-------------------------------|-----------------------|-------------------|
| <b>Work Order:</b>    | 40587                         | <b>Status:</b>        | Transferred       |
| <b>Equipment:</b>     | TRACTOR TANDEM KW T880 [9167] | <b>Serial Number:</b> | 1XKZD40XXLJ969615 |
| <b>Work Location:</b> | Rocky Mountain House Shop     | <b>Business Unit:</b> | Trucks Heavy      |
| <b>Created by:</b>    | Blair MacAulay                | <b>Start Date:</b>    | 3-17-2023         |
| <b>Kms:</b>           | 9140                          | <b>Stop Date:</b>     | 3-21-2023         |
| <b>Hr:</b>            | 9366                          |                       |                   |

**Work Order Cost Summary**

| Description   | Quantity | Labor Type       | Rate               | Total             |
|---|----------|------------------|--------------------|-------------------|
| BRENT EVANS   | 8.00     | RT Shop Mech Rky | \$49.05            | \$392.40          |
| H. KANIELA JOHNSON  | 4.00     | RT Shop Weld Rky | \$47.83            | \$191.32          |
| OLIVER TRAUTMANN  | 4.00     | RT Shop Mech Rky | \$49.05            | \$196.20          |
|   |          |                  | <b>Total Labor</b> | <b>\$779.92</b>   |
| FILTER AIR {P621725} [P637453]  | 1.00     | Each             | \$114.03           | \$114.03          |
| FILTER CAB AIR W/O COVER PB 567 & KW T880 {X1987001, CFR19012, SR2000092} [AF55839] | 1.00     | Each             | \$50.58            | \$50.58           |
| FILTER FUEL SEPARATOR {P550849, FS19764} [FS19763]                                  | 1.00     | Each             | \$21.33            | \$21.33           |
| FILTER FUEL SPIN-ON {DBF6776, FF5971NN} [FF5825NN]                                  | 1.00     | Each             | \$52.74            | \$52.74           |
| FILTER LUBE SPIN-ON {DBL7900, LF1400NN} [LF14001NN]                                 | 1.00     | Each             | \$43.25            | \$43.25           |
|   |          |                  | <b>Total Parts</b> | <b>\$281.93</b>   |
|   |          |                  | <b>Total Equip</b> | <b>\$0.00</b>     |
|   |          |                  | <b>Total Cost</b>  | <b>\$1,061.85</b> |

| Item ID | Description   | Completed By   | Reported Hours |
|---------|---|----------------|----------------|
| 74964   | REPAIR HEADACHE RACK BAR HOLDER                                   | Kani Johnson   | 2.00           |
| 74966   | INSTALL FIRE EXTINGUISHER AND BRACKET                             | Kani Johnson   | 1.00           |
| 74965   | REPAIR LIGHTS   | Blair MacAulay | 2.00           |
| 75072   | REPLACE TIE ROD   | Blair MacAulay | 2.50           |
| 74558   | ADJUST CLUTCH AS REQUIRED - 1/2" BETWEEN CLUTCH BRAKE AND RELEASE | Blair MacAulay | 0.00           |
| 74963   | 30K SERVICE   | Blair MacAulay | 7.00           |
| 75073   | REPLACE #3RH BRAKE POT  | Blair MacAulay | 1.50           |

|                       |                               |                       |                   |
|-----------------------|-------------------------------|-----------------------|-------------------|
| <b>Work Order:</b>    | 40635                         | <b>Status:</b>        | Transferred       |
| <b>Equipment:</b>     | TRACTOR TANDEM KW T880 [9167] | <b>Serial Number:</b> | 1XKZD40XXLJ969615 |
| <b>Work Location:</b> | Rocky Mountain House Shop     | <b>Business Unit:</b> | Trucks Heavy      |

Created by: Blair MacAulay  
Kms: 9140  
Hr: 9366

Start Date: 3-20-2023  
Stop Date: 3-21-2023

**Work Order Cost Summary**

| Description                           | Quantity | Labor Type       | Rate               | Total          |
|---------------------------------------|----------|------------------|--------------------|----------------|
| CLAYTON OLSON                         | 0.50     | RT Shop Mech Rky | \$49.05            | \$24.53        |
|                                       |          |                  | <b>Total Labor</b> | <b>\$24.53</b> |
| LIGHT CORD TRAILER 4 WAY 15' [194015] | 1.00     | Each             | \$50.12            | \$50.12        |
| MOTHERS -X REF 35316 [MOT35316]       | 1.00     | Each             | \$10.89            | \$10.89        |
|                                       |          |                  | <b>Total Parts</b> | <b>\$61.01</b> |
|                                       |          |                  | <b>Total Equip</b> | <b>\$0.00</b>  |
|                                       |          |                  | <b>Total Cost</b>  | <b>\$85.53</b> |

| Item ID | Description             | Completed By  | Reported Hours |
|---------|-------------------------|---------------|----------------|
| 75112   | REPAIR TRAILER FLIPPERS | Clayton Olson | 0.50           |

Work Order: 42364      Status: Transferred  
Equipment: TRACTOR TANDEM KW T880 [9167]      Serial Number: 1XKZD40XXLJ969615  
Work Location: Rocky Mountain House Shop      Business Unit: Trucks Heavy  
Created by: Blair MacAulay      Start Date: 5-12-2023  
Kms: 9140      Stop Date: 5-16-2023  
Hr: 9366

**Work Order Cost Summary**

| Description        | Quantity | Labor Type       | Rate               | Total           |
|--------------------|----------|------------------|--------------------|-----------------|
| BRETT LANGFORD     | 3.00     | RT Shop Mech Rky | \$49.05            | \$147.15        |
| H. KANIELA JOHNSON | 1.25     | RT Shop Weld Rky | \$47.83            | \$59.79         |
|                    |          |                  | <b>Total Labor</b> | <b>\$206.94</b> |
|                    |          |                  | <b>Total Parts</b> | <b>\$0.00</b>   |
|                    |          |                  | <b>Total Equip</b> | <b>\$0.00</b>   |
|                    |          |                  | <b>Total Cost</b>  | <b>\$206.94</b> |

| Item ID | Description         | Completed By   | Reported Hours |
|---------|---------------------|----------------|----------------|
| 78081   | REPAIR LR FENDER    | Blair MacAulay | 2.75           |
| 78082   | REPAIR RR TAILLIGHT | Blair MacAulay | 1.50           |

Work Order: 42734      Status: Transferred  
Equipment: TRACTOR TANDEM KW T880 [9167]      Serial Number: 1XKZD40XXLJ969615  
Work Location: MAIN YARD      Business Unit: Trucks Heavy  
Created by: Darcy Hallock      Start Date: 5-26-2023  
Kms: 9140      Stop Date: 5-26-2023  
Hr: 9366

**Work Order Cost Summary**

| Description  | Quantity | Labor Type        | Rate               | Total           |
|--|----------|-------------------|--------------------|-----------------|
| DARCY HALLOCK  | 0.50     | RT Shop Tire Tech | \$36.33            | \$18.17         |
|  |          |                   | <b>Total Labor</b> | <b>\$18.17</b>  |
| TIRE STEER - FS820/M843/FS821/FS819 [31580R225STEER] | 1.00     | Each              | \$753.14           | \$753.14        |
|  |          |                   | <b>Total Parts</b> | <b>\$753.14</b> |
|  |          |                   | <b>Total Equip</b> | <b>\$0.00</b>   |
|  |          |                   | <b>Total Cost</b>  | <b>\$771.31</b> |

| Item ID | Description                           | Completed By  | Reported Hours |
|---------|---------------------------------------|---------------|----------------|
| 78781   | 9167- 05/22/2023 "REPLACE STEER (X1)" | Darcy Hallock | 0.50           |

|                       |                               |                       |                   |
|-----------------------|-------------------------------|-----------------------|-------------------|
| <b>Work Order:</b>    | 42948                         | <b>Status:</b>        | Transferred       |
| <b>Equipment:</b>     | TRACTOR TANDEM KW T880 [9167] | <b>Serial Number:</b> | 1XKZD40XXLJ969615 |
| <b>Work Location:</b> | Rocky Mountain House Shop     | <b>Business Unit:</b> | Trucks Heavy      |
| <b>Created by:</b>    | Blair MacAulay                | <b>Start Date:</b>    | 6-5-2023          |
| <b>Kms:</b>           | 9140                          | <b>Stop Date:</b>     | 6-6-2023          |
| <b>Hr:</b>            | 9366                          |                       |                   |

**Work Order Cost Summary**

| Description                           | Quantity | Labor Type       | Rate               | Total           |
|---------------------------------------|----------|------------------|--------------------|-----------------|
| JEREMY KEDDY                          | 1.00     | RT Shop Mech Rky | \$49.05            | \$49.05         |
|                                       |          |                  | <b>Total Labor</b> | <b>\$49.05</b>  |
| LIGHT CORD TRAILER 4 WAY 15' [194015] | 1.00     | Each             | \$50.12            | \$50.12         |
| MOTHERS -X REF 35316 [MOT35316]       | 1.00     | Each             | \$11.23            | \$11.23         |
|                                       |          |                  | <b>Total Parts</b> | <b>\$61.35</b>  |
|                                       |          |                  | <b>Total Equip</b> | <b>\$0.00</b>   |
|                                       |          |                  | <b>Total Cost</b>  | <b>\$110.40</b> |

| Item ID | Description                            | Completed By | Reported Hours |
|---------|--|--------------|----------------|
| 79233   | REPLACE RH UPPER EXHAUST STACK BRACKET | Jeremy Keddy | 1.00           |

|                       |                               |                       |                   |
|-----------------------|-------------------------------|-----------------------|-------------------|
| <b>Work Order:</b>    | 43298                         | <b>Status:</b>        | Transferred       |
| <b>Equipment:</b>     | TRACTOR TANDEM KW T880 [9167] | <b>Serial Number:</b> | 1XKZD40XXLJ969615 |
| <b>Work Location:</b> | Blackfalds Shop               | <b>Business Unit:</b> | Trucks Heavy      |
| <b>Created by:</b>    | Oom Jarussirrat               | <b>Start Date:</b>    | 6-13-2023         |
| <b>Kms:</b>           | 9140                          | <b>Stop Date:</b>     | 6-14-2023         |
| <b>Hr:</b>            | 9366                          |                       |                   |

**Work Order Cost Summary**

| Description | Quantity | Labor Type         | Rate    | Total   |
|-------------|----------|--------------------|---------|---------|
| WAYNE KIRK  | 0.50     | RT Shop Mech Blfds | \$52.07 | \$26.04 |

|                    |         |
|--------------------|---------|
| <b>Total Labor</b> | \$26.04 |
| <b>Total Parts</b> | \$0.00  |
| <b>Total Equip</b> | \$0.00  |
| <b>Total Cost</b>  | \$26.04 |

| Item ID | Description                          | Completed By | Reported Hours |
|---------|--------------------------------------|--------------|----------------|
| 79718   | BROKEN REAR FENDER MOUNTING BRACKETS | Wayne Kirk   | 0.50           |

**Work Order:** 43476 **Status:** Transferred  
**Equipment:** TRACTOR TANDEM KW T880 [9167] **Serial Number:** 1XKZD40XXLJ969615  
**Work Location:** MAIN YARD **Business Unit:** Trucks Heavy  
**Created by:** Darcy Hallock **Start Date:** 6-18-2023  
**Kms:** 9140 **Stop Date:** 6-18-2023  
**Hr:** 9366

**Work Order Cost Summary**

| Description                                | Quantity | Labor Type        | Rate               | Total      |
|--|----------|-------------------|--------------------|------------|
| DARCY HALLOCK                              | 4.00     | RT Shop Tire Tech | \$36.33            | \$145.32   |
|  |          |                   | <b>Total Labor</b> | \$145.32   |
| TIRE DRIVE - M775/BDY2/S758 [11R245DRIVE6] | 8.00     | Each              | \$612.82           | \$4,902.55 |
|  |          |                   | <b>Total Parts</b> | \$4,902.55 |
|  |          |                   | <b>Total Equip</b> | \$0.00     |
|  |          |                   | <b>Total Cost</b>  | \$5,047.87 |

| Item ID | Description                            | Completed By  | Reported Hours |
|---------|--|---------------|----------------|
| 80042   | 9167- 06/18/2023 "REPLACE DRIVES (X8)" | Darcy Hallock | 4.00           |

**Work Order:** 43477 **Status:** Transferred  
**Equipment:** TRACTOR TANDEM KW T880 [9167] **Serial Number:** 1XKZD40XXLJ969615  
**Work Location:** Rocky Mountain House Shop **Business Unit:** Trucks Heavy  
**Created by:** Blair MacAulay **Start Date:** 6-19-2023  
**Kms:** 9140 **Stop Date:** 6-20-2023  
**Hr:** 9366

**Work Order Cost Summary**

| Description  | Quantity | Labor Type       | Rate               | Total    |
|--|----------|------------------|--------------------|----------|
| JEREMY KEDDY   | 4.50     | RT Shop Mech Rky | \$49.05            | \$220.73 |
| OLIVER TRAUTMANN   | 5.50     | RT Shop Mech Rky | \$49.05            | \$269.78 |
|  |          |                  | <b>Total Labor</b> | \$490.50 |
| BRAKE CHAMBER - TYPE 3030LS, 3.00" STROKE [FLT3030LCB20] | 1.00     | Each             | \$48.72            | \$48.72  |
| BUSHING-MOUNTING EXHAUST {XR M13109} [M131009]           | 1.00     | Each             | \$35.53            | \$35.53  |
| BUSHING-PIN ISOLATOR [M136001]                           | 1.00     | Each             | \$11.28            | \$11.28  |

|   |           |                    |                 |
|---|-----------|--------------------|-----------------|
| FILTER AIR {P621725} [P637453]  | 1.00 Each | \$149.87           | \$149.87        |
| FILTER CAB AIR W/O COVER PB 567 & KW T880 {X1987001, CFR19012, SR2000092} [AF55839] | 1.00 Each | \$35.66            | \$35.66         |
| FILTER FUEL SEPARATOR {P550849, FS19764} [FS19763]                                  | 1.00 Each | \$22.50            | \$22.50         |
| FILTER FUEL SPIN-ON {DBF6776,FF5971NN} [FF5825NN]                                   | 1.00 Each | \$50.25            | \$50.25         |
| FILTER HYDRAULIC SPIN-ON {P550387} [HF6720]   | 2.00 Each | \$24.27            | \$48.55         |
| FILTER LUBE SPIN-ON {DBL7900, LF14000NN} [LF14001NN]                                | 1.00 Each | \$40.94            | \$40.94         |
| RING - RADIAL RETAINING [E50STZD]   | 1.00 Each | \$0.11             | \$0.11          |
|   |           | <b>Total Parts</b> | <b>\$443.40</b> |
|   |           | <b>Total Equip</b> | <b>\$0.00</b>   |
|   |           | <b>Total Cost</b>  | <b>\$933.90</b> |

| Item ID | Description                       | Completed By   | Reported Hours |
|---------|-----------------------------------|----------------|----------------|
| 75036   | 30K SERVICE - REPLACE ALL FILTERS | Blair MacAulay | 5.50           |
| 80072   | REPAIR LH STACK ISOLATOR          | Blair MacAulay | 0.50           |
| 80068   | REPLACE BRAKE POT #2 AXLE RH      | Blair MacAulay | 1.50           |
| 79125   | REPLACE HYDRAULIC FILTER          | Blair MacAulay | 0.00           |
| 80070   | ADJUST CLUTCH                     | Blair MacAulay | 1.00           |
| 80071   | REPAIR AIR LEAK @ REAR TANK       | Blair MacAulay | 1.00           |
| 80069   | TIGHTEN SHOCK #1 AXLE LH          | Blair MacAulay | 0.50           |

|                       |                               |                       |                   |
|-----------------------|-------------------------------|-----------------------|-------------------|
| <b>Work Order:</b>    | 43580                         | <b>Status:</b>        | Transferred       |
| <b>Equipment:</b>     | TRACTOR TANDEM KW T880 [9167] | <b>Serial Number:</b> | 1XKZD40XXLJ969615 |
| <b>Work Location:</b> | MAIN YARD                     | <b>Business Unit:</b> | Trucks Heavy      |
| <b>Created by:</b>    | Darcy Hallock                 | <b>Start Date:</b>    | 6-21-2023         |
| <b>Kms:</b>           | 9140                          | <b>Stop Date:</b>     | 6-21-2023         |
| <b>Hr:</b>            | 9366                          |                       |                   |

**Work Order Cost Summary**

| Description   | Quantity | Labor Type        | Rate               | Total          |
|---------------|----------|-------------------|--------------------|----------------|
| DARCY HALLOCK | 0.50     | RT Shop Tire Tech | \$36.33            | \$18.17        |
|               |          |                   | <b>Total Labor</b> | <b>\$18.17</b> |
|               |          |                   | <b>Total Parts</b> | <b>\$0.00</b>  |
|               |          |                   | <b>Total Equip</b> | <b>\$0.00</b>  |
|               |          |                   | <b>Total Cost</b>  | <b>\$18.17</b> |

| Item ID | Description                  | Completed By  | Reported Hours |
|---------|------------------------------|---------------|----------------|
| 80209   | 9167- 06/21/2023 "RE-TORQUE" | Darcy Hallock | 0.50           |

**Work Order:** 43733  
**Equipment:** TRACTOR TANDEM KW T880 [9167]  
**Work Location:** Blackfalds Yard  
**Created by:** Bernie Seefried  
**Kms:** 9140  
**Hr:** 9366

**Status:** Transferred  
**Serial Number:** 1XKZD40XXLJ969615  
**Business Unit:** Trucks Heavy  
**Start Date:** 6-27-2023  
**Stop Date:** 6-27-2023

**Work Order Cost Summary**

| Description     | Quantity | Labor Type         | Rate               | Total    |
|-----------------|----------|--------------------|--------------------|----------|
| BERNIE SEEFRIED | 2.50     | RT Shop Mech Blfds | \$52.07            | \$130.18 |
|                 |          |                    | <b>Total Labor</b> | \$130.18 |
|                 |          |                    | <b>Total Parts</b> | \$0.00   |
|                 |          |                    | <b>Total Equip</b> | \$0.00   |
|                 |          |                    | <b>Total Cost</b>  | \$130.18 |

| Item ID | Description  | Completed By    | Reported Hours |
|---------|--------------|-----------------|----------------|
| 80459   | LIGHTS ISSUE | Bernie Seefried | 2.50           |

**Work Order:** 43891  
**Equipment:** TRACTOR TANDEM KW T880 [9167]  
**Work Location:** Rocky Mountain House Shop  
**Created by:** Blair MacAulay  
**Kms:** 9140  
**Hr:** 9366

**Status:** Transferred  
**Serial Number:** 1XKZD40XXLJ969615  
**Business Unit:** Trucks Heavy  
**Start Date:** 7-3-2023  
**Stop Date:** 7-4-2023

**Work Order Cost Summary**

| Description  | Quantity | Labor Type       | Rate               | Total   |
|--------------|----------|------------------|--------------------|---------|
| JEREMY KEDDY | 0.50     | RT Shop Mech Rky | \$49.05            | \$24.53 |
|              |          |                  | <b>Total Labor</b> | \$24.53 |
|              |          |                  | <b>Total Parts</b> | \$0.00  |
|              |          |                  | <b>Total Equip</b> | \$0.00  |
|              |          |                  | <b>Total Cost</b>  | \$24.53 |

| Item ID | Description            | Completed By   | Reported Hours |
|---------|------------------------|----------------|----------------|
| 80749   | REPAIR RH STACK SHIELD | Blair MacAulay | 0.50           |

**Work Order:** 44087  
**Equipment:** TRACTOR TANDEM KW T880 [9167]  
**Work Location:** Rocky Mountain House Shop  
**Created by:** Blair MacAulay  
**Kms:** 9140  
**Hr:** 9366

**Status:** Transferred  
**Serial Number:** 1XKZD40XXLJ969615  
**Business Unit:** Trucks Heavy  
**Start Date:** 7-19-2023  
**Stop Date:** 7-24-2023

**Work Order Cost Summary**

| Description   | Quantity | Labor Type       | Rate               | Total             |
|---|----------|------------------|--------------------|-------------------|
| BLAINE STEFFAN  | 3.00     | RT Shop Lab Rky  | \$31.18            | \$93.54           |
| KANIELA JOHNSON   | 2.00     | RT Shop Weld Rky | \$47.83            | \$95.66           |
| JEREMY KEDDY  | 16.50    | RT Shop Mech Rky | \$49.05            | \$809.33          |
| KIRBY BERGEN  | 13.50    | RT Shop Mech Rky | \$49.05            | \$662.18          |
|   |          |                  | <b>Total Labor</b> | <b>\$1,660.70</b> |
| 5TH WHEEL BRACKET PINS AND BUSHINGS FOR ILS - KIT - HOLLAND FW35 [RK10605]                                    | 1.00     | Each             | \$61.03            | \$61.03           |
| 5TH WHEEL BRACKET PINS AND BUSHINGS FOR ILS - KIT - HOLLAND FW35 [RK10605]                                    | 1.00     | Each             | \$61.03            | \$61.03           |
| A/C SECONDARY BELT - SERPENTINE - RIBS: 6 - EFFECTIVE LENGTH (IN): 64.0 {638K6BLT, 640K6BLT} [D8410006061620] | 1.00     | Each             | \$46.95            | \$46.95           |
| BRAKE DRUM [93807X]   | 4.00     | Each             | \$219.02           | \$876.08          |
| BUSHING-MOUNTING EXHAUST {XR M13109} [M131009]  | 2.00     | Each             | \$35.72            | \$71.44           |
| BUSHING-PIN ISOLATOR [M136001]  | 2.00     | Each             | \$11.30            | \$22.61           |
| CORE[Custom]  | 2.00     | Each             | (\$52.80)          | (\$105.60)        |
| CORE[Custom]  | 4.00     | Each             | (\$52.80)          | (\$211.20)        |
| FAN DRIVE BELT 12RIBS X 2180mm {FLTBT858K12, 858K12BLT} [D8410006122180]                                      | 1.00     | Each             | \$101.15           | \$101.15          |
| FEMALE TRAILER END PLASTIC - 7 WIRE (RV) {764141} [821060]  | 1.00     | Each             | \$18.54            | \$18.54           |
| FRONT DRUMS 16.5 [53123816]   | 2.00     | Each             | \$383.92           | \$767.84          |
| HEIGHT LEVELING VALVE - KENWORTH {VS228} [KD2459]   | 1.00     | Each             | \$214.41           | \$214.41          |
| REMAN SHOE KIT[Custom]  | 2.00     | Each             | (\$95.70)          | (\$191.40)        |
| REMAN SHOE KIT[Custom]  | 4.00     | Each             | (\$120.38)         | (\$481.52)        |
| SHAFT - EXHAUST [M051007]   | 2.00     | Each             | \$75.88            | \$151.76          |
| WHEEL HUB STUD M22 x 1.5 [CM10005669]   | 12.00    | Each             | \$9.55             | \$114.60          |
| WHEEL HUB STUD M22 x 1.5 [CM10005669]   | 5.00     | Each             | \$7.85             | \$39.25           |
|   |          |                  | <b>Total Parts</b> | <b>\$1,556.98</b> |
|   |          |                  | <b>Total Equip</b> | <b>\$0.00</b>     |
|   |          |                  | <b>Total Cost</b>  | <b>\$3,217.68</b> |

| Item ID | Description                         | Completed By | Reported Hours |
|---------|-------------------------------------|--------------|----------------|
| 81679   | REPLACE 5TH WHEEL PINS AND BUSHINGS | Jeremy Keddy | 2.00           |
| 80679   | CVIP INSPECTION                     | Kirby Bergen | 25.00          |
| 81680   | REPLACE STEADY BEARING              | Jeremy Keddy | 0.00           |
| 81677   | REPLACE EXHAUST ISOLATORS           | Jeremy Keddy | 2.00           |
| 81685   | REPAIR AIR LEAKS                    | Jeremy Keddy | 2.50           |

81678 REPLACE BELTS

Jeremy Keddy

0.50

81686 REPAIR RR FENDER MOUNT Jeremy Keddy 3.00

**Work Order:** 45235  
**Equipment:** TRACTOR TANDEM KW T880 [9167]  
**Work Location:** Rocky Mountain House Shop  
**Created by:** Blair MacAulay  
**Kms:** 9140  
**Hr:** 9366

**Status:** Transferred  
**Serial Number:** 1XKZD40XXLJ969615  
**Business Unit:** Trucks Heavy  
**Start Date:** 8-15-2023  
**Stop Date:** 8-16-2023

**Work Order Cost Summary**

| Description  | Quantity | Labor Type       | Rate               | Total             |
|--|----------|------------------|--------------------|-------------------|
| JEREMY KEDDY   | 3.00     | RT Shop Mech Rky | \$49.05            | \$147.15          |
| MAXWELL KRABBEN  | 4.00     | RT Shop Mech Rky | \$49.05            | \$196.20          |
|  |          |                  | <b>Total Labor</b> | <b>\$343.35</b>   |
| FILTER AIR {DON: P621725} [P637453]                            | 1.00     | Each             | \$170.30           | \$170.30          |
| FILTER AIR {PAC: SR2000092, X1987001, FLG: AF55839} [CFR19012] | 1.00     | Each             | \$38.45            | \$38.45           |
| FILTER AIR {PAC: SR2000092, X1987001, FLG: AF55839} [CFR19012] | 1.00     | Each             | \$38.45            | \$38.45           |
| FILTER FUEL SEPARATOR {P550849, FS19764} [FS19763]             | 1.00     | Each             | \$22.34            | \$22.34           |
| FILTER FUEL SPIN-ON {DBF6776, FF5971NN} [FF5825NN]             | 1.00     | Each             | \$145.39           | \$145.39          |
| FILTER HYDRAULIC SPIN-ON {P550387} [HF6720]                    | 1.00     | Each             | \$20.40            | \$20.40           |
| FILTER HYDRAULIC SPIN-ON {P550387} [HF6720]                    | 1.00     | Each             | \$20.40            | \$20.40           |
| FILTER LUBE SPIN-ON {DBL7900, LF14000NN} [LF14001NN]           | 1.00     | Each             | \$44.84            | \$44.84           |
| PIN - SPRING [B656008]   | 4.00     | Each             | \$95.06            | \$380.24          |
|  |          |                  | <b>Total Parts</b> | <b>\$880.81</b>   |
|  |          |                  | <b>Total Equip</b> | <b>\$0.00</b>     |
|  |          |                  | <b>Total Cost</b>  | <b>\$1,224.16</b> |

| Item ID | Description   | Completed By   | Reported Hours |
|---------|---|----------------|----------------|
| 83021   | REPLACE LOOSE TORQUE ROD BOLT #2RH                                | Blair MacAulay | 0.50           |
| 80572   | ADJUST CLUTCH AS REQUIRED - 1/2" BETWEEN CLUTCH BRAKE AND RELEASE | Blair MacAulay | 0.00           |
| 83019   | SECURE HYDRAULIC LINES  | Blair MacAulay | 0.50           |
| 83020   | REPLACE HYDRAULIC FILTERS   | Blair MacAulay | 1.00           |
| 82588   | 30K SERVICE & INSPECTION  | Blair MacAulay | 5.00           |

**Work Order:** 45369  
**Equipment:** TRACTOR TANDEM KW T880 [9167]  
**Work Location:** Rocky Mountain House Shop

**Status:** Transferred  
**Serial Number:** 1XKZD40XXLJ969615  
**Business Unit:** Trucks Heavy

Created by: Blair MacAulay  
Kms: 9140  
Hr: 9366

Start Date: 8-18-2023  
Stop Date: 8-21-2023

**Work Order Cost Summary**

| Description      | Quantity | Labor Type       | Rate               | Total   |
|------------------|----------|------------------|--------------------|---------|
| OLIVER TRAUTMANN | 1.50     | RT Shop Mech Rky | \$49.05            | \$73.58 |
|                  |          |                  | <b>Total Labor</b> | \$73.58 |
|                  |          |                  | <b>Total Parts</b> | \$0.00  |
|                  |          |                  | <b>Total Equip</b> | \$0.00  |
|                  |          |                  | <b>Total Cost</b>  | \$73.58 |

| Item ID | Description | Completed By   | Reported Hours |
|---------|-------------|----------------|----------------|
| 83240   | REPAIR ABS  | Blair MacAulay | 1.50           |

Work Order: 45818  
Equipment: TRACTOR TANDEM KW T880 [9167]  
Work Location: Rocky Mountain House Shop  
Created by: Blair MacAulay  
Kms: 9140  
Hr: 9366

Status: Transferred  
Serial Number: 1XKZD40XXLJ969615  
Business Unit: Trucks Heavy  
Start Date: 9-1-2023  
Stop Date: 9-5-2023

**Work Order Cost Summary**

| Description                     | Quantity | Labor Type       | Rate               | Total    |
|---------------------------------|----------|------------------|--------------------|----------|
| BRENT EVANS                     | 1.00     | RT Shop Mech Rky | \$49.05            | \$49.05  |
|                                 |          |                  | <b>Total Labor</b> | \$49.05  |
| 1" FEMALE WING COUPLER [612516] | 1.00     | Each             | \$150.68           | \$150.68 |
| MNPT- CRIMP [101431616]         | 2.00     | Each             | \$29.89            | \$59.78  |
| MNPT- CRIMP [101431616]         | 1.00     | Each             | \$29.89            | \$29.89  |
|                                 |          |                  | <b>Total Parts</b> | \$240.35 |
|                                 |          |                  | <b>Total Equip</b> | \$0.00   |
|                                 |          |                  | <b>Total Cost</b>  | \$289.40 |

| Item ID | Description            | Completed By | Reported Hours |
|---------|------------------------|--------------|----------------|
| 84062   | REPLACE HYDRAULIC HOSE | Brent Evans  | 1.00           |

Work Order: 46231  
Equipment: TRACTOR TANDEM KW T880 [9167]  
Work Location: Shop Operations - RMH  
Created by: Darcy Hallock  
Kms: 9140  
Hr: 9366

Status: Transferred  
Serial Number: 1XKZD40XXLJ969615  
Business Unit: Trucks Heavy  
Start Date: 9-14-2023  
Stop Date: 9-14-2023

**Work Order Cost Summary**

| Description                 | Quantity | Labor Type        | Rate               | Total             |
|-----------------------------|----------|-------------------|--------------------|-------------------|
| DARCY HALLOCK               | 1.25     | RT Shop Tire Tech | \$36.33            | \$45.41           |
|                             |          |                   | <b>Total Labor</b> | <b>\$45.41</b>    |
| TIRE STEER [31580R225FS819] | 2.00     | Each              | \$672.32           | \$1,344.64        |
|                             |          |                   | <b>Total Parts</b> | <b>\$1,344.64</b> |
|                             |          |                   | <b>Total Equip</b> | <b>\$0.00</b>     |
|                             |          |                   | <b>Total Cost</b>  | <b>\$1,390.05</b> |

| Item ID | Description                            | Completed By  | Reported Hours |
|---------|--|---------------|----------------|
| 84994   | 9167- 09/14/2023 "REPLACE STEERS (X2)" | Darcy Hallock | 1.25           |

**Work Order:** 46822      **Status:** Transferred  
**Equipment:** TRACTOR TANDEM KW T880 [9167]      **Serial Number:** 1XKZD40XXLJ969615  
**Work Location:** Rocky Mountain House Shop      **Business Unit:** Trucks Heavy  
**Created by:** Blair MacAulay      **Start Date:** 10-2-2023  
**Kms:** 9140      **Stop Date:** 10-4-2023  
**Hr:** 9366

**Work Order Cost Summary**

| Description  | Quantity | Labor Type       | Rate               | Total           |
|--|----------|------------------|--------------------|-----------------|
| MAXWELL KRABBEN  | 5.50     | RT Shop Mech Rky | \$49.05            | \$269.78        |
|  |          |                  | <b>Total Labor</b> | <b>\$269.78</b> |
| A/C SECONDARY BELT - SERPENTINE - RIBS: 6 - EFFECTIVE LENGTH (IN): 64.0<br>{638K6BLT, 640K6BLT} [D8410006061620] | 1.00     | Each             | \$42.33            | \$42.33         |
| FAN DRIVE BELT 12RIBS X 2180mm {FLTBT858K12, 858K12BLT}<br>[D8410006122180]                                      | 1.00     | Each             | \$89.45            | \$89.45         |
|  |          |                  | <b>Total Parts</b> | <b>\$131.78</b> |
|  |          |                  | <b>Total Equip</b> | <b>\$0.00</b>   |
|  |          |                  | <b>Total Cost</b>  | <b>\$401.55</b> |

| Item ID | Description          | Completed By   | Reported Hours |
|---------|----------------------|----------------|----------------|
| 86334   | REPAIR LEAK AT PTO   | Blair MacAulay | 0.50           |
| 86337   | REPLACE BELTS        | Blair MacAulay | 1.00           |
| 86335   | REPAIR BUNK HEATER   | Blair MacAulay | 2.00           |
| 86333   | REPAIR ENGINE HEATER | Blair MacAulay | 2.00           |

**Work Order:** 46968      **Status:** Transferred  
**Equipment:** TRACTOR TANDEM KW T880 [9167]      **Serial Number:** 1XKZD40XXLJ969615  
**Work Location:** Rocky Mountain House Shop      **Business Unit:** Trucks Heavy  
**Created by:** Blair MacAulay      **Start Date:** 10-5-2023  
**Kms:** 9140      **Stop Date:** 10-6-2023  
**Hr:** 9366

**Work Order Cost Summary**

| Description | Quantity | Labor Type | Rate               | Total  |
|-------------|----------|------------|--------------------|--------|
|             |          |            | <b>Total Labor</b> | \$0.00 |
|             |          |            | <b>Total Parts</b> | \$0.00 |
|             |          |            | <b>Total Equip</b> | \$0.00 |
|             |          |            | <b>Total Cost</b>  | \$0.00 |

| Item ID | Description      | Completed By   | Reported Hours |
|---------|------------------|----------------|----------------|
| 86582   | REPAIR RR FENDER | Blair MacAulay | 0.00           |

|                       |                               |                       |                   |
|-----------------------|-------------------------------|-----------------------|-------------------|
| <b>Work Order:</b>    | 47606                         | <b>Status:</b>        | Transferred       |
| <b>Equipment:</b>     | TRACTOR TANDEM KW T880 [9167] | <b>Serial Number:</b> | 1XKZD40XXLJ969615 |
| <b>Work Location:</b> | Rocky Mountain House Shop     | <b>Business Unit:</b> | Trucks Heavy      |
| <b>Created by:</b>    | Blair MacAulay                | <b>Start Date:</b>    | 10-24-2023        |
| <b>Kms:</b>           | 9140                          | <b>Stop Date:</b>     | 10-26-2023        |
| <b>Hr:</b>            | 9366                          |                       |                   |

**Work Order Cost Summary**

| Description  | Quantity | Labor Type       | Rate               | Total      |
|--|----------|------------------|--------------------|------------|
| BRENT EVANS  | 5.00     | RT Shop Mech Rky | \$49.05            | \$245.25   |
| CLAYTON OLSON  | 3.75     | RT Shop Mech Rky | \$49.05            | \$183.94   |
|  |          |                  | <b>Total Labor</b> | \$429.19   |
| FILTER AIR {DON: P621725} [P637453]                            | 1.00     | Each             | \$171.05           | \$171.05   |
| FILTER AIR DRYER - BENDIX ADIS {BEN: 5008415PG} [5008414PG]    | 1.00     | Each             | \$131.79           | \$131.79   |
| FILTER FUEL SEPARATOR {DON: P550849, FLG: FS19764} [FS19763]   | 1.00     | Each             | \$21.62            | \$21.62    |
| FILTER FUEL SPIN-ON {DON: DBF6776, FLG: FF5971NN} [FF5825NN]   | 1.00     | Each             | \$60.69            | \$60.69    |
| FILTER HYDRAULIC SPIN-ON {DON: P550387} [HF6720]               | 1.00     | Each             | \$19.21            | \$19.21    |
| FILTER HYDRAULIC SPIN-ON {DON: P550387} [HF6720]               | 1.00     | Each             | \$19.21            | \$19.21    |
| FILTER LUBE SPIN-ON {FLG: LF14000NN, DON: DBL7900} [LF14001NN] | 1.00     | Each             | \$45.36            | \$45.36    |
| GLADHAND SEAL CLOSE [FS312A]                                   | 2.00     | Each             | \$0.56             | \$1.13     |
| WEBASTO THERMO TOP - SMARTEMP CONTROL {5010633} [5010753]      | 1.00     | Each             | \$209.80           | \$209.80   |
|  |          |                  | <b>Total Parts</b> | \$679.84   |
|  |          |                  | <b>Total Equip</b> | \$0.00     |
|  |          |                  | <b>Total Cost</b>  | \$1,109.03 |

| Item ID | Description | Completed By | Reported Hours |
|---------|-------------|--------------|----------------|
| 87712   | 30K SERVICE | Brent Evans  | 7.75           |

|       |                    |               |      |
|-------|--------------------|---------------|------|
| 87715 | REPAIR BUNK HEATER | Clayton Olson | 0.50 |
|-------|--------------------|---------------|------|

|       |                                    |             |      |
|-------|------------------------------------|-------------|------|
| 84621 | REPLACE AIR DRYER CARTRIDGE FILTER | Brent Evans | 0.50 |
|-------|------------------------------------|-------------|------|

**Work Order:** 48111  
**Equipment:** TRACTOR TANDEM KW T880 [9167]  
**Work Location:** Rocky Mountain House Shop  
**Created by:** Nick Depratto  
**Kms:** 9140  
**Hr:** 9366

**Status:** Transferred  
**Serial Number:** 1XKZD40XXLJ969615  
**Business Unit:** Trucks Heavy  
**Start Date:** 11-7-2023  
**Stop Date:** 11-10-2023

**Work Order Cost Summary**

| Description                   | Quantity | Labor Type | Rate               | Total      |
|-------------------------------|----------|------------|--------------------|------------|
|                               |          |            | <b>Total Labor</b> | \$0.00     |
| KW CAL INV# SC1030279[Custom] | 1.00     | Each       | \$3,583.61         | \$3,583.61 |
|                               |          |            | <b>Total Parts</b> | \$3,583.61 |
|                               |          |            | <b>Total Equip</b> | \$0.00     |
|                               |          |            | <b>Total Cost</b>  | \$3,583.61 |

| Item ID | Description  | Completed By  | Reported Hours |
|---------|--|---------------|----------------|
| 88559   | KW CALGARY - HOOD SHOCK MOUNT REPAIRS - INV# SC1030279 | Nick Depratto | 0.00           |

**Work Order:** 48398  
**Equipment:** TRACTOR TANDEM KW T880 [9167]  
**Work Location:**  
**Created by:** Blair MacAulay  
**Kms:** 9140  
**Hr:** 9366

**Status:** Transferred  
**Serial Number:** 1XKZD40XXLJ969615  
**Business Unit:** Trucks Heavy  
**Start Date:**  
**Stop Date:**

**Work Order Cost Summary**

| Description | Quantity | Labor Type | Rate               | Total  |
|-------------|----------|------------|--------------------|--------|
|             |          |            | <b>Total Labor</b> | \$0.00 |
|             |          |            | <b>Total Parts</b> | \$0.00 |
|             |          |            | <b>Total Equip</b> | \$0.00 |
|             |          |            | <b>Total Cost</b>  | \$0.00 |

| Item ID | Description            | Completed By   | Reported Hours |
|---------|------------------------|----------------|----------------|
| 89158   | REPAIR RR FENDER MOUNT | Blair MacAulay | 0.00           |

**Work Order:** 48651  
**Equipment:** TRACTOR TANDEM KW T880 [9167]  
**Work Location:** MAIN YARD  
**Created by:** Darcy Hallock  
**Kms:** 9140  
**Hr:** 9366

**Status:** Transferred  
**Serial Number:** 1XKZD40XXLJ969615  
**Business Unit:** Trucks Heavy  
**Start Date:** 11-22-2023  
**Stop Date:** 11-22-2023

**Work Order Cost Summary**

| Description   | Quantity | Labor Type        | Rate    | Total  |
|---------------|----------|-------------------|---------|--------|
| DARCY HALLOCK | 0.25     | RT Shop Tire Tech | \$36.33 | \$9.08 |

|                    |        |
|--------------------|--------|
| <b>Total Labor</b> | \$9.08 |
| <b>Total Parts</b> | \$0.00 |
| <b>Total Equip</b> | \$0.00 |
| <b>Total Cost</b>  | \$9.08 |

| Item ID | Description                      | Completed By  | Reported Hours |
|---------|----------------------------------|---------------|----------------|
| 89548   | 9167- 11/22/2023 "INSPECT TIRES" | Darcy Hallock | 0.25           |

|                       |                               |                       |                   |
|-----------------------|-------------------------------|-----------------------|-------------------|
| <b>Work Order:</b>    | 48718                         | <b>Status:</b>        | Transferred       |
| <b>Equipment:</b>     | TRACTOR TANDEM KW T880 [9167] | <b>Serial Number:</b> | 1XKZD40XXLJ969615 |
| <b>Work Location:</b> | Rocky Mountain House Shop     | <b>Business Unit:</b> | Trucks Heavy      |
| <b>Created by:</b>    | Blair MacAulay                | <b>Start Date:</b>    | 11-24-2023        |
| <b>Kms:</b>           | 9140                          | <b>Stop Date:</b>     | 11-28-2023        |
| <b>Hr:</b>            | 9366                          |                       |                   |

**Work Order Cost Summary**

| Description  | Quantity | Labor Type       | Rate               | Total    |
|--|----------|------------------|--------------------|----------|
| CLAYTON OLSON  | 0.25     | RT Shop Mech Rky | \$49.05            | \$12.26  |
| JEREMY KEDDY   | 0.50     | RT Shop Mech Rky | \$49.05            | \$24.53  |
|  |          |                  | <b>Total Labor</b> | \$36.79  |
| WEBASTO THERMO TOP C - CIRCULATION PUMP U 4847 - 12 V [90025148] | 1.00     | Each             | \$307.68           | \$307.68 |
|  |          |                  | <b>Total Parts</b> | \$307.68 |
|  |          |                  | <b>Total Equip</b> | \$0.00   |
|  |          |                  | <b>Total Cost</b>  | \$344.47 |

| Item ID | Description          | Completed By   | Reported Hours |
|---------|----------------------|----------------|----------------|
| 87716   | REPAIR ENGINE HEATER | Blair MacAulay | 0.75           |

|                       |                               |                       |                   |
|-----------------------|-------------------------------|-----------------------|-------------------|
| <b>Work Order:</b>    | 49103                         | <b>Status:</b>        | Transferred       |
| <b>Equipment:</b>     | TRACTOR TANDEM KW T880 [9167] | <b>Serial Number:</b> | 1XKZD40XXLJ969615 |
| <b>Work Location:</b> | Shop Operations - RMH         | <b>Business Unit:</b> | Trucks Heavy      |
| <b>Created by:</b>    | Darcy Hallock                 | <b>Start Date:</b>    | 12-8-2023         |
| <b>Kms:</b>           | 9140                          | <b>Stop Date:</b>     | 12-8-2023         |
| <b>Hr:</b>            | 9366                          |                       |                   |

**Work Order Cost Summary**

| Description   | Quantity | Labor Type        | Rate               | Total   |
|---------------|----------|-------------------|--------------------|---------|
| DARCY HALLOCK | 1.25     | RT Shop Tire Tech | \$36.33            | \$45.41 |
|               |          |                   | <b>Total Labor</b> | \$45.41 |
|               |          |                   | <b>Total Parts</b> | \$0.00  |
|               |          |                   | <b>Total Equip</b> | \$0.00  |
|               |          |                   | <b>Total Cost</b>  | \$45.41 |

| Item ID | Description                            | Completed By  | Reported Hours |
|---------|--|---------------|----------------|
| 90385   | 9167- 12/08/2023 "INSTALL RUNOUT (X1)" | Darcy Hallock | 1.25           |

**Work Order:** 49121 **Status:** Transferred  
**Equipment:** TRACTOR TANDEM KW T880 [9167] **Serial Number:** 1XKZD40XXLJ969615  
**Work Location:** Rocky Mountain House Shop **Business Unit:** Trucks Heavy  
**Created by:** Blair MacAulay **Start Date:** 12-8-2023  
**Kms:** 9140 **Stop Date:** 12-11-2023  
**Hr:** 9366

**Work Order Cost Summary**

| Description                    | Quantity | Labor Type       | Rate               | Total           |
|--------------------------------|----------|------------------|--------------------|-----------------|
| BRENT EVANS                    | 3.00     | RT Shop Mech Rky | \$49.05            | \$147.15        |
| MAXWELL KRABBEN                | 2.50     | RT Shop Mech Rky | \$49.05            | \$122.63        |
|                                |          |                  | <b>Total Labor</b> | <b>\$269.78</b> |
| CLUTCH BRAKE {C127200} [SB200] | 1.00     | Each             | \$40.95            | \$40.95         |
|                                |          |                  | <b>Total Parts</b> | <b>\$40.95</b>  |
|                                |          |                  | <b>Total Equip</b> | <b>\$0.00</b>   |
|                                |          |                  | <b>Total Cost</b>  | <b>\$310.72</b> |

| Item ID | Description         | Completed By   | Reported Hours |
|---------|---------------------|----------------|----------------|
| 90404   | REPAIR CLUTCH BRAKE | Blair MacAulay | 5.50           |

**Work Order:** 49195 **Status:** Transferred  
**Equipment:** TRACTOR TANDEM KW T880 [9167] **Serial Number:** 1XKZD40XXLJ969615  
**Work Location:** Fisher Pit **Business Unit:** Trucks Heavy  
**Created by:** Darcy Hallock **Start Date:** 12-11-2023  
**Kms:** 9140 **Stop Date:** 12-11-2023  
**Hr:** 9366

**Work Order Cost Summary**

| Description   | Quantity | Labor Type        | Rate               | Total          |
|---------------|----------|-------------------|--------------------|----------------|
| DARCY HALLOCK | 0.50     | RT Shop Tire Tech | \$36.33            | \$18.17        |
|               |          |                   | <b>Total Labor</b> | <b>\$18.17</b> |
|               |          |                   | <b>Total Parts</b> | <b>\$0.00</b>  |
|               |          |                   | <b>Total Equip</b> | <b>\$0.00</b>  |
|               |          |                   | <b>Total Cost</b>  | <b>\$18.17</b> |

| Item ID | Description                  | Completed By  | Reported Hours |
|---------|------------------------------|---------------|----------------|
| 90475   | 9167- 12/11/2023 "RE-TORQUE" | Darcy Hallock | 0.50           |

**Work Order:** 49888  
**Equipment:** TRACTOR TANDEM KW T880 [9167]  
**Work Location:** Rocky Mountain House Shop  
**Created by:** Blair MacAulay  
**Kms:** 9140  
**Hr:** 9366

**Status:** Transferred  
**Serial Number:** 1XKZD40XXLJ969615  
**Business Unit:** Trucks Heavy  
**Start Date:** 1-10-2024  
**Stop Date:** 1-11-2024

**Work Order Cost Summary**

| Description        | Quantity | Labor Type       | Rate    | Total   |
|--------------------|----------|------------------|---------|---------|
| JEREMY KEDDY       | 1.00     | RT Shop Mech Rky | \$49.05 | \$49.05 |
| MAXWELL KRABBen    | 1.00     | RT Shop Mech Rky | \$49.05 | \$49.05 |
| <b>Total Labor</b> |          |                  |         | \$98.10 |
| <b>Total Parts</b> |          |                  |         | \$0.00  |
| <b>Total Equip</b> |          |                  |         | \$0.00  |
| <b>Total Cost</b>  |          |                  |         | \$98.10 |

| Item ID | Description   | Completed By   | Reported Hours |
|---------|---------------|----------------|----------------|
| 91633   | START AND RUN | Blair MacAulay | 2.00           |

**Work Order:** 50122  
**Equipment:** TRACTOR TANDEM KW T880 [9167]  
**Work Location:** Blackfalds Shop  
**Created by:** Nick Depratto  
**Kms:** 9140  
**Hr:** 9366

**Status:** Transferred  
**Serial Number:** 1XKZD40XXLJ969615  
**Business Unit:** Trucks Heavy  
**Start Date:** 1-18-2024  
**Stop Date:** 1-31-2024

**Work Order Cost Summary**

| Description               | Quantity | Labor Type | Rate       | Total      |
|---------------------------|----------|------------|------------|------------|
| <b>Total Labor</b>        |          |            |            | \$0.00     |
| GWK INV SC1031175[Custom] | 1.00     | Each       | \$6,370.00 | \$6,370.00 |
| <b>Total Parts</b>        |          |            |            | \$6,370.00 |
| <b>Total Equip</b>        |          |            |            | \$0.00     |
| <b>Total Cost</b>         |          |            |            | \$6,370.00 |

| Item ID | Description                           | Completed By  | Reported Hours |
|---------|---------------------------------------|---------------|----------------|
| 91973   | KW CAL - REPAIR CLEAR COATING ON HOOD | Nick Depratto | 0.00           |

**Work Order:** 50486  
**Equipment:** TRACTOR TANDEM KW T880 [9167]  
**Work Location:** Rocky Mountain House Shop  
**Created by:** Blair MacAulay  
**Kms:** 9140  
**Hr:** 9366

**Status:** Transferred  
**Serial Number:** 1XKZD40XXLJ969615  
**Business Unit:** Trucks Heavy  
**Start Date:** 1-30-2024  
**Stop Date:** 1-31-2024

**Work Order Cost Summary**

| Description | Quantity | Labor Type | Rate               | Total  |
|-------------|----------|------------|--------------------|--------|
|             |          |            | <b>Total Labor</b> | \$0.00 |
|             |          |            | <b>Total Parts</b> | \$0.00 |
|             |          |            | <b>Total Equip</b> | \$0.00 |
|             |          |            | <b>Total Cost</b>  | \$0.00 |

| Item ID | Description                      | Completed By   | Reported Hours |
|---------|----------------------------------|----------------|----------------|
| 92511   | REPAIR DIFFERENTIAL LOCK WARNING | Blair MacAulay | 0.00           |

**Work Order:** 50845      **Status:** Transferred  
**Equipment:** TRACTOR TANDEM KW T880 [9167]      **Serial Number:** 1XKZD40XXLJ969615  
**Work Location:** Rocky Mountain House Shop      **Business Unit:** Trucks Heavy  
**Created by:** Blair MacAulay      **Start Date:** 2-8-2024  
**Kms:** 9140      **Stop Date:** 2-9-2024  
**Hr:** 9366

**Work Order Cost Summary**

| Description     | Quantity | Labor Type       | Rate               | Total   |
|-----------------|----------|------------------|--------------------|---------|
| JEREMY KEDDY    | 0.50     | RT Shop Mech Rky | \$49.05            | \$24.53 |
| MAXWELL KRABBEN | 1.00     | RT Shop Mech Rky | \$49.05            | \$49.05 |
|                 |          |                  | <b>Total Labor</b> | \$73.58 |
|                 |          |                  | <b>Total Parts</b> | \$0.00  |
|                 |          |                  | <b>Total Equip</b> | \$0.00  |
|                 |          |                  | <b>Total Cost</b>  | \$73.58 |

| Item ID | Description      | Completed By   | Reported Hours |
|---------|------------------|----------------|----------------|
| 93117   | REPAIR RR FENDER | Blair MacAulay | 1.50           |

**Work Order:** 51294      **Status:** Transferred  
**Equipment:** TRACTOR TANDEM KW T880 [9167]      **Serial Number:** 1XKZD40XXLJ969615  
**Work Location:** Rocky Mountain House Shop      **Business Unit:** Trucks Heavy  
**Created by:** Blair MacAulay      **Start Date:** 2-21-2024  
**Kms:** 9140      **Stop Date:** 2-22-2024  
**Hr:** 9366

**Work Order Cost Summary**

| Description   | Quantity | Labor Type       | Rate               | Total   |
|---------------|----------|------------------|--------------------|---------|
| MICHAEL GATES | 1.00     | RT Shop Mech Rky | \$49.05            | \$49.05 |
|               |          |                  | <b>Total Labor</b> | \$49.05 |
|               |          |                  | <b>Total Parts</b> | \$0.00  |
|               |          |                  | <b>Total Equip</b> | \$0.00  |
|               |          |                  | <b>Total Cost</b>  | \$49.05 |

| Item ID | Description      | Completed By   | Reported Hours |
|---------|------------------|----------------|----------------|
| 93991   | REPAIR AIR LEAKS | Blair MacAulay | 1.00           |

|                       |                               |                       |                   |
|-----------------------|-------------------------------|-----------------------|-------------------|
| <b>Work Order:</b>    | 51350                         | <b>Status:</b>        | Transferred       |
| <b>Equipment:</b>     | TRACTOR TANDEM KW T880 [9167] | <b>Serial Number:</b> | 1XKZD40XXLJ969615 |
| <b>Work Location:</b> | Rocky Mountain House Shop     | <b>Business Unit:</b> | Trucks Heavy      |
| <b>Created by:</b>    | Blair MacAulay                | <b>Start Date:</b>    | 2-22-2024         |
| <b>Kms:</b>           | 9140                          | <b>Stop Date:</b>     | 2-26-2024         |
| <b>Hr:</b>            | 9366                          |                       |                   |

**Work Order Cost Summary**

| Description   | Quantity | Labor Type       | Rate               | Total             |
|---|----------|------------------|--------------------|-------------------|
| BLAINE STEFFAN  | 9.25     | RT Shop Mech Rky | \$49.05            | \$453.71          |
| JEREMY KEDDY  | 3.25     | RT Shop Mech Rky | \$49.05            | \$159.41          |
|   |          |                  | <b>Total Labor</b> | <b>\$613.13</b>   |
| AIR BAG **SEE ATTACHMENT** {W013589865} [67043002]                                      | 1.00     | Each             | \$225.61           | \$225.61          |
| CAP- POWER STEERING RESERVOIR FILL VENT [Q347367]                                       | 1.00     | Each             | \$32.25            | \$32.25           |
| CLAMP [2880212]   | 1.00     | Each             | \$22.64            | \$22.64           |
| EXHAUST PIPE BELLOWS {M741020001, M6670910320} [EBPB11861]                              | 1.00     | Each             | \$372.11           | \$372.11          |
| FILTER AIR {DON: P621725} [P637453]   | 1.00     | Each             | \$160.47           | \$160.47          |
| FILTER AIR {PAC: CFR19012, X1987001, CF19013, FLG: AF55839, NAV: 4070948C1} [SR2000092] | 1.00     | Each             | \$53.74            | \$53.74           |
| FILTER FUEL SEPARATOR {DON: P550849, FLG: FS19764} [FS19763]                            | 1.00     | Each             | \$21.97            | \$21.97           |
| FILTER FUEL SPIN-ON {DON: DBF6776, FLG: FF5971NN} [FF5825NN]                            | 1.00     | Each             | \$54.33            | \$54.33           |
| FILTER LUBE SPIN-ON {FLG: LF14000NN, DON: DBL7900} [LF14001NN]                          | 1.00     | Each             | \$47.33            | \$47.33           |
| GASKET- EXHAUST CIRCULAR 4" [2866636CUM]  | 1.00     | Each             | \$21.63            | \$21.63           |
|   |          |                  | <b>Total Parts</b> | <b>\$1,012.07</b> |
|   |          |                  | <b>Total Equip</b> | <b>\$0.00</b>     |
|   |          |                  | <b>Total Cost</b>  | <b>\$1,625.20</b> |

| Item ID | Description                | Completed By   | Reported Hours |
|---------|----------------------------|----------------|----------------|
| 93350   | QR CODE UPDATE             | Blair MacAulay | 0.00           |
| 94053   | REPLACE EXHAUST BELLOWS    | Blair MacAulay | 2.00           |
| 94052   | 30K SERVICE                | Blair MacAulay | 8.25           |
| 94086   | REPLACE AIR BAGS #2LH #3LH | Blair MacAulay | 2.00           |
| 94085   | REPAIR AIR LEAKS           | Blair MacAulay | 0.25           |
| 94089   | ADJUST CLUTCH              | Blair MacAulay | 0.00           |

|                    |       |                |             |
|--------------------|-------|----------------|-------------|
| <b>Work Order:</b> | 51463 | <b>Status:</b> | Transferred |
|--------------------|-------|----------------|-------------|

**Equipment:** TRACTOR TANDEM KW T880 [9167]  
**Work Location:** Rocky Mountain House Shop  
**Created by:** Blair MacAulay  
**Kms:** 9140  
**Hr:** 9366

**Serial Number:** 1XKZD40XXLJ969615  
**Business Unit:** Trucks Heavy  
**Start Date:** 2-26-2024  
**Stop Date:** 2-28-2024

**Work Order Cost Summary**

| Description  | Quantity | Labor Type       | Rate               | Total             |
|--|----------|------------------|--------------------|-------------------|
| CLAYTON OLSON  | 12.25    | RT Shop Mech Rky | \$49.05            | \$600.86          |
|  |          |                  | <b>Total Labor</b> | <b>\$600.86</b>   |
| AIR BAG **SEE ATTACHMENT** {W013589865} [67043002]   | 2.00     | Each             | \$344.83           | \$689.66          |
| CLUTCH BRAKE {C127200} [SB200]   | 1.00     | Each             | \$42.20            | \$42.20           |
| FILTER DEF {CUM: 4388378, PAC: 2122909PE} [UF106]  | 1.00     | Each             | \$117.65           | \$117.65          |
| FILTER POWER STEERING {DON: P550830, NEL: 87904M} [39375575]   | 1.00     | Each             | \$23.09            | \$23.09           |
| LEVELING VALVE - DUMP PORT AIR UP, NO AIR DOWN {VS228} [KD2429]  | 1.00     | Each             | \$228.57           | \$228.57          |
| LEVELING VALVE - DUMP PORT AIR UP, NO AIR DOWN {VS228} [KD2429]  | 1.00     | Each             | \$203.42           | \$203.42          |
| PLUG, GEAR COVE [3688114]  | 1.00     | Each             | \$12.21            | \$12.21           |
| SHOCK ABSORBER, HYD LOCKOUT UNIT, 15.17 IN. COMP LENGTH, 24.13 IN. EXT LENGTH, 8.95 IN. TRAV LENGTH [60657003] | 4.00     | Each             | \$100.37           | \$401.48          |
|  |          |                  | <b>Total Parts</b> | <b>\$1,718.29</b> |
|  |          |                  | <b>Total Equip</b> | <b>\$0.00</b>     |
|  |          |                  | <b>Total Cost</b>  | <b>\$2,319.15</b> |

| Item ID | Description   | Completed By  | Reported Hours |
|---------|---|---------------|----------------|
| 94084   | REPLACE POWER STEERING FILTER (WAIT UNTIL NEXT SERVICE OR CVIP) | Clayton Olson | 0.50           |
| 94221   | CHECK CAB SHOCKS  | Clayton Olson | 5.50           |
| 94222   | REPLACE AIR BAGS #2RH #3RH                                      | Clayton Olson | 1.50           |
| 93500   | QR CODE UPDATE  | Clayton Olson | 0.25           |
| 94223   | CHECK LEVELING VALVE OPERATION                                  | Clayton Olson | 2.50           |
| 94224   | REPAIR CLUTCH BRAKE   | Clayton Olson | 1.00           |
| 93060   | DEF PUMP FILTER REPLACEMENT                                     | Clayton Olson | 0.50           |
| 94087   | REPAIR AIR HORN   | Clayton Olson | 0.25           |
| 94088   | REPAIR B/U ALARM  | Clayton Olson | 0.25           |

**Work Order:** 51596  
**Equipment:** TRACTOR TANDEM KW T880 [9167]  
**Work Location:** Rocky Mountain House Shop  
**Created by:** Blair MacAulay  
**Kms:** 9140  
**Hr:** 9366

**Status:** Transferred  
**Serial Number:** 1XKZD40XXLJ969615  
**Business Unit:** Trucks Heavy  
**Start Date:** 2-29-2024  
**Stop Date:** 3-6-2024

**Work Order Cost Summary**

| Description   | Quantity | Labor Type         | Rate     | Total             |
|---|----------|--------------------|----------|-------------------|
| KIRBY BERGEN  | 4.50     | RT Shop Mech Rky   | \$49.05  | \$220.73          |
| MAXWELL KRABBen   | 3.50     | RT Shop Mech Rky   | \$49.05  | \$171.68          |
| OLIVER TRAUTMANN  | 8.75     | RT Shop Mech Rky   | \$49.05  | \$429.19          |
|   |          | <b>Total Labor</b> |          | <b>\$821.59</b>   |
| 100P-W-CHK GRN33MM/1.313 [WLCHB]                                  | 60.00    | Each               | \$0.57   | \$34.29           |
| CABGUARD LIGHT BOX (1081)[Custom]                                 | 2.00     | Each               | \$94.95  | \$189.90          |
| JUNCTION TERMINAL BOX [821000]                                    | 1.00     | Each               | \$9.80   | \$9.80            |
| LIGHT AMBER OVAL 6" STOP TAIL TURN LED W/SEALED CONNECTOR [54143] | 4.00     | Each               | \$25.21  | \$100.82          |
| LIGHT PIGTAIL 3 PIN SEALED CONNECTOR [66861]                      | 8.00     | Each               | \$4.65   | \$37.23           |
| LIGHT RED OVAL 6" STOP TURN TAIL W/SEALED CONNECTOR [54142]       | 4.00     | Each               | \$24.69  | \$98.76           |
| MEDIUM TRUCK CHAIN [703017]                                       | 1.00     | Each               | \$542.00 | \$542.00          |
|   |          | <b>Total Parts</b> |          | <b>\$1,012.80</b> |
|   |          | <b>Total Equip</b> |          | <b>\$0.00</b>     |
|   |          | <b>Total Cost</b>  |          | <b>\$1,834.39</b> |

| Item ID | Description                              | Completed By   | Reported Hours |
|---------|--|----------------|----------------|
| 94466   | INSTALL PULL OUT LIGHTS ON HEADACHE RACK | Blair MacAulay | 9.50           |
| 94464   | INSTALL WHEEL NUT INDICATORS             | Blair MacAulay | 0.00           |
| 94456   | PREP FOR LOG HAUL                        | Blair MacAulay | 2.75           |
| 94465   | INSTALL DASH CAMERA                      | Blair MacAulay | 3.00           |
| 94468   | PROGRAM 2 WAY RADIO                      | Blair MacAulay | 0.00           |
| 94463   | INSTALL FIRE AXE HOLDER                  | Blair MacAulay | 1.50           |

|                       |                               |                       |                   |
|-----------------------|-------------------------------|-----------------------|-------------------|
| <b>Work Order:</b>    | 52421                         | <b>Status:</b>        | Transferred       |
| <b>Equipment:</b>     | TRACTOR TANDEM KW T880 [9167] | <b>Serial Number:</b> | 1XKZD40XXLJ969615 |
| <b>Work Location:</b> | Rocky Mountain House Shop     | <b>Business Unit:</b> | Trucks Heavy      |
| <b>Created by:</b>    | Blair MacAulay                | <b>Start Date:</b>    | 3-25-2024         |
| <b>Kms:</b>           | 9140                          | <b>Stop Date:</b>     | 3-28-2024         |
| <b>Hr:</b>            | 9366                          |                       |                   |

**Work Order Cost Summary**

| Description                          | Quantity | Labor Type         | Rate    | Total             |
|--------------------------------------|----------|--------------------|---------|-------------------|
| BRENT EVANS                          | 4.00     | RT Shop Mech Rky   | \$49.05 | \$196.20          |
| BRYCE TURNER                         | 5.00     | RT Shop Mech Rky   | \$49.05 | \$245.25          |
| JEREMY KEDDY                         | 15.50    | RT Shop Mech Rky   | \$49.05 | \$760.28          |
|                                      |          | <b>Total Labor</b> |         | <b>\$1,201.73</b> |
| BULB - HIGH OUTPUT [H6054HO]         | 1.00     | Each               | \$17.15 | \$17.15           |
| FUSE HOLDER {XR 82-2166} [509621001] | 1.00     | Each               | \$3.77  | \$3.77            |

|   |           |                    |            |
|---|-----------|--------------------|------------|
| INV 215486[Custom]  | 1.00 Each | \$402.80           | \$402.80   |
| WASHER PUMP W/GROMMET {PAC: 600208S, T4695001, WB6035402PUMP AUTO: HLK7046} [WB6035402PUMP] | 1.00 Each | \$19.53            | \$19.53    |
|   |           | <b>Total Parts</b> | \$443.24   |
|   |           | <b>Total Equip</b> | \$0.00     |
|   |           | <b>Total Cost</b>  | \$1,644.97 |

| Item ID | Description  | Completed By    | Reported Hours |
|---------|--|-----------------|----------------|
| 106545  | KW MECH INV 215486 - DIAGNOSE LIGHT OPERATION PROBLEMS | Sienna Campbell | 0.00           |
| 96248   | REPAIR COOLANT LEAKS                                   | Blair MacAulay  | 1.00           |
| 96234   | REPAIR LIGHTS  | Blair MacAulay  | 22.00          |
| 96233   | REPAIR WINDSHILD WASHERS                               | Blair MacAulay  | 1.50           |

**Work Order:** 52628      **Status:** Transferred  
**Equipment:** TRACTOR TANDEM KW T880 [9167]      **Serial Number:** 1XKZD40XXLJ969615  
**Work Location:**      **Business Unit:** Trucks Heavy  
**Created by:** Jeremy Detema      **Start Date:**  
**Kms:** 9140      **Stop Date:**  
**Hr:** 9366

**Work Order Cost Summary**

| Description  | Quantity | Labor Type | Rate               | Total    |
|--|----------|------------|--------------------|----------|
|  |          |            | <b>Total Labor</b> | \$0.00   |
| LIGHT CORD TRAILER 4 WAY 15' [194015]                | 1.00     | Each       | \$56.82            | \$56.82  |
| Northern Inv 100-888139[Custom]                      | 1.00     | Each       | \$525.60           | \$525.60 |
| TRAILER LIGHT CORD TARP 15' 2 POLE VERTICAL [212272] | 1.00     | Each       | \$176.33           | \$176.33 |
| TRAILER LIGHT CORD TARP 15' 2 POLE VERTICAL [212272] | 1.00     | Each       | \$198.08           | \$198.08 |
| WIPER BLADE 20" SUMMER *NOTES [WC2010]               | 2.00     | Each       | \$7.93             | \$15.85  |
|  |          |            | <b>Total Parts</b> | \$972.67 |
|  |          |            | <b>Total Equip</b> | \$0.00   |
|  |          |            | <b>Total Cost</b>  | \$972.67 |

| Item ID | Description                            | Completed By  | Reported Hours |
|---------|--|---------------|----------------|
| 96681   | 9167 - 02-04-2024(d/m/y) - DIRECT BILL | Jeremy Detema | 0.00           |

**Work Order:** 52638      **Status:** Transferred  
**Equipment:** TRACTOR TANDEM KW T880 [9167]      **Serial Number:** 1XKZD40XXLJ969615  
**Work Location:** Rocky Mountain House Shop      **Business Unit:** Trucks Heavy  
**Created by:** Blair MacAulay      **Start Date:** 4-2-2024  
**Kms:** 9140      **Stop Date:** 4-3-2024  
**Hr:** 9366

**Work Order Cost Summary**

| Description  | Quantity | Labor Type       | Rate               | Total   |
|--------------|----------|------------------|--------------------|---------|
| JEREMY KEDDY | 0.50     | RT Shop Mech Rky | \$49.05            | \$24.53 |
|              |          |                  | <b>Total Labor</b> | \$24.53 |
|              |          |                  | <b>Total Parts</b> | \$0.00  |
|              |          |                  | <b>Total Equip</b> | \$0.00  |
|              |          |                  | <b>Total Cost</b>  | \$24.53 |

| Item ID | Description                  | Completed By   | Reported Hours |
|---------|------------------------------|----------------|----------------|
| 96689   | REPAIR TRAILER MARKER LIGHTS | Blair MacAulay | 0.50           |

**Work Order:** 52699      **Status:** Transferred  
**Equipment:** TRACTOR TANDEM KW T880 [9167]      **Serial Number:** 1XKZD40XXLJ969615  
**Work Location:** Rocky Mountain House Shop      **Business Unit:** Trucks Heavy  
**Created by:** Blair MacAulay      **Start Date:** 4-3-2024  
**Kms:** 9140      **Stop Date:** 4-8-2024  
**Hr:** 9366

**Work Order Cost Summary**

| Description | Quantity | Labor Type | Rate               | Total  |
|-------------|----------|------------|--------------------|--------|
|             |          |            | <b>Total Labor</b> | \$0.00 |
|             |          |            | <b>Total Parts</b> | \$0.00 |
|             |          |            | <b>Total Equip</b> | \$0.00 |
|             |          |            | <b>Total Cost</b>  | \$0.00 |

| Item ID | Description        | Completed By   | Reported Hours |
|---------|--------------------|----------------|----------------|
| 96787   | REPLACE WINDSHIELD | Blair MacAulay | 0.00           |

**Work Order:** 52783      **Status:** Transferred  
**Equipment:** TRACTOR TANDEM KW T880 [9167]      **Serial Number:** 1XKZD40XXLJ969615  
**Work Location:** Rocky Mountain House Shop      **Business Unit:** Trucks Heavy  
**Created by:** Blair MacAulay      **Start Date:** 4-5-2024  
**Kms:** 9140      **Stop Date:** 4-8-2024  
**Hr:** 9366

**Work Order Cost Summary**

| Description | Quantity | Labor Type | Rate               | Total  |
|-------------|----------|------------|--------------------|--------|
|             |          |            | <b>Total Labor</b> | \$0.00 |
|             |          |            | <b>Total Parts</b> | \$0.00 |
|             |          |            | <b>Total Equip</b> | \$0.00 |
|             |          |            | <b>Total Cost</b>  | \$0.00 |

| Item ID | Description | Completed By | Reported Hours |
|---------|-------------|--------------|----------------|
|---------|-------------|--------------|----------------|

96953 REPAIR TRAILER MARKER LIGHTS Blair MacAulay 0.00

**Work Order:** 52857 **Status:** Transferred  
**Equipment:** TRACTOR TANDEM KW T880 [9167] **Serial Number:** 1XKZD40XXLJ969615  
**Work Location:** **Business Unit:** Trucks Heavy  
**Created by:** Oom Jarussirrat **Start Date:**  
**Kms:** 9140 **Stop Date:**  
**Hr:** 9366

**Work Order Cost Summary**

| Description | Quantity | Labor Type | Rate               | Total  |
|-------------|----------|------------|--------------------|--------|
|             |          |            | <b>Total Labor</b> | \$0.00 |
|             |          |            | <b>Total Parts</b> | \$0.00 |
|             |          |            | <b>Total Equip</b> | \$0.00 |
|             |          |            | <b>Total Cost</b>  | \$0.00 |

| Item ID | Description    | Completed By    | Reported Hours |
|---------|----------------|-----------------|----------------|
| 97074   | 4 WIRES ISSUE. | Oom Jarussirrat | 0.00           |

**Work Order:** 53191 **Status:** Transferred  
**Equipment:** TRACTOR TANDEM KW T880 [9167] **Serial Number:** 1XKZD40XXLJ969615  
**Work Location:** Blackfalds Yard **Business Unit:** Trucks Heavy  
**Created by:** Darcy Hallock **Start Date:** 4-16-2024  
**Kms:** 9140 **Stop Date:** 4-16-2024  
**Hr:** 9366

**Work Order Cost Summary**

| Description   | Quantity | Labor Type        | Rate               | Total   |
|---------------|----------|-------------------|--------------------|---------|
| DARCY HALLOCK | 0.50     | RT Shop Tire Tech | \$36.33            | \$18.17 |
|               |          |                   | <b>Total Labor</b> | \$18.17 |
|               |          |                   | <b>Total Parts</b> | \$0.00  |
|               |          |                   | <b>Total Equip</b> | \$0.00  |
|               |          |                   | <b>Total Cost</b>  | \$18.17 |

| Item ID | Description                            | Completed By  | Reported Hours |
|---------|--|---------------|----------------|
| 97619   | 9167- 04/16/2024 "INSTALL RUNOUT (X1)" | Darcy Hallock | 0.50           |

**Work Order:** 53694 **Status:** Transferred  
**Equipment:** TRACTOR TANDEM KW T880 [9167] **Serial Number:** 1XKZD40XXLJ969615  
**Work Location:** Blackfalds Shop **Business Unit:** Trucks Heavy  
**Created by:** Oom Jarussirrat **Start Date:** 4-30-2024

Kms: 9140  
Hr: 9366

Stop Date: 5-1-2024

**Work Order Cost Summary**

| Description  | Quantity | Labor Type         | Rate               | Total          |
|--------------|----------|--------------------|--------------------|----------------|
| DAMIAN MYERS | 1.00     | RT Shop Mech Blfds | \$52.07            | \$52.07        |
|              |          |                    | <b>Total Labor</b> | <b>\$52.07</b> |
|              |          |                    | <b>Total Parts</b> | <b>\$0.00</b>  |
|              |          |                    | <b>Total Equip</b> | <b>\$0.00</b>  |
|              |          |                    | <b>Total Cost</b>  | <b>\$52.07</b> |

| Item ID | Description                                   | Completed By | Reported Hours |
|---------|---|--------------|----------------|
| 98479   | WATER IN FUEL INDICATOR LIGHT KEEP COMING ON. | Damian Myers | 1.00           |

**Work Order:** 53828      **Status:** Transferred  
**Equipment:** TRACTOR TANDEM KW T880 [9167]      **Serial Number:** 1XKZD40XXLJ969615  
**Work Location:** Rocky Mountain House Shop      **Business Unit:** Trucks Heavy  
**Created by:** Blair MacAulay      **Start Date:** 5-6-2024  
**Kms:** 9140      **Stop Date:** 5-7-2024  
**Hr:** 9366

**Work Order Cost Summary**

| Description        | Quantity | Labor Type       | Rate               | Total           |
|--------------------|----------|------------------|--------------------|-----------------|
| BRENT EVANS        | 2.50     | RT Shop Mech Rky | \$49.05            | \$122.63        |
| H. KANIELA JOHNSON | 2.50     | RT Shop Weld Rky | \$47.83            | \$119.58        |
|                    |          |                  | <b>Total Labor</b> | <b>\$242.20</b> |
|                    |          |                  | <b>Total Parts</b> | <b>\$0.00</b>   |
|                    |          |                  | <b>Total Equip</b> | <b>\$0.00</b>   |
|                    |          |                  | <b>Total Cost</b>  | <b>\$242.20</b> |

| Item ID | Description      | Completed By | Reported Hours |
|---------|------------------|--------------|----------------|
| 98827   | REPAIR LR FENDER | Brent Evans  | 5.00           |

**Work Order:** 54527      **Status:** Transferred  
**Equipment:** TRACTOR TANDEM KW T880 [9167]      **Serial Number:** 1XKZD40XXLJ969615  
**Work Location:** Rocky Mountain House Shop      **Business Unit:** Trucks Heavy  
**Created by:** Oom Jarussirrat      **Start Date:** 7-24-2024  
**Kms:** 9140      **Stop Date:** 7-26-2024  
**Hr:** 9366

**Work Order Cost Summary**

| Description  | Quantity | Labor Type       | Rate    | Total      |
|--------------|----------|------------------|---------|------------|
| KIRBY BERGEN | 29.00    | RT Shop Mech Rky | \$49.05 | \$1,422.45 |

|  |           |               |                    |                   |
|--|-----------|---------------|--------------------|-------------------|
| MAXWELL KRABBen  | 24.00 RT  | Shop Mech Rky | \$49.05            | \$1,177.20        |
| OLIVER TRAUTMANN   | 2.25 RT   | Shop Mech Rky | \$49.05            | \$110.36          |
|  |           |               | <b>Total Labor</b> | <b>\$2,710.01</b> |
| 1" FEMALE WING COUPLER (612516) [NS515W8]                                  | 1.00 Each |               | \$60.89            | \$60.89           |
| STH WHEEL BRACKET PINS AND BUSHINGS FOR ILS - KIT - HOLLAND FW35 [RK10605] | 1.00 Each |               | \$90.95            | \$90.95           |
| AIR BAG **SEE ATTACHMENT** {67043002} [W013589865]                         | 1.00 Each |               | \$223.26           | \$223.26          |
| AXLE SHAFT STEEL GASKET {3303107} [3566160C1]                              | 2.00 Each |               | \$14.33            | \$28.65           |
| BRAKE SHOE HARDWARE KIT {E2769HD, BHK051,MKT4515QHD-B} [KIT8000HD]         | 1.00 Each |               | \$11.93            | \$11.93           |
| BRAKE SHOE HARDWARE KIT {R507064, BHK077} [E10244]                         | 1.00 Each |               | \$9.65             | \$9.65            |
| BUSHING-MOUNTING EXHAUST {AUTO: M13109} [M131009]                          | 2.00 Each |               | \$36.61            | \$73.22           |
| BUSHING-PIN ISOLATOR [M136004]   | 1.00 Each |               | \$10.81            | \$10.81           |
| CLUTCH BRAKE {C127200} [SB200]   | 1.00 Each |               | \$44.55            | \$44.55           |
| FILTER AIR {CF19013, X1987001, FLG: AF55839, NAV: 4070948C1} [SR2000092]   | 1.00 Each |               | \$56.52            | \$56.52           |
| FILTER AIR {DON: P621725} [P637453]  | 1.00 Each |               | \$136.25           | \$136.25          |
| FILTER CAB AIR [CF19013]   | 1.00 Each |               | \$32.77            | \$32.77           |
| FILTER FUEL SEPARATOR {DON: P550849, FLG: FS19764} [FS19763]               | 1.00 Each |               | \$21.53            | \$21.53           |
| FILTER FUEL SPIN-ON {DON: DBF6776, FLG: FF5971NN} [FF5825NN]               | 1.00 Each |               | \$54.59            | \$54.59           |
| FILTER FUEL WATER SEPERATOR {PAC: K371021} [FS20207]                       | 1.00 Each |               | \$38.88            | \$38.88           |
| FILTER HYDRAULIC SPIN-ON {FLG: HF6710, DON: P550388} [HF6720]              | 1.00 Each |               | \$19.63            | \$19.63           |
| FILTER LUBE SPIN-ON {FLG: LF14000NN, DON: DBL7900} [LF14001NN]             | 1.00 Each |               | \$51.94            | \$51.94           |
| GLADHAND SEAL CLOSE [FS312A]   | 2.00 Each |               | \$0.59             | \$1.16            |
| HANGER- MUDFLAP 32 1/2" [A253275RL]  | 2.00 Each |               | \$28.90            | \$57.79           |
| LIGHT PIGTAIL THREE WIRE 90 DEGREE [66843]                                 | 1.00 Each |               | \$3.49             | \$3.49            |
| LIGHT PIGTAIL UNIVERSAL 3 WIRE 90 DEGREE [67090]                           | 1.00 Each |               | \$1.55             | \$1.55            |
| LIGHT WHITE REVERSE 4" ROUND LED [12740310WB]                              | 2.00 Each |               | \$34.97            | \$69.93           |
| PIDHERNEYS MUD FLAP - 24 X 24 [PB2424]                                     | 2.00 Each |               | \$57.64            | \$115.28          |
| SCAM SEAL, ID 1-1/2", OD 2-1/16", THICK 1/4" {TA291270} [E654]             | 4.00 Each |               | \$1.95             | \$7.78            |
| SCAM WASHER - OD 2-1/4, ID 1-17/32, THICK 1/16" [E580]                     | 6.00 Each |               | \$0.78             | \$4.68            |
| WHEEL SEAL DRIVE AXLE [3929131]  | 2.00 Each |               | \$53.98            | \$107.96          |
|  |           |               | <b>Total Parts</b> | <b>\$1,335.66</b> |
|  |           |               | <b>Total Equip</b> | <b>\$0.00</b>     |
|  |           |               | <b>Total Cost</b>  | <b>\$4,045.67</b> |

| Item ID | Description  | Completed By     | Reported Hours |
|---------|--|------------------|----------------|
| 94888   | INSTALL 2024 ASGA STICKERS                                     | Oom Jarussirirat | 0.00           |
| 103074  | INSTALL REFLECTIVE TAPE  | Blair MacAulay   | 0.25           |
| 103061  | REPLACE HYDRAULIC TANK   | Blair MacAulay   | 5.00           |
| 98083   | DAVIES VECU POWER DIVIDER/DIFF PROGRAMING UPDATE - ONLY UPDATE | Blair MacAulay   | 0.50           |

THIS WILL SET THE POWER DIVIDER TO KICK OUT AT 85KM/HR AND THE DIFF LOCKS TO KICK OUT AT 65KM/HR

|        |  |                |       |
|--------|--|----------------|-------|
| 101792 | CVIP INSPECTION CV7843656                  | Blair MacAulay | 13.75 |
| 3073   | REPLACE GLAD HAND SEALS                    | Blair MacAulay | 0.25  |
| 101977 | 30K SERVICE                                | Blair MacAulay | 9.00  |
| 103060 | REPAIR LH UPPER EXHAUST STACK BRACKET      | Max Krabben    | 1.00  |
| 103075 | REPAIR LIGHTS                              | Max Krabben    | 1.00  |
| 103071 | REPAIR CRACKS IN HEADACHE RACK             | Max Krabben    | 1.00  |
| 94848  | INSTALL 2024 ASGA STICKERS                 | Max Krabben    | 0.25  |
| 100117 | REPLACE HYDRAULIC FILTER                   | Max Krabben    | 0.50  |
| 103069 | REPAIR AIR LEAKS                           | Max Krabben    | 0.50  |
| 102580 | BROKEN CLUTCH BRAKE.                       | Max Krabben    | 0.00  |
| 103115 | REPLACE AIR BAG #3RH                       | Max Krabben    | 1.00  |
| 103070 | REPLACE S CAMS AND BUSHINGS #2RH #3RH      | Max Krabben    | 9.00  |
| 103072 | REPLACE 5TH WHEEL SADDLE PINS AND BUSHINGS | Max Krabben    | 3.00  |
| 103068 | REPLACE CLUTCH BRAKE                       | Max Krabben    | 2.00  |
| 103067 | REPLACE WIPER BLADES                       | Max Krabben    | 0.25  |
| 103062 | REPAIR OIL PAN LEAK                        | Max Krabben    | 2.50  |
| 103059 | REPLACE CAB SHOCKS                         | Max Krabben    | 4.50  |

|                       |                               |                       |                   |
|-----------------------|-------------------------------|-----------------------|-------------------|
| <b>Work Order:</b>    | 54951                         | <b>Status:</b>        | Transferred       |
| <b>Equipment:</b>     | TRACTOR TANDEM KW T880 [9167] | <b>Serial Number:</b> | 1XKZD40XXLJ969615 |
| <b>Work Location:</b> | Blackfalds Shop               | <b>Business Unit:</b> | Trucks Heavy      |
| <b>Created by:</b>    | Oom Jarussirirat              | <b>Start Date:</b>    | 6-12-2024         |
| <b>Kms:</b>           | 9140                          | <b>Stop Date:</b>     | 6-13-2024         |
| <b>Hr:</b>            | 9366                          |                       |                   |

**Work Order Cost Summary**

| Description | Quantity | Labor Type         | Rate               | Total           |
|-------------|----------|--------------------|--------------------|-----------------|
| JOSHUA BOTA | 2.00     | RT Shop Mech Blfds | \$52.07            | \$104.14        |
|             |          |                    | <b>Total Labor</b> | <b>\$104.14</b> |
|             |          |                    | <b>Total Parts</b> | <b>\$0.00</b>   |
|             |          |                    | <b>Total Equip</b> | <b>\$0.00</b>   |
|             |          |                    | <b>Total Cost</b>  | <b>\$104.14</b> |

| Item ID | Description                        | Completed By     | Reported Hours |
|---------|------------------------------------|------------------|----------------|
| 100691  | NEED A NEW 4 WIRES PLUG ( FEMALE ) | Oom Jarussirirat | 2.00           |

**Work Order:** 54966 **Status:** Transferred  
**Equipment:** TRACTOR TANDEM KW T880 [9167] **Serial Number:** 1XKZD40XXLJ969615  
**Work Location:** Rocky Mountain House Shop **Business Unit:** Trucks Heavy  
**Created by:** Blair MacAulay **Start Date:** 6-13-2024  
**Kms:** 9140 **Stop Date:** 6-17-2024  
**Hr:** 9366

**Work Order Cost Summary**

| Description        | Quantity | Labor Type    | Rate    | Total           |
|--------------------|----------|---------------|---------|-----------------|
| JEREMY KEDDY       | 5.75 RT  | Shop Mech Rky | \$49.05 | \$282.04        |
| MICHAEL GATES      | 1.00 RT  | Shop Mech Rky | \$49.05 | \$49.05         |
| <b>Total Labor</b> |          |               |         | <b>\$331.09</b> |
| <b>Total Parts</b> |          |               |         | <b>\$0.00</b>   |
| <b>Total Equip</b> |          |               |         | <b>\$0.00</b>   |
| <b>Total Cost</b>  |          |               |         | <b>\$331.09</b> |

| Item ID | Description             | Completed By   | Reported Hours |
|---------|-------------------------|----------------|----------------|
| 100742  | REPLACE LF TIRE         | Blair MacAulay | 0.00           |
| 100715  | REPAIR TRAILER CONTROLS | Blair MacAulay | 6.75           |

**Work Order:** 55522 **Status:** Transferred  
**Equipment:** TRACTOR TANDEM KW T880 [9167] **Serial Number:** 1XKZD40XXLJ969615  
**Work Location:** Blackfalds Shop **Business Unit:** Trucks Heavy  
**Created by:** Oom Jarussirirat **Start Date:** 6-27-2024  
**Kms:** 9140 **Stop Date:** 6-29-2024  
**Hr:** 9366

**Work Order Cost Summary**

| Description        | Quantity | Labor Type | Rate | Total         |
|--------------------|----------|------------|------|---------------|
| <b>Total Labor</b> |          |            |      | <b>\$0.00</b> |
| <b>Total Parts</b> |          |            |      | <b>\$0.00</b> |
| <b>Total Equip</b> |          |            |      | <b>\$0.00</b> |
| <b>Total Cost</b>  |          |            |      | <b>\$0.00</b> |

| Item ID | Description              | Completed By     | Reported Hours |
|---------|--------------------------|------------------|----------------|
| 101659  | R & R TIRES AS NECESSARY | Oom Jarussirirat | 0.00           |

**Work Order:** 55554  
**Equipment:** TRACTOR TANDEM KW T880 [9167]  
**Work Location:** Blackfalds Shop  
**Created by:** Darcy Hallock  
**Kms:** 9140  
**Hr:** 9366

**Status:** Transferred  
**Serial Number:** 1XKZD40XXLJ969615  
**Business Unit:** Trucks Heavy  
**Start Date:** 6-28-2024  
**Stop Date:** 6-28-2024

**Work Order Cost Summary**

| Description                 | Quantity | Labor Type        | Rate               | Total             |
|-----------------------------|----------|-------------------|--------------------|-------------------|
| DARCY HALLOCK               | 3.75     | RT Shop Tire Tech | \$36.33            | \$136.24          |
|                             |          |                   | <b>Total Labor</b> | <b>\$136.24</b>   |
| TIRE DRIVE [11R245BDY2]     | 8.00     | Each              | \$354.45           | \$2,835.57        |
| TIRE STEER [31580R225FS819] | 2.00     | Each              | \$672.32           | \$1,344.64        |
|                             |          |                   | <b>Total Parts</b> | <b>\$4,180.21</b> |
|                             |          |                   | <b>Total Equip</b> | <b>\$0.00</b>     |
|                             |          |                   | <b>Total Cost</b>  | <b>\$4,316.45</b> |

| Item ID | Description                          | Completed By  | Reported Hours |
|---------|--------------------------------------|---------------|----------------|
| 101724  | 9167- 06/28/2024 "REPLACE ALL TIRES" | Darcy Hallock | 3.75           |

**Work Order:** 56174  
**Equipment:** TRACTOR TANDEM KW T880 [9167]  
**Work Location:** Blackfalds Shop  
**Created by:** Oom Jarussirirat  
**Kms:** 9140  
**Hr:** 9366

**Status:** Transferred  
**Serial Number:** 1XKZD40XXLJ969615  
**Business Unit:** Trucks Heavy  
**Start Date:** 7-18-2024  
**Stop Date:** 7-19-2024

**Work Order Cost Summary**

| Description                                    | Quantity | Labor Type         | Rate               | Total             |
|--|----------|--------------------|--------------------|-------------------|
| DAMIAN MYERS                                   | 0.50     | RT Shop Mech Blfds | \$52.07            | \$26.04           |
|  |          |                    | <b>Total Labor</b> | <b>\$26.04</b>    |
| AIR SPRING SERVICE KIT[Custom]                 | 1.00     | Each               | (\$96.65)          | (\$96.65)         |
| AIR SPRING-SERVICE KIT [25523011]              | 1.00     | Each               | \$96.65            | \$96.65           |
| C/S 1.5X28X14.953 RH QP [ARQ0677R]             | 2.00     | Each               | \$102.61           | \$205.22          |
| CAB SHOCK [08308107I]                          | 2.00     | Each               | \$49.00            | \$98.00           |
| CAM BUSHING 1.50X1.88X1.25 [E536]              | 4.00     | Each               | \$2.26             | \$9.04            |
| CAMSHAFT BRACKET 5" {EUCLID: E2477B} [1110018] | 1.00     | Each               | \$21.17            | \$21.17           |
| GASKET - OIL PAN [4026684]                     | 1.00     | Each               | \$347.98           | \$347.98          |
| HYDRAULIC TANK [HYD70CP]                       | 1.00     | Each               | \$1,343.00         | \$1,343.00        |
| PAN, OIL [5647538CUM]                          | 1.00     | Each               | \$1,740.72         | \$1,740.72        |
|  |          |                    | <b>Total Parts</b> | <b>\$3,765.13</b> |
|  |          |                    | <b>Total Equip</b> | <b>\$0.00</b>     |
|  |          |                    | <b>Total Cost</b>  | <b>\$3,791.17</b> |

| Item ID | Description     | Completed By | Reported Hours |
|---------|-----------------|--------------|----------------|
| 102805  | AIR LEAKS ISSUE | Damian Myers | 0.50           |

|                       |                               |                       |                   |
|-----------------------|-------------------------------|-----------------------|-------------------|
| <b>Work Order:</b>    | 56679                         | <b>Status:</b>        | Transferred       |
| <b>Equipment:</b>     | TRACTOR TANDEM KW T880 [9167] | <b>Serial Number:</b> | 1XKZD40XXLJ969615 |
| <b>Work Location:</b> | Blackfalds Shop               | <b>Business Unit:</b> | Trucks Heavy      |
| <b>Created by:</b>    | Nick Depratto                 | <b>Start Date:</b>    | 8-2-2024          |
| <b>Kms:</b>           | 9140                          | <b>Stop Date:</b>     | 8-2-2024          |
| <b>Hr:</b>            | 9366                          |                       |                   |

**Work Order Cost Summary**

| Description  | Quantity | Labor Type         | Rate               | Total           |
|--|----------|--------------------|--------------------|-----------------|
| DAMIAN MYERS   | 1.50     | RT Shop Mech Blfds | \$52.07            | \$78.11         |
|  |          |                    | <b>Total Labor</b> | <b>\$78.11</b>  |
| #16 HOSE TO #16MPT [N1616MP]   | 4.00     | Each               | \$14.52            | \$58.08         |
| 1" QUICK COUPLER FEMALE [QDISOAC1616F]                                   | 1.00     | Each               | \$53.29            | \$53.29         |
| 1" QUICK COUPLER NIPPLE [QDISOAN1616F]                                   | 2.00     | Each               | \$24.88            | \$49.75         |
| 1" WING NUT COUPLER [QDBTTWC1616F]                                       | 1.00     | Each               | \$54.27            | \$54.27         |
| FILTER AIR {CF19013, X1987001, FLG: AF55839, NAV: 4070948C1} [SR2000092] | 1.00     | Each               | \$56.12            | \$56.12         |
|  |          |                    | <b>Total Parts</b> | <b>\$271.51</b> |
|  |          |                    | <b>Total Equip</b> | <b>\$0.00</b>   |
|  |          |                    | <b>Total Cost</b>  | <b>\$349.62</b> |

| Item ID | Description                    | Completed By | Reported Hours |
|---------|--------------------------------|--------------|----------------|
| 103733  | REPLACE LEAKING HYDRAULIC HOSE | Damian Myers | 1.50           |

|                       |                               |                       |                   |
|-----------------------|-------------------------------|-----------------------|-------------------|
| <b>Work Order:</b>    | 56787                         | <b>Status:</b>        | Transferred       |
| <b>Equipment:</b>     | TRACTOR TANDEM KW T880 [9167] | <b>Serial Number:</b> | 1XKZD40XXLJ969615 |
| <b>Work Location:</b> | Blackfalds Shop               | <b>Business Unit:</b> | Trucks Heavy      |
| <b>Created by:</b>    | Oom Jarussirirat              | <b>Start Date:</b>    | 8-7-2024          |
| <b>Kms:</b>           | 9140                          | <b>Stop Date:</b>     | 8-9-2024          |
| <b>Hr:</b>            | 9366                          |                       |                   |

**Work Order Cost Summary**

| Description   | Quantity | Labor Type         | Rate               | Total             |
|---|----------|--------------------|--------------------|-------------------|
| WAYNE KIRK  | 4.00     | RT Shop Mech Blfds | \$52.07            | \$208.28          |
|   |          |                    | <b>Total Labor</b> | <b>\$208.28</b>   |
| 12V, 2000 WATT, PURE SINE WAVE INVERTER [GPISW200012] | 1.00     | Each               | \$992.04           | \$992.04          |
|   |          |                    | <b>Total Parts</b> | <b>\$992.04</b>   |
|   |          |                    | <b>Total Equip</b> | <b>\$0.00</b>     |
|   |          |                    | <b>Total Cost</b>  | <b>\$1,200.32</b> |

| Item ID | Description  | Completed By | Reported Hours |
|---------|--|--------------|----------------|
| 102807  | INSTALL CEL PHONE BOOSTER ( DIRVER WILL PROVIDED THE BOOSTER ) | Wayne Kirk   | 4.00           |

**Work Order:** 57233 **Status:** Transferred  
**Equipment:** TRACTOR TANDEM KW T880 [9167] **Serial Number:** 1XKZD40XXLJ969615  
**Work Location:** **Business Unit:** Trucks Heavy  
**Created by:** Oom Jarussirirat **Start Date:**  
**Kms:** 9140 **Stop Date:**  
**Hr:** 9366

**Work Order Cost Summary**

| Description  | Quantity | Labor Type         | Rate               | Total           |
|--|----------|--------------------|--------------------|-----------------|
| DARCY PLATT  | 4.75     | RT Shop Mech Blfds | \$52.07            | \$247.33        |
|  |          |                    | <b>Total Labor</b> | <b>\$247.33</b> |
| HOSE - SILICONE 2.5" {561.75548} {TRP GW27992} [F501548] | 1.00     | Each               | \$33.43            | \$33.43         |
|  |          |                    | <b>Total Parts</b> | <b>\$33.43</b>  |
|  |          |                    | <b>Total Equip</b> | <b>\$0.00</b>   |
|  |          |                    | <b>Total Cost</b>  | <b>\$280.77</b> |

| Item ID | Description            | Completed By | Reported Hours |
|---------|------------------------|--------------|----------------|
| 14658   | DPF ISSUE              | Darcy Platt  | 1.75           |
| 104657  | BLOWN BOTTOM RAD HOSES | Darcy Platt  | 3.00           |

**Work Order:** 57360 **Status:** Transferred  
**Equipment:** TRACTOR TANDEM KW T880 [9167] **Serial Number:** 1XKZD40XXLJ969615  
**Work Location:** Blackfalds Yard **Business Unit:** Trucks Heavy  
**Created by:** Bernie Seefried **Start Date:** 8-22-2024  
**Kms:** 9140 **Stop Date:** 8-22-2024  
**Hr:** 9366

**Work Order Cost Summary**

| Description     | Quantity | Labor Type         | Rate               | Total          |
|-----------------|----------|--------------------|--------------------|----------------|
| BERNIE SEEFRIED | 1.75     | RT Shop Mech Blfds | \$52.07            | \$91.12        |
|                 |          |                    | <b>Total Labor</b> | <b>\$91.12</b> |
|                 |          |                    | <b>Total Parts</b> | <b>\$0.00</b>  |
|                 |          |                    | <b>Total Equip</b> | <b>\$0.00</b>  |
|                 |          |                    | <b>Total Cost</b>  | <b>\$91.12</b> |

| Item ID | Description            | Completed By    | Reported Hours |
|---------|------------------------|-----------------|----------------|
| 104881  | INSTALL NEW GPS SYSTEM | Bernie Seefried | 1.75           |

**Work Order:** 57449  
**Equipment:** TRACTOR TANDEM KW T880 [9167]  
**Work Location:**  
**Created by:** Jeremy Detema  
**Kms:** 9140  
**Hr:** 9366

**Status:** Transferred  
**Serial Number:** 1XKZD40XXLJ969615  
**Business Unit:** Trucks Heavy  
**Start Date:**  
**Stop Date:**

**Work Order Cost Summary**

| Description  | Quantity | Labor Type | Rate               | Total    |
|--|----------|------------|--------------------|----------|
|  |          |            | <b>Total Labor</b> | \$0.00   |
| CAP - FILL {XR SC2027} [N5349002]                    | 1.00     | Each       | \$31.42            | \$31.42  |
| TIRE DRIVE LIGHT CHAIN 7MM TRIPLE [11R245CHAIN2]     | 2.00     | Each       | \$282.11           | \$564.22 |
| TRAILER LIGHT CORD TARP 15' 2 POLE VERTICAL [212272] | 1.00     | Each       | \$198.04           | \$198.04 |
|  |          |            | <b>Total Parts</b> | \$793.68 |
|  |          |            | <b>Total Equip</b> | \$0.00   |
|  |          |            | <b>Total Cost</b>  | \$793.68 |

| Item ID | Description                    | Completed By  | Reported Hours |
|---------|--------------------------------|---------------|----------------|
| 105031  | 9167 / DIRECTBILL / 2024/08/26 | Jeremy Detema | 0.00           |

**Work Order:** 58003  
**Equipment:** TRACTOR TANDEM KW T880 [9167]  
**Work Location:** Blackfalds Shop  
**Created by:** Oom Jarussirirat  
**Kms:** 9140  
**Hr:** 9366

**Status:** Transferred  
**Serial Number:** 1XKZD40XXLJ969615  
**Business Unit:** Trucks Heavy  
**Start Date:** 9-9-2024  
**Stop Date:** 9-11-2024

**Work Order Cost Summary**

| Description | Quantity | Labor Type         | Rate               | Total    |
|-------------|----------|--------------------|--------------------|----------|
| DARCY PLATT | 6.00     | RT Shop Mech Blfds | \$52.07            | \$312.42 |
|             |          |                    | <b>Total Labor</b> | \$312.42 |
|             |          |                    | <b>Total Parts</b> | \$0.00   |
|             |          |                    | <b>Total Equip</b> | \$0.00   |
|             |          |                    | <b>Total Cost</b>  | \$312.42 |

| Item ID | Description                 | Completed By | Reported Hours |
|---------|-----------------------------|--------------|----------------|
| 99958   | INSTALL 2000 WATTS INVERTOR | Darcy Platt  | 6.00           |

**Work Order:** 58285  
**Equipment:** TRACTOR TANDEM KW T880 [9167]  
**Work Location:**

**Status:** Transferred  
**Serial Number:** 1XKZD40XXLJ969615  
**Business Unit:** Trucks Heavy

Created by: Sienna Campbell  
Kms: 9140  
Hr: 9366

Start Date:  
Stop Date:

Work Order Cost Summary

| Description       | Quantity | Labor Type | Rate               | Total      |
|-------------------|----------|------------|--------------------|------------|
|                   |          |            | <b>Total Labor</b> | \$0.00     |
| INV 69990[Custom] | 1.00     | Each       | \$3,039.85         | \$3,039.85 |
|                   |          |            | <b>Total Parts</b> | \$3,039.85 |
|                   |          |            | <b>Total Equip</b> | \$0.00     |
|                   |          |            | <b>Total Cost</b>  | \$3,039.85 |

| Item ID | Description   | Completed By    | Reported Hours |
|---------|---|-----------------|----------------|
| 106696  | PB RD INV 69990 - TEST AND CLEAN DPF, DRILL AND TAP BROKEN BOLT | Sienna Campbell | 0.00           |

Work Order: 60459      Status: Transferred  
Equipment: TRACTOR TANDEM KW T880 [9167]      Serial Number: 1XKZD40XXLJ969615  
Work Location: Blackfalds Yard      Business Unit: Trucks Heavy  
Created by: Dustin Boon      Start Date: 11-5-2024  
Kms: 9140      Stop Date: 11-6-2024  
Hr: 9366

Work Order Cost Summary

| Description                             | Quantity | Labor Type        | Rate               | Total      |
|---|----------|-------------------|--------------------|------------|
| DUSTIN BOON                             | 6.00     | RT Shop Tire Tech | \$36.33            | \$217.98   |
|   |          |                   | <b>Total Labor</b> | \$217.98   |
| TIRE {M775, BDY2, FST835} [11R245DRIVE] | 8.00     | Each              | \$410.14           | \$3,281.12 |
|   |          |                   | <b>Total Parts</b> | \$3,281.12 |
|   |          |                   | <b>Total Equip</b> | \$0.00     |
|   |          |                   | <b>Total Cost</b>  | \$3,499.10 |

| Item ID | Description                   | Completed By | Reported Hours |
|---------|-------------------------------|--------------|----------------|
| 110523  | 9167 - R&R tires as necessary | Dustin Boon  | 6.00           |

Work Order: 60535      Status: Transferred  
Equipment: TRACTOR TANDEM KW T880 [9167]      Serial Number: 1XKZD40XXLJ969615  
Work Location: Blackfalds Shop      Business Unit: Trucks Heavy  
Created by: Oom Jarussirirat      Start Date: 11-6-2024  
Kms: 9140      Stop Date: 11-8-2024  
Hr: 9366

Work Order Cost Summary

| Description | Quantity | Labor Type | Rate | Total |
|-------------|----------|------------|------|-------|
|-------------|----------|------------|------|-------|

|   |           |                    |           |            |
|---|-----------|--------------------|-----------|------------|
| BRENT TURNEY  | 4.00 RT   | Shop Weld Rky      | \$47.83   | \$191.32   |
| JOSHUA BOTA   | 24.00 RT  | Shop Mech Blfds    | \$52.07   | \$1,249.68 |
| MITCHELL ROHRBACH   | 4.25 RT   | Shop Mech Blfds    | \$52.07   | \$221.30   |
|   |           | <b>Total Labor</b> |           | \$1,662.30 |
| BLOCK HEATER [3500107]  | 1.00 Each |                    | \$94.71   | \$94.71    |
| CLAMP - V BAND [5304600CUM]   | 1.00 Each |                    | \$92.15   | \$92.15    |
| CORE ITEM - KIT, AFTERTREATMENT [5578983RXCUM]                              | 1.00 Each |                    | \$997.79  | \$997.79   |
| CORE ITEM - KIT, AFTERTREATMENT[Custom]                                     | 1.00 Each |                    | (\$91.30) | (\$91.30)  |
| DOOR CONTROL MODULE [Q2710481200]   | 1.00 Each |                    | \$950.85  | \$950.85   |
| EXH GASKET [2880215]  | 1.00 Each |                    | \$25.60   | \$25.60    |
| FILTER AIR {CF19013, X1987001, FLG: AF55839, NAV: 4070948C1}<br>[SR2000092] | 1.00 Each |                    | \$54.31   | \$54.31    |
| FILTER AIR {DON: P621725} [P637453]   | 1.00 Each |                    | \$115.02  | \$115.02   |
| FILTER AIR DRYER - BENDIX ADIS {BEN: 5008415PG} [5008414PG]                 | 1.00 Each |                    | \$177.88  | \$177.88   |
| FILTER FUEL SEPARATOR {DON: P550849, FLG: FS19764} [FS19763]                | 1.00 Each |                    | \$22.54   | \$22.54    |
| FILTER FUEL SPIN-ON {DON: DBF6776, FLG: FF5971NN} [FF5825NN]                | 1.00 Each |                    | \$56.01   | \$56.01    |
| FILTER LUBE SPIN-ON {FLG: LF14000NN, DON: DBL7900} [LF14001NN]              | 1.00 Each |                    | \$50.59   | \$50.59    |
| GASKET - AFM DEVICE/DPF {CUM: 5304868, PAC: 2188190PE} [5417859]            | 3.00 Each |                    | \$99.16   | \$297.48   |
| RD BP INV 70900[Custom]   | 1.00 Each |                    | \$386.95  | \$386.95   |
| RUBBER 90DEG ELBOW {56175250} [F046006]                                     | 1.00 Each |                    | \$110.15  | \$110.15   |
| TRAILER LIGHT CORD TARP 15' 2 POLE VERTICAL [212272]                        | 1.00 Each |                    | \$196.13  | \$196.13   |
| V BAND, CLAMP [5304849]   | 3.00 Each |                    | \$135.86  | \$407.58   |
|   |           | <b>Total Parts</b> |           | \$3,944.43 |
|   |           | <b>Total Equip</b> |           | \$0.00     |
|   |           | <b>Total Cost</b>  |           | \$5,606.73 |

| Item ID | Description   | Completed By | Reported Hours |
|---------|---|--------------|----------------|
| 109216  | 30K SERVICE   | Joshua Bota  | 4.00           |
| 110592  | CHECK ENG BLOCK HEATER                                | Joshua Bota  | 2.00           |
| 110622  | FAN MOTOR LOUND ON HIGH                               | Joshua Bota  | 0.00           |
| 110611  | NEED TO CLEAN ALL BATT'S CONNECTIONS                  | Joshua Bota  | 0.00           |
| 106222  | REPLACE AIR DRYER CARTRIDGE FILTER                    | Joshua Bota  | 0.00           |
| 110627  | NEED A NEW FIRE EXTINGUISHER                          | Joshua Bota  | 0.00           |
| 110625  | NEED A NEW TARP CORD ON DECK                          | Joshua Bota  | 0.00           |
| 110624  | LOOSE FENDER FLAIR ON DS                              | Joshua Bota  | 0.00           |
| 110623  | NEED NEW GLAD HAND RUBBERS                            | Joshua Bota  | 0.00           |
| 110612  | COOLANT LEAKS ISSUE ( UPPER RAD HOSE BY THERMO STAT ) | Joshua Bota  | 11.00          |

|        |  |                   |      |
|--------|--|-------------------|------|
| 110628 | MISSING DS WINDOW BOTTON   | Joshua Bota       | 1.00 |
| 110665 | RD PB INV 70964 CEL ISSUE; DPF ASH LOAD (REMOVE DOC & DPF FILTERS AND<br>SEND THEM OUT TO GET CLEANED) | Mitchell Rohrbach | 7.50 |
| 110614 | NEED TO TOP UP HYD TANK ( HALF WAY UP THE SITE GLASS )   | Joshua Bota       | 0.00 |
| 110835 | NEED A NEW DEF DOZER; LEAKING  | Mitchell Rohrbach | 0.75 |
| 110593 | FILL ALCOHOL EVAP CANISTOR   | Joshua Bota       | 0.00 |
| 110830 | HYD LEAKS ISSUE  | Oom Jarussirirat  | 1.00 |
| 110626 | NEED A CLUTCH ADJUSTMENT   | Oom Jarussirirat  | 1.00 |
| 110613 | CRACKS ON REAR FENDERS   | Brent Turney      | 4.00 |

|                       |                               |                       |                   |
|-----------------------|-------------------------------|-----------------------|-------------------|
| <b>Work Order:</b>    | 61226                         | <b>Status:</b>        | Transferred       |
| <b>Equipment:</b>     | TRACTOR TANDEM KW T880 [9167] | <b>Serial Number:</b> | 1XKZD40XXLJ969615 |
| <b>Work Location:</b> | Blackfalds Shop               | <b>Business Unit:</b> | Trucks Heavy      |
| <b>Created by:</b>    | Oom Jarussirirat              | <b>Start Date:</b>    | 11-25-2024        |
| <b>Kms:</b>           | 9140                          | <b>Stop Date:</b>     | 11-27-2024        |
| <b>Tr:</b>            | 9366                          |                       |                   |

**Work Order Cost Summary**

| Description  | Quantity | Labor Type         | Rate               | Total             |
|--|----------|--------------------|--------------------|-------------------|
| DARCY PLATT  | 11.50    | RT Shop Mech Blfds | \$52.07            | \$598.81          |
|  |          |                    | <b>Total Labor</b> | <b>\$598.81</b>   |
| BURNER - D2 AIRTRONIC [252069100100]                                   | 1.00     | Each               | \$367.91           | \$367.91          |
| CLAMP - V BAND [5304600CUM]  | 1.00     | Each               | \$92.21            | \$92.21           |
| DFN PRESSURE SENSOR [5492073]  | 1.00     | Each               | \$187.61           | \$187.61          |
| ESPAR AIRTRONIC D2/D4 - GASKET, BLOWER [252069010003]                  | 1.00     | Each               | \$7.56             | \$7.56            |
| ESPAR AIRTRONIC D2/D4 - GLOW PIN SCREEN WITH TOOL [252069100102]       | 1.00     | Each               | \$15.71            | \$15.71           |
| ESPAR AIRTRONIC D2/D4 - THERMAL INSULATOR FOR BURNER<br>[252069060001] | 1.00     | Each               | \$5.17             | \$5.17            |
| EXH GASKET [2880215]   | 1.00     | Each               | \$26.09            | \$26.09           |
| GLOW PIN 12V W/WRENCH [252069011300]                                   | 1.00     | Each               | \$226.91           | \$226.91          |
|  |          |                    | <b>Total Parts</b> | <b>\$929.17</b>   |
|  |          |                    | <b>Total Equip</b> | <b>\$0.00</b>     |
|  |          |                    | <b>Total Cost</b>  | <b>\$1,527.98</b> |

| Item ID | Description                | Completed By | Reported Hours |
|---------|----------------------------|--------------|----------------|
| 111894  | BUNK HEATER IS NOT WORKING | Darcy Platt  | 3.50           |
| 111893  | CEL ISSUE; DERATED         | Darcy Platt  | 8.00           |

|                       |                               |                       |                   |
|-----------------------|-------------------------------|-----------------------|-------------------|
| <b>Work Order:</b>    | 62309                         | <b>Status:</b>        | Closed            |
| <b>Equipment:</b>     | TRACTOR TANDEM KW T880 [9167] | <b>Serial Number:</b> | 1XKZD40XXLJ969615 |
| <b>Work Location:</b> | Blackfalds Shop               | <b>Business Unit:</b> | Trucks Heavy      |
| <b>Created by:</b>    | Oom Jarussirirat              | <b>Start Date:</b>    | 1-6-2025          |
| <b>Kms:</b>           | 9140                          | <b>Stop Date:</b>     | 1-7-2025          |
| <b>Hr:</b>            | 9366                          |                       |                   |

**Work Order Cost Summary**

| Description   | Quantity | Labor Type         | Rate    | Total           |
|---------------|----------|--------------------|---------|-----------------|
| BLAKE HOPKINS | 3.50 RT  | Shop Mech Blfds    | \$52.07 | \$182.25        |
| WAYNE KIRK    | 1.75 RT  | Shop Mech Blfds    | \$52.07 | \$91.12         |
|               |          | <b>Total Labor</b> |         | <b>\$273.37</b> |
|               |          | <b>Total Parts</b> |         | <b>\$0.00</b>   |
|               |          | <b>Total Equip</b> |         | <b>\$0.00</b>   |
|               |          | <b>Total Cost</b>  |         | <b>\$273.37</b> |

| Item ID | Description       | Completed By  | Reported Hours |
|---------|-------------------|---------------|----------------|
| 114156  | TRUCK WON'T START | Blake Hopkins | 5.25           |

|                       |                               |                       |                   |
|-----------------------|-------------------------------|-----------------------|-------------------|
| <b>Work Order:</b>    | 62420                         | <b>Status:</b>        | Closed            |
| <b>Equipment:</b>     | TRACTOR TANDEM KW T880 [9167] | <b>Serial Number:</b> | 1XKZD40XXLJ969615 |
| <b>Work Location:</b> | Blackfalds Shop               | <b>Business Unit:</b> | Trucks Heavy      |
| <b>Created by:</b>    | Oom Jarussirirat              | <b>Start Date:</b>    | 1-7-2025          |
| <b>Kms:</b>           | 9140                          | <b>Stop Date:</b>     | 1-8-2025          |
| <b>Hr:</b>            | 9366                          |                       |                   |

**Work Order Cost Summary**

| Description                          | Quantity | Labor Type         | Rate     | Total           |
|--------------------------------------|----------|--------------------|----------|-----------------|
| DAMIAN MYERS                         | 0.50 RT  | Shop Mech Blfds    | \$52.07  | \$26.04         |
| MITCHELL ROHRBACH                    | 1.00 RT  | Shop Mech Blfds    | \$52.07  | \$52.07         |
|                                      |          | <b>Total Labor</b> |          | <b>\$78.11</b>  |
| STRUT-ASSIST, LOCKING HOOD [L711017] | 1.00     | Each               | \$656.20 | \$656.20        |
|                                      |          | <b>Total Parts</b> |          | <b>\$656.20</b> |
|                                      |          | <b>Total Equip</b> |          | <b>\$0.00</b>   |
|                                      |          | <b>Total Cost</b>  |          | <b>\$734.31</b> |

| Item ID | Description                                | Completed By | Reported Hours |
|---------|--|--------------|----------------|
| 114240  | NEED A NEW HOOD SHOCK WITH RED LOCKING TAB | Damian Myers | 1.50           |

|                    |       |                |        |
|--------------------|-------|----------------|--------|
| <b>Work Order:</b> | 62491 | <b>Status:</b> | Closed |
|--------------------|-------|----------------|--------|

**Equipment:** TRACTOR TANDEM KW T880 [9167]  
**Work Location:** Blackfalds Shop  
**Created by:** Oom Jarussirat  
**Kms:** 9140  
**nr:** 9366

**Serial Number:** 1XKZD40XXLJ969615  
**Business Unit:** Trucks Heavy  
**Start Date:** 1-8-2025  
**Stop Date:** 1-9-2025

**Work Order Cost Summary**

| Description  | Quantity | Labor Type         | Rate               | Total   |
|--------------|----------|--------------------|--------------------|---------|
| DAMIAN MYERS | 1.50     | RT Shop Mech Blfds | \$52.07            | \$78.11 |
|              |          |                    | <b>Total Labor</b> | \$78.11 |
|              |          |                    | <b>Total Parts</b> | \$0.00  |
|              |          |                    | <b>Total Equip</b> | \$0.00  |
|              |          |                    | <b>Total Cost</b>  | \$78.11 |

| Item ID | Description                      | Completed By | Reported Hours |
|---------|----------------------------------|--------------|----------------|
| 114358  | REMOVE CELL PHONE BOOSTER SYSTEM | Damian Myers | 1.50           |

**Work Order:** 64322  
**Equipment:** TRACTOR TANDEM KW T880 [9167]  
**Work Location:** Blackfalds Shop  
**Created by:** Oom Jarussirat  
**Kms:** 9140  
**nr:** 9366

**Status:** Closed  
**Serial Number:** 1XKZD40XXLJ969615  
**Business Unit:** Trucks Heavy  
**Start Date:** 2-28-2025  
**Stop Date:** 3-1-2025

**Work Order Cost Summary**

| Description  | Quantity | Labor Type         | Rate               | Total    |
|--|----------|--------------------|--------------------|----------|
| BLAKE HOPKINS  | 1.50     | RT Shop Mech Blfds | \$52.07            | \$78.11  |
|  |          |                    | <b>Total Labor</b> | \$78.11  |
| A/C SECONDARY BELT - SERPENTINE - RIBS: 6 - EFFECTIVE LENGTH (IN): 64.0<br>{638K6BLT, 640K6BLT} [D8410006061620] | 1.00     | Each               | \$49.96            | \$49.96  |
| FAN DRIVE BELT 12RIBS X 2180mm {FLTBT858K12, 858K12BLT}<br>[D8410006122180]                                      | 1.00     | Each               | \$98.97            | \$98.97  |
| TENSIONER, BELT [3690067]  | 1.00     | Each               | \$259.23           | \$259.23 |
|  |          |                    | <b>Total Parts</b> | \$408.16 |
|  |          |                    | <b>Total Equip</b> | \$0.00   |
|  |          |                    | <b>Total Cost</b>  | \$486.27 |

| Item ID | Description                 | Completed By   | Reported Hours |
|---------|-----------------------------|----------------|----------------|
| 117668  | NEED NEW ENG FAN & A/C BELT | Oom Jarussirat | 1.50           |

**Work Order:** 64576  
**Equipment:** TRACTOR TANDEM KW T880 [9167]  
**Work Location:** Rocky Mountain House Shop  
**Created by:** Blair MacAulay  
**Kms:** 9140

**Status:** Closed  
**Serial Number:** 1XKZD40XXLJ969615  
**Business Unit:** Trucks Heavy  
**Start Date:** 3-6-2025  
**Stop Date:** 3-7-2025

Hr: 9366

**Work Order Cost Summary**

| Description   | Quantity | Labor Type       | Rate               | Total   |
|---------------|----------|------------------|--------------------|---------|
| MICHAEL GATES | 1.00     | RT Shop Mech Rky | \$49.05            | \$49.05 |
|               |          |                  | <b>Total Labor</b> | \$49.05 |
|               |          |                  | <b>Total Parts</b> | \$0.00  |
|               |          |                  | <b>Total Equip</b> | \$0.00  |
|               |          |                  | <b>Total Cost</b>  | \$49.05 |

| Item ID | Description           | Completed By   | Reported Hours |
|---------|-----------------------|----------------|----------------|
| 118229  | REPAIR TRAILER LIGHTS | Blair MacAulay | 1.00           |

**Work Order:** 64702      **Status:** Closed  
**Equipment:** TRACTOR TANDEM KW T880 [9167]      **Serial Number:** 1XKZD40XXLJ969615  
**Work Location:** Rocky Mountain House Shop      **Business Unit:** Trucks Heavy  
**Created by:** Blair MacAulay      **Start Date:** 3-11-2025  
**Kms:** 9140      **Stop Date:** 3-12-2025  
**Hr:** 9366

**Work Order Cost Summary**

| Description | Quantity | Labor Type | Rate               | Total  |
|-------------|----------|------------|--------------------|--------|
|             |          |            | <b>Total Labor</b> | \$0.00 |
|             |          |            | <b>Total Parts</b> | \$0.00 |
|             |          |            | <b>Total Equip</b> | \$0.00 |
|             |          |            | <b>Total Cost</b>  | \$0.00 |

| Item ID | Description         | Completed By   | Reported Hours |
|---------|---------------------|----------------|----------------|
| 118450  | REPAIR DUMP CONTROL | Blair MacAulay | 0.00           |

**Work Order:** 64999      **Status:** Closed  
**Equipment:** TRACTOR TANDEM KW T880 [9167]      **Serial Number:** 1XKZD40XXLJ969615  
**Work Location:** Rocky Mountain House Shop      **Business Unit:** Trucks Heavy  
**Created by:** Blair MacAulay      **Start Date:** 3-17-2025  
**Kms:** 9140      **Stop Date:** 3-18-2025  
**Hr:** 9366

**Work Order Cost Summary**

| Description               | Quantity | Labor Type       | Rate               | Total     |
|---------------------------|----------|------------------|--------------------|-----------|
| OLIVER TRAUTMANN          | 1.00     | RT Shop Mech Rky | \$49.05            | \$49.05   |
|                           |          |                  | <b>Total Labor</b> | \$49.05   |
| FENDER LIGHT [TLEDK100CA] | 1.00     | Each             | \$37.77            | \$37.77   |
| LED Light[Custom]         | 1.00     | Each             | (\$37.77)          | (\$37.77) |
|                           |          |                  | <b>Total Parts</b> | \$0.00    |

Total Equip \$0.00

Total Cost \$49.05

| Item ID | Description             | Completed By   | Reported Hours |
|---------|-------------------------|----------------|----------------|
| 118886  | REPAIR RH FENDER MARKER | Blair MacAulay | 1.00           |

**Work Order:** 65342      **Status:** Closed  
**Equipment:** TRACTOR TANDEM KW T880 [9167]      **Serial Number:** 1XKZD40XXLJ969615  
**Work Location:** Rocky Mountain House Shop      **Business Unit:** Trucks Heavy  
**Created by:** Blair MacAulay      **Start Date:** 3-31-2025  
**Kms:** 9140      **Stop Date:** 4-1-2025  
**Hr:** 9366

**Work Order Cost Summary**

| Description   | Quantity | Labor Type       | Rate       | Total             |
|---|----------|------------------|------------|-------------------|
| BLAINE STEFFAN  | 9.50     | RT Shop Mech Rky | \$49.05    | \$465.98          |
| H. KANIELA JOHNSON  | 5.00     | RT Shop Weld Rky | \$47.83    | \$239.15          |
| <b>Total Labor</b>  |          |                  |            | <b>\$705.13</b>   |
| CLUTCH BRAKE {C127200,M1881} [SB200]                              | 1.00     | Each             | \$48.94    | \$48.94           |
| CONNECTOR [1745605PE]   | 1.00     | Each             | \$3.73     | \$3.73            |
| CONNECTOR ELC[Custom]   | 1.00     | Each             | (\$125.66) | (\$125.66)        |
| CONNECTOR, ELC REPAIR [5573151]                                   | 1.00     | Each             | \$125.66   | \$125.66          |
| CORE ITEM - SENSOR NITROGEN OXIDE NOX CUMMINS (REMAN) [3687930RX] | 1.00     | Each             | \$962.05   | \$962.05          |
| CORE ITEM - SENSOR NITROGEN OXIDE NOX CUMMINS (REMAN) [3687930RX] | 1.00     | Each             | \$962.05   | \$962.05          |
| CORE RETURN[Custom]   | 1.00     | Each             | (\$187.00) | (\$187.00)        |
| DOOR STOP - CHECK LINK [R831024]                                  | 1.00     | Each             | \$216.21   | \$216.21          |
| SHIPPING COSTS - ROCKY MOUNTAIN HOUSE [7543]                      | 1.00     | Totl             | \$40.00    | \$40.00           |
| <b>Total Parts</b>  |          |                  |            | <b>\$2,045.98</b> |
| <b>Total Equip</b>  |          |                  |            | <b>\$0.00</b>     |
| <b>Total Cost</b>   |          |                  |            | <b>\$2,751.10</b> |

| Item ID | Description          | Completed By   | Reported Hours |
|---------|----------------------|----------------|----------------|
| 119640  | REPLACE NOX SENSOR   | Blair MacAulay | 3.50           |
| 119556  | REPLACE LH DOOR STOP | Blair MacAulay | 3.00           |
| 119557  | ADJUST CLUTCH BRAKE  | Blair MacAulay | 2.00           |
| 119765  | REPAIR REAR FENDERS  | Kani Johnson   | 3.00           |
| 119639  | REPLACE CLUTCH BRAKE | Blair MacAulay | 3.00           |

**Work Order:** 65826  
**Equipment:** TRACTOR TANDEM KW T880 [9167]  
**Work Location:** MAIN YARD  
**Created by:** Darcy Hallock  
**Kms:** 9140  
**Hr:** 9366

**Status:** Closed  
**Serial Number:** 1XKZD40XXLJ969615  
**Business Unit:** Trucks Heavy  
**Start Date:** 4-8-2025  
**Stop Date:** 4-8-2025

**Work Order Cost Summary**

| Description   | Quantity | Labor Type        | Rate               | Total         |
|---------------|----------|-------------------|--------------------|---------------|
| DARCY HALLOCK | 0.25     | RT Shop Tire Tech | \$36.33            | \$9.08        |
|               |          |                   | <b>Total Labor</b> | <b>\$9.08</b> |
|               |          |                   | <b>Total Parts</b> | <b>\$0.00</b> |
|               |          |                   | <b>Total Equip</b> | <b>\$0.00</b> |
|               |          |                   | <b>Total Cost</b>  | <b>\$9.08</b> |

| Item ID | Description                        | Completed By  | Reported Hours |
|---------|------------------------------------|---------------|----------------|
| 120394  | 9167- 04/08/2025 "CHECK PRESSURES" | Darcy Hallock | 0.25           |

**Work Order:** 65975  
**Equipment:** TRACTOR TANDEM KW T880 [9167]  
**Work Location:** Rocky Mountain House Shop  
**Created by:** Blair MacAulay  
**Kms:** 9140  
**Hr:** 9366

**Status:** Closed  
**Serial Number:** 1XKZD40XXLJ969615  
**Business Unit:** Trucks Heavy  
**Start Date:** 4-11-2025  
**Stop Date:** 4-14-2025

**Work Order Cost Summary**

| Description  | Quantity | Labor Type       | Rate               | Total           |
|--|----------|------------------|--------------------|-----------------|
| KEVIN HUMMEL   | 4.50     | RT Shop Mech Rky | \$49.05            | \$220.73        |
|  |          |                  | <b>Total Labor</b> | <b>\$220.73</b> |
| WASHER PUMP W/GROMMET {PAC: 600208S, T4695001, WB6035402PUMP<br>AUTO: HLK7046} [WB6035402PUMP] | 1.00     | Each             | \$18.47            | \$18.47         |
|  |          |                  | <b>Total Parts</b> | <b>\$18.47</b>  |
|  |          |                  | <b>Total Equip</b> | <b>\$0.00</b>   |
|  |          |                  | <b>Total Cost</b>  | <b>\$239.19</b> |

| Item ID | Description              | Completed By   | Reported Hours |
|---------|--------------------------|----------------|----------------|
| 120675  | REPAIR RR FENDER         | Blair MacAulay | 1.50           |
| 120674  | REPAIR WINDSHIELD WASHER | Blair MacAulay | 1.00           |
| 120673  | ADJUST RIDE HEIGHT       | Blair MacAulay | 2.00           |

**Work Order:** 66111  
**Equipment:** TRACTOR TANDEM KW T880 [9167]  
**Work Location:** Rocky Mountain House Shop

**Status:** Closed  
**Serial Number:** 1XKZD40XXLJ969615  
**Business Unit:** Trucks Heavy

Created by: Blair MacAulay  
Kms: 9140  
Hr: 9366

Start Date: 4-16-2025  
Stop Date: 4-17-2025

Work Order Cost Summary

| Description        | Quantity | Labor Type       | Rate    | Total           |
|--------------------|----------|------------------|---------|-----------------|
| BLAINE STEFFAN     | 5.00     | RT Shop Mech Rky | \$49.05 | \$245.25        |
| OLIVER TRAUTMANN   | 5.00     | RT Shop Mech Rky | \$49.05 | \$245.25        |
| <b>Total Labor</b> |          |                  |         | <b>\$490.50</b> |
| <b>Total Parts</b> |          |                  |         | <b>\$0.00</b>   |
| <b>Total Equip</b> |          |                  |         | <b>\$0.00</b>   |
| <b>Total Cost</b>  |          |                  |         | <b>\$490.50</b> |

| Item ID | Description          | Completed By     | Reported Hours |
|---------|----------------------|------------------|----------------|
| 121027  | REPAIR COOLANT LEAKS | Oliver Trautmann | 1.00           |
| 121026  | REPLACE LH DOOR STOP | Oliver Trautmann | 1.00           |
| 120960  | PERFORM VALVE SET    | Oliver Trautmann | 6.00           |
| 120961  | REPAIR TARP CONTROL  | Oliver Trautmann | 2.00           |

Work Order: 66684      Status: Closed  
Equipment: TRACTOR TANDEM KW T880 [9167]      Serial Number: 1XKZD40XXLJ969615  
Work Location: Rocky Mountain House Shop      Business Unit: Trucks Heavy  
Created by: Blair MacAulay      Start Date: 5-1-2025  
Kms: 9140      Stop Date: 5-7-2025  
Hr: 9366

Work Order Cost Summary

| Description                  | Quantity | Labor Type       | Rate    | Total           |
|------------------------------|----------|------------------|---------|-----------------|
| BLAINE STEFFAN               | 2.00     | RT Shop Mech Rky | \$49.05 | \$98.10         |
| <b>Total Labor</b>           |          |                  |         | <b>\$98.10</b>  |
| 60AMP RESET BREAKER [CB60PB] | 2.00     | Each             | \$56.84 | \$113.67        |
| <b>Total Parts</b>           |          |                  |         | <b>\$113.67</b> |
| <b>Total Equip</b>           |          |                  |         | <b>\$0.00</b>   |
| <b>Total Cost</b>            |          |                  |         | <b>\$211.77</b> |

| Item ID | Description           | Completed By   | Reported Hours |
|---------|-----------------------|----------------|----------------|
| 122028  | REPAIR TARP CONTROL   | Blair MacAulay | 1.00           |
| 122039  | REPLACE TARP BREAKERS | Blair MacAulay | 1.00           |

**Work Order:** 67153  
**Equipment:** TRACTOR TANDEM KW T880 [9167]  
**Work Location:** Rocky Mountain House Shop  
**Created by:** Blair MacAulay  
**Kms:** 9140  
**Hr:** 9366

**Status:** Closed  
**Serial Number:** 1XKZD40XXLJ969615  
**Business Unit:** Trucks Heavy  
**Start Date:** 5-12-2025  
**Stop Date:** 5-14-2025

**Work Order Cost Summary**

| Description   | Quantity | Labor Type       | Rate               | Total             |
|---|----------|------------------|--------------------|-------------------|
| BLAINE STEFFAN  | 5.00     | RT Shop Mech Rky | \$49.05            | \$245.25          |
|   |          |                  | <b>Total Labor</b> | <b>\$245.25</b>   |
| CORE ITEM - FAN HUB HORTON DM ADVANTAGE TWO-SPEED REMAN [79A9782RMAN]         | 1.00     | Each             | \$2,118.48         | \$2,118.48        |
| CORE ITEM - FAN HUB HORTON DM ADVANTAGE TWO-SPEED REMAN [79A9782RMAN][Custom] | 1.00     | Each             | (\$484.00)         | (\$484.00)        |
| FAN HUB KW [010024141]  | 0.00     | Each             | \$577.63           | \$0.00            |
|   |          |                  | <b>Total Parts</b> | <b>\$1,634.48</b> |
|   |          |                  | <b>Total Equip</b> | <b>\$0.00</b>     |
|   |          |                  | <b>Total Cost</b>  | <b>\$1,879.73</b> |

| Item ID | Description     | Completed By   | Reported Hours |
|---------|-----------------|----------------|----------------|
| 122765  | REPLACE FAN HUB | Blair MacAulay | 5.00           |

**Work Order:** 67620  
**Equipment:** TRACTOR TANDEM KW T880 [9167]  
**Work Location:** Rocky Mountain House Shop  
**Created by:** Blair MacAulay  
**Kms:** 9140  
**Hr:** 9366

**Status:** Closed  
**Serial Number:** 1XKZD40XXLJ969615  
**Business Unit:** Trucks Heavy  
**Start Date:** 5-26-2025  
**Stop Date:** 5-27-2025

**Work Order Cost Summary**

| Description                                | Quantity | Labor Type       | Rate               | Total           |
|--|----------|------------------|--------------------|-----------------|
| OLIVER TRAUTMANN                           | 1.50     | RT Shop Mech Rky | \$49.05            | \$73.58         |
|  |          |                  | <b>Total Labor</b> | <b>\$73.58</b>  |
| AIR DRYER PURGE VALVE ADIS, ADIP [K022105] | 1.00     | Each             | \$189.00           | \$189.00        |
|  |          |                  | <b>Total Parts</b> | <b>\$189.00</b> |
|  |          |                  | <b>Total Equip</b> | <b>\$0.00</b>   |
|  |          |                  | <b>Total Cost</b>  | <b>\$262.57</b> |

| Item ID | Description          | Completed By   | Reported Hours |
|---------|----------------------|----------------|----------------|
| 123608  | REPAIR LEAK AT DRYER | Blair MacAulay | 0.50           |
| 123614  | REPLACE PURGE VALVE  | Blair MacAulay | 1.00           |

**Work Order:** 67734  
**Equipment:** TRACTOR TANDEM KW T880 [9167]  
**Work Location:**  
**Created by:** Jeremy Detema  
**ms:** 9140  
**Hr:** 9366

**Status:** Closed  
**Serial Number:** 1XKZD40XXLJ969615  
**Business Unit:** Trucks Heavy  
**Start Date:**  
**Stop Date:**

**Work Order Cost Summary**

| Description  | Quantity | Labor Type | Rate               | Total    |
|--|----------|------------|--------------------|----------|
|  |          |            | <b>Total Labor</b> | \$0.00   |
| CAP - FILL {XR SC2027} [N5349002]                    | 1.00     | Each       | \$55.58            | \$55.58  |
| JUNCTION TERMINAL BOX [821000]                       | 1.00     | Each       | \$11.74            | \$11.74  |
| WHEEL HUB CAP {HA4009} {3434009} [STMCO_3034009]     | 2.00     | Each       | \$16.51            | \$33.01  |
| WIPER BOTTLE CAP {5722007; DORMIN 902-5401} [C5720S] | 1.00     | Each       | \$3.13             | \$3.13   |
|  |          |            | <b>Total Parts</b> | \$103.47 |
|  |          |            | <b>Total Equip</b> | \$0.00   |
|  |          |            | <b>Total Cost</b>  | \$103.47 |

| Item ID | Description                 | Completed By | Reported Hours |
|---------|-----------------------------|--------------|----------------|
| 123769  | 9167-05/28/2025-DIRECT BILL | Kevin Gordan | 0.00           |

**Work Order:** 67793  
**Equipment:** TRACTOR TANDEM KW T880 [9167]  
**Work Location:** MAIN YARD  
**Created by:** Darcy Hallock  
**Kms:** 9140  
**Hr:** 9366

**Status:** Closed  
**Serial Number:** 1XKZD40XXLJ969615  
**Business Unit:** Trucks Heavy  
**Start Date:** 5-29-2025  
**Stop Date:** 5-29-2025

**Work Order Cost Summary**

| Description   | Quantity | Labor Type        | Rate               | Total  |
|---------------|----------|-------------------|--------------------|--------|
| DARCY HALLOCK | 0.25     | RT Shop Tire Tech | \$36.33            | \$9.08 |
|               |          |                   | <b>Total Labor</b> | \$9.08 |
|               |          |                   | <b>Total Parts</b> | \$0.00 |
|               |          |                   | <b>Total Equip</b> | \$0.00 |
|               |          |                   | <b>Total Cost</b>  | \$9.08 |

| Item ID | Description                           | Completed By  | Reported Hours |
|---------|---------------------------------------|---------------|----------------|
| 123890  | 9167- 05/29/2025 "B-STONE TIRE CHECK" | Darcy Hallock | 0.25           |

**Work Order:** 67999  
**Equipment:** TRACTOR TANDEM KW T880 [9167]  
**Work Location:** Rocky Mountain House Shop  
**Created by:** Blair MacAulay

**Status:** Closed  
**Serial Number:** 1XKZD40XXLJ969615  
**Business Unit:** Trucks Heavy  
**Start Date:** 6-3-2025

Kms: 9140  
 Hr: 9366

Stop Date: 6-6-2025

**Work Order Cost Summary**

| Description  | Quantity | Labor Type       | Rate               | Total             |
|--|----------|------------------|--------------------|-------------------|
| CLAYTON OLSON  | 21.00    | RT Shop Mech Rky | \$49.05            | \$1,030.05        |
| H. KANIELA JOHNSON   | 2.00     | RT Shop Weld Rky | \$47.83            | \$95.66           |
| JEFF DUBEAU  | 20.50    | RT Shop Mech Rky | \$49.05            | \$1,005.53        |
|  |          |                  | <b>Total Labor</b> | <b>\$2,131.24</b> |
| BEARING - CENTRE SUPPORT (STEADY) {CB2106611XSA} [10094142]                                | 1.00     | Each             | \$112.82           | \$112.82          |
| BEARING STRAP RETAINER KIT [2507018X]  | 1.00     | Each             | \$33.33            | \$33.33           |
| BEARING STRAP RETAINER KIT [2507018X]  | 1.00     | Each             | \$19.80            | \$19.80           |
| BRAKE CHAMBER - TYPE 3030LS, 3.00" STROKE {SB3030CL} [FLT3030LCB20]                        | 2.00     | Each             | \$62.57            | \$125.13          |
| BUSHING - SPRING PIN {AUTOMANN: MTB186} [B131002]  | 4.00     | Each             | \$81.68            | \$326.73          |
| FEMALE SWV JIC ( 37 ) - CRIMP {ECH_E16-16FJ PAR_10643-16-16} [106431616]                   | 4.00     | Each             | \$25.44            | \$101.76          |
| FILTER AIR {DON: P621725} [P637453]  | 1.00     | Each             | \$113.21           | \$113.21          |
| FILTER DEF {CUM: 4388378, PAC: 2122909PE} [UF106]  | 1.00     | Each             | \$118.76           | \$118.76          |
| FILTER DEF {CUM: 4388378, PAC: 2122909PE} [UF106]  | 1.00     | Each             | \$117.15           | \$117.15          |
| FILTER FUEL SEPARATOR {DON: P550849, FLG: FS19764} [FS19763]                               | 1.00     | Each             | \$22.39            | \$22.39           |
| FILTER FUEL SPIN-ON {DON: DBF6776, FLG: FF5971NN} [FF5825NN]                               | 1.00     | Each             | \$57.59            | \$57.59           |
| FILTER HYDRAULIC SPIN-ON {FLG: HF6720, DON: P550388 DON: P550387, STAUFF: SF6720} [HF6710] | 2.00     | Each             | \$17.51            | \$35.02           |
| FILTER LUBE SPIN-ON {FLG: LF14000NN, DON: DBL7900, SMS: 6002111341} [LF14001NN]            | 1.00     | Each             | \$52.45            | \$52.45           |
| FILTER POWER STEERING {DON: P550830, 3937557S} [87904M]                                    | 1.00     | Each             | \$30.93            | \$30.93           |
| PIN - SPRING {KW: B656008} [M5447]   | 4.00     | Each             | \$101.56           | \$406.24          |
| STRAP - A/T MOUNTING [M846103]   | 1.00     | Each             | \$57.27            | \$57.27           |
| SUNVISOR CLIP, LIGHT GRAY [S161023661]   | 1.00     | Each             | \$30.77            | \$30.77           |
| WHEEL HUB CAP GASKET [453869]  | 1.00     | Each             | \$1.74             | \$1.74            |
| WHEEL SEAL STEER AXLE [3828036]  | 1.00     | Each             | \$48.52            | \$48.52           |
|  |          |                  | <b>Total Parts</b> | <b>\$1,811.64</b> |
|  |          |                  | <b>Total Equip</b> | <b>\$0.00</b>     |
|  |          |                  | <b>Total Cost</b>  | <b>\$3,942.87</b> |

| Item ID | Description   | Completed By  | Reported Hours |
|---------|---|---------------|----------------|
| 115673  | REPLACE POWER STEERING FILTER (WAIT UNTIL NEXT SERVICE OR CVIP) | Jeff Dubeau   | 0.50           |
| 124271  | CVIP INSPECTION CV8131075                                       | Clayton Olson | 12.00          |
| 124354  | REPLACE STEADY BEARING  | Clayton Olson | 2.00           |
| 124363  | WELD RR FENDER  | Kani Johnson  | 1.00           |
| 124353  | SECURE RH BOTTOM STEP   | Jeff Dubeau   | 2.00           |

|        |  |               |      |
|--------|--|---------------|------|
| 124360 | REPLACE BRAKE POTS #2RH #3LH             | Clayton Olson | 2.00 |
| 124361 | REPLACE LH INTERIOR VISOR CLIP           | Clayton Olson | 0.25 |
| 124272 | REPLACE HYDRAULIC FILTER                 | Jeff Dubeau   | 1.00 |
| 124359 | REPLACE FIRE EXTINGUISHER                | Clayton Olson | 0.50 |
| 124368 | REPLACE PRESSURE HOSE OFF HYDRAULIC PUMP | Clayton Olson | 3.75 |
| 124352 | REPAIR LH AIR BAGS DEFLATED              | Clayton Olson | 0.50 |
| 124366 | REPAIR HYDRAULIC PUMP SUPPORT            | Kani Johnson  | 1.00 |
| 124358 | SECURE HOSE #3RH AIR BAG                 | Clayton Olson | 0.25 |
| 124356 | REPAIR DPF MOUNTS                        | Jeff Dubeau   | 0.00 |
| 124273 | 30K SERVICE                              | Clayton Olson | 4.00 |
| 124364 | SECURE BATTERIES                         | Jeff Dubeau   | 0.50 |
| 124367 | REPLACE REAR SPRING PINS #1 AXLE         | Jeff Dubeau   | 8.50 |
| 124355 | SECURE EXHAUST SUPPORT BEHIND FLEX PIPE  | Jeff Dubeau   | 1.50 |
| 124362 | TIGHTEN #2LH TORQUE ROD BOLT             | Clayton Olson | 0.25 |
| 124365 | REPLACE WHEEL SEAL #1LH                  | Jeff Dubeau   | 2.00 |

|                       |                               |                       |                   |
|-----------------------|-------------------------------|-----------------------|-------------------|
| <b>Work Order:</b>    | 68031                         | <b>Status:</b>        | Closed            |
| <b>Equipment:</b>     | TRACTOR TANDEM KW T880 [9167] | <b>Serial Number:</b> | 1XKZD40XXLJ969615 |
| <b>Work Location:</b> | Rocky Mountain House Shop     | <b>Business Unit:</b> | Trucks Heavy      |
| <b>Created by:</b>    | Darcy Hallock                 | <b>Start Date:</b>    | 6-3-2025          |
| <b>Kms:</b>           | 9140                          | <b>Stop Date:</b>     | 6-3-2025          |
| <b>Hr:</b>            | 9366                          |                       |                   |

**Work Order Cost Summary**

| Description                             | Quantity | Labor Type        | Rate               | Total             |
|---|----------|-------------------|--------------------|-------------------|
| DARCY HALLOCK                           | 1.50     | RT Shop Tire Tech | \$36.33            | \$54.50           |
|   |          |                   | <b>Total Labor</b> | <b>\$54.50</b>    |
| TIRE {BST M863, FS821} [31580R225STEER] | 2.00     | Each              | \$874.00           | \$1,748.00        |
|   |          |                   | <b>Total Parts</b> | <b>\$1,748.00</b> |
|   |          |                   | <b>Total Equip</b> | <b>\$0.00</b>     |
|   |          |                   | <b>Total Cost</b>  | <b>\$1,802.50</b> |

| Item ID | Description  | Completed By  | Reported Hours |
|---------|--|---------------|----------------|
| 124322  | 9167- 06/03/2025 "PRESSURE CHECK/REPLACE STEERS(X2)" | Darcy Hallock | 1.50           |

**Work Order:** 68416 **Status:** Closed  
**Equipment:** TRACTOR TANDEM KW T880 [9167] **Serial Number:** 1XKZD40XXLJ969615  
**Work Location:** Blackfalds Yard **Business Unit:** Trucks Heavy  
**Created by:** Bernie Seefried **Start Date:** 6-10-2025  
**Kms:** 9140 **Stop Date:** 6-11-2025  
**Hr:** 9366

**Work Order Cost Summary**

| Description     | Quantity | Labor Type         | Rate               | Total   |
|-----------------|----------|--------------------|--------------------|---------|
| BERNIE SEEFRIED | 0.50     | RT Shop Mech Blfds | \$52.07            | \$26.04 |
|                 |          |                    | <b>Total Labor</b> | \$26.04 |
|                 |          |                    | <b>Total Parts</b> | \$0.00  |
|                 |          |                    | <b>Total Equip</b> | \$0.00  |
|                 |          |                    | <b>Total Cost</b>  | \$26.04 |

| Item ID | Description   | Completed By    | Reported Hours |
|---------|---------------|-----------------|----------------|
| 124955  | TORQUE WHEELS | Bernie Seefried | 0.50           |

**Work Order:** 68912 **Status:** Closed  
**Equipment:** TRACTOR TANDEM KW T880 [9167] **Serial Number:** 1XKZD40XXLJ969615  
**Work Location:** ROCKY VIEW COUNTY 2025 GRAVEL PROGRAM **Business Unit:** Trucks Heavy  
**Created by:** Bernie Seefried **Start Date:** 6-18-2025  
**Kms:** 9140 **Stop Date:** 6-18-2025  
**Hr:** 9366

**Work Order Cost Summary**

| Description     | Quantity | Labor Type         | Rate               | Total    |
|-----------------|----------|--------------------|--------------------|----------|
| BERNIE SEEFRIED | 4.00     | RT Shop Mech Blfds | \$52.07            | \$208.28 |
|                 |          |                    | <b>Total Labor</b> | \$208.28 |
|                 |          |                    | <b>Total Parts</b> | \$0.00   |
|                 |          |                    | <b>Total Equip</b> | \$0.00   |
|                 |          |                    | <b>Total Cost</b>  | \$208.28 |

| Item ID | Description            | Completed By    | Reported Hours |
|---------|------------------------|-----------------|----------------|
| 125648  | RH SIGNAL BLOWING FUSE | Bernie Seefried | 4.00           |

**Work Order:** 69233  
**Equipment:** TRACTOR TANDEM KW T880 [9167]  
**Work Location:** ROCKY VIEW COUNTY 2025 GRAVEL PROGRAM  
**Created by:** Bernie Seefried  
**Kms:** 9140  
**Hr:** 9366

**Status:** Closed  
**Serial Number:** 1XKZD40XXLJ969615  
**Business Unit:** Trucks Heavy  
**Start Date:** 6-24-2025  
**Stop Date:** 6-24-2025

**Work Order Cost Summary**

| Description     | Quantity | Labor Type         | Rate               | Total   |
|-----------------|----------|--------------------|--------------------|---------|
| BERNIE SEEFRIED | 1.00     | RT Shop Mech Blfds | \$52.07            | \$52.07 |
|                 |          |                    | <b>Total Labor</b> | \$52.07 |
|                 |          |                    | <b>Total Parts</b> | \$0.00  |
|                 |          |                    | <b>Total Equip</b> | \$0.00  |
|                 |          |                    | <b>Total Cost</b>  | \$52.07 |

| Item ID | Description      | Completed By    | Reported Hours |
|---------|------------------|-----------------|----------------|
| 126108  | DRIVER DOOR STOP | Bernie Seefried | 1.00           |

**Work Order:** 69586  
**Equipment:** TRACTOR TANDEM KW T880 [9167]  
**Work Location:** Rocky Mountain House Shop  
**Created by:** Blair MacAulay  
**Kms:** 9140  
**Hr:** 9366

**Status:** Closed  
**Serial Number:** 1XKZD40XXLJ969615  
**Business Unit:** Trucks Heavy  
**Start Date:** 7-3-2025  
**Stop Date:** 7-5-2025

**Work Order Cost Summary**

| Description  | Quantity | Labor Type        | Rate               | Total      |
|--|----------|-------------------|--------------------|------------|
| CLAYTON OLSON  | 9.00     | RT Shop Mech Rky  | \$49.05            | \$441.45   |
| DARCY HALLOCK  | 1.50     | RT Shop Tire Tech | \$36.33            | \$54.50    |
| JEFF DUBEAU  | 5.50     | RT Shop Mech Rky  | \$49.05            | \$269.78   |
| MICHAEL GATES  | 1.00     | RT Shop Mech Rky  | \$49.05            | \$49.05    |
|  |          |                   | <b>Total Labor</b> | \$814.77   |
| CLUTCH BRAKE {C127200,M1881} [SB200]                                     | 1.00     | Each              | \$48.45            | \$48.45    |
| CLUTCH SERVO {PAC: E171001} [E176012]                                    | 1.00     | Each              | \$613.80           | \$613.80   |
| DOOR STOP - CHECK LINK [R831024]   | 1.00     | Each              | \$209.75           | \$209.75   |
| FILTER AIR {CF19013, X1987001, FLG: AF55839, NAV: 4070948C1} [SR2000092] | 1.00     | Each              | \$47.70            | \$47.70    |
| FILTER AIR {FLG: AF55836, PAC: SR2000091} [W2084001]                     | 1.00     | Each              | \$17.97            | \$17.97    |
| FILTER CAB AIR {FLG: AF56102} [F371018]                                  | 1.00     | Each              | \$49.33            | \$49.33    |
| FITTING HYD WING COUPLER - 1" FEMALE {PAR_6125-16} [ECH_QWNN1616FP]      | 1.00     | Each              | \$44.34            | \$44.34    |
| TUBE, FUEL DRAIN [3691301]   | 1.00     | Each              | \$67.15            | \$67.15    |
|  |          |                   | <b>Total Parts</b> | \$1,098.50 |
|  |          |                   | <b>Total Equip</b> | \$0.00     |
|  |          |                   | <b>Total Cost</b>  | \$1,913.27 |

| Item ID | Description   | Completed By   | Reported Hours |
|---------|---|----------------|----------------|
| 126442  | TIRE PRESSURE & TREAD DEPTH CHECK - ENTER INTO BS TOOLBOX | Darcy Hallock  | 1.50           |
| 126793  | REPLACE CLUTCH BRAKE                                      | Clayton Olson  | 2.25           |
| 126795  | REPLACE LH DOOR STOP                                      | Blair MacAulay | 2.00           |
| 126887  | REPLACE HYDARULIC QUICK COUPLER                           | Clayton Olson  | 0.25           |
| 126794  | REPAIR DRIVERS WINDOW INTERMITTENT OPERATION              | Blair MacAulay | 0.50           |
| 124673  | PROGRAM VECU & TRANSMISSION WITH PROPER PARAMETERS        | Blair MacAulay | 1.00           |
| 126886  | REPLACE CLUTCH SERVO                                      | Clayton Olson  | 2.75           |
| 126931  | REPLACE FUEL LINE   | Blair MacAulay | 0.50           |
| 126796  | REPAIR A/C  | Blair MacAulay | 6.25           |

|                       |                               |                       |                   |
|-----------------------|-------------------------------|-----------------------|-------------------|
| <b>Work Order:</b>    | 70512                         | <b>Status:</b>        | Closed            |
| <b>Equipment:</b>     | TRACTOR TANDEM KW T880 [9167] | <b>Serial Number:</b> | 1XKZD40XXLJ969615 |
| <b>Work Location:</b> | Blackfalds Shop               | <b>Business Unit:</b> | Trucks Heavy      |
| <b>Created by:</b>    | Oom Jarussirirat              | <b>Start Date:</b>    | 7-21-2025         |
| <b>Kms:</b>           | 9140                          | <b>Stop Date:</b>     | 7-23-2025         |
| <b>Hr:</b>            | 9366                          |                       |                   |

**Work Order Cost Summary**

| Description | Quantity | Labor Type | Rate               | Total  |
|-------------|----------|------------|--------------------|--------|
|             |          |            | <b>Total Labor</b> | \$0.00 |
|             |          |            | <b>Total Parts</b> | \$0.00 |
|             |          |            | <b>Total Equip</b> | \$0.00 |
|             |          |            | <b>Total Cost</b>  | \$0.00 |

| Item ID | Description               | Completed By   | Reported Hours |
|---------|---------------------------|----------------|----------------|
| 128219  | BROKEN BRAKE LINE ON DECK | Blair MacAulay | 0.00           |

|                       |                               |                       |                   |
|-----------------------|-------------------------------|-----------------------|-------------------|
| <b>Work Order:</b>    | 70543                         | <b>Status:</b>        | Closed            |
| <b>Equipment:</b>     | TRACTOR TANDEM KW T880 [9167] | <b>Serial Number:</b> | 1XKZD40XXLJ969615 |
| <b>Work Location:</b> | Rocky Mountain House Shop     | <b>Business Unit:</b> | Trucks Heavy      |
| <b>Created by:</b>    | Blair MacAulay                | <b>Start Date:</b>    | 7-22-2025         |
| <b>Kms:</b>           | 9140                          | <b>Stop Date:</b>     | 7-23-2025         |
| <b>Hr:</b>            | 9366                          |                       |                   |



| Description   | Quantity | Labor Type        | Rate               | Total         |
|---------------|----------|-------------------|--------------------|---------------|
| DARCY HALLOCK | 0.25     | RT Shop Tire Tech | \$36.33            | \$9.08        |
|               |          |                   | <b>Total Labor</b> | <b>\$9.08</b> |
|               |          |                   | <b>Total Parts</b> | <b>\$0.00</b> |
|               |          |                   | <b>Total Equip</b> | <b>\$0.00</b> |
|               |          |                   | <b>Total Cost</b>  | <b>\$9.08</b> |

| Item ID | Description                   | Completed By  | Reported Hours |
|---------|-------------------------------|---------------|----------------|
| 128748  | 9167- 07/25/2025 "TIRE CHECK" | Darcy Hallock | 0.25           |

**Work Order:** 71101 **Status:** Closed  
**Equipment:** TRACTOR TANDEM KW T880 [9167] **Serial Number:** 1XKZD40XXLJ969615  
**Work Location:** Rocky Mountain House Shop **Business Unit:** Trucks Heavy  
**Created by:** Blair MacAulay **Start Date:** 8-1-2025  
**Kms:** 9140 **Stop Date:** 8-5-2025  
**Hr:** 9366

**Work Order Cost Summary**

| Description                    | Quantity | Labor Type       | Rate               | Total           |
|--------------------------------|----------|------------------|--------------------|-----------------|
| JEFF DUBEAU                    | 2.00     | RT Shop Mech Rky | \$49.05            | \$98.10         |
|                                |          |                  | <b>Total Labor</b> | <b>\$98.10</b>  |
| FUEL TANK CAP GASKET [GW21376] | 2.00     | Each             | \$4.86             | \$9.72          |
|                                |          |                  | <b>Total Parts</b> | <b>\$9.72</b>   |
|                                |          |                  | <b>Total Equip</b> | <b>\$0.00</b>   |
|                                |          |                  | <b>Total Cost</b>  | <b>\$107.82</b> |

| Item ID | Description                            | Completed By   | Reported Hours |
|---------|--|----------------|----------------|
| 129439  | REPAIR COOLANT LEAK AT BOTTOM RAD HOSE | Blair MacAulay | 1.00           |
| 129234  | REPLACE WINDSHIELD                     | Blair MacAulay | 0.00           |
| 129440  | REPAIR COOLANT LEAK AT DEF TANK        | Blair MacAulay | 1.00           |

**Work Order:** 72470 **Status:** Closed  
**Equipment:** TRACTOR TANDEM KW T880 [9167] **Serial Number:** 1XKZD40XXLJ969615  
**Work Location:** Rocky Mountain House Shop **Business Unit:** Trucks Heavy  
**Created by:** Bernie Seefried **Start Date:** 8-29-2025  
**Kms:** 9140 **Stop Date:** 9-2-2025  
**Hr:** 9366

**Work Order Cost Summary**

| Description     | Quantity | Labor Type         | Rate               | Total          |
|-----------------|----------|--------------------|--------------------|----------------|
| BERNIE SEEFRIED | 1.00     | RT Shop Mech Blfds | \$52.07            | \$52.07        |
|                 |          |                    | <b>Total Labor</b> | <b>\$52.07</b> |

|                    |         |
|--------------------|---------|
| <b>Total Parts</b> | \$0.00  |
| <b>Total Equip</b> | \$0.00  |
| <b>Total Cost</b>  | \$52.07 |

| Item ID | Description  | Completed By    | Reported Hours |
|---------|--------------|-----------------|----------------|
| 131805  | FENDER ISSUE | Bernie Seefried | 1.00           |

|                       |                               |                       |                   |
|-----------------------|-------------------------------|-----------------------|-------------------|
| <b>Work Order:</b>    | 72516                         | <b>Status:</b>        | Closed            |
| <b>Equipment:</b>     | TRACTOR TANDEM KW T880 [9167] | <b>Serial Number:</b> | 1XKZD40XXLJ969615 |
| <b>Work Location:</b> | Rocky Mountain House Shop     | <b>Business Unit:</b> | Trucks Heavy      |
| <b>Created by:</b>    | Blair MacAulay                | <b>Start Date:</b>    | 9-2-2025          |
| <b>Kms:</b>           | 9140                          | <b>Stop Date:</b>     | 9-3-2025          |
| <b>Hr:</b>            | 9366                          |                       |                   |

**Work Order Cost Summary**

| Description  | Quantity | Labor Type       | Rate               | Total             |
|--|----------|------------------|--------------------|-------------------|
| BLAINE STEFFAN   | 6.00     | RT Shop Mech Rky | \$49.05            | \$294.30          |
| CHANCE NICOLAY   | 6.00     | RT Shop Mech Rky | \$49.05            | \$294.30          |
|  |          |                  | <b>Total Labor</b> | <b>\$588.60</b>   |
| CLUTCH BRAKE {C127200,M1881} [FUL_SB200]   | 1.00     | Each             | \$47.00            | \$47.00           |
| FILTER AIR {CF19013, X1987001, FLG: AF55839, NAV: 4070948C1} [R2000092]                          | 1.00     | Each             | \$43.67            | \$43.67           |
| FILTER AIR {DON: P621725} [P637453]  | 1.00     | Each             | \$112.17           | \$112.17          |
| FILTER CAB AIR {FLG: AF56102} [F371018]  | 1.00     | Each             | \$48.39            | \$48.39           |
| FILTER CAB AIR W/BLACK COVER PB367 [CF19013]   | 1.00     | Each             | \$30.21            | \$30.21           |
| FILTER DIFF {DON: P550939, MERITOR: A3380W1687} [LF3311]   | 1.00     | Each             | \$7.45             | \$7.45            |
| FILTER FUEL SEPARATOR {DON: P550849, FLG: FS19764} [FS19763]                                     | 1.00     | Each             | \$23.47            | \$23.47           |
| FILTER FUEL SPIN-ON {DON: DBF6776, FLG: FF5971NN} [FF5825NN]                                     | 1.00     | Each             | \$61.58            | \$61.58           |
| FILTER FUEL WATER SEPERATOR {PAC: K371021} [FS20207]   | 1.00     | Each             | \$39.28            | \$39.28           |
| FILTER LUBE SPIN-ON {FLG: LF1400NN, DON: DBL7900, SMS: 6002111341, CUMMINS: 5575298} [LF1400INN] | 1.00     | Each             | \$54.32            | \$54.32           |
| HANGER- MUDFLAP 32 1/2" [A253275RL]  | 1.00     | Each             | \$28.41            | \$28.41           |
| PADDED WASHER [HWC05782]   | 3.00     | Each             | \$12.33            | \$36.98           |
| PIDHERNEYS MUD FLAP - 24 X 24 [NM_PB2424]  | 1.00     | Each             | \$53.09            | \$53.09           |
| SCREW - WING M10X1.5X40MM [HWC09341]   | 3.00     | Each             | \$20.37            | \$61.10           |
|  |          |                  | <b>Total Parts</b> | <b>\$647.14</b>   |
|  |          |                  | <b>Total Equip</b> | <b>\$0.00</b>     |
|  |          |                  | <b>Total Cost</b>  | <b>\$1,235.74</b> |

| Item ID | Description          | Completed By   | Reported Hours |
|---------|----------------------|----------------|----------------|
| 11996   | REPLACE CLUTCH BRAKE | Blair MacAulay | 1.00           |
| 132017  | REPAIR LIGHTS        | Blair MacAulay | 0.00           |

|        |   |                |      |
|--------|---|----------------|------|
| 132030 | SECURE WIRING   | Blair MacAulay | 0.50 |
| 132032 | REPAIR LR FENDER  | Blair MacAulay | 2.25 |
| 131115 | 30K SERVICE   | Blair MacAulay | 5.50 |
| 132031 | REPLACE LR MUD FLAP   | Blair MacAulay | 1.00 |
| 132028 | REPLACE TRANSMISSION OIL AND FILTER (IF APPLICABLE) - USE TRANS 75-90 | Blair MacAulay | 0.50 |
| 132029 | REPLACE #1 DIFF FILTER AND FILL OIL                                   | Blair MacAulay | 0.50 |
| 132033 | REPAIR PTO WIRING   | Blair MacAulay | 0.25 |
| 132018 | REMOVE LOGGING LIGHTS   | Blair MacAulay | 0.50 |

|                       |                               |                       |                   |
|-----------------------|-------------------------------|-----------------------|-------------------|
| <b>Work Order:</b>    | 72636                         | <b>Status:</b>        | Closed            |
| <b>Equipment:</b>     | TRACTOR TANDEM KW T880 [9167] | <b>Serial Number:</b> | 1XKZD40XXLJ969615 |
| <b>Work Location:</b> | Rocky Mountain House Shop     | <b>Business Unit:</b> | Trucks Heavy      |
| <b>Created by:</b>    | Blair MacAulay                | <b>Start Date:</b>    | 9-4-2025          |
| <b>Kms:</b>           | 9140                          | <b>Stop Date:</b>     | 9-5-2025          |
| <b>Hr:</b>            | 9366                          |                       |                   |

**Work Order Cost Summary**

| Description   | Quantity | Labor Type       | Rate               | Total             |
|---|----------|------------------|--------------------|-------------------|
| OLIVER TRAUTMANN  | 2.00     | RT Shop Mech Rky | \$49.05            | \$98.10           |
|   |          |                  | <b>Total Labor</b> | <b>\$98.10</b>    |
| CORE ITEM - SENSOR NITROGEN OXIDE NOX [4326874RX]         | 1.00     | Each             | \$1,024.89         | \$1,024.89        |
| CORE ITEM - SENSOR NITROGEN OXIDE NOX [4326874RX][Custom] | 0.00     | Each             | (\$205.70)         | \$0.00            |
|   |          |                  | <b>Total Parts</b> | <b>\$1,024.89</b> |
|   |          |                  | <b>Total Equip</b> | <b>\$0.00</b>     |
|   |          |                  | <b>Total Cost</b>  | <b>\$1,122.99</b> |

| Item ID | Description               | Completed By     | Reported Hours |
|---------|---------------------------|------------------|----------------|
| 132196  | REPLACE OUTLET NOX SENSOR | Oliver Trautmann | 2.00           |

|                       |                               |                       |                   |
|-----------------------|-------------------------------|-----------------------|-------------------|
| <b>Work Order:</b>    | 72897                         | <b>Status:</b>        | Scheduled         |
| <b>Equipment:</b>     | TRACTOR TANDEM KW T880 [9167] | <b>Serial Number:</b> | 1XKZD40XXLJ969615 |
| <b>Work Location:</b> | Rocky Mountain House Shop     | <b>Business Unit:</b> | Trucks Heavy      |
| <b>Created by:</b>    | Bernie Seefried               | <b>Start Date:</b>    | 9-9-2025          |
| <b>Kms:</b>           | 9140                          | <b>Stop Date:</b>     | 9-10-2025         |
| <b>Hr:</b>            | 9366                          |                       |                   |

| Item ID | Description | Completed By | Reported Hours |
|---------|-------------|--------------|----------------|
|---------|-------------|--------------|----------------|

