

# WELD CRACKS AS NECESSARY [126869]

[3108 \[20' LAMAR DECKOVER TRAILER DAY RATE\]](#)

Z10-20  
MAY

Closed: [3108 - 07/02/2025 - GEN CHECK OVER \[69619\]](#)

Requested by OOM JARUSSIRAT on 7/3/2025

Location

MAIN YARD

Type

Trailer Work Order

Problem Code

Priority

MED

Notes

▼ Comments

### Comment

Cut off 2x2 tubing, replace with new, straighten out bent pieces and put old pieces back together

CUT HINGES OFF RAMP DOORS CLEAN UP RUSTY AREA AND WELD ON NEW HINGES

+

▼ Attachments

There are no attachments on this request.

+

### Added By

Kent Woolsey

Kent Woolsey

### Added On

7/4/2025

7/8/2025

# SUSPENSIONS ISSUE [126868]

[3108 \[20' LAMAR DECKOVER TRAILER DAY RATE\]](#)

Closed: [3108 - 07/02/2025 - GEN CHECK OVER \[69619\]](#)

*Requested by OOM JARUSSIRIRAT on 7/3/2025*

Location

MAIN YARD

Type

Trailer Work Order

Problem Code

Priority

MED

Notes

▼ **Comments**

**Comment**

**Added By**

**Added On**

Removed wheels.replaced suspension bolts and bushings on both axles and greased.reinstalled wheels and torqued,i... Darcy Platt

7/3/2025



▼ **Attachments**

*There are no attachments on this request.*



# LIGHTS ISSUE [126865]

[3108 \[20' LAMAR DECKOVER TRAILER DAY RATE\]](#)

Closed: [3108 - 07/02/2025 - GEN CHECK OVER \[69619\]](#)

*Requested by OOM JARUSSIRIRAT on 7/3/2025*

Location

MAIN YARD

Type

Trailer Work Order

Problem Code

Priority

MED

Notes

▼ **Comments**

Comment

Repaired marker light and wiring.rechecked operation of all lights,ok.

Added By

Darcy Platt

Added On

7/3/2025



▼ **Attachments**

*There are no attachments on this request.*

