

Maintenance History (All work types) - WT697

Custom Date Range: 1/1/2023 - 4/14/2026

Work Order ID	Description	Direct Labor \$	Sublet Vendor Labor \$	Part \$	Total \$	Total Labor Hrs	Status Date
56425	1 - PET AUTO BODY: REPLACE HOOD REST BLOCKS	\$0.00	\$365.00	\$0.00	\$365.00	0.00	1/17/2023
58283	1 - CHECK STEER AXLE BRAKES 2 - REPLACE STEERING SHAFT LOWER U-JOINT 3 - MISCELLANEOUS REPAIRS	\$225.00	\$0.00	\$130.70	\$355.70	3.00	4/20/2023
60711	1 - STANDENS: REBUSH AIR RIDE SPRINGS	\$0.00	\$2,324.91	\$0.00	\$2,324.91	0.00	9/12/2023
60886	1 - SLS CALGARY TRUCK REPAIR: CVIP	\$0.00	\$250.00	\$0.00	\$250.00	0.00	11/10/2023
58672	1 - REPLACE WATER PUMP COUPLING	\$37.50	\$0.00	\$0.00	\$37.50	0.50	5/23/2023
58714	1 - A SERVICE	\$187.50	\$0.00	\$115.40	\$302.90	2.50	5/25/2023
62723	1 - IN CIRCLES GLASS: INSTALL WINDSHIELD	\$0.00	\$150.00	\$0.00	\$150.00	0.00	1/16/2024
59353	1 - A SERVICE	\$206.25	\$0.00	\$30.78	\$237.03	2.75	7/6/2023
60037	1 - STARTING ISSUE 2 - A SERVICE 3 - REPAIR AIR LEAK 4 - REPLACE REAR MUDFLAPS	\$468.75	\$0.00	\$119.85	\$588.60	6.25	8/4/2023
60166	1 - REPLACE ALTERNATOR	\$37.50	\$0.00	\$255.44	\$292.94	0.50	8/14/2023
62937	1 - SUNDANCE RADIO COMMUNICATIONS: INSTALL CB RADIO	\$0.00	\$312.40	\$0.00	\$312.40	0.00	1/25/2024
60424	1 - MODIFY TRUCK, ADD CHAINS FOR HOSES	\$187.50	\$0.00	\$0.00	\$187.50	2.50	8/29/2023
60426	1 - B SERVICE	\$175.00	\$0.00	\$20.11	\$195.11	2.25	8/29/2023
60762	1 - REPAIR TRANSMISSION DIPSTICK LEAK	\$75.00	\$0.00	\$8.96	\$83.96	1.00	9/14/2023
60957	1 - REPLACE TRANSMISSION DIPSTICK 2 - B SERVICE 3 - REPLACE PURGE VALVE 4 - REPLACE EXHAUST GASKET	\$375.00	\$0.00	\$859.60	\$1,234.60	5.00	10/4/2023
61194	1 - A SERVICE	\$187.50	\$0.00	\$30.21	\$217.71	2.50	10/25/2023
62195	1 - WELD SPLIT ON DRIVERS SIDE REAR VALVE ON SPRAY BAR	\$56.25	\$0.00	\$0.00	\$56.25	0.75	12/7/2023
63753	1 - CVIP 2 - REPLACE AXLE #3 LEFT SIDE WHEEL SEAL 3 - REPLACE AXLE #1 SPRING PINS AND BUSHINGS 4 - RESEAL FRONT DIFF 5 - CLEAN HYDRAULIC COOLER 6 - RESEAL PTO	\$1,668.75	\$0.00	\$217.52	\$1,886.27	22.25	3/22/2024
64969	1 - IN CIRCLES GLASS	\$0.00	\$150.00	\$0.00	\$150.00	0.00	5/29/2024
64906	1 - A-SERVICE 2 - REPLACE LHS REVERSE LIGHT	\$225.00	\$0.00	\$99.73	\$324.73	3.00	5/27/2024

65005	1 - B-SERVICE	\$75.00	\$0.00	\$0.00	\$75.00	1.00	5/29/2024
66179	1 - A SERVICE 2 - REPLACE EXHAUST CLAMP	\$243.75	\$0.00	\$120.30	\$364.05	3.25	7/19/2024
66855	1 - REPLACE AXLE #3 LEFT SIDE AIRBAG	\$37.50	\$0.00	\$194.94	\$232.44	0.50	8/22/2024
66971	1 - REPLACE COUPLER BETWEEN HYDRAULIC PUMP AND WATER PUMP	\$37.50	\$0.00	\$0.00	\$37.50	0.50	8/28/2024
67017	1 - A SERVICE	\$187.50	\$0.00	\$129.99	\$317.49	2.50	8/30/2024
67680	1 - B SERVICE	\$150.00	\$0.00	\$48.42	\$198.42	2.00	10/7/2024
70498	1 - CVIP 2 - REPLACE AXLE #2 AND #3 LEFT SIDE WHEEL SEALS 3 - REPLACE AXLE #1 FRONT SPRING PINS 4 - REPLACE FRONT ENGINE MOUNT 5 - REPAIR AIR LEAK IN DASH 6 - WELDING	\$618.75	\$0.00	\$321.24	\$939.99	8.25	3/26/2025
70915	1 - IN CIRCLES GLASS: INSTALL WINDSHIELD	\$0.00	\$150.00	\$0.00	\$150.00	0.00	4/23/2025
71518	1 - A SERVICE	\$187.50	\$0.00	\$35.65	\$223.15	2.50	5/12/2025
72022	1 - REPAIR BLOWER MOTOR INOPERABLE	\$112.50	\$0.00	\$63.11	\$175.61	1.50	6/12/2025
72061	1 - REPLACE WATER PUMP	\$581.25	\$2,001.17	\$0.00	\$2,582.42	7.75	6/13/2025
72333	1 - A SERVICE 2 - REPLACE DRIVERS SIDE DOOR SEAL 3 - TIGHTEN RIGHT SIDE TANKER MOUNT BOLTS	\$300.00	\$0.00	\$310.20	\$610.20	4.00	6/27/2025
72620	1 - REPLACE WATER PUMP COUPLER	\$150.00	\$268.25	\$0.00	\$418.25	2.00	7/18/2025
73043	1 - B SERVICE 2 - REPLACE RIGHT SIDE REVERSE LIGHT 3 - REPAIR AIRBAGS NOT INFLATING	\$300.00	\$8.75	\$508.79	\$817.54	4.00	8/6/2025
73608	1 - A SERVICE	\$187.50	\$77.07	\$37.40	\$301.97	2.50	9/9/2025
73699	1 - REPLACE RAD HOSE	\$75.00	\$0.00	\$0.00	\$75.00	1.00	9/22/2025
73898	1 - REPAIR AIR LEAK 2 - REPLACE STEERING COLUMN U-JOINTS 3 - REPLACE AIR TANK DRAIN COCKS 4 - B SERVICE	\$412.50	\$0.00	\$49.76	\$462.26	5.50	9/25/2025
74043	1 - A SERVICE 2 - TIGHTENED TANK BOLTS	\$300.00	\$0.00	\$140.92	\$440.92	4.00	10/8/2025
74604	1 - A SERVICE	\$168.75	\$80.74	\$68.57	\$318.06	2.25	11/5/2025
74867	1 - REPAIR DIESEL TANK LEAKING 2 - REPLACE HOOD TORSION BAR	\$375.00	\$0.00	\$459.35	\$834.35	5.00	11/19/2025
75389	1 - CVIP 2 - REPLACE LEVELING VALVE 3 - REPAIR RIGHT SIDE HEADLIGHT MARKER LIGHT 4 - REPAIR HYDRAULIC LINE 5 - REPLACE AXLE #1 BRAKE DRUMS	\$637.50	\$0.00	\$572.90	\$1,210.40	8.50	1/6/2026
75847	1 - PET AUTO BODY: PAINT	\$0.00	\$5,710.00	\$0.00	\$5,710.00	0.00	2/19/2026
75910	1 - PHOENIX CUSTOM AUTO DESIGNS: INSTALL DECALS	\$0.00	\$148.82	\$0.00	\$148.82	0.00	2/19/2026

75788	1 - RIG UP FOR AUCTION	\$75.00	\$0.00	\$0.00	\$75.00	1.00	2/11/2026
76095	1 - RIG UP FOR AUCTION	\$543.75	\$0.00	\$521.93	\$1,065.68	7.25	2/18/2026
76164	1 - CLEAR FINISH POLISHING: POLISH	\$0.00	\$900.00	\$0.00	\$900.00	0.00	2/19/2026
76117	1 - INSTALL CHROME AXLE COVERS 2 - INSTALL WATER PIPES	\$150.00	\$0.00	\$39.06	\$189.06	2.00	2/18/2026
76143	1 - REPLACE LEFT SIDE WATER PIPE 2 - REPLACE DRIVERS SIDE HEADLIGHT	\$131.25	\$200.00	\$0.00	\$331.25	1.75	2/20/2026
Totals:		\$10,150.00	\$13,097.11	\$5,510.80	\$28,757.91	135.25	