

# Maintenance History (All work types) - TR641

Custom Date Range: 1/1/2023 - 4/14/2026

Work Order ID	Description	Direct Labor \$	Sublet Vendor Labor \$	Part \$	Total \$	Total Labor Hrs	Status Date
56671	1 - GREATWEST KENWORTH: WIRE IN SPEEDOMETER	\$0.00	\$194.60	\$0.00	\$194.60	0.00	1/24/2023
56186	1 - SUNDANCE RADIO COMMUNICATIONS: CHECK RADIO	\$0.00	\$142.50	\$0.00	\$142.50	0.00	1/5/2023
56433	1 - IN CIRCLES GLASS: INSTALL DRIVERS SIDE WINDSHIELD	\$0.00	\$95.00	\$0.00	\$95.00	0.00	1/17/2023
56664	1 - GRATWEST KENWORTH: PROGRAM ECM	\$0.00	\$311.85	\$0.00	\$311.85	0.00	1/24/2023
56669	1 - GREATWEST KENWORTH: PROGRAM ENGINE SOFTWARE	\$0.00	\$365.04	\$0.00	\$365.04	0.00	1/24/2023
56214	1 - B SERVICE	\$150.00	\$0.00	\$38.88	\$188.88	2.00	1/10/2023
56770	1 - A SERVICE 2 - REPLACE HYDRAULIC HOSES	\$281.25	\$0.00	\$455.81	\$737.06	3.75	2/1/2023
56885	1 - REPLACE COOLANT RESERVOIR	\$37.50	\$0.00	\$275.68	\$313.18	0.50	2/7/2023
57396	1 - REPLACE BATTERIES 2 - REPAIR COOLANT LEAK	\$150.00	\$0.00	\$476.45	\$626.45	2.00	3/1/2023
58068	1 - A SERVICE	\$187.50	\$0.00	\$13.78	\$201.28	2.50	4/11/2023
58685	1 - A SERVICE	\$187.50	\$0.00	\$40.41	\$227.91	2.50	5/24/2023
58760	1 - REPLACE LEFT SIDE MIRROR	\$112.50	\$0.00	\$43.48	\$155.98	1.50	5/29/2023
59004	1 - INSTALL BOLTS ON AXLE #2 TORQUE ROD	\$56.25	\$0.00	\$0.00	\$56.25	0.75	6/14/2023
62690	1 - SUNDANCE RADIO COMMUNICATIONS: INSTALL RADIO	\$0.00	\$334.76	\$0.00	\$334.76	0.00	1/16/2024
59284	1 - A SERVICE	\$187.50	\$0.00	\$14.76	\$202.26	2.50	7/4/2023
62757	1 - IN CIRCLES GLASS: INSTALL DRIVERS SIDE WINDSHIELD	\$0.00	\$100.00	\$0.00	\$100.00	0.00	1/17/2024
59566	1 - REPLACE LEVELING VALVE 2 - REPLACE AXLE #3 RIGHT SIDE UPPER TORQUE ROD 3 - MISCELLANEOUS REPAIRS	\$150.00	\$0.00	\$290.38	\$440.38	2.00	7/17/2023
59828	1 - A SERVICE	\$225.00	\$0.00	\$374.79	\$599.79	3.00	7/26/2023
60381	1 - A SERVICE 2 - REMOVE BROKEN PRE-COOLER BOLTS 3 - REPLACE BAR PRESSURE SENSOR	\$431.25	\$0.00	\$364.06	\$795.31	5.75	8/25/2023
60739	1 - REPLACE LOW BEAM HEADLIGHT 2 - REPLACE TARP BREAKER	\$93.75	\$0.00	\$7.09	\$100.84	1.25	9/13/2023

60790	1 - CVIP 2 - CHECK ENGINE LIGHT ON 3 - REPAIR FRONT LEAF SPRINGS SHIFTED 4 - REPLACE 5TH WHEEL PINS 5 - REPAIR LEFT SIDE MIRROR HEAT 6 - REPLACE DOME LIGHT BULBS 7 - LOWER REAR FENDERS 8 - REPLACE AXLE #2 AND #3 BRAKE POTS 9 - REPLACE AXLE #1 RIGHT SIDE WHEEL SEAL 1 - A SERVICE	\$1,237.50	\$0.00	\$700.82	\$1,938.32	16.50	9/18/2023
60874	2 - REPAIR TURBO LEAK 3 - REPAIR COOLANT LEAK	\$375.00	\$0.00	\$43.00	\$418.00	5.00	10/2/2023
61255	1 - A SERVICE	\$187.50	\$0.00	\$15.20	\$202.70	2.50	10/27/2023
63103	1 - IN CIRCLES GLASS: INSTALL DRIVERS SIDE WINDSHIELD	\$0.00	\$100.00	\$0.00	\$100.00	0.00	1/31/2024
61742	1 - A SERVICE 2 - REPLACE FAN AND A/C BELT	\$300.00	\$0.00	\$387.46	\$687.46	4.00	11/15/2023
61853	1 - REPLACE HYDRAULIC HOSE	\$56.25	\$0.00	\$187.59	\$243.84	0.75	11/21/2023
61999	1 - B SERVICE	\$112.50	\$0.00	\$0.00	\$112.50	1.50	11/23/2023
64349	1 - KAL TIRE: RETORQUE WHEELS	\$0.00	\$42.00	\$0.00	\$42.00	0.00	5/3/2024
62084	1 - B SERVICE 2 - REPLACE LEFT SIDE TRANSMISSION COUNTER SHAFT GASKET 3 - REPAIR HYDRAULIC LEAK 4 - REPLACE ALL AIRBAGS 5 - REPLACE EXHAUST MANIFOLD GASKETS 6 - REPLACE AXLE #3 INPUT SEAL	\$1,500.00	\$0.00	\$908.69	\$2,408.69	20.00	12/5/2023
62238	1 - A SERVICE	\$187.50	\$0.00	\$15.20	\$202.70	2.50	12/8/2023
64557	1 - IN CIRCLES GLASS: INSTALL WINDSHIELD	\$0.00	\$200.00	\$0.00	\$200.00	0.00	5/6/2024
62473	1 - REPAIR WEBASTO	\$150.00	\$0.00	\$328.45	\$478.45	2.00	1/3/2024
64576	1 - IN CIRCLES GLASS: INSTALL BACK GLASS	\$0.00	\$100.00	\$0.00	\$100.00	0.00	5/6/2024
63146	1 - A SERVICE	\$300.00	\$0.00	\$116.97	\$416.97	4.00	2/6/2024
64661	1 - IN CIRCLES GLASS: INSTALL WINDSHIELDS	\$0.00	\$200.00	\$0.00	\$200.00	0.00	5/7/2024
63206	1 - REPLACE AXLE #2 EQUALIZER BEAM	\$262.50	\$0.00	\$219.37	\$481.87	3.50	2/12/2024
63513	1 - REPLACE RADIATOR	\$187.50	\$0.00	\$809.25	\$996.75	2.50	3/5/2024
63609	1 - REPLACE BOX CONTROL	\$56.25	\$0.00	\$94.66	\$150.91	0.75	3/18/2024
63614	1 - B SERVICE 2 - REPLACE HYDRAULIC HOSE	\$262.50	\$0.00	\$0.00	\$262.50	3.50	3/14/2024
63773	1 - ENGINE OIL LEAK 2 - FUEL LEAK	\$75.00	\$0.00	\$13.38	\$88.38	1.00	3/25/2024
65228	1 - PET AUTOBODY	\$0.00	\$1,405.75	\$0.00	\$1,405.75	0.00	5/31/2024
64126	1 - A SERVICE	\$187.50	\$0.00	\$16.80	\$204.30	2.50	4/16/2024
64266	1 - CHECK ENGINE LIGHT	\$187.50	\$0.00	\$2.39	\$189.89	2.50	4/23/2024

64337	1 - VALVE SET	\$150.00	\$0.00	\$0.00	\$150.00	2.00	4/26/2024
64788	1 - REPAIR A/C	\$75.00	\$0.00	\$10.41	\$85.41	1.00	5/21/2024
65343	1 - A-SERVICE 2 - REPLACE RIGHT SIDE STACK BUSHING	\$225.00	\$0.00	\$144.66	\$369.66	3.00	6/6/2024
65631	1 - BYPASS POWER STEERING CODES 2 - REPLACE BOTH STEER TIRES	\$75.00	\$0.00	\$0.00	\$75.00	1.00	6/21/2024
65863	1 - A SERVICE	\$187.50	\$0.00	\$16.80	\$204.30	2.50	7/4/2024
66065	1 - REPLACE TRANSMISSION	\$787.50	\$0.00	\$140.27	\$927.77	10.50	7/16/2024
66296	1 - IN CIRCLES GLASS: INSTALL WINDSHIELD	\$0.00	\$200.00	\$0.00	\$200.00	0.00	7/23/2024
66273	1 - B-SERVICE 2 - REPLACE 2ND DIFF SEAL	\$337.50	\$0.00	\$152.49	\$489.99	4.50	7/24/2024
66578	1 - A-SERVICE 2 - REPLACE RHS WORK LIGHT AND BEACON	\$281.25	\$0.00	\$425.92	\$707.17	3.75	8/8/2024
66948	1 - REPAIR TARP INOPERABLE	\$37.50	\$0.00	\$0.00	\$37.50	0.50	8/27/2024
67119	1 - B SERVICE	\$112.50	\$0.00	\$0.00	\$112.50	1.50	9/6/2024
67138	1 - CVIP 2 - REPLACE ALL BRAKE SHOES AND DRUMS 3 - REPLACE AXLE #1 SPRING PINS 4 - A SERVICE 5 - REPAIR GREASE LINES	\$1,987.50	\$0.00	\$1,099.61	\$3,087.11	26.50	9/10/2024
67546	1 - A SERVICE	\$225.00	\$0.00	\$248.47	\$473.47	3.00	9/30/2024
67733	1 - CHECK ENGINE LIGHT ON	\$37.50	\$0.00	\$229.29	\$266.79	0.50	10/8/2024
69205	1 - GREATWEST KENWORTH: ECM REPROGRAM	\$0.00	\$207.90	\$0.00	\$207.90	0.00	2/6/2025
68006	1 - SWAP ECM	\$100.00	\$0.00	\$0.00	\$100.00	1.00	10/23/2024
68190	1 - RPELACE AIR COMPRESSOR DISCHARGE LINE	\$93.75	\$0.00	\$0.00	\$93.75	1.25	11/4/2024
68202	1 - A SERVICE	\$225.00	\$0.00	\$57.62	\$282.62	3.00	11/4/2024
69408	1 - IN CIRCLES GLASS: INSTALL WINDSHIELD	\$0.00	\$100.00	\$0.00	\$100.00	0.00	1/23/2025
68476	1 - REPLACE BLOWER MOTOR	\$75.00	\$0.00	\$235.36	\$310.36	1.00	11/18/2024
69063	1 - A SERVICE	\$187.50	\$0.00	\$47.84	\$235.34	2.50	1/7/2025
69419	1 - TRANSMISSION SWAP 2 - REPLACE WIPER BLADES 3 - CHECK OVER UNIT	\$1,012.50	\$0.00	\$1,022.67	\$2,035.17	13.50	1/24/2025
69628	1 - B SERVICE	\$112.50	\$0.00	\$0.00	\$112.50	1.50	2/3/2025
69775	1 - REPLACE TRAILER LIGHT SWITCH 2 - REPLACE SPEED SENSOR	\$75.00	\$0.00	\$45.91	\$120.91	1.00	2/11/2025
70067	1 - B SERVICE	\$112.50	\$0.00	\$0.00	\$112.50	1.50	2/24/2025
70098	1 - A SERVICE	\$187.50	\$0.00	\$17.59	\$205.09	2.50	2/25/2025
70161	1 - REPLACE YOKE NUT	\$75.00	\$0.00	\$98.24	\$173.24	1.00	2/26/2025
70142	1 - IN CIRCLES GLASS: INSTALL WINDSHIELD	\$0.00	\$100.00	\$0.00	\$100.00	0.00	2/27/2025

70247	1 - CHECK TRANSMISSION LEAK 2 - REPLACE ALTERNATOR PULLEY	\$75.00	\$0.00	\$0.00	\$75.00	1.00	3/4/2025
70364	1 - REPLACE AIR COMPRESSOR DISCHARGE LINE 2 - REPLACE LEFT SIDE CONVEX MIRROR	\$150.00	\$0.00	\$22.16	\$172.16	2.00	3/11/2025
70404	1 - IN CIRCLES GLASS: INSTALL BACKGLASS	\$0.00	\$100.00	\$0.00	\$100.00	0.00	3/12/2025
70606	1 - A SERVICE	\$187.50	\$0.00	\$74.43	\$261.93	2.50	4/2/2025
70860	1 - REPLACE DRIVERS SEAT 2 - REPLACE LEFT SIDE LOW BEAM	\$150.00	\$0.00	\$7.09	\$157.09	2.00	4/11/2025
70990	1 - A SERVICE 2 - REPLACE PASSENGER SIDE HOOD LATCH 3 - REPAIR AXLE #2 PASSENGER SIDE FENDER	\$300.00	\$0.00	\$303.73	\$603.73	4.00	4/21/2025
71214	1 - PET AUTO BODY: REPAIR BATTERY BOX COVER	\$0.00	\$312.50	\$0.00	\$312.50	0.00	4/25/2025
71569	1 - A SERVICE 2 - TIGHTEN #1 DIFF YOKE NUT 3 - REPLACE COOLANT HOSE 4 - REPLACE AXLE #2 LEFT SIDE DUSTSHIELD 5 - STRAIGHTEN TIE ROD 6 - REPLACE BATTERIES 7 - REPAIR PTO LIGHT 8 - REPLACE AXLE #2 LEFT SIDE SLACK ADJUSTER	\$712.50	\$0.00	\$761.72	\$1,474.22	9.50	5/14/2025
71575	1 - WARD TIRE: ALIGNMENT	\$0.00	\$297.00	\$0.00	\$297.00	0.00	5/26/2025
71796	1 - IN CIRCLES GLASS: INSTALL WINDSHIELD	\$0.00	\$100.00	\$0.00	\$100.00	0.00	6/4/2025
72062	1 - REPLACE POWER STEERING BOX	\$225.00	\$0.00	\$1,095.57	\$1,320.57	3.00	6/13/2025
72181	1 - A SERVICE 2 - REPAIR PASSENGER SIDE STEP	\$225.00	\$0.00	\$17.59	\$242.59	3.00	6/18/2025
72402	1 - B SERVICE 2 - REPAIR AIR LEAK	\$150.00	\$0.00	\$0.00	\$150.00	2.00	7/3/2025
72862	1 - A SERVICE 2 - SECURE MIDDLE YOKE NUT 3 - REPLACE EXHAUST FLEX PIPE	\$300.00	\$0.00	\$96.39	\$396.39	4.00	7/25/2025
73050	1 - REPLACE RIGHT SIDE HEADLIGHT	\$37.50	\$0.00	\$7.09	\$44.59	0.50	8/6/2025
73255	1 - CVIP 2 - REPLACE AXLE #3 RIGHT SIDE AIRBAG 3 - REPAIR AIR LEAK BEHIND CAB 4 - REPLACE AXLE #1 SPRING BUSHINGS 5 - ADJUST 5TH WHEEL 6 - REPLACE AXLE #2 RIGHT SIDE SHOCK 7 - REPLACE AXLE #2 AND #3 BRAKE SHOES AND DRUMS 8 - A SERVICE	\$1,256.25	\$139.46	\$1,440.23	\$2,835.94	16.75	8/19/2025
73690	1 - A SERVICE 2 - REPAIR LEFT SIDE FENDER AND STEP	\$281.25	\$139.46	\$63.72	\$484.43	3.75	9/15/2025
74306	1 - A SERVICE	\$187.50	\$135.79	\$18.67	\$341.96	2.50	10/21/2025

74335	1 - REPLACE DRIVERS SIDE WINDOW REGULATOR	\$112.50	\$0.00	\$181.05	\$293.55	1.50	10/22/2025
74353	1 - REPAIR ENGINE RUNNING ROUGH	\$412.50	\$0.00	\$56.01	\$468.51	5.50	10/24/2025
75395	1 - IN CIRCLES GLASS: INSTALL WINDSHIELD	\$0.00	\$100.00	\$0.00	\$100.00	0.00	2/19/2026
74737	1 - REPLACE THERMOSTAT	\$225.00	\$0.00	\$592.69	\$817.69	3.00	11/12/2025
74882	1 - A SERVICE	\$187.50	\$132.12	\$49.41	\$369.03	2.50	11/18/2025
74967	1 - REPLACE AIR DRYER	\$93.75	\$0.00	\$498.75	\$592.50	1.25	11/24/2025
75293	1 - REPLACE PURGE VALVE	\$56.25	\$0.00	\$149.11	\$205.36	0.75	12/11/2025
75408	1 - REPAIR LIGHTS	\$93.75	\$0.00	\$16.75	\$110.50	1.25	12/17/2025
75543	1 - A SERVICE	\$225.00	\$132.12	\$18.67	\$375.79	3.00	1/14/2026
75776	1 - RIG UP FOR AUCTION 2 - INSTALL NEW RENN GRAVEL BOX	\$7,837.50	\$910.00	\$411.62	\$9,159.12	104.50	2/12/2026
76567	1 - CVIP 2 - STRAIGHTEN LEFT SIDE STEP 3 - REPLACE AXLE #2 RIGHT SIDE TORSION BAR 4 - WELDING 5 - RIG UP 6 - REPLACE DRAGLINK	\$3,075.00	\$339.90	\$1,081.32	\$4,496.22	41.00	3/26/2026
76546	1 - PET AUTO BODY: PAINT	\$0.00	\$9,357.53	\$0.00	\$9,357.53	0.00	4/15/2026
76547	1 - PHOENIX CUSTOM AUTO DESIGNS: SUPPLY AND INSTALL DECALS	\$0.00	\$140.60	\$0.00	\$140.60	0.00	4/15/2026
76982	1 - PREP FOR AUCTION	\$450.00	\$0.00	\$919.92	\$1,369.92	6.00	4/13/2026
77006	1 - PREP FOR AUCTION	\$300.00	\$693.25	\$31.12	\$1,024.37	4.00	4/13/2026
76564	1 - CLEAR FINISH POLISHING: FULL TRUCK, NO BACK RIMS	\$0.00	\$900.00	\$0.00	\$900.00	0.00	4/15/2026
<b>Totals:</b>		<b>\$31,956.25</b>	<b>\$18,129.13</b>	<b>\$18,162.72</b>	<b>\$68,248.10</b>	<b>425.75</b>	