

Maintenance History (All work types) - QS640

Custom Date Range: 1/1/2023 - 3/31/2026

Work Order ID	Description	Direct Labor \$	Sublet Vendor	Part \$	Total \$	Total Labor Hrs	Status Date
76835	1 - PREP FOR AUCTION	\$1,406.25	\$0.00	\$2,180.64	\$3,586.89	18.75	4/1/2026
76791	1 - CVIP 2 - REPLACE AXLE #2 ABS SENSORS 3 - REPLACE PLYWOOD ON TAILGATE	\$1,050.00	\$0.00	\$123.17	\$1,173.17	14.00	3/26/2026
76531	1 - B SERVICE	\$300.00	\$0.00	\$15.02	\$315.02	4.00	3/12/2026
76197	1 - B SERVICE	\$112.50	\$0.00	\$0.00	\$112.50	1.50	2/20/2026
75801	1 - B SERVICE 2 - CVIP 3 - WELDING 4 - REPLACE AXLE #3 RIGHT AND AXLE #4 LEFT AIRBAGS 5 - REPLACE ALL BRAKE SHOES 6 - REPLACE RIGHT SIDE SIDEBOARD	\$1,406.25	\$141.45	\$1,524.17	\$3,071.87	18.75	1/27/2026
75343	1 - REPAIR AIRBAGS	\$150.00	\$0.00	\$0.00	\$150.00	2.00	12/15/2025
75224	1 - B SERVICE	\$112.50	\$0.00	\$0.00	\$112.50	1.50	12/9/2025
74496	1 - B SERVICE 2 - REPLACE AXLE #1 AND #2 LEFT SIDE AIRBAGS	\$375.00	\$0.00	\$22.91	\$397.91	5.00	10/30/2025
74136	1 - REPLACE AXLE #3 LEFT SIDE AIRBAG FITTING	\$37.50	\$0.00	\$0.00	\$37.50	0.50	10/14/2025
73886	1 - B SERVICE	\$112.50	\$0.00	\$30.77	\$143.27	1.50	10/1/2025
72742	1 - ABS LIGHT ON	\$187.50	\$0.00	\$51.41	\$238.91	2.50	7/18/2025
72128	1 - B SERVICE	\$131.25	\$0.00	\$0.00	\$131.25	1.75	6/17/2025
71598	1 - REPLACE TARP 2 - ABS LIGHT ON	\$150.00	\$0.00	\$257.25	\$407.25	2.00	5/16/2025
71333	1 - B SERVICE 2 - REPAIR MARKER LIGHTS	\$150.00	\$0.00	\$7.35	\$157.35	2.00	5/2/2025
70745	1 - CVIP 2 - REPLACE AXLE #1 LEFT SIDE WHEEL SEAL 3 - REPLACE ALL BRAKE SHOES AND DRUMS 4 - REPLACE HYDRAULIC HOSE	\$562.50	\$0.00	\$1,441.61	\$2,004.11	7.50	4/8/2025
70500	1 - B SERVICE	\$93.75	\$0.00	\$0.00	\$93.75	1.25	3/26/2025
69930	1 - B SERVICE 2 - REPLACE DRIVERS SIDE SIDEBOARD	\$300.00	\$0.00	\$3.26	\$303.26	4.00	2/18/2025
69687	1 - B SERVICE 2 - RPELACE AXLE #4 RIGHT SIDE ABS SENSOR	\$187.50	\$0.00	\$93.18	\$280.68	2.50	2/6/2025

69382	1 - B SERVICE	\$93.75	\$0.00	\$0.00	\$93.75	1.25	1/21/2025
68826	1 - ADJUST TAILGATE 2 - REPAIR ABS 3 - REPLACE 7-WIRE CABLE	\$112.50	\$0.00	\$20.36	\$132.86	1.50	12/10/2024
68754	1 - READJUST GATE LATCHES, REPAIR LOWER GATE PINS	\$168.75	\$0.00	\$0.00	\$168.75	2.25	12/5/2024
68653	1 - B SERVICE 2 - REPLACE AXLE #2 LEFT SIDE WHEEL SEAL	\$225.00	\$0.00	\$42.58	\$267.58	3.00	12/3/2024
68569	1 - REPAIR AIR LINE 2 - FINISH INSTALLING LINER	\$731.25	\$0.00	\$5.17	\$736.42	9.75	11/27/2024
68530	1 - REMOVED DAMAGED LINER, WELD AND PLATE DAMAGED FLOOR AND WELD CRACKS	\$1,650.00	\$0.00	\$91.45	\$1,741.45	22.00	11/26/2024
68384	1 - B SERVICE 2 - REPLACE DRIVERS SIDE FRONT SIDEBOARD	\$131.25	\$0.00	\$0.00	\$131.25	1.75	11/13/2024
68187	1 - B SERVICE 2 - REPLACE HYDRAULIC HOSE 3 - REPLACE TAILGATE LOCK SPRING 4 - REPLACE TANK DRAIN VALVE 5 - REPAIR AIR LEAK 6 - INSTALL HOIST GREASE FITTINGS	\$393.75	\$0.00	\$149.03	\$542.78	5.25	11/4/2024
67771	1 - B SERVICE	\$93.75	\$0.00	\$0.00	\$93.75	1.25	10/10/2024
67248	1 - B SERVICE 2 - REPAIR AIR LEAK	\$150.00	\$0.00	\$7.40	\$157.40	2.00	9/13/2024
66633	1 - B-SERVICE	\$93.75	\$0.00	\$0.00	\$93.75	1.25	8/9/2024
66331	1 - REPLACE DRIVER SIDE REAR SIDE BOARD	\$75.00	\$0.00	\$38.88	\$113.88	1.00	7/24/2024
66228	1 - B SERVICE 2 - REPLACE AXLE #3 LEFT SIDE AIRBAG	\$281.25	\$0.00	\$1.70	\$282.95	3.75	7/22/2024
65552	1 - B-SERVICE	\$67.50	\$0.00	\$0.00	\$67.50	0.90	6/17/2024
65026	1 - B-SERVICE 2 - AXLE #2 DRIVER SIDE WHEEL SEAL	\$150.00	\$0.00	\$32.71	\$182.71	2.00	5/29/2024
64908	1 - REPAIR TARP MOTOR	\$37.50	\$0.00	\$0.00	\$37.50	0.50	5/27/2024
64519	1 - REPAIR BOX HINGES/WELDING	\$1,687.50	\$0.00	\$0.00	\$1,687.50	22.50	5/14/2024
64113	1 - CVIP 2 - REPLACE ALL SCAM TUBES 3 - REPALCE AXLE #1 RHS AND AXLE #2 LHS WHEEL SEALS	\$1,050.00	\$0.00	\$478.07	\$1,528.07	14.00	5/3/2024
64456	1 - B-SERVICE	\$75.00	\$0.00	\$0.00	\$75.00	1.00	5/3/2024
63310	1 - B SERVICE	\$93.75	\$0.00	\$0.00	\$93.75	1.25	2/21/2024
62435	1 - B SERVICE	\$93.75	\$0.00	\$0.00	\$93.75	1.25	1/2/2024
62317	1 - B SERVICE 2 - REPAIR ABS 3 - REPLACE PASSENGER SIDE REAR SIDEBOARD	\$412.50	\$0.00	\$1.52	\$414.02	5.50	12/19/2023
61626	1 - PHOENIX CUSTOM AUTO DESIGNS: SUPPLY DECALS	\$0.00	\$223.62	\$0.00	\$223.62	0.00	11/22/2023
61791	1 - B SERVICE	\$75.00	\$0.00	\$0.00	\$75.00	1.00	11/17/2023

61597	1 - REPLACE MAC VALVE	\$75.00	\$0.00	\$132.71	\$207.71	1.00	11/10/2023
61558	1 - REPAIR AIR LEAK 2 - B SERVICE 3 - ABS LIGHT ON 4 - REPLACE AXLE #4 RIGHT SIDE SERVICE LINE	\$281.25	\$0.00	\$1.48	\$282.73	3.75	11/10/2023
60969	1 - B SERVICE	\$131.25	\$0.00	\$0.00	\$131.25	1.75	10/4/2023
60605	1 - REPLACE HYDRAULIC HOSE	\$37.50	\$0.00	\$148.82	\$186.32	0.50	9/7/2023
60104	1 - B SERVICE	\$112.50	\$0.00	\$0.00	\$112.50	1.50	8/10/2023
59610	1 - B SERVICE	\$131.25	\$0.00	\$21.32	\$152.57	1.75	7/18/2023
59028	1 - B SERVICE	\$131.25	\$0.00	\$0.00	\$131.25	1.75	6/14/2023
58601	1 - ASSEMBLY AFTER PAINT 2 - INSTALL TARP ARMS AND TARP WIRE	\$1,518.75	\$0.00	\$1,011.86	\$2,530.61	20.25	5/17/2023
58390	1 - STRIP FOR PAINT 2 - CVIP 3 - REPLACE ALL BRAKE POTS 4 - REPLACE AXLE #3 LEFT SIDE AIRBAG 5 - WELDING	\$1,931.25	\$0.00	\$2,105.99	\$4,037.24	25.75	4/28/2023
57837	1 - ABS LIGHT ON 2 - CHECK OVER 3 - REPLACE REAR LEVELING VALVE 4 - REPAIR TAILGATE FLAT BAR	\$168.75	\$0.00	\$78.35	\$247.10	2.25	3/28/2023
57727	1 - B SERVICE	\$75.00	\$0.00	\$0.00	\$75.00	1.00	3/16/2023
57589	1 - B SERVICE 2 - REPLACE ABS WIRE	\$150.00	\$0.00	\$0.00	\$150.00	2.00	3/8/2023
56988	1 - REPLACE HOIST	\$150.00	\$0.00	\$4,031.18	\$4,181.18	2.00	2/27/2023
56787	1 - B SERVICE	\$75.00	\$0.00	\$21.50	\$96.50	1.00	2/2/2023
56114	1 - B SERVICE 2 - WELDING 3 - REPLACE AXLE #4 RIGHT SIDE WHEEL SEAL 4 - INSTALL PLACARD HOLDERS	\$356.25	\$0.00	\$149.30	\$505.55	4.75	1/4/2023
Totals:		\$20,092.50	\$365.07	\$14,322.11	\$34,779.68	267.90	